

2016 Facility Condition Assessment and Educational Suitability Assessment



GORZYCKI MIDDLE SCHOOL

Facility Site

7412 W. Slaughter Lane Austin, TX 78749

Building Area: 169,045 Square Feet

Site: 14 Acres

Date of First Construction: 2009

Assessment Timeline

Facility Condition Interview: 07/26/16
Facility Condition Field Visit: 07/26/16
Educational Suitability Interview: 07/26/16
Educational Suitability Field Visit: 07/26/16



Facility Summary



Gorzycki Middle School was established in 2009, and consists of the Main School Building (BLDG-062A). This building contains classrooms, administration office, two gymnasiums, cafeteria, and kitchen.

Facility Condition Assessment (FCA)

The FCA is a process that is used to understand the deficiencies of a facility. It is conducted by a team of architects and engineers of various disciplines. The FCA is performed using existing data, facility staff interviews, facility walk-though assessments, analysis, and cost estimating.

FCA REPORT CARD

Gorzycki Middle School



*The FCA score is equal to 100 minus the Facility Condition Index (FCI). The FCI is equal to the cost to maintain, repair and replace deficiencies of a facility divided by the current replacement value of the facility.

Educational Suitability Assessment (ESA)

The ESA measures the degree to which the facility supports teaching and learning considering the exterior and site, academic spaces, support spaces, future-ready spaces, library and media center, security, technology, storage, fixtures, furniture and equipment, environmental quality, and controllability of lighting and HVAC systems.

ESA REPORT CARD

Gorzycki Middle School



*The FCA and ESA scores are not a representation of the school's academic performance and does not reflect any construction or improvements performed after the assessment date.

*These are draft scores pending AISD feedback.

Links to Online Surveys:

AISD Educational Suitability Survey - https://www.surveymonkey.com/r/AISD_Educational_Suitability_Survey

AISD Cuestionario para la Condicion de Instalacion y Conveniencia Educativa - https://www.survekymonkey.com/r/AISD_Educational_Suitability_Espanol



Rating

2016 Facility Condition Assessment and Educational Suitability Assessment



Rev. 11/29/2016

Facility Condition Assessment

Scale:	Excellent Good Average Poor Fail	BLDG-062A Main School Building			
Mechanical / HVAC					
	Mechanical / HVAC	A			
	Domestic Water Distribution	G			
	Plumbing Fixtures	©			
	Elevators & Lifts	G			
Electrical					
	Electrical Distribution	©			
	Lighting	A			
	Communications & Security	G			
	Fire Alarm	G			
	Fire Protection / Suppression	<u> </u>			
Exterior Architecture					
	Exterior Doors	<u> </u>			
	Exterior Walls	G			
	Exterior Windows	<u>©</u>			
	Exterior Stairs	G			
	Roofing	<u>A</u>			
In	erior Architecture				
	Interior Ceiling Finishes	<u>©</u>			
	Interior Doors	G			
	Interior Floor Finishes	<u> </u>			
	Interior Walls	G			
	Interior Wall Finishes	A			
	Interior Stairs	A			

Site / Civil				
	Roadways	A		
	Parking Lots	G		
	Pedestrian Paving (Sidewalks)	A		
	Site Development	G		
	Landscaping	A		
	Play Fields	G		

Crawl Space					
	Drainage Below Building	N/A			
	Access / Ventilation	N/A			
	Foundation	N/A			
	Exposed Pipes	N/A			
	Exposed Ductwork	N/A			

Rating Scale

Excellent 81-100

Good 66-80

Average 51-65

Unsatisfactory 36-50

Very Unsatisfactory 20-35

Education Suitability Assessment			
Assessment Area	Score		
Exterior	97		
General Building	70		
General Academic & Elective Spaces	98		
Future Ready Student Development	65		
Library / Media Center	87		
Security	88		
Technology	80		
Storage	67		
Furniture, Fixtures & Equipment	58		
Environmental Quality (Lighting, Odors, Pests)	92		
Controllability of Systems (Lights, Temps, Blinds)	92		

