Clayton Elementary School



Educational Suitability and Facility Condition Assessments - 2021



Facility Summary


Clayton Elementary School, serving an enrollment of approximately 720 students is in southwest Austin. It was built in 2006 and consists of approximately 103,300 square feet. Clayton focuses on the development of literacy, independent thinking, and problem solving as the essential building blocks to becoming responsible individuals. The overall condition of the school is good. The deficiencies that were found include a lack of maker space, specialized special education spaces.

Building Address: 7525 La Crosse Ave Austin, TX 78739

Building Square Footage:	102,300 SF
Site Acreage:	17 Acres
Date of First Construction:	2006

Student Demographics:

Demographic	Percentage
African American	0.6%
Hispanic	15.8%
White	59.9%
American Indian	0.3%
Asian	17.8%
Pacific Islander	0.3%
Two or More Races	5.4%
Economically Disadvantaged	8.7%
English Language Learners	4.6%
Special Education	12.4%
Enrollment	723



Jacobs Perkins&Will

Clayton Elementary School



Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

