Anita Ferrales Coy Facility



Educational Suitability and Facility Condition Assessments - 2021




Facility Summary

The Alternative Learning Center at the Anita Ferrales Coy Facility has a student enrollment that varies from 5 to 180 students in East Austin. It is known for providing a second chance to students. Students attend the school for a predetermined number of days when they have discipline issues at their school or in the community. Low studentto-teacher ratios foster specialized instruction and help improve student behavior. As a specialized facility, the school does not provide many of the programs common at other high schools in the district. Building Address: 4900 Gonzales St Austin, TX 78702

Building Square Footage:	82,000 SF
Site Acreage:	19.3 Acres
Date of First Construction:	1957

Student Demographics:

Demographic	Percentage
African American	33.3%
Hispanic	50.0%
White	16.7%
American Indian	0.0%
Asian	0.0%
Pacific Islander	0.0%
Two or More Races	0.0%
Economically Disadvantaged	83.3%
English Language Learners	16.7%
Special Education	50.0%
Enrollment	6



Jacobs Perkins&Will

Anita Ferrales Coy Facility



Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

