Galindo Elementary School



Educational Suitability and Facility Condition Assessments - 2021



Facility Summary


Galindo Elementary School serves an enrollment of approximately 490 students in south Austin. It was constructed in 1989, with a mechanical building addition in 2001, and consists of approximately 85,000 square feet on 9 acres. The campus participates in the district's AVID (Advancement Via Individual Determination) program and the Creative Learning Institute to bring its students an innovative curriculum. It is also a dual-language school that focuses on social and emotional learning.

Building Address: 3800 S. 2nd St Austin, TX 78704

Building Square Footage:	85,400 SF
Site Acreage:	9 Acres
Date of First Construction:	1989

Student Demographics:

Demographic	Percentage
African American	4.9%
Hispanic	86.8%
White	5.9%
American Indian	0.2%
Asian	2.2%
Pacific Islander	0.0%
Two or More Races	0.0%
Economically Disadvantaged	91.6%
English Language Learners	67.0%
Special Education	19.3%
Enrollment	491



Jacobs Perkins&Will

Galindo Elementary School




Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.



Jacobs Perkins&Will