



Educational Suitability Summary Report

Baldwin Elementary School

Date: 12/21/2020

Score 69% Satisfactory

Baldwin Elementary School, serving an enrollment of approximately 675 students in southwest Austin, is a suburban neighborhood school in the Meridian subdivision. It was built in 2010 with a total of 87,000 square feet on 14 acres. The site has two entrances: one for parent pickup/drop-off and one for buses. The visitor parking lot is in front of the elementary school and is separated from the pickup and drop-off. There are sidewalks along the main streets leading into the school grounds, and the school is across the street from the Meridian Community Pavilion.

The campus grounds are large. There is a covered basketball court adjacent to the indoor gymnasium, and a couple of areas are set up for outdoor classes. There is a trail along the back edge of the grounds. There are open green areas and several trees on campus offering adequate shade. The school has cisterns as well as gardens.

There are opportunities to have breakout sessions in designated areas in the hallways with different types of furniture, but acoustical and supervision issues may arise. There are limited windows from the studios to the hallways to allow for passive supervision. Each studio has built-in cabinets for storage, giving each room ample storage capacity. There are sufficient electrical outlets along the walls and a typical two-switch control for the artificial lighting.

Interview Overview

The interview included Principal Jennifer Murray, Assistant Principal Tammy Thompson, librarian Mackenzie Wright and head custodian Erenia Chavez. Although the building is just over 10 years old, there are areas for improvement the staff would like to see at their campus.

The staff noted there are programs that are not in suitable spaces. They are using the dedicated art room and an adjacent typical studio as another art room. The campus would like to have additional collaboration spaces. There are only two large group collaboration spaces in the learning neighborhoods.

The campus

would also like to have a dedicated robotics space. One corner of the library functions as a maker space. The library has allocated the Literacy Library and A/V storage as a mindfulness room and now lacks adequate storage. The staff desires a dedicated science area and more collaboration spaces and added transparency into corridors. It was mentioned that there is not an adult restroom on the second floor. The administration spaces and nurses' offices also lack sufficient acoustic privacy, making it difficult to hold confidential meetings.

The exterior spaces are an important part of instruction. They would like to have more outdoor

Educational Suitability Summary Report

Baldwin Elementary School

learning spaces such as an edible garden space and increased Wi-Fi connection to outdoor spaces. Other desired exterior improvements are fencing at the portables to secure the connection to the main building.

Assessment Findings

The Educational Suitability Assessment of Baldwin Elementary School earned a 69% overall score and places the campus in a category of Satisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Academics and Learning

Score is unsatisfactory.

There is limited transparency to other studios and very limited shared learning spaces. Only two learning neighborhoods have an open collaboration space and there are no breakout rooms. Special education rooms are in typical studios and are lacking dedicated support spaces.

Administrative Spaces

Score is unsatisfactory.

The administrative space could be more welcoming. It is a small area with minimal seating. However, there are windows from the administration office into the vestibule, giving a clear view for the administrative staff. Staff indicated that acoustic privacy levels are inadequate in the administration spaces and nurses' offices.

Average Categories (51-65%):

Security

Score is average.



Furniture, Fixtures, Equipment

Score is average.

Inconsistent furniture types among studios and within studios with some old and some newer furniture pieces that are more flexible. All studios have tables with loose chairs, but some are not as easily reconfigured, and few have a variety of seating options.

Environmental Quality

Score is average.

The studios have adequate natural lighting in every space and the windows are operable, allowing for fresh air. Some studios have high ribbon windows limiting the views to the exterior.

Baldwin Elementary School

Media Resources

Score is average.

The library is a good size, is in good condition and can be accessed from the public parking afterhours. There are different types of furniture allowing for small and large group study and a reading area for younger students. There are digital and projector screen capabilities in the library and a significant number of windows looking outward but no windows looking into the school or hallway, giving it limited transparency. There are no dedicated quiet rooms for individual study. The library lacks storage due to the only storage space being used as a mindfulness room.

Technology

Score is average.

Studios do not have an adequate number of outlets to charge devices. Cafeteria and gym utilize extension cords for projectors on carts and these cords extend to the steps of the stage and across the gym floor.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

The site has multiple spaces but needs improvements to function well. The large, covered play/activity space is directly adjacent to the gym and is in good condition.

General Building

Score is satisfactory.

Main circulation routes are wide enough, between 8 to 10 feet, for safe and effective movement. Layout of building provides access to library, gym and cafeteria for after-hours functions without gaining access to rest of school.

Controllability of Systems

Score is satisfactory. Shades are provided to control the natural lighting. Each studio has its own thermostat.

Visual and Performing Arts

Score is satisfactory.

School utilizes two spaces for art – one is a dedicated art room, the other a converted studio. Music and performance spaces are adequate.

PE and Wellness

Score is satisfactory.

The gymnasium is a good size and in good condition. There is a dedicated storage room for the gymnasium that can be secured and accessed from the outside via an overhead door. The gymnasium can also be accessed from the public parking lot for after-hour activities.

Food Services

Score is satisfactory.

The cafeteria is adjacent to the gymnasium and can open into one big space for events. The stage has projector capabilities, but there is no permanent overhead projector in the cafeteria area. There

Educational Suitability Summary Report

Baldwin Elementary School

is a need for additional outlets on stage to allow for podium and teaching setups. The stage has lighting and speakers. It was difficult to access the furniture in the cafeteria because it was being used as a studio at the time of the assessment. There were long tables stored along one of the cafeteria walls that would suggest furniture is the standard, long table arrangement.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.

The circulation separates bus, vehicular and pedestrian traffic well. Trash/compost bins are accessible and directly accessible to kitchen area. Exterior facade is in good condition and is well-maintained.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Baldwin Elementary School



Typical studio with varying technology and access to natural light with one large window and tall row of windows with limited views.



Studios connected with bathroom corridor and outfitted with curtain to limit distraction from adjacent room.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Baldwin Elementary School



Bathroom for special education with limited space to accommodate changing table.



Literacy Library and A/V storage converted into mindfulness room. Library lacks storage.

Educational Suitability Summary Report

Baldwin Elementary School



Cafeteria and stage area A/V connection limited with use of extension cord to connect to a projector on a cart.



Variety of furniture seating options in library. Library is in the process of receiving updated furniture.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Baldwin Elementary School

Supporting Photographs



One of the collaboration spaces on campus within one of the learning neighborhoods. Functions well for larger groups. No small group spaces are provided.



Gym appropriately configured with operable partition opening to the cafeteria.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Baldwin Elementary School



Outdoor learning spaces need further development to function well.



Outdoor learning space needs shade and updates to function well.

02/11/2022




Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Baldwin ES	Carlos Cruz & Anacleto Rojas Jr.	12/15/2020

1 - Ex	cterior		1	2	3	4	5	N/A		8.75	94%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen									
		at the same location									
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply						-			
1.2	ls the build	ing easily identified with appropriate signage and			3				Comments		
1.2	community	wayfinding?			3)			Comments	0.25	0.75
	1	Very unsatisfactory - Campus has no signage /									
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply						L			



Exterior (cont.)	1	2	3	4	5	N/A			
3 Is the dumpster accessible for trash / compost disposal?					5		Comments	0.50	2.
 Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. 									
4 Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
5 Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
N/A Does not apply									
Outdoor Learning and Activity	1	2	3	4	5	N/A	х.	15.00	8
Are outdoor studios and support spaces appropriately configured per the ed spec?			3				Comments	1.00	3
1 Very unsatisfactory - No dedicated outdoor studios							Small spaces dispersed around campus, not fully dev	eloped.	
2 Unsatisfactory - Too small, poor condition, disconnected									
from learning spaces, no flexibility, no shade provided									
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
 shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area 									
5 Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full									
shade coverage over studio area N/A Does not apply									
Are active playgrounds (elementary only) and support spaces configured per the ed spec?				4			Comments	1.00	4
1 Very unsatisfactory - No dedicated active playground									
2 Unsatisfactory - Too small, poor condition, no shade provided									
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
shade coverage over play structure 4 Satisfactory - Good size, good condition, more than 50%									
shade coverage over play structure 5 Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									

02/11/2022 ³

2 - Outdoor Learning and Activity (cont)		1	2	3	4	5	N/A	N		
2.3 Are gardens and support spaces appropriately confi spec? (evaluation on infrastructure not condition of				3				Comments	0.00	0.00
 Very unsatisfactory - No dedicated gar Unsatisfactory - Too small, poor conditi from learning spaces, no flexibility, no o source Average - Adequate size, adequate con some renovations or updates to function source is difficult to access 	on, disconnected Iccessible water Indition, needs							Monitoring answer, does not affect score for Outdoo Activity. None are centrally located.	r Learning and	
4 Satisfactory - Good size, good condition learning spaces, good flexibility, water accessible with 100 ft hose										
 5 Very Satisfactory - Generous size, excel connected to learning spaces, excellent source is less than 50ft from the garder N/A Does not apply 	flexibility, water									
2.4 Are the rain gardens and/or cisterns appropriately c ed spec?	onfigured per the		2					Comments	0.00	0.0
IVery unsatisfactory - No rain gardens o2Unsatisfactory - Too small, poor conditi			Į					Recording answer, does not affect score for Outdoor		
functioning, disconnected 3 Average - Adequate size, adequate con connected, needs some renovations or function well								Two large cisterns on campus, but according to Distri the make up water from the cistern should be connec supply, but currently that piping needs to be reestab	cted to the irrig lished. Cistern r	ation
 Satisfactory - Good size, good condition properly Very Satisfactory - Generous size, excel exceptional functionality, connected to 	ent condition,							the playscape is currently connected to the potable s	ирріу.	
educational signage provided N/A Does not apply										
2.5 Does the school have animal husbandry? (optional)		1						Comments	0.00	0.00
1 No 5 Yes										
5 Yes 2.6 Does the school have nature loop trails? (optional)						5		Comments	0.00	0.0
1 No						0		connerta	0.00	0.0
5 Yes	T .	-							0.00	
2.7 Does the school have a learning pond? (optional)		1						Comments	0.00	0.0
5 Yes										
2.8 Does the school have a grass play field and walking	trail?					5		Comments	1.00	5.0
1 No										
5 Yes										

								•=,	,,
3 - General Building	1	2	3	4	5	N/A	<u> </u>	11.25	73
Are interior circulation routes wide enough to safely and effectively accommodate student movement?				4			Comments	0.50	2.0
 Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" 								•	
wide 2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide N/A Does not apply									
Are community use areas arranged so that the school can allow night	(1	Γ				
3.2 functions without full school access?	ł				5		Comments	0.75	3.7
 Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours 						1	Layout provides access to spaces without access to re	est of campus.	
2 Unsatisfactory - Only one of the public spaces (Cafeteria,									
Gym and Library) can be accessed from parking and									
secured after hours Average - Only two of the public spaces can be accessed									
from parking and secured after hours									
4 Satisfactory - All of the public spaces can be accessed									
from parking and secured from the rest of the building but not individually									
5 Very satisfactory - Cafeteria, gym, and library can be									
accessed from parking and locked off from rest of									
campus for night/evening use with their own entrance									
N/A Does not apply							<u></u>		
Is there a community room that is a dedicated meeting space outside	1	_			1				
3.3 of school function?	l	2					Comments	0.75	1.9
1 Very unsatisfactory - No dedicated community room								•	
2 Unsatisfactory - Community room but within school									
function, no access after school hours									
3 Average - Community room, moderate size, but need									
some renovations or updates to function well									
4 Satisfactory - Community room, good size /layout, meets needs /functions well									
5 Very Satisfactory - Community room, generous size, nice									
condition, functions appropriately outside of school									
function									
N/A Does not apply								-	
Does the general appearance of the school convey pride for the	ł			4			Comments		
students and community?	L							0.25	1.0
1 Very unsatisfactory - General appearance is poor							Donor bricks at main entry sidewalk.		
2 Unsatisfactory - General appearance is aged but ok									
3 Average - General appearance is good									
4 Satisfactory - General appearance shows pride in campus and student works									
5 Very Unsatisfactory - General appearance shows pride in									
campus and student works and is welcoming to the									
· · · ·									
community									

4.1 Dees the facility have key card access at all major entries? Comments 0.25 2 Unsubsidiatory - 1/4 of major entries Comments 0.25 3 Average - 1/2 of major entries Comments 0.25 4 Satisfactory - 1/4 of major entries Comments 0.25 5 Very satisfactory - 1/4 of major entries Comments 1.00 1 Very unsubsidiatory - 1/4 of major entries 1.00 Comments 1.00 2 Unsubsidiatory - 1/4 of major entries 1.00 Comments 1.00 2 Unsubsidiatory - 1/4 of major entries in major entries 1.00 Comments 1.00 3 Average - 1/4 per y matchfactory - Ne setterin lighting, no secure Immende 1.00 Comments 1.00 3 Average - 1/4 per y and adverter is end printing to inight-use entries and printing to inight use entries and use widels, perimeter is very secure Comments 1.00 1 Very y unsidiatory - 1/4 and and entries are well use and initial to for the nord up initial to	- Security		1	2	3 4	1	5 I	N/A		16.25	
2 Unatificatory - 1/4 of major entries 3 Average - 1/2 of major entries 5 Very soliatocary - All of major entries 10 N/A 12 How adequate is site lighting and security for the comput overal? 12 How adequate is site lighting particles 13 Interesting to the synthese entries and particing in the secure website in the secure website in the secure website in the secure website is site and particing in the secure website and particing is very soliatocary - Signage, parking to the synthese entries and parking to the synthese entris and parking to the synth	4.1 Does the fa	cility have key card access at all major entries?							Comments	0.25	
3 Average - 1/2 of major entries 5 Very satisfactory - 3/4 of major entries 5 Very satisfactory - All of major entries 1 Very satisfactory - No exterior lighting, no secure perimeter 2 How adequate is site lighting and security for the compus overall? 1 Very unsatisfactory - No exterior lighting, no secure perimeter 2 Institute of the compus overall? 1 Very satisfactory - No exterior lighting, no secure perimeter 2 Unstatifactory - No exterior lighting, no secure perimeter is veries and parking tot in sphree entries and parking tot. but peoprometer is veries entries and parking tot. and entries are parking tot major entries and parking tot. and entries are parking tot space, parking tot sc. and entries are parking tot and entries are parking tot. and entries are parking tot and the entries and parking tot. and entries are parking tot and entries are parking tot and entries are parking tot. and entries areacting tot. and entries areacting tot. and entries a		Very unsatisfactory - No entries								•	
4 Satisfactory - All of major entries 5 Very statisfactory - All of major entries NA Does not capply 12 Iwo adequate is site lighting and security for the compus overall? 2 Very unstitifactory - No excircle righting, no secure perimeter 2 Unstatifactory - Lighting is limited to front entry only, apriming for lighting, poor, security is minimal 3 Average - Lighting at all night-use entries and parking lot, and entries and parking lot, security is mediantice. Security is mediantice as the main office located at the school entry office is well-according, security well lot, and entry office is well-according, security well lot, and entry entries and parking lot. gend entry office located at the school entry office located at the school entry office located with a secure wetlabule of them an ordifice located at the school entry minimal supervision of withor Comments 1.00 1 Very unstitifactory - No secure wetlabule, office located at the school entry minimal supervision of withor Comments 1.00 1 Very unstitifactory - Office is well-located with a secure wetlabule, office located with a secure wetlabule of them on ordifor? Comments 1.00 2 Comments 1.00 2 Comments 1.00 3 kerne wetlatificatory - Office is well-located with a secure wetlabule, office located at the school put the accure wetlabule, office located at the scure wetlabule, office locat		Unsatisfactory - 1/4 of major entries									
5 Very statifactory - All of mojor entries 12 How adequate is site lighting and security for the campus overall? Comments 1.00 12 How adequate is site lighting and security for the campus overall? Comments 1.00 13 Kaverage - Lighting at all night-use entries and parking tot lighting at all night-use entries and parking lots, good condition, signage less wilely. The entries in an aparking lots, good condition, signage less wilely. The entries in an aparking lot, but poor configured with a secure but needs updates Comments 1.00 13 Is the main office located of the school entry and configured with a secure but needs updates Comments 1.00 13 Is the main office located of the school entry and configured with a secure but needs updates Comments 1.00 14 Very sublificatory - No secure vestibule, office located school unsupervised Comments 1.00 13 Is the main office located or the subset proves Excerve entificatory - No secure vestibule, office located school unsupervised 1.00 2 1 Very sublificatory - No secure vestibule, office located school unsupervised 2 Comments 1.00 3 Average - Office close to entry, views of front door, but no socure vestibule, office located with secure vestibule, office located school unsupervised 2 Comments <td< td=""><td>3</td><td>Average - 1/2 of major entries</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></td<>	3	Average - 1/2 of major entries									
N/A Does not apply 12 How adequate is site lighting and security for the campus overall? Comments 1.00 1 Very unsatifactory - No secure perimeter 2 Unsatifactory in lighting is limited to front entry only, parking to it lighting poor, security is minimal 3 Average - Ughting at all night-use entries and parking to it, but poor candition. Security is moderate 4 Satisfactory - Lighting is all night-use entries and parking to it, good caddition, signage less visible, perimeter is well secure but needs updates 5 Very satisfactory - Signage, perking lots, and entries are wellit. Visible and easys to use, perimeter is very socure Comments 1.00 13 Is the main corridor? Comments 1.00 14 Bestore vertibule to the main corridor? Comments 1.00 13 score vertibule to the main corridor? Comments 1.00 14 Satisfactory - No secure vertibule, office located for from main entry, minimal supervision of visitors Satisfactory - Office well-located with a secure vertibule to the main corridor? 2 Comments 1.00 14 Intermedia to appropriate secure vertibule to the score vertibule to the appropriate secure vertibule to the appropriate secure vertibule to the appropriate secure vertif features 2 Comm	4	Satisfactory - 3/4 of major entries									
12 How adequate is site lighting and security for the campus overall? Comments 1.00 1 Very unsatisfactory - No exterior lighting, no secure perimeter Comments 1.00 2 Unsatisfactory - Lighting is limited to front entry only, parking lot lighting at all night-use entries and parking lot, but poor condition. security is imined 6 1.00 3 Average - Lighting at all night-use entries and parking lot, good condition. signage less visible, perimeter is well secures but needs updates 5 Very satisfactory - Nue secure to still the secure but needs to use, perimeter is well secures but needs updates 6 Comments 1.00 3 Average - Lighting at all night-use entries and parking lots, and entries are wells. Comments 1.00 4 Satisfactory - No secure vestibule, office located as the school entry and configured with a secure setuper secure vestibule, office located somewhalt far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule 1 Comments 1.00 4 Satisfactory - Office is well-located with secure vestibule, office located somewhalt far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule and paperpoints excertly features 2 Comments 1.00 1 Very satisfactory - Office	5	Very satisfactory - All of major entries									
1 Very unstitistictory - No exterior lighting, no secure perimeter 2 Unsotifactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal 3 Average - Lighting at all night-use entries and parking lot, but poor condition. Security is molimal 4 Satisfactory - Lighting at all night-use entries and parking lots, and entries are well it, visible and easy to use, perimeter is very secure N/A Deen and papy Entries and paper lighting lots, and entries are well it, visible and easy to use, perimeter is very secure well it, visible and easy to use, perimeter is very secure vertibule to the main configured with a secure vertibule to the main configured with a usupervised 1 Very unsatisfactory - No secure vestibule, office located for from main entry, allows visitors a cess to school unsupervised 2 Comments 1.00 2 Unsatisfactory - Office is well-located with a ceure vestibule and all appropriate security features 2 Comments 1.00 1 Very subsidiatory - Office is well-located with a ceure vestibule and all appropriate security features 2 Comments 1.00 1 Very subsidiatory - Office is well-located with a ceure vestibule and their activities who are not in studies? 2 Comments 1.00 3 Average - Office is well-located with a ceure vestibule of their tonsparency in certain locations sut inadequate or musing in otheth cocations sut indications s	N/A	Does not apply	1							1	
Average - Office locate on entry, and and any shorteners Average - Comments Average - Control of a secure vestibule A satisfactory - Lighting at all right-use entries and parking bet main affice located at the school entry and configured with a secure vestibule to the main corridor? Average - Office data to entry, and configured with a secure vestibule on all appropriate security for the located somewhat for from main entry, minimal supervision of visitor visitor A verage - Office is well-located with secure vestibule A satisfactory - Lighting at an entry and configured with a secure vestibule A verage - Office data to entry, views of front door, but no secure vestibule A satisfactory - Office is well-located with a secure vestibule A verage - Office is entry, views of front door, but no secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - No secure vestibule A satisfactory - No secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - No recure vestibule A satisfactory - No recure vestibule A satisfactory - No recure vestibule A satisfactory - Office is sell-located with a secure vestibule A satisfactory - Office vesti-located with a secure vestibule A satisfactory - Office vest-located with a secure vestibule A satisfactory - No recure vestibule A satisfactory - No recure vestibule A satisfactory - Office vest-located with a secure vestibule	4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	1.00	
2 Unsatisfactory - Lighting is limited to front entry only, parking tot lighting poor, security is molerate 3 Average - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates 4 Statisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secure but needs updates 5 Very solifactory - Signage, parking lots, and entries are well lit, visible on deay to use, perimeter is very secure NA Does not apply 1 Very usolifactory - No secure vestibule, office located somewhat for from main entry, minimal supervision of visitors 2 Unsatisfactory - No secure vestibule, office located with a secure vestibule but memory office is veril-located with a secure vestibule but memory - Office veril-located with a secure vestibule but memory - Office veril-located with a secure vestibule but memory - Office veril-located with a secure vestibule and all appropriate security features 14 Very unstatisfactory - No secure vestibule, office located with a secure vestibule and all appropriate security features 2 Comments 1.00 14 betwee enough interior transparency of raculty to passively supervise vestibule and all appropriate security features 2 Comments 1.00 2 14 betwee enough interior transparency of verils 2 Usatisfactory - Adaptive secure veston scool occur veston scool occur veston scool	1										
parking lot lighting poor, security is minimal 3 Average - Ughting at all night-use entries and parking is. but poor condition. Security is imdered 4 Satisfactory - Lighting at all night-use entries and parking lots, singnage lass visible, perimeter is well secured but needs updates 5 5 Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure NA 13 Is the main office located the school entry and configured with a secure vestibule, office located for from main entry, allows visitors access to school unsupervised Comments 1.00 13 Very satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule and all appropriate security features 2 Comments 1.00 14 Is the enough interior transportency for faculty to pasively supervise 2 Comments 1.00 2 14 Is there enough interior transportency of walls 2 Comments 1.00 2 14 Is there enough interior transportency for faculty to pasively supervise 2 Comments 1.00 2 1 Very satisfactory - Additinge	0										
3 Average - Ughting at all night-use entries and parking lat, but poor condition. Security is moderate 4 Statisfactory - Ughting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates 5 Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure NA Does not apply 1 Very usatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised 2 Unsatisfactory - No secure vestibule, office located far from main entry, nilmord supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule secure vestibule Comments 4 Satisfactory - Office is usell-located with a secure vestibule, and papitize security features Image: Comments N/A Does not apply 2 Comments 1.00 1.4 Is there enough interior transparency for faculty to pasively supervise vestibule, and in approprint security features 2 Comments 1.00 2 1.4 Very unsatisfactory - Not to subjoint of the relia controls with a secure vestibule, and in approprint security features 2 Comments 1.00 2 1.4 Is there enough in each or thistalios Statisfactory - Adequate transparency in cer	2										
Int, but poor condition. Security is moderate Int, but poor condition. Security is moderate A Satisfactory - Lighting at all night-use entries and parking lots, agod condition, signage less visible, perimeter is vell secured but needs updates 5 Very satisfactory - Signage, parking lots, and entries are well lift, visible and easy to use, perimeter is very secure N/A Does not apply 13 Is the moin office located at the school entry and configured with a secure vestibule, office located for from main entry, allows visitors access to school unsupervised Comments 1.00 1 Very unstatisfactory - No secure vestibule, office located somewhat for from main entry, minimal supervision of visitors Satisfactory - Office is well-located with a secure vestibule and all appropriate security features 3 Average - Office close to entry, views of front door, but no secure vestibule and all appropriate security features 2 Comments 1.00 2 14 Is there enough interior transparency for faculty to passively supervise 2 Comments 1.00 2 14 Is there enough interior transparency for faculty to passively supervise 2 Comments 1.00 2 14 Is there enough interior transparency for faculty to passively supervise in certain locations but inadequate or missing in other locations of school 1 Very unstificatory - No trans	3										
4 Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is vell secured but needs updates 5 Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure Comments 1.00 13 ket main office located at the school entry and configured with a secure vestibule to the main corridor? Comments 1.00 2 Unsatisfactory - No secure vestibule, office located for from main entry, allows visitors access to school unsupervised Satisfactory - No secure vestibule, office located somewhat for from main entry, minimal supervision of visitors Satisfactory - Office close to entry, views of front door, but no secure vestibule No 3 Average - Office close to entry, views of front door, but no secure vestibule Satisfactory - Office is well-located with a secure vestibule Comments 1.00 4 Satisfactory - Office vestibule Satisfactory - Office well-located with a secure vestibule 2 Comments 1.00 4 Satisfactory - Office well-located with a secure vestibule 2 Comments 1.00 2 14 Is there enough interior transparency for faculty to passively supervise 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls Satisfactory - No transparency of walls Typical doo	Ū										
parking lots, good condition, signage less visible, perimeter is well secured but needs updates Secure vestivel secured but needs updates Very satisfactory - Sing age, parking lots, and entries are well itt, visible and easy to use, perimeter is very secure Is the main office located at the school entry and configured with a secure vestibule to the main corridor? I Very unsatisfactory - No secure vestibule, office located for from main entry, allows visitors access to school unsupervised 2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule, but needs updates 5 Very satisfactory - Office well-located with a secure vestibule, and all oppropriate security features NA Does not apply 4 Is the enough interior transparency for faculty to passively supervise vestibule and all appropriate security features NA Does not apply 1 Very unsatisfactory - No transparency of walls 2 Unsatisfactory - No transparency of walls 2 Unsatisfactory - No transparency of walls 2 Unsatisfactory - No transparency of school 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school 3 Average - Good transparency in certain locations but inadequate or missing in other locations but inadequate transparency throughout the school 5 Very satisfactory - Located transparency throughout the school 5 Very satisfactory - Locations of school	Λ										
is the main office located out needs updates 2 Comments 1.00 1 Very satisfactory - No secure vestibule, office located for from main entry, allows visitors access to school unsupervised 1.00 1.00 2 Unsuffice close to entry, views of front door, but no secure vestibule, office located with a secure vestibule to the main entry, allows visitors access to school unsupervised 2 Comments 1.00 3 Average - Office close to entry, views of front door, but no secure vestibule, office located with a secure vestibule, and all appropriate security features 5 Very satisfactory - Office is well-located with a secure vestibule, but needs updates 4 Satisfactory - Office well-located with secure vestibule, but needs updates 2 Image: Comments 1.00 2 14 Is there enough interior transporency for faculty to passively supervise learners and their activities who are not in studios? 2 Image: Comments 1.00 2 1 Very unsatisfactory - Na transporency of walls 2 Image: Comments 1.00 2 14 Is there enough interior transporency of needin locations but inadequate or missing in other locations of school 1 1.00 2 3 Average - Good transporency in certain locations but inadequate or missing in other locations of school 1 1.00	4	, , , , , , , , , , , , , , , , , , , ,									
5 Very satisfactory - Signage, parking lots, and entries are well it, visible and easy to use, perimeter is very secure N/A Dees not apply 1.3 Is the moin office located at the school entry and configured with a secure vestibule to the main corridor? 1.3 Is the moin office located at the school entry and configured with a secure vestibule to the main entry, allows visitors access to school unsupervised Comments 1.00 2 Unsatisfactory - No secure vestibule, office located far from main entry, minimal supervision of visitors Satisfactory - No secure vestibule, office located with a secure vestibule, but needs updates Very unsatisfactory - Office close to entry, views of front door, but no secure vestibule, but needs updates Very satisfactory - Office is well-located with a secure vestibule, and all appropriate security features N/A Dees not apply 2 Comments 1.00 14 Is there enough interior transparency for faculty to passively supervise vestibule and all appropriate security features 2 Comments 1.00 2 1 Very unsatisfactory - N transparency of walls Implications of studios are half glass, but many are covered. 1.00 2 1 Very unsatisfactory - Strasparency throughout the school 1 Very satisfactory - Na transparency in certain locations 3 Average - Good transparency in certain locations 1.00 <td></td>											
Well lit, visible and easy to use, perimeter is very secure N/A Dees not apply Comments 1.00 13 Is the main office located at the school entry and configured with a secure vestibule to the main entry, allow visitors access to school unsupervised Comments 1.00 2 Unsatisfactory - No secure vestibule, office located symmetry in an entry, allow visitors access to school unsupervised Statisfactory - No secure vestibule, office located symmetry in an entry, niminal supervision of visitors Statisfactory - Office is vell-located with a secure vestibule office located with a secure vestibule and all appropriate security features Very satisfactory - Office is well-located with a secure vestibule and all appropriate security features N/A Dees not apply 2 Comments 1.00 14 Is there enough interior transportery for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 14 Is there enough interior transportery of walls 2 Image: Comments 1.00 2 1 Very usatisfactory - No transportery of evalis 2 Image: Comments 1.00 2 14 Is there enough interior transportery in certain locations but inadequate armspring in other locations of school Typical doors of studios are half glass, but many are covered. 1.00 <td>5</td> <td></td>	5										
N/A Does not apply 13 Is the main office located at the school entry and configured with a secure vestibule to the main corridor? Comments 1.00 13 Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised 2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule, but needs updates 5 Very satisfactory - Office is well-located with secure vestibule, but needs updates 2 Comments 1.00 2 14 Is there enough interior transparency for faculty to passively supervise 2 Comments 1.00 2 14 Is there enough interior transparency of mathing transparency of walls 2 Comments 1.00 2 1 Very unsatisfactory - imited transparency in certain locations distactory - imited transparency in certain locations distons of school 2 Comments 1.00 2 1 Very unsatisfactory - imited transparency in certain locations distons of school 2 Comments 1.00 2 1 Very unsatisfactory - imited transparency in certain locations distons of school 3 Average - Good transparency in certain locations distoned inadequate or missing in other											
1-3 secure vestibule to the main corridor? 1.00 1 Very unsatisfactory - No secure vestibule, office located far form main entry, allows visitors access to school unsupervised 1.00 2 Unsatisfactory - No secure vestibule, office located somewhat far form main entry, minimal supervision of visitors 1.00 3 Average - Office close to entry, views of front door, but no secure vestibule, but needs updates 1.00 4 Satisfactory - Office is well-located with a secure vestibule and all appropriate security features 1.00 N/A Does not apply 2 Comments 1.00 1 Very unsitifactory - No transparency for faculty to passively supervise vestibule and bit activities who are not in studios? 2 Comments 1.00 1.4 Is there enough interior transparency for faculty to passively supervise vestibule and bit activities who are not in studios? 2 0 Comments 1.00 2 1 Very unsitifactory - No transparency of walls 1 Typical doors of studios are half glass, but many are covered. 1.00 2 1 Very sutsifactory - Limited transparency throughout the school 5 Very sutsifactory - No transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 1.00	N/A							L			
secure vestibule to the main corridor? 1 Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised 1.00 2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors 1 3 Average - Office close to entry, views of front door, but no secure vestibule 1 Satisfactory - Office is well-located with a secure vestibule, but needs updates 1 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features 2 Comments 1.00 2 IV/A Does not apply 2 Image: Comments 1.00 2 1.00 2 1 Very satisfactory - Imited transparency of walls 2 Image: Comments 1.00 2 1 Very astisfactory - No transparency of walls 2 Image: Comments 1.00 2 1 Very astisfactory - No transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 1.00 2 5 Very satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 4 Satisfactory - Excellent transparency throughout the school <td>ls the main</td> <td>office located at the school entry and configured with a</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>Comments.</td> <td></td> <td></td>	ls the main	office located at the school entry and configured with a							Comments.		
is three enough interior transparency for faculty to passively supervise 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 Statisfactory - No transparency of school 1.00 2 2 Unsatisfactory - Adequate transparency in certain locations but indedequate or missing in other locations of school 1 Typical doors of studios are half glass, but many are covered. 1.00 2	4.3 secure vest	ibule to the main corridor?							Comments	1.00	
unsupervised 2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front door, but no secure vestibule 4 Satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls Typical doors of studios are half glass, but many are covered. 1.00 2 1 Very unsatisfactory - No transparency in certain locations but inadequate or missing in other locations but inadequate or missing in other locations but inadequate or missing in other locations but inadequate transparency throughout the school Typical doors of studios are half glass, but many are covered. 5 Very satisfactory - Excellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school	1	Very unsatisfactory - No secure vestibule, office located									
2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors Satisfactory - Office close to entry, views of front door, but no secure vestibule A verage - Office close to entry, views of front door, but no secure vestibule. but needs updates Satisfactory - Office is well-located with a secure vestibule and all appropriate security features Very satisfactory - Office well-located with secure vestibule and all appropriate security features Satisfactory - Office is well-located with secure vestibule and all appropriate security features Image: Comments in the comments in tudios? Image: Comments in tudios in the cution to ansparency in certain locations but inadequate or missing in other locations but inadequate in transparency throughout the school Typical doors of studios are half glass, but many are covered. 4 Satisfactory - Licellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5		far from main entry, allows visitors access to school									
somewhat far from main entry, minimal supervision of visitors 3 Average - Office close to entry, views of front doar, but no secure vestibule 4 Satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply 1.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 1 Very unsatisfactory - Ininited transparency of walls 2 Unsatisfactory - Ininited transparency of walls 2 Unsatisfactory - Limited transparency in certain locations but inadequate or missing in other locations but inadequate or missing in other locations of school 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school		•									
visitors visitors 3 Average - Office close to entry, views of front door, but no secure vestibule 4 Satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply 1.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls Typical doors of studios are half glass, but many are covered. 1.00 2 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 5 5 Very satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5	2										
3 Average - Office close to entry, views of front door, but no secure vestibule 4 Satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features 4 Satisfactory - Office well-located with secure vestibule and all appropriate security features 6 1 N/A Does not apply 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 Typical doors of studios are half glass, but many are covered. 1.00 2 2 Unsatisfactory - Adequate transparency in certain locations 5 Very satisfactory - Kacellent transparency throughout the school 5 Yery satisfactory - Excellent transparency throughout the school 2 0 Comments 1.00 2		<i>,</i> , , , , , , , , , , , , , , , , , ,									
N/A Does not apply 1 Very satisfactory - No transparency of valls 2 Comments 100 2 1 Very unsatisfactory - No transparency of valls Typical doors of studios are half glass, but many are covered. 1 2 1 Statisfactory - Adequate transparency throughout the school 5 Statisfactory - Excellent transparency throughout the school 5	0										
4 Satisfactory - Office is well-located with a secure vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply 1 Very unsatisfactory - No transparency of faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 Inprice doors of studios are half glass, but many are covered. 1.00 2 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 4 4 Satisfactory - Excellent transparency throughout the school 4 5 Very satisfactory - Excellent transparency throughout the school 4 4 4 4 5 4 5 5 4 5 5 4 5 5 4 5	3										
vestibule, but needs updates 5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply 1.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 Typical doors of studios are half glass, but many are covered. 1.00 2 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate ransparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5	Λ										
5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features N/A Does not apply I Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 0 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 0 Comments 1.00 2 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school Typical doors of studios are half glass, but many are covered.	-	,									
vestibule and all appropriate security features N/A Does not apply I.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 I.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 I Very unsatisfactory - No transparency of walls Typical doors of studios are half glass, but many are covered. 1.00 2 I Very unsatisfactory - Limited transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. Image: Coord transparency throughout the school Image: Coord transparency throughout the school Statisfactory - Adequate transparency throughout the school Image: Coord transparency throughout the school I	5	•									
N/A Does not apply 1.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios? 2 Comments 1.00 2 1 Very unsatisfactory - No transparency of walls 2 Image: Typical doors of studios are half glass, but many are covered. 1.00 2 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 5											
1 Very unsatisfactory - No transparency of walls 1.00 2 2 Unsatisfactory - No transparency of walls Typical doors of studios are half glass, but many are covered. 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 4 Satisfactory - Adequate transparency throughout the school Very satisfactory - Excellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school Very satisfactory - Excellent transparency throughout the school	N/A										
1 Very unsatisfactory - No transparency of walls 1.00 2 2 Unsatisfactory - No transparency of walls Typical doors of studios are half glass, but many are covered. 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school Typical doors of studios are half glass, but many are covered. 4 Satisfactory - Adequate transparency throughout the school Very satisfactory - Excellent transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school Very satisfactory - Excellent transparency throughout the school	Is there end	bugh interior transparency for faculty to passively supervise	1			Т	Т				
 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 	4.4 learners an	d their activities who are not in studios?		2					Comments	1.00	2.
 2 Unsatisfactory - Limited transparency in certain locations 3 Average - Good transparency in certain locations but inadequate or missing in other locations of school 4 Satisfactory - Adequate transparency throughout the school 5 Very satisfactory - Excellent transparency throughout the school 	1	Very unsatisfactory - No transparency of walls		· 1					Typical doors of studios are half glass, but many are	covered.	
 Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the school Very satisfactory - Excellent transparency throughout the school 	2	Unsatisfactory - Limited transparency in certain locations									
 Satisfactory - Adequate transparency throughout the school Very satisfactory - Excellent transparency throughout the school 	3										
school 5 Very satisfactory - Excellent transparency throughout the school		inadequate or missing in other locations of school									
5 Very satisfactory - Excellent transparency throughout the school	4	Satisfactory - Adequate transparency throughout the									
school											
	5	, , , , ,									
N/A Does not apply	N1/A							L			
	N/A							L			

02/11/2022 *

5 - Environmental Quality	1	2	3	4	5	N/A	A	25.00	64
5.1 How are acoustics in studios in general?	1						Comments	1.00	1.0
 Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white nois from mechanical system Very satisfactory - Able to hear quiet speaking from across the room N/A Does not apply 							Open corridor layout between studio spaces to attact	hed restrooms.	
5.2 Is the studio artificial lighting adequate quality?			3				Comments	1.00	3.
 Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare N/A Does not apply 	3						Most studios have covers over the light fixtures.		
5.3 Is there access to natural light in studios?					5		Comments	1.00	5.
 Very unsatisfactory - No learning spaces have natur light Unsatisfactory - 1-25% of learning spaces have natu light or windows are too small to let in light Average - 26-50% of learning spaces have natural li Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light N/A Does not apply 	iral ight al						All studios have access to natural light with high wind	lows.	
5.4 Is there access to outside views from learning spaces?			3				Comments	1.00	3.
 Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have N/A Does not apply 	's or						Studios have one window with a series of tall ribbon v views.	windows, with li	imite

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	A		
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply									
6 - 0	Controllabi	lity of Systems	1	2	3	4	5	N/A	A Contraction of the second seco	12.50	76%
6.1	Does the st	udio thermostat allow for individual control?					5			0.50	2.50
	1 5	No Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades							In addition to blinds, some studios have internal light she	lf.	
6.3	N/A What is the	Does not apply quality of lighting controls in the studios?	1		3			1	Comments		
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply	<u> </u>			<u> </u>	<u> </u>	<u> </u>	Studios have 2 switches for alternating rows of lighting.	1.00	3.00

7 - Furniture, F	ixtures & Equipment	1	2	3	4	5	N/A	N	18.75	65%
7.1 What is the	e current condition of the furniture?			3				Comments	0.75	2.2
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply							Inconsistent among studios - some have newer furnit older furniture that is not very flexible.	ture and other	s have
	ty of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.0
1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture							Some studios have a variety of seating options.		
N/A 7.3 How well d	Does not apply loes furniture accommodate rapid reconfiguration of a			3	r					
1 2 3 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply							Comments Some studios are better than others.	1.00	3.0
7.4 Is the furnit	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.0
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs to be active Does not apply							All studios have tables with loose chairs.		

02/11/2022 °

Waste		1	2	3	4	5	N/A	5.00	80
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?				4			Comments 0.50	2.0
1 2 3 4 5	 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. 							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
N/A	Does not apply						1		
of each: gre	afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?				4			Comments 0.50	2.0
1 2 3 4	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria								




Perkins&Will

Austin ISD Educational Suitability Assessment Criteria


Academics - Elementary School

School Name	Walk Attendees:	Date:
Baldwin ES	Carlos Cruz & Anacleto Rojas Jr.	12/15/2020

8 - Academics & Learning		1	2	3	4	5	N//	4	70.00	50%
8.1 Are studios appropriatel	y configured per the ed spec?			3				Comments	1.00	3.0
1 Very unsati	sfactory - Too small, no flexibility, disconnected							Studios are adequately sized around 900 SF. Limited to studios and very limited shared learning spaces.	ansparency to	other
	ory - Too small, only one area for all teaching mited flexibility, disconnected									
teaching m transparen	dequate size, multiple areas for different ethods, adequate flexibility, limited cy and connection to other studios and shared aces, needs updates or renovations to function									
teaching m	y - Good size, multiple areas for different ethods, good flexibility, good transparency and to other studios and shared learning spaces									
different te display are transparen	actory - Generous size, multiple areas for aching methods, excellent flexibility, generous a and visual teaching tools, excellent cy and connection with other studios and ming spaces									
N/A Does not a	oply									
8.2 Do Pre-K and Kinder have restrooms and storage p	ve appropriate support spaces such as er the ed spec?				4			Comments	1.00	4.0
1 Very unsati	sfactory - None provided							Spaces have connected restrooms, but connected corri	dor causes dist	ractior
2 Unsatisfact	ory - Too small, disconnected, poor condition							between rooms.		
	dequate size, average condition, needs renovations to function well									
-	y - Good size, connected, good condition									
5 Very Satisfo condition	actory - Generous size, connected, excellent									
N/A Does not a	oply									



8 - Ac	ademics 8	k Learning (cont.)	1	2	3	4	5	N/A	A		
	Do studios h spec?	ave appropriate support spaces such as storage per the ed			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided								•	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply					1		1		
		arning neighborhoods have small group rooms and open		2					Comments		
	collaboratio									1.00	2.00
	1	Very unsatisfactory - No breakout rooms or open							Only two learning neighborhoods have an open collab	poration space.	No
	2	collaboration spaces are provided Unsatisfactory - Too small or too few, poor condition, no							small breakout rooms.		
	2	flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs some									
		renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	_	acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	N/A	Does not apply									
	,	studios large enough to support project-based learning						1			
		e teaching modalities?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, does not									
		support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									



8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	N N N N N N N N N N N N N N N N N N N		
8.6	Are Maker ed spec?	Spaces and support spaces appropriately configured per the	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected to learning spaces Very Satisfactory - Generous size, excellent condition, connected to learning spaces Does not apply									
8.7	Is there a P	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected Does not apply						-			
8.8	ls there a d	edicated science room and support space?	1						Comments	0.00	0.00
	1 5	No Yes							Recording answer, but doesn't affect overall score.		
8.9		dequate places to display the evidence and artifacts of oth 2D and 3D)?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply									


		& Learning (cont.)	1	2	3	4	5	N/A	<u> </u>		
		uilding provide adequate opportunities for students/teachers		2					Comments		
0.10	to collabore	ate in varying group sizes?		2					commenta	1.00	2.0
	1	Very unsatisfactory - No space to support collaboration in							Only two learning neighborhoods have an open collab	oration space.	No
		various sizes.							small breakout rooms.		
	2	Unsatisfactory - Too small, inflexible, only one option, does									
		not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options									
		to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply	1	1	1	1	1	1			
8.11	Does the bu	ilding provide opportunities for informal interaction?			3				Comments	1.00	3.0
	1	Very unsatisfactory - No space	•						Large front foyer, but lacks furniture to engage inform	al interaction.	
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates or									
		renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
		furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
		layout and furnishings support informal interactions									
	N/A	Does not apply	1	1	1	1	1	1			
		arning neighborhood / building provide adequate	1						Comments		
	opportuniti	es for students to work independently?								1.00	1.0
	I	Very unsatisfactory - No breakout rooms/small study							Only large collaboration spaces in two learning neighb	orhoods.	
	•	spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
	•	disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or									
	4	renovations to function well. Satisfactory - Good size and condition, acoustic privacy,									
	4	variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
	0	acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
		options, connected to rearing neighborhood									

8 - Academics 8	& Learning (cont.)		1						
8.13 Are Special	Education spaces appropriately configured per the ed spec?		3		Comments	1.00	3.00		
1	Very unsatisfactory - Too small, no flexibility, disconnected				Converted typical studios as special education rooms.				
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected				It was not discussed in interview or clear from assessment walk if this was serving as a Life Skills studio. In general, studios are adequately sized but				
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.				support spaces are lacking.	944469, 0204	but		
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces								
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces								
N/A	Does not apply	-		 					
	Education support spaces, such as storage, space for er, appropriately configured per the ed spec?	1			Comments	1.00	1.00		
1	Very unsatisfactory - None provided								
2	Unsatisfactory - Too small, disconnected, poor condition								
3	Neutral - Adequate size, average condition, needs updates or renovations to function well								
4	Satisfactory - Good size, connected, good condition								
5	Very Satisfactory - Generous size, connected, excellent								
N/A	condition								
-	Does not apply								
8 6	ble restrooms and changing rooms readily available to the cation spaces?			5	Comments	1.00	5.00		
1	No				Restrooms lack enough space with the changing table.				
5	Yes								

02/11/2022 °

9	- Visual and Performing Arts			2	3	4	5	5 1	A		15.00	73%
(9.1 Are music s the ed spec					4				Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces										
	2	Unsatisfactory - Too small, poor condition										
	3	Neutral - Adequate size, adequate condition, needs										
		updates or renovations to function well.										
	4	Satisfactory - Good size, good condition										
	5 Very Satisfactory - Generous size, excellent condition											
	N/A	Does not apply										
		and performance storage spaces appropriately configured				Δ				Comments		
	per the ed	spec?				-				Comments	1.00	4.00
	 Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition 											
	3	Neutral - Adequate size, average condition, needs										
		updates or renovations to function well										
	4	Satisfactory - Good size, connected, good condition										
	5	Very Satisfactory - Generous size, connected, excellent condition										
	N/A	Does not apply										
	Are Visual	Arts spaces and storage appropriately configured per the ed			3					Comments		
	spec?				3					Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Two art rooms adjac	ent to each other. One is a dedica	ted art room w	ith the
	2	Unsatisfactory - Too small, poor condition							appropriate configu	ration. The other is a converted stu	idio serving as	an art
	3	Average - Adequate size, adequate condition, needs some							room.			
		renovations or updates to function well										
	4	Satisfactory - Good size, good condition										
	5	Very Satisfactory - Generous size, excellent condition										
	N/A	Does not apply										


10 - PE and Wellness 10.00 80% 2 3 4 5 N/A Does the campus meet the ed spec standard for physical education 10.1 Δ Comments program spaces? 1.00 4.00 Gym is adequately sized and opens to cafeteria through use of operable 1 Very unsatisfactory - Too small, missing program spaces partition. 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.2 Are the physical education storage spaces appropriately configured per the ed spec? 4 Comments 1.00 4.00 Very unsatisfactory - None provided 1 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 11 - Food Services 10.00 80% 2 3 4 5 N/A 1 11.1 Is the Dining Commons appropriately configured per the ed spec? 4 Comments 1.00 4.00 1 Layout allows for evening functions to be held after-hours without access to Very unsatisfactory - Too small, missing program spaces rest of building. It is near entry vestibule, which connects directly to exterior. 2 Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation 3 Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, 4 multiple options for eating space (ex: connection to outdoor eating space) 5 Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) N/A Does not apply Are the Food Services support spaces appropriately configured per the 11.2 Δ Comments ed spec? 1.00 4.00 Very unsatisfactory - None provided 1 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply



12 - Media Res	ources	1	2	3	4	5	N/A	N	30.00	57%
12.1 Is the Libra visitors to t	ry/Media Center easily accessible for the occupants and the school?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition Does not apply									
12.2 How well d	loes the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 2 3 4	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy	1		L						
5 N/A	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply									
12.3 How well d	does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 2 3 4	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and	I	<u>.</u>	<u> </u>		.	<u>,</u>	Mix of furniture to support social interaction.		0.00
5 N/A	furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply									
How well d	Joes the Library/Media Center support collaborative work in ps (4-8 students)?	1						Comments	1.00	1.0
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition	·	·	•					·	

02/11/2022 °

12 - Media Resources - Continued	1	2	3	4	5	N/A			
How well does the Library/Media Center support collaborative work in 12.5			3				Comments		
larger groups (10-25)?			0					1.00	3.00
 Very unsatisfactory - No gathering areas 							Layout of library is large, open space with one distinct	seating area w	vith built-
2 Unsatisfactory - Too small, one common space, limited							in tiered seating. Other areas are surrounded by books	shelves and op	en to
seating, poor condition							rest of library. The library does not have separate brea	ıkout rooms.	
3 Average - Adequate size, one common space, needs									
updates or renovations to function well									
4 Satisfactory - Good size, multiple common spaces with									
seating, good condition									
5 Very Satisfactory - Generous size, multiple commons									
spaces with seating, excellent condition N/A Does not apply									
TWA Does not apply	<u> </u>	1		1	1	1		[
12.6 How well does the Library/Media Center support technology?				4			Comments	1.00	4.00
 Very unsatisfactory - No vis comm tools 									
2 Unsatisfactory - Outdated, poorly functioning, or									
insufficient									
3 Good - Mix of old and new whiteboards/projectors/etc.									
4 Satisfactory - Projectors, marker boards, smart boards in									
most spaces - good condition									
5 Very Satisfactory - Projectors, marker boards, smart									
boards in most spaces - new condition									
N/A Does not apply		-	-		_				
13 - Technology	1	2	3	4	5	N/A		20.00	55%
13.1 How well equipped are the facilities with instructional technology?				4			Comments	1.00	4.00
1 Very unsatisfactory - Limited to no technology present in									
instructional spaces									
2 Unsatisfactory - One type of technology present									
3 Average - Multiple types of technology, smart boards,									
poor condition, limited to only certain areas of school									
4 Satisfactory - Multiple types of technology, smart boards,									
good condition.									
5 Very Satisfactory - Multiple types of technology, smart									
boards, excellent condition N/A Does not apply									
Is there an adequate number of power and data outlets in learning		1	1	1	1	1			
13.2 spaces?		2		1			Comments	1.00	2.00
1 Very unsatisfactory - Outlet configuration does not								1.00	2.00
support digital devices throughout school (1 per wall)									
2 Unsatisfactory - Outlet configuration support digital									
devices only in certain areas of school (2 per wall)									
3 Average - Outlet configuration support digital devices bu									
not enough capacity throughout school (3 per wall)									
4 Satisfactory - Outlet configuration support digital devices									
with adequate coverage and capacity throughout school									
(>3 per wall)									
5 Very Satisfactory - Excellent outlet configuration to									
support digital devices throughout school (>3 per wall)									
N/A Does not apply									



13 -	Technology	(cont.)	1	2	3	4	5	N/A	A		
13.	3 Are there ac	lequate charging locations for devices?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition									
	N/A	Does not apply			1		1				
13.	4 Is there ade	quate AV for presentations spaces – cafeteria and gym?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition					<u>.</u>		Extension cables are needed to connect to projector or	n carts.	
13.	N/A 5 ls there digi	Does not apply al media signage at the reception area?	1			1			Comments	0.00	0.00
	1 2 3 4 5 N/A	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply									

02/11/2022 "

14 -	Administra	tion Spaces	1	2	3	4	5	N/A	A Contract of the second se	20.00	50%
14.1	ls there a re visitors?	ception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint									
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply	-			1	1	1			
14.2	Does the ac	Iministration area feel welcoming?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No welcome space							Small area with minimal seating.		
	2	Unsatisfactory - Too small, poor lighting and transparency,									
	3	limited informal seating, poor condition Average - Adequate size and layout, needs updates or									
	3	renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
		transparency, informal seating provided									
	5	Very Satisfactory - Generous size and layout, plenty of									
		light and transparency, informal seating provided,									
	N1/A	excellent condition									
	N/A	Does not apply baces that require it, does the administration area have	1	1	1	1	1	1	1	[
14.3		coustic privacy?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No acoustic separations							Conversations between offices are clearly understood.		
	2	Unsatisfactory - Acoustic separations do not perform well							acoustic privacy for confidential meetings.		
	3	Average - Some acoustic separations function okay, but									
		portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
	N/A	Does not apply	1	1	1	1	1	1	1		
14.4	Are confere	nce rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Not accessible for public/parent use									
	2	Unsatisfactory - Limited access, no transparency, poor									
		condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
	4	renovations to function well Satisfactory - Good accessibility, good transparency, good									
	4	size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent									
		transparency, generous size, excellent condition									
	N/A	Does not apply									