


FACILITY CONDITION ASSESSMENT

Cunningham ES | February 2022





Executive Summary

Cunningham ES is located at 2200 Berkeley Ave in Austin, Texas. The oldest building is 57 years old (at time of 2020 assessment). It comprises 61,578 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$5,413,164. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Cunningham ES the ten-year need is \$9,212,967.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Cunningham ES facility has a 5-year FCA score of 56.62%.

Summary of Findings


The table below summarizes the condition findings at Cunningham ES

Table 1: Facility Condition by Building

| Number | Building Name | Current Deficiencies | 5-Year Life Cycle Cost | Yrs 6-10 Life Cycle Cost | Total 5 Yr Need (Yr 1-5 + Current Defs) | Total 10 Yr Need (Yr 1-10 + Current Defs) | Replacement Cost | 5-Year FCA |
|--------------|--|-------------------------|---------------------------|-----------------------------|---|---|---------------------|---------------|
| Exterior Sit | te | | | | | | | |
| | Exterior Site | \$1,739,702 | \$430,568 | \$115,952 | \$2,170,270 | \$2,286,222 | \$0 | |
| Permanent | t Building(s) | - | | | • | - | | |
| 113A | Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. | \$3,139,809 | \$2,755,515 | \$285,465 | \$5,895,324 | \$6,180,789 | \$17,028,990 | 65.38% |
| 113B | Stand-Alone Classroom Building | \$533,653 | \$173,666 | \$38,637 | \$707,319 | \$745,956 | \$3,192,608 | 77.85% |
| | Sub Total for Permanent Building(s): | \$3,673,462 | \$2,929,181 | \$324,102 | \$6,602,643 | \$6,926,745 | \$20,221,600 | |
| | Total for Site: | \$5,413,164 | \$3,359,749 | \$440,054 | \$8,772,913 | \$9,212,967 | \$20,221,600 | 56.62% |

M-A-P-P-S ©, Jacobs 2022

Facility Condition Assessment





Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.

M-A-P-P-S ©, Jacobs 2022



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

| | | | Priority | | | | |
|----------------------|-----|-----------|-------------|-------------|-------------|-------------|------------|
| System | 1 | 2 | 3 | 4 | 5 | Total | % of Total |
| Site | \$0 | \$0 | \$0 | \$0 | \$1,739,702 | \$1,739,702 | 32.18 % |
| Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Structural | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Exterior | \$0 | \$396,017 | \$460 | \$4,540 | \$70,769 | \$471,786 | 8.73 % |
| Interior | \$0 | \$0 | \$282,724 | \$1,171,079 | \$194,601 | \$1,648,403 | 30.49 % |
| Mechanical | \$0 | \$0 | \$16,072 | \$2,433 | \$10,773 | \$29,279 | 0.54 % |
| Electrical | \$0 | \$92,563 | \$1,287,744 | \$0 | \$0 | \$1,380,307 | 25.53 % |
| Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Fire and Life Safety | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Specialties | \$0 | \$0 | \$0 | \$130,077 | \$6,303 | \$136,381 | 2.52 % |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Total: | \$0 | \$488,580 | \$1,587,000 | \$1,308,129 | \$2,022,148 | \$5,405,857 | |

The building systems at the site with the most need include:

| Site | - | \$1,739,702 |
|------------|---|-------------|
| Interior | - | \$1,648,403 |
| Electrical | - | \$1,380,307 |



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

| | | Life Cycl | e Capital Renewal Pro | ojections | | |
|----------------------|----------------|----------------|-----------------------|----------------|----------------|-------------|
| System | Year 1 2023 | Year 2 2024 | Year 3 2025 | Year 4 2026 | Year 5 2027 | Total 1-5 |
| Site | \$0 | \$0 | \$0 | \$224,113 | \$206,455 | \$430,568 |
| Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Exterior | \$0 | \$0 | \$0 | \$37,955 | \$0 | \$37,955 |
| Interior | \$0 | \$0 | \$48,868 | \$53,764 | \$0 | \$102,632 |
| Mechanical | \$0 | \$0 | \$32,605 | \$22,749 | \$448,439 | \$503,793 |
| Electrical | \$0 | \$0 | \$0 | \$0 | \$28,852 | \$28,852 |
| Plumbing | \$0 | \$1,798,086 | \$3,184 | \$0 | \$312,946 | \$2,114,216 |
| Fire and Life Safety | \$0 | \$0 | \$0 | \$0 | \$141,733 | \$141,733 |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Specialties | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$0 | \$1,798,086 | \$84,657 | \$338,581 | \$1,138,425 | \$3,359,749 |



Table 3b: Capital Renewal Forecast (Yrs 6-10)

| | | | Life Cycle Capital Renewal Projections | | | | | |
|----------------------|-------------|----------------|--|----------------|----------------|-----------------|------------|-------------|
| System | Total 1-5 | Year 6 2028 | Year 7 2029 | Year 8 2030 | Year 9 2031 | Year 10 2032 | Total 6-10 | Total 1-10 |
| Site | \$430,568 | \$0 | \$0 | \$0 | \$0 | \$4,932 | \$4,932 | \$435,500 |
| Roofing | \$0 | \$0 | \$0 | \$76,102 | \$0 | \$0 | \$76,102 | \$76,102 |
| Exterior | \$37,955 | \$0 | \$4,540 | \$0 | \$0 | \$9,262 | \$13,802 | \$51,757 |
| Interior | \$102,632 | \$0 | \$159,745 | \$32,828 | \$0 | \$162,026 | \$354,599 | \$457,231 |
| Mechanical | \$503,793 | \$0 | \$0 | \$0 | \$0 | \$193,867 | \$193,867 | \$697,660 |
| Electrical | \$28,852 | \$0 | \$0 | \$34,918 | \$0 | \$0 | \$34,918 | \$63,770 |
| Plumbing | \$2,114,216 | \$0 | \$0 | \$0 | \$0 | \$23,200 | \$23,200 | \$2,137,416 |
| Fire and Life Safety | \$141,733 | \$0 | \$0 | \$0 | \$97,773 | \$0 | \$97,773 | \$239,506 |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Specialties | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$3,359,749 | \$0 | \$164,285 | \$143,848 | \$97,773 | \$393,287 | \$799,193 | \$4,158,942 |




Figure 2: Ten Year Capital Renewal Forecast



Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$20,221,600. For planning purposes, the total 5-year need at the Cunningham ES is \$8,772,913 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Cunningham ES facility has a 5-year FCA of 56.62%.



M•A•P•P•S ©, Jacobs 2022



Cunningham ES - Deficiency Summary Site Level Deficiencies

Site

Deficiency Qty UoM Category Priority Repair Cost PROGRAM DEFICIENCIES **ADA Compliance** 800,328 EACH \$1,374,148

Note: SECTION TWO: PROGRAM DEFICIENCIESSite/Exterior ImprovementsEstimated Construction Cost for Site Plan Area C8 122

48\$113.1.2REPORT COST SUMMARY Estimated Construction Cost for Site Plan Area C8,122.48\$ Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division 18,122.48\$ Interior Improvements Estimated Construction Cost for Floor Plan

Estimated Construction Cost for Floor Plan Area 5A & 5B (x2) (Building A)262,583.38\$ Area 4 (Building A)306,738.02\$ Estimated Construction Cost for Floor Plan Area 6 (Building B)113,836.83\$ Estimated Construction Cost for Floor Plan Area 7

(Building A)92,838.01\$ Estimated Construction Cost for Floor Plan Area 8 (Building B)9,367.80\$ Estimated

Construction Cost for Floor Plan Area 9 (Building A)6,841.77\$ Estimated Construction Cost Subtotal for Interior Improvements Total Estimated Construction Cost Subtotal for Program Deficiency Improvements800,328.29 Excluding Division 1792,205.81\$

PUBLIC DEFICIENCIES ADA Compliance 92.025 EACH

SECTION ONE: PUBLIC DEFICIENCIESSite/Exterior Improvements Estimated Construction Cost for Site Plan Area A12,623.54\$

Estimated Construction Cost for Site Plan Area B2,899.46\$ Estimated Construction Cost Subtotal for Site/Exterior Improvements Estimated Construction Cost for Floor Plan Area 1 (Building A)11,227.68\$ Excluding Division 115,523.00\$ Interior Improvements Estimated Construction Cost for Floor Plan Area 2 (Building A)6,191.53\$ Estimated Construction Cost for Floor Plan Area 3

(Building A)59,083.28\$ Estimated Construction Cost Subtotal for Interior Improvements Excluding Division 176,502.49\$

Total Estimated Construction Cost Subtotal for Public Deficiency Improvements92,025.4

TAS ACCESSIBILITY DEFICIENCIES 120.880 EACH \$207.549 2278

Note: SECTION THREE: TAS ACCESSIBILITY DEFICIENCIESInterior Improvements Estimated Construction Cost for Floor Plan Area 10 (Building Estimated Construction Cost for Floor Plan Area 11 (Building B)10,877.06\$ **Estimated Construction Cost**

for Floor Plan Area 12 (Building A)79,783.43\$ Estimated Construction Cost Subtotal for TAS Improvements Excluding Division

Total Estimated Construction Cost Subtotal for TAS Deficiency Improvements120,879.89

Sub Total for System 3 items \$1,739,702

Sub Total for School and Site Level 3 items \$1,739,702

Building: 113A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
|-------------------------------------|-------------------------|--------|------------|----------|-------------|------|
| Metal Exterior Door Replacement | Capital Renewal | 22 | Door | 2 | \$81,554 | 1389 |
| Note: Aged | | | | | | |
| Metal Exterior Door Replacement | Capital Renewal | 4 | Door | 2 | \$14,828 | 1390 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 126 | SF | 2 | \$18,212 | 1383 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 1,512 | SF | 2 | \$218,547 | 1384 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 132 | SF | 2 | \$19,080 | 1385 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 54 | SF | 2 | \$7,805 | 1386 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 200 | SF | 2 | \$28,908 | 1387 |
| Note: Aged | | | | | | |
| Steel Window Replacement | Capital Renewal | 49 | SF | 2 | \$7,083 | 1388 |
| Note: Aged | | | | | | |
| Exterior Painting (Bldg SF) | Capital Renewal | 2,593 | SF | 4 | \$4,540 | 2382 |
| Note: Metal sections | | | | | | |
| Exterior Cleaning | Deferred Maintenance | 12,752 | SF Wall | 5 | \$49,387 | 2452 |
| | Sub Total for System | 10 | items | | \$449,944 | |
| Interior | | | | | | |
| Deficiency | Category | Qty | UoM | Priority | Repair Cost | ID |
| Athletic Sport Flooring Replacement | Capital Renewal | 2,593 | SF | 3 | \$39,780 | 1398 |
| Interior Door Hardware Replacement | Capital Renewal | 103 | Door | 3 | \$152,915 | 2380 |
| Interior Door Replacement | Capital Renewal | 15 | Door | 3 | \$28,134 | 1406 |
| Note: Age | | | | | | |

M-A-P-PS ©, Jacobs 2022







Interior

| interior | 0.1 | 0. | | D: " | D : 0 : | 15 |
|--|-------------------------|--------|---------|---------------|-------------|------|
| Deficiency Interior Deer Replacement | Category | | UoM | Priority 3 | Repair Cost | 107 |
| Interior Door Replacement | Capital Renewal | 33 | Door | 3 | \$61,895 | 1407 |
| Note: Aged | Canital Danawal | 24 442 | C.E. | 4 | \$10E 061 | 1201 |
| Acoustical Ceiling Tile Replacement Note: Aged | Capital Renewal | 31,113 | SF | 4 | \$105,061 | 1391 |
| G . | Capital Panawal | 2 502 | ee. | 4 | ¢22 020 | 1400 |
| Carpet Flooring Replacement Location: Library and Offices | Capital Renewal | 2,593 | SF | 4 | \$32,828 | 1400 |
| · | Capital Panawal | 31,113 | ee. | 4 | ¢120 E62 | 2207 |
| Ceiling Grid Replacement | Capital Renewal | | | | \$129,562 | |
| Ceramic Tile Flooring Replacement Location: Restrooms | Capital Renewal | 1,556 | SF | 4 | \$27,490 | 1401 |
| | Capital Panawal | E 106 | ee. | 4 | \$42.0E2 | 1202 |
| Interior Ceramic Walls Repair or Replacement | Capital Renewal | 5,186 | SF | 4 | \$43,053 | 1393 |
| Note: Age Location: Cafeteria and Restrooms | | | | | | |
| | Capital Danawal | 0.500 | C.E. | 4 | ¢40.700 | 1204 |
| Interior Fiberglass Panels Repair or Replacement | Capital Renewal | 2,593 | Wall | 4 | \$19,728 | 1394 |
| Location: Restrooms, Classroom | | | | | | |
| Metal Interior Door Replacement | Capital Renewal | 32 | Door | 4 | \$92,602 | 1404 |
| Note: Age | • | | | | | |
| Metal Interior Door Replacement | Capital Renewal | 23 | Door | 4 | \$66,558 | 1405 |
| Note: Age | • | | | | . , | |
| Moveable Partition Replacement | Capital Renewal | 800 | SF | 4 | \$129,079 | 1397 |
| | | - | Wall | | *, | |
| Note: Gym | | | | | | |
| Terrazzo Flooring Replacement | Capital Renewal | 519 | SF | 4 | \$17,686 | 1402 |
| Note: Prep for Cafe | | | | | | |
| Toilet Partition Replacement | Capital Renewal | 3 | Stall | 4 | \$6,049 | 1396 |
| Note: Age | | | | | | |
| Vinyl Composition Tile Replacement | Capital Renewal | 43,558 | SF | 4 | \$356,205 | 1403 |
| Location: All areas | | | | | | |
| Exposed Ceiling Repainting | Capital Renewal | 15,000 | SF | 5 | \$34,856 | 1392 |
| Note: Aged | | | | | | |
| Interior Wall Repainting (Bldg SF) | Capital Renewal | 25,928 | SF | 5 | \$116,181 | 3467 |
| | Sub Total for System | 18 | items | | \$1,459,662 | |
| Mechanical | | | | | | |
| Deficiency | Category | Otv | UoM | Priority | Repair Cost | ID |
| Large Diameter Exhausts/Hoods Replacement | Capital Renewal | | Ea. | 3 | \$16,072 | 3469 |
| Ceiling Exhaust Fan Replacement | Capital Renewal | | Ea. | 4 | \$2,433 | |
| Duct Register Replacement | Deferred | | Ea. | 5 | \$3,337 | |
| 2 de Registo Replacomon | Maintenance | Ü | Lu. | Ü | ψ0,007 | 1002 |
| Remove Abandoned Equipment | Deferred | 5 | Ea. | 5 | \$6,197 | 1333 |
| | Maintenance | | | | | |
| Note: Ceiling mounted exposed hot water unit heaters and all associated | · · · - | - | | | | |
| Remove Abandoned Equipment | Deferred Maintenance | 1 | Ea. | 5 | \$1,239 | 1334 |
| Location: Large inline fan in boys restroom | Mantenance | | | | | |
| Location. Large mime ran in boys restroom | Sub Total for System | 5 | items | | \$29,279 | |
| Floatrical | oub rotal for System | 3 | iteilis | | Ψ23,213 | |
| Electrical | | | | | | |
| Deficiency | Category | | UoM | Priority | Repair Cost | ID |
| Distribution Panel Replacement | Capital Renewal | 1 | Ea. | 2 | \$16,905 | 1411 |
| Note: No remaining life | | | | | | |
| Panelboard Replacement | Capital Renewal | 2 | Ea. | 2 | \$10,999 | 1413 |
| Note: No remaining life | | | | | | |
| Panelboard Replacement | Capital Renewal | 1 | Ea. | 2 | \$5,500 | 1414 |
| Note: 250A, No remaining life | | | | | | |
| Panelboard Replacement | Capital Renewal | 4 | Ea. | 2 | \$16,943 | 1415 |
| Note: Unacceptable Manufacturer | | | | | | |
| Panelboard Replacement | Capital Renewal | 1 | Ea. | 2 | \$4,236 | 1416 |
| Note: 125A, Unacceptable Manufacturer | | | | | | |
| | | | | | | |

M=A=P=P=S ©, Jacobs 2022



Electrical Deficiency

| Deficiency | | • | ٠. | | 5 | | |
|---|---|---|---|--------------------------------------|-----------------------------------|---|---------------------------------|
| - | | Category | | UoM | Priority | Repair Cost | ID |
| Panelboard Replace | | Capital Renewal | 1 | Ea. | 2 | \$7,823 | 141 |
| Note: | Unacceptable Manufacturer | 0 " 15 " 1 | | _ | | 40.000 | |
| Panelboard Replace | | Capital Renewal | 1 | Ea. | 2 | \$6,688 | 1418 |
| Note: | No remaining life | 0 "15 | 0 | _ | | 045.040 | |
| Panelboard Replace | | Capital Renewal | 2 | Ea. | 2 | \$15,646 | 1419 |
| Note: | No remaining life | 0 "15 | | _ | • | # 0.000 | 4.40 |
| Canopy Lighting Rep | | Capital Renewal | 4 | Ea. | 3 | \$8,332 | 142 |
| Note: | No remaining life | 0 "15 | _ | _ | • | 04.500 | 4.40 |
| | ilding Lighting Replacement | Capital Renewal | 5 | Ea. | 3 | \$4,509 | 142 |
| Note: | No remaining life | Deferred | E4 0EE | 05 | 0 | CA 507 | 4.40 |
| nterior Power Wiring | g Replacement | Deferred Maintenance | 51,855 | SF | 3 | \$61,587 | 142 |
| Note: | No remaining life | | | | | | |
| ighting Fixtures Re | - | Capital Renewal | 51,855 | SF | 3 | \$950,945 | 142 |
| Note: | No remaining life | · | | | | | |
| _ightning Protection | - | Functional Deficiency | 51,855 | SF | 3 | \$40,494 | 142 |
| Note: | None Installed | • | , | | | . , | |
| | em Replacement, Non-main Building | Deferred Maintenance | 51,855 | SF | 3 | \$36,707 | 142 |
| Note: | No remaining life | Walliterlance | | | | | |
| 14010. | No remaining inc | Sub Total for System | 14 | items | | \$1,187,315 | |
| Technology | | • | | | | | |
| Deficiency | | Category | Qty | UoM | Priority | Repair Cost | ID |
| Public Address Syst | em Head-End Requires Replacement | Functional Deficiency | 1 | Ea. | 3 | \$7,307 | 142 |
| Note: | No remaining life | | | | | | |
| | | Sub Total for System | 1 | items | | \$7,307 | |
| Specialties | | | | | | | |
| Deficiency | | Category | Otv | UoM | Priority | Repair Cost | ID |
| Base Storage Cabin | et Renainting | Deferred | 155 | | 5 T HOTHLY | \$5,255 | |
| Sado Giorago Gasiii | or repairing | Maintenance | 100 | | Ü | ψ0,200 | |
| Note: | Age | | | | | | |
| Upper Storage Cabii | net Renainting | D () | 85 | LF | 5 | \$1,048 | 140 |
| | iot repairting | Deferred | 00 | | U | | |
| | · - | Deferred Maintenance | 00 | | Ü | | |
| Note: | Age | Maintenance | | | Ü | • | |
| | Age | Maintenance Sub Total for System | 2 | items | Ü | \$6,303 | |
| | · - | Maintenance Sub Total for System | 2 | items items | Ū | \$6,303 \$3,139,809 | |
| Sub Total for Build | Age | Maintenance Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. | 2 | | · · | | |
| Sub Total for Build Building: 1 | Age ling 113A - Main building includes Administrat | Maintenance Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. | 2 | | C . | | |
| Sub Total for Build Building: 1 Exterior | Age ling 113A - Main building includes Administrat | Maintenance Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. om Building | 2 50 | items | | \$3,139,809 | ID |
| Sub Total for Build Building: 1 Exterior Deficiency | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Maintenance Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Om Building Category | 2 50 Qty | items UoM | Priority | \$3,139,809 Repair Cost | ID |
| Sub Total for Build Building: 1 Exterior Deficiency | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Maintenance Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. om Building | 2 50 Qty | items | | \$3,139,809 | |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Om Building Category Deferred Maintenance Deferred | 2 50 Qty | UoM Door SF | Priority | \$3,139,809 Repair Cost | 138 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Maintenance | 2 50 Otty 4 5,521 | UoM Door SF Wall | Priority 3 | \$3,139,809 Repair Cost \$460 \$21,382 | 138 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Om Building Category Deferred Maintenance Deferred | 2 50 Otty 4 5,521 | UoM Door SF | Priority 3 | \$3,139,809 Repair Cost \$460 | 138 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning | Age ling 113A - Main building includes Administrat 13B - Stand-Alone Classro | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Om Building Category Deferred Maintenance Deferred Maintenance Sub Total for System | 2 50 Qty 4 5,521 2 | UoM Door SF Wall items | Priority 3 5 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 | 138 245 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning Interior Deficiency | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroe Repainting | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Om Building Category Deferred Maintenance Deferred Maintenance Sub Total for System Category | 2 50 Qty 4 5,521 2 | UoM Door SF Wall items | Priority 3 5 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost | 138 245 ID |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning Interior Deficiency Acoustical Ceiling Ti | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroe Repainting | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Category Category Category | 2 50 Otty 4 5,521 2 Otty 9,236 | UoM Door SF Wall items UoM | Priority 3 5 Priority 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 | 138 245 ID 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning Interior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace | Age ling 113A - Main building includes Administrated 13B - Stand-Alone Classroom Repainting | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Capital Renewal Capital Renewal | 2 50 Otty 4 5,521 2 Otty 9,236 9,236 | UoM Door SF Wall items UoM SF SF | Priority 3 5 Priority 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 | 138 245 ID 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning Interior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace Vinyl Composition Ti | Age ling 113A - Main building includes Administrated 13B - Stand-Alone Classroo Repainting le Replacement le Replacement | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Category Category Category | 2 50 Otty 4 5,521 2 Otty 9,236 | UoM Door SF Wall items UoM SF SF | Priority 3 5 Priority 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 | 138 245 ID 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning nterior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace //inyl Composition Ti Note: | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroo Repainting le Replacement le Replacement Age | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Capital Renewal Capital Renewal Capital Renewal | 2 50 Otty 4 5,521 2 Otty 9,236 9,236 9,236 | UoM Door SF Wall items UoM SF SF | Priority 3 5 Priority 4 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 \$75,529 | 138 245 135 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning nterior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace //inyl Composition Ti Note: | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroo Repainting le Replacement le Replacement Age | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Capital Renewal Capital Renewal | 2 50 Otty 4 5,521 2 Otty 9,236 9,236 | UoM Door SF Wall items UoM SF SF | Priority 3 5 Priority 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 \$75,529 \$43,564 | 138 245 1D 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning nterior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace //inyl Composition Ti Note: | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroo Repainting le Replacement le Replacement Age | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Capital Renewal Capital Renewal Capital Renewal | 2 50 Qty 4 5,521 2 Qty 9,236 9,236 9,722 | UoM Door SF Wall items UoM SF SF | Priority 3 5 Priority 4 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 \$75,529 | 138 245 1D 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning nterior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace //inyl Composition Ti Note: nterior Wall Repaint | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroo Repainting le Replacement le Replacement Age | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal | 2 50 Qty 4 5,521 2 Qty 9,236 9,236 9,722 | UoM Door SF Wall items UoM SF SF SF | Priority 3 5 Priority 4 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 \$75,529 \$43,564 | 138 245 ID 135 135 |
| Sub Total for Build Building: 1 Exterior Deficiency Exterior Metal Door Exterior Cleaning Interior Deficiency Acoustical Ceiling Ti Ceiling Grid Replace Vinyl Composition Ti | Age ling 113A - Main building includes Administrate 13B - Stand-Alone Classroo Repainting le Replacement le Replacement Age | Sub Total for System tion Offices, Classrooms, Cafeteria, & Gym. Deferred Maintenance Deferred Maintenance Sub Total for System Category Category Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal | 2 50 Otty 4 5,521 2 Otty 9,236 9,236 9,236 9,722 4 | UoM Door SF Wall items UoM SF SF SF | Priority 3 5 Priority 4 4 4 | \$3,139,809 Repair Cost \$460 \$21,382 \$21,842 Repair Cost \$31,188 \$38,461 \$75,529 \$43,564 | 138 245 ID 135 |

Note: No remaining life





Austin ISD - Cunningham ES

Electrical

| Deficiency | | | Category | Qty | UoM | Priority | Repair Cost | ID |
|--|-------------------|---------------------------------|-------------------------------|-------|-------|----------|-------------|------|
| Lighting Fixtures Re | placement | | Capital Renewal | 9,722 | SF | 3 | \$178,287 | 1430 |
| Note: | No remaining life | | | | | | | |
| Public Address System Replacement, Non-main Building | | in Building | Deferred Maintenance | 9,722 | SF | 3 | \$6,882 | 1428 |
| Note: | No remaining life | | | | | | | |
| | | | Sub Total for System | 3 | items | | \$192,993 | |
| Specialties | | | | | | | | |
| Deficiency | | | Category | Qty | UoM | Priority | Repair Cost | ID |
| Base Storage Cabin | et Replacement | | Capital Renewal | 80 | LF | 4 | \$44,084 | 1379 |
| Note: | Aged | | | | | | | |
| Location | : Class | | | | | | | |
| Upper Storage Cabi | net Replacement | | Capital Renewal | 80 | LF | 4 | \$85,994 | 1380 |
| Note: | Age | | | | | | | |
| Location | : Class | | | | | | | |
| | | | Sub Total for System | 2 | items | | \$130,077 | |
| | | Sub Total for Building 113B - S | tand-Alone Classroom Building | 11 | items | | \$533,653 | |
| | | | Total for Campus | 64 | items | | \$5,413,164 | |

Repair Cost Remaining Life



Cunningham ES - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

LC Type Description

Site

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|--------------------------------|--------------------------|--------|-------|-------------|----------------|
| Roadway Pavement | Asphalt Driveways | | 12,000 | SF | \$77,165 | 4 |
| Pedestrian Pavement | Sidewalks - Concrete | | 11,000 | SF | \$124,600 | 4 |
| Playfield Areas | ES Playgrounds | | 1 | Ea. | \$22,348 | 4 |
| Fences and Gates | Fencing - Chain Link (4 Ft) | | 1,700 | LF | \$80,235 | 5 |
| Parking Lot Pavement | Asphalt | | 60 | CAR | \$87,048 | 5 |
| Fences and Gates | Fencing - Chain Link (8-10 Ft) | | 500 | LF | \$39,172 | 5 |
| Parking Lot Pavement | Concrete | | 2 | CAR | \$4,932 | 10 |
| | | Sub Total for System | 7 | items | \$435,501 | |
| Roofing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Canopy Roofing | Steel panels | | 1,500 | SF | \$76,102 | 8 |
| | | Sub Total for System | 1 | items | \$76,102 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Parking Lot Lighting | Pole Lighting | | 6 | Ea. | \$34,918 | 8 |
| | | Sub Total for System | 1 | items | \$34,918 | |
| | | Sub Total for Building - | 9 | items | \$546,521 | |

Qty UoM

Building: 113A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description

| Official Decomption | Lo Type Description | | Qty | COIVI | rtopan oost | rtomaning Life |
|---|---|----------------------|--------|---------|-------------|----------------|
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | | 2,593 | SF | \$4,540 | 7 |
| Exterior Wall Veneer | Metal Panel - Bldg SF basis | | 2,593 | SF | \$9,262 | 10 |
| | | Sub Total for System | 2 | items | \$13,802 | |
| Interior | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Wall Coverings | Vinyl/Fabric Wall Covering | | 10,371 | SF | \$48,868 | 3 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | | 25,928 | SF | \$116,181 | 7 |
| Carpeting | Carpet | | 2,593 | SF | \$32,828 | 8 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | | 31,113 | SF | \$105,061 | 10 |
| Wall Coverings | FRP Wall Finish | | 2,593 | SF Wall | \$19,728 | 10 |
| Compartments and Cubicles | Toilet Partitions | | 3 | Stall | \$6,049 | 10 |
| | | Sub Total for System | 6 | items | \$328,716 | |
| Mechanical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Decentralized Cooling | Fan Coil - D/X Only (3 Ton) | | 7 | Ea. | \$14,477 | 3 |
| Decentralized Cooling | Window Units | | 1 | Ea. | \$3,085 | 3 |
| Air Distribution | Make-up Air Unit | | 1 | Ea. | \$8,888 | 5 |
| HVAC Air Distribution | Ductwork (Bldg.SF) | | 51,855 | SF | \$410,300 | 5 |
| Exhaust Air | Roof Exhaust Fan - Small | | 3 | Ea. | \$5,879 | 5 |
| Exhaust Air | Roof Exhaust Fan - Large | | 1 | Ea. | \$8,036 | 5 |
| Exhaust Air | Interior Ceiling Exhaust Fan | | 15 | Ea. | \$7,300 | 5 |
| Heating System Supplementary Components | Controls - DDC (Bldg.SF) | | 51,855 | SF | \$139,865 | 10 |
| Decentralized Cooling | Condenser - Outside Air Cooled (3 Tons) | | 6 | Ea. | \$38,535 | 10 |
| Decentralized Cooling | Condenser - Outside Air Cooled (3 Tons) | | 1 | Ea. | \$6,423 | 10 |
| Facility Hydronic Distribution | Pump - 1HP or Less (Ea.) | | 1 | Ea. | \$4,313 | 10 |
| Exhaust Air | Wall Exhaust Fan | | 1 | Ea. | \$4,731 | 10 |
| | | Sub Total for System | 12 | items | \$651,833 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Electrical Service | Transformer (75 KVA) | | 1 | Ea. | \$7,287 | 5 |







Electrical

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|---|--|---------------------------|--------|---------|----------------------------|----------------|
| Power Distribution | Panelboard - 120/240 225A | - | | Ea. | \$7,823 | 5 |
| | | Sub Total for System | | items | \$15,111 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Otv | UoM | Popair Cost | Remaining Life |
| Domestic Water Equipment | Gas Piping System (BldgSF) | | 51,855 | | \$1,798,086 | 2 |
| | : Principal has complained of many gas leaks in the bi | uilding | 31,033 | 31 | \$1,790,000 | 2 |
| Plumbing Fixtures | Sink - Service / Mop Sink | uliding | 1 | Ea. | \$3,184 | 3 |
| Domestic Water Equipment | Water Heater - Electric - 20 gallon | | | Ea. | \$1,587 | 5 |
| Domestic Water Equipment | Water Heater - Gas - 200 Gallon | | | Ea. | \$27,583 | 5 |
| Domestic Water Piping | Domestic Water Piping System (Bldg.SF) | | 51,855 | | \$186,353 | 5 |
| Sanitary Sewerage Piping | Sanitary Sewer Piping | | 51,855 | | \$57,571 | 5 |
| Plumbing Fixtures | Restroom Lavatory | | | Ea. | \$5,433 | 5 |
| Plumbing Fixtures | Toilets | | | Ea. | \$30,356 | 5 |
| Plumbing Fixtures | Urinals | | | Ea. | \$4,063 | 5 |
| numbing rixtures | Officials | Sub Total for System | | items | \$2,114,214 | 3 |
| | | Sub rotal for System | 3 | iteilis | φ2,114,214 | |
| Fire and Life Safety | | | | | | |
| Iniformat Description | LC Type Description | | | UoM | Repair Cost | Remaining Life |
| Security System Component | Security Alarm System | | 51,855 | SF | \$119,356 | 5 |
| ire Detection and Alarm | Fire Alarm | | 51,855 | SF | \$82,336 | 9 |
| | | Sub Total for System | 2 | items | \$201,692 | |
| Sub Total for Building 113A - N | lain building includes Administration Offices, Class | srooms, Cafeteria, & Gym. | 33 | items | \$3,325,367 | |
| Building: 113B - Stand-A | lone Classroom Building | | | | | |
| banang. 1105 otana / | nono olacorochi Bananig | | | | | |
| Exterior | | | | | | |
| Jniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| exterior Operating Windows | Steel - Windows per SF | | 160 | SF | \$23,127 | 4 |
| Exterior Entrance Doors | Steel - Insulated and Painted | | 4 | Door | \$14,828 | 4 |
| | | Sub Total for System | 2 | items | \$37,955 | |
| Interior | | | | | | |
| Jniformat Description | LC Type Description | | Otv | UoM | Repair Cost | Remaining Life |
| nterior Door Supplementary Components | Door Hardware | | | Door | \$23,754 | 4 |
| nterior Swinging Doors | Wooden Door | | | Door | \$9,378 | 4 |
| Interior Swinging Doors | Wooden Door | | | Door | \$20,632 | 4 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | | 9,722 | | \$43,564 | 7 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | | 9,236 | | \$31,188 | 10 |
| Acoustical Suspended Cellings | Cellings - Acoustical Tiles | Sub Total for System | | items | \$128,515 | 10 |
| M 1, 1 | | oub rotal for dystem | J | items | ψ120,513 | |
| Mechanical | | | | | | |
| Iniformat Description | LC Type Description | 1 | Qty | UoM | Repair Cost | Remaining Life |
| Heating System Supplementary Components | Controls - Electronic (Bldg.SF) | | 9,722 | SF | \$15,043 | 3 |
| Decentralized Cooling | Fan Coil - D/X Only (3 Ton) | | 11 | Ea. | \$22,749 | 4 |
| Exhaust Air | Roof Exhaust Fan - Large | | | Ea. | | 5 |
| _Ariaust All | NOOI EXHAUSI FAH - LAIYE | Sub Total for System | | items | \$8,036 \$45,829 | υ |
| Classical | | ous rotal for System | 3 | neilla | φ45,029 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Electrical Service | Transformer (45 KVA) | | 1 | Ea. | \$5,919 | 5 |
| Power Distribution | Panelboard - 120/240 225A | | 1 | Ea. | \$7,823 | 5 |
| | | Sub Total for System | 2 | items | \$13,742 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Domestic Water Equipment | Water Heater - Electric - 40 gallon | | | Ea. | \$2,684 | 10 |
| Plumbing Fixtures | Classroom Lavatory | | | Ea. | \$20,516 | 10 |
| 3 | | Sub Total for System | | items | \$23,200 | - |
| Fire and Life Safety | | cas . cas for cycloni | - | | \$25,200 | |
| Fire and Life Safety | | | | | _ | _ |
| Iniformat Description | LC Type Description | | | UoM | | Remaining Life |
| Security System Component | Security Alarm System | | 9,722 | SF | \$22,377 | 5 |

M*A*P*P*S ©, Jacobs 2022





Austin ISD - Cunningham ES

Fire and Life Safety

| Uniformat Description | LC Type Description | Qty UoM | Repair Cost | Remaining Life |
|--------------------------|--|----------|-------------|----------------|
| Fire Detection and Alarm | Fire Alarm | 9,722 SF | \$15,437 | 9 |
| | Sub Total for System | 2 items | \$37,814 | |
| | Sub Total for Building 113B - Stand-Alone Classroom Building | 16 items | \$287,054 | |
| | Total for: Cunningham ES | 58 items | \$4.158.942 | |

M•A•P•P•S ©, Jacobs 2022 15



Supporting Photos

General Site Photos



Marquee



Aged Exterior windows




Damaged vinyl composition tile flooring



Exposed interior wall



Damaged interior walls



Broken threshold

M•A•P•P•S ©, Jacobs 2022 16