

FACILITY CONDITION ASSESSMENT

Joslin ES | February 2022





Executive Summary

Joslin ES is located at 4500 Menchaca Rd in Austin, Texas. The oldest building is 66 years old (at time of 2020 assessment). It comprises 45,649 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$4,851,684. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Joslin ES the ten-year need is \$9,655,621.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Joslin ES facility has a 5-year FCA score of 48.47%.

Summary of Findings

The table below summarizes the condition findings at Joslin ES

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Si	ite							
	Exterior Site	\$1,077,252	\$11,639	\$271,256	\$1,088,891	\$1,360,147	\$0	
Permanen	t Building(s)							
198A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$3,191,389	\$1,864,119	\$1,342,796	\$5,055,508	\$6,398,304	\$10,300,610	50.92%
198B	Stand-Alone Classroom Building	\$422,636	\$943,745	\$295,257	\$1,366,381	\$1,661,638	\$3,618,858	62.24%
198C	Stand-Alone Library	\$160,407	\$53,508	\$21,617	\$213,915	\$235,532	\$1,071,208	80.03%
	Sub Total for Permanent Building(s):	\$3,774,432	\$2,861,372	\$1,659,670	\$6,635,804	\$8,295,474	\$14,990,676	
	Total for Site:	\$4,851,684	\$2,873,011	\$1,930,926	\$7,724,695	\$9,655,621	\$14,990,676	48.47%



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Austin ISD - Joslin ES

The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)


			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$0	\$105,575	\$971,677	\$1,077,252	22.20 %
Roofing	\$1,290,622	\$0	\$0	\$0	\$0	\$1,290,622	26.60 %
Structural	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Exterior	\$0	\$101,732	\$52,336	\$0	\$0	\$154,068	3.18 %
Interior	\$0	\$0	\$53,372	\$59,304	\$52,999	\$165,676	3.41 %
Mechanical	\$0	\$1,334,242	\$0	\$70,635	\$0	\$1,404,877	28.96 %
Electrical	\$0	\$23,657	\$59,820	\$0	\$0	\$83,477	1.72 %
Plumbing	\$0	\$4,819	\$133,256	\$65,380	\$0	\$203,455	4.19 %
Fire and Life Safety	\$384,239	\$0	\$0	\$0	\$0	\$384,239	7.92 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$88,019	\$0	\$88,019	1.81 %
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Total:	\$1,674,861	\$1,464,450	\$298,785	\$388,912	\$1,024,676	\$4,851,684	

The building systems at the site with the most need include:

Mechanical	-	\$1,404,877
Roofing	-	\$1,290,622
Site	-	\$1,077,252



Austin ISD - Joslin ES



The chart below represents the building systems and associated deficiency costs.

Figure 1: System Deficiencies



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

		Life Cyc	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$0	\$0	\$0	\$0
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$366,721	\$366,721
Interior	\$0	\$0	\$0	\$0	\$906,050	\$906,050
Mechanical	\$0	\$481,089	\$364,883	\$0	\$291,059	\$1,137,031
Electrical	\$0	\$0	\$5,500	\$11,639	\$43,482	\$60,621
Plumbing	\$0	\$0	\$8,997	\$0	\$182,346	\$191,343
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$211,245	\$211,245
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$481,089	\$379,380	\$11,639	\$2,000,903	\$2,873,011

Table 3a: Capital Renewal Forecast (Yrs 1-5)



Austin ISD - Joslin ES

Table 3b: Capital Renewal Forecast (Yrs 6-10)

		Life Cycle Capital Renewal Projections						
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$0	\$0	\$0	\$0	\$0	\$271,256	\$271,256	\$271,256
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$366,721	\$0	\$0	\$44,289	\$0	\$159,289	\$203,578	\$570,299
Interior	\$906,050	\$0	\$48,426	\$35,107	\$0	\$59,717	\$143,250	\$1,049,300
Mechanical	\$1,137,031	\$0	\$0	\$371,121	\$0	\$242,553	\$613,674	\$1,750,705
Electrical	\$60,621	\$0	\$0	\$0	\$0	\$800,229	\$800,229	\$860,850
Plumbing	\$191,343	\$0	\$0	\$0	\$0	\$130,986	\$130,986	\$322,329
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$211,245	\$0	\$0	\$0	\$0	\$0	\$0	\$211,245
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$2,873,011	\$0	\$48,426	\$450,517	\$0	\$1,664,030	\$2,162,973	\$5,035,984




Figure 2: Ten Year Capital Renewal Forecast



The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$14,990,676. For planning purposes, the total 5-year need at the Joslin ES is \$7,724,695 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Joslin ES facility has a 5-year FCA of 48.47%.





Joslin ES - Deficiency Summary

Site Level Deficiencies

Site

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID	
Concrete Paving Re	placement	Capital Renewal	18	CAR	4	\$44,387	1649	
Fencing Replacement	nt (8' - 10' high Chain Link Fence)	Capital Renewal	781	LF	4	\$61,187	1648	
PUBLIC DEFICIENC	IES	ADA Compliance	155,162	EACH	5	\$266,410	1645	
Note:	Site/Exterior Improvements Estimated Construction Cost for Site Plan Area A \$8,472.24 Estimated Construction Cost Subtotal for Site/Exterior Improvements Estimated Construction Cost for Floor Plan Area 1 - Building A \$8 Estimated Construction Cost for Floor Plan Area 2 - Building A \$5 Estimated Construction Cost for Floor Plan Area 3 - Building A \$5 Estimated Construction Cost Subtotal for Interior Improvements E Total Estimated Construction Cost Subtotal for Public Deficiency I	4,964.32 ,940.40 55,785.85 xcluding Division 1 \$ 146,69						
Location	AISD ADA Report							
TAS ACCESSIBILIT	Y DEFICIENCIES	ADA Compliance	353,480	EACH	5	\$606,918	1646	
Note:	Note: Site/Exterior Improvements Estimated Construction Cost for Site Plan Area B \$ 9,449.66 Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division 1 \$ 9,449.66 Interior Improvements Estimated Construction Cost for Floor Plan Area 4 - Building A \$ 139,541.88 Estimated Construction Cost for Floor Plan Area 5 - Building A \$ 100,580.58 Estimated Construction Cost for Floor Plan Area 6 - Building A \$ 48,507.77 Estimated Construction Cost for Floor Plan Area 7 - Building A \$ 23,2079.08 Estimated Construction Cost for Floor Plan Area 8 - Building A \$ 23,321.26 Estimated Construction Cost Subtotal for Interior Improvements Excluding Division 1 \$ 344,030.57 Total Estimated Construction Cost Subtotal for Interior Improvements \$ 353,480.23							
Location	: AISD ADA Report							
TAS ACCESSIBILIT	Y DEFICIENCIES	ADA Compliance	57,280	EACH	5	\$98,349	1647	
Note: Site/Exterior Improvements Estimated Construction Cost for Site Plan Area C \$ 8,713.44 Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division 1 \$ 8,713.44 Interior Improvements Estimated Construction Cost for Floor Plan Area 9 - Building A \$ 43,659.48 Estimated Construction Cost for Floor Plan Area 10 - Building C \$ 4,907.52 Estimated Construction Cost Subtotal for TAS Improvements Excluding Division 1 \$ 48,567.00 Total Estimated Construction Cost Subtotal for TAS Deficiency Improvements \$57,280.44								
Location	: ASID ADA Report							
		Sub Total for System	5	items		\$1,077,252		
	Sub Total	for School and Site Level	5	items		\$1,077,252		

Building: 198A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Roofing

-							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
AISD ROOFING P2		Capital Renewal	441,988	EACH	1	\$441,978	1804
AISD ROOFING P3		Capital Renewal	111,975	EACH	1	\$111,973	1805
AISD ROOFING P4		Capital Renewal	736,687	EACH	1	\$736,671	1806
		Sub Total for System	3	items		\$1,290,622	
Exterior							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Aluminum Window I	Replacement	Capital Renewal	576	SF	2	\$57,443	1681
Wood Exterior Door	Replacement	Capital Renewal	14	Door	2	\$44,289	1650
Note:	Classrooms with exterior doors do not close and lock properly.						
Location	: Thoughout, specialy 202, 206, and 204, 100 hallway and 300 hallw	vay.					
Caulking Replacement	ent	Deferred Maintenance	2,790	LF	3	\$21,070	1185
Note:	Recaulk windows - 155 @ 6x3						
Caulking Replacem	ent	Deferred Maintenance	420	LF	3	\$3,172	1186
Noto	Boogulk windows 11 @ 10v2						

Note: Recaulk windows - 14 @ 10x3



Austin ISD - Joslin ES

Exterior

Exterior						
Deficiency	Category		UoM	Priority	Repair Cost	ID
Caulking Replacement	Deferred Maintenance	264	LF	3	\$1,994	1187
Note: Recaulk windows - 44 @ 3x2						
Caulking Replacement	Deferred Maintenance	576	LF	3	\$4,350	1188
Note: Recaulk windows - 48 @ 4x3	Sub Total for System	6	items		\$132,318	
Interior		·			<i>↓,</i>	
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Toilet Partition Replacement	Capital Renewal	12	Stall	4	\$24,198	1684
Interior Ceiling Repainting	Deferred Maintenance	2,196	SF	5	\$4,573	1682
Interior Wall Repainting (Bldg SF)	Capital Renewal	3,137	SF	5	\$14,057	1683
	Sub Total for System	3	items		\$42,828	
Mechanical						
Deficiency	Category		UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal		Ea.	2	\$6,423	1685
Air Cooled Condenser Replacement	Capital Renewal		Ea.	2	\$6,423	1686
Gas Piping Replacement (SF Basis)	Capital Renewal	31,367	-	2	\$1,087,659	1689
HVAC VAV Box Replacement	Capital Renewal	32	Ea.	2	\$123,963	1651
Note: Does not control the temperatures. Huge issues.		04 007	05		\$40 500	4050
Existing Controls Are Obsolete	Capital Renewal	31,367	SF	4	\$48,536	1652
Note: Does not control the temperatures. Huge issues.	Sub Total for System	5	items		\$1,273,003	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$1,459	1193
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$2,782	1532
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$1,459	1533
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$10,999	1534
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$5,500	1535
	Sub Total for System	5	items		\$22,198	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Water Heater Replacement	Capital Renewal	1	Ea.	2	\$2,135	1687
Water Heater Replacement	Capital Renewal	1	Ea.	2	\$2,684	1688
Toilet Replacement	Capital Renewal	20	Ea.	3	\$101,188	1691
Urinal Replacement	Capital Renewal	3	Ea.	3	\$4,063	1692
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal		Ea.	4	\$40,744	1690
Fire and Life Safety	Sub Total for System	5	items		\$150,814	
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID
Fire Alarm Replacement	Capital Renewal	31,367		1	\$49,805	1693
Install Fire Sprinklers	Functional Deficiency	31,367		1	\$229,801	1190
Note: no system in place	· · · · · · · · · · · · · · · · · · ·	,				
	Sub Total for System	2	items		\$279,606	
Sub Total for Building 198A - Main building includes Administration Offices,	-		items		\$3,191,389	
Building: 198B - Stand-Alone Classroom Bui	lding					
Exterior	-					
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Caulking Replacement	Deferred	2,880		3	\$21,750	1189

		Sub Total for System	1 items		\$21,750	
Not	e: Recaulk windows - 480 @ 3x2					
Caulking Repla	acement	Deferred Maintenance	2,880 LF	3	\$21,750	1189
Deliciency		Calegory	Qty Uulvi	FIIOIIty	Repair Cost	U



Austin ISD - Joslin ES

Interior

Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal	17	Door	3	\$25,238	1695
Interior Door Replacement	Capital Renewal	15	Door	3	\$28,134	1694
Interior Wall Repainting (Bldg SF)	Capital Renewal	4,408	SF	5	\$19,752	1655
	Sub Total for System	3	items		\$73,124	
Mechanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fan Coil Unit Replacement	Capital Renewal	,	Ea.	2	\$39,400	1438
Note: Look to be original equipment; past life cycle						
Location: Classroom FCUs						
Fan Coil Unit Replacement	Capital Renewal	1	Ea.	2	\$1,970	1439
Note: Looks to be original equipment; past life cycle						
Location: hallway FCU						
HVAC VAV Box Replacement	Capital Renewal	12	Ea.	2	\$46,486	1654
Existing Controls Are Obsolete	Capital Renewal	11,020	SF	4	\$17,052	1653
5	Sub Total for System		items		\$104,908	
Electrical					· · ,- · ·	
	Ontonio	01	11-14	Duiauitu	Danain Caat	10
Deficiency	Category		UoM	Priority	Repair Cost	ID
Panelboard Replacement	Capital Renewal		Ea.	2	\$1,459	1194
	Sub Total for System	1	items		\$1,459	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Toilet Replacement	Capital Renewal	5	Ea.	3	\$25,297	1699
Urinal Replacement	Capital Renewal	2	Ea.	3	\$2,708	1700
Custodial Mop Or Service Sink Replacement	Capital Renewal	1	Ea.	4	\$796	1698
Replace classroom lavatory	Capital Renewal	4	Ea.	4	\$10,258	1696
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal	5	Ea.	4	\$13,581	1697
	Sub Total for System	5	items		\$52,641	
Fire and Life Safety						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	Functional Deficiency	11,020	SF	1	\$80,735	1191
Note: no sprinkler system in place						
	Sub Total for System	1	items		\$80,735	
Specialties	-					
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Replace Cabinetry In Classes/Labs		,	Room	4		
Replace Cabinetry in Classes/Labs	Capital Renewal Sub Total for System		items	4	\$88,019 \$88,019	1701
Sub Total for Building 109P	-					
	Stand-Alone Classroom Building	10	items		\$422,636	
Building: 198C - Stand-Alone Library						
Interior						
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID
Carpet Flooring Replacement	Capital Renewal	2,773		4	\$35,107	1659
Interior Wall Repainting (Bldg SF)	Capital Renewal	3,262		5	\$14,617	1658
	Sub Total for System		items	-	\$49,723	
Mechanical		-			÷,. =0	
	0-1-	~		Deite it	Densi O	15
	Category	-	UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal		Ea.	2	\$6,423	1657
HVAC VAV Box Replacement	Capital Renewal		Ea.	2	\$15,495	1656
Existing Controls Are Obsolete	Capital Renewal	3,262		4		1660
	Sub Total for System	3	items		\$26,965	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lighting Fixtures Replacement	Capital Renewal	3 262	SE	3	\$59,820	1661

-			-		
Lighting Fixtures Replacement	Capital Renewal	3,262 SF	3	\$59,820	1661
	Sub Total for System	1 items		\$59,820	

Austin ISD - Joslin ES



Fire and Life Safety

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	;	Functional Deficiency	3,262 SF	1	\$23,898	1192
Note:	no sprinkler system installed					
		Sub Total for System	1 items		\$23,898	
		Sub Total for Building 198C - Stand-Alone Library	7 items		\$160,407	
		Total for Campus	57 items		\$4,851,684	



Joslin ES - Life Cycle Summary Yrs 1-10

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Roadway Pavement	Concrete Driveways		21,729	SF	\$271,256	10
		Sub Total for System	1	items	\$271,256	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Lighting	Pole Lighting		2	Ea.	\$11,639	4
		Sub Total for System	1	items	\$11,639	
		Sub Total for Building -	2	items	\$282,896	

Building: 198A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		10	Door	\$37,070	5
Exterior Entrance Doors	Wooden Door		14	Door	\$44,289	8
Exterior Wall Veneer	Stucco - Bldg SF basis		4,705	SF	\$24,464	10
Exterior Wall Veneer	E.I.F.S Bldg SF basis		3,137	SF	\$97,032	10
		Sub Total for System	4	items	\$202,855	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Stone Facing	CMU Wall		21,957	SF	\$739,710	5
Tile Wall Finish	Ceramic Tile wall		6,273	SF	\$52,077	5
Interior Door Supplementary Components	Door Hardware		46	Door	\$68,292	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		3,137	SF	\$14,057	7
Compartments and Cubicles	Toilet Partitions		12	Stall	\$24,198	10
Resilient Flooring	Rubber Tile Flooring		1,568	SF	\$23,704	10
Suspended Plaster and	Painted ceilings		2,196	SF	\$4,573	10
		Sub Total for System	7	items	\$926,610	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Facility Hydronic Distribution	4-Pipe System		31,367	SF	\$75,898	3
HVAC Air Distribution	Ductwork (Bldg.SF)		31,367	SF	\$248,190	3
Exhaust Air	Roof Exhaust Fan - Small		2	Ea.	\$3,919	3
Exhaust Air	Roof Exhaust Fan - Large		4	Ea.	\$32,145	3
Exhaust Air	Wall Exhaust Fan		1	Ea.	\$4,731	3
Central Cooling	Chiller - Outdoor Air Cooled (100 Tons)		1	Ea.	\$102,018	5
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		1	Ea.	\$6,423	5
Note:	CU-PRINC, roof					
Decentralized Cooling	Condenser - Outside Air Cooled (10 Tons)		1	Ea.	\$13,749	5
Decentralized Cooling	Condenser - Outside Air Cooled (20 ton)		1	Ea.	\$20,946	5
Decentralized Cooling	Ductless Split System (2 Ton)		1	Ea.	\$4,747	5
HVAC Air Distribution	Roof Top Unit - DX Gas (5 Ton)		1	Ea.	\$15,909	5
HVAC Air Distribution	Roof Top Unit - DX Gas (5 Ton)		2	Ea.	\$31,818	8
Note:	RTU-COR2A, COR2B, roof					
HVAC Air Distribution	Roof Top Unit - DX Gas (10 Ton)		14	Ea.	\$339,303	8
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)		31,367	SF	\$48,536	10
HVAC Air Distribution	AHU 10,000 CFM Interior		2	Ea.	\$171,918	10
		Sub Total for System	15	items	\$1,120,249	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 225A		1	Ea.	\$5,500	3
Distributed Systems	Public Address System Head End Unit		1	Ea.	\$7,307	5
Power Distribution	Panelboard - 120/240 100A		2	Ea.	\$8,471	5
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)		31,367	SF	\$22,204	5
Lighting Fixtures	Light Fixtures (Bldg SF)		31,367		\$575,225	10



Austin ISD - Joslin ES

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)		11	Ea.	\$22,913	10
		Sub Total for System	6	items	\$641,619	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 100 Gallon		1	Ea.	\$6,384	3
Plumbing Fixtures	Showers		2	Ea.	\$2,613	3
Sanitary Sewerage Piping	Sanitary Sewer Piping		31,367	SF	\$34,825	5
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		31,367	SF	\$112,724	5
Plumbing Fixtures	Sink - Service / Mop Sink		4	Ea.	\$3,184	5
Plumbing Fixtures	Non-Refrigerated Drinking Fountain		10	Ea.	\$23,838	5
Domestic Water Equipment	Water Heater - Electric - 30 gallon		1	Ea.	\$2,135	10
Domestic Water Equipment	Water Heater - Electric - 52 gallon		1	Ea.	\$2,684	10
Plumbing Fixtures	Classroom Lavatory		22	Ea.	\$56,419	10
		Sub Total for System	9	items	\$244,805	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Casework	Fixed Cabinetry		24	Room	\$211,245	5
		Sub Total for System	1	items	\$211,245	
Sub Total for Building 198	A - Main building includes Administration Offices, C	lassrooms, Cafeteria, & Gym.	42	items	\$3,347,384	
Building: 198B - Stand	d-Alone Classroom Building					
Exterior	-					
Exterior Uniformat Description	LC Type Description			UoM	· · ·	
Exterior Uniformat Description Exterior Entrance Doors	LC Type Description Steel - Insulated and Painted		2	Door	\$7,414	5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF		2 2,880	Door SF	\$7,414 \$287,213	5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF		2 2,880 192	Door SF SF	\$7,414 \$287,213 \$19,148	5 5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum		2 2,880 192 4	Door SF SF Door	\$7,414 \$287,213 \$19,148 \$15,876	5 5 5 5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF		2 2,880 192 4 1,102	Door SF SF Door SF	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086	5 5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum	Sub Total for System	2 2,880 192 4 1,102	Door SF SF Door	\$7,414 \$287,213 \$19,148 \$15,876	5 5 5 5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum	Sub Total for System	2 2,880 192 4 1,102	Door SF SF Door SF	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086	5 5 5 5 5
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer Interior	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum	Sub Total for System	2 2,880 192 4 1,102 5 Qty	Door SF SF Door SF items UoM	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737	5 5 5 5 10
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer Interior Uniformat Description	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis	Sub Total for System	2 2,880 192 4 1,102 5	Door SF SF Door SF items UoM	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737	5 5 5 10 Remaining Life
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description	Sub Total for System	2 2,880 192 4 1,102 5 Qty	Door SF SF Door SF items UoM SF	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost	5 5 5 10 Remaining Lif
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles	Sub Total for System	2 2,880 192 4 1,102 5 Qty 7,714 4,408	Door SF SF Door SF items UoM SF	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048	5 5 5 10 Remaining Lif
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Entrance Doors Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF)	Sub Total for System	2,880 192 4 1,102 5 Qty 7,714 4,408 2	Door SF SF Door SF items UoM SF SF	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752	5 5 5 10 Remaining Life 5 7
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Contrance Doors Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF)		2,880 192 4 1,102 5 Qty 7,714 4,408 2	Door SF SF Door SF items UoM SF SF Door	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242	5 5 5 10 Remaining Lif 5 7
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Constraints Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors Mechanical	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF)		2,880 192 4 1,102 5 Qty 7,714 4,408 2 3	Door SF SF Door SF items UoM SF SF Door	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242 \$53,042	5 5 5 10 Remaining Lif 5 7 10
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Constraints Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors Mechanical Uniformat Description	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF) Storefront door (Aluminum/Glass)		2,880 192 4 1,102 5 Qty 7,714 4,408 2 3 Qty	Door SF SF Door SF items UoM SF SF Door items	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242 \$53,042	5 5 5 10 Remaining Lif 5 7 10
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Operating Windows Exterior Wall Veneer Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors Mechanical Uniformat Description Hydronic Distribution Systems	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF) Storefront door (Aluminum/Glass) LC Type Description	Sub Total for System	2,880 192 4 1,102 5 Qty 7,714 4,408 2 3 Qty 37	Door SF SF Door SF items UoM SF SF Door items UoM Ton	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242 \$53,042 Repair Cost \$481,089	5 5 5 10 Remaining Lif 7 10 Remaining Lif 2
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Contrained Doors Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors Mechanical Uniformat Description Hydronic Distribution Systems	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF) Storefront door (Aluminum/Glass) LC Type Description Crype Description	Sub Total for System	2,880 192 4 1,102 5 Qty 7,714 4,408 2 3 0 Qty 37 d Source.	Door SF SF Door SF items UoM SF SF Door items UoM Ton	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242 \$53,042 Repair Cost \$481,089	5 5 5 10 Remaining Lif 7 10 Remaining Lif 2
Exterior Uniformat Description Exterior Entrance Doors Exterior Operating Windows Exterior Operating Windows Exterior Parting Windows Exterior Wall Veneer Interior Uniformat Description Acoustical Suspended Ceilings Wall Painting and Coating Interior Swinging Doors Mechanical Uniformat Description Hydronic Distribution Systems	LC Type Description Steel - Insulated and Painted Aluminum - Windows per SF Aluminum - Windows per SF Storefront Doors - Glass/Aluminum E.I.F.S Bldg SF basis LC Type Description Ceilings - Acoustical Tiles Painting/Staining (Bldg SF) Storefront door (Aluminum/Glass) LC Type Description Ground Source Loop Field Pipe Note: Bulding A and C have no Ground Source is not up	Sub Total for System	2,880 192 4 1,102 5 Qty 7,714 4,408 2 3 0 Qty 37 d Source.	Door SF SF Door SF items UoM SF SF Door items UoM Ton Bldg A and O Ea.	\$7,414 \$287,213 \$19,148 \$15,876 \$34,086 \$363,737 Repair Cost \$26,048 \$19,752 \$7,242 \$53,042 Repair Cost \$481,089 C use RTU's for Air	5 5 10 Remaining Life 5 7 10 Remaining Life 2 Conditiioning.

HVAC Air Distribution Ductwork (Bldg.SF) 11,020 SF \$87,195 Exhaust Air Roof Exhaust Fan - Small 4 Ea. \$7,839 Heating System Supplementary Components Controls - Electronic (Bldg.SF) 11,020 SF \$17,052 Sub Total for System 5 items \$599,598 Electrical Qty UoM Repair Cost Remaining Life Uniformat Description LC Type Description Power Distribution Panelboard - 120/208 225A 1 Ea. \$5,500 Lighting Fixtures 11,020 SF Light Fixtures (Bldg SF) \$202,091 Sub Total for System 2 items \$207,590 Plumbing Qty UoM Uniformat Description Repair Cost Remaining Life LC Type Description

Sanitary Sewerage Piping Sanitary Sewer Piping 11,020 SF 10 \$12,235 11,020 SF Domestic Water Piping Domestic Water Piping System (Bldg.SF) \$39,603 10 Sub Total for System \$51,838 2 items Sub Total for Building 198B - Stand-Alone Classroom Building 17 items \$1,275,805

5

10

5

10



Austin ISD - Joslin ES

Building: 198C - Stand-Alone Library

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		1	Door	\$3,707	10
		Sub Total for System	1	items	\$3,707	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Interior Door Supplementary Components	Door Hardware		6	Door	\$8,908	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		3,262	SF	\$11,015	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		3,262	SF	\$14,617	7
Carpeting	Carpet		2,773	SF	\$35,107	8
		Sub Total for System	4	items	\$69,646	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
HVAC Air Distribution	Ductwork (Bldg.SF)		3,262	SF	\$25,810	5
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)		3,262	SF	\$5,047	10
		Sub Total for System	2	items	\$30,858	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Restroom Lavatory		1	Ea.	\$2,716	5
Plumbing Fixtures	Toilets		1	Ea.	\$5,059	5
Sanitary Sewerage Piping	Sanitary Sewer Piping		3,262	SF	\$3,622	10
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		3,262	SF	\$11,723	10
Plumbing Fixtures	Classroom Lavatory		1	Ea.	\$2,565	10
		Sub Total for System	5	items	\$25,684	
	Sub Total for Building	198C - Stand-Alone Library	12	items	\$129,895	
		Total for: Joslin ES	73	items	\$5,035,981	



Austin ISD - Joslin ES

Supporting Photos

General Site Photos





Slight discoloration on hard ceiling tiles



Worn paint on walls



Worn flooring



Aged aluminum windows



Worn and damaged exterior brick



Austin ISD - Joslin ES



Aged aluminum windows