


FACILITY CONDITION ASSESSMENT

Kocurek ES | February 2022



M•A•P•P•S ©, Jacobs 2022



Executive Summary

Kocurek ES is located at 9800 Curlew Dr in Austin, Texas. The oldest building is 34 years old (at time of 2020 assessment). It comprises 78,704 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$5,635,750. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Kocurek ES the ten-year need is \$11,122,785.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Kocurek ES facility has a 5-year FCA score of 68.82%.


Summary of Findings

The table below summarizes the condition findings at Kocurek ES

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Si	ite							
	Exterior Site	\$1,215,126	\$296,020	\$595,083	\$1,511,146	\$2,106,229	\$0	
Permanent	t Building(s)	-			-			
172A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$4,145,752	\$2,015,991	\$1,261,397	\$6,161,743	\$7,423,140	\$22,396,860	72.49%
172B	Stand-Alone Classroom Building	\$274,872	\$111,352	\$1,207,192	\$386,224	\$1,593,416	\$3,448,752	88.80%
	Sub Total for Permanent Building(s):	\$4,420,624	\$2,127,343	\$2,468,589	\$6,547,967	\$9,016,556	\$25,845,608	
	Total for Site:	\$5,635,750	\$2,423,363	\$3,063,672	\$8,059,113	\$11,122,785	\$25,845,608	68.82%

Facility Condition Assessment





Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$0	\$0	\$1,207,956	\$1,207,956	21.43 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$6,455	\$0	\$0	\$0	\$0	\$6,455	0.11 %
Exterior	\$0	\$0	\$8,527	\$0	\$69,379	\$77,906	1.38 %
Interior	\$0	\$0	\$145,800	\$673,766	\$0	\$819,566	14.54 %
Mechanical	\$0	\$193,802	\$96,013	\$0	\$4,171	\$293,986	5.22 %
Electrical	\$0	\$240,940	\$1,563,101	\$0	\$0	\$1,804,041	32.01 %
Plumbing	\$0	\$0	\$0	\$6,607	\$0	\$6,607	0.12 %
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$465,177	\$0	\$465,177	8.25 %
Crawlspace	\$0	\$0	\$0	\$0	\$954,055	\$954,055	16.93 %
Total:	\$6,455	\$434,742	\$1,813,441	\$1,145,551	\$2,235,561	\$5,635,750	

The building systems at the site with the most need include:

Electrical	-	\$1,804,041
Site	-	\$1,207,956
Interior	-	\$819,566



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies

M•A•P•P•S ©, Jacobs 2022 5



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$0	\$0	\$296,020	\$296,020
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$74,140	\$74,140
Interior	\$0	\$0	\$0	\$16,068	\$120,461	\$136,529
Mechanical	\$0	\$0	\$0	\$627,356	\$631,564	\$1,258,920
Electrical	\$0	\$0	\$0	\$63,020	\$81,003	\$144,023
Plumbing	\$0	\$0	\$0	\$0	\$6,384	\$6,384
Fire and Life Safety	\$0	\$0	\$0	\$24,173	\$16,675	\$40,848
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$466,499	\$0	\$466,499
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$0	\$0	\$1,197,116	\$1,226,247	\$2,423,363



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$296,020	\$0	\$0	\$0	\$0	\$264,411	\$264,411	\$560,431
Roofing	\$0	\$0	\$0	\$0	\$0	\$284,115	\$284,115	\$284,115
Exterior	\$74,140	\$0	\$0	\$297,901	\$0	\$14,828	\$312,729	\$386,869
Interior	\$136,529	\$0	\$0	\$307,386	\$0	\$0	\$307,386	\$443,915
Mechanical	\$1,258,920	\$0	\$0	\$359,461	\$0	\$139,209	\$498,670	\$1,757,590
Electrical	\$144,023	\$0	\$0	\$102,116	\$0	\$0	\$102,116	\$246,139
Plumbing	\$6,384	\$0	\$0	\$5,059	\$0	\$22,651	\$27,710	\$34,094
Fire and Life Safety	\$40,848	\$0	\$0	\$156,982	\$108,292	\$0	\$265,274	\$306,122
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$466,499	\$0	\$0	\$1,161,847	\$0	\$0	\$1,161,847	\$1,628,346
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$2,423,363	\$0	\$0	\$2,390,752	\$108,292	\$725,214	\$3,224,258	\$5,647,621




Figure 2: Ten Year Capital Renewal Forecast

M•A•P•P•S ©, Jacobs 2022



Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$25,845,608. For planning purposes, the total 5-year need at the Kocurek ES is \$8,059,113 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Kocurek ES facility has a 5-year FCA of 68.82%.



M=A=P=P=S ©, Jacobs 2022



Kocurek ES - Deficiency Summary Site Level Deficiencies

Site

Deficiency	Category	Qty UoM Prid	ority Repair Cost	טו
PROGRAM DEFICIENCIES	ADA Compliance	439 899 FACH	5 \$755 298	1744

Note: Interior Improvements

Estimated Construction Cost for Floor Plan Area 5 - Building A \$8,130.96 Estimated Construction Cost for Floor Plan Area - Building A \$15,200.08 Estimated Construction Cost for Floor Plan Area 7 - Building A \$64,336.59

Estimated Construction Cost for Floor Plan Area 8 - Building A \$30,507.14
Estimated Construction Cost for Floor Plan Area 9 (9A & 9B - 2 Locations)- Building A \$12,911.00
Estimated Construction Cost for Floor Plan Area 10 (10A & 10B - 2 Locations) - Building A \$220,420.49

Estimated Construction Cost for Floor Plan Area 11 - Building A \$88,392.87

Estimated Construction Cost Subtotal for Interior Improvements Excluding Division 1 \$ 439,899.13 Total Estimated Construction Cost Subtotal for Program Deficiency Improvements \$439,899.13

Location: ASID ADA REPORT

PUBLIC DEFICIENCIES ADA Compliance 151,181 EACH \$259,575 1743

Note: Site/Exterior Improvements

Estimated Construction Cost for Site Plan Area A \$23,164.84 Estimated Construction Cost for Site Plan Area B \$ 26.152.38

Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division 1 \$ 49,317.22

Interior Improvements

Estimated Construction Cost for Floor Plan Area 1 - Building A \$8,997.44 Estimated Construction Cost for Floor Plan Area 2 - Building A \$6,455.50 Estimated Construction Cost for Floor Plan Area 3 - Building A \$30,298.19 Estimated Construction Cost for Floor Plan Area 4 - Building A \$56,112.99

Estimated Construction Cost Subtotal for Interior Improvements Excluding Division 1 \$ 101,864.11 Total Estimated Construction Cost Subtotal for Public Deficiency Improvements \$151,181.33

Location: AISD ADA REPORT

TAS ACCESSIBILITY DEFICIENCIES **ADA Compliance** 112,455 EACH \$193,083 1745

Note: Interior Improvements

Estimated Construction Cost for Floor Plan Area 12 - Building A \$ 39,784.08 Estimated Construction Cost for Floor Plan Area 13 - Building A \$ 45,566.13 Estimated Construction Cost for Floor Plan Area 14 - Building B \$ 7,325.82 Estimated Construction Cost for Floor Plan Area 15 - Building A \$19,778.84

Estimated Construction Cost Subtotal for TAS Improvements Excluding Division 1 \$ 112,454.86 Total Estimated Construction Cost Subtotal for TAS Deficiency Improvements \$112,454.86

Location: AISD ADA REPORT

Sub Total for System	3 items	\$1,207,956
oub rotal for System	3 items	\$1,207,330

Structural

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Structural Study Recommended	Deferred Maintenance	1 Job	1	\$6,455	6719

Note: Structural study to detail scope of work based on the 2017 crawlspace deficiencies provided by AISD

Sub Total for System 1 items \$6,455

Electrical

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Exterior Electrical Enclosure Replacement	Deferred Maintenance	1 Ea.	2	\$715	1442

Note: All equipment

Location: Electrical service location

Sub Total for System 1 items \$715

Sub Total for School and Site Level 5 items \$1,215,126

Building: 172A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Brick Exterior Repair	r	Deferred Maintenance	500 SF Wall	3	\$6,229	1760
Note:	Some bricks are missing or falling					
Exterior Metal Door	Repainting	Deferred Maintenance	10 Door	3	\$1,149	1455
Note:	w/Window					







Exterior

Deficiency	Category	Qty Uo	M Priority	Repair Cost	ID
Exterior Metal Door Repainting	Deferred	10 Do	or 3	\$1,149	1456
	Maintenance				
Note: No window					
Exterior Cleaning	Deferred Maintenance	13,874 SF Wa		\$53,732	1758
Exterior Painting	Capital Renewal	12,000 SF		\$15,646	1454
Extend Full line	oupliur Honowar	Wa		ψ10,010	1101
Note: Age					
Location: Metal Sections					
	Sub Total for System	5 ite	ms	\$77,906	
Interior					
Deficiency	Category	Qty Uo	M Priority	Repair Cost	ID
Athletic Sport Flooring Replacement	Capital Renewal	2,046 SF		\$31,389	1445
Location: Gym	•	,			
Interior Door Replacement	Capital Renewal	15 Do	or 3	\$28,134	1449
Note: w/window	•				
Interior Door Replacement	Capital Renewal	46 Do	or 3	\$86,278	1450
Note: w/o window				, , ,	
Acoustical Ceiling Tile Replacement	Capital Renewal	200 SF	4	\$675	1444
Location: Book Room, Teachers' Work Room, Storage #2, Janitor Closet	•				
Carpet Flooring Replacement	Capital Renewal	6,000 SF	4	\$75,961	1446
Location: Library	,	,			
Carpet Flooring Replacement	Capital Renewal	4,774 SF	4	\$60,440	1762
Metal Interior Door Replacement	Capital Renewal	4 Do		\$11,575	
Note: w/window				, , , , , ,	
Metal Interior Door Replacement	Capital Renewal	8 Do	or 4	\$23,151	1448
Note: w/o window				4 _0,.0.	
Vinyl Composition Tile Replacement	Capital Renewal	61,382 SF	4	\$501,964	1761
, ,	Sub Total for System	9 ite		\$819,566	
Machanical				** ***	
Mechanical Political	Cotogon	Ohi. Ha	M Driorita	Danair Coat	ID
Deficiency	Category	Qty Uo		Repair Cost	ID 1754
Deficiency Boiler Replacement	Capital Renewal	1 Ea	. 2	\$100,146	1754
Deficiency Boiler Replacement Package Roof Top Unit Replacement			. 2		
Deficiency Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room	Capital Renewal Capital Renewal	1 Ea 2 Ea	. 2	\$100,146 \$93,655	1754 1467
Deficiency Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement	Capital Renewal Capital Renewal Capital Renewal	1 Ea 2 Ea 3 Ea	. 2	\$100,146 \$93,655 \$68,182	1754 1467 1755
Deficiency Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 Ea 2 Ea	. 2	\$100,146 \$93,655	1754 1467 1755
Deficiency Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 Ea 2 Ea 3 Ea	. 2	\$100,146 \$93,655 \$68,182	1754 1467 1755
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent.	1 Ea 2 Ea 3 Ea 2 Ea	. 2 . 2 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal	1 Ea 2 Ea 3 Ea	. 2 . 2 . 3 . 3	\$100,146 \$93,655 \$68,182	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal	1 Ea 2 Ea 3 Ea 2 Ea	. 2 . 2 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea	. 2 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal	1 Ea 2 Ea 3 Ea 2 Ea	. 2 . 2 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea	. 2 . 3 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea	. 2 . 3 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758	1754 1467 1755 1470
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea 6 Ea 6 ite	. 2 . 3 . 3 . 3	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986	1754 1467 1755 1470 1469
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency	Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea 6 ite	. 2 . 3 . 3 . 3 . 5 ms	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost	1754 1467 1755 1470 1469 1468
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea 6 ite Qty Uo 1 Ea	2 2 3 3 3 4 5 ms 4 Priority 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712	1754 1467 1755 1470 1469 1468
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Distribution Panel Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal	1 Ea 2 Ea 3 Ea 2 Ea 6 Ea 6 ite Qty Uo 1 Ea 1 Ea 1 Ea 1 Ea	2 2 3 3 3 5 ms 5 ms 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905	1754 1467 1755 1470 1469 1468 ID 1484 1485
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 Ite Qty Uo 1 Ea 1 Ea 2 Ea 2 Ea	2 2 3 3 3 3 5 ms 5 ms 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 ite Qty Uo 1 Ea 1 Ea 2 Ea 4 Ea 4 Ea	2 2 3 3 5 ms M Priority 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement Electrical Transformer Replacement Electrical Transformer Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 ite Qty Uo 1 Ea 1 Ea 2 Ea 4 Ea 1	2 2 3 3 5 ms Priority 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075 \$7,287	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482 1483
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 Ite Qty Uo 1 Ea 4 Ea 4 Ea 1 Ea 1 Ea 1 Ea 1 Ea 1 Ea	2 2 3 3 3 5 ms Priority 2 2 2 2 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075 \$7,287 \$9,908	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482 1483 1486
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 Ite Qty Uo 1 Ea 1 Ea 1 Ea 1 Ea 1 Ea 4 Ea 4 Ea 4 Ea	2 2 3 3 3 5 ms Priority 2 2 2 2 2 2 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$111,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075 \$7,287 \$9,908 \$11,128	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482 1483 1486 1487
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement Panelboard Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 Ea 10 Ea 1 Ea 1 Ea 1 Ea 1 Ea 1 Ea 1 Ea	2 2 3 3 3 5 ms Priority 2 2 2 2 2 2 2 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$11,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075 \$7,287 \$9,908 \$11,128 \$10,999	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482 1483 1486 1487 1488
Boiler Replacement Package Roof Top Unit Replacement Location: R-22/AHU-5 and AHU-6 in main mechanical room Energy Recovery Unit Replacement Large Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF - 18, 19 Small Diameter Exhausts/Hoods Replacement Note: Extremely outdated and corroded, recommend immediate replacer Location: EF 5, 6, 16, 20, 21, 26 Duct Register Replacement Electrical Deficiency Distribution Panel Replacement Electrical Transformer Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal nent. Capital Renewal nent Deferred Maintenance Sub Total for System Category Capital Renewal	1 Ea 2 Ea 3 Ea 6 Ea 6 Ite Qty Uo 1 Ea 1 Ea 1 Ea 1 Ea 1 Ea 4 Ea 4 Ea 4 Ea	2 2 3 3 3 5 ms Priority 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	\$100,146 \$93,655 \$68,182 \$16,072 \$111,758 \$4,171 \$293,986 Repair Cost \$16,712 \$16,905 \$11,838 \$22,075 \$7,287 \$9,908 \$11,128	1754 1467 1755 1470 1469 1468 ID 1484 1485 1481 1482 1483 1486 1487 1488

M*A*P*P*S ©, Jacobs 2022 10



Electrical

Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$1,459	1490
Note: 150A						
Panelboard Replacement	Capital Renewal	2	Ea.	2	\$13,377	1491
Note: 150A, No remaining life						
Switchgear Replacement	Capital Renewal	1	Ea.	2	\$13,645	1478
Switchgear Replacement	Capital Renewal	2	Ea.	2	\$76,774	1479
Canopy Lighting Replacement	Capital Renewal	28	Ea.	3	\$58,323	1493
Note: No remaining life						
Lighting Fixtures Replacement	Capital Renewal	68,202	SF	3	\$1,250,725	1494
Note: No remaining life						
Lightning Protection System Installation	Functional Deficiency	68,202	SF	3	\$53,260	1492
Note: None installed						
	Sub Total for System	16	items		\$1,602,533	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Refrigerated Water Cooler Replacement	Capital Renewal	2	Ea.	4	\$4,405	1466
Note: Age, corrosion						
Location: Located outside teacher work room in corridor						
Refrigerated Water Cooler Replacement	Capital Renewal	1	Ea.	4	\$2,202	1746
	Sub Total for System	2	items		\$6,607	
Specialties						
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Base Storage Cabinet Replacement	Capital Renewal	280		4	\$154,293	1451
Note: Age/All rooms	Oupital Neriewal	200		7	Ψ10-1,230	1401
Bleacher Replacement	Capital Renewal	50	Seat	4	\$20,655	1453
Note: Age	Capital Honowal	00	Cour	·	Ψ20,000	1 100
Location: Courtyard						
Upper Storage Cabinet Replacement	Capital Renewal	270	l F	4	\$290,228	1452
Note: Age/All rooms	Oupital Neriewal	210		7	Ψ230,220	1402
Note: Agg/Aii rooms	Sub Total for System	3	items		\$465,177	
Crawlspace	Can retained by stein				V ,	
•	Cotogony	Otiv	UoM	Driority	Banair Cost	ID
Deficiency CDAWL CDACE DEFICIENCIES Festive and lefe by AISD	Category			Priority 5	Repair Cost	
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred Maintenance	186,905	⊏a.	5	\$219,586	6720
Note: CRAWL SPACE ACCESS/VENTILATION - increase ventilation - 67	7139 GSF					
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred	1,392	Ea.	5	\$1,635	6721
·	Maintenance					
Note: CRAWL SPACE ACCESS/VENTILATION - clear space - 1 EA						
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred	93,452	Ea.	5	\$109,792	6722
Note: CDECIAL FOLINDATIONS repair miner hand combine 9 class asi	Maintenance					
Note: SPECIAL FOUNDATIONS - repair minor honeycombing & clear soi		200 257	Г.	-	#220.270	6700
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred Maintenance	280,357	Ea.	5	\$329,378	6/23
Note: SUSPENDED FLOOR SLABS - repair moderate honeycombing, sp	alling & exposed reinforcin	ng - 67139	GSF			
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred	186,905		5	\$219,586	6724
	Maintenance	,			* -,	
Note: CRAWL SPACE, EXPOSED PIPES - Repair cracked pipes, repair pair pair pair pair pair pair pair	pipe leaks, replace corrode	ed piping - (67139			
	Sub Total for System	5	items		\$879,976	
Sub Total for Building 172A - Main building includes Administration Offices, Classro	ooms, Cafeteria, & Gym.	46	items		\$4,145,752	
Building: 172B - Stand-Alone Classroom Building	n e					
-	,					
Electrical	_			_		
Deficiency	Category		UoM	Priority	Repair Cost	ID
Lighting Fixtures Replacement	Capital Renewal	10,502		3	\$192,591	1477
Lightning Protection System Installation	Functional Deficiency	10,502	SF	3	\$8,201	1476
Note: None installed						
	Sub Total for System	2	items		\$200,793	
Managaras @ Jacobs 2022						
M•A•P•P•S ©, Jacobs 2022						





Austin ISD - Kocurek ES

Crawlspace

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	20,879 Ea.	5	\$24,530	6725
Note:	SOIL/DRAINAGE BELOW BUILDING - Grade soil away from	building - 1 LS				
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	5,985 Ea.	5	\$7,031	6726
Note:	PERIMETER SOIL RETAINERS - repair a few retainers - 430	LF				
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	1,392 Ea.	5	\$1,635	6727
Note:	CRAWL SPACE ACCESS/VENTILATION - increase ventilation	n - 1 LS				
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	34,798 Ea.	5	\$40,882	6728
Note:	CRAWL SPACE, EXPOSED PIPES - Replace rusted pipes ar	nd hangers - 1 LS				
		Sub Total for System	4 items		\$74,079	
	Sub Total for Building 172B - Star	nd-Alone Classroom Building	6 items		\$274,872	
		Total for Campus	57 items		\$5,635,750	

M*A*P*P*S ©, Jacobs 2022 12



Kocurek ES - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)		2,720	LF	\$128,377	5
Pedestrian Pavement	Sidewalks - Concrete		14,800	SF	\$167,643	5
Parking Lot Pavement	Asphalt		85	CAR	\$123,318	10
Roadway Pavement	Asphalt Driveways		20,000	SF	\$128,609	10
Roadway Pavement	Concrete Driveways		1,000	SF	\$12,484	10
		Sub Total for System	5	items	\$560,430	
Roofing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Canopy Roofing	Steel panels		5,600	SF	\$284,115	10
		Sub Total for System	1	items	\$284,115	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Lighting	Pole Lighting		8	Ea.	\$46,557	8
		Sub Total for System	1	items	\$46,557	
		Sub Total for Building -	7	items	\$891,103	

Building: 172A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted	•	10	Door	\$37,070	5
Exterior Entrance Doors	Steel - Insulated and Painted		10	Door	\$37,070	5
Exterior Operating Windows	Steel - Windows per SF		1,013	SF	\$146,421	8
Exterior Operating Windows	Steel - Windows per SF		36	SF	\$5,204	8
Exterior Operating Windows	Steel - Windows per SF		104	SF	\$15,032	8
Exterior Operating Windows	Steel - Windows per SF		608	SF	\$87,881	8
Exterior Operating Windows	Steel - Windows per SF		120	SF	\$17,345	8
Exterior Operating Windows	Steel - Windows per SF		180	SF	\$26,018	8
		Sub Total for System	8	items	\$372,041	

Interior

Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Coverings		Vinyl/Fabric Wall Covering	3,	410	SF	\$16,068	4
	Note:	Gym pads on wall					
Compartments and Cubicles		Toilet Partitions		3	Stall	\$6,049	5
Interior Swinging Doors		Wooden Door		15	Door	\$28,134	5
Interior Swinging Doors		Wooden Door		46	Door	\$86,278	5
Acoustical Suspended Ceilings		Ceilings - Acoustical Tiles	61,;	382	SF	\$207,272	8
Carpeting		Carpet	4,	774	SF	\$60,440	8
Interior Swinging Doors		Metal Door (Steel)		4	Door	\$11,575	8
Interior Swinging Doors		Metal Door (Steel)		8	Door	\$23,151	8
			Sub Total for System	8	items	\$438,966	

Mechanical

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Heat Pump (5 Ton)	48	Ea.	\$582,483	4
	Note: Estimated - All units located above ceiling				
HVAC Air Distribution	Roof Top Unit - DX Gas (25 Ton)	1	Ea.	\$64,260	5
HVAC Air Distribution	Ductwork (Bldg.SF)	68,202	SF	\$539,644	5
Exhaust Air	Wall Exhaust Fan	2	Ea.	\$9,463	5
Heating System Supplementary Components	Controls - DDC (Bldg.SF)	68,202	SF	\$183,956	8
Central Cooling	Cooling Tower - Metal (170 Tons)	1	Ea.	\$51,387	8
Other HVAC Distribution Systems	VFD (5 HP)	1	Ea.	\$4,393	8
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)	1	Ea.	\$4,313	8
Facility Hydronic Distribution	Pump - 50HP - (Ea.)	2	Ea.	\$115,412	8
Heat Generation	Boiler - Steel Tube (2400 MBH)	1	Ea.	\$100,146	10

13







	han	

Uniformat Description					Repair Cost	
Other HVAC Distribution Systems	VFD (40 HP)			UoM Ea.	\$27,872	10
Exhaust Air	Kitchen Exhaust Hoods			Ea.	\$11,191	10
Exhaust All	Alterien Exhaust 11000s	Sub Total for System		items	\$1,694,521	10
Electrical		oub rotal for Gystem		itemo	ψ1,004,021	
Uniformat Description	LC Type Description		Otv	UoM	Renair Cost	Remaining Life
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)		68,202		\$48,279	4
Distributed Systems	Public Address System Head End Unit			Ea.	\$7,307	4
Power Distribution	Power Wiring		68,202		\$81,003	5
Power Distribution	Distribution Panel (1600 Amps)			Ea.	\$25,176	8
Power Distribution	Panelboard - 120/208 100A			Ea.	\$2,782	8
				Ea.		
Power Distribution	Panelboard - 120/208 400A	Sub Total for System		items	\$24,683 \$189,229	8
		Sub rotal for System	•	iteilis	\$109,229	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 100 Gallon		1	Ea.	\$6,384	5
Plumbing Fixtures	Toilets		1	Ea.	\$5,059	8
		Sub Total for System	2	items	\$11,443	
Fire and Life Safety						
Uniformat Description	LC Type Description		Otre	UoM	Rannir Cont	Remaining Life
· · · · · · · · · · · · · · · · · · ·		,	68,202		\$156,982	8
Security System Component Fire Detection and Alarm	Security Alarm System					
Fire Detection and Alarm	Fire Alarm	Sub Total for Sustan	68,202		\$108,292 \$265,274	9
• • • • •		Sub Total for System	2	items	\$265,274	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry		53	Room	\$466,499	4
Casework			1	items	\$466,499	
Casework		Sub Total for System			φ+00,+00	
	A - Main building includes Administration Offices, Cla	•		items	\$3,437,973	
Sub Total for Building 172/		•				
Sub Total for Building 172/ Building: 172B - Stand	A - Main building includes Administration Offices, Cla	•				
Sub Total for Building 172/		•				
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description	I-Alone Classroom Building LC Type Description	•	39 Qty	items UoM	\$3,437,973 Repair Cost	Remaining Life
Sub Total for Building 1728 Building: 172B - Stand Exterior	I-Alone Classroom Building	•	39 Qty	items	\$3,437,973	Remaining Life
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description	I-Alone Classroom Building LC Type Description	•	Qty 4	items UoM	\$3,437,973 Repair Cost	
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description	I-Alone Classroom Building LC Type Description	ssrooms, Cafeteria, & Gym.	Qty 4	UoM Door	\$3,437,973 Repair Cost \$14,828	
Sub Total for Building 172/ Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors	I-Alone Classroom Building LC Type Description	ssrooms, Cafeteria, & Gym.	Qty 4 1	UoM Door	\$3,437,973 Repair Cost \$14,828 \$14,828	10
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior	LC Type Description Steel - Insulated and Painted LC Type Description	ssrooms, Cafeteria, & Gym.	Qty 4 1	UoM Door items	\$3,437,973 Repair Cost \$14,828 \$14,828	10
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description	LC Type Description Steel - Insulated and Painted	ssrooms, Cafeteria, & Gym. Sub Total for System	Qty 4 1 Qty 1,050	UoM Door items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948	10 Remaining Life
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings	LC Type Description Steel - Insulated and Painted LC Type Description	ssrooms, Cafeteria, & Gym.	Qty 4 1 Qty 1,050	UoM Door items UoM SF	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost	10 Remaining Life
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering	ssrooms, Cafeteria, & Gym. Sub Total for System	Oty 4 1 1 Oty 1,050 1	UoM Door items UoM SF items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948	10 Remaining Life 8
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description	ssrooms, Cafeteria, & Gym. Sub Total for System	Otty 4 1 Otty 1,050 1 Otty	UoM Door items UoM SF items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost	10 Remaining Life 8 Remaining Life
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton)	ssrooms, Cafeteria, & Gym. Sub Total for System	Oty 4 1 Oty 1,050 1 Oty 1	UoM Door items UoM SF items UoM Ea.	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873	Remaining Life 8 Remaining Life 4
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description	ssrooms, Cafeteria, & Gym. Sub Total for System	Otty 4 1 Otty 1,050 1 Otty	UoM Door items UoM SF items UoM Ea.	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost	10 Remaining Life 8 Remaining Life
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF)	ssrooms, Cafeteria, & Gym. Sub Total for System	Qty 4 1 Qty 1,050 1 Qty 10,502	UoM Door items UoM SF items UoM Ea. SF	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250	Remaining Life 8 Remaining Life 4 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton)	Sub Total for System Sub Total for System	Qty 4 1 Qty 1,050 1 Qty 4 1,050 4	UoM Door items UoM SF items UoM Ea. SF Ea.	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947	Remaining Life 8 Remaining Life 4
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF)	ssrooms, Cafeteria, & Gym. Sub Total for System	Qty 4 1 Qty 1,050 1 Qty 4 1,050 4	UoM Door items UoM SF items UoM Ea. SF	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250	Remaining Life 8 Remaining Life 4 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF)	Sub Total for System Sub Total for System	Qty 4 1 Qty 1,050 1 Qty 4 1,050 4	UoM Door items UoM SF items UoM Ea. SF Ea.	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947	Remaining Life 8 Remaining Life 4 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan	Sub Total for System Sub Total for System	Qty 4 1 Qty 1,050 1 10,502 4 3	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070	Remaining Life 8 Remaining Life 4 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan	Sub Total for System Sub Total for System	Qty 4 1 Qty 1,050 1 10,502 4 3	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070	Remaining Life 8 Remaining Life 4 5 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan	Sub Total for System Sub Total for System	Qty 4 1 1,050 1 Qty 1,0502 4 3 Qty 10,502	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost	Remaining Life 8 Remaining Life 4 5 5
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF)	Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434	Remaining Life 8 Remaining Life 4 5 5 Remaining Life
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution	LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF)	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918	Remaining Life 8 Remaining Life 4 5 5 Remaining Life
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 2	UoM Door items UoM SF items UoM Ea. SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM UoM	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description Domestic Water Equipment	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description Water Heater - Electric - 30 gallon	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty 1 Qty 1	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost \$2,135	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8 Remaining Life 10
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty 1 8	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost \$2,135 \$20,516	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8
Sub Total for Building 1728 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description Domestic Water Equipment Plumbing Fixtures	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description Water Heater - Electric - 30 gallon	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty 1 8	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost \$2,135	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8 Remaining Life 10
Sub Total for Building 172/8 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description Domestic Water Equipment Plumbing Fixtures	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description Water Heater - Electric - 30 gallon	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty 1 8	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost \$2,135 \$20,516	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8 Remaining Life 10
Sub Total for Building 1724 Building: 172B - Stand Exterior Uniformat Description Exterior Entrance Doors Interior Uniformat Description Wall Coverings Mechanical Uniformat Description Decentralized Cooling Heating System Supplementary Components Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Plumbing Uniformat Description Domestic Water Equipment	Al-Alone Classroom Building LC Type Description Steel - Insulated and Painted LC Type Description Vinyl/Fabric Wall Covering LC Type Description Package DX Unit (30 Ton) Controls - Electronic (Bldg.SF) Interior Ceiling Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Panelboard - 120/208 125A LC Type Description Water Heater - Electric - 30 gallon	Sub Total for System Sub Total for System Sub Total for System	Qty 4 1 1,050 1 10,502 4 3 Qty 10,502 2 Qty 1 8 2	UoM Door items UoM SF items UoM Ea. SF Ea. items UoM SF Ea. items	\$3,437,973 Repair Cost \$14,828 \$14,828 Repair Cost \$4,948 \$4,948 Repair Cost \$44,873 \$16,250 \$1,947 \$63,070 Repair Cost \$7,434 \$2,918 \$10,352 Repair Cost \$21,35 \$20,516 \$22,651	Remaining Life 8 Remaining Life 4 5 5 Remaining Life 4 8 Remaining Life 10

M•A•P•P•S ©, Jacobs 2022





Austin ISD - Kocurek ES

Fire and Life Safety

Uniformat Description	LC Type Description	Qt	/ UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm	10,502	2 SF	\$16,675	5
	Sub Total for Sys	iem 2	2 items	\$40,848	
Specialties					
Uniformat Description	LC Type Description	Qty	/ UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry	132	2 Room	\$1,161,847	8
	Sub Total for Sys	iem '	litems	\$1,161,847	
	Sub Total for Building 172B - Stand-Alone Classroom Build	ing 12	2 items	\$1,318,543	
	Total for: Kocurek	ES 58	3 items	\$5,647,619	

M*A*P*P*S ©, Jacobs 2022 15



Supporting Photos

General Site Photos





Drinking fountain is aged



Pavers are damaged



Door frames are corroded



Vent roof fans are past life



Aged roof top unit

M•A•P•P•S ©, Jacobs 2022 16