

FACILITY CONDITION ASSESSMENT

Liberal Arts and Science Academy | February 2022







Executive Summary

Liberal Arts and Science Academy is located at 1012 Arthur Stiles Rd. in Austin, Texas. The oldest building is 60 years old (at time of 2020 assessment). It comprises 266,081 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$18,436,547. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Liberal Arts and Science Academy the ten-year need is \$43,917,879.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Liberal Arts and Science Academy facility has a 5-year FCA score of 62.98%.

Summary of Findings

The table below summarizes the condition findings at Liberal Arts and Science Academy

Table 1: Facility Condition by Building

| Number | Building Name | Current Deficiencies | 5-Year Life Cycle Cost | Yrs 6-10 Life Cycle Cost | Total 5 Yr Need (Yr 1-5 + Current Defs) | Total 10 Yr Need (Yr 1-10 + Current Defs) | Replacement Cost | 5-Year FCA |
|-------------|--|-------------------------|---------------------------|-----------------------------|---|---|---------------------|---------------|
| Exterior Si | ite | | | | | | | |
| | Exterior Site | \$2,483,916 | \$774,456 | \$477,139 | \$3,258,372 | \$3,735,511 | \$0 | |
| Permanen | t Building(s) | | | | | | | |
| 019A | Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. | \$15,124,035 | \$9,865,367 | \$10,357,916 | \$24,989,402 | \$35,347,318 | \$66,885,380 | 62.64% |
| 019B | Theater Building | \$470,919 | \$527,101 | \$618,574 | \$998,020 | \$1,616,594 | \$6,882,030 | 85.50% |
| 019C | Stand-Alone Classroom Building | \$216,071 | \$685,569 | \$2,018,901 | \$901,640 | \$2,920,541 | \$8,190,047 | 88.99% |
| 019D | Mechanical Building | \$141,606 | \$117,411 | \$877 | \$259,017 | \$259,894 | \$90,488 | -186.25% |
| 019E | Restrooms and Storage | \$0 | \$17,238 | \$20,783 | \$17,238 | \$38,021 | \$141,060 | 87.78% |
| | Sub Total for Permanent Building(s): | \$15,952,631 | \$11,212,686 | \$13,017,051 | <i>\$27,165,317</i> | \$40,182,368 | \$82,189,004 | |
| | Total for Site: | \$18,436,547 | \$11,987,142 | \$13,494,190 | \$30,423,689 | \$43,917,879 | \$82,189,004 | 62.98% |



Austin ISD - Liberal Arts and Science Academy

Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.

M-A-P-P-S ©, Jacobs 2022





The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

| | | | Priority | | | | |
|----------------------|-------------|-------------|-------------|-------------|-------------|--------------|------------|
| System | 1 | 2 | 3 | 4 | 5 | Total | % of Total |
| Site | \$0 | \$0 | \$0 | \$18,860 | \$2,465,056 | \$2,483,916 | 13.47 % |
| Roofing | \$4,125,172 | \$0 | \$0 | \$0 | \$0 | \$4,125,172 | 22.37 % |
| Structural | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Exterior | \$0 | \$592,095 | \$0 | \$0 | \$0 | \$592,095 | 3.21 % |
| Interior | \$0 | \$0 | \$0 | \$787,007 | \$0 | \$787,007 | 4.27 % |
| Mechanical | \$0 | \$6,214,078 | \$572,933 | \$75,730 | \$2,479 | \$6,865,220 | 37.24 % |
| Electrical | \$0 | \$160,551 | \$0 | \$0 | \$0 | \$160,551 | 0.87 % |
| Plumbing | \$0 | \$0 | \$1,252,255 | \$172,565 | \$0 | \$1,424,821 | 7.73 % |
| Fire and Life Safety | \$1,974,462 | \$0 | \$0 | \$0 | \$0 | \$1,974,462 | 10.71 % |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Specialties | \$0 | \$0 | \$0 | \$23,304 | \$0 | \$23,304 | 0.13 % |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Total: | \$6,099,634 | \$6,966,724 | \$1,825,189 | \$1,077,467 | \$2,467,534 | \$18,436,547 | |

The building systems at the site with the most need include:

| Mechanical | - | \$6,865,220 |
|------------|---|-------------|
| Roofing | - | \$4,125,172 |
| Site | - | \$2,483,916 |

The chart below represents the building systems and associated deficiency costs.





Figure 1: System Deficiencies





Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

| | | Life Cycl | e Capital Renewal Pro | ojections | | |
|----------------------|----------------|----------------|-----------------------|----------------|----------------|--------------|
| System | Year 1 2023 | Year 2 2024 | Year 3 2025 | Year 4 2026 | Year 5 2027 | Total 1-5 |
| Site | \$0 | \$0 | \$0 | \$0 | \$745,358 | \$745,358 |
| Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Exterior | \$0 | \$123,695 | \$676,408 | \$10,086 | \$25,532 | \$835,721 |
| Interior | \$0 | \$796,724 | \$742,833 | \$1,639,477 | \$1,388,391 | \$4,567,425 |
| Mechanical | \$0 | \$0 | \$790,758 | \$244,329 | \$3,710,973 | \$4,746,060 |
| Electrical | \$0 | \$0 | \$0 | \$3,607 | \$432,794 | \$436,401 |
| Plumbing | \$0 | \$0 | \$0 | \$159,742 | \$294,435 | \$454,177 |
| Fire and Life Safety | \$0 | \$0 | \$0 | \$0 | \$6,868 | \$6,868 |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$15,970 | \$15,970 |
| Specialties | \$0 | \$20,391 | \$0 | \$0 | \$150,733 | \$171,124 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$0 | \$940,810 | \$2,209,999 | \$2,057,241 | \$6,771,054 | \$11,979,104 |

Table 3b: Capital Renewal Forecast (Yrs 6-10)

| | | | Life Cycle | Capital Renewal F | Projections | | | |
|----------------------|--------------|----------------|----------------|-------------------|----------------|-----------------|--------------|--------------|
| System | Total 1-5 | Year 6 2028 | Year 7 2029 | Year 8 2030 | Year 9 2031 | Year 10 2032 | Total 6-10 | Total 1-10 |
| Site | \$745,358 | \$0 | \$231,834 | \$0 | \$0 | \$245,305 | \$477,139 | \$1,222,497 |
| Roofing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Exterior | \$835,721 | \$0 | \$81,851 | \$19,148 | \$41,121 | \$18,665 | \$160,785 | \$996,506 |
| Interior | \$4,567,425 | \$168,406 | \$0 | \$14,943 | \$190,608 | \$249,712 | \$623,669 | \$5,191,094 |
| Mechanical | \$4,746,060 | \$0 | \$0 | \$441,848 | \$0 | \$1,469,960 | \$1,911,808 | \$6,657,868 |
| Electrical | \$436,401 | \$0 | \$0 | \$227,018 | \$0 | \$4,672,271 | \$4,899,289 | \$5,335,690 |
| Plumbing | \$454,177 | \$879 | \$0 | \$120,767 | \$0 | \$6,285,079 | \$6,406,725 | \$6,860,902 |
| Fire and Life Safety | \$6,868 | \$17,229 | \$0 | \$0 | \$46,467 | \$0 | \$63,696 | \$70,564 |
| Conveyances | \$15,970 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$15,970 |
| Specialties | \$171,124 | \$0 | \$0 | \$44,009 | \$0 | \$247,865 | \$291,874 | \$462,998 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$11,979,104 | \$186,514 | \$313,685 | \$867,733 | \$278,196 | \$13,188,857 | \$14,834,985 | \$26,814,089 |




Figure 2: Ten Year Capital Renewal Forecast



The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$82,189,004. For planning purposes, the total 5-year need at the Liberal Arts and Science Academy is \$30,423,689 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Liberal Arts and Science Academy facility has a 5-year FCA of 62.98%.



M-A-P-P-S ©, Jacobs 2022



Liberal Arts and Science Academy - Deficiency Summary Site Level Deficiencies

Site

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|---|-------------------------------------|--------------|----------|-------------|------|
| Asphalt Paving Replacement | Capital Renewal | 13 CAR | 4 | \$18,860 | 4913 |
| Note: Holes, damage to asphalt | | | | | |
| Location: Southwest, cafeteria area lot | | | | | |
| PROGRAM DEFICIENCIES | ADA Compliance | 535,755 EACH | 5 | \$919,881 | 5762 |
| PUBLIC DEFICIENCIES | ADA Compliance | 561,350 EACH | 5 | \$963,827 | 5761 |
| TAS ACCESSIBILITY DEFICIENCIES | ADA Compliance | 338,587 EACH | 5 | \$581,347 | 5763 |
| | Sub Total for System | 4 items | | \$2,483,916 | |
| | Sub Total for School and Site Level | 4 items | | \$2,483,916 | |

Building: 019A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

| Roofing | | | | | | | |
|--|------------------------------|----------------------|-----------|-------|-----------|-------------|------|
| Deficiency | | Category | Qty | UoM | Priority | Repair Cost | ID |
| AISD ROOFII | NG P1 | Capital Renewal | 836,505 | EACH | 1 | \$836,487 | 5764 |
| AISD ROOFII | NG P2 | Capital Renewal | 1,931,457 | EACH | 1 | \$1,931,415 | 5765 |
| AISD ROOFII | NG P3 | Capital Renewal | 997,338 | EACH | 1 | \$997,316 | 5766 |
| Deficiency AISD ROOFING P1 AISD ROOFING P2 AISD ROOFING P3 AISD ROOFING P4 Exterior Deficiency Aluminum Window Replacement Note: beyond service life - rusted Location: courtyard and north Aluminum Window Replacement | Capital Renewal | 359,963 | EACH | 1 | \$359,955 | 5767 | |
| | | Sub Total for System | 4 | items | | \$4,125,172 | |
| Exterior | | | | | | | |
| Deficiency | | Category | Qty | UoM | Priority | Repair Cost | ID |
| Aluminum Wi | ndow Replacement | Capital Renewal | 2,720 | SF | 2 | \$271,257 | 5129 |
| No | beyond service life - rusted | | | | | | |
| Lo | ocation: courtyard and north | | | | | | |
| Aluminum Wi | ndow Replacement | Capital Renewal | 672 | SF | 2 | \$67,016 | 5131 |
| No | beyond service life - rusted | | | | | | |
| Lo | ocation: courtyards | | | | | | |
| Aluminum Wi | ndow Replacement | Capital Renewal | 288 | SF | 2 | \$28,721 | 5132 |
| No | beyond service life - rusted | | | | | | |
| Lo | ocation: courtyards | | | | | | |
| Metal Exterio | r Door Replacement | Capital Renewal | 42 | Door | 2 | \$155,694 | 5133 |

Note: beyond service life - rusted and damaged Overhead Door Replacement

beyond service life - rusted

Location: west side of building auto shop

Interior Deficiency

| Vinyl Composition Til | e Replacement | Capital Renewal | 80,198 SF | 4 | \$655,836 | 5146 |
|-----------------------|-------------------------|-----------------|-----------|---|-----------|------|
| Note: | beyond service life | | | | | |
| Location: | corridors and cafeteria | | | | | |
| Vinyl Composition Til | e Replacement | Capital Renewal | 16,040 SF | 4 | \$131,171 | 5147 |
| Note: | heyand service life | | | | | |

Capital Renewal

Category

Sub Total for System

Sub Total for System

3 Door

5 items

Qty UoM

2 items

Priority

\$24,922 5134

\$547,611

Repair Cost

\$787,007

Location: classrooms, office, and stairways

Mechanical

| MECHAINCAL | | | | | |
|----------------------------------|-----------------|---------|----------|-------------|------|
| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
| Air Cooled Condenser Replacement | Capital Renewal | 4 Ea. | 2 | \$83,784 | 5072 |
| Note: end of useful life | | | | | |
| Air Cooled Condenser Replacement | Capital Renewal | 1 Ea. | 2 | \$20,817 | 5073 |
| Note: end of useful life | | | | | |





Mechanical

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|--|-----------------|-----------|----------|-------------|------|
| Air Cooled Condenser Replacement | Capital Renewal | 1 Ea. | 2 | \$9,973 | 5074 |
| Note: end of useful life | | | | | |
| Air Cooled Condenser Replacement | Capital Renewal | 1 Ea. | 2 | \$11,586 | 5075 |
| Note: end of useful life | | | | | |
| Air Cooled Condenser Replacement | Capital Renewal | 1 Ea. | 2 | \$6,423 | 5076 |
| Note: end of useful life - equipment uses R-22 refrigerant and is obsolete | | | | | |
| Air Handler HVAC Component Replacement | Capital Renewal | 3 Ea. | 2 | \$129,490 | 5094 |
| Note: end of useful life | | | | | |
| Air Handler HVAC Component Replacement | Capital Renewal | 1 Ea. | 2 | \$43,163 | 5095 |
| Note: end of useful life | | | | | |
| Air Handler HVAC Component Replacement | Capital Renewal | 1 Ea. | 2 | \$85,959 | 5096 |
| Note: end of useful life | | | | | |
| Air Handler HVAC Component Replacement | Capital Renewal | 1 Ea. | 2 | \$85,959 | 5097 |
| Note: end of useful life | | | | | |
| Air Handler HVAC Component Replacement | Capital Renewal | 1 Ea. | 2 | \$29,014 | 5098 |
| Note: end of useful life | | | | | |
| Chiller HVAC Component Replacement | Capital Renewal | 2 Ea. | 2 | \$732,957 | 5069 |
| Note: end of useful life | | | | | |
| Chiller HVAC Component Replacement | Capital Renewal | 2 Ea. | 2 | \$136,220 | 5070 |
| Note: end of useful life | | | | | |
| Location: room 140 | | | | | |
| Copper Tube Boiler Replacement | Capital Renewal | 1 Ea. | 2 | \$32,565 | 5066 |
| Note: end of useful life | | | | | |
| Exterior Metal Cooling Tower Replacement | Capital Renewal | 1 Ea. | 2 | \$105,407 | 5071 |
| Note: end of useful life | | | | | |
| Location: mech yard | | | | | |
| Fan Coil (Chilled Water) HVAC Component Replacement | Capital Renewal | 33 Ea. | 2 | \$188,555 | 5077 |
| Note: end of useful life | • | | | | |
| Location: penthouses | | | | | |
| Fan Coil (Chilled Water) HVAC Component Replacement | Capital Renewal | 11 Ea. | 2 | \$37,291 | 5078 |
| Note: end of useful life | • | | | | |
| Gas Piping Replacement (SF Basis) | Capital Renewal | 91,655 SF | 2 | \$3,178,161 | 5055 |
| Note: 40% of system is at the end of useful life | • | | | | |
| Gas Unit Heater Replacement | Capital Renewal | 11 Ea. | 2 | \$36,439 | 5067 |
| Note: End of useful life | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 6 Ea. | 2 | \$145,415 | 5079 |
| Note: unit uses R-22 refrigerant and is obsolete | • | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 2 Ea. | 2 | \$63,447 | 5080 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 2 Ea. | 2 | \$63,447 | 5081 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 1 Ea. | 2 | \$24,236 | 5082 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 1 Ea. | 2 | \$24,236 | 5083 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 1 Ea. | 2 | \$15,909 | 5084 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 3 Ea. | 2 | \$192,781 | 5085 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| | | | | | |





Mechanical

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|---|----------------------|----------|----------|-------------|------|
| Package Roof Top Unit Replacement | Capital Renewal | 1 Ea. | 2 | \$31,723 | 5088 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 5 Ea. | 2 | \$79,546 | 5099 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Package Roof Top Unit Replacement | Capital Renewal | 4 Ea. | 2 | \$187,311 | 5100 |
| Note: unit uses R-22 refrigerant and is obsolete | | | | | |
| Location: roof | | | | | |
| Steam/HW Unit Heater Replacement | Capital Renewal | 22 Ea. | 2 | \$27,294 | 5068 |
| Note: end of useful life | | | | | |
| Circulation Pump Replacement | Capital Renewal | 2 Ea. | 3 | \$23,121 | 5090 |
| Note: end of useful life | · | | | | |
| Circulation Pump Replacement | Capital Renewal | 3 Ea. | 3 | \$34,682 | 5091 |
| Note: end of useful life | · | | | | |
| Circulation Pump Replacement | Capital Renewal | 2 Ea. | 3 | \$23,121 | 5092 |
| Note: end of useful life | · | | | | |
| Circulation Pump Replacement | Capital Renewal | 1 Ea. | 3 | \$14,381 | 5093 |
| Note: end of useful life | · | | | | |
| Energy Recovery Unit Replacement | Capital Renewal | 4 Ea. | 3 | \$80,463 | 5089 |
| Note: end of useful life | | | | , , | |
| Large Diameter Exhausts/Hoods Replacement | Capital Renewal | 44 Ea. | 3 | \$353,595 | 5102 |
| Note: end of useful life | | | - | ********** | *** |
| Make Up Air Equipment Replacement | Capital Renewal | 1 Ea. | 3 | \$8,888 | 5087 |
| Note: end of useful life | очрни полони | | Ü | φο,σσσ | 000. |
| Ceiling Exhaust Fan Replacement | Capital Renewal | 4 Ea. | 4 | \$1,947 | 5104 |
| Note: end of useful life | Capital Hollowal | , Lu. | • | ψ1,017 | 0101 |
| Chemistry Lab Fume Hood(s) Replacement | Capital Renewal | 1 Ea. | 4 | \$17,655 | 5105 |
| Note: end of useful life | Oupliar Nonewar | ı Lu. | 7 | ψ17,000 | 0100 |
| Kitchen Air/Exhaust Replacement | Capital Renewal | 2 Ea. | 4 | \$21,097 | 5101 |
| Note: end of useful life | Capital Nellewal | 2 La. | 4 | φ21,097 | 3101 |
| Wall Exhaust Fan Ventilation Replacement | Capital Renewal | 3 Ea. | 4 | \$14,194 | 5103 |
| Note: end of useful life | Capital Nellewal | 3 La. | 4 | φ14,194 | 3103 |
| Window AC Unit Component Replacement | Capital Renewal | 3 Ea. | 4 | \$9,256 | 5086 |
| Note: end of useful life | Capital Nellewal | 3 La. | 4 | φ9,230 | 3000 |
| Remove Abandoned Equipment | Deferred | 1 Ea. | 5 | ¢1 220 | 5107 |
| Remove Abandoned Equipment | Maintenance | ı Ea. | 3 | \$1,239 | 3107 |
| Note: remove abandoned in place air handling unit | | | | | |
| Location: basement mech room | | | | | |
| Remove Abandoned Equipment | Deferred | 1 Ea. | 5 | \$1,239 | 5108 |
| | Maintenance | | | | |
| Note: remove abandoned in place exhaust hood | | | | | |
| Location: hood room 508 | | | | | |
| | Sub Total for System | 43 items | | \$6,413,987 | |
| Electrical | | | | | |
| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
| Distribution Panel Replacement | Capital Renewal | 1 Ea. | 2 | \$16,905 | 5154 |
| Electrical Transformer Replacement | Capital Renewal | 1 Ea. | 2 | \$75,780 | 5153 |
| Electrical Transformer Replacement | Capital Renewal | 1 Ea. | 2 | \$7,287 | 5155 |
| Panelboard Replacement | Capital Renewal | 6 Ea. | 2 | \$16,692 | 5156 |
| Panelboard Replacement | Capital Renewal | 1 Ea. | 2 | \$5,500 | 5160 |
| Switchgear Replacement | Capital Renewal | 1 Ea. | 2 | \$38,387 | 5152 |
| - | Sub Total for System | 6 items | | \$160,551 | |
| | | | | , | |





Plumbing

| | | _ | | | | | |
|---|--|---|------------------|----------------------------|---------------|---|------------------------------------|
| Deficiency | | Category | | UoM | Priority | Repair Cost | ID |
| Backflow Preventer Ro | · | Capital Renewal | 1 | Ea. | 3 | \$7,685 | 5054 |
| Note: | end of useful life | 0 11 15 | | _ | | AT 004 | |
| Gas Water Heater Re | | Capital Renewal | 2 | Ea. | 3 | \$7,304 | 5053 |
| Note: | end of useful life | 0 11 15 | | 0= | | 4000 450 | |
| = | Nater Piping System Is Beyond Its Useful Life | Capital Renewal | 229,137 | SF | 3 | \$823,456 | 5056 |
| | throughout the building | 0 7 15 | 000 407 | 05 | • | #054.004 | 5057 |
| Sanitary Sewer Piping | • | Capital Renewal | 229,137 | SF | 3 | \$254,394 | 5057 |
| | throughout the building | Conital Day aveal | 0 | | 0 | 044.750 | 5000 |
| Shower Replacement | | Capital Renewal | 9 | Ea. | 3 | \$11,758 | 5060 |
| Note: | end of useful life | Deferred | 4 | Г. | 2 | ¢2.270 | FOCE |
| Sump Pump Replacer | nent | Deferred Maintenance | 4 | Ea. | 3 | \$2,270 | 5005 |
| Note: | end of useful life | | | | | | |
| Toilet Replacement | | Capital Renewal | 27 | Ea. | 3 | \$136,603 | 5061 |
| Note: | end of useful life | | | | | | |
| Urinal Replacement | | Capital Renewal | 5 | Ea. | 3 | \$6,771 | 5062 |
| Note: | end of useful life | · | | | | | |
| Custodial Mop Or Ser | vice Sink Replacement | Capital Renewal | 10 | Ea. | 4 | \$7,959 | 5059 |
| Note: | end of useful life | · | | | | | |
| Non-Refrigerated Drin | king Fountain Replacement | Capital Renewal | 19 | Ea. | 4 | \$45,292 | 5064 |
| Note: | end of useful life | · | | | | | |
| Restroom Lavatories | Plumbing Fixtures Replacement | Capital Renewal | 31 | Ea. | 4 | \$84,205 | 5058 |
| Note: | end of useful life | | | | | | |
| | | Sub Total for System | 11 | items | | \$1,387,697 | |
| Fire and Life S | afety | | | | | | |
| Deficiency | u.o.y | Category | Otv | UoM | Priority | Repair Cost | ID |
| Install Fire Sprinklers | | Functional Deficiency | 229,137 | | 1 | \$1,678,707 | |
| Note: | missing | Turiolional Bendiency | 223,107 | O. | | ψ1,070,707 | 0100 |
| Note. | Thissing | Sub Total for System | 1 | items | | \$1,678,707 | |
| Charialtica | | oub rotal for dyotom | • | 1101110 | | \$1,010,101 | |
| Specialties | | 0.4 | 0. | | D : :: | 5 . 6 . | |
| Deficiency | | Category | | UoM - | Priority | Repair Cost | ID |
| Metal Gym Locker Re | | Capital Renewal | 48 | Ea. | 4 | \$23,304 | 5165 |
| Note: | beyond service life | | | | | | |
| Location: | snop area | 0.1.799160.94 | | | | | |
| 0.1.7.4.14 | | | | | | *** | |
| | - 0404 Main building includes Administration Offic | Sub Total for System | | items | | \$23,304 | |
| | ng 019A - Main building includes Administration Offic | | | items | | \$23,304 \$15,124,035 | |
| | ng 019A - Main building includes Administration Offic 9B - Theater Building | | | | | | |
| Building: 01 | | | | | | | |
| Building: 01 Exterior | | es, Classrooms, Cafeteria, & Gym. | 73 | items | Priority | \$15,124,035 | ID |
| Building: 01 Exterior Deficiency | 9B - Theater Building | es, Classrooms, Cafeteria, & Gym. Category | 73 Qty | items UoM | Priority 2 | \$15,124,035 Repair Cost | ID 5140 |
| Building: 01 Exterior Deficiency Metal Exterior Door Re | 9B - Theater Building | es, Classrooms, Cafeteria, & Gym. | 73 Qty | items | Priority 2 | \$15,124,035 | ID 5140 |
| Building: 01 Exterior Deficiency Metal Exterior Door Ro | 9B - Theater Building eplacement beyond service life - damaged | es, Classrooms, Cafeteria, & Gym. Category | 73 Qty | items UoM | <u>_</u> _ | \$15,124,035 Repair Cost | |
| Building: 01 Exterior Deficiency Metal Exterior Door Ro | 9B - Theater Building | Category Capital Renewal | Qty 3 | UoM Door | <u>_</u> _ | \$15,124,035 Repair Cost \$11,121 | |
| Building: 01 Exterior Deficiency Metal Exterior Door Re Note: Location: | 9B - Theater Building eplacement beyond service life - damaged | es, Classrooms, Cafeteria, & Gym. Category | Qty 3 | items UoM | <u>_</u> _ | \$15,124,035 Repair Cost | |
| Building: 01 Exterior Deficiency Metal Exterior Door Re Note: Location: Mechanical | 9B - Theater Building eplacement beyond service life - damaged | Category Capital Renewal Sub Total for System | Qty 3 | UoM Door items | 2 | \$15,124,035 Repair Cost \$11,121 | 5140 |
| Building: 01 Exterior Deficiency Metal Exterior Door Re Note: Location: Mechanical Deficiency | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors | Category Capital Renewal Sub Total for System Category | 73 Qty 3 1 | UoM Door items | 2 Priority | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost | 5140 ID |
| Building: 01 Exterior Deficiency Metal Exterior Door Revolution: Note: Location: Mechanical Deficiency Air Handler HVAC Con | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors | Category Capital Renewal Sub Total for System | 73 Qty 3 1 | UoM Door items | 2 | \$15,124,035 Repair Cost \$11,121 | 5140 |
| Building: 01 Exterior Deficiency Metal Exterior Door Re Note: Location: Mechanical Deficiency Air Handler HVAC Cor Note: | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life | Category Capital Renewal Sub Total for System Category Capital Renewal | 2 Qty Qty 2 | UoM Door items UoM Ea. | Priority | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 | 5140 ID 5123 |
| Building: 01 Exterior Deficiency Metal Exterior Door Re Note: Location: Mechanical Deficiency Air Handler HVAC Cor Note: Air Handler HVAC Cor | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement | Category Capital Renewal Sub Total for System Category | 2 Qty Qty 2 | UoM Door items | 2 Priority | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost | 5140 ID 5123 |
| Building: 01 Exterior Deficiency Metal Exterior Door Relector Location: Mechanical Deficiency Air Handler HVAC Connector Note: Air Handler HVAC Connector Note: | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement end of useful life | Category Capital Renewal Sub Total for System Category Capital Renewal Category Capital Renewal Capital Renewal | Qty 3 1 Qty 2 | UoM Door items UoM Ea. | Priority 2 | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 \$29,014 | 5140 ID 5123 5124 |
| Building: 01 Exterior Deficiency Metal Exterior Door Release Location: Mechanical Deficiency Air Handler HVAC Connected Note: Air Handler HVAC Connected Note: Copper Tube Boiler Release Note | eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement end of useful life eplacement | Category Capital Renewal Sub Total for System Category Capital Renewal | Qty 3 1 Qty 2 | UoM Door items UoM Ea. | Priority | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 | 5140 ID 5123 5124 |
| Building: 01 Exterior Deficiency Metal Exterior Door Review Location: Mechanical Deficiency Air Handler HVAC Comercial Air Handler HVAC Comercial Note: Copper Tube Boiler Review Note: | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement end of useful life eplacement end of useful life eplacement end of useful life | Category Capital Renewal Sub Total for System Category Capital Renewal Category Capital Renewal Capital Renewal | Qty 3 1 Qty 2 | UoM Door items UoM Ea. | Priority 2 | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 \$29,014 | 5140 ID 5123 5124 |
| Building: 01 Exterior Deficiency Metal Exterior Door Ronate: Location: Mechanical Deficiency Air Handler HVAC Connote: Air Handler HVAC Connote: Copper Tube Boiler Ronate: Note: | eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement end of useful life eplacement | Category Capital Renewal Sub Total for System Category Capital Renewal Category Capital Renewal Capital Renewal | Qty 3 1 Qty 2 | UoM Door items UoM Ea. | Priority 2 | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 \$29,014 | 5140 ID 5123 5124 |
| Building: 01 Exterior Deficiency Metal Exterior Door Ronate: Location: Mechanical Deficiency Air Handler HVAC Connote: Air Handler HVAC Connote: Copper Tube Boiler Ronate: Location: | 9B - Theater Building eplacement beyond service life - damaged south and west exit doors mponent Replacement end of useful life mponent Replacement end of useful life eplacement end of useful life eplacement end of useful life | Category Capital Renewal Sub Total for System Category Capital Renewal Category Capital Renewal Capital Renewal | Qty 3 1 Qty 2 | UoM Door items UoM Ea. Ea. | Priority 2 | \$15,124,035 Repair Cost \$11,121 \$11,121 Repair Cost \$171,918 \$29,014 | 5140 ID 5123 5124 5119 |





Mechanical

| Wiechanicai | | | | | | | |
|-------------------------|---|----------------------------------|----------|--------|----------|---------------------|------|
| Deficiency | | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Circulation Pump Rep | placement | Capital Renewal | 2 E | a. | 3 | \$23,121 | 5122 |
| Note: | end of useful life | | | | | | |
| Circulation Pump Rep | | Capital Renewal | 1 E | a. | 4 | \$6,850 | 5121 |
| Note: | end of useful life | | | | | | |
| | | Sub Total for System | 6 it | tems | | \$309,628 | |
| Plumbing | | | | | | | |
| Deficiency | | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Backflow Preventer R | Replacement | Capital Renewal | 1 E | a. | 3 | \$879 | 5114 |
| Sump Pump Replace | ment | Deferred | 2 E | a. | 3 | \$1,135 | 5118 |
| | | Maintenance | | | | | |
| Note: | end of useful life | 0 "15 | 4 - | - | | # 700 | 5440 |
| · · | rvice Sink Replacement | Capital Renewal | 1 E | a. | 4 | \$796 | 5116 |
| Note: | end of useful life | 0 110 | | _ | | ^ | |
| = | nking Fountain Replacement | Capital Renewal | 3 E | a. | 4 | \$7,151 | 5117 |
| Note: | end of useful life | | | _ | | | |
| | Plumbing Fixtures Replacement | Capital Renewal | 10 E | a. | 4 | \$27,163 | 5115 |
| Note: | end of useful life | | | | | | |
| | | Sub Total for System | 5 it | tems | | \$37,123 | |
| Fire and Life S | Safety | | | | | | |
| Deficiency | | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Fire Sprinkler System | Replacement (SF Basis) | Capital Renewal | 10,851 S | SF. | 1 | \$113,046 | 5125 |
| Note: | end of useful life | | | | | | |
| | | Sub Total for System | 1 it | tems | | \$113,046 | |
| | Sub Total for | Building 019B - Theater Building | 13 it | tems | | \$470,919 | |
| Building: 01 | 9C - Stand-Alone Classroom Bu | ıildina | | | | | |
| • | 190 - Stand-Alone Glassicom Bt | manig | | | | | |
| Exterior | | | | | | | |
| Deficiency | | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Metal Exterior Door F | Replacement | Capital Renewal | 9 🛭 | Ooor | 2 | \$33,363 | 5136 |
| Note: | beyond service life - rusted | | | | | | |
| | | Sub Total for System | 1 it | tems | | \$33,363 | |
| Fire and Life S | Safety | | | | | | |
| Deficiency | • | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Install Fire Sprinklers | | Functional Deficiency | 24,939 S | | 1 | \$182,708 | 5109 |
| Note: | missing | ŕ | , | | | . , | |
| | G | Sub Total for System | 1 it | tems | | \$182,708 | |
| | Sub Total for Building 019C - | Stand-Alone Classroom Building | | tems | | \$216,071 | |
| Duilding, 04 | <u> </u> | g | | | | * =, | |
| Building: U | 9D - Mechanical Building | | | | | | |
| Mechanical | | | | | | | |
| Deficiency | | Category | Qty L | JoM F | Priority | Repair Cost | ID |
| Air Cooled Condense | r Replacement | Capital Renewal | 1 E | a. | 2 | \$20,817 | 5111 |
| Note: | end of useful life - equipment uses R-22 refrigerant and is | sobsolete | | | | | |
| Location: | mech yard | | | | | | |
| Chiller HVAC Compo | nent Replacement | Capital Renewal | 1 E | a. | 2 | \$104,497 | 5110 |
| Note: | end of useful life - equipment uses R-22 refrigerant and is | s obsolete | | | | | |
| Location: | mech room | | | | | | |
| Circulation Pump Rep | | Capital Renewal | 1 E | a. | 3 | \$11,561 | 5112 |
| Note: | end of useful life | 2 - F | | | - | Ţ, 0 51 | |
| | mech room | | | | | | |
| | ntilation Replacement | Capital Renewal | 1 E | - - | 4 | \$4,731 | 5112 |
| | | Capital Reliewal | 1 5 | _a. | 4 | φ 4 ,/31 | 0110 |
| Note: | end of useful life | | | | | | |
| Location: | mech room | 0.1.7 | | | | A444 | |
| | | Sub Total for System | | tems | | \$141,606 | |
| | Sub Total for Bui | Iding 019D - Mechanical Building | | tems | | \$141,606 | |
| | | Total for Campus | 96 it | tems | | \$18,436,547 | |
| | | | | | | | |





Buildings with no reported deficiencies

019E - Restrooms and Storage

M•A•P•P•S ©, Jacobs 2022 14



Liberal Arts and Science Academy - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|-----------------------------------|--------------------------|--------|-------|-------------|----------------|
| Fences and Gates | Fencing - Chain Link (8-10 Ft) | | 5,625 | LF | \$440,690 | 5 |
| Parking Lot Pavement | Asphalt | | 210 | CAR | \$304,668 | 5 |
| | Note: Northwest parking lot | | | | | |
| Pedestrian Pavement | Sidewalks - Concrete | | 20,467 | SF | \$231,834 | 7 |
| Roadway Pavement | Asphalt Driveways | | 27,318 | SF | \$175,666 | 10 |
| Parking Lot Pavement | Asphalt | | 48 | CAR | \$69,639 | 10 |
| | Note: East and South parking lots | | | | | |
| | | Sub Total for System | 5 | items | \$1,222,498 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Parking Lot Lighting | Pole Lighting | | 5 | Ea. | \$29,098 | 5 |
| | | Sub Total for System | 1 | items | \$29,098 | |
| | | Sub Total for Building - | 6 | items | \$1,251,596 | |

Building: 019A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

| Uniformat Description | LC Type Description | Qty | UoM | Repair Cost | Remaining Life |
|----------------------------|-----------------------------------|------------------------|-------|-------------|----------------|
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | 22,914 | SF | \$40,116 | 2 |
| Exterior Operating Windows | Aluminum - Windows per SF | 3,400 | SF | \$339,071 | 3 |
| Exterior Entrance Doors | Steel - Insulated and Painted | 89 | Door | \$329,923 | 3 |
| Exterior Operating Windows | Aluminum - Windows per SF | 88 | SF | \$8,776 | 4 |
| Exterior Utility Doors | Overhead Door | 1 | Door | \$8,307 | 5 |
| Exterior Wall Veneer | Metal Panel - Bldg SF basis | 22,914 | SF | \$81,851 | 7 |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | 22,914 | SF | \$40,116 | 9 |
| | | Sub Total for System 7 | items | \$848,161 | |

Interior

| Uniformat Description | LC Type Description | | Qty UoM | Panair Coat | Remaining Life |
|--|-----------------------------------|----------------------|----------|---------------|----------------|
| <u> </u> | | | | | |
| Compartments and Cubicles | Toilet Partitions | | 3 Stall | \$6,049 | 2 |
| Interior Swinging Doors | Wooden Door | | 02 Door | \$753,991 | 2 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | 80, | 98 SF | \$270,809 | 3 |
| Suspended Plaster and | Painted ceilings | 142, | 65 SF | \$295,864 | 3 |
| Tile Flooring | Quarry Tile | 2, | 91 SF | \$62,628 | 3 |
| Wall Paneling | Wood Panel wall | 4, | 83 SF | \$71,871 | 4 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | 137, | 82 SF | \$616,046 | 4 |
| Interior Swinging Doors | Metal Door (Steel) | | 16 Door | \$46,301 | 4 |
| Interior Door Supplementary Components | Door Hardware | | 70 Door | \$697,765 | 4 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Grid System | 80, | 98 SF | \$333,964 | 5 |
| Compartments and Cubicles | Toilet Partitions | | 29 Stall | \$58,478 | 5 |
| Athletic Flooring | Athletic/Sport Flooring | 6, | 74 SF | \$105,457 | 5 |
| Resilient Flooring | Vinyl Composition Tile Flooring | 73, | 24 SF | \$599,623 | 5 |
| Carpeting | Carpet | 11, | 157 SF | \$145,048 | 6 |
| Resilient Flooring | Vinyl Composition Tile Flooring | 11, | 157 SF | \$93,692 | 9 |
| Tile Wall Finish | Ceramic Tile wall | 18, | 31 SF | \$152,181 | 10 |
| Interior Swinging Doors | Wooden Door | | 52 Door | \$97,531 | 10 |
| | | Sub Total for System | 17 items | s \$4,407,299 | |

Mechanical

| Uniformat Description | LC Type Description | Qty UoM | Repair Cost Remaining Life |
|---|---------------------------------|------------|----------------------------|
| Heat Generation | Boiler - Copper Tube (750 MBH) | 2 Ea. | \$65,129 3 |
| Heating System Supplementary Components | Controls - DDC (Bldg.SF) | 160,396 SF | \$432,624 3 |
| Heating System Supplementary Components | Controls - Electronic (Bldg.SF) | 68,741 SF | \$106,366 3 |
| Facility Hydronic Distribution | Pump - 1HP or Less (Ea.) | 2 Ea. | \$8,626 3 |
| Facility Hydronic Distribution | Pump - 5HP | 2 Ea. | \$13,700 3 |





\$112,838

\$156,841

\$17,605

31 Ea.

13 Ea.

5

5

Mechanical

Plumbing Fixtures

Plumbing Fixtures

Plumbing Fixtures

Classroom Lavatory

Toilets

Urinals

| Mechanicai | | | | | | |
|---------------------------------|---|----------------------|---------|-------|-------------|---------------|
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Lif |
| Exhaust Air | Kitchen Exhaust Hoods | | 2 | Ea. | \$22,383 | 3 |
| Heat Generation | Boiler - Copper Tube (2400 MBH) | | 1 | Ea. | \$97,435 | 4 |
| Decentralized Cooling | Fan Coil - Water Cool/Water Heat (5 Ton) | | 20 | Ea. | \$114,276 | 4 |
| Decentralized Cooling | Fan Coil - Water Cool/Water Heat (3 Ton) | | 7 | Ea. | \$23,730 | 4 |
| Air Distribution | Make-up Air Unit | | 1 | Ea. | \$8,888 | 4 |
| Decentralized Cooling | Condenser - Outside Air Cooled (3 Tons) | | 2 | Ea. | \$12,845 | 5 |
| HVAC Air Distribution | Roof Top Unit - DX Gas (5 Ton) | | 1 | Ea. | \$15,909 | 5 |
| Facility Hydronic Distribution | 2-Pipe System (Cold) | | 229,137 | SF | \$409,736 | 5 |
| Facility Hydronic Distribution | 2-Pipe Water System (Hot) | | 229,137 | SF | \$974,756 | 5 |
| HVAC Air Distribution | AHU 10,000 CFM Interior | | 2 | Ea. | \$171,918 | 5 |
| HVAC Air Distribution | Ductwork (Bldg.SF) | | 229,137 | SF | \$1,813,034 | 5 |
| HVAC Air Distribution | VAV Boxes / Terminal Device | | 3 | Ea. | \$11,622 | 5 |
| Exhaust Air | Roof Exhaust Fan - Large | | 13 | Ea. | \$104,471 | 5 |
| Heat Generation | Boiler - Copper Tube (200 MBH) | | 1 | Ea. | \$17,428 | 8 |
| Heat Generation | Boiler - Copper Tube (2400 MBH) | | 2 | Ea. | \$194,871 | 8 |
| Decentralized Cooling | Ductless Split System (1 Ton) | | 2 | Ea. | \$6,008 | 8 |
| Decentralized Cooling | Fan Coil - D/X Only (1.5 Ton) | | 6 | Ea. | \$8,915 | 8 |
| HVAC Air Distribution | Roof Top Unit - DX Gas (5 Ton) | | 2 | Ea. | \$31,818 | 8 |
| Other HVAC Distribution Systems | VFD (20 HP) | | 2 | Ea. | \$17,635 | 8 |
| Facility Hydronic Distribution | Pump - 1HP or Less (Ea.) | | 7 | Ea. | \$30,192 | 8 |
| Facility Hydronic Distribution | Pump - 5HP | | 1 | Ea. | \$6,850 | 8 |
| Facility Hydronic Distribution | Pump - 5HP | | 1 | Ea. | \$6,850 | 8 |
| Facility Hydronic Distribution | Pump - 5HP | | 1 | Ea. | \$6,850 | 8 |
| Heat Generation | Boiler - Copper Tube (750 MBH) | | 1 | Ea. | \$32,565 | 10 |
| Heat Generation | Boiler - Copper Tube (750 MBH) | | 1 | Ea. | \$32,565 | 10 |
| Central Cooling | Chiller - Indoor Water Cooled (300 ton) | | 2 | Ea. | \$732,957 | 10 |
| Central Cooling | Chiller - Indoor Water Cooled (50 Tons) | | 2 | Ea. | \$136,220 | 10 |
| Central Cooling | Cooling Tower - Metal (750 Tons) | | 1 | Ea. | \$105,407 | 10 |
| Facility Hydronic Distribution | Pump- 10HP (Ea.) | | 2 | Ea. | \$23,121 | 10 |
| Facility Hydronic Distribution | Pump- 10HP (Ea.) | | 3 | Ea. | \$34,682 | 10 |
| Facility Hydronic Distribution | Pump- 10HP (Ea.) | | 2 | Ea. | \$23,121 | 10 |
| Facility Hydronic Distribution | Pump- 25HP (Ea.) | | 1 | Ea. | \$14,381 | 10 |
| | | Sub Total for System | 37 | items | \$5,869,883 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Li |
| Electrical Service | Switchgear - Main Dist Panel (3000 Amps) | | 1 | Ea. | \$68,027 | 5 |
| Electrical Service | Transformer (225 KVA) | | 1 | Ea. | \$18,241 | 5 |
| Power Distribution | Distribution Panel (1600 Amps) | | 1 | Ea. | \$25,176 | 5 |
| Power Distribution | Distribution Panels (800 Amps) | | 5 | Ea. | \$92,820 | 5 |
| Power Distribution | Distribution Panels (400 Amps) | | 2 | Ea. | \$33,810 | 5 |
| Electrical Service | Transformer (75 KVA) | | 2 | Ea. | \$14,575 | 5 |
| Electrical Service | Transformer (30 KVA) | | 1 | Ea. | \$5,519 | 5 |
| Power Distribution | Panelboard - 120/208 100A | | 10 | Ea. | \$27,820 | 5 |
| Power Distribution | Panelboard - 120/208 225A | | 10 | Ea. | \$54,995 | 5 |
| Power Distribution | Panelboard - 120/208 125A | | 1 | Ea. | \$1,459 | 5 |
| Power Distribution | Panelboard - 277/480 225A | | 1 | Ea. | \$9,372 | 5 |
| Power Distribution | Panelboard - 120/208 400A | | 1 | Ea. | \$12,342 | 5 |
| Power Distribution | Panelboard - 120/208 225A | | 1 | Ea. | \$5,500 | 5 |
| Audio-Video Systems | PA Communications No Head Unit (Bldg SF) | | 229,137 | SF | \$162,201 | 8 |
| Distributed Systems | Public Address System Head End Unit | | | Ea. | \$7,307 | 8 |
| Lighting Fixtures | Light Fixtures (Bldg SF) | | 229,137 | | \$4,202,038 | 10 |
| 5 5 | J | Sub Total for System | | items | \$4,741,203 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Li |
| Compressed-Air Systems | Air Compressor (5 hp) | | 1 | Ea. | \$5,645 | 4 |
| Plumbing Fixtures | Restroom Lavatory | | 35 | Ea. | \$95,070 | 4 |
| Plumbing Fixtures | Showers | | 16 | Ea. | \$20,903 | 4 |
| D F | | | | _ | | _ |

M•A•P•P•S ©, Jacobs 2022 16





| В | ı. | | _ | L | | _ | _ |
|---|----|----|---|----------|---|---|---|
| Ρ | IJ | JI | ш | IN | Ш | | ч |

| Plumbing | | | | | | |
|--|---|-------------------------------|---------|------------|------------------|---------------------|
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Domestic Water Equipment | Backflow Preventers - 3/4 in. (Ea.) | | 1 | Ea. | \$879 | 6 |
| Domestic Water Equipment | Water Heater - Gas - 30 gallon | | 2 | Ea. | \$7,304 | 10 |
| Domestic Water Equipment | Gas Piping System (BldgSF) | | 137,482 | SF | \$4,767,225 | 10 |
| Plumbing Fixtures | Non-Refrigerated Drinking Fountain | | 19 | Ea. | \$45,292 | 10 |
| | | Sub Total for System | 10 | items | \$5,229,602 | |
| Conveyances | | | | | | |
| - | LC Turns Description | | 04. | HaM | Danair Cast | Romaining Life |
| Uniformat Description Elevators | LC Type Description | | | UoM Ea. | \$7,985 | Remaining Life 5 |
| Lievators | Passenger elevator cab finishes | Sub Total for System | | items | \$7,985 | 3 |
| 6 | | oub rotarior system | ' | items | φ1,905 | |
| Specialties | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Casework | Lockers, Gym | | 42 | Ea. | \$20,391 | 2 |
| Fixed Multiple Seating | Bleachers | | 600 | Seat | \$247,865 | 10 |
| | | Sub Total for System | 2 | items | \$268,256 | |
| Sub Total for Building 019A - N | flain building includes Administration Offices, | Classrooms, Cafeteria, & Gym. | 90 | items | \$21,372,387 | |
| Building: 019B - Theater | Ruilding | | | | | |
| Ballallig. 010B Tileater | Bananig | | | | | |
| Exterior | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | - | | SF | \$571 | 2 |
| Exterior Entrance Doors | Steel - Insulated and Painted | | 2 | Door | \$7,414 | 3 |
| Exterior Utility Doors | Overhead Door | | 1 | Door | \$8,307 | 5 |
| Exterior Operating Windows | Aluminum - Windows per SF | | 192 | SF | \$19,148 | 8 |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | | 326 | | \$571 | 9 |
| Exterior Wall Veneer | Metal Panel - Bldg SF basis | | | SF | \$1,165 | 10 |
| | | Sub Total for System | | items | \$37,175 | |
| Intorior | | | - | | ***,*** | |
| Interior | | | | | | |
| Uniformat Description | LC Type Description | | | UoM | | Remaining Life |
| Resilient Flooring | Vinyl Composition Tile Flooring | | 1,628 | | \$13,313 | 2 |
| Wood Flooring | Wood Flooring - All Types | | 1,085 | | \$23,371 | 2 |
| Wall Paneling | Wood Panel wall | | | SF | \$3,403 | 3 |
| Suspended Plaster and | Painted ceilings | | 7,596 | | \$15,819 | 4 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | | 8,681 | SF | \$38,899 | 4 |
| Compartments and Cubicles | Toilet Partitions | | 6 | Stall | \$12,099 | 4 |
| Interior Door Supplementary Components | Door Hardware | | 24 | Door | \$35,631 | 4 |
| Interior Swinging Doors | Wooden Door | | 24 | Door | \$45,014 | 5 |
| Carpeting | Carpet | | 1,845 | SF | \$23,358 | 6 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | | 1,085 | SF | \$3,664 | 8 |
| Tile Flooring | Ceramic Tile | | 868 | SF | \$15,335 | 9 |
| | | Sub Total for System | 11 | items | \$229,906 | |
| Mechanical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Heating System Supplementary | Controls - Electronic (Bldg.SF) | | 10,851 | SF | \$16,790 | 3 |
| Components | , , | | | | | |
| Facility Hydronic Distribution | 2-Pipe System (Cold) | | 10,851 | SF | \$19,403 | 5 |
| HVAC Air Distribution | Ductwork (Bldg.SF) | | 10,851 | SF | \$85,858 | 5 |
| Heat Generation | Boiler - Copper Tube (750 MBH) | | 1 | Ea. | \$32,565 | 10 |
| Facility Hydronic Distribution | Pump - 5HP | | 1 | Ea. | \$6,850 | 10 |
| Facility Hydronic Distribution | Pump- 10HP (Ea.) | | 2 | Ea. | \$23,121 | 10 |
| | | Sub Total for System | 6 | items | \$184,587 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qtv | UoM | Repair Cost | Remaining Life |
| Lighting Fixtures | Building Mounted Fixtures (Ea.) | | | Ea. | \$3,607 | 4 |
| Electrical Service | Transformer (112.5 KVA) | | | Ea. | \$9,908 | 8 |
| Power Distribution | Distribution Panels (400 Amps) | | | Ea. | \$33,810 | 8 |
| Power Distribution | Panelboard - 120/208 100A | | | Ea. | \$2,782 | 8 |
| Power Distribution | Panelboard - 277/480 100A | | | Ea. | | 8 |
| | | | | | \$6,688 \$715 | |
| Packaged Generator Assemblies | Exterior Electrical Enclosure | | 1 | Ea. | \$715 | 8 |





Electrical

| Uniformat Description | LC Type Description | | _ | | | |
|--|--|--|--|---|---|--|
| | LO Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Power Distribution | Power Wiring | | 10,851 | SF | \$12,888 | 10 |
| | | Sub Total for System | 7 | items | \$70,399 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Plumbing Fixtures | Toilets | | | Ea. | \$35,416 | 4 |
| Plumbing Fixtures | Urinals | | 2 | Ea. | \$2,708 | 4 |
| Domestic Water Equipment | Gas Piping System (BldgSF) | | 10,851 | SF | \$376,261 | 10 |
| Domestic Water Piping | Domestic Water Piping System (Bldg.SF) | | 10,851 | SF | \$38,996 | 10 |
| Sanitary Sewerage Piping | Sanitary Sewer Piping | | 10,851 | SF | \$12,047 | 10 |
| Plumbing Fixtures | Non-Refrigerated Drinking Fountain | | 3 | Ea. | \$7,151 | 10 |
| | | Sub Total for System | 6 | items | \$472,579 | |
| Fire and Life Safety | | | | | | |
| Uniformat Description | LC Type Description | | Otv | UoM | Repair Cost | Remaining Life |
| Fire Detection and Alarm | Fire Alarm Panel | | | Ea. | \$6,868 | 5 |
| Fire Detection and Alarm | Fire Alarm | | 10,851 | | \$17,229 | 6 |
| | | Sub Total for System | | items | \$24,097 | |
| Specialties | | | _ | | V =1,000 | |
| Specialties | | | | | | |
| Uniformat Description | LC Type Description | | | UoM | | Remaining Life |
| Fixed Multiple Seating | Auditorium Seating | | 336 | | \$150,733 | 5 |
| Casework | Fixed Cabinetry | | | Room | \$44,009 | 8 |
| | | Sub Total for System | | items | \$194,742 | |
| | Sub Total for Build | ding 019B - Theater Building | 40 | items | \$1,213,486 | |
| Exterior Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| • | | | 000 | CE | \$00 E74 | 2 |
| Exterior Operating Windows | Aluminum - Windows per SF | | 828 | | \$82,574 | 2 |
| Exterior Operating Windows Exterior Wall Veneer | Aluminum - Windows per SF Exterior Painting - Bldg SF basis | | 748 | SF | \$1,310 | 4 |
| Exterior Operating Windows | Aluminum - Windows per SF | Sub Total for System | 748 748 | SF SF | \$1,310 \$2,672 | |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer | Aluminum - Windows per SF Exterior Painting - Bldg SF basis | Sub Total for System | 748 748 | SF | \$1,310 | 4 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis | Sub Total for System | 748 748 3 | SF SF items | \$1,310 \$2,672 \$86,555 | 4 10 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description | Sub Total for System | 748 748 3 Qty | SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost | 4 10 Remaining Life |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring | Sub Total for System | 748 748 3 Qty | SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 | 4 10 Remaining Life |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) | Sub Total for System | 748 748 3 Qty 13,467 23,443 | SF SF items UoM SF SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 | 4 10 Remaining Life 3 4 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 | SF SF items UoM SF SF SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 | 4 10 Remaining Life 3 4 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 | SF SF items UoM SF SF SF SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 | 4 10 Remaining Life 3 4 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 | SF SF items UoM SF SF SF SF Stall | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 | 4 10 Remaining Life 3 4 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 | SF SF items UoM SF SF SF SF Stall SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 | 4 10 Remaining Life 3 4 5 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 | SF SF items UoM SF SF SF SF Stall SF Door | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 | 4 10 Remaining Life 3 4 5 5 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings | Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 | SF SF items UoM SF SF SF SF Stall SF Door SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 | 4 10 Remaining Life 3 4 5 5 5 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 | SF SF items UoM SF SF SF SF Stall SF Door SF SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 | 4 10 Remaining Life 3 4 5 5 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings | Sub Total for System Sub Total for System | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 | SF SF items UoM SF SF SF SF Stall SF Door SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 | 4 10 Remaining Life 3 4 5 5 5 5 5 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 | SF SF SF Stall SF Door SF SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 | 4 10 Remaining Life 3 4 5 5 5 5 5 5 5 8 9 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 | SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 | Remaining Life 3 4 5 5 5 5 8 9 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 | SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost | Remaining Life 3 4 5 5 5 5 8 9 Remaining Life |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) | | 748 748 3 Qty 13,467 23,443 20,699 11 1,247 78 3,990 9,976 9 Qty 1 1 | SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 | Remaining Life 3 4 5 5 5 5 8 9 Remaining Life 3 3 3 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution Decentralized Cooling | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) | | 748 748 3 Qty 13,467 23,443 20,699 11 1,247 78 3,990 9,976 9 Qty 1 1 16 | SF SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$21,5 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 | 4 10 Remaining Life 3 4 5 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution Decentralized Cooling Heat Generation | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 1 16 1 | SF SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$21,5 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$11,561 \$91,421 \$32,565 | 4 10 Remaining Life 3 4 5 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution Decentralized Cooling | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) | | 748 748 3 Qty 13,467 23,443 20,699 11 1,247 78 3,990 9,976 9 Qty 1 1 16 | SF SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$21,5 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 | 4 10 Remaining Life 3 4 5 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 1 16 1 24,939 | SF SF SF SF Stall SF Door SF SF items | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$21,5 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$11,561 \$91,421 \$32,565 | 4 10 Remaining Life 3 4 5 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary Components | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) Controls - DDC (Bldg.SF) | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 16 1 24,939 | SF SF SF Stall SF Door SF SF items UoM Ea. Ea. Ea. SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 \$32,565 \$67,266 | 4 10 Remaining Life 3 4 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 8 8 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Interior Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary Components Air Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) Controls - DDC (Bldg.SF) Make-up Air Unit | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 16 1 24,939 | SF SF SF SF Stall SF Door SF SF items UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea. | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 \$32,565 \$67,266 \$8,888 | 4 10 Remaining Life 3 4 5 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 8 8 8 8 8 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary Components Air Distribution Facility Hydronic Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) Controls - DDC (Bldg.SF) Make-up Air Unit Pump - 1HP or Less (Ea.) | | 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 16 1 24,939 | SF SF SF SF Stall SF Door SF SF items UoM Ea. Ea. Ea. Ea. SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 \$32,565 \$67,266 \$8,888 \$4,313 | 4 10 Remaining Life 3 4 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 8 8 8 8 8 8 8 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary Components Air Distribution Facility Hydronic Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) Controls - DDC (Bldg.SF) Make-up Air Unit Pump - 1HP or Less (Ea.) 2-Pipe System (Cold) | | 748 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 16 1 24,939 1 24,939 24,939 | SF SF SF SF Stall SF Door SF SF items UoM Ea. Ea. Ea. Ea. SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$91,421 \$32,565 \$67,266 \$8,888 \$4,313 \$44,595 | 4 10 Remaining Life 3 4 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 8 8 8 8 8 10 |
| Exterior Operating Windows Exterior Wall Veneer Exterior Wall Veneer Uniformat Description Resilient Flooring Wall Painting and Coating Acoustical Suspended Ceilings Acoustical Suspended Ceilings Compartments and Cubicles Tile Flooring Interior Door Supplementary Components Suspended Plaster and Resilient Flooring Mechanical Uniformat Description Facility Hydronic Distribution Decentralized Cooling Heat Generation Heating System Supplementary Components Air Distribution Facility Hydronic Distribution | Aluminum - Windows per SF Exterior Painting - Bldg SF basis Metal Panel - Bldg SF basis Metal Panel - Bldg SF basis LC Type Description Vinyl Composition Tile Flooring Painting/Staining (Bldg SF) Ceilings - Acoustical Tiles Ceiling Exposed Metal Structure Toilet Partitions Ceramic Tile Door Hardware Painted ceilings Vinyl Composition Tile Flooring LC Type Description Pump- 10HP (Ea.) Pump- 10HP (Ea.) Fan Coil - Water Cool/Water Heat (5 Ton) Boiler - Copper Tube (750 MBH) Controls - DDC (Bldg.SF) Make-up Air Unit Pump - 1HP or Less (Ea.) 2-Pipe System (Cold) 2-Pipe Water System (Hot) | | 748 748 748 3 Qty 13,467 23,443 20,699 249 11 1,247 78 3,990 9,976 9 Qty 1 16 1 24,939 1 24,939 24,939 1 | SF SF SF SF SSF Stall SF Door SF SF items UoM Ea. Ea. Ea. Ea. SF | \$1,310 \$2,672 \$86,555 Repair Cost \$110,129 \$105,046 \$69,895 \$215 \$22,181 \$22,031 \$115,799 \$8,310 \$81,581 \$535,189 Repair Cost \$11,561 \$11,561 \$91,421 \$32,565 \$67,266 \$8,888 \$4,313 \$44,595 \$106,091 | 4 10 Remaining Life 3 4 5 5 5 5 8 9 9 Remaining Life 3 3 3 5 8 8 8 8 8 10 10 10 |





Electrical

| Electrical | | | | | | |
|----------------------------------|---|------------------------------|--------|-------|---------------------------------------|----------------|
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Power Distribution | Distribution Panels (400 Amps) | | 1 | Ea. | \$16,905 | 5 |
| Power Distribution | Panelboard - 120/208 125A | | 1 | Ea. | \$1,459 | 5 |
| Power Distribution | Panelboard - 120/208 100A | | 3 | Ea. | \$8,346 | 5 |
| Lighting Fixtures | Building Mounted Fixtures (Ea.) | | 4 | Ea. | \$3,607 | 8 |
| Lighting Fixtures | Light Fixtures (Bldg SF) | | 24,939 | SF | \$457,345 | 10 |
| | | Sub Total for System | 5 | items | \$487,662 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Plumbing Fixtures | Non-Refrigerated Drinking Fountain | | 3 | Ea. | \$7,151 | 5 |
| Plumbing Fixtures | Restroom Lavatory | | 15 | Ea. | \$40,744 | 8 |
| Plumbing Fixtures | Sink - Service / Mop Sink | | 4 | Ea. | \$3,184 | 8 |
| Plumbing Fixtures | Toilets | | 13 | Ea. | \$65,772 | 8 |
| Plumbing Fixtures | Urinals | | 7 | Ea. | \$9,480 | 8 |
| Domestic Water Equipment | Gas Piping System (BldgSF) | | 24,939 | | \$864,766 | 10 |
| Domestic Water Piping | Domestic Water Piping System (Bldg.SF) | | 24,939 | SF | \$89,624 | 10 |
| Sanitary Sewerage Piping | Sanitary Sewer Piping | | 24,939 | SF | \$27,688 | 10 |
| Plumbing Fixtures | Classroom Lavatory | | 19 | Ea. | \$48,725 | 10 |
| | | Sub Total for System | 9 | items | \$1,157,135 | |
| Fire and Life Safety | | | | | | |
| Uniformat Description | LC Type Description | | | UoM | | Remaining Life |
| Fire Detection and Alarm | Fire Alarm | | 24,939 | | \$39,599 | 9 |
| Fire Detection and Alarm | Fire Alarm Panel | | 1 | Ea. | \$6,868 | 9 |
| _ | | Sub Total for System | 2 | items | \$46,467 | |
| Conveyances | | | | | | |
| Uniformat Description | LC Type Description | | | UoM | · · · · · · · · · · · · · · · · · · · | Remaining Life |
| Elevators | Passenger elevator cab finishes | | | Ea. | \$7,985 | 5 |
| | | Sub Total for System | 1 | items | \$7,985 | |
| Exterior | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | | 248 | SF | \$434 | 2 |
| Exterior Entrance Doors | Steel - Insulated and Painted | | 2 | Door | \$7,414 | 5 |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | | 248 | SF | \$434 | 9 |
| | | Sub Total for System | 3 | items | \$8,282 | |
| Mechanical | | | | | | |
| Uniformat Description | LC Type Description | | | UoM | · · · · · · · · · · · · · · · · · · · | Remaining Life |
| Central Cooling | Chiller - Outdoor Air Cooled (100 Tons) | | | Ea. | \$102,018 | 3 |
| Central Cooling | Chiller - Indoor Water Cooled (100 Ton) | | | Ea. | \$104,497 | 10 |
| Facility Hydronic Distribution | 2-Pipe System (Cold) | | | SF | \$443 | 10 |
| Facility Hydronic Distribution | Pump- 10HP (Ea.) | Out Tatal for Ourters | | Ea. | \$11,561 | 10 |
| Electrical | | Sub Total for System | 4 | items | \$218,519 | |
| Electrical Uniformat Description | LC Type Description | | Otv | UoM | Renair Coet | Remaining Life |
| Power Distribution | Panelboard - 120/208 100A | | | Ea. | \$2,782 | 5 |
| Lighting Fixtures | Light Fixtures (Bldg SF) | | 248 | | \$4,548 | 5 |
| | , , , | Sub Total for System | 2 | items | \$7,330 | |
| | Sub Total for Building | g 019D - Mechanical Building | 9 | items | \$234,132 | |
| Building: 019E - Res | trooms and Storage | | | | | |
| Exterior | J | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Exterior Wall Veneer | Exterior Painting - Bldg SF basis | ı | 859 | | \$1,504 | 5 |
| Exterior Entrance Doors | Steel - Insulated and Painted | | 4 | Door | \$14,828 | 10 |
| | | Sub Total for System | • | | \$16.222 | |

M*A*P*P*S ©, Jacobs 2022

Sub Total for System

2 items

\$16,332



Austin ISD - Liberal Arts and Science Academy

Interior

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|--|-------------------------------------|--------------------------------|-----|-------|--------------|----------------|
| Suspended Plaster and | Painted ceilings | | 904 | SF | \$1,883 | 5 |
| Wall Painting and Coating | Painting/Staining (Bldg SF) | | 904 | SF | \$4,051 | 5 |
| Compartments and Cubicles | Toilet Partitions | | 3 | Stall | \$6,049 | 5 |
| Interior Swinging Doors | Wooden Door | | 2 | Door | \$3,751 | 5 |
| Interior Door Supplementary Components | Door Hardware | | 2 | Door | \$2,969 | 8 |
| | | Sub Total for System | 5 | items | \$18,703 | |
| Mechanical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Heating System Supplementary Components | Controls - Electronic (Bldg.SF) | | 904 | SF | \$1,399 | 8 |
| | | Sub Total for System | 1 | items | \$1,399 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Domestic Water Equipment | Water Heater - Electric - 20 gallon | | 1 | Ea. | \$1,587 | 8 |
| | | Sub Total for System | 1 | items | \$1,587 | |
| | Sub Total for Buildin | g 019E - Restrooms and Storage | 9 | items | \$38,021 | |
| | Total for: Li | beral Arts and Science Academy | 194 | items | \$26,814,091 | |



Supporting Photos

General Site Photos



Electrical transformer aged



Air handling unit beyond useful life



Pump beyond useful life



Metal lockers beyond useful life



Wood floor worn and stained



Unit heater beyond useful life


M•A•P•P•S ©, Jacobs 2022 **21**







Cooling tower rusted



Damaged asphalt in parking lot

M*A*P*P*S ©, Jacobs 2022 22