

## **FACILITY CONDITION ASSESSMENT**

Martin MS | February 2022





## **Executive Summary**

Martin MS is located at 1601 Haskell St in Austin, Texas. The oldest building is 54 years old (at time of 2020 assessment). It comprises 108,878 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$3,068,135. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Martin MS the ten-year need is \$11,876,516.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Martin MS facility has a 5-year FCA score of 77.10%.

## **Summary of Findings**

The table below summarizes the condition findings at Martin MS

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Si	te							
	Exterior Site	\$1,706,847	\$781,183	\$0	\$2,488,030	\$2,488,030	\$0	
Permanen	t Building(s)	-		-	_	-		
051A	Main building includes Administration Offices & Classrooms.	\$437,636	\$3,999,506	\$588,463	\$4,437,142	\$5,025,605	\$18,234,840	75.67%
051B	Stand-Alone Cafeteria, Gym, Band, & Main Mech.	\$923,653	\$684,110	\$2,755,119	\$1,607,763	\$4,362,882	\$19,033,150	91.55%
	Sub Total for Permanent Building(s):	\$1,361,288	\$4,683,616	\$3,343,582	\$6,044,904	\$9,388,486	\$37,267,986	
	Total for Site:	\$3,068,135	\$5,464,799	\$3,343,582	\$8,532,934	\$11,876,516	\$37,267,986	77.10%

M-A-P-P-S ©, Jacobs 2022

## **Facility Condition Assessment**





## **Approach and Methodology**

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

## **Facility Deficiency Priority Levels**

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1** – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$30,995	\$43,980	\$1,624,585	\$1,699,559	55.39 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Exterior	\$0	\$284,733	\$0	\$0	\$0	\$284,733	9.28 %
Interior	\$0	\$0	\$97,097	\$334,043	\$47,483	\$478,624	15.60 %
Mechanical	\$0	\$565,125	\$27,432	\$0	\$0	\$592,557	19.31 %
Electrical	\$0	\$7,287	\$1,028	\$0	\$0	\$8,316	0.27 %
Plumbing	\$0	\$1,264	\$879	\$0	\$0	\$2,142	0.07 %
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$2,204	\$0	\$2,204	0.07 %
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Total:	\$0	\$858,409	\$157,430	\$380,227	\$1,672,068	\$3,068,135	

The building systems at the site with the most need include:

Site	-	\$1,699,559
Mechanical	-	\$592,557
Interior	-	\$478,624

M-A-P-P-S ©, Jacobs 2022



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies

M•A•P•P•S ©, Jacobs 2022 5



## **Life Cycle Capital Renewal Forecast**

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$0	\$67,964	\$561,566	\$629,530
Roofing	\$0	\$0	\$0	\$0	\$70,178	\$70,178
Exterior	\$0	\$0	\$0	\$0	\$170,910	\$170,910
Interior	\$0	\$0	\$184,951	\$70,302	\$547,360	\$802,613
Mechanical	\$0	\$0	\$0	\$6,423	\$624,251	\$630,674
Electrical	\$0	\$17,196	\$0	\$5,519	\$168,363	\$191,078
Plumbing	\$0	\$0	\$6,384	\$0	\$2,343,203	\$2,349,587
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$606,519	\$606,519
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$17,196	\$191,335	\$150,208	\$5,092,350	\$5,451,089

M-A-P-P-S ©, Jacobs 2022



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$629,530	\$0	\$0	\$0	\$0	\$0	\$0	\$629,530
Roofing	\$70,178	\$0	\$0	\$0	\$0	\$0	\$0	\$70,178
Exterior	\$170,910	\$0	\$0	\$0	\$0	\$77,198	\$77,198	\$248,108
Interior	\$802,613	\$0	\$0	\$0	\$0	\$620,415	\$620,415	\$1,423,028
Mechanical	\$630,674	\$0	\$0	\$0	\$0	\$379,292	\$379,292	\$1,009,966
Electrical	\$191,078	\$0	\$0	\$0	\$0	\$83,319	\$83,319	\$274,397
Plumbing	\$2,349,587	\$0	\$0	\$12,768	\$0	\$2,102,107	\$2,114,875	\$4,464,462
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Conveyances	\$0	\$0	\$0	\$0	\$0	\$106,724	\$106,724	\$106,724
Specialties	\$606,519	\$0	\$0	\$0	\$0	\$284,486	\$284,486	\$891,005
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$5,451,089	\$0	\$0	\$12,768	\$0	\$3,653,541	\$3,666,309	\$9,117,398




Figure 2: Ten Year Capital Renewal Forecast



## **Facility Condition Assessment Score**

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$37,267,986. For planning purposes, the total 5-year need at the Martin MS is \$8,532,934 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Martin MS facility has a 5-year FCA of 77.10%.



rigare or o rear rer



# Martin MS - Deficiency Summary Site Level Deficiencies

### Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Driveway Replacement	Capital Renewal	4,820	SF	3	\$30,995	4261
Asphalt Paving Replacement	Capital Renewal	16	CAR	4	\$23,213	4260
Fencing Replacement (4' Chain Link Fence)	Capital Renewal	440	LF	4	\$20,767	4259
PROGRAM DEFICIENCIES	ADA Compliance	534,618	EACH	5	\$917,929	4248
PUBLIC DEFICIENCIES	ADA Compliance	247,637	EACH	5	\$425,188	4247
TAS ACCESSIBILITY DEFICIENCIES	ADA Compliance	163,932	EACH	5	\$281,468	4249
	Sub Total for System	6	items		\$1,699,559	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Electrical Transformer Replacement	Capital Renewal	1	Ea.	2	\$7,287	3844

Note: age, corrosion, damage

Location: AHU-3 room

Sub Total for System 1 items

\$7,287

Sub Total for School and Site Level

Category

7 items

Qty UoM

Priority

\$1,706,847

Repair Cost

## Building: 051A - Main building includes Administration Offices & Classrooms.

LYIGHO	•
Deficiency	

		,	- ,	-1
Brick Exterior Replacement (Bldg SF)	Capital Renewal	5,528 SF	2	\$155,307 4263
Metal Exterior Door Replacement	Capital Renewal	2 Door	2	\$7,414 4262
	Sub Total for System	2 items		\$162,721


#### Interior

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal	10	Door	3	\$14,846	4269
Interior Door Replacement	Capital Renewal	4	Door	3	\$7,502	4268
Acoustical Ceiling Tile Replacement	Capital Renewal	4,422	SF	4	\$14,932	4266
Ceiling Grid Replacement	Capital Renewal	4,422	SF	4	\$18,414	4265
Ceramic Tile Flooring Replacement	Capital Renewal	776	SF	4	\$13,710	4270
Metal Interior Door Replacement	Capital Renewal	6	Door	4	\$17,363	4267
Plaster Ceiling Replacement	Capital Renewal	5,553	SF	4	\$10,825	4250
Stone/Quarry Flooring Replacement	Capital Renewal	1,600	SF	4	\$43,739	4273
Note: Beyond useful Life						
Location: Administration						
Vinyl Composition Tile Replacement	Capital Renewal	1,422	SF	4	\$11,629	4271
Interior Ceiling Repainting	Deferred Maintenance	1,553	SF	5	\$3,234	4264
Interior Wall Repainting (Bldg SF)	Capital Renewal	8,540	SF	5	\$38,267	4288
	Sub Total for System	11	items		\$194,461	

## Mechanical

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$13,749	3852
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$6,423	3857
Ductless Split System AC Replacement	Capital Renewal	1 Ea.	2	\$3,004	3853
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$5,714	3854
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$5,714	3855
Note: 7.5 Tons					
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$7,785	3856
Note: 10 Tons					
Package Roof Top Unit Replacement	Capital Renewal	1 Ea.	2	\$31,723	3859
Thru Wall AC Replacement	Capital Renewal	1 Ea.	2	\$2,875	3858
	Sub Total for System	8 items		\$76.986	








lum	

Fiumbing					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Water Heater Replacement	Capital Renewal	1 Ea.	2	\$1,264	3851
	Sub Total for System	1 items		\$1,264	
Specialties					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Base Storage Cabinet Replacement	Capital Renewal	4 LF	4	\$2,204	3843
<b>Note:</b> replace base cabinet in room 102 (elec. equipmen	t room)				
	Sub Total for System	1 items		\$2,204	
Sub Total for Building 051A - Main building include	s Administration Offices & Classrooms.	23 items		\$437,636	
Building: 051B - Stand-Alone Cafeteria,	Gym, Band, & Main Mecl	h.			
Exterior					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Brick Exterior Replacement (Bldg SF)	Capital Renewal	4,282 SF	2	\$120,624	4274
Stucco Exterior Wall Replacement (Bldg SF)	Capital Renewal	267 SF	2	\$1,388	4275
	Sub Total for System	2 items		\$122,012	
Interior					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Interior Brick/Stone Replacement (Bldg SF)	Capital Renewal	1,400 SF	3	\$47,165	4285
Interior Door Hardware Replacement	Capital Renewal	11 Door	3	\$16,331	4280
Interior Door Replacement	Capital Renewal	6 Door	3	\$11,254	4279
Acoustical Ceiling Tile Replacement	Capital Renewal	1,672 SF	4	\$5,646	4277
Ceiling Grid Replacement	Capital Renewal	1,672 SF	4	\$6,963	4276
Ceramic Tile Flooring Replacement	Capital Renewal	767 SF	4	\$13,551	4281
Interior Wood Wall Replacement (LC)	Capital Renewal	5,335 SF	4	\$83,664	4283
Metal Interior Door Replacement	Capital Renewal	4 Door	4	\$11,575	4278
Stone/Quarry Flooring Replacement	Capital Renewal	2,600 SF	4	\$71,075	4287
Vinyl Composition Tile Replacement	Capital Renewal	1,340 SF	4	\$10,958	4282
Interior Wall Repainting (Bldg SF)	Capital Renewal	1,335 SF	5	\$5,982	4286
	Sub Total for System	11 items		\$284,163	
Mechanical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$9,973	3863
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$6,423	3864
Air Cooled Condenser Replacement	Capital Renewal	1 Ea.	2	\$15,266	3865
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$29,014	3867
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$43,163	3868
Note: 6000 CFM					
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$85,959	3869
<b>Note:</b> 12,000 CFM					
Copper Tube Boiler Replacement	Capital Renewal	2 Ea.	2	\$298,342	3861
Note: 3050 MBH					
Air Compressor Replacement	Capital Renewal	1 Ea.	3	\$4,311	3862
Note: 3 hp					
Circulation Pump Replacement	Capital Renewal	2 Ea.	3	\$23,121	3866
	Sub Total for System	9 items		\$515,571	
Electrical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
2 X 4 Interior Fluorescent Lighting Replacement	Capital Renewal	1 Ea.	3	\$438	3849
Note: broken					
Location: cafeteria					
H.I.D. Lighting Replacement	Capital Renewal	1 Ea.	3	\$590	3850
Note: LED - broken					
Location: small gym					
	Sub Total for System	2 items		\$1,028	

M\*A\*P\*P\*S ©, Jacobs 2022 10





**Plumbing** 

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID_
Backflow Preventer Replace	ment	Capital Renewal	1 Ea.	3	\$879	3860
		Sub Total for System	1 items		\$879	
	Sub Total for Building 051B - Stand-Alone Cafeteria, Gyn	n, Band, & Main Mech.	25 items		\$923,653	
		Total for Campus	55 items		\$3,068,135	

M\*A\*P\*P\*S ©, Jacobs 2022 **11** 



## Martin MS - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)		1,440	LF	\$67,964	4
Fences and Gates	Competition Style Track		1	Ea.	\$294,838	5
Parking Lot Pavement	Asphalt		96	CAR	\$139,277	5
Roadway Pavement	Asphalt Driveways		19,820	SF	\$127,451	5
		Sub Total for System	4	items	\$629,530	
Roofing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Canopy Roofing	Aluminum panels		1,385	SF	\$70,178	5
		Sub Total for System	1	items	\$70,178	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Lighting	Pole Lighting		14	Ea.	\$81,475	5
		Sub Total for System	1	items	\$81,475	
		Sub Total for Building -	6	items	\$781,184	

## **Building: 051A - Main building includes Administration Offices & Classrooms.**

#### **Exterior**

Uniformat Description	LC Type Description		Qty UoM	Repair Cost Remaining L	.ife_
Exterior Operating Windows	Aluminum - Windows per SF		510 SF	\$50,861 5	
Exterior Operating Windows	Aluminum - Windows per SF		290 SF	\$28,921 5	
Exterior Operating Windows	Aluminum - Windows per SF		96 SF	\$9,574 5	
Exterior Entrance Doors	Steel - Insulated and Painted		22 Door	\$81,554 5	
		Sub Total for System	4 items	\$170,909	

#### Interior

Uniformat Description	LC Type Description	C	ty UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)	30,5	40 SF	\$136,847	3
Carpeting	Carpet	5,5	53 SF	\$70,302	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	44,4	22 SF	\$150,002	5
Suspended Plaster and	Painted ceilings	5,5	53 SF	\$11,565	5
Compartments and Cubicles	Toilet Partitions		36 Stall	\$72,593	5
Interior Door Supplementary Components	Door Hardware		72 Door	\$106,892	5
Wall Painting and Coating	Painting/Staining (Bldg SF)	30,5	40 SF	\$136,847	10
		Sub Total for System	7 item:	\$685,049	

## Mechanical


Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		1	Ea.	\$6,423	4
HVAC Air Distribution	AHU 2,000 CFM Interior		1	Ea.	\$29,014	5
HVAC Air Distribution	Ductwork (Bldg.SF)		55,528	SF	\$439,362	5
HVAC Air Distribution	Roof Top Unit - DX Gas (10 Ton)		2	Ea.	\$48,472	5
Exhaust Air	Roof Exhaust Fan - Small		12	Ea.	\$23,516	5
Exhaust Air	Roof Exhaust Fan - Large		4	Ea.	\$32,145	5
		Sub Total for System	6	items	\$578,932	

#### **Electrical**

Uniformat Description	LC Type Description		ty UoM	Repair Cost	Remaining Life
Electrical Service	Transformer (45 KVA)		1 Ea.	\$5,919	2
Electrical Service	Transformer (45 KVA)		1 Ea.	\$5,919	2
Electrical Service	Transformer (30 KVA)		1 Ea.	\$5,519	4
Power Distribution	Panelboard - 120/208 225A		1 Ea.	\$5,500	5
Lighting Fixtures	Building Mounted Fixtures (Ea.)		5 Ea.	\$4,509	5
Power Distribution	Power Wiring	55,5	28 SF	\$65,950	5
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)		29 Ea.	\$60,406	10
		Sub Total for System	7 items	\$153,721	

M•A•P•P•S ©, Jacobs 2022 12







	nbi	

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 52 gallon		1	Ea.	\$2,684	5
Domestic Water Equipment	Gas Piping System (BldgSF)		55,528	SF	\$1,925,448	5
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		55,528	SF	\$199,553	5
Sanitary Sewerage Piping	Sanitary Sewer Piping		55,528	SF	\$61,649	5
Plumbing Fixtures	Classroom Lavatory		55	Ea.	\$141,047	5
Domestic Water Equipment	Water Heater - Electric - 5 to 10 gallon		1	Ea.	\$1,264	10
		Sub Total for System	6	items	\$2,331,645	
Conveyances						
-	107 8 17		0.		5 . 6 .	
Uniformat Description	LC Type Description			UoM	<u>.</u>	Remaining Life
Elevators	Hydraulic (Passenger Elev)			Ea.	\$98,739	10
Elevators	Passenger elevator cab finishes			Ea.	\$7,985	10
		Sub Total for System	2	items	\$106,724	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry		30	Room	\$264,056	5
Casework	Lockers		534	Ea.	\$284,486	10
		Sub Total for System	2	items	\$548,542	
Sub Total for I	Building 051A - Main building includes Administi	•	34	items	\$4,575,522	
Exterior	llone Cafeteria, Gym, Band, 8	i Maiii Mecii.				
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF		45	SF	\$4,488	10
Exterior Operating Windows	Aluminum - Windows per SF		60	SF	\$5,984	10
Exterior Entrance Doors	Steel - Insulated and Painted		18	Door	\$66,726	10
		Sub Total for System	3	items	\$77,197	
Interior						
Uniformat Description	LC Type Description		Otv	UoM	Renair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)		5,335		\$23,906	3
Compartments and Cubicles	Toilet Partitions			Stall	\$24,198	3
·	Ceilings - Acoustical Tiles				\$63,051	5
				Oi		
· · · · · · · · · · · · · · · · · · ·	•		18,672	CE.		
Carpeting	Carpet		5,335		\$67,542	5
Carpeting Interior Door Supplementary Components	Carpet Door Hardware		5,335 51	Door	\$67,542 \$75,715	5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating	Carpet Door Hardware Painting/Staining (Bldg SF)		5,335 51 5,335	Door SF	\$67,542 \$75,715 \$23,906	5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating	Carpet Door Hardware	Sub Total for Sustam	5,335 51 5,335 21,340	Door SF SF	\$67,542 \$75,715 \$23,906 \$459,662	5 5
Acoustical Suspended Ceilings Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring	Carpet Door Hardware Painting/Staining (Bldg SF)	Sub Total for System	5,335 51 5,335 21,340	Door SF	\$67,542 \$75,715 \$23,906	5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring	Carpet Door Hardware Painting/Staining (Bldg SF)	Sub Total for System	5,335 51 5,335 21,340	Door SF SF	\$67,542 \$75,715 \$23,906 \$459,662	5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical	Carpet Door Hardware Painting/Staining (Bldg SF)	Sub Total for System	5,335 51 5,335 21,340 <b>7</b>	Door SF SF	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979	5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types	Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty	Door SF SF items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979	5 5 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description  Exhaust Air	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description	Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty	Door SF SF items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979	5 5 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description  Exhaust Air  Exhaust Air	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small	Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty	Door SF SF items UoM	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost	5 5 10 10 Remaining Life
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description  Exhaust Air Exhaust Air Heat Generation	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4	Door SF SF items UoM Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost \$19,597 \$32,145	5 5 10 10 8 Remaining Life
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Heat Generation Facility Hydronic Distribution	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH)	Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty 10 4 2	Door SF SF items UoM Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost \$19,597 \$32,145 \$298,342	5 5 10 10 10 Remaining Life 5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Heat Generation Facility Hydronic Distribution	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.)	Sub Total for System  Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty 10 4 2 2	Door SF SF items UoM Ea. Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost \$19,597 \$32,145 \$298,342 \$23,121	5 5 10 10 10 Remaining Life 5 5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description  Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.)		5,335 51 5,335 21,340 <b>7</b> Qty 10 4 2 2	Door SF SF items UoM Ea. Ea. Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829	5 5 10 10 10 Remaining Life 5 5 5 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)		5,335 51 5,335 21,340 <b>7</b> Qty 10 4 2 2 1 5	Door SF SF items UoM Ea. Ea. Ea. Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 <b>\$737,979</b> Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 <b>\$431,033</b>	5 5 10 10 8 8 8 8 5 5 10 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)		5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5	Door SF SF items  UoM Ea. Ea. Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033	5 5 10 10 8 8 8 8 10 10 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA)		5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost	5 5 10 10 10 10 Remaining Life 10 10 10 Remaining Life 2
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA)		5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 1 1	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519	5 5 10 10 10 Remaining Life 5 5 10 10 10 10 Remaining Life 2 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Lighting Fixtures	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.)		5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 6	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410	5 5 10 10 10 Remaining Life 2 5 5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service Lighting Fixtures	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA)	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 6 11	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913	5 5 10 10 10 Remaining Life 5 5 10 10 10 10 Remaining Life 2 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Lighting Fixtures Lighting Fixtures	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.)		5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 6 11	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410	5 5 10 10 10 Remaining Life 2 5 5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Lighting Fixtures Lighting Fixtures	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.)	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 6 11	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913	5 5 10 10 10 Remaining Life 2 5 5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service Lighting Fixtures Lighting Fixtures  Plumbing	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.)	Sub Total for System	5,335 51 5,335 21,340 <b>7</b> Qty 10 4 2 2 1 <b>5</b> Qty 1 1 6 11	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913 \$39,199	5 5 10 10 10 Remaining Life 5 5 10 10 10 Remaining Life 2 5 5 10 10 10 10 10 10 10 10 10 10 10 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service Lighting Fixtures Lighting Fixtures  Plumbing Uniformat Description	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.) Canopy Mounted Fixtures (Ea.)	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 6 6 11 4 Qty	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. Ea. items	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913 \$39,199	5 5 10 10 10 Remaining Life 2 5 5 5
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service Lighting Fixtures Lighting Fixtures  Plumbing Uniformat Description Domestic Water Equipment	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.) Canopy Mounted Fixtures (Ea.)	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 4 4 Qty 1	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. items  UoM UoM UoM UoM UoM	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913 \$39,199	5 5 10 10 10 Remaining Life 2 5 5 10 10 10 Remaining Life 2 5 5 10 10 10 10 10 10 10 10 10 10 10 10 10
Carpeting Interior Door Supplementary Components Wall Painting and Coating Wood Flooring  Mechanical Uniformat Description Exhaust Air Exhaust Air Heat Generation Facility Hydronic Distribution Central Cooling  Electrical Uniformat Description Electrical Service Electrical Service Lighting Fixtures Lighting Fixtures  Plumbing Uniformat Description Domestic Water Equipment Plumbing Fixtures	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.) Canopy Mounted Fixtures (Ea.)  LC Type Description  Water Heater - Gas - 100 Gallon	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 4 Qty 1 5 Qty 1 5	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea. La. UoM Ea. Ea. UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913 \$39,199 Repair Cost	5 5 10 10 10 Remaining Life 2 5 5 10 10 Remaining Life 3 3
Carpeting Interior Door Supplementary Components Wall Painting and Coating	Carpet Door Hardware Painting/Staining (Bldg SF) Wood Flooring - All Types  LC Type Description Roof Exhaust Fan - Small Roof Exhaust Fan - Large Boiler - Copper Tube (3200 MBH) Pump- 10HP (Ea.) Cooling Tower - Metal (300 Tons)  LC Type Description Transformer (15 KVA) Transformer (30 KVA) Building Mounted Fixtures (Ea.) Canopy Mounted Fixtures (Ea.)  LC Type Description  Water Heater - Gas - 100 Gallon Classroom Lavatory	Sub Total for System	5,335 51 5,335 21,340 7 Qty 10 4 2 2 1 5 Qty 1 4 Qty 1 5 Qty 1 5	Door SF SF items  UoM Ea. Ea. Ea. items  UoM Ea.	\$67,542 \$75,715 \$23,906 \$459,662 \$737,979 Repair Cost \$19,597 \$32,145 \$298,342 \$23,121 \$57,829 \$431,033 Repair Cost \$5,358 \$5,519 \$5,410 \$22,913 \$39,199 Repair Cost	5 5 10 10 10 10 Remaining Life 2 5 5 10 10 Remaining Life 3 5 5 10 Remaining Life 3 5 5 10 10 10 10 10 10 10 10 10 10 10 10 10

M\*A\*P\*P\*S ©, Jacobs 2022 13





Austin ISD - Martin MS

## Plumbing

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Sanitary Sewerage Piping	Sanitary Sewer Piping		53,349	SF	\$59,230	10
	Sub To	tal for System	6	items	\$2,132,816	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Fixed Cabinetry		3	Room	\$26,406	5
Casework	Lockers, Gym		651	Ea.	\$316,057	5
	Sub To	tal for System	2	items	\$342,462	
	Sub Total for Building 051B - Stand-Alone Cafeteria, Gym, Band,	& Main Mech.	27	items	\$3,760,687	
	Total	for: Martin MS	67	items	\$9,117,393	



## **Supporting Photos**

### **General Site Photos**



Acoustical Ceiling Tile



Damaged casework



Typical hallway finishes



School cafetorium



Damaged paint



Asphalt parking lot

M•A•P•P•S ©, Jacobs 2022 15

## **Facility Condition Assessment**

Austin ISD - Martin MS





Electric transformer



Typical RTU



Sink out of use

M\*A\*P\*P\*S ©, Jacobs 2022