

# FACILITY CONDITION ASSESSMENT

*McCallum HS* | February 2022





### **Executive Summary**

McCallum HS is located at 5600 Sunshine Dr in Austin, Texas. The oldest building is 67 years old (at time of 2020 assessment). It comprises 268,776 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$25,327,905. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For McCallum HS the ten-year need is \$38,836,208.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The McCallum HS facility has a 5-year FCA score of 19.02%.

### **Summary of Findings**

The table below summarizes the condition findings at McCallum HS

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Sit	te							
	Exterior Site	\$372,331	\$0	\$1,009,697	\$372,331	\$1,382,028	\$0	
Permanent	t Building(s)		-		-			
005A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$18,394,868	\$3,431,800	\$3,511,263	\$21,826,668	\$25,337,931	\$26,276,200	16.93%
005B	Mechanical Building (old Boiler House)	\$879,756	\$95,829	\$142,221	\$975,585	\$1,117,806	\$337,579	-188.99%
005C	Theater Building (includes Band Hall & Choir)	\$1,938,042	\$568,152	\$572,706	\$2,506,194	\$3,078,900	\$4,144,485	39.53%
005D	Stand-Alone Gym - Dance gym (includes Weight Room, Lockers & Showers)	\$1,191,441	\$498,558	\$1,052,059	\$1,689,999	\$2,742,058	\$3,244,416	47.91%
005E	Mechanical Building	\$1,872,911	\$7,414	\$0	\$1,880,325	\$1,880,325	\$162,649	- 1056.06%
005F	Baseball Batting Cage & Storage	\$116,062	\$55,555	\$14,092	\$171,617	\$185,709	\$532,787	67.79%
005G	Storage Building (Wood), Track Storage	\$6,593	\$9,493	\$10,588	\$16,086	\$26,674	\$66,259	75.72%
005H	Stand-Alone Auditorium	\$555,902	\$1,087,027	\$1,441,849	\$1,642,929	\$3,084,778	\$3,616,839	54.58%
	Sub Total for Permanent Building(s):	\$24,955,574	\$5,753,828	\$6,744,778	\$30,709,402	\$37,454,180	\$38,381,213	'
	Total for Site:	\$25,327,905	\$5,753,828	\$7,754,475	\$31,081,733	\$38,836,208	\$38,381,213	19.02%



### Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

### **Facility Deficiency Priority Levels**

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1** – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



### The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)


			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$220,032	\$119,421	\$19,967	\$359,421	1.42 %
Roofing	\$2,470,758	\$0	\$0	\$0	\$0	\$2,470,758	9.77 %
Structural	\$12,910	\$0	\$0	\$0	\$0	\$12,910	0.05 %
Exterior	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Interior	\$0	\$0	\$431,843	\$1,858,774	\$277,087	\$2,567,704	10.15 %
Mechanical	\$0	\$6,646,925	\$940,529	\$677,248	\$0	\$8,264,702	32.67 %
Electrical	\$0	\$395,414	\$4,743,722	\$6,026	\$0	\$5,145,161	20.34 %
Plumbing	\$0	\$5,857	\$1,844,696	\$447,881	\$0	\$2,298,435	9.09 %
Fire and Life Safety	\$1,286,571	\$0	\$0	\$0	\$0	\$1,286,571	5.09 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$783,817	\$0	\$783,817	3.10 %
Crawlspace	\$0	\$0	\$0	\$0	\$2,109,198	\$2,109,198	8.34 %
Total:	\$3,770,239	\$7,048,196	\$8,180,823	\$3,893,168	\$2,406,253	\$25,298,678	

The building systems at the site with the most need include:

Mechanical	-	\$8,264,702
Electrical	-	\$5,145,161
Interior	-	\$2,567,704



Austin ISD - McCallum HS



### The chart below represents the building systems and associated deficiency costs.

```
Figure 1: System Deficiencies
```

### Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

	Life Cycle Capital Renewal Projections								
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5			
Site	\$0	\$0	\$0	\$0	\$0	\$0			
Roofing	\$0	\$0	\$0	\$0	\$0	\$0			
Exterior	\$3,164	\$97,083	\$0	\$7,414	\$274,318	\$381,979			
Interior	\$0	\$380,163	\$21,292	\$80,428	\$2,237,440	\$2,719,323			
Mechanical	\$0	\$0	\$0	\$105,134	\$0	\$105,134			
Electrical	\$0	\$0	\$0	\$37,767	\$16,187	\$53,954			
Plumbing	\$0	\$0	\$0	\$145,098	\$0	\$145,098			
Fire and Life Safety	\$0	\$0	\$47,084	\$58,298	\$0	\$105,382			
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0			
Specialties	\$0	\$0	\$545,716	\$141,764	\$1,478,054	\$2,165,534			
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0			
Total	\$3,164	\$477,246	\$614,092	\$575,903	\$4,005,999	\$5,676,404			

Table 3a: Capital Renewal Forecast (Yrs 1-5)



Austin ISD - McCallum HS

Table 3b: Capital Renewal Forecast (Yrs 6-10)

		Life Cycle Capital Renewal Projections						
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$0	\$0	\$0	\$0	\$0	\$1,013,020	\$1,013,020	\$1,013,020
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$381,979	\$0	\$294,611	\$0	\$3,164	\$2,237,106	\$2,534,881	\$2,916,860
Interior	\$2,719,323	\$832,905	\$2,079	\$518,541	\$273,000	\$549,467	\$2,175,992	\$4,895,315
Mechanical	\$105,134	\$0	\$0	\$43,235	\$0	\$4,392,920	\$4,436,155	\$4,541,289
Electrical	\$53,954	\$0	\$0	\$18,822	\$0	\$902,403	\$921,225	\$975,179
Plumbing	\$145,098	\$7,685	\$0	\$0	\$0	\$606,466	\$614,151	\$759,249
Fire and Life Safety	\$105,382	\$0	\$0	\$0	\$0	\$0	\$0	\$105,382
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$2,165,534	\$0	\$0	\$72,824	\$0	\$0	\$72,824	\$2,238,358
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$5,676,404	\$840,590	\$296,690	\$653,422	\$276,164	\$9,701,382	\$11,768,248	\$17,444,652




Figure 2: Ten Year Capital Renewal Forecast



### **Facility Condition Assessment Score**

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$38,381,213. For planning purposes, the total 5-year need at the McCallum HS is \$31,081,733 (Life Cycle Years 1-5 plus the FCA deficiency cost). The McCallum HS facility has a 5-year FCA of 19.02%.





# McCallum HS - Deficiency Summary

### **Site Level Deficiencies**

Site		0.1	o	M D' ''		
Deficiency		Category	Qty Uo		Repair Cost	ID
Asphalt Driveway Rep		Capital Renewal	28,570 SF	3	\$183,717	3020
Note:	Weathering/faulting driveway	Ossitel Deserved	0.000.01		¢00.045	0000
Concrete Walks Repl		Capital Renewal	3,206 SF	3	\$36,315	3023
	All around campus	Deferred	18,665 SF	4	\$77,634	3019
Asphalt Paving Resul	lacing	Maintenance	10,000 51	4	\$77,034	3018
Location:	Parking lots and drive aisle					
Fencing Replacemen	t (Wood Fence)	Deferred Maintenance	110 LF	4	\$3,323	3012
Note:	Wooden fence around tennis court has termite damage					
Location:	Tennis court fence					
Site Drainage Regrad	ling	Deferred Maintenance	26,750 SF	4	\$38,464	3022
Note:	Ponding/grading issues					
Paving Restriping		Deferred Maintenance	306 C/	AR 5	\$10,176	3021
Note:	Faded striping in parking lots and driveways					
Site Marquee Repair		Deferred Maintenance	1 Ea	. 5	\$3,227	3024
Note:	Site Marquee does not function					
Site Signage Replace	ement	Capital Renewal	2 Ea	. 5	\$483	3025
Location:	Driveway entrance, parking lot					
Small Bench Replace	ment	Deferred Maintenance	2 Ea	. 5	\$4,134	3027
Location:	Broken benches near portables					
Tennis Courts, Nets,	And Equipment Repair	Deferred Maintenance	1 Ea	. 5	\$1,420	3013
Note:	Tree growing through pavement					
Location:	Southeast section of tennis courts					
Tree Replacement		Deferred Maintenance	1 Ea	. 5	\$527	3026
Location:	Near Fine Arts Center					
		Sub Total for System	11 ite	ms	\$359,421	
Structural						
Deficiency		Category	Qty Uo	M Priority	Repair Cost	ID
Structural Study Reco	ommended	Deferred Maintenance	2 Jo	b 1	\$12,910	6903
Note:	Structural study to detail scope of work based on the 2017 cra				<b>*</b> 10.515	
		Sub Total for System	1 ite		\$12,910	
	Sub T	otal for School and Site Level	12 ite	ms	\$372,331	

### Gym.

Roofing
---------

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
AISD ROOFING P1	Capital Renewal	467,435	EACH	1	\$491,602	4656
AISD ROOFING P2	Capital Renewal	669,395	EACH	1	\$704,003	4657
AISD ROOFING P3	Capital Renewal	467,435	EACH	1	\$491,602	4658
AISD ROOFING P4	Capital Renewal	477,560	EACH	1	\$502,250	4659
AISD ROOFING P5	Capital Renewal	267,472	EACH	1	\$281,301	4660
	Sub Total for System	5	items		\$2,470,758	



Austin ISD - McCallum HS

### Interior

Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Interior Door Hardware Replacement	Capital Renewal		Door	3	\$155,884	3143
<b>Note:</b> To be done with door replacement	Capital Konoman	100	Dool	Ũ	\$100,001	0110
Location: Various locations						
Interior Door Replacement	Capital Renewal	93	Door	3	\$174,431	314
Note: End of life	ouplui Kenewai	50	Dool	0	ψι / τ,τοι	014
Location: Various locations						
Acoustical Ceiling Tile Replacement	Capital Renewal	71,763	SE	4	\$242,326	313
	Capital Kellewal	71,705	01	4	ψ242,020	515
Note: Damaged/end of life cycle Location: Replace at classrooms, cafeteria, and corridor						
-	Capital Renewal	18,400	сE	4	\$152,754	212
Interior Ceramic Walls Repair or Replacement Note: Loose tiles, broken	Capital Reliewal	10,400	эг	4	\$152,754	313
Location: Small Gym, Corridors	Deferred	10	Fo	4	¢20.165	212
Interior Toilet Partition Repair	Deferred Maintenance	10	Ea.	4	\$20,165	313
Note: End of life						
Location: Various locations						
Interior Wood Wall Replacement (LC)	Capital Renewal	29,441	SF	4	\$461,696	313
Note: Water damaged, stained	·				•	
Location: Classrooms, Corridors						
Metal Interior Door Replacement	Capital Renewal	12	Door	4	\$34,726	314 <sup>.</sup>
Note: End of life	·					
Location: Various locations						
Toilet Partition Replacement	Capital Renewal	22	Stall	4	\$44,363	3139
Note: End of life					• ,	
Location: Various locations						
Vinyl Composition Tile Replacement	Capital Renewal	34,961	SF	4	\$285,901	314
Note: End of life		- ,	•.		+	
Location: Various Locations						
Vinyl Composition Tile Replacement	Capital Renewal	55,202	SF	4	\$451,426	3667
Interior Ceiling Repainting	Deferred	36,801		5	\$76,642	
	Maintenance	00,001	01	0	ψ <i>1</i> 0,042	010-
Note: Peeling, missing, flaking						
Interior Wall Repainting (Bldg SF)	Capital Renewal	34,200	SF	5	\$153,248	3137
Note: Peeling, flaking						
Location: Various locations						
	Sub Total for System	12	items		\$2,253,560	
Mechanical						
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$172,795	6175
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$290,079	6176
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$580,159	6177
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$113,856	
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$683,139	6180
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$85,959	6182
Air Handler HVAC Component Replacement	Capital Renewal		Ea.	2	\$129,490	618
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal		Ea.	2	\$1,176	616
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal		Ea.	2	\$9,496	616
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal Capital Renewal		Ea. Ea.	2 2	\$12,788 \$13,560	616 616
Fan Coil (Chilled Water) HVAC Component Replacement					\$13,560 \$2,121	
Fan Coil (Chilled Water) HVAC Component Replacement	Capital Renewal		Ea.	2	\$2,131 \$603.505	616
Gas Piping Replacement (SF Basis)	Capital Renewal	20,000		2	\$693,505	614
HVAC VAV Box Replacement	Capital Renewal		Ea.	2	\$251,801	6184
Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	184,007		2	\$445,237	6174
Thru Wall AC Replacement	Capital Renewal		Ea.	2	\$2,875	6168
Infrared Gas Radiant Heater Replacement	Capital Renewal		Ea.	3	\$2,180	6155
Kitchen Exhaust Hood Replacement	Capital Renewal	3	Ea.	3	\$33,574	6187



Austin ISD - McCallum HS

#### Mechanical

Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	3 25	UoM Ea. Ea. Ea.	Priority 3 3	Repair Cost \$33,574 \$200,906	ID 6188
Capital Renewal Capital Renewal Capital Renewal	25 10	Ea.	3		6188
Capital Renewal Capital Renewal	10			\$200,906	
Capital Renewal		Ea.	•		6186
•	1		3	\$80,362	6189
Capital Renewal		Ea.	3	\$10,625	6169
	4	Ea.	3	\$35,269	6171
Capital Renewal	4	Ea.	3	\$22,829	6172
Capital Renewal	8	Ea.	3	\$15,677	6185
Capital Renewal	184,007	SF	4	\$496,308	6158
Sub Total for System	26	items		\$4,419,353	
Category	Qty	UoM	Priority	Repair Cost	ID
Capital Renewal	1	Ea.	2	\$17,802	3148
Capital Renewal	1	Ea.	2	\$18,241	3146
Capital Renewal	1	Ea.	2	\$5,358	3147
Capital Renewal	1	Ea.	2	\$47,520	3156
Capital Renewal	2	Ea.	2	\$24,683	3149
, TP1C is a 2 section panel					
Capital Renewal	5	Ea.	2	\$13,910	3150
d the door of the room and o	door swing	impacts	s panel. Als	so, panel P-4 (in	CC
Capital Renewal	8	Ea.	2	\$43,996	3151
C 150) have breakers missir	ng and expo	osed bu	is. Panel S	(in CC 155) has	s panel
Capital Renewal	1	Ea.	2	\$7,823	3714
Capital Renewal	1	Ea.	2	\$38,387	3145
ailable. Assume 1200 A sei	vice				
Capital Renewal	13	Ea.	3	\$27,079	3158
Capital Renewal	25	Ea.	3	\$22,543	3159
Deferred Maintenance	184,007	SF	3	\$218,543	3161
Capital Renewal	184,007	SF	3	\$3,374,420	3160
corridor 22, rooms 154 and	156, etc. h	ave nev	w lighting (I	ess than 10 yea	ars)
Functional Deficiency	184,007	SF	3	\$143,694	3157
Deferred Maintenance	184,007	SF	3	\$130,255	3152
need of repair/replacement.	PA has rep	orted "	dead spots	5"	
Deferred Maintenance	1	Ea.	4	\$4,357	3162
maintenance					
Sub Total for System	16	items		\$4,138,611	
-					
Category	Qty	UoM	Priority	Repair Cost	ID
Capital Renewal			2	\$2,684	6139
Capital Renewal	3	Ea.	3	\$19,151	6140
	184,007	SF	3	\$661,271	6142
Capital Renewal	,			\$204,290	6144
Capital Renewal Capital Renewal	184,007	SF	3	ψ204,230	• • • •
-	184,007	SF Ea.	3	\$57,484	6148
Capital Renewal	184,007 44				
Capital Renewal Capital Renewal	184,007 44 67	Ea.	3	\$57,484	6148
Capital Renewal Capital Renewal Capital Renewal	184,007 44 67 9	Ea. Ea.	3 3	\$57,484 \$338,979	6148 6150
Capital Renewal Capital Renewal Capital Renewal Capital Renewal	184,007 44 67 9 9	Ea. Ea. Ea.	3 3 3	\$57,484 \$338,979 \$12,188	6148 6150 6151
	Capital Renewal Sub Total for System	Capital Renewal184,007Sub Total for System26CategoryQtyCapital Renewal1Capital Renewal1Capital Renewal1Capital Renewal1Capital Renewal2, TP1C is a 2 section panel2Capital Renewal5d the door of the room and door swingCapital Renewal8C150) have breakers missing and exportCapital Renewal1Capital Renewal1Capital Renewal1Capital Renewal1Capital Renewal13Capital Renewal13Capital Renewal25Deferred184,007Maintenance184,007corridor 22, rooms 154 and 156, etc. hFunctional Deficiency184,007Maintenance1Deferred1Maintenance1Deferred1Maintenance1Sub Total for System16CategoryQty	Capital Renewal184,007SFSub Total for System26itemsCategoryQtyUoMCapital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal2Ea.Capital Renewal2Ea., TP1C is a 2 section panel5Ea.Capital Renewal5Ea.d the door of the room and door swing impactsCapital Renewal8Ea.C150) have breakers missing and exposed butCapital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal1Ea.Capital Renewal13Ea.Capital Renewal13Ea.Capital Renewal184,007SFcorridor 22, rooms 154 and 156, etc. have newFunctional Deficiency184,007SFDeferred184,007SFDeferred1Ea.Maintenance1Ea.Naintenance1Ea.Sub Total for System16itemsCategoryQtyUoM	Capital Renewal184,007SF4Sub Total for System26itemsCategoryQtyUoMPriorityCapital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal2Ea.2Capital Renewal5Ea.2Capital Renewal5Ea.2Capital Renewal5Ea.2Capital Renewal5Ea.2Capital Renewal8Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.2Capital Renewal1Ea.3Capital Renewal1Ea.3Capital Renewal13Ea.3Capital Renewal13Ea.3Capital Renewal13Ea.3Capital Renewal184,007SF3Capital Renewal184,007SF3Capital Renewal184,007SF3Capital Renewal184,007SF3Capital Renewal184,007SF3Capital Renewal184,007SF3Capital Renewal184,007SF3Deferred184,007SF3Maintenance1Ea.<	Capital Renewal184,007SF4\$496,308Sub Total for System26items\$4,419,353CategoryQtyUoMPriorityRepair CostCapital Renewal1Ea.2\$17,802Capital Renewal1Ea.2\$18,241Capital Renewal1Ea.2\$5,358Capital Renewal1Ea.2\$47,520Capital Renewal2Ea.2\$24,683, TP1C is a 2 section panel5Ea.2\$13,910d the door of the room and door swing impacts panel. Also, panel P-4 (inCapital Renewal8Ea.2\$43,996C 150) have breakers missing and exposed bus. Panel S (in CC 155) haveCapital Renewal1Ea.2\$7,823Capital Renewal1Ea.2\$7,823\$24,643Capital Renewal1Ea.2\$7,823Capital Renewal1Ea.2\$7,823Capital Renewal1Ea.3\$22,543Deferred184,007SF3\$218,543Maintenance184,007SF3\$143,694Deferred184,007SF3\$143,694Deferred184,007SF3\$143,694Deferred184,007SF3\$130,255Maintenance1Ea.4\$4,357Maintenance1Ea.4\$4,357Maintenance1Ea.4\$4,357<

Capital Renewal

Sub Total for System

72 Ea.

11 items

4

Restroom Lavatories Plumbing Fixtures Replacement

\$195,573 6146

\$1,570,286



Austin ISD - McCallum HS

#### Fire and Life Safety

Security Alarm Replacement Note: Client inf Technology Deficiency Public Address System Head-E	terview indicated PA and security system to be old and terview indicated PA and security system to be old and and Requires Replacement	Capital Renewal	184,007 PA has re 184,007 PA has re <b>3</b> Qty	ported " SF	1	\$423,532	ID
Note: Client int Security Alarm Replacement Note: Client int Technology Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	terview indicated PA and security system to be old and	d in need of repair/replacement. Capital Renewal d in need of repair/replacement. Sub Total for System Category Functional Deficiency Sub Total for System	PA has re 184,007 PA has re <b>3</b> Qty 1	ported " SF ported " items UoM Ea.	dead spots" 1 dead spots" Priority	\$423,532 <b>\$722,570</b> Repair Cost	3154 ID
Security Alarm Replacement Note: Client inf Technology Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	terview indicated PA and security system to be old and	Capital Renewal d in need of repair/replacement. Sub Total for System Category Functional Deficiency Sub Total for System	184,007 PA has re <b>3</b> Qty 1	SF ported " items UoM Ea.	1 dead spots" Priority	\$423,532 <b>\$722,570</b> Repair Cost	ID
Note: Client int Technology Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	End Requires Replacement	d in need of repair/replacement. Sub Total for System Category Functional Deficiency Sub Total for System	PA has re 3 Qty	ported " items UoM Ea.	dead spots'	\$722,570 Repair Cost	ID
Technology Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	End Requires Replacement	Sub Total for System Category Functional Deficiency Sub Total for System	3 Qty 1	UoM Ea.	Priority	<b>\$722,570</b> Repair Cost	
Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	ement	Category Functional Deficiency Sub Total for System	Qty 1	UoM Ea.		Repair Cost	ID 3153
Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	ement	Functional Deficiency Sub Total for System	1	Ea.			
Deficiency Public Address System Head-E Specialties Deficiency Metal Student Lockers Replace	ement	Functional Deficiency Sub Total for System	1	Ea.			
Specialties Deficiency Metal Student Lockers Replace	ement	Sub Total for System			3	\$7,307	3153
Deficiency Metal Student Lockers Replace			1	items			
Deficiency Metal Student Lockers Replace		Category				\$7,307	
Deficiency Metal Student Lockers Replace		Category				. ,	
Metal Student Lockers Replace		Calegory	Otv	UoM	Priority	Repair Cost	ID
		Capital Renewal	1,320		4	\$703,225	3144
Note. Litu of it.		Capital Kellewal	1,520	La.	4	ψ/ 05,225	5144
Location: Corridors							
Location. Comuois	3	Sub Total for System	1	items		\$703,225	
Crewlenses		Sub rotarior System		nems		φ/03,223	
Crawlspace			-				
Deficiency		Category	,	UoM	Priority	Repair Cost	ID
CRAWL SPACE DEFICIENCIE	S - Estimate and Info by AISD	Deferred Maintenance	412,867	Ea.	5	\$485,057	6904
Note: SOIL/DR	AINAGE BELOW BUILDING - improve drainage - 148						
CRAWL SPACE DEFICIENCIE		Deferred	395,463	Fa	5	\$464,610	6905
		Maintenance	000,100		Ū	¢.0.1,010	0000
Note: PERIME	TER SOIL RETAINERS - replace soil retainers - 4059	LF					
CRAWL SPACE DEFICIENCIE	S - Estimate and Info by AISD	Deferred Maintenance	639,943	Ea.	5	\$751,838	6906
Note: CRAWL	SPACE ACCESS/VENTILATION - improve ventilation	n - 148308 SF					
CRAWL SPACE DEFICIENCIE	S - Estimate and Info by AISD	Deferred Maintenance	13,919	Ea.	5	\$16,353	6907
Note: CRAWL	SPACE ACCESS/VENTILATION - repair acess - 5 EA	Ą					
CRAWL SPACE DEFICIENCIE	S - Estimate and Info by AISD	Deferred Maintenance	206,433	Ea.	5	\$242,528	6908
Note: SUSPEN	NDED FLOOR SLABS - repair minor honeycombing &	reinforcement - 148308 SF					
CRAWL SPACE DEFICIENCIE	S - Estimate and Info by AISD	Deferred Maintenance	126,665	Ea.	5	\$148,813	6909
Note: CRAWL	SPACE, EXPOSED PIPES - Replace rusted pies and	hangers and missing insulation	- 1 LS				
		Sub Total for System	6	items		\$2,109,198	

### Building: 005B - Mechanical Building (old Boiler House)

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Handler HVAC Component Replacement	Capital Renewal	1 Ea.	2	\$43,163	6212
Note: 4,000 CFM					
Copper Tube Boiler Replacement	Capital Renewal	4 Ea.	2	\$389,742	6199
Note: 2,070 MBH					
Copper Tube Boiler Replacement	Capital Renewal	1 Ea.	2	\$71,293	6201
Note: 1,500 MBH					
Gas Piping Replacement (SF Basis)	Capital Renewal	2,376 SF	2	\$82,388	6192
HVAC VAV Box Replacement	Capital Renewal	4 Ea.	2	\$15,495	6213
Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	2,376 SF	2	\$10,108	6210
Air Compressor Replacement	Capital Renewal	1 Ea.	3	\$5,645	6207
Note: 3 HP					
Circulation Pump Replacement	Capital Renewal	2 Ea.	3	\$28,763	6211
Replace Variable Frequency Drive	Capital Renewal	1 Ea.	3	\$4,393	6208
Note: 3 HP					
Replace Variable Frequency Drive	Capital Renewal	2 Ea.	3	\$21,249	6209



Austin ISD - McCallum HS

Mechanical							
Deficiency		Category	Qty U		Priority	Repair Cost	ID
Small Diameter Exha	austs/Hoods Replacement	Capital Renewal	1 E	a.	3	\$1,960	621
Existing Controls Are	e Obsolete	Capital Renewal	2,376 S	F	4	\$6,409	620
		Sub Total for System	12 it	ems		\$680,609	
Electrical							
Deficiency		Category	Qty U	oM P	Priority	Repair Cost	ID
Panelboard Replace	ement	Capital Renewal	1 E	a.	2	\$2,782	316
Note:	Panels do not have arc flash/PPE labeling						
Panelboard Replace	ement	Capital Renewal	1 E	a.	2	\$9,372	316
Note:	Panel "no ID" (rated 208V) was found without faceplate, exposing w	viring					
Canopy Lighting Rep	placement	Capital Renewal	9 E	a.	3	\$18,747	317
Location	: Canopy from Building B to Building A, behind the large gym wasnot with the associated canopy lighting, for this building	ID'd on either the Building A	A plan or Bui	ilding B ı	plan. It w	as included, al	ong
Exterior Mounted Bu	uilding Lighting Replacement	Capital Renewal	4 E	a.	3	\$3,607	317
_ighting Fixtures Re	placement	Capital Renewal	2,364 S	F	3	\$43,352	318
Note:	Section from Orch to Choir appeared to be newer than 1953 - no in	fo provided/available on buil	ding mods				
Public Address Syste	em Replacement, Non-main Building	Deferred Maintenance	2,364 S	F	3	\$1,673	316
Note:	Did not see evidence of seccurity or PA system in old boiler areas						
		Sub Total for System	6 ite	ems		\$79,534	
Plumbing							
Deficiency		Category	Qty U	oM P	Priority	Repair Cost	ID
Plumbing / Domestic	Water Piping System Is Beyond Its Useful Life	Capital Renewal	2,376 S	F	3	\$8,539	619
Sanitary Sewer Pipir	ng Replacement	Capital Renewal	2,376 S	F	3	\$2,638	619
Shower Replacemer	nt	Capital Renewal	1 E	a.	3	\$1,306	619
Foilet Replacement		Capital Renewal	4 E	a.	3	\$20,238	619
Jrinal Replacement		Capital Renewal	2 E	a.	3	\$2,708	619
Water Storage Tank	Replacement	Capital Renewal	1 E	a.	3	\$27,691	638
Nater Storage Tank	Replacement	Capital Renewal	1 E	a.	3	\$27,691	638
Restroom Lavatories	s Plumbing Fixtures Replacement	Capital Renewal	2 E	a.	4	\$5,433	619
		Sub Total for System	8 it	ems		\$96,244	
Fire and Life	Safety						
Deficiency		Category	Qty U	oM P	Priority	Repair Cost	ID
Fire Alarm Panel Re	placement	Capital Renewal	1 E	a.	1	\$6,868	317
Fire Alarm Replacen	nent	Capital Renewal	2,364 S	F	1	\$3,754	316
Note:	Did not see evidence of emergency lighting or PA system in old boi	ler areas					
Security Alarm Repla	acement	Capital Renewal	2,364 S	F	1	\$5,441	316
Note:	Did not see evidence of seccurity or PA system in old boiler areas						
		Sub Total for System	3 it	ems		\$16,063	
Technology							
Deficiency		Category	Qty U		Priority	Repair Cost	ID
	em Head-End Requires Replacement	Functional Deficiency	1 E		3	\$7,307	316
Note:	Did not see evidence of seccurity or PA system in old boiler areas	Tunctional Deliciency	1 6	α.	5	φ1,501	510
Note.	Did not see evidence of seccurity of PA system in oid boller areas	Sub Total for System	1 it			\$7,307	
	Out Tatal for Duilding OOED Machanical Dui	Sub Total for System					
	Sub Total for Building 005B - Mechanical Bui		30 it	ems		\$879,756	
Building: 0	05C - Theater Building (includes Band	Hall & Choir)					
Interior							
Deficiency		Category	Qty U	oMP	Priority	Repair Cost	ID
Mood Electing Bong	air	Deferred Maintenance	8,126 S	F	4	\$134,591	329
иоой гюоппу кера							
Note:	Refinish stage due to wear and tear						
	Refinish stage due to wear and tear	Sub Total for System	1 ite	ems		\$134,591	
Note:	Refinish stage due to wear and tear	Sub Total for System	1 ite	ems		\$134,591	
Wood Flooring Repa Note: Mechanical Deficiency	Refinish stage due to wear and tear	Sub Total for System	<b>1 it</b> d Qty U		Priority	<b>\$134,591</b> Repair Cost	ID



Austin ISD - McCallum HS

Deficiency						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Air Handler HVAC Component Replacement	Capital Renewal	1	Ea.	2	\$113,856	6232
Air Handler HVAC Component Replacement	Capital Renewal	2	Ea.	2	\$171,918	6233
Air Handler HVAC Component Replacement	Capital Renewal	1	Ea.	2	\$85,959	6234
Ductless Split System AC Replacement	Capital Renewal	1	Ea.	2	\$4,747	6226
HVAC VAV Box Replacement	Capital Renewal	12	Ea.	2	\$46,486	6236
Mechanical / HVAC Piping / System Is Beyond Its Useful Life	Capital Renewal	29,023	SF	2	\$70,226	6231
Replace Variable Frequency Drive	Capital Renewal	4	Ea.	3	\$17,573	6230
Small Diameter Exhausts/Hoods Replacement	Capital Renewal	1	Ea.	3	\$1,960	6237
Existing Controls Are Obsolete	Capital Renewal	29,023	SF	4	\$78,282	6224
	Sub Total for System	10	items		\$600,979	
Electrical						
Deficiency	Category	Qtv	UoM	Priority	Repair Cost	ID
Electrical Transformer Replacement	Capital Renewal	,	Ea.	2	\$36,483	3183
<b>Note:</b> Transformers not provided with required clearance					¥,	
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$5,500	3184
Note: No arc strike cabelling at panels	Capital Frenchai	•	20.	-	\$0,000	0.01
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$2,782	3185
Note: No arc strike cabelling at panels	espisa Kononui			-	Ψ <b>2</b> ,1 02	0.00
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$9,372	3186
Note: No arc strike cabelling at panels	Capital Honoral		Lu.	-	\$0,07 Z	0100
Canopy Lighting Replacement	Capital Renewal	2	Ea.	3	\$4,166	3715
Interior Power Wiring Replacement	Deferred Maintenance	29,023		3	\$34,470	
Lighting Fixtures Replacement	Capital Renewal	29,023	SF	3	\$532,239	3195
Lightning Protection System Installation	Functional Deficiency	29,023		3	\$22,665	3192
5 5	· · · · · · · · · · · · · · · · · · ·	- ,			• ,	
Note: No lightning protection installed						
Note: No lightning protection installed Public Address System Replacement, Non-main Building	Deferred Maintenance	29,023	SF	3	\$20,545	3187
			SF Ea.	3 4	\$20,545 \$1,669	
Public Address System Replacement, Non-main Building	Maintenance Functional Deficiency	1	Ea.	4		
Public Address System Replacement, Non-main Building Canopy Lighting Installation	Maintenance Functional Deficiency	1 dor to rea	Ea.	4		
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car	Maintenance Functional Deficiency nopy light for egress out from corri	1 dor to rea	Ea. r of buil	4	\$1,669	
Public Address System Replacement, Non-main Building Canopy Lighting Installation	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b>	1 dor to real <b>10</b>	Ea. r of buil <b>items</b>	4 ding	\$1,669 <b>\$669,891</b>	3194
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car Plumbing	Maintenance Functional Deficiency nopy light for egress out from corri	1 dor to rea <b>10</b> Qty	Ea. r of buil	4	\$1,669 <b>\$669,891</b> Repair Cost	3194 ID
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal	1 dor to rear 10 Qty 2	Ea. r of buil <b>items</b> UoM	4 ding Priority	\$1,669 <b>\$669,891</b> Repair Cost \$3,173	3194 ID 6215
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category	1 dor to rear <b>10</b> Qty 2 11	Ea. r of buil <b>items</b> UoM Ea.	4 ding <u>Priority</u> 2	\$1,669 <b>\$669,891</b> Repair Cost	3194 ID 6215 6220
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal Capital Renewal Capital Renewal	1 dor to rear <b>10</b> Qty 2 11	Ea. r of buil <b>items</b> UoM Ea. Ea. Ea.	4 ding Priority 2 3	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063	3194 ID 6215 6220 6221
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 Qty 2 11 3 1	Ea. r of buili items UoM Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4	\$1,669 <b>\$669,891</b> Repair Cost \$3,173 \$55,653 \$4,063 \$796	3194 ID 6215 6220 6221 6382
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a ca Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 Qty 2 11 3 1 1	Ea. r of buili items UoM Ea. Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4 4 4	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202	ID 6215 6220 6221 6382 6223
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to real 10 Qty 2 11 3 1 1 5	Ea. r of buili items UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4 4 4 4	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822	ID 6215 6220 6221 6382 6223 6217
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a ca Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9	Ea. r of buil <b>items</b> UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4 4 4	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447	3194 ID 6215 6220 6221 6382 6223 6217
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement	Maintenance Functional Deficiency nopy light for egress out from corri <b>Sub Total for System</b> Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9	Ea. r of buili items UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4 4 4 4	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822	3194 ID 6215 6220 6221 6382 6223 6217
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System	1 dor to read 10 2 11 3 1 1 5 9 <b>7</b>	Ea. rof buili items UoM Ea. Ea. Ea. Ea. Ea. Ea. Ea. Ea. Ea. Ea.	4 ding Priority 2 3 3 4 4 4 4 4	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156	ID 6215 6220 6221 6382 6223 6217 6218
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category	1 dor to read 10 2 11 3 1 1 5 9 7 7 0 ty	Ea. r of built items UoM Ea. Ea. Ea. Ea. Ea. Ea. items UoM	4 ding Priority 2 3 4 4 4 4 4 4 Priority	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost	ID 6215 6220 6221 6382 6223 6217 6218
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement	Maintenance         Functional Deficiency         nopy light for egress out from corris         Sub Total for System         Category         Capital Renewal         Sub Total for System         Category         Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 0 ty 1	Ea. of built items UoM Ea. Ea. Ea. Ea. Ea. items UoM Ea.	4 ding 2 3 4 4 4 4 4 Priority 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868	3194 ID 6215 6220 6221 6382 6223 6217 6218 ID 3191
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 Qty 1 29,023	Ea. rof buil items UoM Ea. Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF	4 ding 2 3 4 4 4 4 4 9 riority 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083	ID 6215 6220 6221 6382 6223 6217 6218 ID 3191 3190
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement Fire Sprinkler System Replacement (SF Basis)	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 0 0 ty 29,023 29,023	Ea. of buili items UoM Ea. Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF SF	4 ding 2 3 4 4 4 4 4 4 9 riority 1 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364	ID 6218 6220 6221 6382 6223 6218 1D 3190 6238
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 Qty 1 29,023 29,023 29,023	Ea. r of buili items UoM Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF SF	4 ding 2 3 4 4 4 4 4 9 riority 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364 \$66,803	ID 6218 6220 6221 6382 6223 6218 1D 3190 6238
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a cat Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement Fire Sprinkler System Replacement Security Alarm Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 Qty 1 29,023 29,023 29,023	Ea. of buili items UoM Ea. Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF SF	4 ding 2 3 4 4 4 4 4 4 9 riority 1 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364	ID 6218 6220 6221 6382 6223 6218 1D 3190 6238
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a can Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement Fire Sprinkler System Replacement (SF Basis)	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 Qty 1 29,023 29,023 29,023	Ea. r of buili items UoM Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF SF	4 ding 2 3 4 4 4 4 4 4 9 riority 1 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364 \$66,803	ID 6215 6220 6221 6382 6223 6217 6218 ID 3190 6238
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a cat Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire and Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement Fire Sprinkler System Replacement Security Alarm Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal	1 dor to read 10 2 11 3 1 1 5 9 7 7 0 ty 1 29,023 29,023 29,023 29,023 4 0 0 ty	Ea. of buili items UoM Ea. Ea. Ea. Ea. Ea. items UoM Ea. SF SF items UoM	4 ding Priority 2 3 3 4 4 4 4 4 4 4 4 9 riority 1 1 1 1 1 1 9 riority	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364 \$66,803	ID 6215 6220 6221 6382 6223 6217 6218 ID 3190 6238
Public Address System Replacement, Non-main Building Canopy Lighting Installation Note: For safety and security purposes, it is suggested to add a car Plumbing Deficiency Water Heater Replacement Toilet Replacement Urinal Replacement Custodial Mop Or Service Sink Replacement Refrigerated Water Cooler Replacement Replace classroom lavatory Restroom Lavatories Plumbing Fixtures Replacement Fire And Life Safety Deficiency Fire Alarm Panel Replacement Fire Alarm Replacement Fire Sprinkler System Replacement Fire Sprinkler System Replacement Fire Sprinkler System Replacement Fire Alarm Replacement Fire Sprinkler System Replacement Fire Alarm Replacement Fire Sprinkler System Replacement Fire Alarm Replacement	Maintenance Functional Deficiency nopy light for egress out from corri Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Sub Total for System	1 dor to read 10 2 11 3 1 1 5 9 7 7 0 ty 1 29,023 29,023 29,023 29,023 4 0 0 ty	Ea. of built items UoM Ea. Ea. Ea. Ea. Ea. items SF SF items	4 ding Priority 2 3 3 4 4 4 4 4 4 9 riority 1 1 1 1 1	\$1,669 \$669,891 Repair Cost \$3,173 \$55,653 \$4,063 \$796 \$2,202 \$12,822 \$24,447 \$103,156 Repair Cost \$6,868 \$46,083 \$302,364 \$66,803 \$422,118	ID 6215 6220 6221 6382 6223 6217 6218 3191 3190 6239 3189 3189



# Building: 005D - Stand-Alone Gym - Dance gym (includes Weight Room, Lockers & Showers)

Interior	
Interior	

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Hardwar	e Replacement	Capital Renewal		Door	3	\$23,754	3417
Note:	Replace with doors						
Interior Door Replace	ment	Capital Renewal	14	Door	3	\$26,258	3411
Note:	End of life						
Metal Interior Door Re	eplacement	Capital Renewal	2	Door	4	\$5,788	3405
Note:	Damaged/broken						
Location:	Corridor						
Toilet Partition Replace	cement	Capital Renewal	6	Stall	4	\$12,099	3402
Note:	Damaged						
Location:	Restrooms						
Interior Ceiling Repai	nting	Deferred Maintenance	10,224	SF	5	\$21,292	3400
Note:	Peeling/Flaking						
Location:	Various locations						
Interior Door Repainti	ng	Deferred Maintenance	6	Door	5	\$268	3412
Note:	Needs paint						
Interior Door Repair		Deferred Maintenance	4	Door	5	\$2,582	3410
Interior Wall Repainti	ıg	Deferred Maintenance	9,800	SF Wall	5	\$22,014	3401
Note:	Peeling/chipped/missing						
Location:	various locations						
		Sub Total for System	8	items		\$114,054	
Mechanical							
Deficiency		Category	Qtv	UoM	Priority	Repair Cost	ID
Air Cooled Condense	r Repair	Deferred Maintenance	-	TonAC	2	\$80,104	6253
Note:	compressor operation is short-cycling						
Location:	north end of building						
Copper Tube Boiler F	leplacement	Capital Renewal	1	Ea.	2	\$32,565	6383
HVAC VAV Box Repl	acement	Capital Renewal	23	Ea.	2	\$89,099	6260
Energy Recovery Uni	t Replacement	Capital Renewal	1	Ea.	3	\$20,116	6254
Danlaga Variahla Fra						φ=0,0	
Replace variable Fre	quency Drive	Capital Renewal	1	Ea.	3	\$4,393	6255
•		Capital Renewal Capital Renewal		Ea. Ea.	3 3		6255 6256
Replace Variable Fre	quency Drive	·	3			\$4,393	
Replace Variable Fre Replace Variable Fre	quency Drive quency Drive	Capital Renewal	3 1	Ea.	3	\$4,393 \$13,179	6256
Replace Variable Fre Replace Variable Fre Circulation Pump Rep	quency Drive quency Drive blacement	Capital Renewal Capital Renewal	3 1 1	Ea. Ea.	3 3	\$4,393 \$13,179 \$5,223	6256 6257 6258
Replace Variable Fre Replace Variable Fre Circulation Pump Rep	quency Drive quency Drive blacement	Capital Renewal Capital Renewal Capital Renewal	3 1 1 1	Ea. Ea. Ea.	3 3 4	\$4,393 \$13,179 \$5,223 \$6,850	6256 6257 6258
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep	quency Drive quency Drive blacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal	3 1 1 1	Ea. Ea. Ea. Ea.	3 3 4	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313	6256 6257 6258
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical	quency Drive quency Drive blacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b>	3 1 1 9	Ea. Ea. Ea. Ea. <b>items</b>	3 3 4 4	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b>	6256 6257 6258 6259
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep <b>Electrical</b> Deficiency	quency Drive quency Drive blacement blacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category	3 1 1 9 Qty	Ea. Ea. Ea. items	3 3 4	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost	6256 6257 6258 6259
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep <b>Electrical</b> Deficiency Electrical Transforme	r Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b>	3 1 1 9 Qty	Ea. Ea. Ea. Ea. <b>items</b>	3 3 4 4 Priority	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b>	6256 6257 6258 6259
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep <b>Electrical</b> Deficiency Electrical Transforme <b>Note:</b>	quency Drive quency Drive blacement blacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category	3 1 1 9 Qty	Ea. Ea. Ea. items	3 3 4 4 Priority	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost	6256 6257 6258 6259
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location:	r Replacement KVA assumed (estimate) Exterior location	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category Capital Renewal	3 1 1 1 9 Qty 1	Ea. Ea. Ea. items	3 3 4 4 9 Priority 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519	6256 6257 6258 6259 ID
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Location: Electrical Transforme	r Replacement KVA assumed (estimate) Exterior location r Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category	3 1 1 1 9 Qty 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 3 4 4 Priority	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost	6256 6257 6258 6259 ID
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Electrical Transforme Note:	r Replacement KVA assumed (estimate) Exterior location	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category Capital Renewal	3 1 1 1 9 Qty 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 3 4 4 9 Priority 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519	6256 6257 6258 6259 ID
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Note: Location:	quency Drive quency Drive blacement blacement r Replacement KVA assumed (estimate) Exterior location r Replacement Storage/clearance issue "Elec bath" room	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category Capital Renewal Capital Renewal	3 1 1 9 <u>Qty</u> 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 4 4 Priority 2 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519 \$7,287	6256 6257 6258 6259 ID 3237
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Electrical Transforme Note: Location:	r Replacement KVA assumed (estimate) Exterior location r Replacement Storage/clearance issue "Elec bath" room r Replacement	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category Capital Renewal	3 1 1 9 <u>Qty</u> 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 3 4 4 9 Priority 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519	6256 6257 6258 6259 ID 3237
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Electrical Transforme Note: Location:	quency Drive quency Drive blacement blacement r Replacement KVA assumed (estimate) Exterior location r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue	Capital Renewal Capital Renewal Capital Renewal Capital Renewal <b>Sub Total for System</b> Category Capital Renewal Capital Renewal	3 1 1 9 <u>Qty</u> 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 4 4 Priority 2 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519 \$7,287	6256 6257 6258 6259 ID 3237
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Electrical Transforme Note: Location: Electrical Transforme Note: Location:	quency Drive quency Drive blacement blacement r Replacement KVA assumed (estimate) Exterior location r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue "Elec bath" room	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal	3 1 1 9 Qty 1 1	Ea. Ea. Ea. items UoM Ea. Ea.	3 3 4 4 Priority 2 2 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519 \$7,287 \$5,919	6256 6257 6258 6259 1D 3237 3238
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Electrical Transforme Note: Location: Electrical Transforme Note: Location: Panelboard Replacer	r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal	3 1 1 9 Qty 1 1	Ea. Ea. Ea. <b>items</b> UoM Ea.	3 4 4 Priority 2 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519 \$7,287	6256 6257 6258 6259 1D 3237 3238
Replace Variable Fre Replace Variable Fre Circulation Pump Rep Circulation Pump Rep Electrical Deficiency Electrical Transforme Note: Location: Electrical Transforme Note: Location:	quency Drive quency Drive blacement blacement r Replacement KVA assumed (estimate) Exterior location r Replacement Storage/clearance issue "Elec bath" room r Replacement Storage/clearance issue "Elec bath" room nent Storage/Clearance issue at "elec bath" room, pa	Capital Renewal Capital Renewal Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal	3 1 1 9 <u>Qty</u> 1 1 1	Ea. Ea. Ea. items UoM Ea. Ea.	3 3 4 4 Priority 2 2 2	\$4,393 \$13,179 \$5,223 \$6,850 \$4,313 <b>\$255,842</b> Repair Cost \$5,519 \$7,287 \$5,919	6256 6257 6258 6259 3237 3238 3238 3238



Austin ISD - McCallum HS

#### Electrical

Electrical	Catagon	<u>067 11-14</u>	Driant	Donais Orai	
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID 2040
Panelboard Replacement	Capital Renewal	1 Ea.	2	\$2,782	3242
Note: Storage/Clearance issue at "elec bath" room, panels do	0 1	4 5-	•	¢0,000	0040
Panelboard Replacement	Capital Renewal	1 Ea.	2	\$6,688	3243
Note: 125A, Storage/Clearance issue at "elec bath" room, pa			•	¢40.004	0044
Panelboard Replacement	Capital Renewal	1 Ea.	2	\$13,891	3244
Note: Storage/Clearance issue at "elec bath" room, panels do		1 5-	0	¢40.645	2226
Switchgear Replacement	Capital Renewal	1 Ea.	2	\$13,645	3236
Note: Assume service disconnect/main switch gear, with ratin	Capital Renewal	4 Ea.	3	¢0 222	3251
Canopy Lighting Replacement Exterior Mounted Building Lighting Replacement	•	4 Ea. 6 Ea.	3	\$8,332 \$5,410	3251
Interior Power Wiring Replacement	Capital Renewal Deferred	0 Ea. 22,720 SF	3	\$5,410 \$26,984	3252
	Maintenance	22,720 31	5	φ20,90 <del>4</del>	5255
Lightning Protection System Installation	Functional Deficiency	22,720 SF	3	\$17,742	3250
Note: No lightning protection found					
Public Address System Replacement, Non-main Building	Deferred Maintenance	22,720 SF	3	\$16,083	3246
Note: "1ea"					
	Sub Total for System	14 items		\$137,242	
Plumbing					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Gas Water Heater Replacement	Capital Renewal	6 Ea.	3	\$82,748	6241
Shower Replacement	Capital Renewal	18 Ea.	3	\$23,516	6245
Shower Replacement	Capital Renewal	14 Ea.	3	\$18,290	6249
Note: 5 head carousels					
Toilet Replacement	Capital Renewal	41 Ea.	3	\$207,435	6246
Urinal Replacement	Capital Renewal	10 Ea.	3	\$13,542	6247
Water Storage Tank Replacement	Capital Renewal	1 Ea.	3	\$27,691	6240
Custodial Mop Or Service Sink Replacement	Capital Renewal	1 Ea.	4	\$796	6244
Refrigerated Water Cooler Replacement	Capital Renewal	6 Ea.	4	\$13,214	6248
Replace classroom lavatory	Capital Renewal	1 Ea.	4	\$2,565	6242
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal	41 Ea.	4	\$111,368	6243
	Sub Total for System	10 items		\$501,165	
Fire and Life Safety					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Fire Alarm Panel Replacement	Capital Renewal	1 Ea.	1	\$6,868	3249
Fire Alarm Replacement	Capital Renewal	22,720 SF	1	\$36,075	3248
Security Alarm Replacement	Capital Renewal	22,720 SF	1	\$52,295	
	Sub Total for System	3 items		\$95,238	
Technology	· · · · · · · · · · · · · · · · · · ·			,	
	Cotogon	Oty HoM	Priority	Panair Cost	п
Deficiency Public Address System Head-End Requires Replacement	Category Functional Deficiency	Qty UoM 1 Ea.	3	Repair Cost \$7,307	ID 3247
Public Address System Head-End Requires Replacement		i ⊑a. 1 items	3		3247
On a sighting	Sub Total for System	i items		\$7,307	
Specialties					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Metal Gym Locker Replacement	Capital Renewal	166 Ea.	4	\$80,592	3433
Note: End of life					
Location: Boys' locker room				***	
	Sub Total for System	1 items		\$80,592	
Sub Total for Building 005D - Stand-Alone Gym - Dance gym (includes	Weight Room, Lockers & Showers)	46 items		\$1,191,441	
Building: 005E - Mechanical Building					
Mechanical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Chiller HVAC Component Replacement	Capital Renewal	2 Ea.	2	\$1,281,975	6261



\$1,872,911

18 items

Austin ISD - McCallum HS

#### Mechanical

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Mechanical / HVAC	Piping / System Is Beyond Its Useful Life	Capital Renewal	1,139 SF	2	\$2,037	6265
Circulation Pump Re	placement	Capital Renewal	2 Ea.	3	\$23,121	6267
Circulation Pump Re	placement	Capital Renewal	2 Ea.	3	\$115,412	6269
Circulation Pump Re	placement	Capital Renewal	2 Ea.	3	\$115,412	6270
Large Diameter Exh	austs/Hoods Replacement	Capital Renewal	1 Ea.	3	\$8,036	6271
Replace Variable Fr	equency Drive	Capital Renewal	2 Ea.	3	\$21,249	6263
Replace Variable Fr	equency Drive	Capital Renewal	2 Ea.	3	\$27,872	6264
Existing Controls Ar	e Obsolete	Capital Renewal	1,139 SF	4	\$3,072	6384
		Sub Total for System	10 item	s	\$1,809,001	
Electrical						
Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Distribution Panel R	eplacement	Capital Renewal	1 Ea.	2	\$25,176	3255
Note:	Distribution panel DP1V is in need of immediate repair or re the main breaker appears broken and is held together by ta		not secured and	interior pow	er wires are exp	osed;
Electrical Transform	er Replacement	Capital Renewal	1 Ea.	2	\$5,519	3254
Panelboard Replace	ment	Capital Renewal	1 Ea.	2	\$2,782	3256
Panelboard Replace	ment	Capital Renewal	1 Ea.	2	\$5,500	3261
Location	: Mounted on exterior					
	: Mounted on exterior ilding Lighting Replacement	Capital Renewal	2 Ea.	3	\$1,803	3258
	ilding Lighting Replacement	Capital Renewal Deferred Maintenance	2 Ea. 1,139 SF	3 3	\$1,803 \$1,353	3258 3260
Exterior Mounted Bu	ilding Lighting Replacement g Replacement	Deferred				
Exterior Mounted Bu Interior Power Wiring	ilding Lighting Replacement g Replacement placement	Deferred Maintenance	1,139 SF	3	\$1,353	3260
Exterior Mounted Bu Interior Power Wirin Lighting Fixtures Re	ilding Lighting Replacement g Replacement placement	Deferred Maintenance Capital Renewal	1,139 SF 1,139 SF	3	\$1,353 \$20,888	3260 3259

Sub Total for Building 005E - Mechanical Building

## Building: 005F - Baseball Batting Cage & Storage

#### Interior

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Athletic Sport Floori	ing Replacement	Capital Renewal	3,358	SF	3	\$51,516	3438
Note:	End of life						
Interior Wood Wall	Replacement (LC)	Capital Renewal	186	SF	4	\$2,917	3437
		Sub Total for System	2	items		\$54,433	
Electrical							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replace	ement	Capital Renewal	1	Ea.	2	\$5,500	3262
Location	n: Mounted on exterior						
Canopy Lighting Re	placement	Capital Renewal	10	Ea.	3	\$20,830	3268
Note:	Batting cage assumed to be large canopy						
Exterior Mounted B	uilding Lighting Replacement	Capital Renewal	2	Ea.	3	\$1,803	3269
Lightning Protection	System Installation	Functional Deficiency	3,731	SF	3	\$2,914	3267
Note:	No lightning protection found						
		Sub Total for System	4	items		\$31,046	
Fire and Life	Safety						
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Emergency Lighting	Installation	Functional Deficiency	3,731	SF	1	\$2,910	3266
Note:	No PA or emergency lighting components installed						
Fire Alarm Is Missin	g	Capital Renewal	3,731	SF	1	\$11,413	3264
Note:	No PA or Emergency lighting components						
Fire Alarm Panel Is	Missing	Educational Adequacy	1	Ea.	1	\$7,672	3265
Note:	No PA or emergency lighting components installed						

Functional Deficiency

3,731 SF

1

Security Alarm Is Missing

\$8,588 3263



Austin ISD - McCallum HS

#### Fire and Life Safety

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Note:	No PA or security system					
		Sub Total for System	4 items		\$30,583	
	Sub Total for Building 005F - Base	eball Batting Cage & Storage	10 items		\$116,062	

# Building: 005G - Storage Building (Wood), Track Storage

Deficiency		Category	Qtv	UoM	Priority	Repair Cost	ID
Exposed Ceiling Re	placement	Capital Renewal	464		4	\$401	3439
Note:	Ceiling is Plywood, repair/replace wood rotting						
Interior Wall Repair	ting	Deferred Maintenance	464	SF Wall	5	\$1,042	3440
Note:	Needs another coat on walls						
		Sub Total for System	2	items		\$1,444	
Electrical							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replac	ement	Capital Renewal	1	Ea.	2	\$4,236	3291
Note:	Panels have no arc flash labeling						
Interior Power Wirin	g Replacement	Deferred Maintenance	464	SF	3	\$551	3293
Lightning Protection	System Installation	Functional Deficiency	464	SF	3	\$362	3292
Note:	No lighting protection installed						
		Sub Total for System	3	items		\$5,149	
		Building (Wood), Track Storage	5	items		\$6,593	

# Building: 005H - Stand-Alone Auditorium

Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Carpet Flooring Replacement	Capital Renewal	760	SF	4	\$9,622	3442
Note: Wear and tear						
Location: Entry and seating						
	Sub Total for System	1	items		\$9,622	
Mechanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Copper Tube Boiler Replacement	Capital Renewal	1	Ea.	2	\$97,435	6385
Exterior Chiller Replacement	Capital Renewal	1	Ea.	2	\$191,385	6286
HVAC VAV Box Replacement	Capital Renewal	15	Ea.	2	\$58,108	6292
Circulation Pump Replacement	Capital Renewal	2	Ea.	3	\$23,121	6291
Replace Variable Frequency Drive	Capital Renewal	5	Ea.	3	\$26,116	6287
Replace Variable Frequency Drive	Capital Renewal	3	Ea.	3	\$13,179	6288
Replace Variable Frequency Drive	Capital Renewal	1	Ea.	3	\$7,559	6289
Circulation Pump Replacement	Capital Renewal	2	Ea.	4	\$13,700	6290
Existing Controls Are Obsolete	Capital Renewal	25,328	SF	4	\$68,315	6285
	Sub Total for System	9	items		\$498,919	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lightning Protection System Installation	Functional Deficiency	25,328	SF	3	\$19,779	3294
Note: No lightning protection found						
	Sub Total for System	1	items		\$19,779	
Plumbing						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Gas Water Heater Replacement	Capital Renewal	2	Ea.	3	\$27,583	6275
	Sub Total for System	1	items		\$27,583	
	Sub Total for Building 005H - Stand-Alone Auditorium	12	items		\$555,902	
	Total for Campus	247	items		\$25,327,905	



# McCallum HS - Life Cycle Summary Yrs 1-10

### Site Level Life Cycle Items

#### Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Wood		110	LF	\$3,323	10
Parking Lot Pavement	Asphalt		183	CAR	\$265,497	10
Roadway Pavement	Asphalt Driveways		114,275	SF	\$734,837	10
Roadway Pavement	Concrete Driveways		750	SF	\$9,363	10
		Sub Total for System	4	items	\$1,013,020	
		Sub Total for Building -	4	items	\$1,013,020	

### Building: 005A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Wooden Door		1	Door	\$3,164	1
Exterior Wall Veneer	Pre-cast Concrete Panel - Bldg SF basis		3,680	SF	\$69,010	2
Exterior Operating Windows	Aluminum - Windows per SF		84	SF	\$8,377	2
Exterior Operating Windows	Aluminum - Windows per SF		88	SF	\$8,726	2
Exterior Operating Windows	Aluminum - Windows per SF		110	SF	\$10,970	2
Exterior Entrance Doors	Steel - Insulated and Painted		35	Door	\$129,745	5
Exterior Operating Windows	Aluminum - Windows per SF		484	SF	\$48,268	7
Exterior Operating Windows	Aluminum - Windows per SF		8	SF	\$748	7
Exterior Operating Windows	Aluminum - Windows per SF		189	SF	\$18,848	7
Exterior Operating Windows	Aluminum - Windows per SF		138	SF	\$13,762	7
Exterior Operating Windows	Aluminum - Windows per SF		1,734	SF	\$172,926	7
Exterior Entrance Doors	Wooden Door		1	Door	\$3,164	9
Exterior Window Wall	Storefront / Curtain Wall (Bldg SF)		85,563	SF	\$2,069,029	10
Exterior Entrance Doors	Steel - Insulated and Painted		25	Door	\$92,675	10
		Sub Total for System	14	items	\$2,649,412	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)		57,042	SF	\$255,601	2
Compartments and Cubicles	Toilet Partitions		39	Stall	\$78,643	2
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		1,840	SF	\$6,213	5
Note:	FRP/Kitchen					
Acoustical Suspended Ceilings	Ceilings - Adhered acoustical tiles		22,081	SF	\$153,854	5
Tile Flooring	Quarry Tile		1,840	SF	\$50,300	5
Wood Flooring	Wood Flooring - All Types		18,401	SF	\$396,356	5
Interior Swinging Doors	Storefront door (Aluminum/Glass)		2	Door	\$7,242	5
Interior Swinging Doors	Metal Door (Steel)		16	Door	\$46,301	5
Tile Flooring	Ceramic Tile		46,002	SF	\$812,731	5
Carpeting	Carpet		18,401	SF	\$232,960	6
Interior Swinging Doors	Wooden Door		154	Door	\$288,842	6
Interior Door Supplementary Components	Door Hardware		170	Door	\$252,383	8
Wall Painting and Coating	Painting/Staining (Bldg SF)		57,042	SF	\$255,601	9
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		71,763	SF	\$242,326	10
Suspended Plaster and	Painted ceilings		36,801	SF	\$76,642	10
		Sub Total for System	15	items	\$3,155,994	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Heating Equipment	Unit Heater Steam/HW (85 MBH)		4	Ea.	\$5,944	8
Decentralized Cooling	Fan Coil - Water Cool/Water Heat ( 3 Ton)		11	Ea.	\$37,291	8
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		184,007	SF	\$496,308	10
Other HVAC Distribution Systems	VFD (25 HP)		1	Ea.	\$10,625	10
Other HVAC Distribution Systems	VFD (20 HP)		4	Ea.	\$35,269	10
Other HVAC Distribution Systems	VFD (10 HP)		4	Ea.	\$22,829	10



Austin ISD - McCallum HS

#### Mechanical

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Exhaust Air	Kitchen Exhaust Hoods		3	Ea.	\$33,574	10
		Sub Total for System	8	items	\$675,414	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Power Distribution	Panelboard - 120/208 225A		2	Ea.	\$10,999	8
	Note: Panel TP1D (in elec 112) is 20 years old; and the "no_r	name_pnl" in prep room is app	orox. 10 y	ears old		
Power Distribution	Panelboard - 120/240 225A		1	Ea.	\$7,823	8
	Note: Panel J3 in Big Gym workout area is 20 years old					
		Sub Total for System	2	items	\$18,822	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Plumbing Fixtures	Restroom Lavatory		4	Ea.	\$10,865	4
Plumbing Fixtures	Restroom Lavatory		6	Ea.	\$16,298	4
Domestic Water Equipment	Water Heater - Electric - 52 gallon		1	Ea.	\$2,684	10
Domestic Water Equipment	Water Heater - Gas - 100 Gallon		3	Ea.	\$19,151	10
		Sub Total for System	4	items	\$48,998	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Casework	Fixed Cabinetry		62	Room	\$545,716	3
Casework	Lockers		557	Ea.	\$296,739	5
Casework	Lockers, Gym		358	Ea.	\$173,807	5
Fixed Multiple Seating	Bleachers		850	Seat	\$351,142	5
		Sub Total for System	4	items	\$1,367,404	
	05A - Main building includes Administration Offices, Classro		47	items	\$7,916,044	

Exterior						
Uniformat Description	LC Type Description			UoM	· · ·	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		7	Door	\$25,949	5
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum		2	Door	\$7,938	7
Exterior Wall Veneer	Brick - Bldg SF basis		2,340	SF	\$65,741	10
		Sub Total for System	3	items	\$99,628	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings		236	SF	\$492	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		1,655	SF	\$7,416	5
Interior Swinging Doors	Metal Door (Steel)		2	Door	\$5,788	5
Interior Swinging Doors	Wooden Door		24	Door	\$45,014	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		2,128	SF	\$7,186	8
Wall Coverings	Vinyl/Fabric Wall Covering		709	SF	\$3,341	8
Compartments and Cubicles	Toilet Partitions		1	Stall	\$2,016	8
Interior Door Supplementary Components	Door Hardware		26	Door	\$38,600	8
Resilient Flooring	Vinyl Composition Tile Flooring		2,128	SF	\$17,399	9
		Sub Total for System	9	items	\$127,251	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		1	Ea.	\$6,423	4
Decentralized Cooling	Ductless Split System (2 Ton)		1	Ea.	\$4,747	4
Heat Generation	Boiler - Copper Tube (2400 MBH)		4	Ea.	\$389,742	10
Heat Generation	Boiler - Copper Tube (1600 MBH)		1	Ea.	\$71,293	10
Note	abandoned/main mech.					
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		2,376	SF	\$6,409	10
Other HVAC Distribution Systems	VFD (5 HP)		1	Ea.	\$4,393	10
Other HVAC Distribution Systems	VFD (25 HP)		2	Ea.	\$21,249	10
Facility Hydronic Distribution	Pump- 25HP (Ea.)		2	Ea.	\$28,763	10
		Sub Total for System	8	items	\$533,018	
	Sub Total for Building 005B - Mechanical	Building (old Boiler House)	20	items	\$759,898	



Austin ISD - McCallum HS

### Building: 005C - Theater Building (includes Band Hall & Choir)

### Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		11	Door	\$40,777	5
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum		4	Door	\$15,876	7
Exterior Utility Doors	Overhead Door		1	Door	\$8,307	7
		Sub Total for System	3	items	\$64,960	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	1	2,902		\$9,799	5
Suspended Plaster and	Painted ceilings		4,353	SF	\$9,066	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		18,865	SF	\$84,533	5
Resilient Flooring	Vinyl Composition Tile Flooring		12,190	SF	\$99,686	5
Wood Flooring	Wood Flooring - All Types		8,126	SF	\$175,033	5
Interior Swinging Doors	Metal Door (Steel)		4	Door	\$11,575	5
Carpeting	Carpet		4,353	SF	\$55,110	6
Tile Flooring	Ceramic Tile		871	SF	\$15,388	6
Interior Swinging Doors	Wooden Door		34	Door	\$63,770	6
Interior Door Supplementary Components	Door Hardware		38	Door	\$56,415	6
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		8,707	SF	\$29,401	8
Wall Coverings	FRP Wall Finish		871	SF Wall	\$6,627	8
Wall Coverings	Vinyl/Fabric Wall Covering		8,707	SF	\$41,028	8
Compartments and Cubicles	Toilet Partitions		9	Stall	\$18,148	8
Athletic Flooring	Athletic/Sport Flooring		2,902	SF	\$44,521	10
Resilient Flooring	Rubber Tile Flooring		580	SF	\$8,768	10
		Sub Total for System	16	items	\$728,868	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Fan Coil - DX Cool w/Electric Heat (3 Ton)			Ea.	\$1,970	4
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		1	Ea.	\$6,423	4
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		29,023	SF	\$78,282	10
Other HVAC Distribution Systems	VFD (5 HP)		4	Ea.	\$17,573	10
		Sub Total for System	4	items	\$104,247	
Electrical						
Uniformat Description	LC Type Description		Otv	UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 100A			Ea.	\$2,782	5
	: No arc strike cabelling at panels			20.	ψ2,102	0
Note	. No are strike cabelling at parlets	Sub Total for System	1	items	\$2,782	
Dlumbing			-	literine	<i> </i>	
Plumbing			_			
Uniformat Description	LC Type Description			UoM		Remaining Life
Domestic Water Equipment	Water Heater - Electric - 20 gallon			Ea.	\$3,173	10
			29,023		\$104,301	10
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)					10
Domestic Water Piping Sanitary Sewerage Piping	Domestic Water Piping System (Bldg.SF) Sanitary Sewer Piping		29,023		\$32,222	10
Domestic Water Piping Sanitary Sewerage Piping		Sub Total for System		SF items	\$32,222 <b>\$139,696</b>	10
Domestic Water Piping		Sub Total for System				
Domestic Water Piping Sanitary Sewerage Piping		Sub Total for System	3		\$139,696	Remaining Life
Domestic Water Piping Sanitary Sewerage Piping Specialties	Sanitary Sewer Piping	Sub Total for System	3	items UoM	\$139,696	
Domestic Water Piping Sanitary Sewerage Piping <b>Specialties</b> Uniformat Description	Sanitary Sewer Piping	Sub Total for System	3 Qty 282	items UoM	<b>\$139,696</b> Repair Cost	Remaining Life
Domestic Water Piping Sanitary Sewerage Piping Specialties Uniformat Description Fixed Multiple Seating	Sanitary Sewer Piping LC Type Description Auditorium Seating	Sub Total for System	3 Qty 282 150	items UoM Ea.	\$139,696 Repair Cost \$126,508	Remaining Life

### Building: 005D - Stand-Alone Gym - Dance gym (includes Weight Room, Lockers & Showers)

Uniformat Description	LC Type Description		Qty UoM	Repair Cost Remaining Lif	e
Exterior Entrance Doors	Steel - Insulated and Painted		19 Door	\$70,433 5	-
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum		2 Door	\$7,938 7	
		Sub Total for System	2 items	\$78,371	



Austin ISD - McCallum HS

#### Interior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Compartments and Cubicles	Toilet Partitions		18	Stall	\$36,297	2
Suspended Plaster and	Painted ceilings		10,224	SF	\$21,292	3
Wall Painting and Coating	Painting/Staining (Bldg SF)		17,949	SF	\$80,428	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		909	SF	\$3,069	5
Fluid-Applied Flooring	Epoxy Coating		2,272	SF	\$27,385	5
Resilient Flooring	Vinyl Composition Tile Flooring		4,317	SF	\$35,303	5
Interior Swinging Doors	Storefront door (Aluminum/Glass)		2	Door	\$7,242	5
Tile Flooring	Ceramic Tile		6,816	SF	\$120,420	6
Interior Door Supplementary Components	Door Hardware		24	Door	\$35,631	8
Athletic Flooring	Athletic/Sport Flooring		4,544	SF	\$69,711	10
Wood Flooring	Wood Flooring - All Types		4,544	SF	\$97,877	10
		Sub Total for System	11	items	\$534,657	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Other HVAC Distribution Systems	VFD (5 HP)			Ea.	\$4,393	10
Other HVAC Distribution Systems	VFD (5 HP)		3	Ea.	\$13,179	10
Other HVAC Distribution Systems	VFD (7.5 HP)		1	Ea.	\$5,223	10
Facility Hydronic Distribution	Pump - 5HP		1	Ea.	\$6,850	10
Facility Hydronic Distribution	Pump - 1HP or Less (Ea.)		1	Ea.	\$4,313	10
Heat Generation	Boiler - Copper Tube (750 MBH)		1	Ea.	\$32,565	10
		Sub Total for System	6	items	\$66,523	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)		22,720	SF	\$416,652	10
Note	Approximately 1/2 of the 22720 coverage of lightin years old	ng appears to be 10 years old or le	ess, the rer	maining 1/2	has lighting that is n	nore than 20
	years ou	Sub Total for System	1	items	\$416,652	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Gas - 200 Gallon		6	Ea.	\$82,748	10
Note	: 4 of the 6 do not work: 3 of these 4 are shut down	with fault codes on screen, the fo	urth one h	as a blank s	creen and is inopera	able
Domestic Water Equipment	Gas Piping System (BldgSF)		5,680	SF	\$196,956	10
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		22,720	SF	\$81,650	10
Sanitary Sewerage Piping	Sanitary Sewer Piping		22,720	SF	\$25,224	10
		Sub Total for System	4	items	\$386,578	
Specialties		-				
Uniformat Description	LC Type Description		Qtv	UoM	Repair Cost	Remaining Life
Casework	Lockers, Gym			Ea.	\$141,764	4
-		Sub Total for System		items	\$141,764	
					\$1,624,545	

### Building: 005E - Mechanical Building

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		2	Door	\$7,414	5
		Sub Total for System	1	items	\$7,414	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Central Cooling	Chiller - Indoor Water Cooled (750 Tons)		2	Ea.	\$1,281,975	10
Central Cooling	Cooling Tower - Metal (750 Tons)		2	Ea.	\$210,814	10
Other HVAC Distribution Systems	VFD (25 HP)		2	Ea.	\$21,249	10
Other HVAC Distribution Systems	VFD (40 HP)		2	Ea.	\$27,872	10
Facility Hydronic Distribution	Pump- 10HP (Ea.)		2	Ea.	\$23,121	10
Facility Hydronic Distribution	Pump - 50HP - (Ea.)		2	Ea.	\$115,412	10
Facility Hydronic Distribution	Pump - 50HP - (Ea.)		2	Ea.	\$115,412	10
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		1,139	SF	\$3,072	10
		Sub Total for System	8	items	\$1,798,928	
	Sub Total for Building	005E - Mechanical Building	9	items	\$1,806,342	



Austin ISD - McCallum HS

### Building: 005F - Baseball Batting Cage & Storage

#### Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Wood / Composite Siding - Bldg SF basis		746	SF	\$9,661	10
		Sub Total for System	1	items	\$9,661	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Paneling	Wood Panel wall		187	SF	\$2,933	5
Wall Coverings	Vinyl/Fabric Wall Covering		3,171	SF	\$14,942	5
		Sub Total for System	2	items	\$17,874	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)		731	SF	\$13,405	5
	Note: Interior lighting found in shed and concrete enclosur	e - sq footage estimated for the	se two stru	uctures		
Power Distribution	Power Wiring		3,731	SF	\$4,431	10
		Sub Total for System	2	items	\$17,837	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Lockers, Gym		50	Ea.	\$24,275	5
		Sub Total for System	1	items	\$24,275	
	Sub Total for Building 005F - Baseb	all Batting Cage & Storage	6	items	\$69,646	
Buildina: 005G - St	orage Building (Wood), Track Stora	ae				
-		5-				
Exterior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
			-	-	A7 444	

Exterior Entrance Doors	Steel - Insulated and Painted		2	Door	\$7,414	4
		Sub Total for System	1	items	\$7,414	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)		464	SF	\$2,079	7
		Sub Total for System	1	items	\$2,079	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)		464	SF	\$8,509	10
	Note: Interior LED lighting appears to be no more the	han 10 years old				
		Sub Total for System	1	items	\$8,509	
	Sub Total for Building 005G - Storage	e Building (Wood), Track Storage	3	items	\$18,002	

### Building: 005H - Stand-Alone Auditorium

#### Interior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Carpeting	Carpet		760	SF	\$9,622	2
Suspended Plaster and	Painted ceilings		3,799	SF	\$7,912	5
Wall Coverings	Vinyl/Fabric Wall Covering		2,533	SF	\$11,936	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		10,131	SF	\$45,396	5
Wood Flooring	Wood Flooring - All Types		5,066	SF	\$109,121	5
Interior Swinging Doors	Metal Door (Steel)		2	Door	\$5,788	5
Interior Swinging Doors	Wooden Door		24	Door	\$45,014	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		6,332	SF	\$21,382	8
Compartments and Cubicles	Toilet Partitions		12	Stall	\$24,198	8
Interior Door Supplementary Components	Door Hardware		26	Door	\$38,600	8
Carpeting	Carpet		760	SF	\$9,622	10
		Sub Total for System	11	items	\$328,589	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		4	Ea.	\$25,690	4
Central Cooling	Chiller - Outdoor Air Cooled (20 Ton)		1	Ea.	\$35,469	4
Decentralized Cooling	Ductless Split System (2 Ton)		4	Ea.	\$18,987	4
Decentralized Cooling	Ductless Split System (3 Ton)		1	Ea.	\$5,425	4



Austin ISD - McCallum HS

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		25,328	SF	\$68,315	10
Central Cooling	Chiller - Outdoor Air Cooled (175 Tons)		1	Ea.	\$191,385	10
Other HVAC Distribution Systems	VFD (7.5 HP)		5	Ea.	\$26,116	10
Other HVAC Distribution Systems	VFD (5 HP)		3	Ea.	\$13,179	10
Other HVAC Distribution Systems	VFD (15 HP)		1	Ea.	\$7,559	10
Facility Hydronic Distribution	4-Pipe System		25,328	SF	\$61,286	10
Facility Hydronic Distribution	Pump - 5HP		2	Ea.	\$13,700	10
Facility Hydronic Distribution	Pump- 10HP (Ea.)		2	Ea.	\$23,121	10
HVAC Air Distribution	AHU 30,000 CFM Outdoor		1	Ea.	\$229,560	10
HVAC Air Distribution	AHU 15,000 CFM Outdoor		2	Ea.	\$288,253	10
HVAC Air Distribution	AHU 10,000 CFM Outdoor		1	Ea.	\$101,341	10
HVAC Air Distribution	AHU 5,000 CFM Outdoor		3	Ea.	\$148,301	10
Exhaust Air	Roof Exhaust Fan - Large		1	Ea.	\$8,036	10
Heat Generation	Boiler - Copper Tube (2400 MBH)		1	Ea.	\$97,435	10
		Sub Total for System	18	items	\$1,363,159	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)		25,328	SF	\$17,929	4
Lighting Fixtures	Building Mounted Fixtures (Ea.)		22	Ea.	\$19,838	4
Lighting Fixtures	Canopy Mounted Fixtures (Ea.)		4	Ea.	\$8,332	10
Lighting Fixtures	Light Fixtures (Bldg SF)		25,328	SF	\$464,479	10
		Sub Total for System	4	items	\$510,578	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Plumbing Fixtures	Restroom Lavatory		1	Ea.	\$2,716	4
Plumbing Fixtures	Sink - Service / Mop Sink		4	Ea.	\$3,184	4
Plumbing Fixtures	Toilets		18	Ea.	\$91,069	4
Plumbing Fixtures	Urinals		4	Ea.	\$5,417	4
Plumbing Fixtures	Refrigerated Drinking Fountain		4	Ea.	\$8,810	4
Plumbing Fixtures	Restroom Lavatory		2	Ea.	\$5,433	4
1	Note: 3 faucet head wash station					
Plumbing Fixtures	Showers		1	Ea.	\$1,306	4
Domestic Water Equipment	Backflow Preventers - 4 in. (Ea.)		1	Ea.	\$7,685	6
Domestic Water Equipment	Water Heater - Gas - 200 Gallon		2	Ea.	\$27,583	10
Plumbing Fixtures	Classroom Lavatory		12	Ea.	\$30,774	10
		Sub Total for System	10	items	\$183,976	
Fire and Life Safety						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Fire Detection and Alarm	Fire Alarm		25,328	SF	\$40,216	3
Fire Detection and Alarm	Fire Alarm Panel		1	Ea.	\$6,868	3
Security System Component	Security Alarm System		25,328	SF	\$58,298	4
		Sub Total for System	3	items	\$105,382	
Specialties						
Iniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Lif
Fixed Multiple Seating	Auditorium Seating		1,127	Ea.	\$505,583	5
		Sub Total for System	1	items	\$505,583	
	Sub Total for Building 005	H - Stand-Alone Auditorium	47	items	\$2,997,267	
	ous rotario. Sanang oo				<i>q</i> =,001,=01	



Austin ISD - McCallum HS

## **Supporting Photos**

### **General Site Photos**




Wood door is well worn



Concrete masonry wall has chipped and peeling paint



corrosion of acoustic ceiling tile grid



Wear and tear of vinyl composite tile



Hole in plaster wall



Damaged asphalt



Austin ISD - McCallum HS



Damaged sidewalk



Wooden bench is damaged and worn



Obstructed electrical panel