



# FACILITY CONDITION ASSESSMENT

*O. Henry MS* | February 2022



## Executive Summary

O. Henry MS is located at 2610 W 10th St in Austin, Texas. The oldest building is 67 years old (at time of 2020 assessment). It comprises 123,694 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$8,122,421. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For O. Henry MS the ten-year need is \$21,655,134.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The O. Henry MS facility has a 5-year FCA score of 49.27%.

## Summary of Findings

The table below summarizes the condition findings at O. Henry MS

Table 1: Facility Condition by Building

| Number                                      | Building Name  | Current Deficiencies | 5-Year Life Cycle Cost | Yrs 6-10 Life Cycle Cost | Total 5 Yr Need (Yr 1-5 + Current Defs) | Total 10 Yr Need (Yr 1-10 + Current Defs) | Replacement Cost    | 5-Year FCA    |
|---|--|----------------------|------------------------|--------------------------|---|---|---------------------|---------------|
| <b>Exterior Site</b>                        |  |                      |                        |                          |   |   |                     |               |
|   | Exterior Site  | \$943,819            | \$542,362              | \$0                      | \$1,486,181                             | \$1,486,181                               | \$0                 |               |
| <b>Permanent Building(s)</b>                |  |                      |                        |                          |   |   |                     |               |
| 047A  | Main building includes Administration Offices, Classrooms, Cafeteria, & Gym. | \$7,178,603          | \$11,942,774           | \$1,047,577              | \$19,121,377                            | \$20,168,954                              | \$40,619,880        | 52.93%        |
| <b>Sub Total for Permanent Building(s):</b> |  | <b>\$7,178,603</b>   | <b>\$11,942,774</b>    | <b>\$1,047,577</b>       | <b>\$19,121,377</b>                     | <b>\$20,168,954</b>                       | <b>\$40,619,876</b> |               |
| <b>Total for Site:</b>                      |  | <b>\$8,122,421</b>   | <b>\$12,485,136</b>    | <b>\$1,047,577</b>       | <b>\$20,607,557</b>                     | <b>\$21,655,134</b>                       | <b>\$40,619,876</b> | <b>49.27%</b> |

## Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

**Life Cycle Forecast:** Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

## Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1 – Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.

The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

| System               | Priority |             |             |           |             | Total       | % of Total |
|----------------------|----------|-------------|-------------|-----------|-------------|-------------|------------|
|                      | 1        | 2           | 3           | 4         | 5           |             |            |
| Site                 | \$0      | \$0         | \$214,748   | \$1,868   | \$708,473   | \$925,089   | 11.40 %    |
| Roofing              | \$0      | \$0         | \$0         | \$0       | \$0         | \$0         | 0.00 %     |
| Structural           | \$12,910 | \$0         | \$0         | \$0       | \$0         | \$12,910    | 0.16 %     |
| Exterior             | \$0      | \$2,838,625 | \$0         | \$84,101  | \$0         | \$2,922,726 | 36.02 %    |
| Interior             | \$0      | \$0         | \$965,127   | \$342,985 | \$19,577    | \$1,327,690 | 16.36 %    |
| Mechanical           | \$0      | \$88,140    | \$0         | \$0       | \$0         | \$88,140    | 1.09 %     |
| Electrical           | \$0      | \$5,564     | \$247,906   | \$0       | \$0         | \$253,470   | 3.12 %     |
| Plumbing             | \$0      | \$0         | \$581,846   | \$2,384   | \$0         | \$584,230   | 7.20 %     |
| Fire and Life Safety | \$0      | \$0         | \$0         | \$0       | \$0         | \$0         | 0.00 %     |
| Conveyances          | \$0      | \$0         | \$0         | \$0       | \$0         | \$0         | 0.00 %     |
| Specialties          | \$0      | \$0         | \$0         | \$7,991   | \$0         | \$7,991     | 0.10 %     |
| Crawlspace           | \$0      | \$0         | \$0         | \$0       | \$1,992,868 | \$1,992,868 | 24.56 %    |
| <b>Total:</b>        | \$12,910 | \$2,932,329 | \$2,009,629 | \$439,329 | \$2,720,918 | \$8,115,114 |            |

The building systems at the site with the most need include:

|          |   |             |
|----------|---|-------------|
| Exterior | - | \$2,922,726 |
| Interior | - | \$1,327,690 |
| Site     | - | \$925,089   |

The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies

## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

| System               | Life Cycle Capital Renewal Projections |                |                |                 |                     | Total 1-5           |
|----------------------|--|----------------|----------------|-----------------|---------------------|---------------------|
|                      | Year 1<br>2023                         | Year 2<br>2024 | Year 3<br>2025 | Year 4<br>2026  | Year 5<br>2027      |                     |
| Site                 | \$0                                    | \$0            | \$0            | \$0             | \$507,444           | \$507,444           |
| Roofing              | \$0                                    | \$0            | \$0            | \$0             | \$0                 | \$0                 |
| Exterior             | \$0                                    | \$0            | \$0            | \$0             | \$782,052           | \$782,052           |
| Interior             | \$0                                    | \$0            | \$0            | \$78,303        | \$4,012,920         | \$4,091,223         |
| Mechanical           | \$0                                    | \$0            | \$0            | \$0             | \$1,087,303         | \$1,087,303         |
| Electrical           | \$0                                    | \$0            | \$0            | \$0             | \$199,684           | \$199,684           |
| Plumbing             | \$0                                    | \$0            | \$0            | \$0             | \$4,924,582         | \$4,924,582         |
| Fire and Life Safety | \$0                                    | \$0            | \$0            | \$0             | \$0                 | \$0                 |
| Conveyances          | \$0                                    | \$0            | \$0            | \$0             | \$0                 | \$0                 |
| Specialties          | \$0                                    | \$0            | \$0            | \$0             | \$892,848           | \$892,848           |
| Crawlspace           | \$0                                    | \$0            | \$0            | \$0             | \$0                 | \$0                 |
| <b>Total</b>         | <b>\$0</b>                             | <b>\$0</b>     | <b>\$0</b>     | <b>\$78,303</b> | <b>\$12,406,833</b> | <b>\$12,485,136</b> |

Table 3b: Capital Renewal Forecast (Yrs 6-10)

| System               | Life Cycle Capital Renewal Projections |                |                |                 |                |                    | Total 6-10         | Total 1-10          |
|----------------------|--|----------------|----------------|-----------------|----------------|--------------------|--------------------|---------------------|
|                      | Total 1-5                              | Year 6<br>2028 | Year 7<br>2029 | Year 8<br>2030  | Year 9<br>2031 | Year 10<br>2032    |                    |                     |
| Site                 | \$507,444                              | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$507,444           |
| Roofing              | \$0                                    | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$0                 |
| Exterior             | \$782,052                              | \$0            | \$0            | \$50,616        | \$0            | \$24,922           | \$75,538           | \$857,590           |
| Interior             | \$4,091,223                            | \$0            | \$0            | \$0             | \$0            | \$880,400          | \$880,400          | \$4,971,623         |
| Mechanical           | \$1,087,303                            | \$0            | \$0            | \$0             | \$0            | \$166,794          | \$166,794          | \$1,254,097         |
| Electrical           | \$199,684                              | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$199,684           |
| Plumbing             | \$4,924,582                            | \$0            | \$0            | \$0             | \$0            | \$19,612           | \$19,612           | \$4,944,194         |
| Fire and Life Safety | \$0                                    | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$0                 |
| Conveyances          | \$0                                    | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$0                 |
| Specialties          | \$892,848                              | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$892,848           |
| Crawlspace           | \$0                                    | \$0            | \$0            | \$0             | \$0            | \$0                | \$0                | \$0                 |
| <b>Total</b>         | <b>\$12,485,136</b>                    | <b>\$0</b>     | <b>\$0</b>     | <b>\$50,616</b> | <b>\$0</b>     | <b>\$1,091,728</b> | <b>\$1,142,344</b> | <b>\$13,627,480</b> |




Figure 2: Ten Year Capital Renewal Forecast

## Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building’s health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.

$$FCAS = 100 - (\text{Total Repair Cost} / \text{Replacement Cost})$$

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.

- Very Unsatisfactory (0-35)
- Unsatisfactory (36-50)
- Average (51-65)
- Satisfactory (66-80)
- Very Satisfactory (81-100)

Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today’s estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$40,619,876. For planning purposes, the total 5-year need at the O. Henry MS is \$20,607,557 (Life Cycle Years 1-5 plus the FCA deficiency cost). The O. Henry MS facility has a 5-year FCA of 49.27%.

5-Year Need vs. Replacement




Figure 3: 5-Year FCA



## O. Henry MS - Deficiency Summary

### Site Level Deficiencies

#### Site

| Deficiency  | Category             | Qty       | UoM          | Priority | Repair Cost      | ID   |
|---|----------------------|-----------|--------------|----------|------------------|------|
| Asphalt Driveway Replacement  | Capital Renewal      | 23,859    | SF           | 3        | \$153,424        | 4062 |
| <b>Note:</b> Beyond useful life   |                      |           |              |          |                  |      |
| Concrete Walks Replacement  | Capital Renewal      | 3,441     | SF           | 3        | \$38,977         | 4004 |
| Playground Equipment Replacement  | Capital Renewal      | 1         | Ea.          | 3        | \$22,348         | 2995 |
| <b>Note:</b> Old and broken down  |                      |           |              |          |                  |      |
| <b>Location:</b> South side of building   |                      |           |              |          |                  |      |
| Gate Replacement  | Deferred Maintenance | 2         | Ea.          | 4        | \$1,234          | 2996 |
| <b>Note:</b> Gate leading into track on the south side is bent and damaged. Gate between tennis court and portable is extremely rusted.         |                      |           |              |          |                  |      |
| Site Drainage Needs Installation Of Drainage Piping   | Deferred Maintenance | 10        | LF           | 4        | \$634            | 2998 |
| <b>Note:</b> Drainage pipe in the middle south edge of south lawn is full of debris - needs to be cleared to confirm it is functioning properly |                      |           |              |          |                  |      |
| <b>Location:</b> South lawn   |                      |           |              |          |                  |      |
| Paving Restriping   | Deferred Maintenance | 99        | CAR          | 5        | \$3,292          | 2997 |
| <b>Note:</b> Faded striping   |                      |           |              |          |                  |      |
| <b>Location:</b> Throughout site  |                      |           |              |          |                  |      |
| PROGRAM DEFICIENCIES  | ADA Compliance       | 256,986   | EACH         | 5        | \$441,240        | 3983 |
| PUBLIC DEFICIENCIES   | ADA Compliance       | 68,626    | EACH         | 5        | \$117,830        | 3982 |
| Small Bench Replacement   | Deferred Maintenance | 1         | Ea.          | 5        | \$2,067          | 2999 |
| <b>Note:</b> Middle plank on table and bench damaged  |                      |           |              |          |                  |      |
| <b>Location:</b> South side of building   |                      |           |              |          |                  |      |
| TAS ACCESSIBILITY DEFICIENCIES  | ADA Compliance       | 83,894    | EACH         | 5        | \$144,044        | 3984 |
| <b>Sub Total for System</b>   |                      | <b>10</b> | <b>items</b> |          | <b>\$925,089</b> |      |

#### Structural

| Deficiency   | Category             | Qty      | UoM          | Priority | Repair Cost     | ID   |
|--|----------------------|----------|--------------|----------|-----------------|------|
| Structural Study Recommended   | Deferred Maintenance | 2        | Job          | 1        | \$12,910        | 6868 |
| <b>Note:</b> Structural study to detail scope of work based on the 2017 crawlspace deficiencies provided by AISD |                      |          |              |          |                 |      |
| <b>Sub Total for System</b>  |                      | <b>1</b> | <b>items</b> |          | <b>\$12,910</b> |      |

#### Electrical

| Deficiency                                    | Category        | Qty       | UoM          | Priority | Repair Cost      | ID   |
|---|-----------------|-----------|--------------|----------|------------------|------|
| Pole Lighting Replacement                     | Capital Renewal | 1         | Ea.          | 3        | \$5,820          | 2994 |
| <b>Note:</b> One missing light pole from base |                 |           |              |          |                  |      |
| <b>Location:</b> W 10th Street parking lot    |                 |           |              |          |                  |      |
| <b>Sub Total for System</b>                   |                 | <b>1</b>  | <b>items</b> |          | <b>\$5,820</b>   |      |
| <b>Sub Total for School and Site Level</b>    |                 | <b>12</b> | <b>items</b> |          | <b>\$943,819</b> |      |

## Building: 047A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

#### Exterior

| Deficiency                                    | Category        | Qty      | UoM          | Priority | Repair Cost        | ID   |
|---|-----------------|----------|--------------|----------|--------------------|------|
| Aluminum Storefront Exterior Door Replacement | Capital Renewal | 2        | Door         | 2        | \$7,938            | 4063 |
| Brick Exterior Replacement (Bldg SF)          | Capital Renewal | 2,954    | SF           | 2        | \$2,780,071        | 4006 |
| Wood Exterior Door Replacement                | Capital Renewal | 16       | Door         | 2        | \$50,616           | 4005 |
| CMU Wall Replacement (Bldg SF)                | Capital Renewal | 3,739    | SF           | 4        | \$84,101           | 4014 |
| <b>Sub Total for System</b>                   |                 | <b>4</b> | <b>items</b> |          | <b>\$2,922,726</b> |      |

#### Interior

| Deficiency                                 | Category        | Qty   | UoM | Priority | Repair Cost | ID   |
|--|-----------------|-------|-----|----------|-------------|------|
| Interior Brick/Stone Replacement (Bldg SF) | Capital Renewal | 9,477 | SF  | 3        | \$319,271   | 3997 |

**Interior**

| Deficiency  | Category        | Qty       | UoM          | Priority | Repair Cost        | ID   |
|---|-----------------|-----------|--------------|----------|--------------------|------|
| Interior Brick/Stone Replacement (Bldg SF)<br><b>Note:</b> Damaged/Beyond useful life<br><b>Location:</b> Building Wide | Capital Renewal | 8,813     | SF           | 3        | \$296,901          | 4055 |
| Interior Brick/Stone Replacement (Bldg SF)<br><b>Note:</b> Beyond useful Life   | Capital Renewal | 8,477     | SF           | 3        | \$285,582          | 4065 |
| Interior Door Hardware Replacement  | Capital Renewal | 25        | Door         | 3        | \$37,115           | 4013 |
| Interior Door Replacement   | Capital Renewal | 14        | Door         | 3        | \$26,258           | 4012 |
| Acoustical Ceiling Tile Replacement<br><b>Note:</b> Beyond useful life  | Capital Renewal | 12,369    | SF           | 4        | \$41,767           | 4045 |
| Ceiling Grid Replacement<br><b>Note:</b> Beyond useful life   | Capital Renewal | 12,369    | SF           | 4        | \$51,507           | 4044 |
| Ceramic Tile Flooring Replacement   | Capital Renewal | 1,211     | SF           | 4        | \$21,395           | 4007 |
| Interior Ceramic Walls Repair or Replacement  | Capital Renewal | 309       | SF           | 4        | \$98,352           | 3998 |
| Metal Interior Door Replacement   | Capital Renewal | 3         | Door         | 4        | \$8,681            | 4011 |
| Toilet Partition Replacement  | Capital Renewal | 10        | Stall        | 4        | \$20,165           | 4009 |
| Vinyl Composition Tile Replacement  | Capital Renewal | 8,954     | SF           | 4        | \$73,223           | 4008 |
| Wood Flooring Replacement   | Capital Renewal | 1,295     | SF           | 4        | \$27,894           | 4010 |
| Interior Wall Repainting (Bldg SF)  | Capital Renewal | 4,369     | SF           | 5        | \$19,577           | 3996 |
| <b>Sub Total for System</b>   |                 | <b>14</b> | <b>items</b> |          | <b>\$1,327,690</b> |      |

**Mechanical**

| Deficiency  | Category        | Qty      | UoM          | Priority | Repair Cost     | ID   |
|---|-----------------|----------|--------------|----------|-----------------|------|
| Ductwork Replacement (SF Basis)<br><b>Note:</b> Duct has holes and is severely worn<br><b>Location:</b> Duct to HRU-1 on roof | Capital Renewal | 60       | SF           | 2        | \$475           | 2533 |
| Electric Unit Heater Replacement  | Capital Renewal | 1        | Ea.          | 2        | \$1,958         | 2529 |
| Fan Coil (Chilled Water) HVAC Component Replacement   | Capital Renewal | 14       | Ea.          | 2        | \$79,993        | 2608 |
| Fan Coil (Chilled Water) HVAC Component Replacement<br><b>Note:</b> Not working<br><b>Location:</b> Room #206                 | Capital Renewal | 1        | Ea.          | 2        | \$5,714         | 2609 |
| <b>Sub Total for System</b>   |                 | <b>4</b> | <b>items</b> |          | <b>\$88,140</b> |      |

**Electrical**

| Deficiency   | Category             | Qty      | UoM          | Priority | Repair Cost      | ID   |
|--|----------------------|----------|--------------|----------|------------------|------|
| Panelboard Replacement   | Capital Renewal      | 2        | Ea.          | 2        | \$5,564          | 3648 |
| 2 X 4 Interior Fluorescent Lighting Replacement<br><b>Note:</b> Broken<br><b>Location:</b> Room 700  | Capital Renewal      | 1        | Ea.          | 3        | \$438            | 2557 |
| Canopy Lighting Replacement  | Capital Renewal      | 3        | Ea.          | 3        | \$6,249          | 3647 |
| Exterior Mounted Building Lighting Replacement   | Capital Renewal      | 1        | Ea.          | 3        | \$902            | 2555 |
| Interior Power Wiring Replacement<br><b>Note:</b> Damaged conduit due to wind damage. Wires are out of conduit outdoors. RTU-1 power wiring (gym unit)<br><b>Location:</b> Located on the roof | Deferred Maintenance | 25       | SF           | 3        | \$30             | 2559 |
| Interior Power Wiring Replacement<br><b>Note:</b> Beyond useful life   | Deferred Maintenance | 123,693  | SF           | 3        | \$146,908        | 4057 |
| Public Address System Replacement, Non-main Building<br><b>Note:</b> Beyond useful life  | Deferred Maintenance | 123,693  | SF           | 3        | \$87,560         | 4058 |
| <b>Sub Total for System</b>  |                      | <b>7</b> | <b>items</b> |          | <b>\$247,651</b> |      |

**Plumbing**

| Deficiency   | Category        | Qty     | UoM | Priority | Repair Cost | ID   |
|--|-----------------|---------|-----|----------|-------------|------|
| Plumbing / Domestic Water Piping System Is Beyond Its Useful Life<br><b>Note:</b> Beyond useful life | Capital Renewal | 123,693 | SF  | 3        | \$444,519   | 4060 |
| Sanitary Sewer Piping Replacement<br><b>Note:</b> Beyond useful life                                 | Capital Renewal | 123,693 | SF  | 3        | \$137,327   | 4061 |

**Plumbing**

| Deficiency                                     | Category        | Qty      | UoM          | Priority | Repair Cost      | ID   |
|--|-----------------|----------|--------------|----------|------------------|------|
| Non-Refrigerated Drinking Fountain Replacement | Capital Renewal | 1        | Ea.          | 4        | \$2,384          | 2525 |
| <b>Sub Total for System</b>                    |                 | <b>3</b> | <b>items</b> |          | <b>\$584,230</b> |      |

**Technology**

| Deficiency   | Category              | Qty      | UoM          | Priority | Repair Cost    | ID   |
|--|-----------------------|----------|--------------|----------|----------------|------|
| Public Address System Head-End Requires Replacement<br><b>Note:</b> Beyond useful life | Functional Deficiency | 1        | Ea.          | 3        | \$7,307        | 4059 |
| <b>Sub Total for System</b>  |                       | <b>1</b> | <b>items</b> |          | <b>\$7,307</b> |      |

**Specialties**

| Deficiency                        | Category        | Qty      | UoM          | Priority | Repair Cost    | ID   |
|-----------------------------------|-----------------|----------|--------------|----------|----------------|------|
| Metal Student Lockers Replacement | Capital Renewal | 15       | Ea.          | 4        | \$7,991        | 4039 |
| <b>Sub Total for System</b>       |                 | <b>1</b> | <b>items</b> |          | <b>\$7,991</b> |      |

**Crawlspace**

| Deficiency   | Category             | Qty       | UoM          | Priority | Repair Cost        | ID   |
|--|----------------------|-----------|--------------|----------|--------------------|------|
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> SOIL/DRAINAGE BELOW BUILDING - improve drainage - 86151 SF              | Deferred Maintenance | 239,831   | Ea.          | 5        | \$281,766          | 6860 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> CRAWL SPACE ACCESS/VENTILATION - Improve ventilation - 86151 SF         | Deferred Maintenance | 371,739   | Ea.          | 5        | \$436,738          | 6861 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> CRAWL SPACE ACCESS/VENTILATION - repair access - 10 EA                  | Deferred Maintenance | 139,192   | Ea.          | 5        | \$163,530          | 6862 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> SPECIAL FOUNDATIONS - repair minor honeycombing - 2930 LF               | Deferred Maintenance | 40,786    | Ea.          | 5        | \$47,917           | 6863 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> SUSPENDED FLOOR BEAMS - repair minor honeycombing & spalling            | Deferred Maintenance | 59,958    | Ea.          | 5        | \$70,442           | 6864 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> SUSPENDED FLOOR SLABS - repair minor honeycombing & spalling - 86151 SF | Deferred Maintenance | 119,916   | Ea.          | 5        | \$140,883          | 6865 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> CRAWL SPACE, EXPOSED PIPES - Repair rusted pipes and hangers - 1 LS     | Deferred Maintenance | 125,273   | Ea.          | 5        | \$147,177          | 6866 |
| CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD<br><b>Note:</b> CRAWL SPACE, INSULATION - replace insulation, 75% - 86151 SF            | Deferred Maintenance | 599,578   | Ea.          | 5        | \$704,415          | 6867 |
| <b>Sub Total for System</b>  |                      | <b>8</b>  | <b>items</b> |          | <b>\$1,992,868</b> |      |
| <b>Sub Total for Building 047A - Main building includes Administration Offices, Classrooms, Cafeteria, &amp; Gym.</b>                        |                      | <b>42</b> | <b>items</b> |          | <b>\$7,178,603</b> |      |
| <b>Total for Campus</b>  |                      | <b>54</b> | <b>items</b> |          | <b>\$8,122,421</b> |      |

## O. Henry MS - Life Cycle Summary Yrs 1-10

### Site Level Life Cycle Items

#### Site

| Uniformat Description       | LC Type Description            | Qty | UoM            | Repair Cost      | Remaining Life |
|-----------------------------|--------------------------------|-----|----------------|------------------|----------------|
| Fences and Gates            | Fencing - Chain Link (4 Ft)    | 751 | LF             | \$35,445         | 5              |
| Fences and Gates            | Fencing - Chain Link (8-10 Ft) | 428 | LF             | \$33,532         | 5              |
| Fences and Gates            | Competition Style Track        | 1   | Ea.            | \$294,838        | 5              |
| Parking Lot Pavement        | Asphalt                        | 99  | CAR            | \$143,629        | 5              |
| <b>Sub Total for System</b> |                                |     | <b>4 items</b> | <b>\$507,444</b> |                |

#### Electrical

| Uniformat Description           | LC Type Description | Qty | UoM            | Repair Cost      | Remaining Life |
|---------------------------------|---------------------|-----|----------------|------------------|----------------|
| Parking Lot Lighting            | Pole Lighting       | 6   | Ea.            | \$34,918         | 5              |
| <b>Sub Total for System</b>     |                     |     | <b>1 items</b> | <b>\$34,918</b>  |                |
| <b>Sub Total for Building -</b> |                     |     | <b>5 items</b> | <b>\$542,362</b> |                |

### Building: 047A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

#### Exterior

| Uniformat Description       | LC Type Description               | Qty   | UoM            | Repair Cost      | Remaining Life |
|-----------------------------|-----------------------------------|-------|----------------|------------------|----------------|
| Exterior Operating Windows  | Aluminum - Windows per SF         | 3,600 | SF             | \$359,017        | 5              |
| Exterior Operating Windows  | Aluminum - Windows per SF         | 1,368 | SF             | \$136,426        | 5              |
| Exterior Operating Windows  | Aluminum - Windows per SF         | 705   | SF             | \$70,307         | 5              |
| Exterior Operating Windows  | Aluminum - Windows per SF         | 396   | SF             | \$39,492         | 5              |
| Exterior Entrance Doors     | Steel - Insulated and Painted     | 22    | Door           | \$81,554         | 5              |
| Exterior Entrance Doors     | Storefront Doors - Glass/Aluminum | 24    | Door           | \$95,256         | 5              |
| Exterior Entrance Doors     | Wooden Door                       | 16    | Door           | \$50,616         | 8              |
| Exterior Utility Doors      | Overhead Door                     | 3     | Door           | \$24,922         | 10             |
| <b>Sub Total for System</b> |                                   |       | <b>8 items</b> | <b>\$857,590</b> |                |

#### Interior

| Uniformat Description                  | LC Type Description                 | Qty    | UoM             | Repair Cost        | Remaining Life |
|--|-------------------------------------|--------|-----------------|--------------------|----------------|
| Carpeting                              | Carpet                              | 6,185  | SF              | \$78,303           | 4              |
| Acoustical Suspended Ceilings          | Ceilings - Adhered acoustical tiles | 6,185  | SF              | \$43,095           | 5              |
| Suspended Plaster and                  | Painted ceilings                    | 6,185  | SF              | \$12,881           | 5              |
| Wall Painting and Coating              | Painting/Staining (Bldg SF)         | 12,369 | SF              | \$55,425           | 5              |
| Compartments and Cubicles              | Toilet Partitions                   | 57     | Stall           | \$114,940          | 5              |
| Athletic Flooring                      | Athletic/Sport Flooring             | 2,474  | SF              | \$37,955           | 5              |
| Tile Flooring                          | Ceramic Tile                        | 3,711  | SF              | \$65,563           | 5              |
| Resilient Flooring                     | Vinyl Composition Tile Flooring     | 98,954 | SF              | \$809,217          | 5              |
| Wood Flooring                          | Wood Flooring - All Types           | 9,895  | SF              | \$213,137          | 5              |
| Interior Door Supplementary Components | Door Hardware                       | 262    | Door            | \$388,967          | 5              |
| Acoustical Suspended Ceilings          | Ceilings - Acoustical Tiles         | 86,585 | SF              | \$292,376          | 5              |
| Stone Facing                           | CMU Wall                            | 58,754 | SF              | \$1,979,364        | 5              |
| Acoustical Suspended Ceilings          | Ceilings - Acoustical Grid System   | 86,585 | SF              | \$360,561          | 10             |
| Acoustical Suspended Ceilings          | Ceilings - Acoustical Tiles         | 12,369 | SF              | \$41,767           | 10             |
| Interior Swinging Doors                | Storefront door (Aluminum/Glass)    | 16     | Door            | \$57,938           | 10             |
| Interior Swinging Doors                | Wooden Door                         | 224    | Door            | \$420,134          | 10             |
| <b>Sub Total for System</b>            |                                     |        | <b>16 items</b> | <b>\$4,971,624</b> |                |

#### Mechanical

| Uniformat Description           | LC Type Description                     | Qty | UoM            | Repair Cost        | Remaining Life |
|---------------------------------|---|-----|----------------|--------------------|----------------|
| Decentralized Cooling           | AHU 50,000 CFM Interior                 | 2   | Ea.            | \$355,178          | 5              |
| Decentralized Cooling           | AHU 50,000 CFM Interior                 | 1   | Ea.            | \$177,589          | 5              |
| Heat Generation                 | Boiler - Copper Tube (1600 MBH)         | 3   | Ea.            | \$213,880          | 5              |
| Central Cooling                 | Chiller - Outdoor Air Cooled (100 Tons) | 1   | Ea.            | \$102,018          | 5              |
| HVAC Air Distribution           | Roof Top Unit - DX Gas (5 Ton)          | 15  | Ea.            | \$238,638          | 5              |
| Central Cooling                 | Cooling Tower - Metal (300 Tons)        | 1   | Ea.            | \$57,829           | 10             |
| Other HVAC Distribution Systems | VFD (20 HP)                             | 2   | Ea.            | \$17,635           | 10             |
| Exhaust Air                     | Roof Exhaust Fan - Small                | 22  | Ea.            | \$43,113           | 10             |
| Exhaust Air                     | Roof Exhaust Fan - Large                | 6   | Ea.            | \$48,217           | 10             |
| <b>Sub Total for System</b>     |   |     | <b>9 items</b> | <b>\$1,254,097</b> |                |

**Electrical**

| Uniformat Description       | LC Type Description            | Qty      | UoM          | Repair Cost      | Remaining Life |
|-----------------------------|--------------------------------|----------|--------------|------------------|----------------|
| Power Distribution          | Distribution Panels (600 Amps) | 1        | Ea.          | \$17,802         | 5              |
| Power Distribution          | Panelboard - 120/208 100A      | 2        | Ea.          | \$5,564          | 5              |
| Power Distribution          | Panelboard - 120/240 225A      | 8        | Ea.          | \$62,586         | 5              |
| Power Distribution          | Panelboard - 120/240 400A      | 5        | Ea.          | \$51,735         | 5              |
| Lighting Fixtures           | Canopy Mounted Fixtures (Ea.)  | 13       | Ea.          | \$27,079         | 5              |
| <b>Sub Total for System</b> |                                | <b>5</b> | <b>items</b> | <b>\$164,766</b> |                |

**Plumbing**

| Uniformat Description       | LC Type Description                 | Qty       | UoM          | Repair Cost        | Remaining Life |
|-----------------------------|-------------------------------------|-----------|--------------|--------------------|----------------|
| Domestic Water Equipment    | Backflow Preventers - 3/4 in. (Ea.) | 2         | Ea.          | \$1,757            | 5              |
| Domestic Water Equipment    | Gas Piping System (BldgSF)          | 123,693   | SF           | \$4,289,088        | 5              |
| Plumbing Fixtures           | Classroom Lavatory                  | 69        | Ea.          | \$176,950          | 5              |
| Plumbing Fixtures           | Restroom Lavatory                   | 40        | Ea.          | \$108,652          | 5              |
| Plumbing Fixtures           | Sink - Service / Mop Sink           | 6         | Ea.          | \$4,775            | 5              |
| Plumbing Fixtures           | Showers                             | 33        | Ea.          | \$43,113           | 5              |
| Plumbing Fixtures           | Toilets                             | 49        | Ea.          | \$247,910          | 5              |
| Plumbing Fixtures           | Urinals                             | 11        | Ea.          | \$14,896           | 5              |
| Plumbing Fixtures           | Refrigerated Drinking Fountain      | 17        | Ea.          | \$37,441           | 5              |
| Domestic Water Equipment    | Water Heater - Electric - 80 gallon | 1         | Ea.          | \$4,460            | 10             |
| Domestic Water Equipment    | Water Heater - Gas - 100 Gallon     | 2         | Ea.          | \$12,768           | 10             |
| Plumbing Fixtures           | Non-Refrigerated Drinking Fountain  | 1         | Ea.          | \$2,384            | 10             |
| <b>Sub Total for System</b> |                                     | <b>12</b> | <b>items</b> | <b>\$4,944,193</b> |                |

**Specialties**

| Uniformat Description   | LC Type Description | Qty       | UoM          | Repair Cost         | Remaining Life |
|---|---------------------|-----------|--------------|---------------------|----------------|
| Fixed Multiple Seating  | Bleachers           | 256       | Seat         | \$105,756           | 5              |
| Casework  | Fixed Cabinetry     | 48        | Room         | \$422,490           | 5              |
| Casework  | Lockers             | 452       | Ea.          | \$240,801           | 5              |
| Casework  | Lockers, Gym        | 255       | Ea.          | \$123,801           | 5              |
| <b>Sub Total for System</b>   |                     | <b>4</b>  | <b>items</b> | <b>\$892,848</b>    |                |
| <b>Sub Total for Building 047A - Main building includes Administration Offices, Classrooms, Cafeteria, &amp; Gym.</b> |                     | <b>54</b> | <b>items</b> | <b>\$13,085,119</b> |                |
| <b>Total for: O. Henry MS</b>   |                     | <b>59</b> | <b>items</b> | <b>\$13,627,481</b> |                |

## Supporting Photos

### General Site Photos




Missing light fixture




Damaged thermostat



Exposed wiring in mechanical Room



Corrugated pipes



Exposed Concrete



Aged ventilation Unit



Water pooling will eventually cause serious damage



Damaged roof