


# FACILITY CONDITION ASSESSMENT

## Odom ES | February 2022





## **Executive Summary**

Odom ES is located at 1010 Turtle Creek Blvd in Austin, Texas. The oldest building is 50 years old (at time of 2020 assessment). It comprises 65,911 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$6,030,293. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Odom ES the ten-year need is \$14,447,028.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Odom ES facility has a 5-year FCA score of 36.39%.

## **Summary of Findings**

The table below summarizes the condition findings at Odom ES

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Site	8							
	Exterior Site	\$2,165,570	\$457,424	\$5,820	\$2,622,994	\$2,628,814	\$0	
Permanent	Building(s)		-		-			
156A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$3,864,723	\$7,280,983	\$672,508	\$11,145,706	\$11,818,214	\$21,644,510	48.51%
	Sub Total for Permanent Building(s):	\$3,864,723	\$7,280,983	\$672,508	\$11,145,706	\$11,818,214	\$21,644,514	
	Total for Site:	\$6,030,293	\$7,738,407	\$678,328	\$13,768,700	\$14,447,028	\$21,644,514	36.39%



## **Approach and Methodology**

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

**Current Deficiencies:** Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

## **Facility Deficiency Priority Levels**

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

**Priority 1** – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

**Priority 2 - Indirect Impact to Educational Mission:** Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

**Priority 3 - Short-Term Conditions:** Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

**Priority 4 - Long-Term Requirements:** Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

**Priority 5 - Enhancements:** Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



Austin ISD - Odom ES

## The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)


			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$36,474	\$101,556	\$2,021,086	\$2,159,115	35.80 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$6,455	\$0	\$30,002	\$0	\$0	\$36,457	0.60 %
Exterior	\$0	\$84,472	\$0	\$0	\$0	\$84,472	1.40 %
Interior	\$0	\$0	\$30,010	\$269,444	\$0	\$299,453	4.97 %
Mechanical	\$0	\$189,817	\$75,843	\$21,097	\$0	\$286,757	4.76 %
Electrical	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Plumbing	\$0	\$0	\$3,398	\$119,274	\$0	\$122,672	2.03 %
Fire and Life Safety	\$482,871	\$0	\$0	\$0	\$0	\$482,871	8.01 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$140,830	\$0	\$140,830	2.34 %
Crawlspace	\$0	\$0	\$0	\$0	\$2,417,666	\$2,417,666	40.09 %
Total:	\$489,326	\$274,289	\$175,726	\$652,201	\$4,438,751	\$6,030,293	

The building systems at the site with the most need include:

Site	-	\$2,159,115
Fire and Life Safety	-	\$482,871
Interior	-	\$299,453



Austin ISD - Odom ES



The chart below represents the building systems and associated deficiency costs.

Figure 1: System Deficiencies



## Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$294,838	\$80,471	\$37,419	\$44,696	\$457,424
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$168,633	\$0	\$34,307	\$202,940
Interior	\$0	\$380,233	\$243,938	\$280,901	\$508,948	\$1,414,020
Mechanical	\$0	\$0	\$61,191	\$453,563	\$525,612	\$1,040,366
Electrical	\$0	\$5,500	\$0	\$1,262,656	\$114,252	\$1,382,408
Plumbing	\$0	\$0	\$0	\$230,634	\$2,564,481	\$2,795,115
Fire and Life Safety	\$0	\$0	\$0	\$0	\$151,706	\$151,706
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$281,660	\$0	\$0	\$0	\$281,660
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$962,231	\$554,233	\$2,265,173	\$3,944,002	\$7,725,639

Table 3a: Capital Renewal Forecast (Yrs 1-5)



Austin ISD - Odom ES

Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$457,424	\$0	\$0	\$0	\$0	\$0	\$0	\$457,424
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$202,940	\$0	\$0	\$0	\$0	\$0	\$0	\$202,940
Interior	\$1,414,020	\$0	\$0	\$0	\$0	\$341,229	\$341,229	\$1,755,249
Mechanical	\$1,040,366	\$0	\$0	\$0	\$0	\$438,876	\$438,876	\$1,479,242
Electrical	\$1,382,408	\$0	\$0	\$5,820	\$0	\$78,280	\$84,100	\$1,466,508
Plumbing	\$2,795,115	\$0	\$0	\$0	\$0	\$28,334	\$28,334	\$2,823,449
Fire and Life Safety	\$151,706	\$0	\$0	\$0	\$0	\$0	\$0	\$151,706
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$281,660	\$0	\$0	\$0	\$0	\$0	\$0	\$281,660
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$7,725,639	\$0	\$0	\$5,820	\$0	\$886,719	\$892,539	\$8,618,178




Figure 2: Ten Year Capital Renewal Forecast



The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$21,644,514. For planning purposes, the total 5-year need at the Odom ES is \$13,768,700 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Odom ES facility has a 5-year FCA of 36.39%.





## **Odom ES - Deficiency Summary**

## **Site Level Deficiencies**

Site							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Concrete Walks Re	placement	Capital Renewal	3,220	SF	3	\$36,474	4624
Asphalt Paving Rep	lacement	Capital Renewal	70	CAR	4	\$101,556	4623
PROGRAM DEFICI	ENCIES	ADA Compliance	602,637	EACH	5	\$1,034,716	5144
Note:	SECTION TWO: PROGRAM DEFICIENCIES Site/Exterior Improvements Estimated Construction Cost for Site Plan Area C \$ 14,712.11 Estimated Construction Cost for Site Plan Area D \$ 10,469.70 Estimated Construction Cost Subtotal for Site/Exterior Improvement Interior Improvements Estimated Construction Cost for Floor Plan Area 5 \$ 27,750.49 Estimated Construction Cost for Floor Plan Area 6 \$ 102,955.21 Estimated Construction Cost for Floor Plan Area 7 \$ 260,631.29 Estimated Construction Cost for Floor Plan Area 8 \$ 112,626.82 Estimated Construction Cost for Floor Plan Area 9 \$ 61,455.57 Estimated Construction Cost for Floor Plan Area 10 \$ 12,036.08 Estimated Construction Cost Subtotal for Interior Improvements Ex Total Estimated Construction Cost Subtotal for Program Deficiency	cluding Division 1 \$ 577,45	5.46				
PUBLIC DEFICIEN	CIES	ADA Compliance	354,320	EACH	5	\$608,361	5143
Note:	SECTION ONE: PUBLIC DEFICIENCIES Site/Exterior Improvements Estimated Construction Cost for Site Plan Area A \$16,245.71 Estimated Construction Cost for Site Plan Area B \$30,650.91 Estimated Construction Cost Subtotal for Site/Exterior Improvement Interior Improvements Estimated Construction Cost for Floor Plan Area 1 \$ 19,856.29 Estimated Construction Cost for Floor Plan Area 2 \$ 189,116.46 Estimated Construction Cost for Floor Plan Area 3 \$ 71,333.10 Estimated Construction Cost for Floor Plan Area 4 \$ 27,117.50 Estimated Construction Cost Subtotal for Interior Improvements Ex Total Estimated Construction Cost Subtotal for Public Deficiency In	cluding Division 1 \$ 307,42					
TAS ACCESSIBILIT	TY DEFICIENCIES	ADA Compliance	220,159	EACH	5	\$378,009	5145
Note:	SECTION THREE: TAS ACCESSIBILITY DEFICIENCIES Interior Improvements Estimated Construction Cost for Floor Plan Area 11 \$ 15,298.62 Estimated Construction Cost for Floor Plan Area 12 \$ 63,346.31 Estimated Construction Cost for Floor Plan Area 13 \$ 21,885.43 Estimated Construction Cost for Floor Plan Area 14 \$ 40,273.52 Estimated Construction Cost for Floor Plan Area 15 \$ 34,108.61 Estimated Construction Cost for Floor Plan Area 16 \$ 45,246.95 Estimated Construction Cost Subtotal for TAS Improvements Exclu Total Estimated Construction Cost Subtotal for TAS Deficiency Imp		4				
		Sub Total for System	5	items		\$2,159,115	
Structural							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Structural Study Re	commended	Deferred Maintenance	1	Job	1	\$6,455	6598
Note:	Structural study to detail scope of work based on the 2017 crawlsp	ace deficiencies provided b	y AISD				
		Sub Total for System	1	items		\$6,455	
	Sub Total f	or School and Site Level	6	items		\$2,165,570	

## Gym.

#### Structural

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
ADD INSULATION STRUCTURE UNDERSIDE	Deferred Maintenance	1 Job	3	\$30,002	6731
	Sub Total for System	1 items		\$30,002	
Exterior					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Aluminum Window Replacement	Capital Renewal	560 SF	2	\$55,847	4630
Aluminum Window Replacement	Capital Renewal	64 SF	2	\$6,383	4631
Metal Exterior Door Replacement	Capital Renewal	6 Door	2	\$22,242	4632



Austin ISD - Odom ES

#### Exterior Deficiency

Exterior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Location: Kitchen and entrances	Sub Total for Sustam	•			¢04.470	
Interior	Sub Total for System	3	items		\$84,472	
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Interior Door Replacement	Capital Renewal	16	Door	3	\$30,010	462
Acoustical Ceiling Tile Replacement	Capital Renewal	23,069	SF	4	\$77,898	462
Metal Interior Door Replacement	Capital Renewal	1	Door	4	\$2,894	462
Vinyl Composition Tile Replacement	Capital Renewal	23,069	SF	4	\$188,652	462
	Sub Total for System	4	items		\$299,453	
Mechanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Air Handler HVAC Component Replacement	Capital Renewal	1	Ea.	2	\$85,959	461
Cast Iron Water Boiler Replacement	Capital Renewal	1	Ea.	2	\$77,555	461
Location: Mechanical room						
Fan Coil HVAC Component Replacement	Capital Renewal	1	Ea.	2	\$2,068	4613
Package Roof Top Unit Replacement	Capital Renewal	1	Ea.	2	\$24,236	461
Location: Roof					• ,	
Energy Recovery Unit Replacement	Capital Renewal	1	Ea.	3	\$20,116	461
Location: Roof					<b>+</b> ,	
Kitchen Exhaust Hood Replacement	Capital Renewal	2	Ea.	3	\$22,383	462
Make Up Air Equipment Replacement	Capital Renewal		Ea.	3	\$8,888	461
Location: Roof	ouplin Renewal		Lu.	0	φ0,000	401
Replace Variable Frequency Drive	Capital Renewal	3	Ea.	3	\$15,670	461
	Capital Renewal		Ea.	3		461
Replace Variable Frequency Drive	•		Ea. Ea.		\$8,786	
Kitchen Air/Exhaust Replacement	Capital Renewal		⊏a. items	4	\$21,097 <b>\$286,757</b>	4620
	Sub Total for System	10	nems		<i>\$</i> 200,7 <i>51</i>	
Plumbing						
Deficiency	Category		UoM	Priority	Repair Cost	ID
Backflow Preventer Replacement	Capital Renewal	1	Ea.	3	\$2,092	460
Shower Replacement	Capital Renewal	1	Ea.	3	\$1,306	4610
Location: Gym restroom						
Custodial Mop Or Service Sink Replacement	Capital Renewal	6	Ea.	4	\$4,775	4609
Location: Janitors closet						
Non-Refrigerated Drinking Fountain Replacement	Capital Renewal	5	Ea.	4	\$11,919	461
Location: Hall						
Replace classroom lavatory	Capital Renewal	40	Ea.	4	\$102,580	4608
Location: Throughout the classroom						
	Sub Total for System	5	items		\$122,672	
Fire and Life Safety						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Install Fire Sprinklers	Functional Deficiency	65,910	SF	1	\$482,871	462 <sup>-</sup>
Note: Missing						
	Sub Total for System	1	items		\$482,871	
Specialties						
-	Catagony	0.5.7	LIOM	Priority	Renair Cost	חו
Deficiency	Category		UoM	Priority	Repair Cost	ID
Specialties Deficiency Replace Cabinetry In Classes/Labs	Capital Renewal	16	Room	Priority 4	\$140,830	
Deficiency Replace Cabinetry In Classes/Labs		16			-	
Deficiency	Capital Renewal	16 1	Room		\$140,830	ID 4629

Note: SOIL/DRAINAGE BELOW BUILDING - Improve drainage - 61182 GSF



Austin ISD - Odom ES

#### Crawlspace

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	510,964	Ea.	5	\$600,307	6600
Note:	CRAWL SPACE ACCESS/VENTILATION - improve ventilation - 6	51182					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	11,135	Ea.	5	\$13,082	6601
Note:	CRAWL SPACE ACCESS/VENTILATION - repair access - 4 EA						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	91,032	Ea.	5	\$106,949	6602
Note:	SPECIAL FOUNDATIONS - repair perimeter - 2180 LF						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	425,803	Ea.	5	\$500,255	6603
Note:	SUSPENDED FLOOR BEAMS - repair beams - 61182 GSF						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	510,964	Ea.	5	\$600,307	6604
Note:	SUSPENDED FLOOR SLABS - repair slab bottom - 61182 GSF						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	99,105	Ea.	5	\$116,434	6605
Note:	CRAWL SPACE, EXPOSED PIPES - replace corroded pipe hange	ers and pipes, repair leaks,	replace de	graded i	insulation -	1 IS	
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	68,204	Ea.	5	\$80,130	6606
Note:	CRAWL SPACE, EXPOSED DUCTWORK - repair insulation - 1 L	S					
		Sub Total for System	8	items		\$2,417,666	
Sub Total for Build	ling 156A - Main building includes Administration Offices, Class	rooms, Cafeteria, & Gym.	33	items		\$3,864,723	
		Total for Campus	39	items		\$6,030,293	



## Odom ES - Life Cycle Summary Yrs 1-10

### Site Level Life Cycle Items

#### Site

Uniformat Description	L	_C Type Description		Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	C	Competition Style Track		1	Ea.	\$294,838	2
	Note: U	Jnpaved					
Fences and Gates	F	Fencing - Chain Link (4 Ft)		1,705	i LF	\$80,471	3
Roadway Pavement	A	Asphalt Driveways		5,819	SF	\$37,419	4
Playfield Areas	E	ES Playgrounds		2	Ea.	\$44,696	5
			Sub Total for System	4	items	\$457,424	
Electrical							
Uniformat Description	L	_C Type Description		Qty	UoM	Repair Cost	Remaining Life
Parking Lot Lighting	F	Pole Lighting		1	Ea.	\$5,820	8
			Sub Total for System	1	items	\$5,820	
			Sub Total for Building -	5	items	\$463,243	

### Building: 156A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF		180	SF	\$17,951	3
Exterior Operating Windows	Aluminum - Windows per SF		16	SF	\$1,596	3
Exterior Operating Windows	Aluminum - Windows per SF		160	SF	\$15,956	3
Exterior Operating Windows	Aluminum - Windows per SF		480	SF	\$47,869	3
Exterior Entrance Doors	Steel - Insulated and Painted		23	Door	\$85,261	3
Exterior Operating Windows	Aluminum - Windows per SF		64	SF	\$6,383	5
Exterior Operating Windows	Aluminum - Windows per SF		144	SF	\$14,361	5
Exterior Operating Windows	Aluminum - Windows per SF		120	SF	\$11,967	5
Exterior Operating Windows	Aluminum - Windows per SF		16	SF	\$1,596	5
		Sub Total for System	9	items	\$202,939	

Interior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Carpeting	Carpet		16,478	SF	\$208,614	2
Tile Flooring	Ceramic Tile		4,614	SF	\$81,517	2
Tile Flooring	Quarry Tile		3,296	SF	\$90,102	2
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		13,182	SF	\$44,512	3
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System		23,069	SF	\$96,065	3
Wall Paneling	Wood Panel wall		6,591	SF	\$103,361	3
Suspended Plaster and	Painted ceilings		17,796	SF	\$37,062	4
Wall Coverings	Vinyl/Fabric Wall Covering		3,296	SF	\$15,531	4
Wall Painting and Coating	Painting/Staining (Bldg SF)		37,569	SF	\$168,344	4
Interior Swinging Doors	Metal Door (Steel)		12	Door	\$34,726	4
Interior Door Supplementary Components	Door Hardware		17	Door	\$25,238	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System		13,182	SF	\$54,893	5
Compartments and Cubicles	Toilet Partitions		22	Stall	\$44,363	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System		7,909	SF	\$32,935	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		7,909	SF	\$26,707	5
Resilient Flooring	Vinyl Composition Tile Flooring		11,864	SF	\$97,020	5
Interior Swinging Doors	Wooden Door		70	Door	\$131,292	5
Interior Door Supplementary Components	Door Hardware		82	Door	\$121,738	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		23,069	SF	\$77,898	10
Tile Wall Finish	Ceramic Tile wall		6,591	SF	\$54,717	10
Carpeting	Carpet		16,478	SF	\$208,614	10
		Sub Total for System	21	items	\$1,755,249	
Mechanical						

Uniformat Description	LC Type Description	Qty UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)	39,546 SF	\$61,191	3
HVAC Air Distribution	Roof Top Unit - DX Gas (5 Ton)	1 Ea.	\$15,909	4



Austin ISD - Odom ES

#### Mechanical

Jniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
acility Hydronic Distribution	2-Pipe System (Cold)		65,910	SF	\$117,858	4
Facility Hydronic Distribution	2-Pipe Water System (Hot)		65,910	SF	\$280,383	4
Eacility Hydronic Distribution	Pump- 10HP (Ea.)		3	Ea.	\$34,682	4
Exhaust Air	Wall Exhaust Fan		1	Ea.	\$4,731	4
IVAC Air Distribution	Ductwork (Bldg.SF)		59,319	SF	\$469,358	5
Exhaust Air	Roof Exhaust Fan - Large		7	Ea.	\$56,254	5
leat Generation	Boiler - Cast Iron - Water (3264 MBH)		1	Ea.	\$77,555	10
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		26,364	SF	\$71,110	10
Other HVAC Distribution Systems	VFD (7.5 HP)		3	Ea.	\$15,670	10
Other HVAC Distribution Systems	VFD (5 HP)		2	Ea.	\$8,786	10
IVAC Air Distribution	AHU 5,000 CFM Interior		1	Ea.	\$43,163	10
IVAC Air Distribution	AHU 5,000 CFM Outdoor		1	Ea.	\$49,434	10
IVAC Air Distribution	AHU 10,000 CFM Outdoor		1	Ea.	\$101,341	10
IVAC Air Distribution	AHU 5,000 CFM Outdoor		1	Ea.	\$49,434	10
Exhaust Air	Kitchen Exhaust Hoods		2	Ea.	\$22,383	10
		Sub Total for System	17	items	\$1,479,241	
Electrical						
Iniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 225A		1	Ea.	\$5,500	2
udio-Video Systems	PA Communications No Head Unit (Bldg SF)		65,910	SF	\$46,656	4
Distributed Systems	Public Address System Head End Unit		1	Ea.	\$7,307	4
ighting Fixtures	Light Fixtures (Bldg SF)		65,910	SF	\$1,208,693	4
Electrical Service	Switchgear - Main Dist Panel (1600 Amps)		1	Ea.	\$55,918	5
Power Distribution	Distribution Panels (800 Amps)		1	Ea.	\$18,564	5
Electrical Service	Transformer (45 KVA)		1	Ea.	\$5,919	5
Power Distribution	Panelboard - 120/208 125A		2	Ea.	\$2,918	5
Power Distribution	Panelboard - 277/480 100A		1	Ea.	\$6,688	5
Power Distribution	Panelboard - 277/480 225A		2	Ea.	\$18,745	5
Power Distribution	Panelboard - 120/208 225A		1	Ea.	\$5,500	5
Power Distribution	Power Wiring		65,910	SF	\$78,280	10
	-	Sub Total for System	12	items	\$1,460,688	
Plumbing						
Iniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Restroom Lavatory		13	Ea.	\$35,312	4
Plumbing Fixtures	Toilets		37	Ea.	\$187,197	4
Plumbing Fixtures	Urinals		6	Ea.	\$8,125	4
Domestic Water Equipment	Gas Piping System (BldgSF)		65,910	SF	\$2,285,447	5
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		59,319	SF	\$213,176	5
Sanitary Sewerage Piping	Sanitary Sewer Piping		59,319	SF	\$65,858	5
Domestic Water Equipment	Water Heater - Electric - 20 gallon		1	Ea.	\$1,587	10
Domestic Water Equipment	Water Heater - Electric - 5 to 10 gallon		1	Ea.	\$1,264	10
Domestic Water Equipment	Water Heater - Gas - 100 Gallon		2	Ea.	\$12,768	10
Plumbing Fixtures	Sink - Service / Mop Sink		1	Ea.	\$796	10
Plumbing Fixtures	Non-Refrigerated Drinking Fountain		5	Ea.	\$11,919	10
		Sub Total for System	11	items	\$2,823,448	
					_	
Fire and Life Safety				UoM	-	Remaining Life
Jniformat Description	LC Type Description					
•	Security Alarm System	Sub Total for System	65,910 <b>1</b>	SF items	\$151,706 <b>\$151,706</b>	5
Jniformat Description		Sub Total for System				5
Jniformat Description Security System Component		Sub Total for System	1		\$151,706	5 Remaining Life
Uniformat Description Security System Component Specialties	Security Alarm System	Sub Total for System	1 Qty	items	\$151,706	

Total for: Odom ES

77 items

\$8,618,174



Austin ISD - Odom ES

## **Supporting Photos**

### **General Site Photos**



Mismatched ceiling tiles



Exterior windows are beyond their useful life



Asphalt pavemnt needs to be replaced



Metal Door is scuffed



Concrete sidewalks present cracking



Asphalt needs to be repaved



Austin ISD - Odom ES



Grout between quarry tiles needs to be redone



The gas boiler is approaching the end of life.



Mop sinks are original and beyond their useful life.



Water fountains are beyond their useful life.



Condenser - looks to be uneven on the concrete slab