

FACILITY CONDITION ASSESSMENT

Rosedale School | February 2022





Executive Summary

Rosedale School is located at 2117 W 49th St in Austin, Texas. The oldest building is 81 years old (at time of 2020 assessment). It comprises 36,549 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$2,708,095. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Rosedale School the ten-year need is \$9,236,396.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Rosedale School facility has a 5-year FCA score of 41.70%.

Summary of Findings

The table below summarizes the condition findings at Rosedale School

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Sit	ite							
	Exterior Site	\$1,036,835	\$167,545	\$0	\$1,204,380	\$1,204,380	\$0	
Permanent	t Building(s)							
251A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$1,538,863	\$5,043,399	\$1,263,344	\$6,582,262	\$7,845,606	\$11,851,270	44.46%
251B	Mechanical Building (old Boiler House)	\$132,397	\$54,013	\$0	\$186,410	\$186,410	\$157,771	-18.15%
	Sub Total for Permanent Building(s): Total for Site:	<i>\$1,671,260</i> \$2,708,095	<i>\$5,097,412</i> \$5,264,957	<i>\$1,263,344</i> \$1,263,344	<i>\$6,768,672</i> \$7,973,052	<i>\$8,032,016</i> \$9,236,396	<i>\$12,009,038</i> \$12,009,038	41.70%

M-A-P-P-S ©, Jacobs 2022

Facility Condition Assessment





Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.


Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.

M-A-P-P-S ©, Jacobs 2022

Facility Condition Assessment





The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$0	\$58,032	\$972,349	\$1,030,381	38.05 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$6,455	\$0	\$0	\$0	\$0	\$6,455	0.24 %
Exterior	\$0	\$153,406	\$16,796	\$0	\$5,833	\$176,034	6.50 %
Interior	\$0	\$0	\$0	\$45,691	\$0	\$45,691	1.69 %
Mechanical	\$0	\$194,516	\$0	\$6,171	\$1,239	\$201,926	7.46 %
Electrical	\$0	\$130,775	\$8,436	\$0	\$0	\$139,210	5.14 %
Plumbing	\$0	\$0	\$117,598	\$84,767	\$0	\$202,365	7.47 %
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Crawlspace	\$0	\$0	\$0	\$0	\$906,033	\$906,033	33.46 %
Total:	\$6,455	\$478,696	\$142,830	\$194,661	\$1,885,454	\$2,708,095	

The building systems at the site with the most need include:

Site	-	\$1,030,381
Plumbing	-	\$202,365
Mechanical	-	\$201,926



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$63,905	\$45,000	\$58,640	\$167,545
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$0	\$0	\$0	\$0	\$1,053,835	\$1,053,835
Interior	\$0	\$0	\$109,677	\$462,812	\$724,803	\$1,297,292
Mechanical	\$0	\$1,035,943	\$0	\$285,552	\$0	\$1,321,495
Electrical	\$0	\$0	\$0	\$117,326	\$734,953	\$852,279
Plumbing	\$0	\$0	\$0	\$15,417	\$170,272	\$185,689
Fire and Life Safety	\$0	\$0	\$0	\$0	\$140,370	\$140,370
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$246,452	\$0	\$246,452
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$1,035,943	\$173,582	\$1,172,559	\$2,882,873	\$5,264,957



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$167,545	\$0	\$0	\$0	\$0	\$0	\$0	\$167,545
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$1,053,835	\$0	\$0	\$0	\$0	\$0	\$0	\$1,053,835
Interior	\$1,297,292	\$0	\$0	\$45,691	\$0	\$0	\$45,691	\$1,342,983
Mechanical	\$1,321,495	\$0	\$0	\$0	\$0	\$0	\$0	\$1,321,495
Electrical	\$852,279	\$0	\$0	\$0	\$0	\$5,564	\$5,564	\$857,843
Plumbing	\$185,689	\$1,251,396	\$0	\$0	\$0	\$8,768	\$1,260,164	\$1,445,853
Fire and Life Safety	\$140,370	\$0	\$0	\$0	\$0	\$0	\$0	\$140,370
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$246,452	\$0	\$0	\$0	\$0	\$0	\$0	\$246,452
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$5,264,957	\$1,251,396	\$0	\$4 5,691	\$0	\$14,332	\$1,311,419	\$6,576,376




Figure 2: Ten Year Capital Renewal Forecast



Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$12,009,038. For planning purposes, the total 5-year need at the Rosedale School is \$7,973,052 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Rosedale School facility has a 5-year FCA of 41.70%.



M=A=P=P=S ©, Jacobs 2022

\$1,036,835

Repair Cost ID

5 items

Qty UoM

Priority



Rosedale School - Deficiency Summary Site Level Deficiencies

Site

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Asphalt Paving Replacement	Capital Renewal	40 CAR	4	\$58,032	3946
PROGRAM DEFICIENCIES	ADA Compliance	191,951 EACH	5	\$329,576	3952
PUBLIC DEFICIENCIES	ADA Compliance	186,789 EACH	5	\$320,713	3951
TAS ACCESSIBILITY DEFICIENCIES	ADA Compliance	187,573 EACH	5	\$322,059	3953
	Sub Total for System	4 items		\$1,030,381	
Structural					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Structural Study Recommended	Deferred Maintenance	1 Job	1	\$6,455	6958
Note: Structural study to detail scope of work based on the 2017 crawlspace	e deficiencies provided by	y AISD			
	Sub Total for System	1 items		\$6,455	

Building: 251A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Sub Total for School and Site Level

Category

Exterior Deficiency

		<u> </u>					
Aluminum Window R	eplacement	Capital Renewal	832	SF	2	\$82,973	3955
Metal Exterior Door F	Replacement	Capital Renewal	17	Door	2	\$63,019	3954
Caulking Replacement	nt	Deferred Maintenance	1,248	LF	3	\$9,425	2426
Note:	Recaulk 104 each, 4x2 windows.						
Location:	Class/office						
Caulking Replacement	nt	Deferred Maintenance	576	LF	3	\$4,350	2427
Note:	Recaulk 36 each, 4x4 windows						
Location:	Class/office						
Caulking Replacement	nt	Deferred Maintenance	400	LF	3	\$3,021	2428
Note:	Recaulk 20 each, 6x4 windows						
Location:	Class/office						
Exterior Cleaning		Deferred Maintenance	1,421	SF Wall	5	\$5,503	2425
		Sub Total for System	6	items		\$168,291	
Interior							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Carpet Flooring Repla	acement	Capital Renewal	3,609	SF	4	\$45,691	3472
		Sub Total for System	1	items		\$45,691	
Mechanical							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Fan Coil (Chilled Wat	ter) HVAC Component Replacement	Capital Renewal	27	Ea.	2	\$154,273	2440
Location:	Classrooms, halls and closet						
Fan Coil HVAC Comp	ponent Replacement	Capital Renewal	3	Ea.	2	\$6,204	2439
Location:	Offices						
Package DX Unit Rep	placement	Capital Renewal	2	Ea.	2	\$34,039	4554
Note:	Age, general condition, rust. May be abandoned equipment						
Location:	Roof						
Window AC Unit Com	nponent Replacement	Capital Renewal	2	Ea.	4	\$6,171	2442
Location:	Offices						
Remove Abandoned	Equipment	Deferred Maintenance	1	Ea.	5	\$1,239	4638
Note:	Remove abandoned AHU in penthouse						







Mechanical

Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
	: Main Building Penthouse		,		. ,		
	·	Sub Total for System	5	items		\$201,926	
Electrical		•					
Deficiency		Category	Otv	UoM	Priority	Repair Cost	ID
Panelboard Replace	ement	Capital Renewal		Ea.	2	\$12,342	
Note:	Age/corrosion	Capital Monewal		Lu.	_	Ψ12,042	2400
	: Custodian office						
Panelboard Replace		Capital Renewal	1	Ea.	2	\$2,782	2451
Note:	Age/corrosion					* , -	
	: Admin office						
		Sub Total for System	2	items		\$15,124	
Plumbing		·					
Deficiency		Category	Otv	UoM	Priority	Repair Cost	ID
Backflow Preventer	Replacement	Capital Renewal		Ea.	3	\$1,757	
	: Classroom/restroom	Capital Nellewal	2	La.	3	Ψ1,737	2431
Shower Replacement		Capital Renewal	2	Ea.	3	\$2,613	2435
•	: Restrooms	Capital Hollowal	_	Lu.	Ü	Ψ2,010	2100
Toilet Replacement		Capital Renewal	22	Ea.	3	\$111,307	2436
·	: Restrooms					• , • • .	
Urinal Replacement		Capital Renewal	1	Ea.	3	\$1,354	2437
	: Restrooms	•					
Non-Refrigerated Dr	rinking Fountain Replacement	Capital Renewal	1	Ea.	4	\$2,384	2438
Location	ı: Gym	•					
Replace classroom	lavatory	Capital Renewal	12	Ea.	4	\$30,774	2433
Location	: Classrooms						
Restroom Lavatories	s Plumbing Fixtures Replacement	Capital Renewal	19	Ea.	4	\$51,610	2434
Location	a: Restrooms						
		Sub Total for System	7	items		\$201,798	
Crawlspace							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred	199,034	Ea.	5	\$233,835	6959
		Maintenance					
Note:	SOIL/DRAINAGE BELOW BUILDING - improve drainage - 35748 S			_			
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred Maintenance	154,251	Ea.	5	\$181,222	6960
Note:	CRAWL SPACE ACCESS/VENTILATION - improve ventilatoin - 357						
	FICIENCIES - Estimate and Info by AISD	Deferred	34,798	Ea.	5	\$40,882	6961
	, , , , , , , , , , , , , , , , , , , ,	Maintenance	,			* -,	
Note:	CRAWL SPACE ACCESS/VENTILATION - repair hatch - 5 EA						
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred	99,517	Ea.	5	\$116,918	6962
Note:	CLICDENIDED ELOOD REAMS, rangir minor hangygamhing 8 apoll	Maintenance					
	SUSPENDED FLOOR BEAMS - repair minor honeycombing & spall FICIENCIES - Estimate and Info by AISD	Deferred	248,792	Ea	5	\$292,294	6063
CRAWL SPACE DE	FICIENCIES - Estimate and initio by AISD	Maintenance	240,792	Ea.	5	ΨZ9Z,Z94	0903
Note:	SUSPENDED FLOOR SLABS - repair masonry, spalling & reinforce	ment - 35748 GSF					
CRAWL SPACE DE	FICIENCIES - Estimate and Info by AISD	Deferred	34,798	Ea.	5	\$40,882	6964
		Maintenance		_			
Note:	CRAWL SPACE, EXPOSED PIPES - Replace rusted pipes and han	=				4000 000	
Out Total Comment	Burn OPAA - Mater building tool - too A Lot to - C - C - C - C - C - C - C - C - C -	Sub Total for System		items		\$906,033	
	ling 251A - Main building includes Administration Offices, Classro	_	27	items		\$1,538,863	
Building: 2	51B - Mechanical Building (old Boiler I	House)					
Exterior							
Deficiency		Category	Qtv	UoM	Priority	Repair Cost	ID
Metal Exterior Door	Replacement	Capital Renewal		Door	2	\$7,414	3956
	•			-		* ,	





Austin ISD - Rosedale School

Exterior

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Exterior Cleaning	Deferred Maintenance	85 SF Wall	5	\$329	2430
	Sub Total for S	System 2 items		\$7,743	
Electrical					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Distribution Panel Replacement	Capital Renewa	al 1 Ea.	2	\$18,564	2447
Note: Age/corrosion					
Location: MER					
Panelboard Replacement	Capital Renewa	al 1 Ea.	2	\$2,782	2448
Note: Age/corrosion					
Location: MER					
Switchgear Replacement	Capital Renewa	al 1 Ea.	2	\$38,387	2445
Note: Age/corrosion					
Location: MER					
Switchgear Replacement	Capital Renewa	al 1 Ea.	2	\$55,918	2446
Note: Age/corrosion					
Location: MER					
Lighting Fixtures Replacement	Capital Renewa	al 460 SF	3	\$8,436	3473
	Sub Total for S	System 5 items		\$124,087	
Plumbing					
Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Sump Pump Replacement	Deferred Maintenance	1 Ea.	3	\$567	2443
Location: Boiler room					
	Sub Total for S	System 1 items		\$567	
	Sub Total for Building 251B - Mechanical Building (old Boiler I	House) 8 items		\$132,397	
	Total for C	ampus 40 items		\$2,708,095	



Rosedale School - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)		1,354 LF	\$63,905	3
Roadway Pavement	Asphalt Driveways		6,998 SF	\$45,000	4
Playfield Areas	ES Playgrounds		2 Ea.	\$44,696	5
Pedestrian Pavement	Sidewalks - Concrete		1,231 SF	\$13,944	5
		Sub Total for System	4 items	\$167,545	
		Sub Total for Building -	4 items	\$167 545	

Building: 251A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Brick - Bldg SF basis	28,871	SF	\$811,119	5
Exterior Wall Veneer	Vinyl siding - clapboard style	1,804	SF	\$11,183	5
Exterior Operating Windows	Steel - Windows per SF	576	SF	\$83,256	5
Exterior Operating Windows	Steel - Windows per SF	480	SF	\$69,380	5
Exterior Entrance Doors	Storefront Doors - Glass/Aluminum	14	Door	\$55,566	5
		Sub Total for System 5	items	\$1,030,503	

Interior

Uniformat Description	LC Type Description	Q	y UoM	Repair Cost	Remaining Life
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	32,48	0 SF	\$109,677	3
Wall Painting and Coating	Painting/Staining (Bldg SF)	21,65	3 SF	\$97,025	4
Resilient Flooring	Vinyl Composition Tile Flooring	21,65	3 SF	\$177,072	4
Wood Flooring	Wood Flooring - All Types	1,80	4 SF	\$38,858	4
Interior Swinging Doors	Storefront door (Aluminum/Glass)		2 Door	\$7,242	4
Interior Door Supplementary Components	Door Hardware	ę	1 Door	\$135,099	4
Suspended Plaster and	Painted ceilings	3,60	9 SF	\$7,516	4
Compartments and Cubicles	Toilet Partitions	1	1 Stall	\$22,181	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Grid System	32,48	0 SF	\$135,255	5
Tile Wall Finish	Ceramic Tile wall	14,43	6 SF	\$119,845	5
Tile Flooring	Ceramic Tile	1,08	3 SF	\$19,134	5
Terrazzo Flooring	Terrazzo	7,21	8 SF	\$245,963	5
Interior Swinging Doors	Wooden Door	8	9 Door	\$166,928	5
Carpeting	Carpet	3,60	9 SF	\$45,691	8
		Sub Total for System 1	4 items	\$1,327,487	

Mechanical

Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exhaust Air		Roof Exhaust Fan - Small		7	Ea.	\$13,718	2
Exhaust Air		Roof Exhaust Fan - Large		1	Ea.	\$8,036	2
Hydronic Distribution Systems		Ground Source Loop Field Pipe		78	Ton	\$1,014,189	2
	Note:	Building A is 65% and Building B is 0%. RTU's are used for	35% of Building A				
HVAC Air Distribution		Ductwork (Bldg.SF)		36,089	SF	\$285,552	4
		S	ub Total for System	4	items	\$1,321,495	

Electrical

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Building Mounted Fixtures (Ea.)		10	Ea.	\$9,017	4
Electrical Service	Switchgear - Main Dist Panel (1200 Amps)		1	Ea.	\$38,387	4
Power Distribution	Panelboard - 120/208 100A		13	Ea.	\$36,166	4
Audio-Video Systems	PA Communications No Head Unit (Bldg SF)		36,089	SF	\$25,547	4
Distributed Systems	Public Address System Head End Unit		1	Ea.	\$7,307	4
Lighting Fixtures	Light Fixtures (Bldg SF)		36,089	SF	\$661,820	5
Power Distribution	Power Wiring		36,089	SF	\$42,862	5
Power Distribution	Panelboard - 120/208 225A		3	Ea.	\$16,499	5
Power Distribution	Panelboard - 120/208 100A		2	Ea.	\$5,564	10
		Sub Total for System	9	items	\$843,169	







Plumbing

Di II Fi i		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures		Refrigerated Drinking Fountain		7	Ea.	\$15,417	4
	Note:	Located in hallways					
Domestic Water Piping		Domestic Water Piping System (Bldg.SF)		36,089	SF	\$129,694	5
Sanitary Sewerage Piping		Sanitary Sewer Piping		36,089	SF	\$40,067	5
Domestic Water Equipment		Gas Piping System (BldgSF)		36,089	SF	\$1,251,396	6
Domestic Water Equipment		Water Heater - Gas - 100 Gallon		1	Ea.	\$6,384	10
Plumbing Fixtures		Non-Refrigerated Drinking Fountain		1	Ea.	\$2,384	10
			Sub Total for System	6	items	\$1,445,341	
Fire and Life Safety	/						
Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Security System Component		Security Alarm System	,	36,089	SF	\$83,067	5
Fire Detection and Alarm		Fire Alarm		36,089	SF	\$57,303	5
			Sub Total for System	2	items	\$140,370	
Specialties							
Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework		Fixed Cabinetry	,	28	Room	\$246,452	4
			Sub Total for System	1	items	\$246,452	
Sub Total for Building	251A - Ma	ain building includes Administration Offices, C	lassrooms, Cafeteria, & Gym.	41	items	\$6,354,816	
Exterior Uniformat Description		LC Type Description		Qty	UoM	Repair Cost	Remaining Life
		LC Type Description Brick - Bldg SF basis		Qty 460	UoM SF	Repair Cost \$12,924	Remaining Life
Uniformat Description				460			
Uniformat Description Exterior Wall Veneer		Brick - Bldg SF basis	Sub Total for System	460 72	SF	\$12,924	5
Uniformat Description Exterior Wall Veneer		Brick - Bldg SF basis	Sub Total for System	460 72	SF SF	\$12,924 \$10,407	
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior		Brick - Bldg SF basis	Sub Total for System	460 72 2	SF SF	\$12,924 \$10,407 \$23,331	5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows		Brick - Bldg SF basis Steel - Windows per SF	Sub Total for System	460 72 2	SF SF items	\$12,924 \$10,407 \$23,331	5 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description		Brick - Bldg SF basis Steel - Windows per SF LC Type Description	Sub Total for System Sub Total for System	460 72 2 Qty 460	SF SF items	\$12,924 \$10,407 \$23,331 Repair Cost	5 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description		Brick - Bldg SF basis Steel - Windows per SF LC Type Description		460 72 2 Qty 460	SF SF items UoM	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497	5 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing		Brick - Bldg SF basis Steel - Windows per SF LC Type Description		460 72 2 Qty 460 1	SF SF items UoM	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497	5 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall		460 72 2 Qty 460 1	SF SF items UoM SF items	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497	5 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description		460 72 2 Qty 460 1 Qty 1	SF SF items UoM SF items	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost	5 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.)		460 72 2 Qty 460 1 Qty 1 1	SF SF items UoM SF items UoM Ea.	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902	5 5 Remaining Life 5 Remaining Life
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A		460 72 2 Qty 460 1 Qty 1 1 1 2	SF SF items UoM SF items UoM Ea. Ea.	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342	5 5 S Remaining Life 4 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A	Sub Total for System	460 72 2 Qty 460 1 Qty 1 1 1 2	SF SF items UoM SF items UoM Ea. Ea.	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342 \$1,430	5 5 S Remaining Life 4 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution Packaged Generator Assemblies		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A	Sub Total for System	460 72 2 Qty 460 1 1 1 2 3 3	SF SF items UoM SF items UoM Ea. Ea.	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342 \$1,430 \$14,674	5 5 Remaining Life 5 Remaining Life 4 5 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution Packaged Generator Assemblies Plumbing Uniformat Description		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A Exterior Electrical Enclosure	Sub Total for System	460 72 2 Qty 460 1 1 1 2 3 3	SF SF items UoM SF items UoM Ea. Ea. items	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342 \$1,430 \$14,674	5 5 Remaining Life 5 Remaining Life 4 5 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution Packaged Generator Assemblies Plumbing		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A Exterior Electrical Enclosure LC Type Description	Sub Total for System	460 72 2 Qty 460 1 1 2 3 Qty 460	SF SF items UoM SF items UoM Ea. Ea. items	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342 \$1,430 \$14,674	5 5 Remaining Life 5 Remaining Life 4 5 5
Uniformat Description Exterior Wall Veneer Exterior Operating Windows Interior Uniformat Description Stone Facing Electrical Uniformat Description Lighting Fixtures Power Distribution Packaged Generator Assemblies Plumbing Uniformat Description		Brick - Bldg SF basis Steel - Windows per SF LC Type Description CMU Wall LC Type Description Building Mounted Fixtures (Ea.) Panelboard - 120/208 400A Exterior Electrical Enclosure LC Type Description	Sub Total for System Sub Total for System Sub Total for System	460 72 2 Qty 460 1 1 2 3 Qty 460 1	SF SF items UoM SF items UoM Ea. Ea. items	\$12,924 \$10,407 \$23,331 Repair Cost \$15,497 \$15,497 Repair Cost \$902 \$12,342 \$1,430 \$14,674	5 5 Remaining Life 5 Remaining Life 4 5 5

M*A*P*P*S ©, Jacobs 2022



Supporting Photos

General Site Photos



Corroded main disconnect



Damaged Window Frame



Damaged Window Hardware



Interior doors are aged and beyond their useful life



Broken window




Exterior doors are corroded and beyond their useful life

Facility Condition Assessment

Austin ISD - Rosedale School





Aged piping systems



Aged furnance equipment



Pumps are beyond their useful life



Exhaust is loose from ceiling

M*A*P*P*S ©, Jacobs 2022 15