



FACILITY CONDITION ASSESSMENT

Saegert Bus Terminal | February 2022







Executive Summary

Saegert Bus Terminal is located at 3300 Jones Rd in Austin, Texas. The oldest building is 45 years old (at time of 2020 assessment). It comprises 19,121 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$5,436,844. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Saegert Bus Terminal the ten-year need is \$8,433,800.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Saegert Bus Terminal facility has a 5-year FCA score of 15.73%.


Summary of Findings

The table below summarizes the condition findings at Saegert Bus Terminal

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Si	ite							
	Exterior Site	\$4,368,393	\$0	\$1,727,063	\$4,368,393	\$6,095,456	\$0	
Permanen	nt Building(s)		_					
960A	Main building includes Administration Offices, & Shop	\$854,588	\$445,602	\$178,012	\$1,300,190	\$1,478,202	\$3,786,604	65.66%
960B	Shop and Storage Area	\$41,651	\$49,167	\$46,704	\$90,818	\$137,522	\$645,209	85.92%
960C	Tire Shop	\$6,892	\$5,493	\$9,958	\$12,385	\$22,343	\$140,432	91.18%
960D	Administrative Building / Training Rooms	\$165,321	\$348,577	\$186,380	\$513,898	\$700,278	\$2,886,666	82.20%
	Sub Total for Permanent Building(s):	\$1,068,451	\$848,839	\$421,054	\$1,917,290	\$2,338,344	\$7,458,911	
	Total for Site:	\$5,436,844	\$848,839	\$2,148,117	\$6,285,683	\$8,433,800	\$7,458,911	15.73%

M-A-P-P-S ©, Jacobs 2022





Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.

M-A-P-P-S ©, Jacobs 2022





The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$116,809	\$3,917	\$4,243,558	\$4,364,284	80.49 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Exterior	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Interior	\$0	\$0	\$147,763	\$61,922	\$48,181	\$257,866	4.76 %
Mechanical	\$0	\$471,438	\$23,978	\$40,128	\$0	\$535,543	9.88 %
Electrical	\$0	\$7,018	\$62,328	\$0	\$0	\$69,345	1.28 %
Plumbing	\$0	\$1,264	\$81,991	\$16,428	\$0	\$99,683	1.84 %
Fire and Life Safety	\$86,707	\$0	\$0	\$0	\$0	\$86,707	1.60 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$8,802	\$0	\$8,802	0.16 %
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Total:	\$86,707	\$479,720	\$432,868	\$131,197	\$4,291,739	\$5,422,231	

The building systems at the site with the most need include:

Site	-	\$4,364,284
Mechanical	-	\$535,543
Interior	_	\$257,866



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies





Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-5
Site	\$0	\$0	\$0	\$0	\$0	\$0
Roofing	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$41,361	\$168,216	\$0	\$0	\$0	\$209,577
Interior	\$0	\$0	\$44,538	\$299,393	\$38,795	\$382,726
Mechanical	\$0	\$0	\$0	\$51,715	\$5,493	\$57,208
Electrical	\$0	\$0	\$0	\$0	\$137,164	\$137,164
Plumbing	\$0	\$0	\$0	\$66,550	\$0	\$66,550
Fire and Life Safety	\$0	\$0	\$6,868	\$0	\$0	\$6,868
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$0	\$0
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$41,361	\$168,216	\$51,406	\$417,658	\$181,452	\$860,093



Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$0	\$0	\$0	\$1,425,047	\$0	\$302,016	\$1,727,063	\$1,727,063
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Exterior	\$209,577	\$0	\$0	\$119,159	\$0	\$6,327	\$125,486	\$335,063
Interior	\$382,726	\$50,586	\$739	\$8,180	\$0	\$9,616	\$69,121	\$451,847
Mechanical	\$57,208	\$0	\$0	\$0	\$0	\$29,890	\$29,890	\$87,098
Electrical	\$137,164	\$0	\$0	\$28,640	\$0	\$196,351	\$224,991	\$362,155
Plumbing	\$66,550	\$0	\$0	\$0	\$0	\$7,320	\$7,320	\$73,870
Fire and Life Safety	\$6,868	\$0	\$0	\$0	\$0	\$0	\$0	\$6,868
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$5,826	\$0	\$0	\$5,826	\$5,826
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$860,093	\$50,586	\$739	\$1,586,852	\$0	\$551,520	\$2,189,697	\$3,049,790




Figure 2: Ten Year Capital Renewal Forecast



The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$7,458,911. For planning purposes, the total 5-year need at the Saegert Bus Terminal is \$6,285,683 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Saegert Bus Terminal facility has a 5-year FCA of 15.73%.



M*A*P*P*S ©, Jacobs 2022



Saegert Bus Terminal - Deficiency Summary Site Level Deficiencies

Site

Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Asphalt Driveway Replacement	Capital Renewal	18,165	SF	3	\$116,809	778
Note: potholes, rutting, and cracking throughout site						
Location: primarily in northeast and northwest parking lots						
Fencing Replacement (8' - 10' high Chain Link Fence)	Capital Renewal	50	LF	4	\$3,917	777
Note: damaged fencing						
Location: northeast corner of site						
Paving Restriping	Deferred Maintenance	50	CAR	5	\$1,663	779
Note: pavement striping is fading						
Location: primarily NE and SW parking lots						
PROGRAM DEFICIENCIES	ADA Compliance	748,760	EACH	5	\$4,185,471	4385
PUBLIC DEFICIENCIES	ADA Compliance	32,318	EACH	5	\$55,489	4384
Site Signage Replacement	Capital Renewal	1	Ea.	5	\$241	780
Wheel Stop Replacement	Deferred Maintenance	4	Ea.	5	\$694	781
Note: four damaged wheel stops						
Location: all three (3) parking areas						
	Sub Total for System	7	items		\$4,364,284	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Pole Lighting Repair	Deferred Maintenance	1	Ea.	3	\$4,109	775
Note: light is hanging down						
Location: south light pole						
	Sub Total for System	1	items		\$4,109	
5	Sub Total for School and Site Level	8	items		\$4,368,393	

Building: 960A - Main building includes Administration Offices, & Shop

Interior

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Interior Brick/Stone	Replacement (Bldg SF)	Capital Renewal	3,718 SF	3	\$125,256	3902
Note:	Damaged, torn, ripped					
Interior Door Replac	ement	Capital Renewal	6 Door	3	\$11,254	3906
Acoustical Ceiling Ti	ile Replacement	Capital Renewal	1,941 SF	4	\$6,554	3901
Note:	Broken, sagging, stained					
Metal Interior Door F	Replacement	Capital Renewal	5 Door	4	\$14,469	3905
Vinyl Composition T	ile Replacement	Capital Renewal	1,941 SF	4	\$15,873	3904
Note:	Lifting, broken, worn					
Interior Wall Repain	ting (Bldg SF)	Capital Renewal	2,912 SF	5	\$13,048	3903
Note:	Chipped, stained, flacking					
		Sub Total for System	6 items		\$186,454	

Mechanical

Deficiency	Category	Qty UoM	Priority	Repair Cost	ID
Air Cooled Condenser Replacement	Capital Renewal	2 Ea.	2	\$19,945	3891
Ductwork Replacement (SF Basis)	Capital Renewal	9,707 SF	2	\$76,806	3894
Fan Coil Unit Replacement	Capital Renewal	2 Ea.	2	\$7,103	3892
Gas Piping Replacement (SF Basis)	Capital Renewal	9,707 SF	2	\$336,593	3882
Infrared Gas Radiant Heater Replacement	Capital Renewal	10 Ea.	3	\$21,798	3889
Ceiling Exhaust Fan Replacement	Capital Renewal	2 Ea.	4	\$973	3895
Ceiling Exhaust Fan Replacement	Capital Renewal	10 Ea.	4	\$4,867	3896
Existing Controls Are Obsolete	Capital Renewal	9,707 SF	4	\$15,020	3890

M-A-P-P-S ©, Jacobs 2022







Mechanical

D. C. '	0.1	0.		D : "	D : 0 :	15
Deficiency	Category		UoM	Priority	Repair Cost	ID
Window AC Unit Component Replacement	Capital Renewal		Ea.	4	\$3,085	3893
	Sub Total for System	9	items		\$486,191	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$4,236	2950
Canopy Lighting Replacement	Capital Renewal	5	Ea.	3	\$10,415	2955
Exterior Mounted Building Lighting Replacement	Capital Renewal	6	Ea.	3	\$5,410	2956
Interior Power Wiring Replacement	Deferred Maintenance	9,707	SF	3	\$11,529	2957
Public Address System Replacement, Non-main Building	Deferred Maintenance	9,707	SF	3	\$6,871	2951
	Sub Total for System	5	items		\$38,461	
Plumbing						
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Gas Water Heater Replacement	Capital Renewal		Ea.	3	\$3,265	3881
Plumbing / Domestic Water Piping System Is Beyond Its Useful Life	Capital Renewal	9,707		3	\$34,884	3883
Sanitary Sewer Piping Replacement	Capital Renewal	9,707		3	\$10,777	3884
Toilet Replacement	Capital Renewal	,	Ea.	3	\$30,356	3887
Urinal Replacement	Capital Renewal		Ea.	3	\$2,708	3898
Custodial Mop Or Service Sink Replacement	Capital Renewal		Ea.	4	\$796	3897
Refrigerated Water Cooler Replacement	Capital Renewal		Ea.	4	\$2,202	3888
Replace classroom lavatory	Capital Renewal		Ea.	4	\$2,565	3885
Restroom Lavatories Plumbing Fixtures Replacement	Capital Renewal		Ea.	4	\$10,865	3886
Nestroom Lavatories i fumbring i ixtures replacement	Sub Total for System		items	7	\$98,419	3000
Fire and Life Cofety	oub rotal for dystem	3	items		ψ30, + 13	
Fire and Life Safety	_					
Deficiency	Category		UoM	Priority	Repair Cost	ID
Fire Alarm Replacement	Capital Renewal	9,707		1	\$15,413	2954
Security Alarm Replacement	Capital Renewal	9,707		1	\$22,343	2953
	Sub Total for System	2	items		\$37,756	
Technology						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Public Address System Head-End Requires Replacement	Functional Deficiency	1	Ea.	3	\$7,307	2952
	Sub Total for System	1	items		\$7,307	
Sub Total for Building 960A - Main building includes	Administration Offices, & Shop	32	items		\$854,588	
Building: 960B - Shop and Storage Area						
Interior						
Deficiency	Category		UoM	Priority	Repair Cost	ID_
Interior Wood Wall Replacement (LC)	Capital Renewal	83	SF	4	\$1,302	3911
Note: Stained, wood rot						
Location: West wall						
Metal Interior Door Replacement	Capital Renewal	3	Door	4	\$8,681	3913
Interior Wall Repainting (Bldg SF)	Capital Renewal	165	SF	5	\$739	3912
Note: Scuffs, stains						
	Sub Total for System	3	items		\$10,722	
Mechanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Infrared Gas Radiant Heater Replacement	Capital Renewal		Ea.	3	\$2,180	3899
Wall Exhaust Fan Ventilation Replacement	Capital Renewal	1	Ea.	4	\$4,731	3900
·	Sub Total for System		items		\$6,911	
Electrical	•				. ,	
	Cotogony	04.	I IoM	Driorit.	Popoir Cost	ID
Deficiency Page I board Page 2 ages	Category		UoM	Priority	Repair Cost	ID
Panelboard Replacement Canopy Lighting Replacement	Category Capital Renewal Capital Renewal	1	UoM Ea. Ea.	Priority 2	Repair Cost \$2,782 \$4,166	ID 2958 2962





Electrical

Deficiency Exterior Mounted Building Lighting Replacement						
Exterior Mounted Building Lighting Poplacement	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Mounted Building Lighting Replacement	Capital Renewal	2	Ea.	3	\$1,803	2963
Interior Power Wiring Replacement	Deferred Maintenance	1,654	SF	3	\$1,964	2964
	Sub Total for System	4	items		\$10,716	
Fire and Life Safety						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Fire Alarm Panel Replacement	Capital Renewal	1	Ea.	1	\$6,868	2961
Fire Alarm Replacement	Capital Renewal	1,654	SF	1	\$2,626	2960
Security Alarm Replacement	Capital Renewal	1,654	SF	1	\$3,807	2959
	Sub Total for System	3	items		\$13,301	
Sub Total for Building 960	B - Shop and Storage Area	12	items		\$41,651	
Building: 960C - Tire Shop						
·						
Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Epoxy Flooring Repair Or Replacement	Deferred Maintenance	360	SF	4	\$4,339	3915
Note: Peeling and worn						
Interior Ceiling Repainting	Deferred	360	SF	5	\$750	3914
	Maintenance	_	!4av		#F 000	
	Sub Total for System	2	items		\$5,089	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Exterior Mounted Building Lighting Replacement	Capital Renewal	2	Ea.	3	\$1,803	2965
Note: Wallmount appears to be in poor condition						
Location: Rear of the building						
	Sub Total for System	1	items		\$1,803	
Sub Total fo	r Building 960C - Tire Shop	3	items		\$6,892	
Building: 960D - Administrative Building / Train	ing Rooms					
	· ·					
Interior	Onto many	Otro	11-84	Daireite	Danain Cast	ID
Deficiency	Category		UoM	Priority	Repair Cost	ID
Deficiency Interior Door Replacement	Capital Renewal	6	Door	3	\$11,254	3920
Deficiency			Door			
Deficiency Interior Door Replacement	Capital Renewal Deferred	6	Door	3	\$11,254	3920
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking	Capital Renewal Deferred	6	Door SF	3	\$11,254	3920
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement	Capital Renewal Deferred Maintenance	6 888	Door SF	3 4	\$11,254 \$10,703	3920 3919
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking	Capital Renewal Deferred Maintenance Deferred	6 888	Door SF SF	3 4	\$11,254 \$10,703	3920 3919
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Deferred	6 888 2,890	Door SF SF	3 4 5	\$11,254 \$10,703 \$24,960	3920 3919 3918
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Deferred	6 888 2,890	Door SF SF SF	3 4 5	\$11,254 \$10,703 \$24,960	3920 3919 3918 3916
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance	6 888 2,890 110	Door SF SF SF	3 4 5 5	\$11,254 \$10,703 \$24,960 \$229	3920 3919 3918 3916
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance	2,890 110	Door SF SF SF	3 4 5 5	\$11,254 \$10,703 \$24,960 \$229	3920 3919 3918 3916
Deficiency Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance	2,890 110	Door SF SF SF SF Wall	3 4 5 5	\$11,254 \$10,703 \$24,960 \$229 \$8,455	3920 3919 3918 3916
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System	2,890 110 3,764	Door SF SF SF SF Wall items	3 4 5 5	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601	3920 3919 3918 3916 3917
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category	6 888 2,890 110 3,764 5 Qty	Door SF SF SF Wall items	3 4 5 5 5	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost	3920 3919 3918 3916 3917
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal	2,890 110 3,764 5	Door SF SF SF SF Wall items UoM Ea.	3 4 5 5 5 5 Priority 2	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991	3920 3919 3918 3916 3917
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal	6 888 2,890 110 3,764 5 Qty 8 7,400	Door SF SF SF Wall items UoM Ea. SF	3 4 5 5 5	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991 \$11,450	3920 3919 3918 3916 3917
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement Existing Controls Are Obsolete	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal	6 888 2,890 110 3,764 5 Qty 8 7,400	Door SF SF SF SF Wall items UoM Ea.	3 4 5 5 5 5 Priority 2	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991	3920 3919 3918 3916 3917
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement Existing Controls Are Obsolete Electrical	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Sub Total for System	6 888 2,890 110 3,764 5 Qty 8 7,400 2	Door SF SF SF SF Wall items UoM Ea. SF items	3 4 5 5 7 7 Priority 2 4	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991 \$11,450 \$42,441	3920 3919 3918 3916 3917 ID 3910 3909
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement Existing Controls Are Obsolete Electrical Deficiency	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Sub Total for System Category Category	2,890 110 3,764 5 Qty 8 7,400 2	Door SF SF SF SF Wall items UoM Ea. SF items	3 4 5 5 5 Priority 2 4 Priority	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991 \$11,450 \$42,441 Repair Cost	3920 3919 3918 3916 3917 ID 3910 3909
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement Existing Controls Are Obsolete Electrical Deficiency Exterior Mounted Building Lighting Replacement	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Sub Total for System Category Capital Renewal Capital Renewal Capital Renewal	5 2,890 110 3,764 5 Qty 8 7,400 2 Qty 10	Door SF SF SF SF Wall items UoM Ea. SF items	3 4 5 5 5 Priority 2 4 Priority 3	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991 \$11,450 \$42,441 Repair Cost \$9,017	3920 3919 3918 3916 3917 ID 3910 3909 ID 2971
Interior Door Replacement Epoxy Flooring Repair Or Replacement Note: Peeling and cracking Concrete Flooring Repair Or Repainting Interior Ceiling Repainting Note: Flaking, chipping and missing Interior Wall Repainting Note: Chipped, cracked and flacking Mechanical Deficiency HVAC VAV Box Replacement Existing Controls Are Obsolete Electrical Deficiency	Capital Renewal Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal Sub Total for System Category Category	6 888 2,890 110 3,764 5 Qty 8 7,400 2 Qty 10 7,400	Door SF SF SF SF Wall items UoM Ea. SF items	3 4 5 5 5 Priority 2 4 Priority	\$11,254 \$10,703 \$24,960 \$229 \$8,455 \$55,601 Repair Cost \$30,991 \$11,450 \$42,441 Repair Cost	3920 3919 3918 3916 3917 ID 3910 3909





Plumbing

Deficiency	Category	Qty U	οМ	Priority	Repair Cost	ID
Water Heater Replacement	Capital Renewal	1 E	a.	2	\$1,264	3908
	Sub Total for System	1 ite	ems		\$1,264	
Fire and Life Safety						
Deficiency	Category	Qty U	оМ	Priority	Repair Cost	ID
Fire Alarm Panel Replacement	Capital Renewal	1 E	a.	1	\$6,868	2970
Fire Alarm Replacement	Capital Renewal	7,400 S	F	1	\$11,750	2969
Security Alarm Replacement	Capital Renewal	7,400 S	F	1	\$17,033	2968
	Sub Total for System	3 ite	ems		\$35,650	
Technology						
Deficiency	Category	Qty U	оМ	Priority	Repair Cost	ID
Public Address System Head-End Requires Replacement	Functional Deficiency	1 E	a.	3	\$7,307	2967
	Sub Total for System	1 ite	ems		\$7,307	
Specialties						
Deficiency	Category	Qty U	оМ	Priority	Repair Cost	ID
Replace Cabinetry In Classes/Labs	Capital Renewal	1 R	oom	4	\$8,802	3907
Note: Base cabinets and upper cabinets beyond repair						
Location: C021						
	Sub Total for System	1 ite	ems		\$8,802	
Sub Total for Building 960D - Administrati	ive Building / Training Rooms	15 it	ems		\$165,321	
	Total for Campus	70 it			\$5,436,844	



Saegert Bus Terminal - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (8-10 Ft)		2,425 LF	\$189,986	8
Parking Lot Pavement	Asphalt		202 CAR	\$293,062	8
Parking Lot Pavement	Concrete		10 CAR	\$24,660	8
	Note: NE parking lot				
Roadway Pavement	Asphalt Driveways		142,656 SF	\$917,339	8
Roadway Pavement	Concrete Driveways		24,193 SF	\$302,016	10
		Sub Total for System	5 items	\$1,727,063	
		Sub Total for Building -	5 items	\$1 727 063	

Building: 960A - Main building includes Administration Offices, & Shop

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Metal Panel - Bldg SF basis		9,707	SF	\$34,674	1
Exterior Operating Windows	Aluminum - Windows per SF		48	SF	\$4,787	2
Exterior Operating Windows	Aluminum - Windows per SF		72	SF	\$7,180	2
Exterior Entrance Doors	Steel - Insulated and Painted		5	Door	\$18,535	2
Exterior Utility Doors	Overhead Door		12	Door	\$99,688	2
		Sub Total for System	5	items	\$164,865	

Interior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Stone Facing	CMU Wall	6,795	SF	\$228,917	4
Wall Painting and Coating	Painting/Staining (Bldg SF)	2,912	SF	\$13,048	4
Interior Swinging Doors	Wooden Door	6	Door	\$11,254	4
Interior Door Supplementary Components	Door Hardware	11	Door	\$16,331	4
Compartments and Cubicles	Toilet Partitions	7	Stall	\$14,115	5
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles	1,941	SF	\$6,554	10
		Sub Total for System 6	items	\$290,219	

Mechanical

Uniformat Description	LC Type Description		Qty UoM	Repair Cost Remaining Life
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)		9,707 SF	\$15,020 10
		Sub Total for System	1 items	\$15,020

Electrical

Uniformat Description	LC Type Description		Qty UoM	Repair Cost	Remaining Life
Power Distribution	Panelboard - 120/208 125A		1 Ea.	\$1,459	5
Lighting Fixtures	Light Fixtures (Bldg SF)		9,707 SF	\$178,012	10
		Sub Total for System	2 items	\$179.471	

Plumbing

Uniformat Description	LC Type Description		Qty UoM	Repair Cost Remaining Life
Domestic Water Equipment	Water Heater - Gas - 40 gallon		1 Ea.	\$3,491 10
		Sub Total for System	1 items	\$3,491

Fire and Life Safety

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm Panel		1	Ea.	\$6,868	3
		Sub Total for System	1	items	\$6,868	

Sub Total for Building 960A - Main building includes Administration Offices, & Shop

Building: 960B - Shop and Storage Area

Exterior

Uniformat Description	LC Type Description	Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Metal Panel - Bldg SF basis	1,571	SF	\$5,612	1
Exterior Wall Veneer	Wood / Composite Siding - Bldg SF basis	83	SF	\$1,075	1
Exterior Operating Windows	Aluminum - Windows per SF	132	SF	\$13,164	2

M•A•P•P•S ©, Jacobs 2022

16 items

\$659,934





Exterior

Exterior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		5	Door	\$18,535	2
Exterior Entrance Doors	Wooden Door		2	Door	\$6,327	2
Exterior Entrance Doors	Wooden Door		2	Door	\$6,327	10
		Sub Total for System	6	items	\$51,040	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Interior Door Supplementary Components	Door Hardware		3	Door	\$4,454	3
Wall Painting and Coating	Painting/Staining (Bldg SF)		165	SF	\$739	7
		Sub Total for System	2	items	\$5,193	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Distribution Panels (600 Amps)		1	Ea.	\$17,802	8
Power Distribution	Panelboard - 120/240 100A		1	Ea.	\$4,236	8
Lighting Fixtures	Light Fixtures (Bldg SF)		1,000	SF	\$18,339	10
		Sub Total for System	3	items	\$40,377	
	Sub Total for Buildi	ng 960B - Shop and Storage Area	11	items	\$96,609	
Building: 960C - Tire Sho	эр					
Exterior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF		14	SF	\$1,396	8
		Sub Total for System	1	items	\$1,396	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Suspended Plaster and	Painted ceilings		360	SF	\$750	10
		Sub Total for System	1	items	\$750	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Thru-Wall AC (2 Ton)	,	1	Ea.	\$5,493	5
Exhaust Air	Roof Exhaust Fan - Small		1	Ea.	\$1,960	10
		Sub Total for System	2	items	\$7,453	
Electrical						
Licotifical						

Building: 960D - Administrative Building / Training Rooms

LC Type Description

Light Fixtures (Bldg SF)

Exterior

Uniformat Description

Lighting Fixtures

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Operating Windows	Aluminum - Windows per SF		301	SF	\$30,018	8
Exterior Operating Windows	Aluminum - Windows per SF		343	SF	\$34,206	8
Exterior Operating Windows	Aluminum - Windows per SF		351	SF	\$35,004	8
Exterior Entrance Doors	Steel - Insulated and Painted		5	Door	\$18,535	8
		Sub Total for System	4	items	\$117,763	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Interior Door Supplementary Components	Door Hardware		27	Door	\$40,084	3
Wall Painting and Coating	Painting/Staining (Bldg SF)	6,	660	SF	\$29,843	4
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		740	SF	\$2,499	5
Compartments and Cubicles	Toilet Partitions		11	Stall	\$22,181	5
Tile Flooring	Ceramic Tile		740	SF	\$13,074	6
Interior Swinging Doors	Wooden Door		20	Door	\$37,512	6
Interior Swinging Doors	Metal Door (Steel)		1	Door	\$2,894	8
Interior Coiling Doors	Interior Overhead Doors		1	Ea.	\$5,286	8
Suspended Plaster and	Painted ceilings	1,	110	SF	\$2,312	10

M•A•P•P•S ©, Jacobs 2022

Sub Total for System

Qty UoM

1 items

5 items

9 items

360 SF

Sub Total for System

Sub Total for Building 960C - Tire Shop

Repair Cost Remaining Life

\$6,602

\$6,602

\$16,201

\$155,685





Mechanical

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Ductless Split System (1 Ton)		1	Ea.	\$3,004	4
Decentralized Cooling	Fan Coil - DX cool w/Electric Heat (15 ton)		1	Ea.	\$9,463	4
Decentralized Cooling	Fan Coil - DX Cool w/Electric Heat (10 ton)		1	Ea.	\$4,553	4
Decentralized Cooling	Condenser - Outside Air Cooled (20 ton)		1	Ea.	\$20,946	4
Decentralized Cooling	Condenser - Outside Air Cooled (10 Tons)		1	Ea.	\$13,749	4
Exhaust Air	Interior Ceiling Exhaust Fan		3	Ea.	\$1,460	10
Heating System Supplementary Components	Controls - Electronic (Bldg.SF)		7,400	SF	\$11,450	10
		Sub Total for System	7	items	\$64,625	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)		7,400	SF	\$135,705	5
		Sub Total for System	1	items	\$135,705	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain		1	Ea.	\$2,202	4
Plumbing Fixtures	Restroom Lavatory		7	Ea.	\$19,014	4
Plumbing Fixtures	Sink - Service / Mop Sink		1	Ea.	\$796	4
Plumbing Fixtures	Toilets		8	Ea.	\$40,475	4
Plumbing Fixtures	Urinals		3	Ea.	\$4,063	4
Plumbing Fixtures	Classroom Lavatory		1	Ea.	\$2,565	10
Domestic Water Equipment	Water Heater - Electric - 5 to 10 gallon		1	Ea.	\$1,264	10
		Sub Total for System	7	items	\$70,378	
Specialties						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Casework	Lockers, Gym		12	Ea.	\$5,826	8
		Sub Total for System	1	items	\$5,826	
	Sub Total for Building 960D - Administrat	ve Building / Training Rooms	29	items	\$549,983	
	To	otal for: Saegert Bus Terminal	66	items	\$3,049,790	

M*A*P*P*S ©, Jacobs 2022 15



Supporting Photos

General Site Photos




Mildew on window seal




Damaged epoxy floor



Damaged interior window seals due to water leak



Shop ceiling insulation panels damaged



Bldg A Access Steel Door to be replaced



Potholes

M•A•P•P•S ©, Jacobs 2022 16