

FACILITY CONDITION ASSESSMENT

Sunset Valley ES | February 2022





Executive Summary

Sunset Valley ES is located at 3000 Jones Rd in Austin, Texas. The oldest building is 49 years old (at time of 2020 assessment). It comprises 67,227 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$7,582,968. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Sunset Valley ES the ten-year need is \$12,037,314.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Sunset Valley ES facility has a 5-year FCA score of 57.86%.

Summary of Findings

The table below summarizes the condition findings at Sunset Valley ES

Table 1: Facility Condition by Building

Number	Building Name	Current Deficiencies	5-Year Life Cycle Cost	Yrs 6-10 Life Cycle Cost	Total 5 Yr Need (Yr 1-5 + Current Defs)	Total 10 Yr Need (Yr 1-10 + Current Defs)	Replacement Cost	5-Year FCA
Exterior Sit	'e							
	Exterior Site	\$1,412,543	\$312,520	\$254,466	\$1,725,063	\$1,979,529	\$0	
Permanent	Building(s)		-		-	-		
158A	Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.	\$5,885,834	\$1,267,217	\$2,270,276	\$7,153,051	\$9,423,327	\$19,065,670	62.48%
158B	Stand-Alone Classroom Building	\$284,591	\$140,484	\$209,383	\$425,075	\$634,458	\$3,011,008	85.88%
	Sub Total for Permanent Building(s):	\$6,170,425	\$1,407,701	\$2,479,659	\$7,578,126	\$10,057,785	\$22,076,676	
	Total for Site:	\$7,582,968	\$1,720,221	\$2,734,125	\$9,303,189	\$12,037,314	\$22,076,676	57.86%



Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)


			Priority				
System	1	2	3	4	5	Total	% of Total
Site	\$0	\$0	\$0	\$0	\$1,404,658	\$1,404,658	18.54 %
Roofing	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Structural	\$6,455	\$0	\$0	\$0	\$0	\$6,455	0.09 %
Exterior	\$0	\$276,543	\$689	\$5,082	\$52,257	\$334,572	4.42 %
Interior	\$0	\$0	\$262,408	\$1,629,671	\$192,704	\$2,084,783	27.52 %
Mechanical	\$0	\$172,505	\$0	\$2,062	\$0	\$174,567	2.30 %
Electrical	\$0	\$74,331	\$1,179,016	\$0	\$0	\$1,253,347	16.54 %
Plumbing	\$0	\$0	\$6,384	\$0	\$0	\$6,384	0.08 %
Fire and Life Safety	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	0.00 %
Specialties	\$0	\$0	\$0	\$748,693	\$0	\$748,693	9.88 %
Crawlspace	\$0	\$0	\$0	\$0	\$1,562,204	\$1,562,204	20.62 %
Total:	\$6,455	\$523,379	\$1,448,497	\$2,385,508	\$3,211,823	\$7,575,661	

The building systems at the site with the most need include:

Interior	-	\$2,084,783
Site	-	\$1,404,658
Electrical	-	\$1,253,347



Austin ISD - Sunset Valley ES



The chart below represents the building systems and associated deficiency costs.

Figure 1: System Deficiencies



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

		Life Cycl	e Capital Renewal Pro	ojections		
System	Year 1 2023	Year 2 2024	Year 3 2025	Year 4 2026	Year 5 2027	Total 1-
Site	\$0	\$0	\$0	\$0	\$185,683	\$185,683
Roofing	\$0	\$0	\$0	\$0	\$126,837	\$126,837
Exterior	\$0	\$0	\$0	\$0	\$22,242	\$22,242
Interior	\$0	\$0	\$0	\$28,208	\$35,636	\$63,844
Mechanical	\$0	\$0	\$478,634	\$38,381	\$56,254	\$573,269
Electrical	\$0	\$0	\$68,953	\$0	\$36,366	\$105,319
Plumbing	\$0	\$0	\$6,607	\$368,892	\$81,086	\$456,585
Fire and Life Safety	\$0	\$0	\$0	\$0	\$133,631	\$133,631
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$0	\$0	\$0	\$0	\$52,811	\$52,811
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$0	\$0	\$554,194	\$435,481	\$730,546	\$1,720,221

Table 3a: Capital Renewal Forecast (Yrs 1-5)



Austin ISD - Sunset Valley ES

Table 3b: Capital Renewal Forecast (Yrs 6-10)

			Life Cycle	Capital Renewal F	Projections			
System	Total 1-5	Year 6 2028	Year 7 2029	Year 8 2030	Year 9 2031	Year 10 2032	Total 6-10	Total 1-10
Site	\$185,683	\$0	\$0	\$0	\$0	\$254,466	\$254,466	\$440,149
Roofing	\$126,837	\$0	\$0	\$0	\$0	\$0	\$0	\$126,837
Exterior	\$22,242	\$0	\$5,082	\$0	\$0	\$1,559,899	\$1,564,981	\$1,587,223
Interior	\$63,844	\$0	\$107,219	\$36,752	\$0	\$167,374	\$311,345	\$375,189
Mechanical	\$573,269	\$0	\$0	\$0	\$0	\$812,916	\$812,916	\$1,386,185
Electrical	\$105,319	\$0	\$0	\$0	\$0	\$168,146	\$168,146	\$273,465
Plumbing	\$456,585	\$0	\$0	\$0	\$0	\$10,844	\$10,844	\$467,429
Fire and Life Safety	\$133,631	\$0	\$0	\$0	\$106,743	\$0	\$106,743	\$240,374
Conveyances	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Specialties	\$52,811	\$0	\$0	\$0	\$0	\$0	\$0	\$52,811
Crawlspace	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0
Total	\$1,720,221	\$0	\$112,301	\$36,752	\$106,743	\$2,973,645	\$3,229,441	\$4,949,662




Figure 2: Ten Year Capital Renewal Forecast



The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$22,076,676. For planning purposes, the total 5-year need at the Sunset Valley ES is \$9,303,189 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Sunset Valley ES facility has a 5-year FCA of 57.86%.





Sunset Valley ES - Deficiency Summary

Site Level Deficiencies

Site							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
PROGRAM DEFICI	IENCIES	ADA Compliance	500,079	EACH	5	\$858,626	247
Note:	Site/Exterior Improvements Estimated Construction Cost for Site Plan Area B \$ 17,239.89 Estimated Construction Cost Subtotal for Site/Exterior Improvements Estimated Construction Cost for Floor Plan Area 4 (Building A) \$ Estimated Construction Cost for Floor Plan Area 5 (Building A) \$ Estimated Construction Cost for Floor Plan Area 6A & 6B (x2) (Bu Estimated Construction Cost for Floor Plan Area 7 (Building A) \$ Estimated Construction Cost for Floor Plan Area 8A & 8B & 8C & Estimated Construction Cost for Floor Plan Area 8A & 8B & 8C & Estimated Construction Cost for Floor Plan Area 8A with the floor Plan Area	7,479.18 50,925.11 uilding A) \$ 130,284.30 138,246.18 8D (x4) (Building B) \$ 155,90 Excluding Division 1 \$ 482,839	4.24 9.01				
Location	n: AISD ADA REPORT						
PUBLIC DEFICIEN	CIES	ADA Compliance	161,968	EACH	5	\$278,096	246
Note:	Site/Exterior Improvements Estimated Construction Cost for Site Plan Area A \$1,665.49 Estimated Construction Cost Subtotal for Site/Exterior Improvements Estimated Construction Cost for Floor Plan Area 1 (Building A) \$ Estimated Construction Cost for Floor Plan Area 2 (Building A) \$ Estimated Construction Cost for Floor Plan Area 3 (Building A) \$ Estimated Construction Cost for Floor Plan Area 3 (Building A) \$ Estimated Construction Cost Subtotal for Interior Improvements Total Estimated Construction Cost Subtotal for Public Deficiency	85,866.84 66,740.93 7,694.26 Excluding Division 1 \$ 160,302					
Location	n: AISD ADA REPORT						
Small Bench Replac	cement	Deferred Maintenance	23	Ea.	5	\$47,537	245
TAS ACCESSIBILIT	TY DEFICIENCIES	ADA Compliance	128,364	EACH	5	\$220,399	247
Note:	Interior Improvements Estimated Construction Cost for Floor Plan Area 9 \$ 19,675.44 Estimated Construction Cost for Floor Plan Area 10 \$ 81,308.79 Estimated Construction Cost for Floor Plan Area 11 \$ 27,379.74 Estimated Construction Cost Subtotal for TAS Improvements Exc Total Estimated Construction Cost Subtotal for TAS Deficiency Im		7				
Location	n: AISD ADA REPORT	,					
		Sub Total for System	4	items		\$1,404,658	
Structural							
Deficiency		Category	Qty	UoM	Priority	Repair Cost	ID
Structural Study Re	commended	Deferred Maintenance	1	Job	1	\$6,455	657
Note:	Structural study to detail scope of work based on the 2017 crawls	pace deficiencies provided by	AISD				
		Sub Total for System	1	items		\$6,455	
Electrical							
		Category	Otv	UoM	Priority	Repair Cost	ID
Deficiency		Deferred		Ea.	2	\$1,430	
	Inclosure Replacement	Maintenance					
-	Site transformer is aged	Maintenance					
Deficiency Exterior Electrical E Note:		Maintenance Sub Total for System	1	items		\$1,430	

Building: 158A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Deficiency		Category	Qty UoM	Priority	Repair Cost	ID
Aluminum Window I	Replacement	Capital Renewal	720 SF	2	\$71,803	1869
Note:	30 @ 3x8; replace due to age					
Aluminum Window I	Replacement	Capital Renewal	80 SF	2	\$7,978	1897
Note:	5 @ 4x4					
Aluminum Window I	Replacement	Capital Renewal	240 SF	2	\$23,934	1898
Note:	20 @ 3x4					
Aluminum Window I	Replacement	Capital Renewal	168 SF	2	\$16,754	1899

M•A•P•P•S ©, Jacobs 2022



Austin ISD - Sunset Valley ES

\$40,455 2461

\$36,752 2074

\$48,351 1960

\$51,288 2075

\$548,873 2067

\$14,469 2358

\$5,788 2359

\$129,079 2072

\$14,115 2070

\$355,841 2077

\$125,061 2078

\$84,637 2462

\$78,044 2449

ID

2374

\$1,834,370

Repair Cost

\$24,593

Exterior

Category	Qty UoM	Priority	Repair Cost	ID
Capital Renewal	29 Door	2	\$107,503	1900
Capital Renewal	6 Door	2	\$22,242	1901
Capital Renewal	2,903 SF	4	\$5,082	2465
Deferred Maintenance	13,493 SF Wall	5	\$52,257	2473
Sub Total for System	8 items		\$307,554	
Category	Qty UoM	Priority	Repair Cost	ID
Capital Renewal	82 Door	3	\$121,738	2463
Capital Renewal	21 Door	3	\$39,388	2360
Capital Renewal	54 Door	3	\$101,282	2361
Capital Renewal	11,611 SF	4	\$39,209	1962
•				
·				
	Capital Renewal Capital Renewal Capital Renewal Deferred Maintenance Sub Total for System Category Capital Renewal Capital Renewal	Capital Renewal 29 Door Capital Renewal 6 Door Capital Renewal 2,903 SF Deferred 13,493 SF Maintenance Wall Sub Total for System 8 items Category Qty UoM Capital Renewal 21 Door Capital Renewal 21 Door Capital Renewal 54 Door	Capital Renewal 29 Door 2 Capital Renewal 6 Door 2 Capital Renewal 2,903 SF 4 Deferred 13,493 SF 5 Maintenance Wall 5 Sub Total for System 8 items Category Qty UoM Priority Capital Renewal 21 Door 3 Capital Renewal 21 Door 3 Capital Renewal 54 Door 3	Capital Renewal29Door2\$107,503Capital Renewal6Door2\$22,242Capital Renewal2,903SF4\$5,082Deferred13,493SF5\$52,257MaintenanceWall8items\$307,554CategoryQtyUoMPriorityRepair CostCapital Renewal82Door3\$121,738Capital Renewal21Door3\$39,388Capital Renewal54Door3\$101,282

	Toplace and to age
Acoustical Ceiling Tile	Replacement
Note:	age
Location:	various
Adhered Acoustical C	eiling Tile Replacement
Location:	Cafeteria
Carpet Flooring Repla	acement
Note:	replace due to age
Location:	library
Ceiling Grid Replacen	nent
Note:	age
Location:	various
Ceramic Tile Flooring	Replacement
Note:	replace due to age
Location:	IRR's

Acoustical Celling The	Replacement	Capital Reliewal	11,011 36	4
Note:	age			
Location:	various			
Adhered Acoustical C	eiling Tile Replacement	Capital Renewal	5,806 SF	4
Location:	Cafeteria			
Carpet Flooring Repla	acement	Capital Renewal	2,903 SF	4
Note:	replace due to age			
Location:	library			
Ceiling Grid Replacer	nent	Capital Renewal	11,611 SF	4
Note:	age			
Location:	various			
Ceramic Tile Flooring	Replacement	Capital Renewal	2,903 SF	4
Note:	replace due to age			
Location:	IRR's			
Interior Wood Wall Re	eplacement (LC)	Capital Renewal	35,000 SF	4
Note:	replace due to age			
Metal Interior Door Re	eplacement	Capital Renewal	5 Door	4
Note:	replace due to age			
Metal Interior Door Re	eplacement	Capital Renewal	2 Door	4
Note:	replace due to age			
Moveable Partition Re	placement	Capital Renewal	800 SF Wall	4
Note:	replace due to age			
Location:	various			
Toilet Partition Replace	cement	Capital Renewal	7 Stall	4
Note:	replace due to age			
Vinyl Composition Tile	e Replacement	Capital Renewal	42,846 SF	4
Note:	replace due to age			
Wood Flooring Replace	cement	Capital Renewal	5,806 SF	4

Capital Renewal

Deferred

Category

Maintenance

Capital Renewal

Sub Total for System

\$147,912 2375

2

5

5

Priority

2

40,640 SF

17,417 SF

17 items

Qty UoM

1 Ea.

Note:

Note:

Interior Ceiling Repainting

Mechanical Deficiency

Boiler Replacement

Boiler Replacement

Interior Wall Repainting (Bldg SF)

Location: stage/gym

Location: mech room

replcae due to age

age/condition



Austin ISD - Sunset Valley ES

Mechanical

Meenanical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Ceiling Exhaust Fan Replacement	Capital Renewal	4	Ea.	4	\$1,947	2472
Ductwork Repair	Deferred Maintenance	20	LF	4	\$115	2379
Note: rust/exposed	Waintenance					
Location: gym						
	Sub Total for System	4	items		\$174,567	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Panelboard Replacement	Capital Renewal	1	Ea.	2	\$2,782	2365
Note: no remaining life						
Panelboard Replacement	Capital Renewal	10	Ea.	2	\$54,995	2366
Panelboard Replacement	Capital Renewal		Ea.	2	\$12,342	2367
Panelboard Replacement	Capital Renewal		Ea.	2	\$2,782	
Exterior Mounted Building Lighting Replacement	Capital Renewal	23	Ea.	3	\$20,740	2372
Note: no remainin glife					• • • • • • • • •	
ighting Fixtures Replacement	Capital Renewal	58,057	SF	3	\$1,064,681	2373
Note: no remaining life						
ightning Protection System Installation	Functional Deficiency	58,057	SF	3	\$45,338	2371
Note: none installed	5 / 1				A 4 4 99 -	
Public Address System Replacement, Non-main Building	Deferred Maintenance	58,057	SF	3	\$41,097	2368
	Sub Total for System	8	items		\$1,244,756	
Plumbing	-				.,,,	
Deficiency	Category	Otv	UoM	Priority	Repair Cost	ID
Bas Water Heater Replacement	Capital Renewal	-	Ea.	3	\$6,384	3476
	Sub Total for System		items	0	\$6,384	0110
Fechnology					<i>+</i> 0,00	
	October	0.		Duiauitu	Densis Cost	
Deficiency Dublic Address System Hand End Requires Perlagement	Category		UoM Ea.	Priority 3	Repair Cost	ID 2260
Public Address System Head-End Requires Replacement	Functional Deficiency Sub Total for System		⊏a. items	3	\$7,307 \$7,307	2369
	Sub Total for System	'	ILEIIIS		φ1, 30 1	
Specialties		-				
	Category		UoM	Priority	Repair Cost	ID
Base Storage Cabinet Replacement	Capital Renewal	280	LF	4	\$154,293	2362
Note: replace due to age						
Location: various	Capital Panawal	27	Room	4	¢225 660	3523
Replace Cabinetry In Classes/Labs	Capital Renewal	250		4 4	\$325,669 \$268,730	
Jpper Storage Cabinet Replacement Note: replace due to age	Capital Renewal	250	LF	4	\$200,730	2303
Location: various						
	Sub Total for System	3	items		\$748,693	
Crawlspace		0	nems		ψ1 1 0,000	
•					_	
	Category	,	UoM	Priority -	Repair Cost	ID
RAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred Maintenance	159,929	Ea.	5	\$187,893	6565
Note: SOIL/DRAINAGE BELOW BUILDING - correct standin						
RAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred	53,478	Ea.	5	\$62,829	6566
	Maintenance					
Note: PERIMETER SOIL RETAINERS - repair soil retainers	- 1921 LS					
RAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred Maintenance	247,890	Ea.	5	\$291,234	6567
Note: CRAWL SPACE ACCESS/VENTILATION - improve ve						
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred	16,703	Ea.	5	\$19,624	6568
Note: CRAWL SPACE ACCESS/VENTILATION - repair acce	Maintenance					
	Deferred	700 646	Fa	5	\$020 165	6569
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Maintenance	799,646	∟а.	5	\$939,465	0009
Note: SUSPENDED FLOOR SLABS - repair cracks, spalling	& reinforcement - 57449 GSF					

Note: SUSPENDED FLOOR SLABS - repair cracks, spalling & reinforcement - 57449 GSF



Austin ISD - Sunset Valley ES

Crawlspace

Crawlspace						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
CRAWL SPACE DEFICIENCIES - Estimate and Info by AISD	Deferred Maintenance	52,058	Ea.	5	\$61,160	6570
Note: CRAWL SPACE, EXPOSED PIPES - Repair rusted pi	pes and hangers - 1 IS					
	Sub Total for System	6	items		\$1,562,204	
Sub Total for Building 158A - Main building includes Administration Off	ices, Classrooms, Cafeteria, & Gym.	48	items		\$5,885,834	
Building: 158B - Stand-Alone Classroom B	Building					
Exterior	5					
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Aluminum Window Replacement	Capital Renewal	240		2	\$23,934	2481
Aluminum Window Replacement	Capital Renewal	24	SF	2	\$2,393	2482
Exterior Metal Door Repainting	Deferred Maintenance	2	Door	3	\$230	1902
Exterior Metal Door Repainting	Deferred Maintenance	4	Door	3	\$460	1903
	Sub Total for System	4	items		\$27,017	
Interior						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Acoustical Ceiling Tile Replacement	Capital Renewal	8,711	SF	4	\$29,415	1907
Ceiling Grid Replacement	Capital Renewal	8,711	SF	4	\$36,275	1904
Note: replace due to age						
Location: all						
Interior CMU Walls Repainting	Capital Renewal	2,200	SF	4	\$2,272	1912
Note: repaint due to age						
Moveable Partition Replacement	Capital Renewal	480	SF Wall	4	\$77,447	1915
Note: 4 @ 15x8						
Vinyl Composition Tile Replacement	Capital Renewal	9,169	SF	4	\$74,981	1916
Note: replace due to age						
Location: all						
Interior Door Repainting	Deferred Maintenance	9	Door	5	\$402	1917
Note: w/o windows						
Interior Door Repainting	Deferred Maintenance	10	Door	5	\$446	1928
Note: repaint due to age						
Interior Wall Repainting (Bldg SF)	Capital Renewal	6,511	SF	5	\$29,175	2466
	Sub Total for System	8	items		\$250,413	
Electrical						
Deficiency	Category	Qty	UoM	Priority	Repair Cost	ID
Lightning Protection System Installation	Functional Deficiency	9,169	SF	3	\$7,160	2364
	Sub Total for System	1	items		\$7,160	

Sub Total for Building 158B - Stand-Alone Classroom Building

13 items

67 items

Total for Campus

\$284,591

\$7,582,968



Sunset Valley ES - Life Cycle Summary Yrs 1-10

Site Level Life Cycle Items

Site

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fences and Gates	Fencing - Chain Link (4 Ft)		1,720	LF	\$81,179	5
Playfield Areas	ES Playgrounds		2	Ea.	\$44,696	5
Pedestrian Pavement	Sidewalks - Concrete		5,280	SF	\$59,808	5
Parking Lot Pavement	Asphalt		105	CAR	\$152,334	10
Roadway Pavement	Asphalt Driveways		12,000	SF	\$77,165	10
Roadway Pavement	Concrete Driveways		2,000	SF	\$24,967	10
		Sub Total for System	6	items	\$440,150	
Roofing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Canopy Roofing	Steel panels		2,500	SF	\$126,837	5
		Sub Total for System	1	items	\$126,837	
		Sub Total for Building -	7	items	\$566,987	

Building: 158A - Main building includes Administration Offices, Classrooms, Cafeteria, & Gym.

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Wall Veneer	Exterior Painting - Bldg SF basis		2,903	SF	\$5,082	7
Exterior Wall Veneer	Brick - Bldg SF basis		55,154	SF	\$1,549,529	10
Exterior Wall Veneer	Metal Panel - Bldg SF basis		2,903	SF	\$10,370	10
		Sub Total for System	3	items	\$1,564,981	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Wall Painting and Coating	Painting/Staining (Bldg SF)		17,417	SF	\$78,044	7
Carpeting	Carpet		2,903	SF	\$36,752	8
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		11,611	SF	\$39,207	10
Compartments and Cubicles	Toilet Partitions		7	Stall	\$14,115	10
Suspended Plaster and	Painted ceilings		40,640	SF	\$84,637	10
		Sub Total for System	5	items	\$252,756	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Decentralized Cooling	Fan Coil - D/X only (5 Ton)		1	Ea.	\$2,617	3
Decentralized Cooling	Condenser - Outside Air Cooled (3 Tons)		1	Ea.	\$6,423	3
HVAC Air Distribution	Ductwork (Bldg.SF)		58,057	SF	\$459,373	3
Exhaust Air	Interior Ceiling Exhaust Fan		21	Ea.	\$10,221	3
Other HVAC Distribution Systems	VFD (10 HP)		3	Ea.	\$17,122	4
Other HVAC Distribution Systems	VFD (15 HP)		1	Ea.	\$7,559	4
Facility Hydronic Distribution	Pump - 5HP		2	Ea.	\$13,700	4
Exhaust Air	Roof Exhaust Fan - Large		7	Ea.	\$56,254	5
Heat Generation	Boiler - Steel Tube (750 MBH)		1	Ea.	\$24,593	10
Heat Generation	Boiler - Steel Tube (4800 MBH)		1	Ea.	\$147,912	10
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		58,057	SF	\$156,593	10
Central Cooling	Chiller - Outdoor Air Cooled (175 Tons)		1	Ea.	\$191,385	10
Air Distribution	Make-up Air Unit		1	Ea.	\$8,888	10
Facility Hydronic Distribution	4-Pipe System		58,057	SF	\$140,479	10
Facility Hydronic Distribution	Pump- 10HP (Ea.)		2	Ea.	\$23,121	10
HVAC Air Distribution	VAV Boxes / Terminal Device		10	Ea.	\$38,739	10
Exhaust Air	Roof Exhaust Fan - Large		4	Ea.	\$32,145	10
Exhaust Air	Kitchen Exhaust Hoods		2	Ea.	\$22,383	10
		Sub Total for System	18	items	\$1,359,504	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Power Wiring		58,057	SF	\$68,953	3
Power Distribution	Distribution Panels (600 Amps)		1	Ea.	\$17,802	5

M•A•P•P•S ©, Jacobs 2022



Austin ISD - Sunset Valley ES

Electrical

Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Power Distribution	Distribution Panels (800 Amps)		1	Ea.	\$18,564	5
		Sub Total for System	3	items	\$105,320	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Plumbing Fixtures	Refrigerated Drinking Fountain		3	Ea.	\$6,607	3
Domestic Water Piping	Domestic Water Piping System (Bldg.SF)		58,057	SF	\$208,641	4
Sanitary Sewerage Piping	Sanitary Sewer Piping		58,057	SF	\$64,457	4
Plumbing Fixtures	Restroom Lavatory		4	Ea.	\$10,865	4
Plumbing Fixtures	Sink - Service / Mop Sink		5	Ea.	\$3,979	4
Plumbing Fixtures	Toilets		16	Ea.	\$80,950	4
Plumbing Fixtures	Classroom Lavatory		5	Ea.	\$12,822	5
Plumbing Fixtures	Classroom Lavatory		26	Ea.	\$66,677	5
Domestic Water Equipment	Water Heater - Electric - 80 gallon		1	Ea.	\$4,460	10
Domestic Water Equipment	Water Heater - Gas - 100 Gallon		1	Ea.	\$6,384	10
		Sub Total for System	10	items	\$465,843	
Fire and Life Safety						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Security System Component	Security Alarm System		58,057	SF	\$133,631	5
Fire Detection and Alarm	Fire Alarm		58,057	SF	\$92,184	9
		Sub Total for System	2	items	\$225,815	
Sub Total for Building 158	BA - Main building includes Administration Offices, C	lassrooms, Cafeteria, & Gym.	41	items	\$3,974,219	

Building: 158B - Stand-Alone Classroom Building

Exterior

Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Exterior Entrance Doors	Steel - Insulated and Painted		2	Door	\$7,414	5
Exterior Entrance Doors	Steel - Insulated and Painted		4	Door	\$14,828	5
		Sub Total for System	2	items	\$22,242	
Interior						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Interior Door Supplementary Components	Door Hardware		19	Door	\$28,208	4
Interior Swinging Doors	Wooden Door		9	Door	\$16,880	5
Interior Swinging Doors	Wooden Door		10	Door	\$18,756	5
Wall Painting and Coating	Painting/Staining (Bldg SF)		6,511	SF	\$29,175	7
Acoustical Suspended Ceilings	Ceilings - Acoustical Tiles		8,711	SF	\$29,415	10
		Sub Total for System	5	items	\$122,434	
Mechanical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Heating System Supplementary Components	Controls - DDC (Bldg.SF)		9,169	SF	\$24,731	10
Exhaust Air	Interior Ceiling Exhaust Fan		4	Ea.	\$1,947	10
		Sub Total for System	2	items	\$26,678	
Electrical						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Lighting Fixtures	Light Fixtures (Bldg SF)		9,169	SF	\$168,146	10
		Sub Total for System	1	items	\$168,146	
Plumbing						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Domestic Water Equipment	Water Heater - Electric - 20 gallon		1	Ea.	\$1,587	5
		Sub Total for System	1	items	\$1,587	
Fire and Life Safety						
Uniformat Description	LC Type Description		Qty	UoM	Repair Cost	Remaining Life
Fire Detection and Alarm	Fire Alarm		9,169	SF	\$14,559	9
		Sub Total for System	1	items	\$14,559	

Austin ISD - Sunset Valley ES



Specialties

Uniformat Description	LC Type Description	Qty UoM	Repair Cost Remaining Life
Casework	Fixed Cabinetry	6 Room	\$52,811 5
	Sub Total for System	1 items	\$52,811
	Sub Total for Building 158B - Stand-Alone Classroom Building	13 items	\$408,456
	Total for: Sunset Valley ES	61 items	\$4,949,662



Austin ISD - Sunset Valley ES

Supporting Photos

General Site Photos




Ductwork is at end of life



625 MBH boiler at end of life



Aged cabinets



Accoustical ceilings are aged and damaged



Aged exterior electrical service