

FACILITY CONDITION ASSESSMENT

Travis Heights ES | February 2022





Executive Summary

Travis Heights ES is located at 2010 Alameda Dr in Austin, Texas. The oldest building is 82 years old (at time of 2020 assessment). It comprises 55,057 gross square feet.

The findings contained within this report are the result of an assessment of building systems and the conditions found on the site at the time of the visit. The assessment was performed by building professionals experienced in disciplines including architecture, mechanical, plumbing and electrical. The total current deficiencies for this site, in 2020 construction cost dollars, are estimated at \$4,877,495. A ten-year need was developed to provide an understanding of the current need as well as the projected needs in the near future. For Travis Heights ES the ten-year need is \$8,844,200.

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined to calculate a Facility Condition Assessment (FCA) score. A 5-year FCA was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCA calculation. The Travis Heights ES facility has a 5-year FCA score of 58.19%.

Summary of Findings

The table below summarizes the condition findings at Travis Heights ES

Table 1: Facility Condition by Building

| Number | Building Name | Current Deficiencies | 5-Year Life Cycle Cost | Yrs 6-10 Life Cycle Cost | Total 5 Yr Need (Yr 1-5 + Current Defs) | Total 10 Yr Need (Yr 1-10 + Current Defs) | Replacement Cost | 5-Year FCA |
|--------------|---|-------------------------|---------------------------|-----------------------------|---|---|---------------------|---------------|
| Exterior Sit | ite | | | | | | | |
| | Exterior Site | \$2,704,432 | \$282,672 | \$67,882 | \$2,987,104 | \$3,054,986 | \$0 | |
| Permanent | t Building(s) | | | | | | | |
| 140A | Main building includes Administration Offices, Classrooms, Cafeteria. | \$2,046,938 | \$1,932,810 | \$564,371 | \$3,979,748 | \$4,544,119 | \$13,324,750 | 70.13% |
| 140B | Stand-Alone Gym | \$54,350 | \$324,776 | \$104,315 | \$379,126 | \$483,441 | \$2,400,110 | 84.20% |
| 140C | Stand-Alone Classroom Building | \$71,774 | \$449,500 | \$240,379 | \$521,274 | \$761,653 | \$3,093,762 | 83.15% |
| | Sub Total for Permanent Building(s): | \$2,173,063 | \$2,707,086 | \$909,065 | \$4,880,149 | \$5,789,214 | \$18,818,625 | |
| | Total for Site: | \$4,877,495 | \$2,989,758 | \$976,947 | \$7,867,253 | \$8,844,200 | \$18,818,625 | 58.19% |

M-A-P-P-S ©, Jacobs 2022

Facility Condition Assessment





Approach and Methodology

A facility condition assessment evaluates each building's overall condition. Two components of the facility condition assessment are combined to total the cost for facility need. The two components of the facility condition assessment are current deficiencies and life cycle forecast.

Current Deficiencies: Deficiencies are items in need of repair or replacement as a result of being broken, obsolete, or beyond useful life. The existing deficiencies that currently require correction are identified and assigned a priority. An example of a current deficiency might include a broken lighting fixture or an inoperable roof top air conditioning unit.

Life Cycle Forecast: Life cycle analysis evaluates the ages of a building's systems to forecast system replacement as they reach the end of serviceable life. An example of a life cycle system replacement is a roof with a 20-year life that has been in place for 15 years and may require replacement in five years.

All members of the survey team recorded existing conditions, identified problems and deficiencies, and documented corrective action and quantities. The team took digital photos at each site to better identify significant deficiencies.

Facility Deficiency Priority Levels

Deficiencies were ranked according to five priority levels, with Priority 1 items being the most critical to address:

Priority 1 – **Mission Critical Concerns:** Deficiencies or conditions that may directly affect the site's ability to remain open or deliver the educational curriculum. These deficiencies typically relate to building safety, code compliance, severely damaged or failing building components, and other items that require near-term correction. An example of a Priority 1 deficiency is a fire alarm system replacement.

Priority 2 - Indirect Impact to Educational Mission: Items that may progress to a Priority 1 item if not addressed in the near term. Examples of Priority 2 deficiencies include inadequate roofing that could cause deterioration of integral building systems, and conditions affecting building envelopes, such as roof and window replacements.

Priority 3 - Short-Term Conditions: Deficiencies that are necessary to the site's mission but may not require immediate attention. These items should be considered necessary improvements required to maximize facility efficiency and usefulness. Examples of Priority 3 items include site improvements and plumbing deficiencies.

Priority 4 - Long-Term Requirements: Items or systems that may be considered improvements to the instructional environment. The improvements may be aesthetic or provide greater functionality. Examples include cabinets, finishes, paving, removal of abandoned equipment, and educational accommodations associated with special programs.

Priority 5 - Enhancements: Deficiencies aesthetic in nature or considered enhancements. Typical deficiencies in this priority include repainting, replacing carpet, improved signage, or other improvements to the facility environment.



The following table summarizes this site's current deficiencies by building system and priority.

Table 2: System by Priority (Site & Permanent Buildings)

| | | | Priority | | | | |
|----------------------|-------------|-----------|----------|-----|-------------|-------------|------------|
| System | 1 | 2 | 3 | 4 | 5 | Total | % of Total |
| Site | \$0 | \$0 | \$22,276 | \$0 | \$2,675,702 | \$2,697,977 | 55.31 % |
| Roofing | \$1,063,588 | \$0 | \$0 | \$0 | \$0 | \$1,063,588 | 21.81 % |
| Structural | \$6,455 | \$0 | \$0 | \$0 | \$0 | \$6,455 | 0.13 % |
| Exterior | \$0 | \$4,336 | \$0 | \$0 | \$1,960 | \$6,296 | 0.13 % |
| Interior | \$0 | \$0 | \$16,331 | \$0 | \$8,962 | \$25,293 | 0.52 % |
| Mechanical | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Electrical | \$0 | \$168,728 | \$28,977 | \$0 | \$0 | \$197,704 | 4.05 % |
| Plumbing | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Fire and Life Safety | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Specialties | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | 0.00 % |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$880,183 | \$880,183 | 18.05 % |
| Total: | \$1,070,042 | \$173,064 | \$67,583 | \$0 | \$3,566,806 | \$4,877,495 | |

The building systems at the site with the most need include:

| Site | _ | \$2,697,977 |
|------------|---|-------------|
| Roofing | - | \$1,063,588 |
| Electrical | - | \$197,704 |

M-A-P-P-S ©, Jacobs 2022



The chart below represents the building systems and associated deficiency costs.




Figure 1: System Deficiencies

M•A•P•P•S ©, Jacobs 2022 5



Life Cycle Capital Renewal Forecast

During the facility condition assessment, assessors inspected all major building systems. If an assessor identified a need for immediate replacement, a deficiency was created with the item's repair costs. The identified deficiency contributes to the facility's total current repair costs.

However, capital planning scenarios span multiple years, as opposed to being constrained to immediate repairs. Construction projects may begin several years after the initial facility condition assessment. Therefore, in addition to the current year repair costs, it is necessary to forecast the facility's future costs using a ten-year life cycle renewal forecast model.

Life cycle renewal is the projection of future building system costs based upon each individual system's expected serviceable life. Building systems and components age over time, eventually break down, reach the end of their useful lives, and may require replacement. While an item may be in good condition now, it might reach the end of its life before a planned construction project occurs.

The following tables show current deficiencies and the subsequent ten-year life cycle capital renewal projections. The projections outline costs for major building systems in which a component is expected to reach the end of its useful life and require capital funding for replacement.

Table 3a: Capital Renewal Forecast (Yrs 1-5)

| | | Life Cycl | e Capital Renewal Pro | ojections | | |
|----------------------|----------------|----------------|-----------------------|----------------|----------------|-------------|
| System | Year 1 2023 | Year 2 2024 | Year 3 2025 | Year 4 2026 | Year 5 2027 | Total 1-5 |
| Site | \$0 | \$0 | \$0 | \$16,076 | \$217,237 | \$233,313 |
| Roofing | \$0 | \$0 | \$0 | \$49,359 | \$0 | \$49,359 |
| Exterior | \$0 | \$0 | \$0 | \$0 | \$1,396 | \$1,396 |
| Interior | \$0 | \$0 | \$12,675 | \$33,103 | \$249,056 | \$294,834 |
| Mechanical | \$0 | \$0 | \$0 | \$86,225 | \$417,634 | \$503,859 |
| Electrical | \$0 | \$0 | \$0 | \$68,278 | \$1,077,682 | \$1,145,960 |
| Plumbing | \$0 | \$0 | \$0 | \$0 | \$367,857 | \$367,857 |
| Fire and Life Safety | \$0 | \$0 | \$108,022 | \$126,724 | \$0 | \$234,746 |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Specialties | \$0 | \$158,434 | \$0 | \$0 | \$0 | \$158,434 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$0 | \$158,434 | \$120,697 | \$379,765 | \$2,330,862 | \$2,989,758 |

M-A-P-P-S ©, Jacobs 2022



Table 3b: Capital Renewal Forecast (Yrs 6-10)

| | | | Life Cycle | Capital Renewal F | Projections | | | |
|----------------------|-------------|----------------|----------------|-------------------|----------------|-----------------|------------|-------------|
| System | Total 1-5 | Year 6 2028 | Year 7 2029 | Year 8 2030 | Year 9 2031 | Year 10 2032 | Total 6-10 | Total 1-10 |
| Site | \$233,313 | \$216 | \$32,152 | \$0 | \$0 | \$0 | \$32,368 | \$265,681 |
| Roofing | \$49,359 | \$0 | \$35,514 | \$0 | \$0 | \$0 | \$35,514 | \$84,873 |
| Exterior | \$1,396 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,396 |
| Interior | \$294,834 | \$0 | \$40,104 | \$43,916 | \$0 | \$0 | \$84,020 | \$378,854 |
| Mechanical | \$503,859 | \$0 | \$0 | \$266,824 | \$0 | \$152,144 | \$418,968 | \$922,827 |
| Electrical | \$1,145,960 | \$0 | \$0 | \$2,782 | \$0 | \$83,192 | \$85,974 | \$1,231,934 |
| Plumbing | \$367,857 | \$0 | \$0 | \$39,971 | \$0 | \$107,708 | \$147,679 | \$515,536 |
| Fire and Life Safety | \$234,746 | \$0 | \$0 | \$102,009 | \$0 | \$0 | \$102,009 | \$336,755 |
| Conveyances | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Specialties | \$158,434 | \$70,415 | \$0 | \$0 | \$0 | \$0 | \$70,415 | \$228,849 |
| Crawlspace | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 | \$0 |
| Total | \$2,989,758 | \$70,631 | \$107,770 | \$455,502 | \$0 | \$343,044 | \$976,947 | \$3,966,705 |




Figure 2: Ten Year Capital Renewal Forecast



Facility Condition Assessment Score

The Facility Condition Assessment Score (FCAS) is used throughout the facility condition assessment industry as a general indicator of a building's health. The FCAS is used to benchmark the relative condition of a group of sites. The FCAS is derived by dividing the total repair cost, site-related repairs, by the total replacement cost and subtracting it from 100. A facility with a lower FCAS percentage has more need, or higher priority, than a facility with a lower FCAS. It should be noted that costs in the New Construction category are not included in the FCAS calculation.


FCAS = 100 - (Total Repair Cost/ Replacement Cost)

For master planning purposes, the total current deficiencies and the first five years of projected life cycle needs were combined. This provides an understanding of the current needs of a facility as well as the projected needs in the near future. A 5-year FCAS was calculated by dividing the 5-year need by the total replacement cost. Costs associated with new construction are not included in the FCAS calculation.



Financial modeling has shown that over a 30-year period, it is more cost effective to replace than repair sites with a FCAS of 35 percent or greater. This is due to efficiency gains with facilities that are more modern and the value of the building at the end of the analysis period. It is important to note that the FCAS at which a facility should be considered for replacement is typically debated and adjusted based on property owners and facility managers approach to facility management. Of course, FCAS is not the only factor used to identify buildings that need renovation, replacement, or even closure. Historical significance, enrollment trends, community sentiment, and the availability of capital are additional factors that are analyzed when making campus facility decisions.

The replacement value represents the estimated cost of replacing the current building with another building of like size, based on today's estimated cost of construction in the Austin area. The estimated replacement cost for this facility is \$18,818,625. For planning purposes, the total 5-year need at the Travis Heights ES is \$7,867,253 (Life Cycle Years 1-5 plus the FCA deficiency cost). The Travis Heights ES facility has a 5-year FCA of 58.19%.





Travis Heights ES - Deficiency Summary Site Level Deficiencies

Site

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|---------------------------------------|-------------------------|----------|----------|-------------|------|
| Playground Impact Surface Replacement | Deferred Maintenance | 1,750 SF | 3 | \$22,276 | 2477 |

Note: Playground chips need to be replaced. Signs of wear.

PROGRAM DEFICIENCIES **ADA Compliance** 769,451 EACH \$1,321,133 2317

Note:

SECTION TWO: PROGRAM DEFICIENCIESSite/Exterior Improvements Estimated Construction Cost for Site Plan Area D2,683.80\$ Estimated Construction Cost for Site Plan Area E171,427.73\$ Estimated Construction Cost for Site Plan Area F3,061.07\$ Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division Construction Cost for Site Plan Area G1,051.09\$ Estimated Construction Cost for Floor Plan Area 9 - Building A 11,218.28\$ 1178,223.68\$Interior Improvements Estimated Construction Cost for Floor Plan Area 10 - Building A 153,174.24\$ Estimated Construction Cost for Floor Plan Area 11 (Areas 11A &11B) (X2) - Building Estimated Construction Cost for Floor Plan Area 12 - Building A56,693.36\$ Estimated Construction Cost for Floor Plan Area Estimated Construction Cost for Floor Plan Area 14 - Building C35,085.89\$ Estimated Construction Cost for Floor Plan Årea 15 (Areas 15A & 15B) (X2) - Building C60,335.66\$ Estimated Construction Cost for Floor Plan Area 16 - Building A30,919.29\$ Estimated Construction Cost for Floor Plan Area 17 - Building A15,054.20\$ Estimated Construction Cost for Floor Plan Area 18 - Building Estimated Construction Cost Subtotal for Interior Improvements Excluding Division 1591,226.95\$Total Estimated Construction

Cost Subtotal for Program Deficiency Improvements769,450.64

PUBLIC DEFICIENCIES ADA Compliance 666.659 EACH \$1.144.641 2316

Note:

SECTION ONE: PUBLIC DEFICIENCIESSite/Exterior Improvements Estimated Construction Cost for Site Plan Area A27,733.24\$ Estimated Construction Cost for Site Plan Area B2,510.31\$ Estimated Construction Cost for Site Plan Area C70,699.92\$ Estimated Construction Cost Subtotal for Site/Exterior Improvements Excluding Division 1100,943.47\$Interior Improvements for Floor Plan Area 1 - Building A222,891.24\$ Estimated Construction Cost for Floor Plan Area 2 - Building A145,011.47\$ Construction Cost for Floor Plan Area 3 - Building A8,951.81\$ Estimated Construction Cost for Floor Plan Area 4 - Building A41,282.69\$ Estimated Construction Cost for Floor Plan Area 5 - Building A15,603.80\$ Estimated Construction Cost for Floor Plan Area 6 - Building Estimated Construction Cost for Floor Plan Årea 7 - Building B59,110.31\$ Estimated Construction Cost for Floor Plan Årea 8 -

Building B66,089.53\$ Estimated Construction Cost Subtotal for Interior Improvements Excluding Division

1565,715.54\$140.1.2REPORTCOSTSUMMARYTotal Estimated Construction Cost Subtotal for Public Deficiency Improvements666,659.01

TAS ACCESSIBILITY DEFICIENCIES

ADA Compliance 122,266 EACH

Note:

SECTION THREE: TAS ACCESSIBILITY DEFICIENCIESInterior Improvements Estimated Construction Cost for Floor Plan Area 19 - Building Estimated Construction Cost for Floor Plan Area 20 - Building A43,278.96\$ Estimated Construction Cost for Floor Plan A 32,829.97\$ Estimated Construction Cost for Floor Plan Area 22 - Building A6,282.97\$ Estimated Construction Cost for Floor Plan Area 22 - Building C21,426.50\$ Estimated Construction Cost Subtotal for TAS Improvements Excluding Division 1122,265.68\$Total Estimated Construction Cost for Floor Plan Area 21 - Building A32,829.97\$ Estimated Construction Cost for Floor Plan Area 23 - Building C21,426.50\$

Estimated Construction Cost Subtotal for TAS Deficiency Improvements122,265.68

Sub Total for System 4 items \$2.697.977

Structural

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|------------------------------|----------|---------|----------|-------------|------|
| Structural Study Recommended | Deferred | 1 Job | 1 | \$6,455 | 6564 |

Note: Structural study to detail scope of work based on the 2017 crawlspace deficiencies provided by AISD

> Sub Total for System 1 items \$6.455

Sub Total for School and Site Level 5 items \$2,704,432

Building: 140A - Main building includes Administration Offices, Classrooms, Cafeteria. Roofing

| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
|------------------------------------|----------------------|--------------|----------|-------------|------|
| AISD ROOFING P1 | Capital Renewal | 87,652 EACH | 1 | \$87,650 | 2313 |
| AISD ROOFING P2 | Capital Renewal | 433,540 EACH | 1 | \$433,530 | 2314 |
| AISD ROOFING P4 | Capital Renewal | 542,419 EACH | 1 | \$542,407 | 2315 |
| | Sub Total for System | 3 items | | \$1,063,588 | |
| Exterior | | | | | |
| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
| Steel Window Replacement | Capital Renewal | 30 SF | 2 | \$4,336 | 2468 |
| Note: 5 @ 3x2 - original windows | | | | | |
| | Sub Total for System | 1 items | | \$4,336 | |
| Interior | | | | | |
| Deficiency | Category | Qty UoM | Priority | Repair Cost | ID |
| Interior Door Hardware Replacement | Capital Renewal | 11 Door | 3 | \$16,331 | 1964 |
| Note: Original Equipment | | | | | |
| Interior Wall Repainting (Bldg SF) | Capital Renewal | 2,000 SF | 5 | \$8,962 | 3932 |
| | Sub Total for System | 2 items | | \$25,293 | |

MªAªPªPS ©. Jacobs 2022








Electrical

| Deficiency | | Category | Qty UoM | Priority | Repair Cost | ID |
|----------------------|---|-------------------------------|----------------|----------|-------------|------|
| Distribution Panel R | eplacement | Capital Renewal | 1 Ea. | 2 | \$17,802 | 1931 |
| Note: | 600 amp distribution panel in of crawl space - weathered | | | | | |
| Panelboard Replace | ement | Capital Renewal | 1 Ea. | 2 | \$7,823 | 1935 |
| Note: | located in kitchen and panelboard is rusted | | | | | |
| Panelboard Replace | ement | Capital Renewal | 2 Ea. | 2 | \$10,999 | 2490 |
| Note: | estimated - Panels DP & 2P | | | | | |
| Location | n: ground level boiler room | | | | | |
| Panelboard Replace | ement | Capital Renewal | 4 Ea. | 2 | \$16,943 | 2640 |
| Note: | (125A) replace all. rusted/kitchen | | | | | |
| Switchgear Replace | ement | Capital Renewal | 2 Ea. | 2 | \$76,774 | 1927 |
| Note: | Old switchgear | | | | | |
| Location | n: Boiler room | | | | | |
| Switchgear Replace | ement | Capital Renewal | 1 Ea. | 2 | \$38,387 | 2641 |
| Note: | 1000 amp subsection of 1200 amp needs to be replaced | | | | | |
| Exterior Mounted Bu | uilding Lighting Replacement | Capital Renewal | 15 Ea. | 3 | \$13,526 | 2489 |
| Note: | All building mounted lights are aged and damaged. | | | | | |
| | | Sub Total for System | 7 items | S | \$182,254 | |
| Crawlspace | | | | | | |
| Deficiency | | Category | Qty UoM | Priority | Repair Cost | ID |
| | FICIENCIES - Estimate and Info by AISD | Deferred | 43,845 Ea. | 5 | \$51,511 | 6547 |
| CRAWL SI ACE DE | TiolENGIEG - Estimate and find by Alob | Maintenance | 45,045 La. | 3 | ψ51,511 | 0047 |
| Note: | SOIL/DRAINAGE BELOW BUILDING - minor repairs to improve | ve drainage - 28636 GSF | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 239,155 Ea. | 5 | \$280,971 | 6548 |
| Note: | CRAWL SPACE ACCESS/VENTILATION - improve ventilation | n - 28636 GSF | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 11,135 Ea. | 5 | \$13,082 | 6549 |
| Note: | CRAWL SPACE ACCESS/VENTILATION - repair acess - 4 EA | A | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 39,859 Ea. | 5 | \$46,828 | 6550 |
| Note: | STANDARD FOUNDATIONS - repair columns - 28636 GSF | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 32,003 Ea. | 5 | \$37,599 | 6551 |
| Note: | SPECIAL FOUNDATIONS - repair perimeter - 1437 LF | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 79,718 Ea. | 5 | \$93,657 | 6552 |
| Note: | SUSPENDED FLOOR BEAMS - repair beams - 28636 GSF | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 159,436 Ea. | 5 | \$187,314 | 6553 |
| Note: | SUSPENDED FLOOR SLABS - repair slab bottom - 28636 GS | SF. | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 18,095 Ea. | 5 | \$21,259 | 6554 |
| Note: | CRAWL SPACE, EXPOSED PIPES - imporve drainage - 1 LS | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 33,406 Ea. | 5 | \$39,247 | 6555 |
| Note: | CRAWL SPACE, EXPOSED DUCTWORK - repair insulation - | 1 LS | | | | |
| | | Sub Total for System | 9 items | s | \$771,468 | |
| Sub Total | for Building 140A - Main building includes Administration Off | fices, Classrooms, Cafeteria. | 22 items | S | \$2,046,938 | |
| Building: 1 | 40B - Stand-Alone Gym | | | | | |
| Exterior | | | | | | |
| Deficiency | | Category | Qty UoM | Priority | Repair Cost | ID |
| Exterior Cleaning | | Deferred Maintenance | 506 SF Wall | 5 | \$1,960 | 2474 |
| | | Sub Total for System | 1 items | S | \$1,960 | |
| Electrical | | - | | | | |
| | | Catagory | Ohr Hold | Driority | Popoir Cost | ID |
| Deficiency | placement | Category | Qty UoM | Priority | Repair Cost | ID |
| Canopy Lighting Re | piacement | Capital Renewal | 2 Ea. | 3 | \$3,791 | 2488 |







Electrical

| Deficiency | | Category | Qty | | Priority | Repair Cost | |
|--|--|--|--------------------------------------|--------------------------------|--------------------|--|------------------------------------|
| Note: | Aged lights at entries | | | | | | |
| _ | | Sub Total for System | 1 | items | | \$3,791 | |
| Crawlspace | | | | | | | |
| Deficiency | | Category | Qty | UoM | Priority | Repair Cost | ID |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 15,311 | Ea. | 5 | \$17,988 | 6556 |
| Note: | CRAWL SPACE ACCESS/VENTILATION - inprove ventilati | | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 1,392 | Ea. | 5 | \$1,797 | 6557 |
| Note: | CRAWL SPACE ACCESS/VENTILATION - clear access - 1 | EA | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 8,936 | Ea. | 5 | \$10,498 | 6558 |
| Note: | SPECIAL FOUNDATIONS - repair perimeter - 321 LF | | | | | | |
| CRAWL SPACE DE | FICIENCIES - Estimate and Info by AISD | Deferred Maintenance | 15,590 | Ea. | 5 | \$18,316 | 6559 |
| Note: | CRAWL SPACE, EXPOSED PIPES - repair rusted pipes, ha | angers and broken pipes - 1 LS | | | | | |
| | | Sub Total for System | 4 | items | | \$48,600 | |
| | Sub Total for Bu | ilding 140B - Stand-Alone Gym | 6 | items | | \$54,350 | |
| Building: 1 | 40C - Stand-Alone Classroom Bui | lding | | | | | |
| _ | | _ | | | | | |
| Electrical | | _ | | | | | |
| Electrical Deficiency | | Category | Qty | UoM | Priority | Repair Cost | ID |
| | placement | Category Capital Renewal | | UoM Ea. | Priority 3 | Repair Cost \$6,249 | ID 1955 |
| Deficiency | placement aged at entries | | | | <u>_</u> | | |
| Deficiency Canopy Lighting Re Note: | • | | 3 | | <u>_</u> | | |
| Deficiency Canopy Lighting Re Note: | aged at entries | Capital Renewal | 3 | Ea. | 3 | \$6,249 | 1955 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu | aged at entries illding Lighting Replacement | Capital Renewal | 3 | Ea. | 3 | \$6,249 | 1955 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu | aged at entries illding Lighting Replacement | Capital Renewal Capital Renewal | 3 | Ea. | 3 | \$6,249 \$5,410 | 1955 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: | aged at entries illding Lighting Replacement | Capital Renewal Capital Renewal | 3 6 2 | Ea. | 3 | \$6,249 \$5,410 | 1955 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency | aged at entries illding Lighting Replacement | Capital Renewal Capital Renewal Sub Total for System | 3 6 2 | Ea. tems UoM | 3 | \$6,249 \$5,410 \$11,659 | 1955 1956 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency | aged at entries uilding Lighting Replacement Broken on all sides | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance | 3 6 2 Qty | Ea. tems UoM | 3 3 Priority | \$6,249 \$5,410 \$11,659 Repair Cost | 1955 1956 ID |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance | 3 6 2 Qty | Ea. items UoM Ea. | 3 3 Priority | \$6,249 \$5,410 \$11,659 Repair Cost | 1955 1956 ID |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance prove drainage - 9345 GSF Deferred | 3 6 2 Qty 14,308 | Ea. items UoM Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 | 1955 1956 ID 6560 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: CRAWL SPACE DE Note: | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance prove drainage - 9345 GSF Deferred | 3 6 2 Qty 14,308 | Ea. items UoM Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 | 1955 1956 ID 6560 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: CRAWL SPACE DE Note: | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp FICIENCIES - Estimate and Info by AISD SPECIAL FOUNDATIONS - repair perimter - 548 LF | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance brove drainage - 9345 GSF Deferred Maintenance Deferred Maintenance | 3 6 2 Qty 14,308 12,204 | Ea. items UoM Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 \$14,338 | 1955 1956 ID 6560 6561 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp FICIENCIES - Estimate and Info by AISD SPECIAL FOUNDATIONS - repair perimter - 548 LF FICIENCIES - Estimate and Info by AISD | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance brove drainage - 9345 GSF Deferred Maintenance Deferred Maintenance | 3 6 2 Qty 14,308 12,204 | Ea. items UoM Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 \$14,338 | 1955 1956 ID 6560 6561 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE | aged at entries uilding Lighting Replacement Broken on all sides FICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imperior im | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance prove drainage - 9345 GSF Deferred Maintenance Deferred Maintenance | 3 6 2 Qty 14,308 12,204 15,311 | Ea. items UoM Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 \$14,338 | 1955 1956 ID 6560 6561 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE | aged at entries uilding Lighting Replacement Broken on all sides EFICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp EFICIENCIES - Estimate and Info by AISD SPECIAL FOUNDATIONS - repair perimter - 548 LF EFICIENCIES - Estimate and Info by AISD CRAWL SPACE, EXPOSED PIPES - repair rusted pipes - 1 EFICIENCIES - Estimate and Info by AISD | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance prove drainage - 9345 GSF Deferred Maintenance Deferred Maintenance | 3 6 2 Qty 14,308 12,204 15,311 9,345 | Ea. items UoM Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 \$14,338 | 1955 1956 ID 6560 6561 |
| Deficiency Canopy Lighting Re Note: Exterior Mounted Bu Note: Crawlspace Deficiency CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE Note: CRAWL SPACE DE | aged at entries uilding Lighting Replacement Broken on all sides EFICIENCIES - Estimate and Info by AISD SOIL/DRAINAGE BELOW BUILDING - Minor repairs to imp EFICIENCIES - Estimate and Info by AISD SPECIAL FOUNDATIONS - repair perimter - 548 LF EFICIENCIES - Estimate and Info by AISD CRAWL SPACE, EXPOSED PIPES - repair rusted pipes - 1 EFICIENCIES - Estimate and Info by AISD | Capital Renewal Capital Renewal Sub Total for System Category Deferred Maintenance Deferred Maintenance Deferred Maintenance Deferred Maintenance Sub Total for System | Qty 14,308 12,204 15,311 9,345 | Ea. items UoM Ea. Ea. Ea. | 3 3 Priority 5 | \$6,249 \$5,410 \$11,659 Repair Cost \$16,810 \$14,338 \$17,988 | 1955 1956 ID 6560 6561 |



Travis Heights ES - Life Cycle Summary Yrs 1-10 Site Level Life Cycle Items

Site

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|-----------------------|--------------------------------|--------------------------|-------|-------|-------------|----------------|
| Roadway Pavement | Asphalt Driveways | | 2,500 | SF | \$16,076 | 4 |
| Fences and Gates | Fencing - Chain Link (4 Ft) | | 600 | LF | \$28,318 | 5 |
| Fences and Gates | Fencing - Chain Link (8-10 Ft) | | 130 | LF | \$10,185 | 5 |
| Playfield Areas | ES Playgrounds | | 1 | Ea. | \$22,348 | 5 |
| Parking Lot Pavement | Asphalt | | 50 | CAR | \$72,540 | 5 |
| Roadway Pavement | Concrete Driveways | | 1,000 | SF | \$12,484 | 5 |
| Pedestrian Pavement | Sidewalks - Concrete | | 6,300 | SF | \$71,362 | 5 |
| Pedestrian Pavement | Sidewalks - Gravel | | 350 | SF | \$216 | 6 |
| Roadway Pavement | Asphalt Driveways | | 5,000 | SF | \$32,152 | 7 |
| | | Sub Total for System | 9 | items | \$265,681 | |
| Roofing | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Canopy Roofing | Wood Covered Walkways | | 1,400 | SF | \$49,359 | 4 |
| Canopy Roofing | Steel panels | | 700 | SF | \$35,514 | 7 |
| | | Sub Total for System | 2 | items | \$84,873 | |
| | | Sub Total for Building - | 11 | items | \$350,554 | |

Building: 140A - Main building includes Administration Offices, Classrooms, Cafeteria.


Interior

| Uniformat Description | LC Type Description | | ty UoM | Repair Cost | Remaining Life |
|-------------------------------|-----------------------------|----------------------|----------|-------------|----------------|
| Suspended Plaster and | Painted ceilings | 6,0 | 36 SF | \$12,675 | 3 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | 34,4 | 90 SF | \$116,464 | 5 |
| Carpeting | Carpet | 4,0 | 58 SF | \$51,375 | 5 |
| Compartments and Cubicles | Toilet Partitions | | 15 Stall | \$30,247 | 8 |
| | | Sub Total for System | 4 items | \$210,761 | |

| Uniformat Description | | LC Type Description | Qtv | UoM | Repair Cost | Remaining Life |
|---|-------|--|--------|-----|---|----------------|
| Decentralized Cooling | | Fan Coil - D/X Only (3 Ton) | | Ea. | \$47,567 | 4 |
| 3 | Note: | All classrooms have vertical classroom unit ventilators, model VUV in them | | | , | |
| HVAC Air Distribution | | Roof Top Unit - DX Gas (5 Ton) | 1 | Ea. | \$15,909 | 4 |
| | Note: | No tag, roof | | | | |
| Exhaust Air | | Kitchen Exhaust Hoods | 1 | Ea. | \$11,191 | 5 |
| Facility Hydronic Distribution | | Pump - 5HP | 1 | Ea. | \$6,850 | 5 |
| | Note: | PCHWP -1, Near Chiller | | | | |
| Exhaust Air | | Roof Exhaust Fan - Small | 7 | Ea. | \$13,718 | 5 |
| Exhaust Air | | Roof Exhaust Fan - Large | 1 | Ea. | \$8,036 | 5 |
| Exhaust Air | | Wall Exhaust Fan | 25 | Ea. | \$118,284 | 5 |
| HVAC Air Distribution | | Roof Top Unit - DX Gas (5 Ton) | 4 | Ea. | \$63,637 | 5 |
| Heat Generation | | Boiler - Cast Iron - Water (1275 MBH) | 1 | Ea. | \$41,601 | 8 |
| Heating System Supplementary Components | | Controls - Electronic (Bldg.SF) | 40,576 | SF | \$62,785 | 8 |
| Decentralized Cooling | | Condenser - Inside Air Cooled (3 ton) | 2 | Ea. | \$12,845 | 8 |
| Decentralized Cooling | | Ductless Split System (2 Ton) | 1 | Ea. | \$4,747 | 8 |
| Decentralized Cooling | | Heat Pump (3 Ton) | 2 | Ea. | \$17,815 | 8 |
| Other HVAC Distribution Systems | | VFD (5 HP) | 2 | Ea. | \$8,786 | 8 |
| Other HVAC Distribution Systems | | VFD (25 HP) | 2 | Ea. | \$21,249 | 8 |
| Facility Hydronic Distribution | | Pump - 5HP | 2 | Ea. | \$13,700 | 8 |
| | Note: | SHWP - 1,2, Boiler Room | | | | |
| Decentralized Cooling | | Ductless Split System (2 Ton) | 1 | Ea. | \$4,747 | 8 |
| Other HVAC Distribution Systems | | VFD (5 HP) | 2 | Ea. | \$8,786 | 8 |
| Facility Hydronic Distribution | | Pump- 10HP (Ea.) | 2 | Ea. | \$23,121 | 8 |
| | Note: | SHWP- 1, 2 Boiler Room | | | | |
| HVAC Air Distribution | | Roof Top Unit - DX Gas (10 Ton) | 1 | Ea. | \$24,236 | 8 |
| | Note: | No Tag, roof | | | | |

M•A•P•P•S ©, Jacobs 2022 12







Mechanical

| moonamoar | | | | | | |
|--------------------------------|---|----------------------------------|--------|-------|---------------------|----------------|
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Facility Hydronic Distribution | 4-Pipe System | | 40,576 | SF | \$98,181 | 10 |
| | | Sub Total for System | 21 | items | \$627,792 | |
| Electrical | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Audio-Video Systems | PA Communications No Head Unit (Bldg SF) | | 40,576 | SF | \$28,723 | 4 |
| Distributed Systems | Public Address System Head End Unit | | 1 | Ea. | \$7,307 | 4 |
| Power Distribution | Panelboard - 120/208 225A | | 4 | Ea. | \$21,998 | 4 |
| Not | e: estimated - no information, or blocked panels (NP2, | 4P, L, 3P) | | | | |
| Power Distribution | Panelboard - 120/208 400A | | 3 | Ea. | \$37,025 | 5 |
| Lighting Fixtures | Canopy Mounted Fixtures (Ea.) | | 3 | Ea. | \$6,249 | 5 |
| Lighting Fixtures | Light Fixtures (Bldg SF) | | 40,576 | SF | \$744,105 | 5 |
| Not | e: Lighting within classroom is dim, which appears to b | pe from deeply yellowing diffuse | rs | | | |
| Power Distribution | Panelboard - 120/208 100A | | 1 | Ea. | \$2,782 | 8 |
| Power Distribution | Distribution Panels (600 Amps) | | 1 | Ea. | \$17,802 | 10 |
| Not | e: SDSB 600 amp blocked by storage - not reviewed g | ground floor electrical room 32 | | | | |
| Power Distribution | Power Wiring | | 40,576 | SF | \$48,192 | 10 |
| | | Sub Total for System | 9 | items | \$914,182 | |
| Plumbing | | | | | | |
| Uniformat Description | LC Type Description | | Ot- | UoM | Ponsir Cost | Remaining Life |
| <u> </u> | LC Type Description | | | | <u> </u> | |
| Domestic Water Equipment | Water Heater - Electric - 120 gallon | | | Ea. | \$5,719 \$50,759 | 5 |
| Plumbing Fixtures | Restroom Lavatory | | | Ea. | \$59,758 | 5 |
| Plumbing Fixtures | Sink - Service / Mop Sink | | | Ea. | \$3,184 | 5 |
| Plumbing Fixtures | Toilets | | | Ea. | \$166,960 | 5 |
| Plumbing Fixtures | Urinals | | | Ea. | \$8,125 | 5 |
| Plumbing Fixtures | Non-Refrigerated Drinking Fountain | | | Ea. | \$54,827 | 5 |
| Domestic Water Equipment | Water Heater - Instant 3.2 GPM | | | Ea. | \$4,214 | 8 |
| Plumbing Fixtures | Classroom Lavatory | | | Ea. | \$69,241 | 10 |
| | | Sub Total for System | 8 | items | \$372,028 | |
| Fire and Life Safety | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Fire Detection and Alarm | Fire Alarm | | 40,576 | SF | \$64,427 | 3 |
| Fire Detection and Alarm | Fire Alarm Panel | | 1 | Ea. | \$6,868 | 3 |
| Security System Component | Security Alarm System | | 40,576 | SF | \$93,395 | 4 |
| Water-Based Fire-Suppression | Fire Pump | | 1 | Ea. | \$49,294 | 8 |
| | | Sub Total for System | 4 | items | \$213,984 | |
| Specialties | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Casework | Fixed Cabinetry | | | Room | \$158,434 | 2 |
| | • | Sub Total for System | 1 | items | \$158,434 | |
| Sub Total for Building | 140A - Main building includes Administration Offic | • | | items | \$2,497,181 | |
| Building: 140B - Stand- | _ | , | | | 4 =,, | |
| • | Alone Gym | | | | | |
| Exterior | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Exterior Operating Windows | Aluminum - Windows per SF | | 14 | SF | \$1,396 | 5 |
| | | Sub Total for System | 1 | items | \$1,396 | |
| Interior | | | | | | |
| Uniformat Description | LC Type Description | | Otv | UoM | Renair Cost | Remaining Life |
| Resilient Flooring | Vinyl Composition Tile Flooring | | 4,048 | | \$33,103 | 4 |
| Compartments and Cubicles | Toilet Partitions | | | Stall | \$8,066 | 5 |
| Suspended Plaster and | | | 1,012 | | | 5 |
| | Painted ceilings | | | | \$2,108 \$13,660 | 8 |
| Acoustical Suspended Ceilings | Ceilings - Acoustical Tiles | Sub Total for System | 4,048 | | \$13,669 | 8 |
| Machanical | | Sub Total for System | 4 | items | \$56,946 | |
| Mechanical | | | | | _ | |
| Uniformat Description | LC Type Description | | | UoM | | Remaining Life |
| Decentralized Cooling | Condenser - Outside Air Cooled (3 Tons) | | | Ea. | \$32,113 | 5 |
| Decentralized Cooling | Heat Pump (1 Ton) | | 5 | Ea. | \$36,792 | 5 |
| | | | | | | |



Repair Cost Remaining Life

5

5

5

\$2,716

\$796

\$65,772

Qty UoM

1 Ea.

1 Ea.

13 Ea.





| | | ca |
|--|--|----|
| | | |
| | | |

PlumbingUniformat Description

Plumbing Fixtures

Plumbing Fixtures

Plumbing Fixtures

LC Type Description

Restroom Lavatory

Toilets

Sink - Service / Mop Sink

| Mechanicai | | | | | | | |
|--|-------|--|---|---|---|--|--|
| Uniformat Description | | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| HVAC Air Distribution | | VAV Boxes / Terminal Device | | 5 | Ea. | \$19,369 | 5 |
| Decentralized Cooling | | Condenser - Outside Air Cooled (3 Tons) | | 5 | Ea. | \$32,113 | 5 |
| Decentralized Cooling | | Heat Pump (1 Ton) | | 5 | Ea. | \$36,792 | 5 |
| | Note: | GF-1. GF-2, GF-5 in AHU 1 Room in Mezz, GF-4, C | GF-5 in AHUU 2 room on Mezz | | | | |
| Heating System Supplementary Components | | Controls - Electronic (Bldg.SF) | | 5,060 | SF | \$7,830 | 8 |
| Facility Hydronic Distribution | | 4-Pipe System | | 5,060 | SF | \$12,244 | 10 |
| Exhaust Air | | Wall Exhaust Fan | | 2 | Ea. | \$9,463 | 10 |
| | | | Sub Total for System | 8 | items | \$186,715 | |
| Electrical | | | | | | | |
| | | LO Toma Decembring | | 01: | I I - M | D i O t | Daniela a Life |
| Uniformat Description | | LC Type Description | | | UoM | <u>.</u> | Remaining Life |
| Audio-Video Systems | | PA Communications No Head Unit (Bldg SF) | | 5,060 | | \$3,582 | 4 |
| Lighting Fixtures | | Light Fixtures (Bldg SF) | | 5,060 | | \$92,793 | 5 |
| Power Distribution | | Power Wiring | | 5,060 | | \$6,010 | 10 |
| | | | Sub Total for System | 3 | items | \$102,385 | |
| Plumbing | | | | | | | |
| Uniformat Description | | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Plumbing Fixtures | | Non-Refrigerated Drinking Fountain | | 1 | Ea. | \$2,384 | 8 |
| | | | Sub Total for System | 1 | items | \$2,384 | |
| Fire and Life Safety | , | | | | | | |
| | | | | | | | |
| Uniformat Description | | LC Type Description | | | UoM | | Remaining Life |
| Fire Detection and Alarm | | Fire Alarm | | 5,060 | | \$8,034 | 3 |
| Fire Detection and Alarm | | Fire Alarm Panel | | | Ea. | \$6,868 | 3 |
| | | | | 5,060 | CE. | \$11,647 | 4 |
| Security System Component | | Security Alarm System | | 3,000 | SF | Ψ11,0-11 | |
| Security System Component Water-Based Fire-Suppression | | Security Alarm System Fire Sprinkler System (Bldg.SF) | | 5,060 | | \$52,715 | 8 |
| Water-Based Fire-Suppression | and-A | Fire Sprinkler System (Bldg.SF) | Sub Total for System ng 140B - Stand-Alone Gym | 5,060 4 | | | 8 |
| Water-Based Fire-Suppression | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Buildin | | 5,060 4 | SF items | \$52,715 \$79,264 | 8 |
| Water-Based Fire-Suppression Building: 140C - Sta | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Buildin | | 5,060 4 21 | SF items | \$52,715 \$79,264 \$429,090 | |
| Water-Based Fire-Suppression Building: 140C - Sta | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building | | 5,060 4 21 | SF items items | \$52,715 \$79,264 \$429,090 | |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description | | 5,060 4 21 | SF items items | \$52,715 \$79,264 \$429,090 Repair Cost | Remaining Life |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles | | 5,060 4 21 Qty 9,421 | SF items items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 | Remaining Life |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System | | 5,060 4 21 Qty 9,421 9,421 8,950 | SF items items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 | Remaining Life 5 5 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System | ng 140B - Stand-Alone Gym | 5,060 4 21 Qty 9,421 9,421 8,950 | SF items UoM SF SF SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 | Remaining Life 5 5 |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical | and-A | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) | ng 140B - Stand-Alone Gym | 5,060 4 21 Qty 9,421 9,421 8,950 3 | SF items UoM SF SF SF items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 | Remaining Life 5 5 7 |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description | and-A | Sub Total for Building Ione Classroom Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description | ng 140B - Stand-Alone Gym | 5,060 4 21 Qty 9,421 9,421 8,950 3 | SF items UoM SF SF SF items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost | Remaining Life 5 5 7 Remaining Life |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical | | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty | SF items UoM SF SF SF items UoM Ea. | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 | Remaining Life 5 5 7 |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling | | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (tage) | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Oty 9,421 9,421 8,950 3 Oty 11 ery classror | UoM SF SF items UoM Ea. | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 | Remaining Life 5 5 7 Remaining Life |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary | | Fire Sprinkler System (Bldg.SF) Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Oty 9,421 9,421 8,950 3 Oty 11 ery classror | UoM SF SF items UoM Ea. | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost | Remaining Life 5 5 7 Remaining Life |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classrc 10 9,420 | UoM SF SF SF items UoM Ea. SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 | Remaining Life 5 5 7 Remaining Life 4 5 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (tat VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classro 10 9,420 | UoM SF SF SF items UoM Ea. Oom Ea. SF SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 | Remaining Life 5 5 7 Remaining Life 4 5 8 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) | Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classro 10 9,420 9,420 2 | UoM SF SF SF items UoM Ea. SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 | Remaining Life 5 5 7 Remaining Life 4 5 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (tat VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System | ng 140B - Stand-Alone Gym Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classro 10 9,420 9,420 2 | UoM SF SF SF items UoM Ea. Oom Ea. SF SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 | Remaining Life 5 5 7 Remaining Life 4 5 8 |
| Water-Based Fire-Suppression Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (tat VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System | Sub Total for System | 5,060 4 21 Oty 9,421 9,421 8,950 3 Oty 11 ery classrc 10 9,420 9,420 2 5 | UoM SF SF SF items UoM Ea. SF | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 |
| Water-Based Fire-Suppression Building: 140C - State Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan | Sub Total for System | 5,060 4 21 Oty 9,421 9,421 8,950 3 Oty 11 ery classrc 10 9,420 9,420 2 5 | UoM SF SF items UoM Ea. SF SF SF items UoM UoM UoM UoM UoM | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 |
| Water-Based Fire-Suppression Building: 140C - State Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical Uniformat Description | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan | Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classrc 10 9,420 9,420 2 5 Qty 9,420 9,420 | UoM SF SF items UoM Ea. SF SF SF items UoM UoM UoM UoM UoM UoM | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 Repair Cost | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 Remaining Life |
| Water-Based Fire-Suppression Building: 140C - State Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical Uniformat Description Audio-Video Systems | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) | Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classrc 10 9,420 9,420 2 5 Qty 9,420 1 | UoM SF SF items UoM Ea. SF SF Ea. items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 Repair Cost \$6,668 \$17,802 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 10 Remaining Life 4 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Power Distribution Power Distribution | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Distribution Panels (600 Amps) Panelboard - 120/208 225A | Sub Total for System | 5,060 4 21 Otty 9,421 9,421 8,950 3 Otty 11 ery classro 10 9,420 9,420 2 5 Otty 9,420 1 1 1 | UoM SF SF items UoM Ea. Oom Ea. SF SF Ea. items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 Repair Cost \$6,668 \$17,802 \$5,500 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 10 Remaining Life 4 5 5 5 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Power Distribution Lighting Fixtures | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Distribution Panels (600 Amps) Panelboard - 120/208 225A Light Fixtures (Bldg SF) | Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classro 10 9,420 9,420 2 5 Qty 9,420 1 1 9,420 | UoM SF SF items UoM Ea. oom Ea. items UoM SF Ea. items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 Repair Cost \$6,668 \$17,802 \$5,500 \$172,749 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 10 Remaining Life 4 5 5 5 5 |
| Building: 140C - Sta Interior Uniformat Description Acoustical Suspended Ceilings Acoustical Suspended Ceilings Wall Painting and Coating Mechanical Uniformat Description Decentralized Cooling HVAC Air Distribution Heating System Supplementary Components Facility Hydronic Distribution Exhaust Air Electrical Uniformat Description Audio-Video Systems Power Distribution Power Distribution Power Distribution | | Sub Total for Building LC Type Description Ceilings - Acoustical Tiles Ceilings - Acoustical Tiles Ceilings - Acoustical Grid System Painting/Staining (Bldg SF) LC Type Description Fan Coil - D/X Only (3 Ton) Vertical classroom unit ventilators modeled VUV (ta VAV Boxes / Terminal Device Controls - Electronic (Bldg.SF) 4-Pipe System Wall Exhaust Fan LC Type Description PA Communications No Head Unit (Bldg SF) Distribution Panels (600 Amps) Panelboard - 120/208 225A | Sub Total for System | 5,060 4 21 Qty 9,421 9,421 8,950 3 Qty 11 ery classro 10 9,420 9,420 2 5 Qty 9,420 1 1 9,420 | UoM SF SF items UoM Ea. OOM Ea. Items UoM SF Ea. SF Ea. Items | \$52,715 \$79,264 \$429,090 Repair Cost \$31,812 \$39,231 \$40,104 \$111,148 Repair Cost \$22,749 \$38,739 \$14,576 \$22,793 \$9,463 \$108,320 Repair Cost \$6,668 \$17,802 \$5,500 | Remaining Life 5 5 7 Remaining Life 4 5 8 10 10 10 Remaining Life 4 5 5 5 |





Austin ISD - Travis Heights ES

Plumbing

| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
|---------------------------|------------------------------------|--------------------------------|-------|-------|-------------|----------------|
| Plumbing Fixtures | Non-Refrigerated Drinking Fountain | | 14 | Ea. | \$33,373 | 8 |
| Plumbing Fixtures | Classroom Lavatory | | 15 | Ea. | \$38,467 | 10 |
| | | Sub Total for System | 5 | items | \$141,124 | |
| Fire and Life Safety | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Fire Detection and Alarm | Fire Alarm | | 9,420 | SF | \$14,957 | 3 |
| Fire Detection and Alarm | Fire Alarm Panel | | 1 | Ea. | \$6,868 | 3 |
| Security System Component | Security Alarm System | | 9,420 | SF | \$21,682 | 4 |
| | | Sub Total for System | 3 | items | \$43,507 | |
| Specialties | | | | | | |
| Uniformat Description | LC Type Description | | Qty | UoM | Repair Cost | Remaining Life |
| Casework | Fixed Cabinetry | | 8 | Room | \$70,415 | 6 |
| | | Sub Total for System | 1 | items | \$70,415 | |
| | Sub Total for Building 140C - | Stand-Alone Classroom Building | 23 | items | \$689,881 | |
| | | Total for: Travis Heights ES | 102 | items | \$3,966,706 | |



Supporting Photos

General Site Photos



Cracked sidewalk



Damaged asphalt

M*A*P*P*S ©, Jacobs 2022