



Educational Suitability Summary Report

St. Elmo Elementary School

Date: 07/22/2016 (Rev 1 – 11/14/2016 : CAC Comments)

Score 58% Average

St. Elmo Elementary School, serving a student population of approximately 290 students, is located south of downtown Austin. The school features Pre-K through 5th grade, and 90% of the students come from low income families. Principal Gonzales was largely satisfied with the programs at her campus, but expressed dissatisfaction with office and meeting space, storage, access to instructional technology, and difficulty with funding her small, but well-performing school.

Survey Overview

Survey results from the principal, Mrs. Gonzales, give a satisfactory level of educational suitability for most major spaces, including the library, classrooms, common spaces, and playgrounds. However, the administration and counselor offices, storage, and condition of classroom built-ins and equipment received unsatisfactory scores. The boys' restroom off of the cafeteria is noted as having a recurring rodent issue, and the gym is reported to have a recurring moldy smell. The survey results identify the desire for additional tablets, laptops, and charging stations for technology.

Interview Overview

The interview at St. Elmo Elementary school was attended by the school principal, Mrs. Adriana Gonzales. The conversations with Mrs. Gonzales indicated that she is satisfied with most of the spaces on the campus. The main issues reported were the lack of storage and the need for new technology throughout the campus. The office space and meeting space in the building is also inadequate. Additionally, she expressed dissatisfaction with the difficulty in obtaining sufficient funding for her campus due to their higher performance but smaller size. She envisions the future of education will be dependent on increasing student access to technology as well as providing adequate technological training for parents. She reports that this campus is a community landmark; however, there are no specific features that are untouchable in the event of future renovations.

The CAC expressed that the technology in the school is nearing end-of-life, and that the District needs to refresh technology at this campus as soon as possible. In addition, the CAC expressed that the surface on one of the campus playgrounds is wearing away, creating a slipping hazard for both parents and students. The stage on campus now has ADA access due to upgrades completed this summer associated with the 2013 bond program. They also expressed concerns about erosion and sidewalk conditions which is addressed in the FCA.

Assessment Findings

The Educational Suitability Assessment of St. Elmo Elementary School earned a 58% overall score and places the campus in a category of average. The assessment consists of 11 categories to determine

PERKINS+WILL

Educational Suitability Summary Report

St. Elmo Elementary School

areas that need more attention.

Lower Scoring Categories: Unsatisfactory Categories

Future Ready Student Development

The score is unsatisfactory.

The campus does not feature hands-on learning spaces or adequate support for such projects. The casework in classrooms is very limited and is in older condition. The meeting space is limited and currently the speech classroom is a converted custodian closet. The facility lacks consistent visual communication tools across classrooms. Some upper grade levels have innovation stations, but lower grade levels lack this technology.

Exterior

The score is unsatisfactory.

The bus loop at the front of the school is narrow, and there is a small area for parking and dropoff. Courtyards are present, but they are not being used for outdoor learning spaces. The playground has a variety of equipment and a shaded basketball area. However, these areas could use some updates. The building has some signage that needs improvement.

Controllability of Systems

The score is unsatisfactory.

The classrooms do not have functional individual thermal controls or adequate artificial lighting controls. However, the classrooms do have blinds for controlling natural light.

Storage

The score is unsatisfactory.

The general building storage is inadequate. The bookrooms are undersized and the classroom storage is limited to small, outdated built-in cabinets that are not sufficient. Student storage is accommodated by the new furniture.

Higher Scoring Categories: Average, Good, and Excellent Categories

Academic & Co-Curricular Support

The score is average.

Restrooms are being upgraded in the classroom spaces that had outdated restroom facilities. The Pre-K and Kindergarten area does not feature a separate play area, but otherwise the classrooms are well-sized and configured. Athletic spaces are lacking adequate storage support. The music room is currently in a portable, while the art room is a converted classroom. The principal expressed that there is not an acoustically appropriate room for music in the building, which is why it was placed in the portable. Both the music and art spaces lack sufficient storage. The special education spaces have adequate classroom space but undersized storage and some outdated equipment. The principal expressed that she would like to clarify that they currently do not have a current need for a life skills classroom. The cafeteria is a moderate size, but is sufficient for the current needs of the campus. The stage in the cafeteria is worn and needs updates. There is no separate storage for the stage. Upgrades this

PERKINS+WILL

Educational Suitability Summary Report

St. Elmo Elementary School

summer have added ADA access to the stage.

General Building

The score is average.

The cafeteria and library are accessible from the main hallway and can be secured from the rest of the building for community functions. The general appearance of the school is good despite some older finishes. The hallways are well-sized but feature louvers to the classrooms, which can allow for some sound transmission. The principal expressed that this is more a fire safety concern for her than an acoustic concern.

Environmental Quality

The score is good.

The quality of the artificial lighting is appropriate for classroom functions, while the acoustics are inadequate as sounds are heard from the corridor through louvers. All of the learning spaces have exterior views and ample natural light. However, some pest issues in the form of rats and roaches are reported by school administration.

Security

The score is good.

The location of the central office does not create a secure vestibule for the campus; however it is located at the front entry. Key card access is at all major entries, and the interior transparency is very good for faculty supervision within the school. Site lighting around the campus is unsatisfactory and needs upgrades.

Library/Media Center

The score is good.

The library has space and flexibility for collaborative work of different group sizes. The library needs more large group collaboration space and upgraded technology. The principal expressed she would rather see technology in the form of COWs in the classrooms than in the library.

Technology

The score is good.

There is an adequate number of power outlets and data ports in learning spaces which raises this category score. However, there is a mix of older and newer technology in the form of projectors and some innovation stations. Older grades are equipped with innovation stations while younger grades do not have this classroom technology. The CAC comments that all campus technology is approaching end-of-life, and that the District will need to refresh the technology as soon as possible.

Furniture, Fixtures & Equipment

The score is excellent.

The campus recently received all new furniture. This furniture is satisfactory for flexible configurations and is ergonomic. However, the built-in casework is not very tall and the whiteboards are at a lower elevation than is typical.

Educational Suitability Summary Report

St. Elmo Elementary School



Very Unsatisfactory

PERKINS + WILL

44%

Austin ISD Educational Suitability Assessment Criteria Overall Educational Suitability Score 58% St. Elmo Elementary School BLDG - 136 School 1 - Exterior 42% Ellen Saathoff & Sam Shipp Name 2 - General Building 60% 3 - Academic & Co-Curricular Support 53% 7/19/2016 (Rev 1 - 11/14 - Principal & CAC Comments) 4 - Future Ready Student Development 40% Date 5 - Library/Media Center 71% **Scoring Scale** 69% 6 - Security 81%-100% Excellent 7 - Technology 70% 66%-80% Good 8 - Storage 47% 51%-65% 9 - Furniture, Fixtures & Equipment 93% Average 36%-50% 10 - Environmental Quality 76% Unsatisfactory

11 - Controllability of Systems

1 - Exterior	1	2	3	4	5	N/A			6.7
1.1 Does the site permit desirable separation of vehicular, bus and pedestrian traffic?		2					Comments	1.00	2.00
1) Bus , car and pedestrian all happen at the same location.							The bus loop is narrow at the entrance of the school.		
2) Cars and buses mix, pedestrians are separated.									
 Buses, cars, and pedestrians are separate but stack space is small. 									
 Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria. 									
5) Buses, cars, and pedestrians are separate and drop off area has a canopy and destination. N/A) Does not apply.									
Are opportunities provided for outdoor learning (outdoor classrooms, gardens, etc.)?	1						Comments	1.00	1.00
1) Outdoor space exists is not developed 2)Outdoor space for learning exists but not connected to classroom learning areas. 3. Outdoor learning spaces exist and are accessible but not in good condition. 4. Outdoor learning spaces need minor improvements to function well. 5. Outdoor learning spaces are in excellent condition.							There are courtyards present, but they are not being utilized classrooms/learning spaces.	as outdoor	
N/A) Does not apply.									
Are outdoor play spaces and playfields adequate in size and configuration?			3				Comments	1.00	3.00
1) Outdoor play space exists, not developed							The playground equipment is worn and does not have adequ	uate shade.	
2)Outdoor play space exists but is not connected to gym or other athletic support areas or is too small.									
 Outdoor play spaces exist, are connected to other athletic areas, are the right size, but are not in good condition. Outdoor play spaces need minor improvements to function well. 									
Outdoor play spaces are in excellent condition.									
N/A) Does not apply.									
1.4 Is the building easily identified with appropriate signage and community wayfinding?			3				Comments	0.25	0.75
1) Campus has no signage and no striping.2) Signage is faded/hidden.							The signage could be more clear.		
3) Signage & striping visible but not apparent.									
4) Signage is visible but not good condition.									
5. Signage and wayfinding is visible and easy to use.									
N/A) Does not apply.									

2 - General Building	1	2	3	4	5	N/A			4.50
2.1 Are interior circulation routes wide enough to safely and effectively accommodate student movement?			3				Comments	0.50	1.50
1) Primary circulation is 5'-0" to 6'-0" wide.		-		-			The interior circulation is sufficient, but the acoustics are ur	•	
2) Primary circulation is 6'-0" to 7'-0" wide							hallways due to louvers to the classrooms. The wood paneli	ng also makes sor	ne
3) Primary circulation is 7'-0" to 8'-0" wide							corridors appear dark.		
4) Primary circulation is 8'-0"-10'-0" wide									
5) Primary circulation is 10'-0"+ wide									
N/A) Does not apply.									
2.2 Are community use areas arranged so that the school can allow night functions without full school access?			3				Comments	0.75	2.25
 Cafeteria, gym, and library cannot be accessed from parking area or secured from the rest of campus. 							The library and cafeteria are accessible from the main entry secured from the rest of the building. The gym is far remove the school.	• •	
 Only one of the public spaces (Cafeteria, Gym an Library) can be accessed from parking and secured from the rest of the building. 	d								
 3) Only two of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured from the rest of the building. 4) All of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured from the rest of the building but do not have individual entrances. 	i								
5) Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance.									
N/A) Does not apply.									
2.3 Does the general appearance of the school evoke pride for the students and community?			3				Comments	0.25	0.75
1) General appearance is poor.							The appearance in and around the school is good despite so	ome older finishes	. The
2) General appearance is aged but ok.							school has plenty of display areas for student work.		
3) General appearance is good.									
4) General appearance shows pride in campus and student works.									
5) General appearance shows pride in campus and student works and is welcoming to the community.									
N/A) Does not apply.									

	- Academic & Co-Curricular Support	1	2	3	4	5	N/A			29.00
	Are Pre-K and Kinder classrooms appropriately configured per the ed				4			Comments		
	spec? (elementary school only)				Ľ			Comments	1.00	4.00
	 Very unsatisfactory - Too small, awkward layout, does not meet needs Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility Neutral - Moderate size, two areas for different teaching methods, some flexibility, access to student storage/casework Satisfactory - Good size, at least two zones for different teaching methods, flexibility and student storage, not new Very Satisfactory - Good size, two zones for different teaching methods, flexibility and student 									
	storage/casework, adequate display area and visual teaching tools									
	N/A) Does not apply.									
	Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? (elementary only)				4			Comments	1.00	4.00
	1) Very unsatisfactory - No storage, casework, or restrooms 2) Unsatisfactory - unsatisfactory size or condition of storage, casework, or restrooms 3) Neutral - Moderate size or moderate condition storage, casework, and restrooms 4) Satisfactory - Satisfies ed spec for storage, casework, and restrooms 5) Very Satisfactory - exceeds ed spec for storage, casework, and restrooms							Principal Comment: Outdated restrooms were upgraded in c as a result of the 2013 bond program.	lassrooms this su	mmer
	N/A) Does not apply. 3.4 Are Science Classrooms/Labs appropriately configured per the ed spec?						N/A	Comments	0.00	0.00
L	 Very unsatisfactory Unsatisfactory Neutral Satisfactory Very Satisfactory N/A) Does not apply. (Elementary schools) 								0.00	0.00
	3.5 Are Science Classrooms/Labs support areas appropriately configured per the ed spec?						N/A	Comments	0.00	0.00
	1) Very unsatisfactory - Support spaces are disconnected from served spaces, too small, do not meet needs 2) Unsatisfactory - Support spaces are connected, but too small, do not meet needs 3) Average - Connected, moderate size, but need some renovations or updates 4) Good - Connected, good size, meets needs, functions well 5) Very good - connected, generous size, nice condition, functions appropriately N/A) Does not apply. (Elementary schools)			•						

3 -	Academic & Co-Curricular Support - Continued	1	2	3	4	5	N/A			
3	Are Physical Education and Athletic spaces appropriately configured per the ed spec?				4			Comments	1.00	4.00
	Very unsatisfactory Unsatisfactory							The gym is lacking natural light, but is ADA compliant. The athle access to the outdoor spaces.	etic spaces do	have
	3) Average 4) Good									
	5) Very good									
	N/A) Does not apply.									
3	configured per the ed spec?		2					Comments	1.00	2.00
	1) Very unsatisfactory - Support spaces are disconnected from served spaces, too small, do not meet needs 2) Unsatisfactory - Support spaces are connected, but too small, inadequate for needs 3) Average - Connected, moderate size, but need some renovations or updates to function well 4) Good - Connected, good size/layout, meets needs/functions well 5) Very good - connected, generous size, nice condition, functions appropriately N/A) Does not apply.							The storage spaces are unacceptable, with little to no storage.		
3	Are music, drama, or performance spaces appropriately configured per the ed spec?		2					Comments	1.00	2.00
	 Very unsatisfactory Unsatisfactory Average Good Very good N/A) Does not apply. 			•			,	The music classroom is in a portable. The stage is showing signs usable storage.	s of wear and l	
3	.9 Are music, drama, or performance support spaces appropriately configured per the ed spec?	1						Comments	1.00	1.00
	1) Very unsatisfactory - Support spaces are disconnected from served spaces, too small, do not meet needs 2) Unsatisfactory - Support spaces are connected, but too small, inadequate for needs 3) Average - Connected, moderate size, but need some renovations or updates to function well 4) Good - Connected, good size/layout, meets needs/functions well 5) Very good - connected, generous size, nice condition, functions appropriately N/A) Does not apply.							There is no stage storage and no ADA access to the stage. CAC/ADA access to the stage has been added as a result of the 2013		

3 - Academic & Co-Curricular Support - Continued		1	2	3	4	5	N/A			
3.10 Are Visual Arts spaces appropriately configured per the ed sp	ec?			3				Comments	1.00	3.00
 Very unsatisfactory Unsatisfactory Average Good Very good N/A) Does not apply. 								There is no art room, currently a normal classroom has bee room.	n repurposed as	the art
3.11 Are Visual Arts support spaces appropriately configured per to spec?	the ed	1		Π	Τ		Τ	Comments	1.00	1.00
1) Very unsatisfactory - Support spaces a disconnected from served spaces, too sm meet needs 2) Unsatisfactory - Support spaces are concept but too small, inadequate for needs 3) Average - Connected, moderate size, but some renovations or updates to function 4) Good - Connected, good size/layout, maneeds/functions well 5) Very good - connected, generous size, condition, functions appropriately N/A) Does not apply.	onnected, out need well neets							The kiln is down the hall from the visual arts space.		
3.12 Are computer lab spaces appropriately configured?			Ι	T	Τ	Π	N/A	Comments	0.00	0.00
 Very unsatisfactory Unsatisfactory Average Good Very good 				•	•	•	•	Ther is no dedicated computer lab. The principal states that COWs.	the school prefe	
N/A) Does not apply.										
3.13 Are computer lab support spaces appropriately configured? 1) Very unsatisfactory - Support spaces a disconnected from served spaces, too small meet needs 2) Unsatisfactory - Support spaces are constant.	nall, do not						N/A	See 3.12	0.00	0.00
but too small, inadequate for needs 3) Average - Connected, moderate size, be some renovations or updates to function 4) Good - Connected, good size/layout, needs/functions well 5) Very good - connected, generous size, condition, functions appropriately N/A) Does not apply.	well neets									

3 - Academic & Co-Curricula	r Support - Continued	1	2	3	4	5	N/A			
3.14 Are Special Education space	ces appropriately configured per the ed spec?			3				Comments	1.00	3.00
1) Ve	ry unsatisfactory							The special education spaces have dedicated classroom, but	the equipment is	s
2) Un	satisfactory							inadequate.		
3) Ave	erage									
4) God	od									
5) Ver	y good									
N/A) [Does not apply.									
3.15 Are Special Education sup ed spec?	port spaces appropriately configured per the		2					Comments	1.00	2.00
discor meet 2) Un but to 3) Ave some 4) Goo needs 5) Ver condit	ry unsatisfactory - Support spaces are nnected from served spaces, too small, do not needs satisfactory - Support spaces are connected, so small, inadequate for needs erage - Connected, moderate size, but need renovations or updates to function well od - Connected, good size/layout, meets s/functions well ry good - connected, generous size, nice tion, functions appropriately Does not apply.							There is not an adequate changing area and equipment stora inadequate. Principal Comment: The principal expressed that that their campus does not have a current need for a life skills there is no such unit at this campus.	she wanted to c	• •
3.16 Are the student dining fac				3				Comments	1.00	3.00
inflexi 2) Un circula 3) Ave circula 4) Goo good 0 5) Ver seatin optior	ry unsatisfactory - Too small, poor circulation, ible seating in poor condition satisfactory - Too small or inadequate ation, seating in poor condition erage - moderate size, with adequate ation, seating in okay condition od - good size, adequate circulation, seating in condition ry good - good size, adequate circulation, ag in good condition, with more than one in for eating space (ex: connection to outdoor g space)							The dining facilities are small but adequate. The school enrol the needs for the current number of students.	Ilment is low, so	it suits

I - Future Ready Student Development	1	2	3	4	5	N/A			16.0
4.1 Does the facility provide specialized space and opportunities for hands- on project-based learning?	1						Comments	1.00	1.0
Very unsatisfactory - No project space Unsatisfactory - Non-dedicated, undersized or				!	ļ		There is no space available for hands-on learning.		
otherwise inadequate 3) Average - Limited dedicated spaces of moderate									
size and layout, equipment and furniture									
appropriate but need updates 4) Good - Dedicated spaces of adequate size and									
layout, most of the equipment and furniture is									
appropriate for program 5) Very good - Dedicated spaces of adequate size									
and layout, equipment and furniture appropriate for									
program N/A) Does not apply.									
4.2 Are general classrooms large enough to support project-based learning		2					Comments		
and multiple teaching modalities?							Comments	1.00	2.0
1) Very unsatisfactory -too small to move, set for							The classrooms are too small to promote project-based lear	ning or multiple	
lecture only, no connectivity, no flexibility 2) Unsatisfactory - adequate size but set for lecture							teaching modalities.		
only, no connectivity, no flexibility 3) Neutral - have flexibility and space for hands on or									
project based learning									
 Satisfactory - have flexibility and space for hands on or project based learning and connectivity for 									
global learning 5) Very Satisfactory - space for hands on learning,									
flexibility for different groupings, and connectivity									
for global classrooms									
N/A) Does not apply.									
4.3 Is there adequate storage and or support space to support project-based learning?		2					Comments	1.00	2.0
1) Very unsatisfactory - none			•		•	•	The casework is limited and outdated.		
2) Unsatisfactory-minimal support									
3) Average - moderately sized casework									
4) Good - large casework/cabinets/support									
5) Very good - walk-in storage/ample support space									
N/A) Does not apply.									
4.4 Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?				4			Comments	1.00	4.0
1) Very unsatisfactory - No display cases or wall			•						
space for display									
2) Unsatisfactory - 1 wall in classrooms or very few									
spaces for display 3) Average - 2 walls in classrooms or some hallway									
spaces for display									
4) Good - 3 walls in classrooms or multiple hallway spaces for display									
5) Very good - ample classroom display space or									
many hallway spaces, including display cases									

4 - Future Ready Student Development - Continued	1	2	3	4	5	N/A			
4.5 Does the building provide adequate opportunities for students/teachers to collaborate in varying group sizes?		2					Comments	1.00	2.00
1) Very unsatisfactory - no common spaces or meeting rooms or in very poor condition 2) Unsatisfactory - a few common spaces or meeting rooms in unsatisfactory condition 3) Average - a few common spaces and meeting areas needing updates 4) Good - multiple common spaces and meeting rooms in good condition 5) Very good - adequate common spaces and meeting rooms of excellent quality N/A) Does not apply.			•			•	Available meeting space is limited. The speech classroom is closet.	in a converted cu	ıstodian
4.6 Does the building provide opportunities for informal interaction?		2					Comments	1.00	2.00
 Very unsatisfactory - no gathering areas or areas in very poor condition Unsatisfactory - one exterior or interior common space with no seating or unsatisfactory condition Average - one exterior or interior common space with seating needing updates Good - 2 exterior or interior common spaces with appropriate seating/good condition Very good - multiple exterior and interior commons spaces with appropriate seating in excellent condition Does not apply. 							The lack of open hallway space and underutilized courtyard informal interaction.	s provide few are	as for
4.7 Does the building provide adequate opportunities for students to work independently?	1		Π			Π	Comments	1.00	1.00
1) Very unsatisfactory - None/poor condition 2) Unsatisfactory - One area far from classrooms in unsatisfactory condition 3) Average - one area for independent work with appropriate furniture needing updates 4) Good - clusters or small rooms adjacent to classrooms with furniture in good condition 5) Very good - multiple clusters or small rooms adjacent to classrooms with appropriate furniture in excellent condition N/A) Does not apply.			•			•	The Ibrary is the only dedicated space for students to work	independently.	

4 - Future Ready Student Development - Continued	1	2	3	4	5	N/A			
4.8 Does the building support career education per house bill 5? (High School only)						N/A	Comments	0.00	0.0
 Very unsatisfactory - No dedicated spaces Unsatisfactory -Some spaces being used for both career education and other subjects 									
 Average - A few dedicated career ed spaces, but inadequate configuration/ equipment for needs 									
4) Good - Some dedicated career ed spaces with adequate configuration and equipment for program needs 5) Very good - Dedicated career ed spaces with good configuration and equipment for program needs - new condition N/A) Does not apply.									
4.9 Do the career education spaces simulate real world or college environments? (High School Only)						N/A	Comments	0.00	0.0
1) Very unsatisfactory - No dedicated spaces, lack of necessary equipment 2) Unsatisfactory - Non-dedicated, undersized or otherwise inadequate 3) Average - A few dedicated spaces of moderate size/layout, equipment and furniture appropriate but need updates 4) Good - Dedicated spaces of adequate size and layout, most of the equipment and furniture is appropriate for program 5) Very good - Dedicated spaces of adequate size and layout, equipment and furniture appropriate for program N/A) Does not apply.									
4.10 Does the building have adequate visual communication tools?		2					Comments	1.00	2.0
 Very unsatisfactory - No vis comm tools Unsatisfactory - outdated, poorly functioning, or insufficient Good - mix of old and new whiteboards/projectors/etc. Good - projectors, marker boards, smart boards in most spaces - good condition Very good - projectors, marker boards, smart boards in most spaces - new condition N/A) Does not apply. 							Innovation stations are present in classrooms for upper gralacking technology. CAC comment: Innovation stations and computers are approaching the end-of-life. The campus nee refresh campus technology as soon as possible.	other classroom	

5 - Library/Media Center	1	2	3	4	5	N/A			19.50
Is the Library/Media Center easily accessible for the occupants and visitors to the school?			3				Comments	0.50	1.50
1) Very unsatisfactory							The library is off of the main hallway. However, it does not h	nave direct access	s from
2) Unsatisfactory							the front parking area.		
3) Average									
4) Good									
5) Very good									
N/A) Does not apply.									
5.2 How well does the Library/Media Center support quiet study?				4			Comments	1.00	4.00
1) Very unsatisfactory							The library has space for quiet study, but it is a limited area.		
2) Unsatisfactory									
3) Average									
4) Good									
5) Very good									
N/A) Does not apply.									
5.3 How well does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1) Very unsatisfactory							There are some areas for social interaction, including a socia	al stair.	
2) Unsatisfactory									
3) Average									
4) Good									
5) Very good									
N/A) Does not apply.									
How well does the Library/Media Center support collaborative work in small groups (4-8 students)?					5		Comments	1.00	5.00
1) Very unsatisfactory							There are small group tables available.		
2) Unsatisfactory									
3) Average									
4) Good									
5) Very good									
N/A) Does not apply.									

5 - Library/Media Center - Continued	1	2	3	4	5	N/A			
5.5 How well does the Library/Media Center support collaborative work in larger groups (10-25)?		2					Comments	1.00	2.00
1) Very unsatisfactory							The library is small and is unable to accommodating many la	rge groups.	
2) Unsatisfactory									
3) Average									
4) Good									
5) Very good									
N/A) Does not apply.									
5.6 How well does the Library/Media Center support technology?			3				Comments	1.00	3.00
1) Very unsatisfactory - Very inadequate power outlets, no Wi-Fi capability, no computers, tablets, laptops, media carts or screens for use 2) Unsatisfactory - Some power, no Wi-Fi capability, outdated and inadequate technology available 3) Average - Some power outlets, network connectivity, technology available 4) Good - Adequate power outlets available, network connectivity, appropriate number of computers/tablets/laptops/media carts or screens available 5) Very good - Adequate power outlets available, good network connectivity, computers, tablets, laptops and media carts or screens available and adequate for number of students N/A) Does not apply.							There is only a small amount of technology present in the lib prefers that "COWs" go directly to the classrooms so that the moved around the school.		

6 - Security		1	2	3	4	5	N/A			11.25
6.1 Does the fa	cility have key card access at all major entries?					5		Comments	0.25	1.25
	 Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries have key card access Average 1/2 of entries have key card access Good - 3/4 of major entries have key card access Very good - all of major entries have key card 			•						
	access N/A) Does not apply.									
6.2 How adequ	ate is site lighting and security for the campus overall?		2					Comments	1.00	2.00
	 No exterior lighting, no secure perimeter Lighting is limited to front entry only, parking lot lighting poor, security is minimal Lighting at all night-use entries and parking lot, but poor condition. Security is moderate 				•	•	•	The site lighting is poor and needs improvement.		
	 4) Lighting at all night-use entries and parking lots, good condition, signage less visible. Perimeter is well secured, but needs updates. 5) Signage, parking lots, and entries are well lit, visible and easy to use. Perimeter is very secure. N/A) Does not apply. 									
1 6 ₹	office properly located and configured with a secure the main corridor?			3				Comments	1.00	3.00
	 Very unsatisfactory - No secure vestibule, office located far from main entry. Allows visitors access to school unsupervised. Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors. Average - Office close to entry, views of front door, but no secure vestibule Good - Office is well-located with a secure vestibule, but needs updates Very good - Office well-located with secure vestibule and all appropriate security features. 	,		•	•				1.00	3,00
Is there end	N/A) Does not apply. Dough interior transparency for faculty to affectively supervise			Π	Π		Т	Comments		
6.4 students wl	1) Very unsatisfactory 2) Unsatisfactory 3) Average 4) Good 5) Very good N/A) Does not apply.					5		Comments	1.00	5.00

7 - Technology	1	2	3	4	5	N/A			7.00
7.1 How well equipped are the facilities with instructional technology?		2					Comments	1.00	2.00
 Very unsatisfactory - very few or no available computers or devices. Old/outdated technology Unsatisfactory- few computers/devices. Some outdated technology Average- A few computers/devices. A mix of new and outdated technology Good - multiple computers or devices per room. Mostly new technology. Very good - multiple computers and devices and new technology. Does not apply. 							Older grade levels are equipped with innovation stations and the lower grades do not have this technology in the classroo Innovation stations and other classroom computers are appliance The campus needs District support to refresh campus technology.	oms. CAC comments	nt: of-life.
7.2 Is there an adequate number of power and data outlets in learning spaces?					5		Comments	1.00	5.00
1) Very unsatisfactory - none									
2) Unsatisfactory - only for teacher									
3) Average - for teacher and 1-2 students									
4) Good - 2-3 outlets per wall									
5) Very good - 3-4 per wall									
N/A) Does not apply.									

8 - Storage	1	2	3	4	5	N/A			7.00	
8.1 Is there adequate general storage in the building?		2					Comments	1.00	2.00	
1) Very unsatisfactory							The book rooms are undersized and there are only a few are	eas for storage.		
2) Unsatisfactory										
3) Average										
4) Good										
5) Very good										
N/A) Does not apply.										
8.2 Is there adequate classroom storage?		2					Comments	1.00	2.00	
1) Very unsatisfactory							The casework is small and outdated. There are no storage c	losets for classroo	oms.	
2) Unsatisfactory										
3) Average										
4) Good										
5) Very good										
N/A) Does not apply.										
8.3 Is there adequate student storage?			3				Comments	1.00	3.00	
1) Very unsatisfactory							The desks provide some student storage.			
2) Unsatisfactory										
3) Average										
4) Good										
5) Very good										
N/A) Does not apply.										

9 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A			12.75
9.1 What is the current condition of the furniture?					5		Comments	0.75	3.75
1) Very unsatisfactory - damaged/non-functioning							The school has just received new furniture.	•	
2) Unsatisfactory - torn, bent, wrong size									
3) Average - scratched/dented/marked									
4) Good - not new but sturdy and clean									
5) Very good - new									
N/A) Does not apply.									
9.2 How well does furniture accommodate rapid reconfiguration of a space?					5		Comments	1.00	5.00
 Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure and that cannot Good - Furniture is flexible for multiple configurations of space Very good - furniture is flexible for multiple configurations of space, easy to move and stack N/A) Does not apply. 									
9.3 Is the furniture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
1) Very unsatisfactory - desk with attached chair combinations too small for grade level 2) Unsatisfactory -desk with attached chair combinations 3) Average - mix of classrooms with tables/loose chairs and desks with fixed seats 4) Good - tables with loose chairs 5) Very good - tables with loose chairs that allow students to bounce in seat N/A) Does not apply.							The placement of whiteboards and the height of the casewo	ork is lower than	usual.


10 - Environmental Quality	1	2	3	4	5	N/A			19.00
10.1 How are acoustics in classrooms in general?		2					Comments	1.00	2.00
1)Recognized word/sound from adjacent classroom/corridor 2) audible sound from adjacent classroom/corridor 3) slight sound from outside room 4) walls to deck insulated only white noise from						•	Louvers are present in the walls between classrooms and the louvers allow for sound to travel from one space to the other. The principal expressed that this is not an issue for her instru	er. <i>Principal Comn</i>	
mechanical system 5) Able to hear quiet speaking from across the room N/A) Does not apply.									
10.2 Is the classroom artificial lighting adequate quality?			Т	Τ	5	Т	Comments		
 Very unsatisfactory - sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Good - 30-39 FC and no glare Very good - 40+ FC and no glare N/A) Does not apply. 									
10.3 Is there access to natural light in classrooms?					5		Comments	1.00	5.0
 No learning spaces have natural light 1-25% of learning spaces have natural light or windows are too small to let in light 26-50% of learning spaces have natural light 51-75% of learning spaces have natural light 76-100% of learning spaces have natural light N/A) Does not apply. 				•	•				


10 - Environmental Quality - Continued	1	2	3	4	ļ.	5	N/A			
10.4 Is there access to outside views from learning spaces?						5		Comments	1.00	5.00
1) No learning spaces have views										
2) 1-25% of learning spaces have views or windows are too small to see out										
3) 26-50% of learning spaces have views										
4) 51-75% of learning spaces have views										
5) 76-100% of learning spaces have views										
N/A) Does not apply.							'			
10.5 Does the building have odor or pest problems?		2						Comments	1.00	2.00
1) Very unsatisfactory								There are rats and roaches reported at the facility.	_	
2) Unsatisfactory										
3) Average										
4) Good										
5) Very Satisfactory										
N/A) Does not apply.										

1	1 - Controllability of Systems	1	2	3	4	5	N/A			5.50
	11.1 Does the classroom thermostat allow for individual control?	1						Comments	0.50	0.50
	1) No									
	5) Yes									
	11.2 Are shades provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1) No, windows are covered with boards/paper									
	2) No, windows have no light control									
	3) Yes, but poor condition blinds									
	4) Yes, blinds									
	5) Blackout shades									
	N/A) Does not apply.									
	11.3 What is the quality of lighting controls in the classrooms?	1						Comments	1.00	1.00
	1) Single switch only per room									
	2) Alternating rows switch off									
	3) Alternating lamps in single fixtures switch off									
	4) Tri level switching									
	5) Dimmable									
	N/A) Does not apply.									











4.1 Visual Communication

