

Ann Richards School for Young Women Leaders

Date: 01/28/2021 Score 95% Very Satisfactory

Ann Richards School, serving an enrollment of approximately 880 students in south Austin, is an all-girls school for sixth through 12th grades. Named after the 45th governor of Texas, the school embodies Ann Richard's lifelong dedication to the advancement of women to pursue their highest potential in career and community. The school opened in 2007, and in January 2021, the school moved into its new home built next to the old school, which will be demolished in the coming year. This assessment is based on the new school, and the site improvements that are in progress.

The new school is a very open and light-filled space conducive to collaboration. The heart of the school is a large, two-story dining commons. The space has a stage for events but is not set-up for formal theatrical productions. The library is directly adjacent and provides additional areas for quiet study and group collaboration. The learning neighborhoods comprise the academic wing of the building and are a mixture of studios, small group rooms, and large open collaboration spaces. On the second level, there are two large rooms identified as forum rooms. Throughout the school, the new furniture is flexible, provides opportunity for individual/group study and provides adequate power for 1-to-1 devices. The aesthetics of the interior have a "high-tech" feeling and convey the atmosphere that students will find in college and in the working world.

The layout of the building provides numerous indoor/outdoor connections – at the cafeteria to an adjacent porch/future shade structure, the learning neighborhoods to an academic courtyard, a courtyard where art and maker spaces can spill outdoors, and a porch off the second floor of the library. A track will be added to the site where the old school is located. Circulation of bus, pickup and drop-off, and student parking is separated with access from each of the perimeter roads effectively utilizing a tight site.

Interview Overview

The interview with the Ann Richards SYWL administration took place two months after the school opened and at the time of the interview a portion of the school was still under construction. Areas such as the library, gymnasium, maker space and music studios were not yet available for campus use.

In the short time occupying the new school, Principal Waugh said the staff and students have embraced the open collaborative design concept which supports overall communication and connectivity. The large, flexible lecture halls, or "forums" as the school refers to them, were specifically identified as spaces of great value that are highly utilized.

A shared arts courtyard, multiple covered exterior patios, and outdoor dining space are provided to create a balance between play and academia. The principal and staff identified this as a high priority for the school along with a strong indoor/outdoor connection with nature. At the time of the

Educational Suitability Summary Report

Ann Richards School for Young Women Leaders

interview, demolition was just beginning on the old school, which once removed will free up the open space necessary for the designed playing fields and other outdoor spaces.

The only space deficiency voiced by the administration is the lack of a dedicated performance auditorium. The new building has a black box theater but once completed it will only be a shell and will not have the necessary lighting, audio/visual, technology and support spaces to function as a performance space. As a part of the overall school master plan, an auditorium is planned for future construction but there is currently no funding for this portion of work.

Assessment Findings

The Educational Suitability Assessment of Ann Richards School for Young Women Leaders earned a 95% overall score and places the campus in a category of very satisfactory. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Average Categories (51-65%):

Athletics and Wellness

Score is average.

The indoor athletic facilities are generous in size and are very well equipped for the current enrollment, but certain dedicated storage, for swimming, golf, were not identified on construction plans. There is an 8-lane track and exterior play field, but due to site constraints, no softball fields or tennis courts are provided.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.

Even though it is a tight site, bus and vehicular pickup and drop-off are separate. There are multiple prominent entry points into the building, and additional signage to the front entry would aid in wayfinding to the new entry off Panther Lane. All three dumpster (trash, composting, recycling) are available, and the route is barrier free.

Outdoor Learning and Activity

Score is very satisfactory.

A wide variety of outdoor learning spaces are well distributed around the building. The courtyards are easily accessible and many of them are shaded. Most of the outdoor activity spaces such as play fields and gardens were not constructed at the time of the assessment site walk.

General Building

Score is very satisfactory.

Both the library and gym have dedicated exterior entrances that allow the school to remain secure during nighttime events. There is a dedicated community room with restrooms and its own exterior entry.

Security

Ann Richards School for Young Women Leaders

Score is very satisfactory.

Environmental Quality

Score is very satisfactory.

All education spaces have generous access to natural light and views. Corridors and collaboration spaces also receive ample natural light due to the large amount of interior glazing in the studios.

Controllability of Systems

Score is very satisfactory.

All spaces have an adequate level of control of thermostats, natural light and artificial light.

Furniture, Fixtures, Equipment

Score is very satisfactory.

All areas have a wide variety of furniture types. The library provides furniture for both individual and group learning, and the cafeteria has multiple seating zones with varied seating styles.

Academics & Learning

Score is very satisfactory.

The general studios are slightly under the AISD required square footage, but they have good access to collaboration and flex spaces for studios to spill into. The learning neighborhoods are very flexible and provide a wide variety of learning environments.

CTE and Career Connected Learning

Score is very satisfactory.

The campus provides all the CTE and Career Connected Learning programs identified in the master plan. The CTE spaces are highly flexible and can be used for other classes when CTE courses are not being taught.

Visual and Performing Arts

Score is very satisfactory.

Visual and performing arts education spaces are generous in size and well supported. The art classrooms open to a generous outdoor art space. The campus does not have a dedicated auditorium, but a small stage area is provided in the cafeteria. A black box theater has been provided and at the time of the assessment walk, did not have lighting or audio/visual equipment.

Food Services

Score is very satisfactory.

Cafeteria is generous in size and has multiple seating options. The layout allows for great flexibility for use of the space outside dining hours.

Media Resources

Score is very satisfactory.

The library supports multiple types of learning and interaction. Small and medium group rooms are provided in addition to a large, tiered seating area for lecture-style presentations. Individual and

Educational Suitability Summary Report

Ann Richards School for Young Women Leaders

quiet learning zones are provided with acoustically treated furniture.

Technology

Score is very satisfactory.

There are adequate power and data ports provided throughout the building in addition to complete Wi-Fi coverage.

Administration Spaces

Score is very satisfactory.

The administration suite is at the main entry with a large amount of interior and exterior glazing to allow clear sight lines of people entering and leaving the building. The reception area is open and inviting with a good amount of natural light.

Ann Richards School for Young Women Leaders



Main school entry off Panther Trail has a large canopy to provide protection from weather.



The building has unique murals/graphics. This one is at the entry of the school. In general, there are limited places for 2D and 3D display throughout the school.

Ann Richards School for Young Women Leaders



Cafeteria has a stage but is not set-up for formal productions. There is a variety of seating within the space.



Two-story multipurpose space serves as a cafeteria and a large meeting space that opens to outdoor courtyard/seating.

Ann Richards School for Young Women Leaders



Media Center: Two-story space with a variety of seating types, a collaboration stair, and a second-floor porch for additional outdoor space.




Typical studio has a variety of furniture. Some studios have movable partitions to open to collaboration space and adjacent studio.

Ann Richards School for Young Women Leaders



Centralized collaboration space with studios along the perimeter. Each learning neighborhood has a different color scheme and different types of flexible furniture.



Small group rooms with technology and whiteboards are in each of the learning neighborhoods.

Ann Richards School for Young Women Leaders



Furniture provides variety for individualized study and group work and supports charging/technology needs.



Science lab with overhead power and prep room between two lab spaces.

Ann Richards School for Young Women Leaders

Supporting Photographs



Main gym is adequately sized with bleachers along one side of the gym. The projection screen and projector are sized adequately for the large space.



Art studios are flexible spaces with movable worktables and overhead doors between the two art rooms as well as one to the outdoors. They are next to engineering studios and a maker space.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Ann Richards School for Young Women Leaders	Lynn Petermann and Travis Hughbanks	01.28.21

1 - Ex	cterior		1	2	3	4	5	N/A		8.75	94%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?					5		Comments	1.00	5.00
	1 2 3	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small									
	4 5	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
1.2		ing easily identified with appropriate signage and wayfinding?			3				Comments	0.25	0.75
	1 2	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden							There are multiple prominent entry points but the prinot well identified. The primary entry is on Panther Tr signage to the main entry and visitor parking would be	ail and additio	-
	3	Average - Signage / wayfinding visible but not apparent							longituge to the main only and visitor parking would be	o bononcian.	
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A	N.		
1.3	Is the dump	oster accessible for trash / compost disposal?					5		Comments	0.50	2.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
2 - (N/A Outdoor Lo	Does not apply arning and Activity	1	2	3	4	5	N/A		10.00	100%
2.1	Are outdoo	or studios and support spaces appropriately configured per	'		3	4	5	IN/A	Comments	1.00	5.00
	1 2 3 4	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area				•			Multiple large outdoor patios are provided that can The spaces are well distributed and the majority are		tudios.
2.2	,	Does not apply playgrounds (elementary only) and support spaces per the ed spec?						n/a	Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply		,		•					

2 - C	outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	4		
2.3		s and support spaces appropriately configured per the ed					5		Comments		
	spec? (evai	uation on infrastructure not condition of plants)								0.00	0.00
	1	Very unsatisfactory - No dedicated gardens							Gardens are not built yet but are identified in plan in		
	2	Unsatisfactory - Too small, poor condition, disconnected							location. (Monitoring answer, does not affect score for	or Outdoor Lec	arning
		from learning spaces, no flexibility, no accessible water							and Activity.)		
	•	source									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water									
		some removations or apacies to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to									
	•	learning spaces, good flexibility, water source is									
		accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces, excellent flexibility, water									
		source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain	n gardens and/or cisterns appropriately configured per the					5		Comments		
2.4	ed spec?						5		Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns					ļ.		Large rain garden provided. (Monitoring answer, doe	es not affect sc	ore for
	2	Unsatisfactory - Too small, poor condition, not							Outdoor Learning and Activity.)		
		functioning, disconnected									
	3	Average - Adequate size, adequate condition, is									
		connected, needs some renovations or updates to									
		function well									
	4	Satisfactory - Good size, good condition, functions									
	_	properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces,									
		educational signage provided									
	N/A	Does not apply									
2.5		hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No					I		35		
	5	Yes									
2.6	Does the sc	hool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes									
2.7		hool have a learning pond? (optional)					5		Comments	0.00	0.00
	•										
0.0							-			100	
2.8							5		Comments	1.00	5.00
	•										
	5 Does the sc	Yes					5		Comments	0.00	5.00

3 - General Building	1	2	3	4	5	N/A	ı.	11.25	100%
Are interior circulation routes wide enough to safely and effectively					5		Comments		
accommodate student movement?					5		Comments	0.50	2.50
1 Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
wide									
2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A Does not apply					•				
Are community use areas arranged so that the school can allow night					5		Comments		
functions without full school access?	<u> </u>							0.75	3.75
1 Very unsatisfactory - Cafeteria, gym, and library cannot							Library and gym both have dedicated entry points th		-
be accessed after hours 2 Unsatisfactory - Only one of the public spaces (Cafeteria							secure community access. The cafeteria allows for ea	-	
Gym and Library) can be accessed from parking and	,						series of overhead coiling grilles can be secured from	the rest of the	school.
secured after hours									
3 Average - Only two of the public spaces can be accessed									
from parking and secured after hours									
4 Satisfactory - All of the public spaces can be accessed									
from parking and secured from the rest of the building									
but not individually									
5 Very satisfactory - Cafeteria, gym, and library can be									
accessed from parking and locked off from rest of									
campus for night/evening use with their own entrance									
N/A Does not apply									
ls there a community room that is a dedicated meeting space outside					5		Comments		
of school function?	<u> </u>						Comments	0.75	3.75
1 Very unsatisfactory - No dedicated community room									
2 Unsatisfactory - Community room but within school									
function, no access after school hours 3 Average - Community room, moderate size, but need									
3 Average - Community room, moderate size, but need some renovations or updates to function well									
4 Satisfactory - Community room, good size /layout, meets									
needs /functions well									
5 Very Satisfactory - Community room, generous size, nice									
condition, functions appropriately outside of school									
function									
N/A Does not apply									
Does the general appearance of the school convey pride for the					5		Comments		
students and community?	<u> </u>						Comments	0.25	1.25
1 Very unsatisfactory - General appearance is poor									
2 Unsatisfactory - General appearance is aged but ok									
3 Average - General appearance is good									
4 Satisfactory - General appearance shows pride in									
campus and student works									
5 Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the									
campus and student works and is welcoming to the community									
N/A Does not apply									
. 4									

	4 - Security		1	2	3	4	5 I	N/A		16.25	
	4.1 Does the fo	acility have key card access at all major entries?							Comments	0.25	
,	1	Very unsatisfactory - No entries									•
	2	Unsatisfactory - 1/4 of major entries									
	3	Average - 1/2 of major entries									
	4	Satisfactory - 3/4 of major entries									
	5	Very satisfactory - All of major entries									
	N/A	Does not apply									
	4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	1.00	
ļ	1	Very unsatisfactory - No exterior lighting, no secure perimeter									
	2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal									
	3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate									
	4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates									
	5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure									
	N/A	Does not apply									
	4.3 Is the main	office located at the school entry and configured with a							Comments		
	secure vest	ibule to the main corridor?							Comments	1.00	
	1	Very unsatisfactory - No secure vestibule, office located									
		far from main entry, allows visitors access to school									
	2	unsupervised									
	2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of									
		visitors									
	3	Average - Office close to entry, views of front door, but									
	, and the second	no secure vestibule									
	4	Satisfactory - Office is well-located with a secure									
		vestibule, but needs updates									
	5	Very satisfactory - Office well-located with secure									
		vestibule and all appropriate security features									
	N/A	Does not apply									
	ls there end	ough interior transparency for faculty to passively supervise					_		Community		
	4.4 learners an	d their activities who are not in studios?					5		Comments	1.00	5.00
,	1	Very unsatisfactory - No transparency of walls							All studio spaces have excellent transparency to ope	n collaboration	and
	2	Unsatisfactory - Limited transparency in certain locations							flex spaces.		
	3	Average - Good transparency in certain locations but									
	J	inadequate or missing in other locations of school									
	4	Satisfactory - Adequate transparency throughout the school									
	5	Very satisfactory - Excellent transparency throughout the school									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁶

5 - Environmental Quality		1	2	3	4	5	N/A		25.00	100%
5.1 How are acoustics in studios in general?						5		Comments	1.00	5.00
1 Very unsatisfactory - Recognized word adjacent studio/corridor 2 Unsatisfactory - Audible sound from a studio/corridor 3 Average - Slight sound from outside recognized in the studio of the studio	adjacent oom only white noise									
5.2 Is the studio artificial lighting adequate quality?						5		Comments	1.00	5.00
1 Very unsatisfactory - Sporadic lights v than 20 FC 2 Unsatisfactory - 10-19 FC or serious glo 3 Average- 20-29 FC minor glare 4 Satisfactory - 30-39 FC and no glare 5 Very satisfactory - 40+ FC and no glare N/A Does not apply	are									
5.3 Is there access to natural light in studios?						5		Comments	1.00	5.00
1 Very unsatisfactory - No learning span light 2 Unsatisfactory - 1-25% of learning span light or windows are too small to let in 3 Average - 26-50% of learning spaces 4 Satisfactory - 51-75% of learning spac light 5 Very satisfactory - 76-100% of learnin natural light	aces have natural n light have natural light tes have natural							Studios and all learning spaces have a great amoun exterior glazing as well as generous interior glazing flight.	_	
N/A Does not apply	1					1			T	
5.4 Is there access to outside views from learning space	es?					5		Comments	1.00	5.00
1 Very unsatisfactory - No learning space 2 Unsatisfactory - 1-25% of learning space windows are too small to see out 3 Average - 26-50% of learning spaces 4 Satisfactory - 51-75% of learning space 5 Very satisfactory - 76-100% of learning views N/A Does not apply	aces have views or have views es have views							See above		

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	N.		
5.5 Does the b	ouilding have odor or pest problems?					5		Comments	1.00	5.00
1	Very unsatisfactory - Evidence of both pests and odors									
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	\	12.50	92%
6.1 Does the s	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No	•					•			
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with							Limited spaces have blackout shades but the majorit	y of spaces hav	⁄e
	boards/paper							blinds.		
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?					5		Comments	1.00	5.00
1	Very unsatisfactory - Single switch only per room	•			•		•			
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							'		

7 - Furniture, I	Fixtures & Equipment	1	2	3	4	5	N/A	4	18.75	100%
7.1 What is the	e current condition of the furniture?					5		Comments	0.75	3.75
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply									
	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?					5		Comments	1.00	5.00
1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture							All areas have multiple types of furniture.		
7.3 How well of space?	Does not apply does furniture accommodate rapid reconfiguration of a					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply									
7.4 Is the furni	iture ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow students to be active Does not apply									

Perkins&Will 02/11/2022 ⁹

Waste	1	2	3	4	5	N/A		5.00	100
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?					5		Comments	0.50	2.
1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. 5 Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. N/A Does not apply							A score for this category is being recorded, but this co-calculated in the overall ESA average.	itegory is not	
Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?					5		Comments	0.50	2
1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting. N/A Does not apply		1						0.00	



Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Ann Richards School for Young Women Leaders	Lynn Petermann and Travis Hughbanks	01.28.21

8 - Academi	ics & Learning	1	2	3	4	5	N/A	50.00	92%
8.1 Are stud	dios appropriately configured per the ed spec?				4			Comments 1.00	4.00
1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools,							General studios are 750SF. Slightly undersized per Ed Spec but good connectivity to other studios through the use of movable partitions. Transparency is used from collaboration spaces into studios.	
N1/A	excellent transparency and connection with other studios and shared learning spaces								
8.2 Do studied specific	ios have appropriate support spaces such as storage per the				4			Comments 1.00	4.00
1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply								

8 - 8	Academics	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do typical	learning neighborhoods have small and medium (high					5		Comments		
0.3	school only	y) group rooms and open collaboration space?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No breakout rooms or open							Learning neighborhoods have large central collabore	ation spaces. S	Studios
		collaboration spaces are provided							have transparency into collaboration spaces and smo	all/medium gr	oup
	2	Unsatisfactory - Too small or too few, poor condition, no							rooms also line collaboration space.		
		flexibility, lacks visual connection to learning							·		
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	_	acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition									
		and flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply		1	1			1			
8.4		e Labs and support spaces appropriately configured per					5		Comments		
	the ed spe					<u> </u>	<u> </u>			1.00	5.00
	1	Very unsatisfactory - No dedicated science room									
	2	Unsatisfactory - Too small, poor condition, no connected									
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	_	support spaces Very Satisfactory - Generous size, excellent condition,									
	5	connected support spaces									
	N/A	Does not apply									
		Spaces and support spaces appropriately configured per		Г		l	1				
8.5		c? (cross reference with CTE below)					5		Comments	1.00	5.00
	1	Very unsatisfactory - No dedicated maker spaces		1		l	l		Maker space and engineering lab are provided with		
	2	Unsatisfactory - Too small, poor condition, disconnected								good support	(ciedii
	2	from learning spaces, no flexibility							room, prep, storage).		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	7	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply									

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A			
8.6 Is there a Professional Learning Center in the learning neighborhood?					5		Comments	1.00	5.00
Very unsatisfactory - No dedicated space for Professional Learning Center						•	PLC provided in learning neighborhoods.		
2 Unsatisfactory - Too small, poor condition, disconnected									
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4 Satisfactory - Good size, good condition, connected									
5 Very Satisfactory - Generous size, excellent condition,									
connected									
8.7 Are there adequate places to display the evidence and artifacts of			3				Comments		
learning (both 2D and 3D)?			3				Comments	1.00	3.00
 Very unsatisfactory - No dedicated space 							Ample 2D display space provided but limited display	area for 3D art	t.
2 Unsatisfactory - Too small, non-dedicated, poor									
condition 3 Average - Adequate size, adequate condition, needs									
updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
Does the building / learning neighborhood provide adequate									
8.8 opportunities for students/teachers to collaborate in varying group					5		Comments		
sizes?								1.00	5.00
1 Very unsatisfactory - No space to support collaboration					l	l	A great mixture of open collaboration space, small g		
in various sizes.							rooms.		5 - 1
 Unsatisfactory - Too small, inflexible, only one option, 									
does not support a variety of group sizes									
 Average - Adequate space for collaboration, needs 									
updates or renovations to function well.									
4 Satisfactory - Good size, good condition, multiple									
options to support a variety of group sizes									
5 Very Satisfactory - Generous size, excellent condition,									
multiple options to support a variety of group sizes									
N/A Does not apply						ı	T		
8.9 Does the building provide opportunities for informal interaction?					5		Comments	1.00	5.00
1 Very unsatisfactory - No space							Yes, open collaboration space is very generous.		
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply									

cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
	•					5		Comments	1.00	5.00
1 2 3 4 5 5	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood							Yes, small/medium group rooms are available in eve neighborhood.		5.50
N/A	Does not apply									
•					1	ı				
Are Special spec?	Education spaces appropriately configured per the ed						n/a	Comments	0.00	0.00
1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							No special education program at school.		
Are Special							,			
washer/dry	er, appropriately configured per the ed spec?						n/a	Comments	0.00	0.00
1 2 3 4 5 N/A	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply									
	Does the but work indepto work indepto work indepto 1 2 3 4 4 5 5 N/A Are Special Edu 3 3 4 4 5 5 N/A Are Special washer/dry 1 2 2 3 3 4 5 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1 5 1	verk independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Does the building provide adequate opportunities for students to work independently? 1	Deset the building provide adequate apportunities for students to work independently? 1	Does the building provide adequate opportunities for students to use independently? I very unsettifactory - No breakout rooms/small study spaces 2 Unsettifactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updotes or renovations to function well. 4 Satisfactory - God size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Sotisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Sotisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood N/A Does not opply Special Education spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, not flexibility, disconnected under the special education spaces appropriately configured per the ed spec? 2 Unsatisfactory - Too small, not flexibility, disconnected transprency and connection other studies and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - God size, multiple areas for different teaching methods, open flexibility, generous size, multiple areas for different teaching methods, specified resulting and connection to other studies and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, specified resulting and connection to other studies and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, generous size, on the studies and shared learning spaces. 5 Very Satisfactory - Generous size, connected, poor condition, needs updates or renovotions to function well. 1 Very unsatisfactory - Too small, not inconnected, poor con

O2/11/2O22 ⁵

8 - Academics & Learning (cont.)	ı	2	3	4	5	N/A			
Are Accessible restrooms and changing rooms readily available to the Special Education spaces?						n/a	Comments	0.00	0.00
1 No									
5 Yes									
STEAM Center									
8.14 Does the campus have space to support a "STEAM" center?					5		Comments	0.00	0.00
1 Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space 2 Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size 3 Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately 4 Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center 5 Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning							Monitoring answer, but does not count toward overa	Il score	
N/A Does not apply									
9 - CTE and Career Connected Learning								5.00	100%
How close is your campus to a CTE cluster pathway that is aligned with your CTE programs (Middle School only)?						n/a	Comments	0.00	0.00
 Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway. Average - School support half of CTE programs listed in the cluster pathway, but missing some. Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway. Very Satisfactory - School is aligned with CTE cluster pathway. N/A Does not apply 							CTE programs are provided per Master Plan.		
,									
9.2 Do campus facilities align with the CTE Ed Spec Requirements for the current pathways offered?: Architecture and Construction						n/a		0.00	0.00
1 No 5 Yes N/A Does not apply									
9.3 Arts, Audio and Video Technology and Communications					5			0.25	1.25
9.4 Business, Management and Administration						n/a		0.00	0.00
9.5 Education and Training						n/a		0.00	0.00
9.6 Health Science					5			0.25	1 25

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism						n/a		0.00	0.00
9.8 Human Services (high school only)						n/a		0.00	0.00
9.9 Information Technology					5			0.25	1.25
9.10 Agriculture, Food and Natural Resources						n/a		0.00	0.00
9.11 Science, Technology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportation, Distribution and Logistics						n/a		0.00	0.00
9.13 Finance (high school only)						n/a		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						n/a		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						n/a		0.00	0.00
9.16 Manufacturing (high school only)						n/a		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						n/a		0.00	0.00
10 - Visual and Performing Arts								35.00	89%
10.1 Is there flexibility of space to also be used by CTE and Athletics?					5		Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
U I Es									
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?					5		Comments	1.00	5.00
Are band and support spaces (rehearsal and storage) appropriately					5			1.00	5.00
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition					5		Comments	1.00	5.00
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply Are orchestra and support spaces appropriately configured per the					5		Comments Band and ensemble room generously sized.	1.00	5.00
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec?				4	5		Comments	1.00	5.00
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the				4	5		Comments Band and ensemble room generously sized.		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec?				4	5		Comments Band and ensemble room generously sized. Comments		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1				4	5		Comments Band and ensemble room generously sized. Comments		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1				4	5		Comments Band and ensemble room generously sized. Comments		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1				4	5		Comments Band and ensemble room generously sized. Comments		

10 - Visual and	d Performing Arts (cont.)	1	2	3	4	5	N/A	1		
10.4 Are choir o	nd support spaces appropriately configured per the ed				4			Comments		
spec?					4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces							Good size at approximately 1000 SF.		
2	Unagtisfactory Top small poor condition									
3	Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs									
3	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Are dance	and support spaces appropriately configured per the ed									
10.5 Are dance spec?						5		Comments	1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces							Generously sized at 1975 SF. Separate dressing and le	ocker room.	
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1	ı	ı	T	ı	ı			
10.6 Are theate spec?	r and support spaces appropriately configured per the ed			3				Comments	1.00	3.00
spec:	Very unsatisfactory - Too small, missing program spaces	<u> </u>						Shell for black box theater provided but no lighting of		
· ·	very unsatisfactory 100 smail, missing program spaces							provided, so the space can not support performance		pport
2	Unsatisfactory - Too small, poor condition							provided, so the space can not support performance	.	
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply							T	T	
10.7	arts and support spaces appropriately configured per the					5		Comments		
ed spec?		<u> </u>							1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces							Both high school and middle school art rooms are ge	nerously sized.	Have
2	Unsatisfactory - Too small, poor condition							access to outdoor art courtyard.		
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1					Ι	1		
10.8 Does the c	ampus have adequate space for the specialty arts					5		Commonto		
programs	(Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments	1.00	F 00
1	No								1.00	5.00
5	Yes									

11 - Athletics and Wellness						20.00	60%
11.1 Does the campus meet ed spec standard for physical education program spaces?			5		Comments	1.00	5.00
Very unsatisfactory - Too small, missing program spaces		1 1			For the current student enrollment, the physical educa generous in size.		
2 Unsatisfactory - Too small, poor condition							
Average - Adequate size, adequate condition, needs							
some renovations or updates to function well							
 Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition 							
N/A Does not apply							
	T						
11.2 Does the campus have a dedicated wellness center?	1				Comments	0.50	0.50
1 No							
5 Yes			-				
11.3 Does the community have access to exterior playfields/courts?				n/a	Comments	0.00	0.00
1 No			l l		not known at this time		
5 Yes							
11.4 Are facilities available to facilitate eSports (High School only)?	1				Comments	0.00	0.00
1 No					Monitoring answer, but doesn't affect overall score.	0.00	0.00
5 Yes					aniswer, but doesn't direct overdir score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			5		Comments	0.25	1.25
1 No 5 Yes							
11.6 Are facilities set up to support UIL sanctioned athletics for track?			5		Comments		
<u> </u>	Ш.				Commente	0.25	1.25
1 No 5 Yes							
11.7 Are facilities set up to support UIL sanctioned athletics for football?				n/a	Comments		
· · ·	Щ.					0.00	0.00
1 No 5 Yes							
73 O. A., 6 - 1/2			_		6 .		
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			5		Comments	0.25	1.25
1 No							
5 Yes							
1].9 Are facilities set up to support UIL sanctioned athletics for tennis?	1				Comments	0.25	0.25
1 No					No courts	0.20	0.20
5 Yes					1.000000		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1				Comments		
11.10 And radinales set up to support oil surictioned difficults for soccer:					Comments	0.25	0.25
1 No					Field available but not for spectator games.		
5 Yes							

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A		
11.11 Are facilities (dedicated storage) set up to support UII athletics for cross-country (high school only)?	L sanctioned	1					Comments 0.25	0.25
1 No 5 Yes							adequate storage for sports but dedicated storage not identified in construction plans	n
11.12 Are facilities (dedicated storage) set up to support UII athletics for golf (high school only)?	L sanctioned	1					Comments 0.25	0.25
1 No 5 Yes							adequate storage for sports but dedicated storage not identified in construction plans	n
Are facilities (dedicated storage) set up to support UII athletics for swimming (high school only)?	L sanctioned	1					Comments 0.25	0.25
1 No 5 Yes							adequate storage for sports but dedicated storage not identified in construction plans	n
Are facilities set up to support UIL sanctioned athletic (high school only)?	s for wrestling					n/a	Comments 0.00	0.00
1 No 5 Yes								
Are facilities set up to support UIL sanctioned athletic (high school only)?	s for baseball					n/a	Comments 0.00	0.00
1 No 5 Yes								
Are facilities set up to support UIL sanctioned athletic (high school only)?	s for softball	1					Comments 0.25	0.25
1 No 5 Yes							There is no dedicated softball field.	
11.17 Are facilities (dedicated space outside of the gymnasi support competitive spirit activities for cheerleading of					5		Comments 0.25	1.25
1 No 5 Yes								
11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A		
How do the athletics fields align with FMP Campus Im 11.18 Turf Field, Parking lot lighting, ADA accessible amenit only)					5		Comments 0.00	0.00
1 Very unsatisfactory - No turf, inaccessibl 2 Unsatisfactory - No turf/field in poor cor accessibility concerns, poor site lighting 3 Average - Field in adequate condition, n updates or renovations to function well 4 Satisfactory - Turf field in good condition access and site lighting 5 Very Satisfactory - Turf field with excelle excellent ADA access for spectators and excellent site lighting N/A Does not apply.	ndition, some needs some n, good ADA ent maintenance,						Does not affect Athletics overall score. Drawings identify turf fields exterior lighting.	and

12 -	Food Servi	ces								10.00	100%
12.	ls the Dining	g Commons appropriately configured per the ed spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, missing program spaces							Large open area with a variety of seating options an the outdoors.	d good connec	ction to
	2	Unsatisfactory - Too small, poor condition, only one							and suitabble,		
	3	option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates									
		or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation,									
		multiple options for eating space (ex: connection to outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition									
		and circulation, multiple options for eating space (ex:									
	N/A	connection to outdoor eating space)									
	Are the Foo	Does not apply d Services support spaces appropriately configured per		l l	1		l	I			
12.	the ed spec						5		Comments	1.00	5.00
	1	Very unsatisfactory - None provided				ı		1			
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4 5	Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
	5	condition									
	N/A	Does not apply									
13 -	Media Res	ources	1	2	3	3 4	5	N/A		30.00	97%
13.	Is the Librar	y/Media Center easily accessible for the occupants and					5		Comments		
13.	visitors to th						5			1.00	5.00
	1	Very unsatisfactory - Not accessible							Easily accessible for nighttime events with dedicated	entry and eas	ily
	2	Unsatisfactory - Limited access, difficult to find, no transparency							accessible from main entry reception.		
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Accessible, easy to find, good									
	_	transparency, good condition									
	5	Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
	N/A	Does not apply									

13 - Media Res	3 - Media Resources - Continued			3	4	5	N/A	A	
13.2 How well o	does the Library/Media Center support quiet study?				4			Comments 1.00	4.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply							One quiet study room within media resources center and many three learning neighborhoods. Furniture in niches provides for quiet study	-
	does the Library/Media Center support social interaction?					5		Comments 1.00	5.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							Learning stairs for informal interaction.	3.33
	Does not apply does the Library/Media Center support collaborative work					5		Comments	
in small gra	very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply							Space provides for flexibility that allows for small/medium/large collaboration.	5.00
How well o	does the Library/Media Center support collaborative work roups (10-25)?					5		Comments 1.00	5.00
1 2 3	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well		1	ı		L	ı	Space provides for flexibility that allows for small/medium/large collaboration.	3.30
4 5	Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons								
N/A	spaces with seating, excellent condition Does not apply								

Perkins&Will 02/11/2022 12

1	13 - Media Res	ources - Continued	1	2	3	4	5	N/A	N.		
	13.6 How well d	oes the Library/Media Center support technology?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart									
	N/A	boards in most spaces - new condition Does not apply									
٠,	I4 - Technolog		1	2	3	4	5	N/A		20.00	100%
		quipped are the facilities with instructional technology?	•				5	14,71	Comments	1.00	5.00
	1 2 3	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart									
	5 N/A	boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition Does not apply									
		adequate number of power and data outlets in learning					5		Comments	1.00	5.00
	1 2 3	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall)									
	4 5 N/A	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall) Does not apply									

Perkins&Will 02/11/2022 13

14 - Technolog	gy (cont.)	1	2	3	4	5	N/A	A		
14.3 Are there of	adequate charging locations for devices?					5		Comments	1.00	5.00
1	Very unsatisfactory - Not enough charging locations throughout school for 1:1					•				
2	Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices									
3	Average - Charging locations well organized but not enough capacity for 1:1									
4	Satisfactory - Charging locations, haphazard locations, but supports 1:1.									
5	Very Satisfactory - Charging locations throughout school to support 1:1.									
N/A	Does not apply									
14.4 Is there ad gym?	lequate AV for presentations spaces – cafeteria, gym, aux					5		Comments	1.00	5.00
1	Very unsatisfactory - AV not present in one or more		•					Large motorized drop-down screen and ceiling-mou	nted projector	in both
	space							gym and cafeteria.		
2	Unsatisfactory - AV undersized for room. Poor condition									
3	Average - AV adequately sized / poor condition OR AV									
	undersized / average condition									
4	Satisfactory - AV adequately sized for room. Average									
	Condition.									
5	Very Satisfactory - AV adequately sized for room.									
N1/A	Excellent condition.									
N/A	Does not apply		1	1	1	1	1	T		
	gital media signage at the reception area?					5		Comments	0.00	0.00
1	Very unsatisfactory - No digital media present in									
	reception area									
2 3	Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR									
3	undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good									
· ·	condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

15 - Administration Spaces		1	2	3	4	5	N/A	·	20.00	95%
ls there a r visitors?	reception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
15.2 Does the o	administration area feel welcoming?					5		Comments	1.00	5.00
1	Very unsatisfactory - No welcome space							Very open and welcoming with good natural light.		
2	Unsatisfactory - Too small, poor lighting and									
	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
	excellent condition									
N/A	Does not apply									
For those s	spaces that require it, does the administration area have					_		Community		
15.3 adequate	acoustic privacy?					5		Comments	1.00	5.00
1	Very unsatisfactory - No acoustic separations									
2	Unsatisfactory - Acoustic separations do not perform									
	well									
3 Average - Some acoustic separations function okay, but portions need updates or renovations										
4 Satisfactory - Good acoustic separations										
5 Very Satisfactory - Excellent acoustic separations										
N/A	Does not apply									
15.4 Are confer	rence rooms easily accessed for public / parent use?				4			Comments	1.00	4.00
1	Very unsatisfactory - Not accessible for public/parent							Yes, there is one in the admin area and one off of the		
	use							. 55, 1.5.5 is one in the damin area and one on or the	· canaadon k	J J 1111
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
	good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent									
	transparency, generous size, excellent condition									
N/A	Does not apply									