

Educational Suitability Summary Report

Bedichek Middle School

Date: 10/21/2020

Score 64% Average

Bedichek Middle School serves a student enrollment of approximately 780 students in south Austin and has a high percentage of students with special education needs. The school comprises a large central courtyard and spacious open-air hallways. Technology is well distributed through the campus, with large screens and projectors in all studios, and an abundance of screens and projectors in the library. Most studios lack sufficient access to daylight and have only two small windows. Several studios have no windows. Science Lab furniture needs to be updated, while the art studios are under construction and currently not accessible.

Interview Overview

The interview with Principal Herbin and Bedichek staff members confirmed many of the findings from the assessment. The administration's primary concern on campus are the portables that currently house the entire 6th grade. These portables are more than 400 feet from any entry to the main school building, with no covered pathways for students. This means classes have to be canceled during severe weather.

Furniture throughout the campus could be improved. Most studios do not have flexible seating that allows it to be rearranged for different group sizes. More dry erase boards or smart boards for collaboration between students are needed. Some lab tables in the science studios are original to the building. These tables are in disrepair, heavy, and not easily moved around for different activities.

Teachers and staff want better outdoor studio spaces. They need spaces that are covered, supplied with power and data, and have surfaces to write on. Ideally, these outdoor studios would be visually separated from existing studios so as not to distract students. Principal Herbin raised the possibility of studios with garage doors that would allow for indoor/outdoor uses.

Assessment Findings

The Educational Suitability Assessment of Bedichek Middle School earned a 64% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory (36%-50%):

Controllability of Systems

Score is unsatisfactory.

Both lighting and temperature controls in many of the studios are unsatisfactory. Mini blinds control natural light in the learning spaces, although not all studios have exterior windows. There is no

Educational Suitability Summary Report

Bedichek Middle School

dimming or alternate switching provided in the studios, and no ability to control separate zones of the studios. Many of the thermostats did not function properly. Some do not function at all, while others control a different room altogether.

Technology

Score is unsatisfactory.

Overall, the school is well equipped with technology in the learning spaces. Each studio has a large mobile screen in addition to projectors. Power and data are not adequate to support "One-to-One" technology. There are a limited number of outlets along the perimeter of all the studios.

Average (51%-65%):

Exterior

Score is average.

The building has two covered entries that are less than 50 feet apart, which makes it difficult for visitors to know where to enter. Large trees create a pleasant environment at the front of the school but obscure the main building signage. The campus has plenty of spaces that have the potential to be excellent outdoor learning environments. The partially covered central courtyard presents a great opportunity, if technology and acoustical issues could be improved.

General Building

Score is average.

The building is well configured for hosting community events; both the Library and Cafeteria are frequently used for after-school functions. The building's configuration around the large central courtyard means visitors can access the library and theater without gaining entry to the rest of the school. Hallways and circulation paths are wide enough to accommodate student circulation. Covered ramps and an elevator give accessible pathways for students to get to most studios.

Security

Score is average.



Environmental Quality

Score is average.

Acoustics in the studios is average, with some noise heard from outside rooms. Some studios had return air grilles into the hallways, which presents sound issues. Although 50% of studios have exterior windows, these windows are small and often have limited views. Artificial lighting is adequate, although the controls are limited to on or off. There is evidence of pests entering the building and working their way through ceilings and cabinets.

Academic & Co-Curricular Support

Score is average.

Educational Suitability Summary Report

Bedichek Middle School

The school's studios are almost all a single open space with limited flexibility for rearranging. Many of the studios have inadequate storage and little to no support spaces. The learning neighborhoods do not have breakout spaces for small groups. Due to lack of visibility from studios, teachers cannot supervise students outside the studio. The school has one dedicated space designed for group projects and collaboration.

CTE and Career Connected Learning

Score is average.

The Facilities Master Plan identifies seven CTE and Career Connected Learning courses to be offered at the campus. Of those courses identified, four are not currently offered per discussion with administration and staff which are listed below:

- Architecture and Construction
- Arts, Audio and Technology and Communications
- Business, Management and Administration
- Science, Technology, Engineering and Mathematics

Satisfactory (66%-80%):

Outdoor Learning and Activity

Score is satisfactory.

The interior courtyard can provide multiple opportunities for outdoor studios, but upgrades to furniture and technology are required.

Visual and Performing Arts

Score is satisfactory.

Band and orchestra spaces are satisfactory, but dance and visual art studios are unsatisfactory. Dance takes place in a converted studio without any support spaces, and the current art studios are to be renovated in January 2021.

Athletics and Wellness

Score is satisfactory.

Athletic facilities are in good condition, and the school has a full-size track and field. Both gyms floors are in excellent shape and locker rooms have ample space for team meetings. The facilities support practice for outdoor UIL sports, but there is no spectator seating for games / matches.

Food Services

Score is satisfactory.

The cafeteria and kitchen are adequately sized. The cafeteria furniture does not provide variety in seating options.

Media Resources

Score is satisfactory.

The Library/Media Center is centrally located, spacious, and well equipped with technology. Flexible furniture allows the large open space to be rearranged to support collaboration for groups of various sizes. Breakout space for individuals or small group activity is limited to one enclosed conference room. A significant portion of the library space is dedicated to a computer lab for students. The room has multiple projectors and several mobile television screens.

Bedichek Middle School

Administration Spaces

Score is satisfactory.

administration space feels welcoming despite the limited number of exterior windows. The two conference rooms available for public/parent use are somewhat remote and do not have good transparency.

Very Satisfactory (81%-100%):

Furniture, Fixtures, Equipment

Score is very satisfactory.

The school has a diverse collection of furniture of different types and ages, but as part of the 2017 Bond Program, the school will be receiving new furniture in the summer of 2021. The new furniture will be flexible and allow for multiple types of furniture configurations within learning spaces. The current library is well equipped with moveable bookshelves, tables, and seating that give ample flexibility. Several the science studios are using heavy, immobile lab tables that are more than 50 years old, and it is assumed those will remain.

Educational Suitability Summary Report

Bedichek Middle School



Building Entry – Main Building Signage



Interior Circulation - Accessible Ramps in Central Courtyard Space

Educational Suitability Summary Report

Bedichek Middle School



Technology - Library Media Center is well equipped.



Environmental Quality – Small windows do not provide adequate natural light in studios and furniture is not flexible.

Educational Suitability Summary Report

Bedichek Middle School



School Pride - Murals throughout the campus show pride in student community



Furniture - Original Lab Tables in disrepair, these are heavy and immobile



Educational Suitability Summary Report

Bedichek Middle School



STEAM-learning space for woodshop and robotics



Outdoor Learning - Existing outdoor theater needs maintenance and is close to the street

Educational Suitability Summary Report

Bedichek Middle School



Outdoor Learning – Existing space disrupted by noisy mechanical equipment and no shade is provided.



Evidence of Learning – Display artifacts of learning at each studio cluster

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Bedichek Middle School	Travis Hughbanks and Kevin Kinsey	10.21.2020

Ī	- Exte	rior		1	2	3	4	5	N/A	Ą	8.75	60%
	11	pes the sit	e permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen							Bus drop at front and parent drop in back but some p	arents drop in	front
			at the same location							and kids cross bus traffic. When buses are lined up fo	r pickup, cars i	n visitor
		2	Unsatisfactory - Cars and buses mix, pedestrians are separated							parking area are blocked in and cannot leave.		
		3	Average - Buses, cars, and pedestrians are separate but stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply									
			ng easily identified with appropriate signage and wayfinding?			3				Comments	0.25	0.75
		1	Very unsatisfactory - Campus has no signage /							Two front entry points and it is difficult to tell which is	primary. Signa	age on
			wayfinding							building not visible through trees.		
		2	Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not good condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									

02/11/2022 ²

1 - Exterior (co	ont.)	1	2	3	4	5	N/A	· · · · · · · · · · · · · · · · · · ·		
1.3 Is the dum	npster accessible for trash / compost disposal?			3				Comments	0.50	1.50
1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							Composting is located at a loading dock outside the barrier free. To open the compost bin you must be or there is not an ADA ramp.		
N/A	Does not apply earning and Activity	1	2	3	4	5	N/A		10.00	80%
	por studios and support spaces appropriately configured per			3	4		A VI	Comments	10.00	3.00
1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Plenty of space at interior courtyard; needs furniture support learning environment. No transparency from	-	
22	Does not apply playgrounds (elementary only) and support spaces d per the ed spec?						N/A	Comments	0.00	0.0
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

02/11/2022 ³

- Outdoor	Learning and Activity (cont)	1	2	3	4	5	N/A	A	
	dens and support spaces appropriately configured per the ed evaluation on infrastructure not condition of plants)				4			Comments 0.00	0.0
1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learning an Activity.	d
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
N/A	Does not apply					1		1	
Are the ed spec	rain gardens and/or cisterns appropriately configured per the ?		2					Comments 0.00	0.0
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor Learning an	d
2	Unsatisfactory - Too small, poor condition, not							Activity. Two 50-gallon drums connected to roof down spouts in a	
	functioning, disconnected							constrained location.	
3	Average - Adequate size, adequate condition, is								
	connected, needs some renovations or updates to function well								
4	function well Satisfactory - Good size, good condition, functions								
4	properly								
5	Very Satisfactory - Generous size, excellent condition,								
-	exceptional functionality, connected to learning spaces,								
	educational signage provided								
N/A									
2.5 Does th	e school have animal husbandry? (optional)	1						Comments 0.00	0.
1	No								
5	Yes								
2.6 Does th	e school have nature loop trails? (optional)					5		Comments 0.00	0.
1	No								
5	Yes								
2.7 Does th	e school have a learning pond? (optional)					5		Comments 0.00	0.
1 5	No Yes								
2.8 Does th	e school have a grass play field and walking trail?					5		Comments 1.00	5.
1	No								
	Yes								

8 - General Bu	lilding	1	2	3	4	5	N/A	Λ	11.25	64%
Are interio	r circulation routes wide enough to safely and effectively					5		Comments		
accommod	date student movement?					5		Comments	0.50	2.5
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Primary circulation throughout the school is through	the exterior	
	wide							courtyard/breezeways, which has very wide walkway	ys.	
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are comm	unity use areas arranged so that the school can allow night					1		_		
2.0	vithout full school access?				4			Comments	0.75	3.0
1	Very unsatisfactory - Cafeteria, gym, and library cannot				1		1	The theater and library have direct access to the cen	tral courtvard.	which
	be accessed after hours							allows easy public access and all other doors can ren	-	
2	Unsatisfactory - Only one of the public spaces (Cafeteria,							cafeteria is connected to the courtyard via a corridor		
	Gym and Library) can be accessed from parking and							some studio spaces.		
	secured after hours									
3	Average - Only two of the public spaces can be accessed									
	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building									
_	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
NI/A	campus for night/evening use with their own entrance									
N/A	Does not apply		1		1	1	1		1	
3.3 Is there a c of school fi	community room that is a dedicated meeting space outside	1						Comments	0.75	• •
									0.75	0.7
1 2	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school							Community uses library and cafeteria but no dedicat	ted community	room
2	function, no access after school hours									
3	Average - Community room, moderate size, but need									
Ũ	some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
	function									
N/A	Does not apply								-	
< /l	eneral appearance of the school convey pride for the				4			Comments		
students a	nd community?				-			Commenta	0.25	1.0
1	Very unsatisfactory - General appearance is poor									
2	Unsatisfactory - General appearance is aged but ok									
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
	campus and student works									
5	Very satisfactory - General appearance shows pride in									
	campus and student works and is welcoming to the									
N/A	community									
	Does not apply									

		<u> </u>		T T	Ά	16.25
I.1 Does the fo	acility have key card access at all major entries?				Comments	0.25
1	Very unsatisfactory - No entries			<u> </u>)	
2	Unsatisfactory - 1/4 of major entries					
3	Average - 1/2 of major entries					
4	Satisfactory - 3/4 of major entries					
5	Very satisfactory - All of major entries					
N/A	Does not apply					
.2 How adeq	uate is site lighting and security for the campus overall?				Comments	1.00
1	Very unsatisfactory - No exterior lighting, no secure		1			1.00
	perimeter					
2	Unsatisfactory - Lighting is limited to front entry only,					
	parking lot lighting poor, security is minimal					
3	Average - Lighting at all night-use entries and parking					
	lot, but poor condition. Security is moderate					
4	Satisfactory - Lighting at all night-use entries and					
·	parking lots, good condition, signage less visible,					
	perimeter is well secured but needs updates					
5						
	Very satisfactory - Signage, parking lots, and entries are					
	well lit, visible and easy to use, perimeter is very secure					
N/A	Does not apply			- <u>,</u> ,		-
	n office located at the school entry and configured with a				Comments	
secure vest	tibule to the main corridor?				Commenta	1.00
1	Very unsatisfactory - No secure vestibule, office located					
	far from main entry, allows visitors access to school					
	unsupervised					
2	Unsatisfactory - No secure vestibule, office located					
	somewhat far from main entry, minimal supervision of					
	visitors					
3	Average - Office close to entry, views of front door, but					
4	no secure vestibule					
4	Satisfactory - Office is well-located with a secure vestibule, but needs updates					
5	Very satisfactory - Office well-located with secure					
0	very satisfactory - Once wen-located with secure vestibule and all appropriate security features					
	Does not apply				L	
N/A						
N/A		1 1 1				
ls there end	ough interior transparency for faculty to passively supervise	1			Comments	100
Is there end learners ar	ough interior transparency for faculty to passively supervise nd their activities who are not in studios?	1				1.00
Is there end learners ar 1	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls				Comments Majority of studios have no transparency to corrido	
I.4 Is there end learners ar 1 2	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations					
Is there end learners ar 1	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but					
I.4 Is there end learners ar 1 2 3	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school					
I.4 Is there end learners ar 1 2	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the					
I.4 Is there end learners ar 1 2 3 4	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the school					
I.4 Is there end learners ar 1 2 3	ough interior transparency for faculty to passively supervise nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the					

Environmental Quality	1	2	3	4	5	N/	ΎΑ	25.00	56%
.1 How are acoustics in studios in general?			3				Comments	1.00	3.00
1 Very unsatisfactory - Recognized word/sound from				1					
adjacent studio/corridor									
2 Unsatisfactory - Audible sound from adjacent									
studio/corridor									
 Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise 									
from mechanical system									
5 Very satisfactory - Able to hear quiet speaking from									
across the room									
N/A Does not apply		r		-			1		
2 Is the studio artificial lighting adequate quality?			3				Comments	1.00	3.00
1 Very unsatisfactory - Sporadic lights work, glare, less									
than 20 FC									
 Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare 									
4 Satisfactory - 30-39 FC and no glare									
5 Very satisfactory - 40+ FC and no glare									
N/A Does not apply									
.3 Is there access to natural light in studios?			3				Comments	1.00	3.00
1 Very unsatisfactory - No learning spaces have natural		1	<u> </u>	1	1		Over 50% of studios have natural light but windows		
light							only limited natural light.		
2 Unsatisfactory - 1-25% of learning spaces have natural									
light or windows are too small to let in light									
3 Average - 26-50% of learning spaces have natural light									
4 Satisfactory - 51-75% of learning spaces have natural									
light 5 Very satisfactory - 76-100% of learning spaces have									
natural light									
N/A Does not apply									
.4 Is there access to outside views from learning spaces?			3				Comments		
			0					1.00	3.00
Very unsatisfactory - No learning spaces have views							Majority of studios have small or no windows. Most	of the windows	are too
2 Unsatisfactory - 1-25% of learning spaces have views or							small for a true view outside.		
windows are too small to see out									
3 Average - 26-50% of learning spaces have views									
3 Average - 26-50% of learning spaces have views									

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	A contract of the second se		
5.5	Does the bu	uilding have odor or pest problems?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							Evidence of pests entering from the exterior and com ceiling and upper cabinets. Staff brought up ongoing control in the main building. No noticeable odor.	0 0	
6 - 0	ontrollabi	lity of Systems	1	2	3	4	5	N/A	A Contract of the second se	12.50	36%
6.1	Does the st	udio thermostat allow for individual control?	1						Comments	0.50	0.50
	1 5	No Yes		I	1						
6.2	Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades							Mini blinds in studio exterior windows.		
	N/A	Does not apply						1			
6.3	What is the	quality of lighting controls in the studios?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply			<u>.</u>			<u> </u>	There is no dimming or alternate switching provided.		

7 - Furniture,	Fixtures & Equipment	1	2	3	4	5	N/A		18.75	89%
7.1 What is th	e current condition of the furniture?					5		Comments	0.75	3.75
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply			<u> </u>	<u> </u>		<u> </u>	Furniture for the most part is in good working conditi- conducive to modern teaching methods. 2017 Bond N to be completed by Perkins&Will in Summer 2021. The category is based on this upcoming scope of work.	lote: Furniture	
	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?				4			Comments	1.00	4.00
1	Very Unsatisfactory - Same furniture used in all spaces									
2	Unsatisfactory - Furniture variety in one multi-use space									
3 4 5 N/A	Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture Does not apply									
7.3 How well a space?	does furniture accommodate rapid reconfiguration of a				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply							Some studios have new flexible tables and chairs but chairs with tablet arms. New flexible furniture will acc group sizes.		
7.4 Is the furn	iture ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
1 2 3 4 5	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow		1	1			1	All attached desk / chair combinations to be removed		5.00
N/A	students to be active Does not apply								92.50	

02/11/2022 °

Naste		1	2	3	4	5	N/A	· · · · · · · · · · · · · · · · · · ·	5.00	70
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?		2					Comments	0.50	1.0
1 2 3	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.							A score for this category is being recorded, but this categoral calculated in the overall ESA average. No signage or instructions for bins. Recycling bins are inf corridors but are in the majority of studio spaces.		
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply			1	- 1					
of each: gr	afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?					5		Comments	0.50	2.5
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.			1				At each tray-drop location there are student-made post what can be composted, recycled, and what goes to the	-	ng
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
3	three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as									
	three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Bedichek Middle School	Travis Hughbanks and Kevin Kinsey	10.21.2020

8 - Academ	ics & Learning	1	2	3	4	5	N/A	A	65.00	52%
8.1 Are stud	lios appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility,							Studios are typically one large open space. Limited to	o no transparei	ncy to
	disconnected							corridors. Varying levels of natural light. Multiple stud	lios have no no	atural
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							light.		
3	Neutral - Adequate size, multiple areas for different									
	teaching methods, adequate flexibility, limited									
	transparency and connection to other studios and									
	shared learning spaces, needs updates or renovations to									
	function well.									
4	Satisfactory - Good size, multiple areas for different									
	teaching methods, good flexibility, good transparency and connection to other studios and shared learning									
	spaces									
5	Very Satisfactory - Generous size, multiple areas for									
	different teaching methods, excellent flexibility, generous									
	display area and visual teaching tools, excellent									
	transparency and connection with other studios and									
	shared learning spaces									
N/A										
X 7	ios have appropriate support spaces such as storage per the		2					Comments		
ed spec			2					conments	1.00	2.00
1	Very unsatisfactory - None provided							Limited to no support spaces for studios. Limited store	age, access to	PLC and
2	Unsatisfactory - Too small, disconnected, poor condition							no access to breakout collaboration. Limited access t	o outdoor lear	ning.
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

02/11/2022 ²

8 - Academi	cs & Learning (cont.)	1	2	3	4	5	N/A			
8.3 Do typic	al learning neighborhoods have small and medium (high	1						Comments		
o.o school o	nly) group rooms and open collaboration space?	I						Comments	1.00	1.00
1	Very unsatisfactory - No breakout rooms or open							No breakout spaces provided for studios. No group r	ooms or open	
	collaboration spaces are provided							collaboration spaces.		
2	Unsatisfactory - Too small or too few, poor condition, no									
	flexibility, lacks visual connection to learning									
	neighborhood, poor acoustic privacy									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition and flexibility,									
	transparency and connection to learning neighborhood,									
	acoustic privacy									
5	Very Satisfactory - Generous size, excellent condition and									
	flexibility, transparency and connection to learning									
	neighborhood, acoustic privacy									
N/A						1				
87	nce Labs and support spaces appropriately configured per			3				Comments		
the ed s				0				commenta	1.00	3.00
1	Very unsatisfactory - No dedicated science room							Two science labs are very outdated and need to be f	ully renovated	to be
2	Unsatisfactory - Too small, poor condition, no connected							brought up to Ed Spec standards. Other labs are in g	ood condition	but lac
	support space							the Ed Spec's required flexibility.		
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition, connected									
_	support spaces									
5	Very Satisfactory - Generous size, excellent condition,									
N1/A	connected support spaces									
N/A			-	-		1	-		1	
	er Spaces and support spaces appropriately configured per			3				Comments		
	pec? (cross reference with CTE below)								1.00	3.00
1	Very unsatisfactory - No dedicated maker spaces							Large flexible space with movable tables and perime	eter casework b	out not
2	Unsatisfactory - Too small, poor condition, disconnected							well connected to other learning spaces.		
	from learning spaces, no flexibility									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition, connected to									
	learning spaces									
5	Very Satisfactory - Generous size, excellent condition,									
	connected to learning spaces Does not apply									
N/A										

02/11/2022 ³

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A	<u>\</u>		
8.6 Is there a Professional Learning Center in the learning neighborhood?		2					Comments	1.00	2.00
 Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected 							Some teacher work spaces provided but not well dist	ributed and sn	nall in
8.7 Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?			3				Comments	1.00	3.00
 Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition N/A Does not apply 							Multiple locations to display student work but they ne entry point of each studio pod there is an area for stu displayed.		
Does the building / learning neighborhood provide adequate 8.8 opportunities for students/teachers to collaborate in varying group sizes?		2					Comments	1.00	2.00
 Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes 							No small or medium group learning spaces provided open collaboration areas in close proximity to studios		dio. No
N/A Does not apply 8.9 Does the building provide opportunities for informal interaction?		2					Comments	1.00	2.00
 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. 							Central courtyard is the only opportunity for informal furniture does not encourage interaction.	l interaction bu	ıt
 Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, 									
layout and furnishings support informal interactions N/A Does not apply									



	Does the h	uilding provide adequate opportunities for students to		[1				
8.10	work indep		1					Comments	1.00	1.4
	1	Very unsatisfactory - No breakout rooms/small study		1						
		spaces								
	2	Unsatisfactory - Too small, poor condition, no acoustic								
		privacy, only one space for independent work,								
		disconnected from learning neighborhood								
	3	Average - Adequate size and condition, needs updates								
		or renovations to function well.								
	4	Satisfactory - Good size and condition, acoustic privacy,								
		variety of independent work space options, connected to								
		learning neighborhood								
	5	Very Satisfactory - Generous size, excellent condition,								
		acoustic privacy, variety of independent work space								
		options, connected to learning neighborhood								
	N/A	Does not apply								
	Special Edu	ucation		1		T	1	1		
8.11		Education spaces appropriately configured per the ed			4			Comments		
0.11	spec?				-			Commenta	1.00	4.
	1	Very unsatisfactory - Too small, no flexibility,						Ample special education spaces. Both studio and livi	ng area were	recen
		disconnected						constructed and fall in line with Ed Spec. Areas lackir	ig are transpa	arency
	2	Unsatisfactory - Too small, only one area for all teaching						and connectivity to other studios and shared learning	g spaces.	
		methods, limited flexibility, disconnected								
	3	Neutral - Adequate size, multiple areas for different								
		teaching methods, adequate flexibility, limited								
		transparency and connection to other studios and								
		shared learning spaces, needs updates or renovations to								
		function well.								
	4	Satisfactory - Good size, multiple areas for different								
		teaching methods, good flexibility, good transparency								
		and connection to other studios and shared learning spaces								
	5	spaces Very Satisfactory - Generous size, multiple areas for								
	5	different teaching methods, excellent flexibility, generous								
		display area and visual teaching tools, excellent								
		transparency and connection with other studios and								
		shared learning spaces								
	N/A	Does not apply								
8.12	Are Special	Education support spaces, such as storage, space for			4			Commente		
0.12	washer/dry	ver, appropriately configured per the ed spec?			4			Comments	1.00	4
	1	Very unsatisfactory - None provided								
	2	Unsatisfactory - Too small, disconnected, poor condition								
	3	Neutral - Adequate size, average condition, needs								
		updates or renovations to function well								
	4	Satisfactory - Good size, connected, good condition								
	5	Very Satisfactory - Generous size, connected, excellent								
		condition								
	N/A	Does not apply								


8 - Academics	& Learning (cont.)	1	2	3	4	5	N/A			
	ble restrooms and changing rooms readily available to the acation spaces?					5		Comments	1.00	5.00
1	No								1.00	0.00
5	Yes									
STEAM Cer	iter									
8.14 Does the co	impus have space to support a "STEAM" center?		2					Comments	0.00	0.00
1	Very unsatisfactory - No available space for STEAM							Monitoring answer, but does not count towards over	all score	
2	center and inadequate studio / collaborative space Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size Neutral - Collaborative areas / studios for CTE/CCL are							Limited options for space for a STEAM center and op in close proximity to studios.	tions are not lo	ocated
3 4	adjacent but function separately Satisfactory - Collaborative areas / studios for CTE/CCL									
5	function and have space availability to create STEAM center Very Satisfactory - Functioning STEAM center offers									
, i i i i i i i i i i i i i i i i i i i	studios, labs, common collaborative areas to support multimedia distance and hands-on project based									
N/A	learning Does not apply									
	reer Connected Learning								8.75	54%
How close i	s your campus to a CTE cluster pathway that is aligned		1	1					0.1.0	••
9.1 with your C	TE programs (Middle School only)?				4			Comments	1.00	4.00
1	Very unsatisfactory - No correlation to CTE cluster							Bedichek feeds to Akins, Crockett, Travis ECHS where	all CTE progra	ıms are
2	pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE							offered.		
	programs that are listed in the cluster pathway.									
3	Average - School support half of CTE programs listed in the cluster pathway, but missing some.									
4	Satisfactory - School support a majority of CTE programs									
	listed in the CTE cluster pathway.									
5	Very Satisfactory - School is aligned with CTE cluster pathway.									
N/A	Does not apply									
0.0	facilities align with the CTE Ed Spec Requirements for the hways offered?: Architecture and Construction	1								
1	No								0.25	0.25
5	Yes									
N/A	Does not apply		•							
9.3 Arts, Audio	and Video Technology and Communications	1							0.25	0.25
9.4 Business, M	lanagement and Administration	1							0.25	0.25
9.5 Education of	and Training						N/A		0.00	0.00
9.6 Health Scie	nce						N/A		0.00	0.00

02/11/2022	6	
------------	---	--

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A		
9.7 Hospitality and Tourism					5		0.25	1.25
9.8 Human Services (high school only)						N/A	0.00	0.00
9.9 Information Technology					5		0.25	1.25
9.10 Agriculture, Food and Natural Resources						N/A	0.00	0.00
9.]] Science, Technology, Engineering, and Mathematics	1						0.25	0.25
9.12 Transportation, Distribution and Logistics					5		0.25	1.25
9.13 Finance (high school only)						N/A	0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						N/A	0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						N/A	0.00	0.00
9.16 Manufacturing (high school only)						N/A	0.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A	0.00	0.00
10 - Visual and Performing Arts							35.00	69 %
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments 0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.	
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?					5		Comments 1.00	5.00
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition N/A Does not apply 								
10.3 Are orchestra and support spaces appropriately configured per the ed spec?				4			Comments 1.00	4.00
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition N/A Does not apply 					<u>.</u>	·	Only one practice room for orchestra, ed spec requires 4. However, orchestra is adjacent to auxiliary band room, which has three pract rooms that can be shared.	

10 - Visual and	Performing Arts (cont.)	1	2	3	4	5	N/A	A		
10.4 Are choir an spec?	nd support spaces appropriately configured per the ed			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Missing MIDI lab. Adequate spaces but needs update	e. Has built-in t	iered
2	Unsatisfactory - Too small, poor condition							floor, which creates ADA accessibility issues.		
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply		1	1			r			
10.5	and support spaces appropriately configured per the ed	1						Comments		
spec?									1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces							Dance is in a typical studio with no other dedicated s	upport spaces.	Dance
2	Unsatisfactory - Too small, poor condition							shares the theater stage for practice space.		
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1	1	1	-	1	r		[
	r and support spaces appropriately configured per the ed					5		Comments	1.00	
spec?									1.00	5.00
	Very unsatisfactory - Too small, missing program spaces							School has dedicated theater with tiered seating as w	-	-
2	Unsatisfactory - Too small, poor condition							the cafeteria. Generous sizes, numerous spaces, and	in good condit	ion.
3	Neutral - Adequate size, adequate condition, needs									
4	updates or renovations to function well.									
5	Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
	arts and support spaces appropriately configured per the	1			1	<u> </u>				
10.7 ed spec?		1						Comments	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces				1			There is a graphics lab as part of the A/V studio but r		
2	Unsatisfactory - Too small, poor condition							spaces are provided. There is one dedicated art room		
3	Neutral - Adequate size, adequate condition, needs							usable due to mold issues. It is expected that the art i	room should be	÷
-	updates or renovations to function well.							renovated by January 2021.		
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
D										
	ampus have adequate space for the specialty arts Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments		
programs (Ensemble, Guitar, Music studies, Music theory and Plano)?								1.00	5.00
1	No							The campus has a dedicated guitar studio.	-	
5	Yes									

11 - Athletics and Wellness						18.75	73%
11.1 Does the campus meet ed spec standard for physical education program spaces?			5		Comments	1.00	5.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply					All athletic spaces are in great condition and are gene gym floors are in excellent shape and boys'/girls' lock open spaces for team meetings.		
11.2 Does the campus have a dedicated wellness center?			5		Comments	0.50	2.50
1 No 5 Yes							
11.3 Does the community have access to exterior playfields/courts?			5		Comments	0.50	2.50
1 No 5 Yes	1			1			
11.4 Are facilities available to facilitate eSports (High School only)?				N/A	Comments	0.00	0.00
1 No 5 Yes					Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			5		Comments	0.25	1.25
1 No 5 Yes							
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1				Comments	0.25	0.25
1 No 5 Yes					6 lane track but no spectator seating		
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1				Comments	0.25	0.25
1 No 5 Yes					supports practice but no spectator seating		
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			5		Comments	0.25	1.25
1 No 5 Yes							
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1				Comments	0.25	0.25
1 No 5 Yes					only two courts		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1				Comments	0.25	0.25
1 No 5 Yes					supports practice but no spectator seating		



II - Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
Are facilities (dedicated storage) set up to support UIL sanctioned athletics for cross-country (high school only)?						N/A	Comments	0.00	0.
1 No 5 Yes									
Are facilities (dedicated storage) set up to support UIL sanctioned athletics for golf (high school only)?	Γ					N/A	Comments	0.00	0.
1 No 5 Yes	1								
Are facilities (dedicated storage) set up to support UIL sanctioned athletics for swimming (high school only)?						N/A	Comments	0.00	0.
1 No 5 Yes	1								
Are facilities set up to support UIL sanctioned athletics for wrestling (high school only)?						N/A	Comments	0.00	0
1 No 5 Yes									_
Are facilities set up to support UIL sanctioned athletics for baseball (high school only)?						N/A	Comments	0.00	0
1 No 5 Yes									
Are facilities set up to support UIL sanctioned athletics for softball (high school only)?						N/A	Comments	0.00	0
1 No 5 Yes									
Are facilities (dedicated space outside of the gymnasium) available to support competitive spirit activities for cheerleading and drill team?	1						Comments	0.25	c
1 No 5 Yes									
- Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
How do the athletics fields align with FMP Campus Improvements? 1.18 Turf Field, Parking lot lighting, ADA accessible amenities (high School only)						N/A	Comments	0.00	0
1 Very unsatisfactory - No turf, inaccessible, no site lighting		1	1				Monitoring answer, but doesn't affect overall score.	0.00	
2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting									
3 Average - Field in adequate condition, needs some updates or renovations to function well									
4 Satisfactory - Turf field in good condition, good ADA access and site lighting									
5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes,									
excellent site lighting N/A Does not apply.									

2 - Food Services								10.00	70%
12.1 Is the Dining Commons appropriately configured per the ed spec?				4			Comments	1.00	4.0
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) N/A Does not apply 							Large open space in good condition but scale is not varying furniture. Dining area is not set up to encour utilized throughout the day as a learning environme	age space to b	
Are the Food Services support spaces appropriately configured per the ed spec?	Γ		3				Comments	1.00	3.0
 Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition 							No dedicated chair storage. Kitchen and serving line	s are adequate	e.
N/A Does not apply		•	•		_				
3 - Media Resources 13.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?		2	3	4	5	N/A	Comments	30.00	73 [°] 4.0
 Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition N/A Does not apply 		-					Limited transparency to main courtyard and circulat and centrally located.	ion. Very easy t	to find

13 - Media Rese	ources - Continued	1	2	3	4	5	N/A	A		
13.2 How well do	pes the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy							No breakout spaces other than one conference room space without defined zones of quiet and group stud		en
N/A 13.3 How well do	Does not apply bes the Library/Media Center support social interaction?					5		Comments	1.00	
1 2 3 4 5 N/A	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply							Very flexible, generously sized open space that can a groups. Furniture and stacks are movable for flexibilit		5.00 arge
How well do	pose the Library/Media Center support collaborative work ups (4-8 students)?			3			Γ	Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition							Only one enclosed space, which is a conference room		
	Does not apply bes the Library/Media Center support collaborative work bups (10-25)?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply							Very flexible, generously sized open space that can a groups. Furniture and stacks are movable for flexibilit		

13 - Media Res	sources - Continued	1	2	3	4	5	N/A	A Contract of the second se		
13.6 How well d	does the Library/Media Center support technology?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition Does not apply							No smart board but has 3 projectors and multiple m provided throughout for easy charging. Wi-Fi is stron		Power
14 - Technolog	JY	1	2	3	4	5	N/A	,	20.00	50%
14.1 How well e	equipped are the facilities with instructional technology?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition Does not apply							Every studio has a mobile flat-panel screen and a m have projectors and screens.		
	adequate number of power and data outlets in learning		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)		<u>.</u>	<u>.</u>	·			Varies space to space, but in general, power is not a one learning environment, where each student has t provided by the district.	•	

14 - Technolog	ıy (cont.)	1	2	3	4	5	N/A	A		
14.3 Are there adequate charging locations for devices?			2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school									2.0
N/A	to support 1:1.									
	Does not apply equate AV for presentations spaces – cafeteria, gym, aux		2		T			Comments	1.00	2.0
1 2	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition							Manual drop-down screens are present but PA and p and not dedicated for each space.	projectors are r	nobile
3 4	Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition.									
5 N/A	Condition. Very Satisfactory - AV adequately sized for room. Excellent condition. Does not apply									
14.5 Is there digital media signage at the reception area?						5		Comments	0.00	0.0
1 2 3 4 5 N/A	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply							Large flat screen behind reception desk.		

5 - Administi	ration Spaces	1	2	3	4	5	N/A	<u> </u>	20.00	80
15.1 Is there a visitors?	reception area that functions as a security checkpoint for all							Comments	1.00	
1 2 3 4 5 N/A	Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply									
	administration area feel welcoming?				4			Comments	1.00	4.
1 2 3 4 5	Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition						1	Very welcoming administration area, but limited nat reception area and offices in general.		
5 3	Does not apply spaces that require it, does the administration area have e acoustic privacy?				4			Comments	1.00	4.
1 2 3 4 5 N/A	Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations function okay, but portions need updates or renovations Satisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Does not apply						.	Majority of space is adequate acoustically but couns well soundproofed from the attendant/waiting area	selor offices are	-
15.4 Are conference rooms easily accessed for public / parent use?				3				Comments	1.00	3.
1 2 3 4 5 N/A	Very unsatisfactory - Not accessible for public/parent use Unsatisfactory - Limited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Good accessibility, good transparency, good size and condition Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition Does not apply							Two conference rooms. Larger conference room isolo section of admin with little transparency. Neither con good transparency.	•	