

Educational Suitability Summary Report

Clifton Career Development School

Date: 10/30/2020 Score 50% Unsatisfactory

Clifton Career Development School serves approximately 250 high school students who receive instruction in the areas of career and technical curriculum within the AISD special education program. The school was built in 1977 and supports agriculture, culinary arts, health science, horticulture, hospitality and mechanics programs. The school also offers a career practicum to help students gain employment.

Interview Overview

Principal Tony Dishner and other staff members were present for the interview. The campus focuses on providing special education students with career and technical courses. Principal Dishner informed us that the Texas Education Agency (TEA) is eliminating CTE special education, so the programs and capacity at Clifton will need to be expanded so that the school can become a district-wide CTE hub for all students while still serving special education students. It is expected that Clifton will need to expand to serve 800-900 students.

The culinary program is hampered in getting new equipment due to existing infrastructure for the ventilation hood. Fryers are needed but cannot be installed due to code requirements with existing hoods. The horticulture program needs updates to the aging greenhouses and systems that are not fully functioning. Greenhouse temperature regulation is inconsistent with current equipment. Floral design and landscape design are taught in a portable that has a rotting floor, and the exterior siding is deteriorating. They would like to expand the culinary garden. The staff expressed other needs such as an expanded health sciences area to accommodate multiple hospital beds; a room for certification testing; more labs; and a mass production and teaching greenhouse. There is also space on the campus where a "mini expo center" could be located for district-wide animal showing competitions.

The staff also has security and safety concerns. Electrical circuits are often overloaded and trip breakers.

Learning spaces are mostly adequate but lack ADA-accessible restrooms.

Transforming this campus to a hub for all students will involve the upgrades listed above as well as new programs and spaces for the expanded population. Their requests include an agriculture center with a barn, flex space, studio and performance show arena; more studio spaces and support for added programs connected to the labs they serve; cosmetology program space; construction management studio and lab; small engines Lab; expanded health sciences simulation and certification labs; expanded greenhouses and outdoor garden areas; and campus-wide accessibility and infrastructure upgrades.

Educational Suitability Summary Report

Clifton Career Development School

Assessment Findings

The Educational Suitability Assessment of Clifton Career Development School earned a 50% overall score and places the campus in a category of unsatisfactory. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention. (Categories that do not apply to this facility include Visual and Performing Arts, Athletics and Wellness, Media Resources and Food Services.)

Very Unsatisfactory Categories (0-35%):

Exterior

Score is very unsatisfactory.

Bus drop-off and main entrance are the same. Only one loop and has very short stack space. Staff parking is separate and distant from front entry. Signage on building is visible but not apparent. No street marquee or other signage to identify the building. No compost. Trash and recycling are far from building and there is a ramp from the loading dock to parking lot level.

Outdoor Learning & Activity

Score is very unsatisfactory.

Outdoor spaces for learning do not have space with seating. Large garden area with greenhouse and studio is configured well but needs updates and is disconnected from the rest of the school.

Academics & Learning

Score is very unsatisfactory.

Learning neighborhood studios are adequately sized, but dated accordion partition separates adjacent studio, limiting ability to have multiple learning areas. Studios have built-in casework with limited mobile storage. There is a lack of collaboration spaces within learning neighborhoods. No furniture is provided for informal interaction in circulation spaces. Multiple rooms for different programs have same configuration. Special education areas are in typical studios. Campus has not been updated for needed ADA spaces.

Unsatisfactory Categories (36-50%):

General Building

Score is unsatisfactory.

Primary circulation to studios is less than 7 feet in width. Larger corridor at main entry of building only. Small, centralized gathering space is present but only accessible through main entry. New carpet, wall base and paint in studios and corridors, but most spaces are aged with old, movable partitions that allow sound to transmit easily.

Controllability of Systems

Score is unsatisfactory.

Studios do not have individual thermostats. Blinds are present in studios, but in poor condition. Single switch for lighting in studios.

Technology

Score is unsatisfactory.

Perkins&Will

Educational Suitability Summary Report

Clifton Career Development School

Mobile flat panels are available in most spaces but appear to be the only provided technology. An old television with a VCR was observed in one studio. Typical outlet configuration in typical studio with limited capacity (approximately three per wall). Cafeteria projection screen is too small compared to the size of the space. There is no digital media signage present at the reception area.

Average Categories (51-65%):

Security

Score is average.

Furniture, Fixtures, Equipment

Score is average.

Mix of old and new, but in good condition. May not support all students with special needs. No variety of seating for informal/soft seating in common spaces. Furniture is not easily movable due to age and weight. Most furniture is sized for appropriate grade levels.

Administration Spaces

Score is average.

Administration area is small, lacks area for seating and does not feel welcoming. Conference room is centrally located near main entry but needs updating for transparency.

Satisfactory Categories (66-80%):

Environmental Quality

Score is satisfactory.

Acoustics between adjacent studios are poor due to aged movable partitions. Artificial light levels are average with minor glare on some surfaces. Most spaces have access to outside views and natural light. No evidence of pests or odors and appears very clean.

Very Satisfactory Categories (81-100%):

CTE and Career Connected Learning

Score is very satisfactory.

Clifton is a specialty school with CTE programs for specific populations and career development and training. (Principal noted that TEA is eliminating CTE special education, so programs will have to begin to comply with general CTE standards.)


Not Applicable Categories: Visual and Performing Arts, Athletics and Wellness, Media Resources, Food Services

Clifton Career Development School



Main entry of school.






Clifton Career Development School



Outdoor learning space with greenhouse.




Greenhouses for horticulture, floral design and landscape design.





Front Entry: Narrow corridors with only one wide area at front entry.







Clifton Career Development School





Typical studios with dated accordion partition. Typically kept closed due to sound transmission.







No restroom on campus appears to have adequate ADA accessibility. Accessibility will be covered within the Facility Condition Assessment but is noted here since it does not create an equitable use of space for all students.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Clifton Career Development School	Anacleto Rojas Jr and Emilie Ogburn	10.22.2020

1 - E	xterior		1	2	3	4	5	N/A	4	8.75	26%
1.1	Does the sit	e permit desirable separation of vehicular, bus and traffic?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Bus drop-off and main entrance are the same. Staff	parking is sepo	arate in
		at the same location							the back of school and there is no visitor parking in fr	ont lot.	
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply				1	1				
1.2		ng easily identified with appropriate signage and			3				Comments		
12	community	wayfinding?			0				Comments	0.25	0.75
	1	Very unsatisfactory - Campus has no signage /							Signage on building is hard to spot and only located	at the entranc	e. No
	2	Unsatisfactory - Signage/wayfinding is faded/hidden							street marquee or other signage to identify building.		
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not									
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible and									
		easy to use									
	N/A	Does not apply									

O2/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N//	4		
1.3	ls the dump	oster accessible for trash / compost disposal?	1						Comments	0.50	0.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							No compost. Trash and recycling are far from buildin from the loading dock to parking lot level.	g and there is o	a ramp
2 (N/A	Does not apply	1	0	2	1	E	NI//	A	F 00	200/
		arning and Activity or studios and support spaces appropriately configured per	ı	2	3	4	5 	N/A		5.00	20%
2.1	the ed spec		1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated outdoor studios							No outdoor learning space with seating.		
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility, no shade provided									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
	4	shade coverage over studio area Satisfactory - Good size, good condition, connected to									
		learning spaces, good flexibility, more than 50% shade									
		coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition,									
		connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
	Are active r	playgrounds (elementary only) and support spaces				l					
2.2		per the ed spec?						N/A	Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated active playground									
	2	Unsatisfactory - Too small, poor condition, no shade									
		provided									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50%									
	7	shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full									
		shade coverage over play structure									
	N/A	Does not apply									

2 - 0	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A			
0.0	Are garden	s and support spaces appropriately configured per the ed					_		6 .		
2.3		uation on infrastructure not condition of plants)					5		Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens			1	ı	l		Monitoring answer, does not affect score for Outdoo	r Learning and	
	2	Unsatisfactory - Too small, poor condition, disconnected							Activity. Large garden and greenhouse with a studio	-	0
		from learning spaces, no flexibility, no accessible water							adjacency is good to the gardens but the studio itself	•	
		source							the rest of the school.		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well, water									
		source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces, good flexibility, water source is									
	5	accessible with 100 ft hose									
	3	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water									
		source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
		gardens and/or cisterns appropriately configured per the		1		1					
2.4	ed spec?	gardens and/or disterns appropriately configured per the						N/A	Comments	0.00	0.00
	1	Vancousantiafantamo Na varia arandana ay sistema		ļ	<u> </u>	ļ	<u> </u>		Manitarina manayan da aa nat affaat aa aa fan Oyteda	0.00	0.00
	2	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not							Monitoring answer, does not affect score for Outdoo	r Learning and	
	2	functioning, disconnected							Activity.		
	3	Average - Adequate size, adequate condition, is									
	ŭ	connected, needs some renovations or updates to									
		function well									
	4	Satisfactory - Good size, good condition, functions									
		properly									
	5	Very Satisfactory - Generous size, excellent condition,									
		exceptional functionality, connected to learning spaces,									
		educational signage provided									
	N/A	Does not apply									
2.5	Does the sc	hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No									
0.7	5	Yes		1			ı	l		0.00	0.00
2.6	Does the sc	nool have nature loop trails? (optional) No							Comments	0.00	0.00
	1 5	No Yes									
2.7		nool have a learning pond? (optional)	1						Comments	0.00	0.00
2.7	1	No	- 1				<u> </u>		Comments	0.00	0.00
	5	Yes									
2.8		nool have a grass play field and walking trail?						N/A	Comments	0.00	0.00
	1	No						.,			
	5	Yes									

	3 - General Bu	ilding	1	2	3	4	5	N/A	4	7.50	40%
	3.1 Are interior	circulation routes wide enough to safely and effectively		2					Comments		
	accommod	ate student movement?							Comments	0.50	1.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Most double-loaded corridor circulation leading to s	tudios is <7'-0".	. Larger
		wide							corridors present around entry and admin.		
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
	Are commu	nity use areas arranged so that the school can allow night						N/A	Community		
	3.2 functions w	ithout full school access?						N/A	Comments	0.00	0.00
	1	Very unsatisfactory - Cafeteria, gym, and library cannot							No entry to cafeteria from exterior. No library or gym	n present due t	o being
		be accessed after hours							a specialty campus where students only spend a por	tion of the day	and
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,							are shuttled in from other high schools in the district.		
		Gym and Library) can be accessed from parking and									
	3	secured after hours Average - Only two of the public spaces can be accessed									
	3	from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
	22	ommunity room that is a dedicated meeting space outside		2					Comments		
	of school fu			_						0.75	1.50
	1	Very unsatisfactory - No dedicated community room							Centralized conference and gathering space present	, but only acce	essible
	2	Unsatisfactory - Community room but within school							through main entry.		
	3	function, no access after school hours									
	3	Average - Community room, moderate size, but need some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets									
	·	needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
		condition, functions appropriately outside of school									
		function									
-	N/A	Does not apply	1	ı	ı	1		1	I	ı	
	3/1 -	eneral appearance of the school convey pride for the		2					Comments	0.05	0.50
L	students ar	nd community? Very unsatisfactory - General appearance is poor		<u> </u>			L		New carpeting and rubber base in studio corridors a	0.25	0.50
	2	Unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok								na new paint i	ii studio
	3	Average - General appearance is good							but much of the rest of the campus is aged.		
	4	Satisfactory - General appearance shows pride in									
		campus and student works									
	5	Very satisfactory - General appearance shows pride in									
		campus and student works and is welcoming to the									
		community									
	N/A	Does not apply									

4 - Security	1	2	3	4	5 N	1/A		16.25
4.1 Does the facility have key card access at all major entries?							Comments	0.25
1 Very unsatisfactory - No entries								
2 Unsatisfactory - 1/4 of major entries								
3 Average - 1/2 of major entries								
4 Satisfactory - 3/4 of major entries								
5 Very satisfactory - All of major entries								
N/A Does not apply								
4.2 How adequate is site lighting and security for the campus overall?							Comments	1.00
Very unsatisfactory - No exterior lighting, no secure perimeter								
2 Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal								
Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate								
4 Satisfactory - Lighting at all night-use entries and								
parking lots, good condition, signage less visible, perimeter is well secured but needs updates								
5								
Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A Does not apply						L		
ls the main office located at the school entry and configured with a							Comments	
secure vestibule to the main corridor?							Comments	1.00
1 Very unsatisfactory - No secure vestibule, office located								
far from main entry, allows visitors access to school								
unsupervised 2 Unsatisfactory - No secure vestibule, office located								
2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of								
visitors								
3 Average - Office close to entry, views of front door, but								
no secure vestibule								
4 Satisfactory - Office is well-located with a secure								
vestibule, but needs updates								
5 Very satisfactory - Office well-located with secure								
vestibule and all appropriate security features						Į		
N/A Does not apply								
ls there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios?			3				Comments	1.00 3.00
1 Very unsatisfactory - No transparency of walls							Narrow lites in studio doors and some transparency t	rom certain
2 Unsatisfactory - Limited transparency in certain locations							studios/learning spaces to corridors. Winding double	-loaded corridor does
3 Average - Good transparency in certain locations but							not offer high visibility for passive supervision.	
inadequate or missing in other locations of school								
4 Satisfactory - Adequate transparency throughout the								
school								
5 Very satisfactory - Excellent transparency throughout the school								
N/A Does not apply								<u> </u>

5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	76%
5.1 How are ac	coustics in studios in general?	1						Comments	1.00	1.00
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Acoustic control between studios is poor due to aged between pairs of studios.	l movable parti	tions
	o artificial lighting adequate quality?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply							Glare on some surfaces but no controls for lights (sindimmability).	gle switch, no	
5.3 Is there acc	tess to natural light in studios?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios have windows.		
	Does not apply tess to outside views from learning spaces?					5		Comments		
1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply							Views are present but most to roads/parking.	1.00	5.00

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	A.		
5.5 Does the b	ouilding have odor or pest problems?					5		Comments	1.00	5.00
1	Very unsatisfactory - Evidence of both pests and odors							School was clean, did not come across pests.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	\	12.50	36%
6.1 Does the st	tudio thermostat allow for individual control?	1						Comments	0.50	0.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?			3				Comments	1.00	3.00
1	Very unsatisfactory - No, windows are covered with							Blinds present but very aged/missing rods or pulls.		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, F	Fixtures & Equipment	1	2	3	4	5	N/A	4	18.75	59%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
1	Very unsatisfactory - Damaged or broken, non- functioning							Mismatch of old and new, but in good condition. May with special needs.	y not support s	tudents
2	Unsatisfactory - Torn/ bent/ wrong size									
4	Average - Scratched/dented/marked									
5	Satisfactory - Not new, but sturdy and clean Very satisfactory - New									
N/A	Does not apply									
IVA	Воез пос арргу			1			I			
	ety of furniture types being accommodated throughout the	1						Comments		
school - led	arning commons, dining commons, other multi-use spaces?	'						Comments	1.00	1.00
1	Very Unsatisfactory - Same furniture used in all spaces						1	No informal/soft seating present. No choice present i	1.00	1.00
2								multiuse spaces.	ir diriirig or oth	iei
	Unsatisfactory - Furniture variety in one multi-use space							multiuse spaces.		
3	Average - Furniture variety in more than one multi-use									
4	space Satisfactory - All multi-use spaces have greater than one									
	type of furniture									
5	Very satisfactory - All multi-use spaces have greater than									
	two types of furniture									
N/A	Does not apply		1			1	1	T		
/3	does furniture accommodate rapid reconfiguration of a			3				Comments	1.00	0.00
space?	Very Unsatisfactory - Furniture is fixed or very heavy						1	Furniture is movable but may be difficult to do due to	1.00	3.00
2	Unsatisfactory - Furniture does not allow desks to be							I difficult is movable but may be difficult to do due to	ruge.	
_	configured as individuals, small groups, or large groups									
3	Average - Mix of furniture that can reconfigure but is									
	cumbersome to move									
4	Satisfactory - Furniture is flexible for multiple									
_	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
N/A	configurations of space, easy to move and stack									
IN/A	Does not apply			ı			I			
7.4 Is the furni	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
1	Very unsatisfactory - Desk with attached chair							Tables with loose chairs, but may not accommodate s	students with s	special
_	combinations too small for grade level							needs/disabilities.		
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4	Very satisfactory - Tables with loose chairs									
5	Very satisfactory - Tables with loose chairs that allow									
	students to be active									
N/A	Does not apply								88 75	

Perkins&Will 02/11/2022 ⁹

Waste	1	2	3	4	5	N/A	4	5.00	30%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?		2					Comments	0.50	1.00
1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. 5 Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this co- calculated in the overall ESA average. Studios have recycling bins present, but no sorting im- instructions. Most corridors too narrow for bins so the	nages or bilingu	
N/A Does not apply Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?	1						Comments	0.50	0.50
 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting. 				·			No bins are present; however school likely not serving No compost dumpster present.		



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Clifton Career Development School	Anacleto Rojas Jr and Emilie Ogburn	10.22.2020

- Academics	& Learning	1	2	3	4	5	N/A	50.00	329
8.1 Are studios	appropriately configured per the ed spec?			3				Comments 1.00	3.0
1	Very unsatisfactory - Too small, no flexibility,							Studios are paired with a moveable partition to connect/double siz	e.
	disconnected							Adequate size but not enough for multiple teaching areas.	
2	Unsatisfactory - Too small, only one area for all teaching								
	methods, limited flexibility, disconnected								
3	Neutral - Adequate size, multiple areas for different								
	teaching methods, adequate flexibility, limited								
	transparency and connection to other studios and								
	shared learning spaces, needs updates or renovations to								
4	function well. Satisfactory - Good size, multiple areas for different								
4	teaching methods, good flexibility, good transparency								
	and connection to other studios and shared learning								
	spaces								
5	Very Satisfactory - Generous size, multiple areas for								
	different teaching methods, excellent flexibility, generous								
	display area and visual teaching tools, excellent								
	transparency and connection with other studios and								
	shared learning spaces								
N/A	Does not apply								
8 2	nave appropriate support spaces such as storage per the			3				Comments	
ed spec?								1.00	3.00
1	Very unsatisfactory - None provided							All studios have casework but limited mobile storage through FF&E.	
2	Unsatisfactory - Too small, disconnected, poor condition								
3	Neutral - Adequate size, average condition, needs								
	updates or renovations to function well								
4	Satisfactory - Good size, connected, good condition								
5	Very Satisfactory - Generous size, connected, excellent								
	condition								
N/A	Does not apply								

8 - 1	Academics -	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do typical I	earning neighborhoods have small and medium (high	1						Comments		
0.3	school only	group rooms and open collaboration space?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open							No group rooms or collaboration spaces within studio	areas. Due to)
		collaboration spaces are provided							student population and curriculum, they may not be	necessary. Hov	vever,
	2	Unsatisfactory - Too small or too few, poor condition, no							dedicated de-escalation/chill rooms could be benefic	cial.	
		flexibility, lacks visual connection to learning							, , , , , , , , , , , , , , , , , , , ,		
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
8.4		Labs and support spaces appropriately configured per						N/A	Comments		
	the ed spec							, , .	Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated science room									
	2	Unsatisfactory - Too small, poor condition, no connected									
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected support spaces									
	N/A	Does not apply		1	1		1	1			
8.5		Spaces and support spaces appropriately configured per						N/A	Comments		
	the ed spec	? (cross reference with CTE below)								0.00	0.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	_	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected to learning spaces Does not apply									
	N/A										

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6	Is there a Pi	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1 2	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected							No dedicated space. Teacher lounge and conferencinot in learning neighborhood.	ng space prese	nt but
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4 5	Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected									
8.7		dequate places to display the evidence and artifacts of oth 2D and 3D)?	1						Comments	1.00	1.00
	1 2	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition							Limited space/area for display in narrow studio corrion program and functionality.	dors due to the	
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition									
	5 N/A	Very Satisfactory - Generous size, excellent condition Does not apply									
8.8		uilding / learning neighborhood provide adequate es for students/teachers to collaborate in varying group	1						Comments	1.00	1.00
	1 2 3	Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes Average - Adequate space for collaboration, needs							No group/breakout spaces in learning neighborhood different from standard studio spaces due to curricul having space for small group learning and individual	ls, though may um. Ed Spec no	be otes
	4 5	updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply		1		1					
8.9	Does the bu	uilding provide opportunities for informal interaction?	1						Comments	1.00	1.00
	1 2 3	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates							No furnishings provided/limited opportunities for loc informal interaction in circulation spaces.	ations for futur	e
	4	or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									

8 - Ac	ademics 8	k Learning (cont.)	1	2	3	4	5	N/A	<u> </u>		
8 10		ilding provide adequate opportunities for students to	1						Comments		·
0.10	work indepe	endently?	'						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms/small study							No individualized or small group space.		
		spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
	Ŭ	acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply									
9	Special Edu	· · · · · ·									
	•	Education spaces appropriately configured per the ed		1	1						
8 11	spec?	Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility,		<u> </u>	<u> </u>				Multiple rooms for different programs within the scho		0.00
	'	disconnected							configured the same except for specialty areas (laune		
	2	Unsatisfactory - Too small, only one area for all teaching							mechanical/maintenance, culinary, horticulture, etc.)	•	
		methods, limited flexibility, disconnected								•	
	3	Neutral - Adequate size, multiple areas for different							in typical studio spaces. Campus seems geared towa	•	
		teaching methods, adequate flexibility, limited							students and finding careers and training in jobs but		-
		transparency and connection to other studios and							standard and not ADA accessible. Flexible partitions	are not acoust	IC.
		shared learning spaces, needs updates or renovations to									
		function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
	-	spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous									
		display area and visual teaching tools, excellent transparency and connection with other studios and									
		shared learning spaces									
	N/A	Does not apply									
<i>F</i>		Education support spaces, such as storage, space for							_		
עו א		er, appropriately configured per the ed spec?						N/A	Comments	0.00	0.00
	1	Very unsatisfactory - None provided							School does not have life skills programming, but opp	ortunities for	
	2	Unsatisfactory - Too small, disconnected, poor condition							teaching without other present spaces (culinary, laun		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.13		ple restrooms and changing rooms readily available to the cation spaces?	1						Comments	1.00	1.00
	1	No				'	•				
	5	Yes									
	STEAM Cent	ter									
8.14	Does the ca	mpus have space to support a "STEAM" center?						N/A	Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning							Monitoring answer, but does not count towards over	all score	
	N/A	Does not apply						L			
9 - C	TE and Car	reer Connected Learning								6.25	100%
9.1		s your campus to a CTE cluster pathway that is aligned TE programs (Middle School only)?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway. Average - School support half of CTE programs listed in the cluster pathway, but missing some. Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway. Very Satisfactory - School is aligned with CTE cluster pathway.							Specialty school with CTE programs for specific popul development and training. (Note: Principal noted the CTE special education, so programs will have to beging general CTE standards.)	at TEA is elimin	ating
	N/A	Does not apply									
9.2	•	facilities align with the CTE Ed Spec Requirements for the nways offered?: Architecture and Construction						N/A		0.00	0.00
	1 5 N/A	No Yes Does not apply									
9.3	Arts, Audio	and Video Technology and Communications						N/A		0.00	0.00
9.4	Business, Mo	anagement and Administration						N/A		0.00	0.00
9.5	Education a	nd Training						N/A		0.00	0.00
9.6	Health Scier	nce					5			0.25	1.25

Perkins&Will 02/11/2022 ⁶

9 - CTE and Career Connected Learning (cont.)	1		2	3 4	4	5	N/A			
9.7 Hospitality and Tourism						5			0.25	1.25
9.8 Human Services (high school only)							N/A		0.00	0.00
9.9 Information Technology							N/A		0.00	0.00
9.10 Agriculture, Food and Natural Resources						5			0.25	1.25
9.11 Science, Technology, Engineering, and Mathematics						5		Mechanical Program	0.25	1.25
9.12 Transportation, Distribution and Logistics							N/A		0.00	0.00
9.13 Finance (high school only)							N/A		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)							N/A		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)							N/A		0.00	0.00
9.16 Manufacturing (high school only)						5		Maintenance Program	0.25	1.25
9.17 Marketing, Sales and Services (high school only)							N/A			
20 Visconi and Braffe and a Arts									0.00	0.00
10 - Visual and Performing Arts		Π							0.00	N/A
							N/A	Comments		
10.1 Is there flexibility of space to also be used by CTE and Athletics?							IN/A	Comments	0.00	0.00
10.1 Is there flexibility of space to also be used by CTE and Athletics? 1 No 5 Yes								Monitoring answer, but doesn't affect overall score.	0.00	0.00
1 No									0.00	0.00
1 No 5 Yes Are band and support spaces (rehearsal and storage) appropriately			I		I		N/A	Monitoring answer, but doesn't affect overall score.		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition					<u> </u>		N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs		I					N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.					I		N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.							N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply					<u></u>		N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition							N/A	Monitoring answer, but doesn't affect overall score. Comments		
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces							N/A	Monitoring answer, but doesn't affect overall score. Comments Campus does not have a fine arts program.	0.00	0.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition		I					N/A	Monitoring answer, but doesn't affect overall score. Comments Campus does not have a fine arts program.	0.00	0.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs		I					N/A	Monitoring answer, but doesn't affect overall score. Comments Campus does not have a fine arts program.	0.00	0.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.							N/A	Monitoring answer, but doesn't affect overall score. Comments Campus does not have a fine arts program.	0.00	0.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs							N/A	Monitoring answer, but doesn't affect overall score. Comments Campus does not have a fine arts program.	0.00	0.00

Perkins&Will 02/11/2022 ⁷

10 - Visual and	d Performing Arts (cont.)	1	2	3	4	5	N/A			
	and support spaces appropriately configured per the ed						N/A			
spec?							IN/ A	Comments	0.00	0.00
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
_	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5 N/A	Very Satisfactory - Generous size, excellent condition Does not apply									
Aro danco	and support spaces appropriately configured per the ed		I		1	П	Π			
10.5 spec?	and dapport spaces appropriately comigated por the sa						N/A	Comments	0.00	0.0
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5 N/A	Very Satisfactory - Generous size, excellent condition Does not apply									
Are theate	r and support spaces appropriately configured per the ed		I			1	I			
10.6 spec?	. and cappoint spaces appropriately cominguing per the ca						N/A	Comments	0.00	0.00
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5 N/A	Very Satisfactory - Generous size, excellent condition									
· · · · · · · · · · · · · · · · · · ·	Does not apply arts and support spaces appropriately configured per the		I			ı	I		1	
10.7 ed spec?	arts and support spaces appropriately configured per tile						N/A	Comments	0.00	0.00
1	Very unsatisfactory - Too small, missing program spaces						•			
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1								
IN 8	ampus have adequate space for the specialty arts						N/A	Comments		
programs ((Ensemble, Guitar, Music studies, Music theory and Piano)?						IN/A	Comments	0.00	0.0
1	No						1		0.00	5.00
5	Yes									
								I .		

Perkins&Will 02/11/2022 ⁸

11 - Athletics and Wellness					0.00	N/A
11.1 Does the campus meet ed spec standard for physical education program spaces?			N/A	Comments	0.00	0.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply				Campus does not have an athletics program		
11.2 Does the campus have a dedicated wellness center?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.3 Does the community have access to exterior playfields/courts?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.4 Are facilities available to facilitate eSports (High School only)?			N/A	Comments	0.00	0.00
1 No 5 Yes				Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.6 Are facilities set up to support UIL sanctioned athletics for track?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.7 Are facilities set up to support UIL sanctioned athletics for football?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			N/A	Comments	0.00	0.00
1 No 5 Yes						
1].9 Are facilities set up to support UIL sanctioned athletics for tennis?			N/A	Comments	0.00	0.00
1 No 5 Yes						
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?			N/A	Comments	0.00	0.00
1 No 5 Yes						

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont	.)	1	2	3 4	5	N/A			
11.11 Are facilities (dedicated storage) athletics for cross-country (highs	set up to support UIL sanctioned school only)?					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.12 Are facilities (dedicated storage) athletics for golf (high school onl						N/A	Comments	0.00	0.00
1 No 5 Yes									
11.13 Are facilities (dedicated storage) athletics for swimming (high scho						N/A	Comments	0.00	0.00
1 No 5 Yes									
Are facilities set up to support UI (high school only)?	L sanctioned athletics for wrestling					N/A	Comments	0.00	0.00
1 No 5 Yes									
(high school only)?	L sanctioned athletics for baseball					N/A	Comments	0.00	0.00
1 No 5 Yes			1						
(high school only)?	L sanctioned athletics for softball					N/A	Comments	0.00	0.00
1 No 5 Yes			1						
	utside of the gymnasium) available to les for cheerleading and drill team?					N/A	Comments	0.00	0.00
1 No 5 Yes									
11 - Athletics and Wellness (cont	.)	1	2	3 4	5	N/A			
How do the athletics fields align 11.18 Turf Field, Parking lot lighting, Al only)	with FMP Campus Improvements? DA accessible amenities (high School					N/A	Comments	0.00	0.00
1 Very unsatisfactory	- No turf, inaccessible, no site lighting						Monitoring answer, but doesn't affect overall score.		
•	turf/field in poor condition, some ns, poor site lighting								
-	dequate condition, needs some ions to function well								
4 Satisfactory - Turf f access and site ligh	eld in good condition, good ADA ting								
5 Very Satisfactory - ⁻	Furf field with excellent maintenance, ss for spectators and athletes,								
N/A Does not apply.									

O2/11/2022 ¹⁰

2 - Food Servi	ces								0.00	N/
12.1 Is the Dinin	g Commons appropriately configured per the ed spec?						N/A	Comments	0.00	0.0
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply									
Are the Foo	od Services support spaces appropriately configured per						h 1 / A			
2.2 the ed spec	c?						N/A	Comments	0.00	0
1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
3 - Media Res		1	2	3	4	5	N/A		0.00	I
visitors to t							N/A	Comments	0.00	C
1 2 3 4 5	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A	Does not apply									

13 - Media Resources - Continued	1	2	3	4	5	N/A			
13.2 How well does the Library/Media Center support quiet study?						N/A	Comments	0.00	0.00
Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates									
or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy 5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy									
N/A Does not apply									
13.3 How well does the Library/Media Center support social interaction?						N/A	Comments	0.00	0.00
1 Very unsatisfactory - No space									
2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
 Average - Adequate size and condition, needs updates or renovations to function well. 									
4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply									
How well does the Library/Media Center support collaborative work		1			1				
in small groups (4-8 students)?						N/A	Comments	0.00	0.00
Very unsatisfactory - No breakout rooms, no flexible									
furniture, no support									
 Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, 									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition N/A Does not apply									
How well does the Library/Media Center support collaborative work							_		
in larger groups (10-25)?						N/A	Comments	0.00	0.00
1 Very unsatisfactory - No gathering areas						•			
 Unsatisfactory - Too small, one common space, limited 									
seating, poor condition									
3 Average - Adequate size, one common space, needs updates or renovations to function well									
4 Satisfactory - Good size, multiple common spaces with									
seating, good condition									
5 Very Satisfactory - Generous size, multiple commons									
spaces with seating, excellent condition									
N/A Does not apply									

1	3 - Media Res	sources - Continued	1	2	3	4	ţ	5	N/A			
	13.6 How well d	does the Library/Media Center support technology?							N/A	Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition										
,	N/A	Does not apply	,	2	_			5	N/A		15.00	47%
	4 - Technolog 14.1 How well e 1 2 3 4 5 N/A	equipped are the facilities with instructional technology? Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition Does not apply		2	3	4				Comments Mobile flat panels are available in nearly all spaces to only technology provided. Cafeteria has projection so projector (screen is aged).	1.00 out appears to	2.00 be the
		adequate number of power and data outlets in learning			3					Comments	1.00	3.00
	. 1 2 3 4	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)			•	1	1	•		Different numbers of outlets in studios/learning space function.		
	N/A	Does not apply										

14 - Technolog	y (cont.)	1	2	3	4	5	N/	[′] A	
14.3 Are there a	dequate charging locations for devices?						N/	Comments 0.00	0.0
1 2 3 4 5	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.				•			Unsure what devices are provided to students or need for charging.	
N/A Is there ade gym?	Does not apply equate AV for presentations spaces – cafeteria, gym, aux		2					Comments 1.00	2.0
1 2 3 4 5	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.							Cafeteria has a small projection screen but aged and may not function highly for the space.	on
N/A	Does not apply ital media signage at the reception area?	1						Comments	
1 2 3 4 5 N/A	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply							0.00	0.0

	15 - Administration Spaces			2	3	4	5	N/A		20.00	60%
	15.1 Is there a revisitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint									
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	15.2 Does the ad	dministration area feel welcoming?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No welcome space							Good size, no seating available (could be due to COV	(ID), could use	
	2	Unsatisfactory - Too small, poor lighting and							updates or reconfiguration.		
		transparency, limited informal seating, poor condition									
	3										
		renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
		transparency, informal seating provided									
	5	5 Very Satisfactory - Generous size and layout, plenty of									
		light and transparency, informal seating provided,									
		excellent condition									
	N/A Does not apply										
	For those sp	For those spaces that require it, does the administration area have		0				Comments			
	adequate o	acoustic privacy?			3				Comments	1.00	3.00
	Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations function okay, but								Admin area is very small and some staff share a com	mon space.	
									•		
		portions need updates or renovations 4 Satisfactory - Good acoustic separations									
	4										
	5 Very Satisfactory - Excellent acoustic separations										
	N/A Does not apply										
	15.4 Are confere	ence rooms easily accessed for public / parent use?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Not accessible for public/parent							Centrally located near main entry but could use updo	ating and does i	not
		use							have transparency (partition is movable however).	· ·	
	2	Unsatisfactory - Limited access, no transparency, poor							(F 20 10 10 10 10 10 10 10 10 10 10 10 10 10		
		condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Good accessibility, good transparency,									
		good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent									
		transparency, generous size, excellent condition									
	N/A	Does not apply									