

Educational Suitability Summary Report

Eastside Early College High School and International School at the Original L.C. Anderson Campus

Date: 01/19/2021 Score 91% Very Satisfactory

Eastside Early College High School and International High School is a 20-acre campus under construction on the site of the original L.C. Anderson Campus as part of the 2017 Bond Program. Eastside Memorial has an enrollment of approximately 490 students and the International School serves approximately 250 students. The campus is in east Austin and will be composed of two new academic buildings totaling 131,200 square feet as well as a new fieldhouse and existing athletic support structures. Construction is slated to be complete in July 2021 with the campus opening in the fall of 2021.

The International School educates students from across the globe and prepares them for transition into public education in the United States. The school offers programs that help students develop the skill set needed to adapt to their new lives and allow for future success.

Eastside Memorial Early College High School focuses on career classes in science, technology, engineering and math. In addition to providing STEM programs such as Project Lead the Way, the school also works with neighborhood schools through the Creative Learning initiative to provide an arts-rich education.

Interview Overview

Separate interviews were conducted for Eastside Early College High School and International School. Because the focus of this interview was on a new building that is still under construction, the interviewees were unable to draw on their experience of using the building to inform the discussion. Thus, no comments were made concerning relics on campus of significant importance, campus security and camera coverage, or the functionality of outdoor learning spaces. There was discussion regarding items that must be kept, the functionality of spaces of the building and outdoor learning spaces, as well as how the campus will function in the future.

Eastside Early College High School

The Eastside Early College High School interview was attended by Principal Miguel Garcia. It was mentioned that the Yellow Jacket Community Room is a space of community importance, where relics of the historic L.C. Anderson campus will be located. Due to budgetary constraints a couple of programs were not included in the new campus design and several sports amenities could not be provided due to site constraints. These include a dance studio, on-site baseball and softball fields, tennis courts, and an additional CTE pathway (yet to be determined.) Looking forward, the school would like to add the missing programs as well as explore ideas of how to improve student and community access to athletic amenities not supported on site. Outdoor learning spaces are designed

Educational Suitability Summary Report

Eastside ECHS and International HS

to function similarly to the current Eastside campus, including a chicken coop, apiary, vegetable gardens and a wellness walk.

Comments during the interview indicated that the campus is poised to support the six C's by providing an open concept plan with spaces to accommodate a variety of learning group sizes as well as offering modern spaces that are similar to real world professional environments. Additionally, the campus is able to host community events by utilizing the cafeteria and choir room.

International School

The International School interview was attended by Principal Leticia Vega and a stakeholder from the maintenance department. Several programs were identified that are not in suitable spaces per district standards. The campus is not planned to provide space for the Automotive Tech program, though the program will be available to students at another district campus. Additionally, there are no softball or baseball fields planned to be located on campus, however an agreement is underway that would allow students to use a nearby field owned by the city. Finally, the practice pad for the marching band is planned to be smaller than what is provided at most area high schools but was viewed as being adequate for the size of the band at this campus.

Comments during the interview indicated that the campus as designed would be able to accommodate growth and changes over the next 20 years as flexibility was a key part of the Campus Architectural Team (CAT) committee vision. Additionally, the facility will be able to host district meetings and is planned to become the hub of the community it serves.

Assessment Findings

The Educational Suitability Assessment of Eastside Memorial and International HS earned an 91% overall score and places the campus in a category of Very Satisfactory. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

The campus is situated on a hill with the peak in the middle and the grade sloping quickly away in both the east and west directions. The primary buildings for the campus are at the top of the hill with entrances on the north and south sides. Due to the constraints of the site, teacher and student parking share an entry point with the bus drop-off. The parent drop-off is on the opposite side of the school, providing good traffic separation but the queue length for pickup/drop-off is limited.

Outdoor Learning and Activity

Score is satisfactory.

Outdoor learning studio spaces are provided, and they are easily accessible from the typical studio spaces, but no covered outdoor studio space is provided. The raised gardens and animal husbandry areas are not easily accessible from the main buildings.

Educational Suitability Summary Report

Eastside ECHS and International HS

Athletics and Wellness

Score is satisfactory.

Due to the constrained site, certain athletic facilities such as baseball, softball and tennis cannot be accommodated on-site. The school has an agreement with the city to use neighboring facilities.

Very Satisfactory Categories (81-100%):

General Building

Score is very satisfactory.

Circulation routes are generous. Cafeteria and gym can open after hours, and a dedicated community room is provided.

Security

Score is very satisfactory.

Environmental Quality

Score is very satisfactory.

The buildings have a high percentage of exterior glazing that provides both ample natural lighting to the interior spaces and great views out. Both acoustics and artificial light are accommodated.

Controllability of Systems

Score is very satisfactory.

All rooms allow for individual thermostat control, and blinds are provided for exterior windows.

Furniture, Fixtures, Equipment

Score is very satisfactory.

All furniture will be new, provide adequate flexibility and multiple seating options in multi-use spaces.

Academics & Learning

Score is very satisfactory.

A wide variety of learning spaces are provided in the academic areas, from enclosed small group rooms to large open collaboration areas. These spaces are well-distributed throughout the school. Studio spaces are highly flexible and have good transparency.

CTE and Career Connected Learning

Score is very satisfactory.

Many CTE programs are accommodated throughout the school. Health sciences has over 3,000 square feet of dedicated space. Automotive does not have space however, students are provided transportation to another campus through the district's student sharing program.

Visual and Performing Arts

Score is very satisfactory.

Educational Suitability Summary Report

Eastside ECHS and International HS

Some visual and performing arts spaces are not provided due to site constraints, but with a smaller student enrollment, spaces are adequate. No auxiliary rehearsal spaces are provided for choir or band.

Food Services

Score is very satisfactory.

The dining commons is an adequate size to serve the school's capacity. The seating area is one large open space and does not provide for a variety of eating areas.

Media Resources

Score is very satisfactory.

The library/media center is next to the primary entry and is easily accessible to students as well as the public. It provides a large, open space with mobile furniture that allows for good flexibility. No acoustically separated areas are provided in the space.

Technology

Score is very satisfactory.


All academic spaces provide multiple types of instructional technology. Both studio and gathering spaces will have ample charging and Wi-Fi capabilities. A large digital display is provided in the reception area that is highly visible to visitors.

Administration Spaces

Score is very satisfactory.

The administration area is split between levels due to two schools sharing the campus. Conference rooms and reception areas are provided at the secure entry points to the school and most of the administration area is accommodated on the second floor of the four-story building.

Supporting Renderings



Historic Entry located off of Thompson Street



Supporting Renderings




Student Entry



Page **6** of **7**

Supporting Renderings



Student Entry Stair with graphics for school pride



Collaboration Area



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Eastside ECHS and International School on L.C. Anderson Campus	Travis Hughbanks (virtual)	2/15/2021

1.1 Does the site permit desirable separation of vehicular, bus and pedestrian traffic? 1 Very unsatisfactory - Bus, car and pedestrian all happen at the same location 2 Unsatisfactory - Cars and buses mix, pedestrians are separated 3 Average - Buses, cars, and pedestrians are separate but stack space is small 4 Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 1 Very unsatisfactory - Campus has no signage / wayfinding The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off separated on north side but has limited queue space. The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off separated on north side but has limited queue space. The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off separated on north side but has limited queue space. The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off separated on north side but has limited queue space. The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off share a drive. Parent drop-off separated on north side but has limited queue space. The site is relatively constrained at the top of the hill and student/sto parking and bus drop-off share a drive. Parent drop-off share a driv	
at the same location 2 Unsatisfactory - Cars and buses mix, pedestrians are separated a separated a separated stack space is small 4 Satisfactory - Buses, cars, and pedestrians are separate but stack space is small 5 Very satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
2 Unsatisfactory - Cars and buses mix, pedestrians are separated 3 Average - Buses, cars, and pedestrians are separate but stack space is small 4 Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	the
separated 3 Average - Buses, cars, and pedestrians are separate but stack space is small 4 Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
stack space is small 4 Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Comments 0.25 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
but drop off does not have a canopy or a holding place like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Comments 0.25 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
like a commons or cafeteria 5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 5 Comments 0.25 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
5 Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
separate and drop off area has a canopy and destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
destination N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 1.3 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
N/A Does not apply 1.2 Is the building easily identified with appropriate signage and community wayfinding? 1.3 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
1.2 Is the building easily identified with appropriate signage and community wayfinding? 1.2 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
1.2 community wayfinding? 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
community wayfinding? 0.25 1 Very unsatisfactory - Campus has no signage / The primary historic entry is well-defined and highly visible.	
	1.25
11 4) 111 411 9	
2 Unsatisfactory - Signage/wayfinding is faded/hidden	
3 Average - Signage / wayfinding visible but not apparent	
4 Satisfactory - Signage / wayfinding is visible but not good condition	
5 Very satisfactory - Signage and wayfinding is visible and easy to use	
N/A Does not apply	

Perkins&Will 02/11/2022 ²

1 - E	xterior (cor	nt.)	1	2	3	4	5	N/A	A		
1.3	Is the dump	ester accessible for trash / compost disposal?					5		Comments		
1.0		oter decession for tradity compete dispersal.					Ŭ		Comments	0.50	2.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped							Space is provided for recycling, composting and trasi construction documents.	n dumpsters on	the
		/ positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0	Outdoor Le	arning and Activities	1	2	3	4	5	N/A	A	5.00	80%
2.1	Are outdoo the ed spec	r studios and support spaces appropriately configured per ?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No dedicated outdoor studios		•	•	•		•	Outdoor studio spaces have tree shade provided but	no structured o	canopy
	2 3 4 5	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							provided.		
	•	Does not apply playgrounds (elementary only) and support spaces			1	I		1			
2.2		per the ed spec?						n/a	Comments	0.00	0.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

2 - Outdoor Le	arning and Activities (cont)	1	2	3	4	5	N/A	1		
2.3 Are garden	s and support spaces appropriately configured per the ed			0				Community		
2.3 spec? (eval	uation on infrastructure not condition of plants)			3				Comments	0.00	0.00
1	Very unsatisfactory - No dedicated gardens							Monitoring answer, but does not affect overall score	for Outdoor Le	earning
2	Unsatisfactory - Too small, poor condition, disconnected							& Activity.		
	from learning spaces, no flexibility, no accessible water									
	source							Raised gardens and animal husbandry areas are pro	vided with wa	ter
3	Average - Adequate size, adequate condition, needs							access close by. The spaces are not easily accessible	from studios.	
	some renovations or updates to function well, water source is difficult to access									
4	Satisfactory - Good size, good condition, connected to									
7	learning spaces, good flexibility, water source is									
	accessible with 100 ft hose									
5	Very Satisfactory - Generous size, excellent condition,									
	connected to learning spaces, excellent flexibility, water									
	source is less than 50ft from the garden or has irrigation									
N/A	Does not apply									
2.4 Are the rain	gardens and/or cisterns appropriately configured per the				4			Comments		
ed spec?					4			Comments	0.00	0.00
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, but does not affect overall score	for Outdoor Le	earning
2	Unsatisfactory - Too small, poor condition, not							& Activity.		_
	functioning, disconnected							,		
3	Average - Adequate size, adequate condition, is							A series of terraced rain gardens are provided but no	cistern.	
	connected, needs some renovations or updates to									
	function well									
4	Satisfactory - Good size, good condition, functions									
5	properly Very Satisfactory - Generous size, excellent condition,									
3	exceptional functionality, connected to learning spaces,									
	educational signage provided									
N/A	Does not apply									
2.5 Does the sc	hool have animal husbandry? (optional)					5		Comments	0.00	0.00
1	No									
5	Yes									
2.6 Does the sc	hool have nature loop trails? (optional)					5		Comments	0.00	0.00
1	No									
5	Yes		1			1				
2./ Does the sc	hool have a learning pond? (optional)	1						Comments	0.00	0.00
1 5	No Yes									
	hool have a grass play field and walking trail?					5		Comments	1.00	5.00
2.6 Does the sc	No							Comments	1.00	5.50
5	Yes									

	3 - General Bu	General Building			3	4	5	N/A	4	11.25	82%
	3.1 Are interior	circulation routes wide enough to safely and effectively				1			Comments		
	accommod	ate student movement?				4			Comments	0.50	2.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							All primary circulation in building 1 (single-story build	ing) is over 10'-	-6".
		wide							Building 2 (four-story building) has 12' -0" corridors or	n the first floor	and the
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide							upper floors corridors vary between 7'-6" and 10'-0".		
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
	Are commu	nity use areas arranged so that the school can allow night			1						
	3')	rithout full school access?			3				Comments	0.75	2.25
ļ.	1	Very unsatisfactory - Cafeteria, gym, and library cannot		<u> </u>	<u> </u>	<u> </u>	<u> </u>	1	Dedicated community room, cafeteria and gym are c		
	·	be accessed after hours							night functions without access to the entire school. Th	ū	
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,							riight functions without access to the entire school. If	ie library is no	ι.
		Gym and Library) can be accessed from parking and									
		secured after hours									
	3	Average - Only two of the public spaces can be accessed									
		from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
	22	ommunity room that is a dedicated meeting space outside					5		Comments		
	of school fu									0.75	3.75
	1	Very unsatisfactory - No dedicated community room							The Yellow Jacket Community Center has a dedicate	d entry point.	The
	2	Unsatisfactory - Community room but within school							space has multiple restrooms, gallery space, storage	meeting area	and pre-
	_	function, no access after school hours							function space.		
	3	Average - Community room, moderate size, but need									
	4	some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
	Ü	condition, functions appropriately outside of school									
		function									
	N/A	Does not apply									
	Does the ge	eneral appearance of the school convey pride for the					_				
	3.4 students ar	nd community?					5		Comments	0.25	1.25
	1	Very unsatisfactory - General appearance is poor									
	2	Unsatisfactory - General appearance is aged but ok									
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in									
		campus and student works									
	5	Very satisfactory - General appearance shows pride in									
		campus and student works and is welcoming to the									
		community									
	N/A	Does not apply									

4 - Security	1	2	3	4	5	N/A		16.25	
4.1 Does the facility have key card access at all major entries?							Comments	0.25	
1 Very unsatisfactory - No entries	l								_
2 Unsatisfactory - 1/4 of major entries									
3 Average - 1/2 of major entries									
4 Satisfactory - 3/4 of major entries									
5 Very satisfactory - All of major entries									
N/A Does not apply							ļ.		ī
***							_		_
4.2 How adequate is site lighting and security for the campus overall?							Comments	1.00	
Very unsatisfactory - No exterior lighting, no secure				1					_
perimeter									
2 Unsatisfactory - Lighting is limited to front entry only,									
parking lot lighting poor, security is minimal									
3 Average - Lighting at all night-use entries and parking									
lot, but poor condition. Security is moderate									
4 Satisfactory - Lighting at all night-use entries and									
parking lots, good condition, signage less visible,									
perimeter is well secured but needs updates									
5 Very satisfactory - Signage, parking lots, and entries are									
well lit, visible and easy to use, perimeter is very secure	7								
									-
N/A Does not apply Is the main office located at the school entry and configured with a		1	1	1					_
4.3 secure vestibule to the main corridor?							Comments	100	
Very unsatisfactory - No secure vestibule, office located								1.00	
far from main entry, allows visitors access to school									i
unsupervised									
2 Unsatisfactory - No secure vestibule, office located									
somewhat far from main entry, minimal supervision of									
visitors									
3 Average - Office close to entry, views of front door, but									
no secure vestibule									
4 Satisfactory - Office is well-located with a secure									
vestibule, but needs updates									
5 Very satisfactory - Office well-located with secure									
vestibule and all appropriate security features									_
N/A Does not apply									
ls there enough interior transparency for faculty to passively supervis	е			4			Comments		
learners and their activities who are not in studios?				7			Comments	1.00 4.0	0
1 Very unsatisfactory - No transparency of walls							All studios and learning spaces have high visibility to	corridors with the	
Unsatisfactory - Limited transparency in certain location	ns						exception of the historic corridors on Level 1.		
3 Average - Good transparency in certain locations but									
inadequate or missing in other locations of school									
4 Satisfactory - Adequate transparency throughout the									
school									
5 Very satisfactory - Excellent transparency throughout th	е								
school									
N/A Does not apply									

Perkins&Will 02/11/2022 ⁶

5 - Enviror	nmental Quality	1	2	3	4	5	N/A		25.00	100%
5.1 How o	are acoustics in studios in general?					5		Comments	1.00	5.00
:	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Sound baffles or ACT ceiling provided throughout. Al batt insulation.	l walls have ac	coustic
	studio artificial lighting adequate quality?					5		Comments	1.00	5.00
; ; ,	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is ther	re access to natural light in studios?					5		Comments	1.00	5.00
3	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply							Great views and daylight in all learning spaces.		
5.4 Is ther	re access to outside views from learning spaces?					5		Comments	1.00	5.00
	1 Very unsatisfactory - No learning spaces have views				1		l	Great views and daylight in all learning spaces.	1.00	3.00
; ,	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views									

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5 Does the b	ouilding have odor or pest problems?					5		Comments	1.00	5.0
1	Very unsatisfactory - Evidence of both pests and odors							1		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in excellent condition									
N/A	Does not apply									
- Controllab	ility of Systems	1	2	3	4	5	N/A		12.50	92
6.1 Does the s	tudio thermostat allow for individual control?					5		Comments	0.50	2.5
1	No		•							
5	Yes									
6.2 Are shade	s provided to control natural light in learning spaces?				4			Comments	1.00	4.0
1	Very unsatisfactory - No, windows are covered with boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?					5		Comments	1.00	5.0
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - F	urniture, F	ixtures & Equipment	1	2	3	4	5	N/A	4	18.75	100%
7.1	What is the	current condition of the furniture?					5		Comments	0.75	3.75
	1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply							All new furniture		
	14//	Does not apply		1		1	1				
7.2		ty of furniture types being accommodated throughout the urning commons, dining commons, other multi-use spaces?					5		Comments	1.00	5.00
	1	Very Unsatisfactory - Same furniture used in all spaces							Furniture provided in separate package and selected	I to meet the E	d Specs.
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one									
		type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than									
	N/A	two types of furniture									
		Does not apply oes furniture accommodate rapid reconfiguration of a		1		1	1	l	-		
7.3	space?	oes furniture accommodate rapid recominguration of a					5		Comments	1.00	5.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy				I	I		Furniture provided in separate package and selected		
	2	Unsatisfactory - Furniture does not allow desks to be									•
		configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is									
		cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple									
	5	configurations of space Very satisfactory - Furniture is flexible for multiple									
	3	configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	Is the furnit	ure ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Desk with attached chair							Furniture provided in separate package and selected	I to meet the E	d Specs.
		combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁹

Zero Waste		1	2	3	4	5	N/A	5.00	0%
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?						N/A	Comments 0.50	0.00
1 2 3 4 5	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across	,	,					A score for this category is being recorded, but this category is not calculated in the overall ESA average. Building still under construction.	
N/A Does the ca	campus. Does not apply feteria (or wherever meals are served) have at least one								
	en compost bin, blue recycle bin, and landfill bin? Are the d clearly with bilingual and/or image sorting?						N/A	Comments 0.50	0.00
1 2 3 4 5 N/A	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting. Does not apply							Building still under construction.	



Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Eastside ECHS and International School on L.C. Anderson Campus	Travis Hughbanks (virtual)	2/15/2021

8 - 8	Academics	& Learning	1	2	3	4	5	N/A		65.00	95%
8.1	Are studios	appropriately configured per the ed spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, no flexibility,							Studios all over 800 sq. ft. and have good access/con	nection to flex	(and
		disconnected							collaboration spaces.		
	2	Unsatisfactory - Too small, only one area for all teaching							·		
		methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different									
		teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to									
		function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
	_	spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous									
		display area and visual teaching tools, excellent									
		transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
		,						ı			
8.2	ed spec?	have appropriate support spaces such as storage per the					5		Comments	1.00	5.00
	ea spec :	Vancousantisfacture. Nana muscialad						<u> </u>		1.00	5.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

8 - A	\cademics	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do typical I	earning neighborhoods have small and medium (high					5		Comments		
8.3	school only) group rooms and open collaboration space?					Э		Comments	1.00	5.00
	1	Very unsatisfactory - No breakout rooms or open							Enclosed small and medium group rooms and open o	ollaboration spe	aces
		collaboration spaces are provided							distributed throughout learning neighborhoods. Each		
	2	Unsatisfactory - Too small or too few, poor condition, no							group, 1 medium group, and 2 open collaboration sp		
		flexibility, lacks visual connection to learning							[9 p,		
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
8.4	Are Science	Labs and support spaces appropriately configured per					5		Comments		
0.4	the ed spec	?					0		Confinents	1.00	5.00
	1	Very unsatisfactory - No dedicated science room							Science labs are over 1500 sq. ft. and have direct con	nection to a sha	ıred
	2	Unsatisfactory - Too small, poor condition, no connected							prep room.		
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected support spaces									
	N/A	Does not apply		ı	1	T		ı			
8.5		Spaces and support spaces appropriately configured per				4			Comments		
	the ed spec	? (cross reference with CTE below)		<u> </u>	<u> </u>			<u> </u>		1.00	4.00
	1	Very unsatisfactory - No dedicated maker spaces							There is one dedicated maker space slightly under re	quired square	
	2	Unsatisfactory - Too small, poor condition, disconnected							footage and support spaces are adequate.		
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - Aca	demics	& Learning (cont.)	1	2	3	4	5	N/A			
8.6 ls	there a P	rofessional Learning Center in the learning neighborhood?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No dedicated space for Professional Learning Center							One PLC of 500 sq. ft. provided per floor.		
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected			1			1			
8 /		dequate places to display the evidence and artifacts of					5		Comments		
le		oth 2D and 3D)?								1.00	5.00
	1 2	Very unsatisfactory - No dedicated space									
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs									
	ŭ	updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
D	oes the bu	uilding / learning neighborhood provide adequate									
8.8 0	pportuniti	es for students/teachers to collaborate in varying group					5		Comments		
si	izes?									1.00	5.00
	1	Very unsatisfactory - No space to support collaboration		•	•	•			Multiple open areas for collaboration dispersed thro	ughout the sch	ool.
		in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
	4	updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
	Ü	multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.9 D	oes the bu	uilding provide opportunities for informal interaction?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No space				•	•		In the academic areas, gathering spaces, and outdoo	or areas, space	es are
	2	Unsatisfactory - Too small, poor condition, layout and							provided for informal interaction.		
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
	5	furnishings support informal interactions Very Satisfactory - Generous size, excellent condition,									
	3	layout and furnishings support informal interactions									
	N/A	Does not apply							L		

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/	/A		
8.10	Does the bu	uilding provide adequate opportunities for students to endently?					5		Comments	1.00	5.00
	1 2 3 4 5 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply					l		Multiple small group areas provided as well as break that can be used for independent work.		
	Special Edu	· · · ·									
8.11	•	Education spaces appropriately configured per the ed				4			Comments	1.00	4.00
	1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							Good sized spaces but lack transparency to other stuspaces.	idios and learn	ing
	N/A	Does not apply Education support spaces, such as storage, space for		I	1	ı		ı			
8.12		er, appropriately configured per the ed spec?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition			,	,			Multiple studio spaces dedicated to special educatio support spaces.	n in addition to	o ample
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁵

8 - A	Academics & Learning (cont.)		1	2	3	4	5	N/A			
8.13	Are Accessible restrooms and changing Special Education spaces?	rooms readily available to the					5		Comments	1.00	5.00
	1 No									1	
	5 Yes										
	STEAM Center										
8.14	Does the campus have space to support							5	Comments	0.00	0.00
	3 Neutral - Collaborative ar adjacent but function sepo 4 Satisfactory - Collaborative function and have space a center 5 Very Satisfactory - Function	udio / collaborative space ative areas / studios for eparate but adequate size reas / studios for CTE/CCL are arately ve areas / studios for CTE/CCL availability to create STEAM oning STEAM center offers laborative areas to support							Monitoring answer, but does not count toward overc	ill score	
	N/A Does not apply							L			
9 - C	CTE and Career Connected Learnin									17.50	94%
9.1	How close is your campus to a CTE clust with your CTE programs (Middle School							n/a	Comments	0.00	0.00
	programs that are listed in Average - School support I the cluster pathway, but m Satisfactory - School support listed in the CTE cluster path Very Satisfactory - School i pathway.	pports less than half of the CTE in the cluster pathway. half of CTE programs listed in nissing some. Fort a majority of CTE programs withway.									
	N/A Does not apply							-		1	
9.2	Do campus facilities align with the CTE I current pathways offered?: Architecture	·					5			0.25	1.25
	1 No 5 Yes N/A Does not apply										
9.3	Arts, Audio and Video Technology and G	Communications					5			0.25	1.25
9.4	Business, Management and Administrat	ıtion					5			0.25	1.25
9.5	Education and Training							n/a		0.00	0.00
9.6	Health Science						5			0.25	1.25

9 - CTE and Caree	r Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and	Tourism					5			0.25	1.25
9.8 Human Services	s (high school only)					5			0.25	1.25
9.9 Information Tea	chnology					5			0.25	1.25
9.10 Agriculture, Foo	od and Natural Resources					5			0.25	1.25
9.]] Science, Techno	ology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportation	, Distribution and Logistics	1						Student sharing opportunity with nearby campuses.	0.25	0.25
9.13 Finance (high se	chool only)					5			0.25	1.25
9.14 Government ar (high school on	nd Public Administration / JROTC Military programs ly)					5			0.25	1.25
9.15 Law, Public Safe	ety, Corrections and Security (high school only)					5			0.25	1.25
9.16 Manufacturing	(high school only)						n/a		0.00	0.00
9.17 Marketing, Sale	es and Services (high school only)					5			0.25	1.25
10 - Visual and Pe	rforming Arts								35.00	83%
10.1 Is there flexibility	ty of space to also be used by CTE and Athletics?					5		Comments	0.00	0.00
1 No 5 Ye		•						Monitoring answer, but doesn't affect overall score.		
10.2 Are band and s configured per	support spaces (rehearsal and storage) appropriately the ed spec?				4			Comments	1.00	4.00
2 Ur 3 Ne up 4 So 5 Ve	ery unsatisfactory - Too small, missing program spaces insatisfactory - Too small, poor condition eutral - Adequate size, adequate condition, needs obdates or renovations to function well. stisfactory - Good size, good condition ery Satisfactory - Generous size, excellent condition							Large rehearsal hall with good support spaces. No aux provided, approved deviation from the Ed Specs.	iliary rehears	al hall
	pes not apply and support spaces appropriately configured per the				4			Comments	1.00	4.00
2 Ur 3 Ne	ery unsatisfactory - Too small, missing program spaces nsatisfactory - Too small, poor condition eutral - Adequate size, adequate condition, needs adates or renovations to function well.							Spaces are small for a high school but it adequate for t	he school ca	pacity.

- Visual ar	nd Performing Arts (cont.)	1	2	3	4	5	N/	4	
).4 Are choir spec?	and support spaces appropriately configured per the ed				4			Comments 1.00 4	1.00
1	Very unsatisfactory - Too small, missing program spaces							No auxiliary rehearsal hall or large ensemble space, approved deviation	n
2	Unsatisfactory - Too small, poor condition							from the Ed Specs.	
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.								
4	Satisfactory - Good size, good condition								
5 N/A	Very Satisfactory - Generous size, excellent condition Does not apply								
).5 Are danc spec?	e and support spaces appropriately configured per the ed			3				Comments 1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Dance is held in the auxiliary gym, approved deviation from the Ed Spe	cs.
2	Unsatisfactory - Too small, poor condition								
3	Neutral - Adequate size, adequate condition, needs								
	updates or renovations to function well.								
4	Satisfactory - Good size, good condition								
5	Very Satisfactory - Generous size, excellent condition								
N/A	Does not apply		1	T	1	T	1		
).6 spec?	ter and support spaces appropriately configured per the ed				4				1.00
1	Very unsatisfactory - Too small, missing program spaces							No auditorium on campus due to site constraints and campus capactiy	;
2	Unsatisfactory - Too small, poor condition							Stage is in the cafeteria and has ability to open up to the exterior for	
3	Neutral - Adequate size, adequate condition, needs							outside performances, approved deviation from the Ed Specs.	
	updates or renovations to function well.								
4 5	Satisfactory - Good size, good condition								
b N/A	Very Satisfactory - Generous size, excellent condition Does not apply								
Are visua	l arts and support spaces appropriately configured per the		T	T	1	I	T		
).7 ed spec?	rates and support spaces appropriately configured per the					5		Comments 1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces					1		Two large art studios provided with kiln room and storage area.	
2	Unsatisfactory - Too small, poor condition								
3	Neutral - Adequate size, adequate condition, needs								
	updates or renovations to function well.								
4	Satisfactory - Good size, good condition								
5	Very Satisfactory - Generous size, excellent condition								
N/A	Does not apply								
Does the	campus have adequate space for the specialty arts								
	s (Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments	
							1	1.00	5.00
								1.00	
1 5	No Yes							1.00	

11 - Athletics and Wellness					26.25	77%
Does the campus meet ed spec standard for physical education program spaces?			5	Comments	1.00	5.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply				Locker rooms are small for a high school but are adequaged capacity.	uate for schoo	1
11.2 Does the campus have a dedicated wellness center?			5	Comments	0.50	2.50
1 No 5 Yes						
11.3 Does the community have access to exterior playfields/courts?			5	Comments	0.50	2.50
1 No 5 Yes						
11.4 Are facilities available to facilitate eSports (High School only)?	1			Comments	0.00	0.00
1 No 5 Yes				Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			5	Comments	0.25	1.25
1 No 5 Yes						
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1			Comments	0.25	0.25
1 No 5 Yes				Support spaces are not adequate to host events. Prac	tice field only.	
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1			Comments	0.25	0.25
1 No 5 Yes				Field condition and support spaces are not adequate practice field only.	to host events.	•
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			5	Comments	0.25	1.25
1 No 5 Yes						
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1			Comments	0.25	0.25
1 No 5 Yes				No tennis courts on site.		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1			Comments	0.25	0.25
1 No 5 Yes				Field condition and support spaces are not adequate Practice field only.	to host events.	

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)		1	2	3	4	5	N/A			
11.11 Are facilities (dedicated storage) set up to support UIL athletics for cross-country (high school only)?	sanctioned					5		Comments	0.25	1.25
1 No 5 Yes										
11.12 Are facilities (dedicated storage) set up to support UIL athletics for golf (high school only)?	sanctioned					5		Comments	0.25	1.25
1 No 5 Yes										
11.13 Are facilities (dedicated storage) set up to support UIL athletics for swimming (high school only)?	sanctioned					5		Comments	0.25	1.25
1 No 5 Yes										
11.14 Are facilities set up to support UIL sanctioned athletics (high school only)?	for wrestling					5		Comments	0.25	1.25
l No 5 Yes								No dedicated wrestling space, will use aux gym.		
11.15 Are facilities set up to support UIL sanctioned athletics (high school only)?	for baseball	1						Comments	0.25	0.25
1 No 5 Yes								No baseball field on site.		
11.16 Are facilities set up to support UIL sanctioned athletics (high school only)?	for softball	1						Comments	0.25	0.25
1 No 5 Yes	<u>'</u>				·			No softball field on site.		
11.17 Are facilities (dedicated space outside of the gymnasia support competitive spirit activities for cheerleading a						5		Comments	0.25	1.25
1 No 5 Yes										
11 - Athletics and Wellness (cont.)		1	2	3	4	5	N/A			
How do the athletics fields align with FMP Campus Im 11.18 Turf Field, Parking lot lighting, ADA accessible ameniti only)		1						Comments	0.00	0.00
1 Very unsatisfactory - No turf, inaccessible 2 Unsatisfactory - No turf/field in poor con accessibility concerns, poor site lighting 3 Average - Field in adequate condition, no updates or renovations to function well 4 Satisfactory - Turf field in good condition access and site lighting 5 Very Satisfactory - Turf field with exceller excellent ADA access for spectators and excellent site lighting N/A Does not apply.	dition, some eeds some , good ADA at maintenance,							Monitoring answer, but doesn't affect overall score. N lighting is not sufficient. No work is being done to the bond other than minor irrigation repairs.		

Perkins&Will 02/11/2022 10

12 - Food Servi	ices							10.0	0	100%
12.1 Is the Dinin	ng Commons appropriately configured per the ed spec?					5		Comments 1.0	0	5.0
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply							Dining commons and kitchen are adequate for student capac Cafeteria is one large open space and provides multiple seati	-	
12.2 Are the Footthe the ed spec	od Services support spaces appropriately configured per c?					5		Comments 1.0	00	5.0
1	Very unsatisfactory - None provided		<u> </u>	<u> </u>				Kitchen is adequately sized to support dining commons.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
N/A	condition									
·	Does not apply									
3 - Media Res		1	2		3 4	5	N/	'A 30.0	0	83
l3.1 Is the Libra visitors to t	ry/Media Center easily accessible for the occupants and he school?					5		Comments 1.0	0	5.0
1 2	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency							Library is near the main entry and highly visible. Library has ar transparency and natural daylighting.	nple	
3	Average - Adequate accessibility, needs updates or renovations to function well									
4	Satisfactory - Accessible, easy to find, good									
	transparency, good condition									
5	Very Satisfactory - Accessible, easy to find, excellent									
N/A	transparency, excellent condition Does not apply									
1 1/ //	Does not apply									

13 - Media Res	ources - Continued	1	2	3	4	5	N/A	4		
13.2 How well d	loes the Library/Media Center support quiet study?			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy							Two zones (main floor and elevated stage) for study s acoustical separation.	paces but no	
N/A 13.3 How well d	Does not apply loes the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							It is good sized but not generous and is very open to einteraction	1.00 encourage info	4.00 rmal
N/A How well d	Does not apply loes the Library/Media Center support collaborative work			3				Comments		
1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply							Multiple areas provided but no acoustic separation b	1.00 etween them.	3.00
13 5	roups (10-25)?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply									

13 - Med	dia Res	ources - Continued	1	2	3	4		5	N/A			
13.6 Ho	w well do	oes the Library/Media Center support technology?						5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition								Ceiling-mounted projector with drop-down screen p study area provided with 8 student desktop compute		nology
	N/A	Does not apply										
14 - Tech	nnology	y	1	2	3	4		5	N/A		20.00	100%
14.1 Ho	w well ed	quipped are the facilities with instructional technology?					:	5		Comments	1.00	5.00
	1	Very unsatisfactory - Limited to no technology present in instructional spaces			•	•	•					
	2	Unsatisfactory - One type of technology present										
	3	Average - Multiple types of technology, smart boards.										
	4	Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition.										
	5	Very Satisfactory - Multiple types of technology, smart										
		boards. Excellent condition										
	N/A	Does not apply			ı	1		ı				
142	nere an a aces?	adequate number of power and data outlets in learning						5		Comments	1.00	5.00
	1	Very unsatisfactory - Outlet configuration does not		<u> </u>								
	2	support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)										
	3	Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall)										
	4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall)										
	5	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)										
	N/A	Does not apply										

Perkins&Will 02/11/2022 13

14 - Technolog	y (cont.)	1	2	3	3 4	5	Ν	/A			
14.3 Are there of	adequate charging locations for devices?					5			Comments	1.00	5.00
1	Very unsatisfactory - Not enough charging locations throughout school for 1:1										
2	Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices										
3	Average - Charging locations well organized but not enough capacity for 1:1										
4	Satisfactory - Charging locations, haphazard locations, but supports 1:1.										
5	Very Satisfactory - Charging locations throughout school to support 1:1.										
N/A	Does not apply										
ls there adagram?	equate AV for presentations spaces – cafeteria, gym, aux					5			Comments	1.00	5.00
1	Very unsatisfactory - AV not present in one or more space								otorized drop-down screen and ceiling projector pr th audio system.	ovided in both	along
2	Unsatisfactory - AV undersized for room. Poor condition								•		
3	Average - AV adequately sized / poor condition OR AV undersized / average condition										
4	Satisfactory - AV adequately sized for room. Average Condition.										
5	Very Satisfactory - AV adequately sized for room. Excellent condition.										
N/A	Does not apply										
14.5 Is there dig	gital media signage at the reception area?					5			Comments	0.00	0.0
1	Very unsatisfactory - No digital media present in reception area				-			70"	" display provided on main wall in reception area.		
2	Unsatisfactory - Undersized, poor condition										
3	Average - Adequately sized / poor condition OR undersized / adequate condition										
4	Satisfactory - Media signage present, good sized, good condition										
5	Very Satisfactory - Generously sized, excellent condition										
N/A	Does not apply							,			

15 - Administration Spaces		1	2	3	4	5	N/A	i.	20.00	100%
15.1 Is there a r	eception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition							·		
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
15.2 Does the a	administration area feel welcoming?					5		Comments	1.00	5.00
1	Very unsatisfactory - No welcome space									
2	Unsatisfactory - Too small, poor lighting and									
	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
· ·	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
	excellent condition									
N/A	Does not apply									
For those spaces that require it, does the administration area have			5 Comments	Comments						
adequate	acoustic privacy?					Ŭ			1.00	5.00
1 Very unsatisfactory - No acoustic separations								Interior walls are acoustically treated and go to the underside of the floor		
2	Unsatisfactory - Acoustic separations do not perform							slab above.		
2	well 3 Average - Some acoustic separations function okay, but									
portions need updates or renovations 4 Satisfactory - Good acoustic separations 5 Very Satisfactory - Excellent acoustic separations										
N/A	Does not apply									
15.4 Are confer	ence rooms easily accessed for public / parent use?					5		Comments	1.00	5.00
1	Very unsatisfactory - Not accessible for public/parent			1	1			Conference room/parent room provided at main ent		
	use							conference room provided in administration suite ac	•	
2	Unsatisfactory - Limited access, no transparency, poor							,		
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
-	good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A	Does not apply									