



Educational Suitability Summary Report

Future Liberal Arts and Science Academy at Current Eastside Campus

Date: 01/26/2021

Score 53% Average

International High School and Eastside Memorial Early College High School share a campus in east Austin. Together, they serve an enrollment of approximately 675 students. Both the International and Eastside programs are moving to a new campus and the Liberal Arts and Science Academy (LASA) will begin occupying the campus in fall 2021. The campus will undergo partial renovations during the summer of 2021 in preparation for the new users.

The original campus was built in the 1950s and consists of approximately 253,300 square feet on 26 acres. The overall campus appears aged, parking is undersized, and wayfinding signage is poor. While the campus is large with ample daylight and courtyards for outdoor learning, it needs renovations and modernizations to meet the current Educational Specifications.

The primary campus building is one story with traditional double-loaded academic corridors and fullheight exterior windows that maximize natural light in the studios. There is no transparency between most studios and corridors and no room for collaboration or breakout space outside the studios. Most of the furniture and finishes are outdated and need updates to fully support a modern and collaborative learning environment. The athletic additions are undersized, difficult to navigate and need modernization.

The campus is scheduled to undergo partial renovations in spring of 2021 that will be completed by beginning of the 2021 school year. The renovations will consist of reconfiguring some academic studios, CTE rooms, and athletic spaces to functionally support the programs at LASA. Newly accommodated programs will include dance, guitar/jazz band, wood shop, metal shop, robotics, scitech, and additional science labs.

The student parking lot on the north side of the building will be reconfigured and restriped to support marching band practice.

Interview Overview

The interview was conducted virtually with the future users of the campus, the Liberal Arts and Science Academy. We were joined by Principal Crescenzi along with select faculty and staff. While participants generally expressed the need for more space for their growing enrollment, they agreed there are some features of the campus that should be preserved. These features include the Veterans' Memorial at the main entrance, the future College Center and the existing courtyards that provide access to daylight, views and outdoor learning opportunities.

Participants also shared their concerns about the suitability of certain programmatic spaces. Both the main gymnasium and the Performing Arts Center are undersized, and neither can support whole-campus events. The campus has no dedicated marching pad, and the interior instructional and

Educational Suitability Summary Report Future Liberal Arts and Science Academy

support spaces are undersized for their robust music program. In the CTE and Fine Arts wing, the robotics room is limited by the low ceiling height. The wrestling room needs a dedicated practice area, and the weight room could be larger. Some teachers expressed concerns about the lack of flexible collaboration spaces throughout the campus.

In the future, the school hopes to include programs such as music production, anthropology, animation production, biotech lab research, fire academy, marketing/business/accounting, and sports medicine. These programs need room to grow, and participants emphasized the lack of available interior space as a significant barrier to programmatic growth. Campus representatives shared their hope to create more permanent outdoor learning spaces in the exterior courtyards. Establishing strong network connections that support digital learning will be an important consideration for future campus planning.

Assessment Findings

The Educational Suitability Assessment of the future LASA campus at 1012 Arthur Stiles Road earned a 53% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Academics & Learning

Score is very unsatisfactory.

Learning studios are not organized into learning neighborhoods. The layout consists of traditional double-loaded corridors with solid walls. Studios lack flexibility, transparency and collaboration space. Studios are generally undersized and need mobile furniture to support project-based learning.

Visual and Performing Arts

Score is very unsatisfactory.

The visual arts and music rooms are in adequate condition but are generally undersized and some programmatic spaces are missing entirely.

Technology

Score is very unsatisfactory.

Technology is inconsistent across the campus. Some studios contain ample wall outlets, projectors and digital display screens, while others do not. The cafeteria and media center both have a large screen, but no mounted projector. Gym does not have AV. Digital media signage is missing in the reception area.

Unsatisfactory Categories (36-50%):

Exterior

Score is unsatisfactory.

The age of the original building is showing, and the entrances need updates. Signage is limited and the main entry is difficult to find. There is a mixing of bus and car traffic at both the front and back of the school. Stack space is undersized.

General Building

Score is unsatisfactory.

The age of the original building is showing, and the exterior entrances need updates. Signage is limited and the main entry is difficult to find.

Furniture, Fixtures, Equipment

Score is unsatisfactory.

None of the learning spaces have a variety of flexible furniture. Studios have single desks/tables and loose chairs that are cumbersome to rearrange for project-based learning. The cafeteria provides folding tables with loose chairs and fixed booth seating that is outdated.

Athletics and Wellness

Score is unsatisfactory.

Physical education spaces are inconsistent. The main gymnasium and weight rooms are undersized. Support spaces generally need updates. In an upcoming project, one of the gyms will be converted to rooms dedicated to dance and wrestling. In general, the athletics wing has narrow corridors with poor lighting, finishes and signage.

Food Services

Score is unsatisfactory.

The cafeteria is adequately sized with plenty of natural light and access to outdoor dining. No table and chair storage or projector were observed. Furniture is outdated and difficult to rearrange.

Average Categories (51-65%):

Security

Score is average.

Controllability of Systems

Score is average.

Studios allow for individual control of thermostats. The majority of the lighting controls in the studios are on a single switch. Window blinds are present, but some are damaged and need to be updated.

Media Resources

Score is average.

The library is adequately sized per the ed specs. A variety of flexible furniture and breakout rooms are needed to support collaboration in varying group sizes. There is no direct exterior access for visitors to utilize the library for after-hours functions.

Administration Spaces

Score is average.

which will bring natural light and

Educational Suitability Summary Report

Future Liberal Arts and Science Academy

transparency into reception. The rest of the administration suite will remain small with very limited natural light. The conference room has no transparency and is difficult to find for public or parent use.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

The campus has plenty of courtyards that provide opportunities for outdoor learning. Many of the spaces are overgrown, not well-maintained and are not ADA accessible. In an upcoming project, of the courtyards will have site drainage improvements.

Environmental Quality

Score is very satisfactory. All studios have access to plenty of natural light and exterior views.

Satisfactory Categories (81-100%):

CTE and Career Connected Learning


Score is very satisfactory.

All CTE programs identified in the master plan are offered at the new LASA campus and have dedicated spaces. As a part of the 2021 renovations, many CTE spaces are being upgraded to better align with ed spec requirements.

Educational Suitability Summary Report

Future Liberal Arts and Science Academy

Supporting Photographs



summer of 2021.

<image>

The marquee sign is far from the main entry and is overgrown with weeds (left). School gardens are present, but the unraised beds and cracked walkways are not ADA compliant (right).

Educational Suitability Summary Report

Future Liberal Arts and Science Academy

Supporting Photographs



The campus has plenty of courtyards that bring in natural light and provide opportunities for outdoor learning and dining. Renovations are needed to bring some of the courtyards into ADA compliance.



Tennis courts appear to be new and/or in good condition (left). Exterior handrailing is bent with peeling paint and stairs pose a trip hazard (right).

Educational Suitability Summary Report Future Liberal Arts and Science Academy

Supporting Photographs



Media Center: The library is in good condition but needs mobile furniture and technology updates.



The furniture in the cafeteria is not mobile and there is no projector.



Educational Suitability Summary Report Future Liberal Arts and Science Academy

Supporting Photographs




Typical studios have plenty of daylight but need mobile furniture and movable partitions to fully support project-based learning.



Typical corridors have no transparency into the studios and some lockers appear to be damaged/broken.

Educational Suitability Summary Report Future Liberal Arts and Science Academy

Supporting Photographs



Locker rooms have plenty of natural light (left). Athletic corridors are very narrow, dark and difficult to navigate (right).



The main gym is too small to support bleachers on either side of the playing area and lacks dedicated restrooms.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Future Liberal Arts and Science Academy at Eastside Campus	Travis Hughbanks & Shani Saul	1/26/2021

1 - Ex	terior		1	2	3	4	5	N/A		8.75	40%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Per school, there will be both pedestrian, car and bus	traffic out from	nt at the
		at the same location							beginning and end of the day (some, but not exclusiv	ve for car). The	re will
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated							be bus and car traffic out back at the late bus/end or	-	
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply							<u> </u>		
1.2		ing easily identified with appropriate signage and wayfinding?		2					Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage / wayfinding		•				•	The signage is generally poor. There are no wayfindi the main entry and upcoming renovations will remov	•	o access
	2	Unsatisfactory - Signage/wayfinding is faded/hidden							marquee sign at the southwest corner of the site. A n	ew marquee si	gn will
	3	Average - Signage / wayfinding visible but not apparent							be provided by the District, but will do little to improv	ve wayfinding	to the
	4	Satisfactory - Signage / wayfinding is visible but not good condition							main entry.		
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

02/11/2022 ²

Exterior (cont.)	1	2	3	4	5	N/A	۱. 		
.3 Is the dumpster accessible for trash / compost disposal?		2					Comments	0.50	1.0
 Very unsatisfactory - No compost present, route ha obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obs to dumpster Average - Compost is present (<100' to cafeteria), R to dumpster is free and clear but the two are not di adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are dire adjacent and route is barrier free. Very Satisfactory - Compost and dumpster are sh / positioned so people of all heights can access it. 	tacles Route irectly ectly		I				The door out of the kitchen to the compost bin has s		
N/A Does not apply									
- Outdoor Learning and Activity	1	2	3	4	5	N/A	х	10.00	80
Are outdoor studios and support spaces appropriately configure the ed spec?	ed per		3				Comments	1.00	3.0
1 Very unsatisfactory - No dedicated outdoor studios	s						Multiple locations are provided for outdoor studios.	A covered area	a with
2 Unsatisfactory - Too small, poor condition, disconn	ected						picnic tables is provided in the main cafeteria courty	ard and other	small
from learning spaces, no flexibility, no shade provid	ded						courtyards have chairs, tables and seating for inforn	nal outdoor lea	arning
3 Average - Adequate size, adequate condition, new some renovations or updates to function well, 50% less shade coverage over studio area									
4 Satisfactory - Good size, good condition, connecte learning spaces, good flexibility, more than 50% sh									
coverage over studio area 5 Very satisfactory - Generous size, excellent conditio connected to learning spaces, excellent flexibility, f									
shade coverage over studio area N/A Does not apply									
Are active playgrounds (elementary only) and support spaces		Ι				n/a	Comments		
configured per the ed spec?								0.00	0.
1 Very unsatisfactory - No dedicated active playgrou									
2 Unsatisfactory - Too small, poor condition, no shad provided	le								
 provided Average - Adequate size, adequate condition, need some renovations or updates to function well, 50% less shade coverage over play structure 									
4 Satisfactory - Good size, good condition, more that	n 50%								
shade coverage over play structure 5 Very satisfactory - Generous size, excellent conditic									

02/11/2022 ³

- Outdoor Le	earning and Activity (cont)	1	2	3	4	5	N/A		
2.3 Are garder spec? (eva	ns and support spaces appropriately configured per the ed luation on infrastructure not condition of plants)		2					Comments 0.00	0.0
1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source				•			Monitoring answer, does not affect score for Outdoor Learning and Activity.	
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
N/A	Does not apply					1	1		
2.4 Are the rai ed spec?	n gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.0
1	Very unsatisfactory - No rain gardens or cisterns		-				-	Monitoring answer, does not affect score for Outdoor Learning and	
2	Unsatisfactory - Too small, poor condition, not							Activity.	
_	functioning, disconnected								
3	Average - Adequate size, adequate condition, is								
	connected, needs some renovations or updates to function well								
4	Satisfactory - Good size, good condition, functions								
	properly								
5	Very Satisfactory - Generous size, excellent condition,								
	exceptional functionality, connected to learning spaces,								
	educational signage provided								
N/A	Does not apply					1			
	chool have animal husbandry? (optional)	1						Comments 0.00	0.0
1 5	No							Animals moving to new Eastside. Animals to be	
-	Yes chool have nature loop trails? (optional)	1						taken care of by clubs and science classes. Comments 0.00	0.0
2.0 Does the st	No	1				ļ		Comments 0:00	0.0
5	Yes								
-	chool have a learning pond? (optional)	1						Comments 0.00	0.0
1	No					1	l		
5	Yes								
2.8 Does the se	chool have a grass play field and walking trail?					5		Comments 1.00	5.0
1	No						L		
5	Yes								

- General Building	1	2	3	4	5	N/A	A Contraction of the second seco	11.25	47
Are interior circulation routes wide enough to safely and effective	əly				5		Comments		
accommodate student movement?					0		commenta	0.50	2.5
 Very unsatisfactory - Primary circulation is 5'-0" to 6 	'-0"								
wide									
2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" w	vide								
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide	e								
N/A Does not apply									
Are community use areas arranged so that the school can allow r	night	2					Comments		
functions without full school access?		2					Comments	0.75	1.9
 Very unsatisfactory - Cafeteria, gym, and library car 	nnot						The cafeteria and library do not have after-hours en	trances or the o	ability
be accessed after hours							to close off the rest of the school securely. The theate	er and gymnasi	ium
2 Unsatisfactory - Only one of the public spaces (Cafe							both allow for secure after-hours functions.		
Gym and Library) can be accessed from parking and secured after hours	a								
 Average - Only two of the public spaces can be acce 	hassed								
from parking and secured after hours	03500								
4 Satisfactory - All of the public spaces can be accessed	ed								
from parking and secured from the rest of the buildi									
but not individually									
5 Very satisfactory - Cafeteria, gym, and library can b	e								
accessed from parking and locked off from rest of									
campus for night/evening use with their own entran	ice								
N/A Does not apply									
Is there a community room that is a dedicated meeting space out	tside						Comments		
of school function?							Commenta	0.75	0.
1 Very unsatisfactory - No dedicated community room									
2 Unsatisfactory - Community room but within school									
function, no access after school hours	а								
3 Average - Community room, moderate size, but nee some renovations or updates to function well	a								
4 Satisfactory - Community room, good size /layout, n	neets								
needs /functions well	10000								
5 Very Satisfactory - Community room, generous size,	nice								
condition, functions appropriately outside of school									
function									
N/A Does not apply		-	r		1	1		T	
Does the general appearance of the school convey pride for the		2					Comments		
students and community?								0.25	0.
1 Very unsatisfactory - General appearance is poor							The school's age is showing. Sidewalks are uneven a		
2 Unsatisfactory - General appearance is aged but ok	< C						Landscaping is overgrown. Paint is peeling, and som	e railings are b	ent.
3 Average - General appearance is good									
4 Satisfactory - General appearance shows pride in campus and student works									
5 Very satisfactory - General appearance shows pride	e in								
campus and student works and is welcoming to the									
community									
N/A Does not apply									

- Security		1	2	3	4	5	N/A		16.25
.] Does the fo	acility have key card access at all major entries?							Comments	0.25
1	Very unsatisfactory - No entries				<u> </u>				
2	Unsatisfactory - 1/4 of major entries								
3	Average - 1/2 of major entries								
4	Satisfactory - 3/4 of major entries								
5	Very satisfactory - All of major entries								
N/A	Does not apply								
.2 How adeq	uate is site lighting and security for the campus overall?							Comments	1.00
1	Very unsatisfactory - No exterior lighting, no secure								
0	perimeter								
2	Unsatisfactory - Lighting is limited to front entry only,								
0	parking lot lighting poor, security is minimal								
3	Average - Lighting at all night-use entries and parking								
4	lot, but poor condition. Security is moderate								
4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible,								
	perimeter is well secured but needs updates								
5									
	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply								
Is the main	n office located at the school entry and configured with a								
.3 secure ves	tibule to the main corridor?							Comments	1.00
1	Very unsatisfactory - No secure vestibule, office located								
	far from main entry, allows visitors access to school								
	unsupervised								
2	Unsatisfactory - No secure vestibule, office located								
	somewhat far from main entry, minimal supervision of								
2	visitors								
3	Average - Office close to entry, views of front door, but no secure vestibule								
4	Satisfactory - Office is well-located with a secure								
	vestibule, but needs updates								
5	Very satisfactory - Office well-located with secure								
	vestibule and all appropriate security features								
N/A	Does not apply								
Is there en	ough interior transparency for faculty to passively supervise							Comments	
.4 learners ar	nd their activities who are not in studios?							Comments	1.00
1	Very unsatisfactory - No transparency of walls								
2	Unsatisfactory - Limited transparency in certain locations	5							
2	Average - Good transparency in certain locations but								
3	inadequate or missing in other locations of school								
3									
4	Satisfactory - Adequate transparency throughout the								
	Satisfactory - Adequate transparency throughout the school								
		•							
4	school	,							

02/11/2022 °

5 - Environmental Quality	1	2	3	4	5	N/A	A	25.00	72%
5.1 How are acoustics in studios in general?			3				Comments	1.00	3.0
 Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room 		•				1			
 4 Satisfactory - Walls to deck insulated only white noise from mechanical system 5 Very satisfactory - Able to hear quiet speaking from 									
across the room N/A Does not apply									
5.2 Is the studio artificial lighting adequate quality?			3				Comments	1.00	3.0
 Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare 							New renovations will improve the lighting in some sp of studios will still have unsatisfactory lighting.	baces, but the n	najorit
N/A Does not apply									
5.3 Is there access to natural light in studios?					5		Comments	1.00	5.0
 Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light 							All studio spaces in the main building have large sec glazing from countertop height to ceiling. The annex windows, but all studios have access to natural light	es have smalle	
 Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light 									
5 Very satisfactory - 76-100% of learning spaces have natural light									
N/A Does not apply		1	r		1	1	1	Г	
5.4 Is there access to outside views from learning spaces?					5		Comments	1.00	5.0
Very unsatisfactory - No learning spaces have views							See above		
2 Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out									
3 Average - 26-50% of learning spaces have views									
 4 Satisfactory - 51-75% of learning spaces have views 5 Very satisfactory - 76-100% of learning spaces have 									
views N/A Does not apply									

5 - E	nvironmen	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	uilding have odor or pest problems?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							There is evidence of cockroaches, but no noticeable of According to the staff and neighbors, racoons are a b get into the building and live in the area between the	ig problem and	
6 - 0	Controllabi	lity of Systems	1	2	3	4	5	N/A		12.50	52%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes									
6.2	Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades									
	N/A	Does not apply				1					
6.3	What is the	quality of lighting controls in the studios?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply							The majority of lights are on a single switch. Annex sp switches.	paces have dua	I

7 - Furniture, Fixtures & Equipment 18.75 3 4 5 N/A 1 2 7.1 What is the current condition of the furniture? 3 Comments 0.75 Very unsatisfactory - Damaged or broken, nonfunctioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply Are a variety of furniture types being accommodated throughout the 2 Comments school - learning commons, dining commons, other multi-use spaces? 1.00 Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater

than two types of furniture N/A Does not apply How well does furniture accommodate rapid reconfiguration of a 7.3 2 Comments space? 2.00 1.00 Very Unsatisfactory - Furniture is fixed or very heavy The majority of studio furniture is not able to be reconfigured for individual 1 2 Unsatisfactory - Furniture does not allow desks to be learning. configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is 3 cumbersome to move Satisfactory - Furniture is flexible for multiple 4 configurations of space 5 Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack N/A Does not apply 7.4 Is the furniture ergonomic and size appropriate for grade level? 3 Comments 1.00 3.00 Very unsatisfactory - Desk with attached chair 1 combinations too small for grade level 2 Unsatisfactory - Desk with attached chair combinations

desks with fixed seats 4 Very satisfactory - Tables with loose chairs

Average - Mix of studios with tables/loose chairs and

5 Very satisfactory - Tables with loose chairs that allow students to be active

N/A Does not apply

7.2

1

2

3

4

5

N/A

1

2

3

4

5

3

02/11/2022 8

49%

2.25

2.00

02/11/2022 °

Do studies and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions? 2 2 0 0 0.00 1 Very unstificatory - There are no recycling and landing bins and signage are sparse or infrequent. OR there are only londfill bins with no recycleng bins. A score for this category is being recorded, but this category is not calculated in the overall ESA average. A score for this category is being recorded, but this category is not calculated in the overall ESA average. 3 A verage - 50% of ordinors and studies have both a landfill and recycle corridors and studies have o valible location. The containers have clear signage. A so this category is not signage are sparse or infrequent and/or incode clear signage. 4 Sa trifficatory - 75% of studies and corridors have a valible location. The containers have clear signage, and the style and format is consistent and uniform accessible locations. The containers have clear signage, and the style and format is consistent and uniform accessible location. The containers have a test so ne or as compus. 4 4 Comments N/A Does not copply Example 4 4 Comments 0.50 1 Very sustificatory - There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 4 4 6 Comments 0.50 1 Very sustificatory - There may be landfill bins, but there are no compost and/or recycle bins. There is not clear	Waste		1	2	3	4	5	N/A		5.00	60
bins and signage are sparse or infrequent. OR there are only londfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and taulois have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Isotisfactory - 75% of studies and corridors have a visible location. The containers have clear signage. 5 Very satisfactory - All studies / corridors and uniform accessible locations. The containers have clear signage, and the style and format is consistent and uniform across compus. N/A Does not apply Does the offeteria (or wherever meals are served) have at least one of each yiele and fill bin? Are the bins labeled clearly with bing exercise is in a coressible. bins labeled clearly with bing exercise is in a coressible bins labeled clearly with bing exercise is in a coressible bins labeled clearly with bing exercise is not clear sing signage. 2 Unsatisfactory - There may be landfill bin? Are the bins a baseled clearly with bing are sprayed and no runge sorting? 2 Unsatisfactory - There may be landfill bins are prosent, but the bins are satured and no conclused next to one another. Signage is absent or inconsistent. 3 Average - There is at least one wate station with all three bins (exclearly - There are several more station with all three bins (exclearly - There are several more station with all three bins (exclearly - There are several wate stations as described above. 5 Very Satisfactory - There are several wate stations as described above, and additional signage in the cofferent to the nourage excercing clear stations as described above.		,		2					Comments	0.50	1.0
Dest the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting? 4 Comments 0.50 1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 0.50 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.	3 4 5	bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.								ry is not	
 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory - There are several waste stations as described above Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting. 	Does the co of each: gre	afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the				4			Comments	0.50	2.0
described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.		are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and						1		0.00	
cafeteria that encourages recycling/composting.		described above									
	N/A	described above, and additional signage in the									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Future Liberal Arts and Science Academy at Eastside Campus	Travis Hughbanks & Shani Saul	1/26/2021
	_	

8 - /	Academics &	k Learning	1	2	3	4	5	N/A	A	65.00	34%
8.1	Are studios	appropriately configured per the ed spec?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Too small, no flexibility,							Learning studios are not organized into learning neig	hborhoods. Th	е
		disconnected							layout consists of traditional double-loaded corridors	s with solid wal	ls.
	2	Unsatisfactory - Too small, only one area for all teaching							Studios lack flexibility, transparency and collaboratio	on space. Studio	os are
		methods, limited flexibility, disconnected							generally undersized and need mobile furniture to su	pport project-l	based
	3	Neutral - Adequate size, multiple areas for different							learning.		
		teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
		spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility,									
		generous display area and visual teaching tools,									
		excellent transparency and connection with other									
	N/A	studios and shared learning spaces Does not apply									
		ave appropriate support spaces such as storage per the							1		
8.2	ed spec?	iave appropriate support spaces such as storage per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided					I			1.00	0.00
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
	3	updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	-	condition									
	N/A	Does not apply									
		,									

02/11/2022 ²

8 - Ac	ademics &	& Learning (cont.)	1	2	3	4	5	N/A	A					
8.3 [[]	Do typical le	earning neighborhoods have small and medium (high		2					Comments					
8.3 s	chool only)	group rooms and open collaboration space?		2					Comments	1.00	2.00			
	1	Very unsatisfactory - No breakout rooms or open							The east and west annexes have two small group rooms as well as small					
		collaboration spaces are provided							collaboration spaces in the corridors. The main building has no small					
	2	Unsatisfactory - Too small or too few, poor condition, no							group, medium group or collaboration areas.	-				
		flexibility, lacks visual connection to learning												
		neighborhood, poor acoustic privacy												
	3	Average - Adequate size, adequate condition, needs												
		some renovations or updates to function well												
	4	Satisfactory - Good size, good condition and flexibility,												
		transparency and connection to learning neighborhood,												
		acoustic privacy												
	5	Very Satisfactory - Generous size, excellent condition												
		and flexibility, transparency and connection to learning												
		neighborhood, acoustic privacy												
	N/A	Does not apply							1					
84		Labs and support spaces appropriately configured per			3				Comments					
t t	he ed spec									1.00	3.00			
	1	Very unsatisfactory - No dedicated science room							After summer renovations all science labs will have t	he necessary v	vater,			
	2	Unsatisfactory - Too small, poor condition, no connected							gas, and fume hoods per ed spec. Majority of labs c	ire in poor con	dition			
		support space							and need renovations.					
	3	Average - Adequate size, adequate condition, needs												
		some renovations or updates to function well												
	4	Satisfactory - Good size, good condition, connected												
	_	support spaces												
	5	Very Satisfactory - Generous size, excellent condition,												
	N1/A	connected support spaces												
	N/A	Does not apply		1	1	1	1	1						
		Spaces and support spaces appropriately configured per ? (cross reference with CTE below)		2					Comments	1.00				
										1.00	2.00			
	1	Very unsatisfactory - No dedicated maker spaces												
	2	Unsatisfactory - Too small, poor condition, disconnected												
	0	from learning spaces, no flexibility												
	3	Average - Adequate size, adequate condition, needs												
	,	some renovations or updates to function well												
	4	Satisfactory - Good size, good condition, connected to												
	_	learning spaces												
	5	Very Satisfactory - Generous size, excellent condition,												
	N1/A	connected to learning spaces												
	N/A	Does not apply												

02/11/2022 ³

8	Academics & Learning (cont.)	1	2	3	4	5	N/A			
8	6 Is there a Professional Learning Center in the learning neighborhood?		2					Comments	1.00	2.00
	 Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected 							Only two teachers lounges provided throughout the spaces are dedicated for teachers use outside of the		ier
	 Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected 									
ε	7 Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?		2					Comments	1.00	2.00
	 Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition N/A Does not apply 									
8	Does the building / learning neighborhood provide adequate 8 opportunities for students/teachers to collaborate in varying group sizes?	1						Comments	1.00	1.00
	 Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 							Studios are not flexible and do not have the necessa technology or infrastructure to adjust to group size.	ry furniture,	
8	N/A Does not apply 9 Does the building provide opportunities for informal interaction?	1						Comments	1.00	1.00
	 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 									



8 - Academics	& Learning (cont.)	1	2	3	4	5	N//	4		
Does the b	uilding provide adequate opportunities for students to	1						Comments		
work indep	pendently?	1						Comments	1.00	1.00
1	Very unsatisfactory - No breakout rooms/small study									
	spaces									
2	Unsatisfactory - Too small, poor condition, no acoustic									
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy,									
	variety of independent work space options, connected to									
	learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space									
	options, connected to learning neighborhood									
N/A	Does not apply									
Special Ed	ucation		r	1	_	1	1			
	l Education spaces appropriately configured per the ed		2					Comments		
spec?			4					commenta	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility,									
	disconnected									
2	Unsatisfactory - Too small, only one area for all teaching									
	methods, limited flexibility, disconnected									
3	Neutral - Adequate size, multiple areas for different									
	teaching methods, adequate flexibility, limited									
	transparency and connection to other studios and									
	shared learning spaces, needs updates or renovations to									
	function well.									
4	Satisfactory - Good size, multiple areas for different									
	teaching methods, good flexibility, good transparency									
	and connection to other studios and shared learning									
	spaces									
5	Very Satisfactory - Generous size, multiple areas for									
	different teaching methods, excellent flexibility,									
	generous display area and visual teaching tools,									
	excellent transparency and connection with other									
	studios and shared learning spaces									
N/A	Does not apply		-	1	-	1	1			
	I Education support spaces, such as storage, space for	1						Comments	1.00	
	yer, appropriately configured per the ed spec?					<u> </u>		I	1.00	1.00
1	Very unsatisfactory - None provided									
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

8 - A	Academics &	& Learning (cont.)	1	2	3	4	5	N/A			
8.13		ble restrooms and changing rooms readily available to the	1						Comments		
	Special Edu	acation spaces?								1.00	1.00
	5	No Yes									
	STEAM Cen										
8.14		impus have space to support a "STEAM" center?	1						Comments	0.00	0.00
	1	Very unsatisfactory - No available space for STEAM							Monitoring answer, but does not count toward overa	III score	
	2	center and inadequate studio / collaborative space Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size									
	3	Neutral - Collaborative areas / studios for CTE/CCL are									
	4	adjacent but function separately Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM									
	5	center Very Satisfactory - Functioning STEAM center offers									
		studios, labs, common collaborative areas to support									
		multimedia distance and hands-on project based									
	N/A	learning Does not apply									
9 - 0		reer Connected Learning								7.50	87%
		s your campus to a CTE cluster pathway that is aligned							Commente		
9.1	with your C	TE programs (Middle School only)?						n/a	Comments	0.00	0.00
	1	Very unsatisfactory - No correlation to CTE cluster									
	2	pathway, no CTE programs. Unsatisfactory - School supports less than half of the CTE									
		programs that are listed in the cluster pathway.									
	3	Average - School support half of CTE programs listed in the cluster pathway, but missing some.									
	4	Satisfactory - School support a majority of CTE programs									
		listed in the CTE cluster pathway.									
	5	Very Satisfactory - School is aligned with CTE cluster									
	N/A	pathway. Does not apply									
9.2		facilities align with the CTE Ed Spec Requirements for the hways offered?: Architecture and Construction						n/a			
										0.00	0.00
	5	No Yes									
	N/A	Does not apply									
9.3	Arts, Audio	and Video Technology and Communications					5			0.25	1.25
9.4	Business, M	anagement and Administration						n/a		0.00	0.00
9.5	Education o	and Training						n/a		0.00	0.00
9.6	Health Scie	nce					5			0.25	1.25

02/11/2022 °

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism						n/a		0.00	0.00
9.8 Human Services (high school only)	1						Currently have classes but there is no designated space for long term.	0.25	0.25
9.9 Information Technology					5			0.25	1.25
9.10 Agriculture, Food and Natural Resources						n/a		0.00	0.00
9.]] Science, Technology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportation, Distribution and Logistics						n/a		0.00	0.00
9.13 Finance (high school only)						n/a		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						n/a		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)					5			0.25	1.25
9.16 Manufacturing (high school only)						n/a		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						n/a			
10 - Visual and Performing Arts								0.00	0.00 34%
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments		
1 No							Monitoring answer, but doesn't affect overall score.	0.00	0.00
5 Yes		r - 1							
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?		2					Comments	1.00	2.00
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition 							The band hall is undersized, has no auxiliary rehears majority of its support spaces are undersized. The ove condition with plenty of natural light.		
N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec?		2					Comments	1.00	2.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply							The rehearsal hall is too small and is missing the enser overall space is in good condition.	mble room. Th	ne

10 - Visual and	d Performing Arts (cont.)	1	2	3	4	5	N/A	4		
10.4 Are choir a spec?	nd support spaces appropriately configured per the ed		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition	1	I	I			<u> </u>	The rehearsal hall is to small and is missing the ensen space is in good condition.		
N/A	Does not apply									
10.5 Are dance spec?	and support spaces appropriately configured per the ed		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition				·			A new dance area will be provided after the renovati be undersized per ed specs and no dedicated suppor present.	•	
N/A	Does not apply									
10.6 Are theate spec?	r and support spaces appropriately configured per the ed	1						Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition							The stage has limited wing space, limited storage thr need updating. There is no theater classroom or blac	-	spaces
N/A	Does not apply	1		r	-		1			
10.7 Are visual of ed spec?	arts and support spaces appropriately configured per the		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply							Two art labs are provided, but are undersized.		
10.8	ampus have adequate space for the specialty arts (Ensemble, Guitar, Music studies, Music theory and Piano)?	1						Comments	1.00	1.00
1 5	No Yes									

11 - Athletics and Wellness							26.25	50%
11.1 Does the campus meet ed spec standard for physical education program spaces?			;	3		Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply						Physical education spaces are inconsistent. Some area condition, while others are in poor condition. The weig gymnasium are both undersized. A future dance and v be provided in a conversion of one of the gyms.	ht room and	main
11.2 Does the campus have a dedicated wellness center?	1					Comments	0.50	0.50
l No 5 Yes					_			
1].3 Does the community have access to exterior playfields/courts?					5	Comments	0.50	2.50
1 No 5 Yes								
11.4 Are facilities available to facilitate eSports (High School only)?	1					Comments	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?	1					Comments	0.25	0.25
1 No 5 Yes						New side backboards required.		
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1					Comments	0.25	0.25
1 No 5 Yes		_				supports practice. 6 lane track. No spectator seating.		
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1					Comments	0.25	0.25
l No 5 Yes						Campus only has a practice field (shared with soccer)		
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?					5	Comments	0.25	1.25
1 No 5 Yes								
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1					only 4 tennis courts in adequate shape	0.25	0.25
1 No 5 Yes								
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1					Campus only has a practice field (shared with football)	0.25	0.25
1 No 5 Yes								

11 - Athletics ar	nd Wellness (cont.)	1	2	3	4	5	N/A			
	s (dedicated storage) set up to support UIL sanctioned r cross-country (high school only)?	1						Comments	0.25	0.25
1 5	No Yes									
	s (dedicated storage) set up to support UIL sanctioned r golf (high school only)?	1						Comments	0.25	0.25
1 5	No Yes									
	s (dedicated storage) set up to support UIL sanctioned swimming (high school only)?	1						Comments	0.25	0.25
1 5	No Yes									
11.14 Are facilities (high schoo	s set up to support UIL sanctioned athletics for wrestling I only)?					5		Comments	0.25	1.25
1 5	No Yes									
11.15 Are facilities (high schoo						5		Comments	0.25	1.25
1 5	No Yes							small bleachers for spectator seating.		
11.16 Are facilities (high schoo	s set up to support UIL sanctioned athletics for softball I only)?					5		Comments	0.25	1.25
1 5	No Yes									
	s (dedicated space outside of the gymnasium) available to npetitive spirit activities for cheerleading and drill team?	1						Comments	0.25	0.25
1 5	No Yes		•				•			
11 - Athletics ar	nd Wellness (cont.)	1	2	3	4	5	N/A			
	athletics fields align with FMP Campus Improvements? arking lot lighting, ADA accessible amenities (high School	1						Comments	0.00	0.00
1	Very unsatisfactory - No turf, inaccessible, no site lighting						1	Monitoring answer, but doesn't affect overall score.		
2	Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting									
3	Average - Field in adequate condition, needs some updates or renovations to function well									
4	Satisfactory - Turf field in good condition, good ADA access and site lighting									
5	Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes, excellent site lighting									
N/A	Does not apply.							L		

02/11/2022 °

2 - Food Serv	ices								10.00	50
12.1 Is the Dinir	ng Commons appropriately configured per the ed spec?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply							Multiple seating options are present, but the furnitur mobile. The cafeteria is one large, open space with p clearly defined circulation for two serving lines.		
· · ·	od Services support spaces appropriately configured per		2					Comments	1.00	2.
1 2 3 4 5 N/A	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply							No table and chair storage was observed.		
3 - Media Res	,	1	2	3	4	5	N/A	A	30.00	5
121	ary/Media Center easily accessible for the occupants and the school?			3				Comments	1.00	3.
1 2 3 4 5 N/A	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition Does not apply							The library is near the front door but has limited transignage.	sparency and	no

13 - Meo	dia Resources - Continued	1	2	3	4	5	N/A			
13.2 Ho	ow well does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
	 Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy N/A Does not apply 							One conference room is present. Renovations will cor rooms in the library into a studio. Mobile furniture is r quiet study.		
13.3 Ho	ow well does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
	 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 									
	w well does the Library/Media Center support collaborative work small groups (4-8 students)?			3				Comments	1.00	3.00
	1 Very unsatisfactory - No breakout rooms, no flexible furniture, no support 2 Unsatisfactory - Too small, one area, poor condition 3 Average - Adequate size, multiple areas provided, needing updates or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition 5 Very Satisfactory - Multiple clusters or small rooms adjacent to media condition 6 N/A 0 Does not apply	1								
	ow well does the Library/Media Center support collaborative work larger groups (10-25)?			3				Comments	1.00	3.00
	1 Very unsatisfactory - No gathering areas 2 Unsatisfactory - Too small, one common space, limited seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply	1		1						

13 - Media Resources - Continued	1	2	3	4	5	N/A	<u> </u>		
13.6 How well does the Library/Media Center support technology?			3				Comments	1.00	3.0
 Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition 							Multiple desktop computers are provided for studen A mobile A/V cart and drop-down screen with a mob available for presentations.		
N/A Does not apply									
4 - Technology	1	2	3	4	5	N/A	<u> </u>	20.00	35
14.] How well equipped are the facilities with instructional technology?			3				Comments	1.00	3.0
 instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition N/A Does not apply 							display.		
Is there an adequate number of power and data outlets in learning spaces?		2					Comments	1.00	2.0
 Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) 			1	1	1		Power and data access appears to be inconsistent a two annexes generally have adequate outlets, but th building studios often only have two walls with limite	cross the camp ne main acade	ous. The
5 Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									
· · · · · · · · · · · · · · · · · · ·									

14 - Technolog	ıy (cont.)	1	2	3	4	5	N/A	<u> </u>		
14.3 Are there c	adequate charging locations for devices?	1						Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.							The charging locations appear to be inconsistent acr areas have charging towers and racks but others are outlets. The Principal noted that the charging towers the new Eastside campus, and the LASA does not hav towers.	limited to only are likely mov	wall ing to
N/A	Does not apply		1	1	_	-	1			
ls there add 14.4 gym?	equate AV for presentations spaces – cafeteria, gym, aux	1						Comments	1.00	1.00
1 2 3 4 5 N/A	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition. Does not apply							Gym does not have AV.		
14.5 Is there dig	ital media signage at the reception area?	1						Comments	0.00	0.0
1 2 3 4 5 N/A	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply				·					

	tration Spaces	1	2	3	4	5	N/A		20.00	55
51	a reception area that functions as a security checkpoint for all							Comments		
visitors?				_				commenta	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply					-	-		-	
5.2 Does the	administration area feel welcoming?		2					Comments	1.00	2.0
1	Very unsatisfactory - No welcome space	I				I	I	There is no natural light in the reception area and ve		
2	Unsatisfactory - Too small, poor lighting and							transparency. The seating area is small and needs up	•	
-	transparency, limited informal seating, poor condition							it ansparency. The seating area is small and needs up	Juanny.	
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
_	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
N/A	excellent condition Does not apply									
· · · · · ·	e spaces that require it, does the administration area have		1		1	l –	T		1	
62	te acoustic privacy?				4			Comments	1.00	4.0
1	Very unsatisfactory - No acoustic separations	ļ								
2	Unsatisfactory - Acoustic separations do not perform									
	well									
3	Average - Some acoustic separations function okay, but									
	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply	1	1	1	r	r –	1		1	
5.4 Are conf	erence rooms easily accessed for public / parent use?			3				Comments	1.00	3.0
1	Very unsatisfactory - Not accessible for public/parent	I		t	<u> </u>	I		The conference room has no transparency into the co		
	use							within the administration suite.		•
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
•	good size and condition									
5	5									
5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									