

## **Educational Suitability Summary Report**

LBJ Early College High School

Date: 12/9/2020 Score 59% Average

LBJ Early College High School and LASA High School serve an enrollment of approximately 2,100 students in east Austin on a shared campus. LASA HS will be moving at the end of the 2020-21 academic year. LBJ ECHS will remain and undergo renovations to grow its Medical Sciences pathway. A large courtyard at the front of the building creates a welcoming and distinct entry. The campus has recently completed a long-range master plan that includes renovations of the existing academic wings, demolition of fine arts, and new construction of athletic and other support spaces.

In general, the campus does not meet most of the new Educational Specifications. The quality of the artificial lighting and natural daylight in studio spaces is poor. Many of the learning spaces in the building (studios, media center, gyms, etc.) do not have access to natural light or exterior views. Windows are limited in size, and the amount of natural light is minimal. Acoustics are adequate with only slight sounds traveling between the corridor and adjacent studio spaces. Campus circulation does not allow for clear wayfinding, making navigation of the space difficult.

The campus is planned to undergo partial renovations to the academic wing starting in April 2021. The renovations will assist in bringing natural daylight to the center of building, while creating a more vibrant media center that meets the latest Educational Specifications. The renovations will also include medical science lab spaces, a community meeting room, and security features. In addition, the courtyard is being designed to be a space for outdoor learning.

Existing outdoor sports fields, tennis courts and a full running track are in good condition and well-secured by a perimeter fence. The indoor athletic spaces are aged and are planned to be moved to a new facility per the master plan.

#### **Interview Overview**

The interview for LBJ Early College High School was conducted with Principal Jon Bailey and various staff members. The front entry courtyard is important to the campus identity; it contains a large marble Texas monument, a student memorial, and seating that is used for outdoor learning. They also noted that the new medical sciences area functions well, but many of the other learning spaces are outdated and do not meet modern standards.

Many programs on campus are not housed in appropriate spaces. The Fire Academy program does not have a dedicated space or adequate storage for equipment. The fine arts studios need to be updated, and the athletics wing is outdated and not appropriate for today's schools. CTE courses take place in a basement with no daylight or views to the outside. The school would like to add more CTE programs, including cosmetology, architecture and construction, manufacturing and culinary arts.

## **Educational Suitability Summary Report**

LBJ Early College High School

The current campus does little to foster connectivity and creativity. Collaboration is a challenge due to lack of available meeting spaces. The school needs more flexible spaces that can accommodate different group sizes and have enough transparency to feel open and inviting. Additional lecture spaces of various sizes would be helpful for hosting guest speakers and events. Updated technology in the studios and social spaces is essential to keep up with changing teaching methods.

Outdoor learning takes place at several loose picnic tables in the front courtyard and a small area near the bus drop-off. The school needs dedicated outdoor learning areas that are covered to protect students from weather. These spaces should also have access to technology, including power and data ports, so students can charge laptops and stay connected.



#### **Assessment Findings**

The Educational Suitability Assessment of LBJ and LASA high schools earned a 59% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

#### **Unsatisfactory Categories (36-50%):**

## Furniture, Fixtures, Equipment

Score is unsatisfactory.

Furniture throughout the school varies. Some science labs have received new furniture, but in general, furniture does not meet the intent of an easily reconfigurable space as indicated in the Educational Specifications. There are currently no collaboration spaces that have furniture for individual, small or large group collaboration.

#### **Environmental Quality**

Score is unsatisfactory.

Evidence of pests is seen both inside and out. The basement level has an odor of water penetration. Even if spaces have access to natural daylight, the amount of light is limited due to the size of the windows.

#### **Controllability of Systems**

Score is unsatisfactory.

Controllability of systems varies from room to room. Most studios have thermostats, but users indicate that some thermostats are not working. Light switching varies from room to room, ranging from one switch for all lights and alternating row. No lights are dimmable. Some teaching spaces have light switches that are hard to find.

#### **Technology**

Score is unsatisfactory.

## **Educational Suitability Summary Report**

LBJ Early College High School

Many spaces have an inadequate number of power and data outlets. The renovation project will address some of this, but future work will be needed to address all technological needs.

#### **Academics & Learning**

Score is unsatisfactory.

Studio square footage does not meet the new Educational Specifications. The campus is subdivided by department and not per learning neighborhoods. Science labs are not configured per the Ed Spec and some science labs are smaller than standard studio spaces. No maker spaces or collaboration spaces were observed during the assessment.

#### **Athletics and Wellness**

Score is unsatisfactory.

The existing athletics spaces need renovations or replacement. Locker rooms are aged, and restrooms in the space do not provide privacy for student athletes. The weight room is dated and not appropriately sized for the enrollment. Equipment has met life expectancy and will need to be replaced.

#### Average Categories (51-65%):

#### **Exterior**

Score is average.

Traffic patterns are separated, but bus loading occurs on the street and could be improved for student safety. Finding the front door can be a challenge if you have never been to the campus. The building lacks clear signage and wayfinding as well as Shade is very limited on campus. There is limited visitor parking, and most ADA spaces are taken by staff before visitors arrive. The main entrance to the school is directly off a central courtyard that features stone seating, a variety of shade trees, multiple tables and a few monumental signs.

#### Security

Score is average.

#### **Visual and Performing Arts**

Score is average.

The band, orchestra and choir halls are in dated, small spaces that do not fully meet the current Educational Specifications. The Performing Arts Center is also dated and needs updated facilities for use by students.

## **Food Services**

Score is average.

The cafeteria has some natural daylight, but the space is dated. There are multiple types of seating but could use updates.

## **Educational Suitability Summary Report**

LBJ Early College High School

#### Satisfactory Categories (66-80%):

### **General Building**

Score is satisfactory.

The general appearance of the school is dated and features a large courtyard at the public front. The arrangement of school spaces allows for nighttime use for public functions, but the public spaces are spread across opposite ends of the school. (The gym is opposite the library, which is on the second floor.) The interior circulation on campus is adequate, but wayfinding tends to be a challenge. The current building plan does not allow for ease of after-hours use, as it is difficult to lock down portions of the school. The renovations will allow for meeting spaces and allow for more natural daylight into the core of the school.

## **Outdoor Learning and Activity**

Score is satisfactory.

Although the campus has a large courtyard space, the space has not been fully developed to meet the intent of the Educational Specifications. There are outdoor tables, but they need to be configured to better suit teaching and learning. There are no active outdoor gardens or cisterns.

## **CTE and Career Connected Learning**

Score is satisfactory.

A large number of the CTE spaces are in the basement level, which does not allow natural daylight to enter these spaces. These spaces need renovations. The campus has the needed equipment and space to meet the needs of the users.

#### **Administration Spaces**

Score is satisfactory.

Partial renovations of the administration suite will occur in 2021.

## Very Satisfactory Categories (81-100%):

#### **Media Resources**

Score is very satisfactory.

The media resources space will be renovated to meet the new Educational Specifications.



Visual and Performing Arts: Theater and drama expansion is the newest addition to the school



Granite monument sign at center of entry courtyard. Lighting would increase its impact



CTE: Well-equipped manufacturing shop with a wide variety of tools and equipment.



Many studios and learning spaces have no windows or access to daylight.




Gym is original to school. Insulation falls from exposed ceiling and paint is peeling from walls.



Locker rooms are in poor condition and lack privacy.



CTE: Health science lab is new and very well-equipped.



CTE: Emergency services program equipment storage and staging.



Windows in studios are too small and let in minimal daylight.



Large display cases show the success and pride the school takes in athletics.



# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
LBJ Early College High School	Kevin Kinsey & Koleman Uresti	12/8/2020

11			- 1	2	3	4	5	N/A	A	8.75	57%
pec	es the site destrian t	re permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Buses load on street. Currently LASA has own entranc	e. LBJ has sep	arate
		at the same location							entrance. Students and staff park in same parking lot		
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									ļ
		but drop off does not have a canopy or a holding place like a commons or cafeteria									ļ
	5	Very satisfactory - Buses, cars, and pedestrians are									ļ
	· ·	separate and drop off area has a canopy and									ļ
		destination									ļ
	N/A	Does not apply									
1.2 Is th	he buildir	ng easily identified with appropriate signage and		2					Comments		
con	mmunity	wayfinding?							Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage /									ļ
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									ļ
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and									ļ
	N/A	easy to use Does not apply									

O2/11/2022 <sup>2</sup>

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A	4		
1.3	Is the dump	oster accessible for trash / compost disposal?			3				Comments	0.50	1.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							The dumpsters are present, but are not accessible by	ramp.	
	N/A	Does not apply		_	•		-			10.00	2001
2-0		arning and Activity	1	2	3	4	5	N/A	1	10.00	80%
2.1	the ed spec	or studios and support spaces appropriately configured per c?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios			<u> </u>	<u> </u>			The courtyard has some tables for outdoor learning.	The Keep Austi	n
	2	Unsatisfactory - Too small, poor condition, disconnected							Beautiful Grant will assist in providing new outdoor s		
		from learning spaces, no flexibility, no shade provided									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
	4	shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade									
	5	coverage over studio area  Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full									
	N/A	shade coverage over studio area  Does not apply									
2.2	Are active p	olaygrounds (elementary only) and support spaces per the ed spec?						Na	Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated active playground									
	2	Unsatisfactory - Too small, poor condition, no shade									
	3	provided  Average - Adequate size, adequate condition, needs									
	3	some renovations or updates to function well, 50% or less									
		shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50%									
	5	shade coverage over play structure  Very satisfactory - Generous size, excellent condition, full									
	3	shade coverage over play structure									
	N/A	Does not apply							L		

2 - 0	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	4	
2.3		is and support spaces appropriately configured per the eduation on infrastructure not condition of plants)	1						Comments 0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learning and Activity.	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access  Satisfactory - Good size, good condition, connected to								
		learning spaces, good flexibility, water source is accessible with 100 ft hose								
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
	N/A	Does not apply					•		<u>,                                      </u>	
2.4	Are the rained spec?	n gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.00
	1 2 3	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Monitoring answer, does not affect score for Outdoor Learning and Activity.	
	<b>4</b> 5	Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
	N/A	Does not apply						1		
2.5	Does the so	hool have animal husbandry? (optional)	1				<u> </u>		Comments 0.00	0.00
	1 5	No Yes								
2.6		tes chool have nature loop trails? (optional)	1				1		Comments 0.00	0.00
2.0	1	No							Comments 0.00	0.00
	5	Yes								
2.7	Does the so	hool have a learning pond? (optional)	1						Comments 0.00	0.00
	1	No								
	5	Yes								
2.8		hool have a grass play field and walking trail?					5		Comments 1.00	5.00
	1	No								
	5	Yes								

- General Bu	ilding	1	2	3	4	5	N/A		11.25	80%
3.1						5		Comments	0.50	2.50
1 2 3 4 5 N/A Are commu functions w	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide  Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide  Average - Primary circulation is 7'-0" to 8'-0" wide  Satisfactory - Primary circulation is 8'-0"-10'-0" wide  Very satisfactory - Primary circulation is 10'-0"+ wide  Does not apply  Inity use areas arranged so that the school can allow night without full school access?  Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours			3				Hallways are 10' wide.  Comments  New lecture hall, library and existing cafeteria are acmain entry. Library is unsecured from central space.	0.75	2.25
3 4 5	Gym and Library) can be accessed from parking and secured after hours  Average - Only two of the public spaces can be accessed from parking and secured after hours  Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually  Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
	,		1	ı	1		1	Ι		
<i>२ '</i> २	,					5		Comments	0.75	3.75
1 2 3 4 5	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function							•		
				l						
	nd community?		2					Comments	0.25	0.50
1 2 3 4 5	Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very Satisfactory - General appearance shows pride in campus and student works and is welcoming to the community									
	3.1 Are interior accommoded  1 2 3 4 5 N/A 3.2 Are communifunctions with functions with function	accommodate student movement?  1	3.1 Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	3.1 Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	Are interior circulation routes wide enough to safely and effectively accommodate student movement?  1	3.1 All interior circulation routes wide enough to safety and effectively accommodate student movement??  1	3. All interior circulation routes wide enough to safely and effectively cocommodified student movement?  1

	4 - Security		1	2	3 4	5	N/A		16.25	
	4.1 Does the fa	cility have key card access at all major entries?						Comments	0.25	
,	1	Very unsatisfactory - No entries			1	ı			I.	
	2	Unsatisfactory - 1/4 of major entries								
	3	Average - 1/2 of major entries								
	4	Satisfactory - 3/4 of major entries								
	5	Very satisfactory - All of major entries								
	N/A	Does not apply						L		
	4.2 How adequ	uate is site lighting and security for the campus overall?						Comments	1.00	
Į.	1	Very unsatisfactory - No exterior lighting, no secure								
		perimeter								
	2	Unsatisfactory - Lighting is limited to front entry only,								
		parking lot lighting poor, security is minimal								
	3	Average - Lighting at all night-use entries and parking								
	· ·	lot, but poor condition. Security is moderate								
	4	Satisfactory - Lighting at all night-use entries and								
	7	parking lots, good condition, signage less visible,								
		perimeter is well secured but needs updates								
	5									
		Very satisfactory - Signage, parking lots, and entries are								
		well lit, visible and easy to use, perimeter is very secure								
	N/A	Does not apply						,		
	71.3	office located at the school entry and configured with a						Comments		
	secure vest	ibule to the main corridor?						33	1.00	
	1	Very unsatisfactory - No secure vestibule, office located								
		far from main entry, allows visitors access to school								
	2	unsupervised Unsatisfactory - No secure vestibule, office located								
	2	somewhat far from main entry, minimal supervision of								
		visitors								
	3	Average - Office close to entry, views of front door, but								
		no secure vestibule								
	4	Satisfactory - Office is well-located with a secure								
		vestibule, but needs updates								
	5	Very satisfactory - Office well-located with secure								
		vestibule and all appropriate security features								
	N/A	Does not apply								
	ls there end	ough interior transparency for faculty to passively supervise	1					Comments		
	learners an	d their activities who are not in studios?	-					Comments	1.00	1.00
	1	Very unsatisfactory - No transparency of walls								
	2	Unsatisfactory - Limited transparency in certain locations								
	3	Average - Good transparency in certain locations but								
		inadequate or missing in other locations of school								
	4	Satisfactory - Adequate transparency throughout the								
		school								
	5	Very satisfactory - Excellent transparency throughout the								
		school								
	N/A	Does not apply								

5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	44%
5.1 How are ac	coustics in studios in general?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
5.2 Is the studio	o artificial lighting adequate quality?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply							Quality of light is dependent on the location of the rohas been recently updated.	om and if the r	room
5.3 Is there acc	ess to natural light in studios?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							Less than half of learning spaces have access to dayl building configuration. The interior studios and labs a windows.	-	-
N/A	Does not apply tess to outside views from learning spaces?		2					Comments		
1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views							Studios that have exterior windows are limited by sm in center core have no windows.	1.00 all openings. S	2.00 tudios
N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	ouilding have odor or pest problems?		2					Comments	1.00	2.00
1	Very unsatisfactory - Evidence of both pests and odors							Previous signs of pest problems and water infiltration	n in fine arts an	id
2	Unsatisfactory - Evidence of pests or odors							athletics. Exterior indicates pests have burrowed und	ler the building	as well
3	Average - Limited evidence of pests, no odors							· ·	-	
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	4	12.50	44%
6.1 Does the s	tudio thermostat allow for individual control?	1						Comments	0.50	0.50
1	No							Due to reconfiguration, many studios do not have inc	dividual contro	ls.
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?			3				Comments	1.00	3.00
1	Very unsatisfactory - No, windows are covered with							Mini blinds are used throughout the school.		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply							1	T	
6.3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
1	Very unsatisfactory - Single switch only per room			-				Depending on the studio, some rooms have multiple	switches to adj	just
2	Unsatisfactory - Alternating rows switch off							lighting; others have just one switch.	·	
3	Average - Alternating lamps in single fixtures switch off							,		
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, F	ixtures & Equipment	1	2	3	4	5	N/A		18.75	47%
7.1 What is the	e current condition of the furniture?	1						Comments	0.75	0.75
1	Very unsatisfactory - Damaged or broken, non-							Furniture throughout the campus is old.		
	functioning									
2	Unsatisfactory - Torn/ bent/ wrong size									
3	Average - Scratched/dented/marked									
4	Satisfactory - Not new, but sturdy and clean									
5	Very satisfactory - New									
N/A	Does not apply									
Are a varie	ty of furniture types being accommodated throughout the									
1 / ')	arning commons, dining commons, other multi-use spaces?			3				Comments		
3011001 100	arring commons, airing commons, other maid add spaces.								1.00	3.00
1	Very Unsatisfactory - Same furniture used in all spaces		•				•			
2	Unsatisfactory - Furniture variety in one multi-use space									
3	Average - Furniture variety in more than one multi-use									
Ŭ	space									
4	Satisfactory - All multi-use spaces have greater than one									
	type of furniture									
5	Very satisfactory - All multi-use spaces have greater than									
	two types of furniture									
N/A	Does not apply									
/ 3	oes furniture accommodate rapid reconfiguration of a		2					Comments		
space?									1.00	2.00
1	Very Unsatisfactory - Furniture is fixed or very heavy							Depending on the studio, some furniture has the abili	ity to be reconf	igured
2	Unsatisfactory - Furniture does not allow desks to be							easily. Other studios do not have that option.		
	configured as individuals, small groups, or large groups									
3	Average - Mix of furniture that can reconfigure but is									
	cumbersome to move									
4	Satisfactory - Furniture is flexible for multiple									
5	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
N/A	configurations of space, easy to move and stack									
IN/A	Does not apply		ı		I	1		T		
7.4 Is the furnit	ture ergonomic and size appropriate for grade level?			3				Comments	1.00	3.00
1	Very unsatisfactory - Desk with attached chair									
	combinations too small for grade level									
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4	Very satisfactory - Tables with loose chairs									
5	Very satisfactory - Tables with loose chairs  Very satisfactory - Tables with loose chairs that allow									
3	students to be active									
N/A	Does not apply									
	· · · · · · · · · · · · · · · · ·									

Perkins&Will 02/11/2022 <sup>9</sup>

Waste	1	2	3	4	5	N/A		5.00	40
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?		2					Comments	0.50	1.
<ol> <li>Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.</li> <li>Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.</li> <li>Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.</li> <li>Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.</li> <li>Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.</li> </ol>							A score for this category is being recorded, but this categorical calculated in the overall ESA average.	ory is not	
N/A Does not apply  Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?		2					Comments	0.50	1
1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.				ı				3.55	



# **Austin ISD Educational Suitability Assessment Criteria**

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
LBJ Early College High School	Kevin Kinsey & Koleman Uresti	12/8/2020

8 - A	cademics 8	& Learning	1	2	3	4	5	N/	A	65.00	42%
8.1	Are studios	appropriately configured per the ed spec?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected							Typical studio is 25' x 30' (750 s.f.). Studios lack transp daylight.	arency and no	atural
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
8.2	Do studios h ed spec?	nave appropriate support spaces such as storage per the	1						Comments	1.00	1.00
	1	Very unsatisfactory - None provided							Storage is often disconnected from studios. Limited fu	rniture for sto	rage in
	2	Unsatisfactory - Too small, disconnected, poor condition							typical studio.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	<b>4</b> 5	Satisfactory - Good size, connected, good condition  Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do typical le	earning neighborhoods have small and medium (high	1						Comments		
8.3	school only)	group rooms and open collaboration space?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open							There are no learning neighborhoods that meet Ed S	pec. The buildi	ng is
		collaboration spaces are provided							subdivided by LASA/LBJ and inside each school it is g	rouped by	
	2	Unsatisfactory - Too small or too few, poor condition, no							department. Existing learning neighborhoods lack tro	ansparency and	d
		flexibility, lacks visual connection to learning							collaboration spaces.		
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
	_	neighborhood, acoustic privacy									
	N/A	Does not apply									
8.4		Labs and support spaces appropriately configured per		2					Comments		
	the ed spec									1.00	2.00
	1	Very unsatisfactory - No dedicated science room							Science labs do not meet Ed Spec required sizes. Mul	tiple labs on bo	oth
	2	Unsatisfactory - Too small, poor condition, no connected							floors were not designed as science labs and were co	nverted later. S	Some
		support space							furniture in second floor is new, but is dated and not	easily reconfigi	urable.
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	_	support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N/A	connected support spaces Does not apply									
		Spaces and support spaces appropriately configured per		l l							
8.5		? (cross reference with CTE below)	1						Comments	1.00	1.00
	ine ed spec			l					The second of the sheet or other second	1.00	1.00
	0	Very unsatisfactory - No dedicated maker spaces							There are no dedicated maker spaces.		
	2	Unsatisfactory - Too small, poor condition, disconnected									
	2	from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	·									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	5	connected to learning spaces									
		connected to learning spaces									

8 - Academics	s & Learning (cont.)	1	2	3	4	5	N/A			
8.6 Is there a	Professional Learning Center in the learning neighborhood?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected							Renovations are limited to media center and medical sprovided in LASA. LBJ has one for entire campus.  Well-connected to the school. The area is highly visible transparency.		not
8 /	adequate places to display the evidence and artifacts of both 2D and 3D)?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition							The campus creatively displays student work and scho cabinets on the second floor displaying trophies and scopportunities could be improved significantly.	-	
N/A	Does not apply	1	1	1	1	ı	1			
	building / learning neighborhood provide adequate ities for students/teachers to collaborate in varying group	1						Comments	1.00	1.00
1 2 3 4 5 N/A	Very unsatisfactory - No space to support collaboration in various sizes.  Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes  Average - Adequate space for collaboration, needs updates or renovations to function well.  Satisfactory - Good size, good condition, multiple options to support a variety of group sizes  Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes  Does not apply				,			There are no collaboration spaces with furniture.		
	building provide opportunities for informal interaction?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
N/A	Does not apply							·		

8 - Academics	& Learning (cont.)	1	2	3	4	5	N/	A		
8.10 Does the bound work indep	uilding provide adequate opportunities for students to pendently?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply							Due to the existing corridors and building layout, the that would allow for independent workspace, but the have furniture.		
Special Edi										
-	l Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - Too small, no flexibility, disconnected  Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected  Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.  Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces  Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							The life skills area was renovated 2-3 years ago. Laur and the kitchen was renovated. There are restrooms, does not meet Ed Spec. It is adequate at this time, but teaching spaces to meet new requirements.	but the space	still
N/A Are Special	Does not apply  I Education support spaces, such as storage, space for									
	yer, appropriately configured per the ed spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided									
2	Unsatisfactory - Too small, disconnected, poor condition									
3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

8 - A	cademics a	& Learning (cont.)	1	2	3	4	5	N/A			
8.13		ble restrooms and changing rooms readily available to the cation spaces?					5		Comments	1.00	5.00
	1	No								1.00	0.00
	5	Yes									
	STEAM Cen										
8.14	Does the ca	impus have space to support a "STEAM" center?	1						Comments	0.00	0.00
	1	Very unsatisfactory - No available space for STEAM							Monitoring answer, but does not count toward overc	ıll score.	
		center and inadequate studio / collaborative space									
	2	Unsatisfactory - Collaborative areas / studios for									
	2	CTE/CCL are completely separate but adequate size									
	3	Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately									
	4	Satisfactory - Collaborative areas / studios for CTE/CCL									
	-	function and have space availability to create STEAM									
		center									
	5	Very Satisfactory - Functioning STEAM center offers									
		studios, labs, common collaborative areas to support									
		multimedia distance and hands-on project based									
		learning									
	N/A	Does not apply									
9 - C	TE and Ca	reer Connected Learning								13.75	71%
9.1		s your campus to a CTE cluster pathway that is aligned TE programs (Middle School only)?						NA	Comments	0.00	0.00
	1	Very unsatisfactory - No correlation to CTE cluster		_						0.00	
		pathway, no CTE programs.									
	2	Unsatisfactory - School supports less than half of the CTE									
		programs that are listed in the cluster pathway.									
	3	Average - School support half of CTE programs listed in									
		the cluster pathway, but missing some.									
	4	Satisfactory - School support a majority of CTE programs									
	_	listed in the CTE cluster pathway.									
	5	Very Satisfactory - School is aligned with CTE cluster									
	NI/A	pathway.									
	N/A	Does not apply									
9.2	•	facilities align with the CTE Ed Spec Requirements for the	1	j							
7.2	current pat	hways offered?: Architecture and Construction	'	j						0.25	0.25
	1	No I								0.20	0.20
	5	Yes									
	N/A	Does not apply						Į.			
	Auto Audio	and Middle Technology and Communications		j				b.i.a			
9.3	Arts, Audio	and Video Technology and Communications						NA		0.00	0.00
9.4	Business, M	anagement and Administration					5			0.25	1.25
9.5	Education o	ınd Training					5			0.25	1.25
0.6	Health Scie	nce					5			0.20	0
9.0	i lealth scie						J			0.25	1.25

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A	N	
9.7 Hospitality and Tourism	1						0.25	0.25
9.8 Human Services (high school only)					5		0.25	1.25
9.9 Information Technology					5		0.25	1.25
9.10 Agriculture, Food and Natural Resources					5		0.25	1.25
9.11 Science, Technology, Engineering, and Mathematics					5		0.25	1.25
9.12 Transportation, Distribution and Logistics						NA	0.00	0.00
9.13 Finance (high school only)						NA	0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						NA	0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)	1						0.25	0.25
9.16 Manufacturing (high school only)	1						0.25	0.25
9.17 Marketing, Sales and Services (high school only)						NA	0.00	0.00
10 - Visual and Performing Arts							35.00	51%
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments 0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.	
Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?			3				Comments 1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition							The band hall has been converted from an old theater. The space is adequate and has storage, rehearsal halls and work rooms. The space dated and needs renovations and some acoustical remediation.	
N/A Does not apply  Are orchestra and support spaces appropriately configured per the ed spec?			3				Comments 1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply							Orchestra is currently in the old band hall.	

	10 - Visual and	Performing Arts (cont.)	1	2	3	4	5	N/A	A		
	10.4 Are choir ar	nd support spaces appropriately configured per the ed			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Choir hall has built-in risers, which makes it difficult to	be rearrange	d. The
	2	Unsatisfactory - Too small, poor condition							space shares practice rooms with band and has ense	mble rooms.	
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply	1	1		1	1	1	1		
	10.5	and support spaces appropriately configured per the ed		2					Comments	100	
L	spec?		<u> </u>						The setting of the second of the set in the second of the	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							The ceilings are low, and a column is in the middle of		
	2	Unsatisfactory - Too small, poor condition							space should be open and unobstructed. The space h	ias storage an	d office
	3	Neutral - Adequate size, adequate condition, needs							space.		
	4	updates or renovations to function well.									
	5	Satisfactory - Good size, good condition  Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
f	Are theater	and support spaces appropriately configured per the ed				T					
	10.6 spec?	3				4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces									
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
_	N/A	Does not apply	1	1		1	1	1	1		
	10.7	rts and support spaces appropriately configured per the		2					Comments	100	
-	ed spec?								Visual arts studios are in spaces with no natural dayli	1.00	2.00
		Very unsatisfactory - Too small, missing program spaces							converted to art rooms.	gnt that have	been
	2	Unsatisfactory - Too small, poor condition							Converted to divisionis.		
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	D + I	,									
	1/1/8	Impus have adequate space for the specialty arts Ensemble, Guitar, Music studies, Music theory and Piano)?	1						Comments		
	programs (i	Ensemble, Saltar, Music studies, Music theory and Flanor:								1.00	1.00
	1	No							Required to share space with Orchestra, Jazz or Band	d.	
	5	Yes									

11 - Athletics and Wellness					26.25	50%
11.1 Does the campus meet ed spec standard for physical education program spaces?		3		Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply				Athletics spaces are older and most restroom spaces meet ADA. Showers are not easily accessible by all sp		s do not
11.2 Does the campus have a dedicated wellness center?	1			Comments	0.50	0.50
1 No 5 Yes						
11.3 Does the community have access to exterior playfields/courts?			5	Comments	0.50	2.50
1 No 5 Yes						
11.4 Are facilities available to facilitate eSports (High School only)?	1			Comments	0.00	0.00
1 No 5 Yes				Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			5	Comments	0.25	1.25
1 No 5 Yes						
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1			Comments	0.25	0.25
1 No 5 Yes				Supports practice but not spectator events because o	f lack of seatin	ng.
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1			Comments	0.25	0.25
1 No 5 Yes				Supports practice but not spectator events because o	f lack of seatin	ng.
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			5	Comments	0.25	1.25
1 No 5 Yes						
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?			5	Comments	0.25	1.25
1 No 5 Yes				8 courts		
11,10 Are facilities set up to support UIL sanctioned athletics for soccer?	1			Comments	0.25	0.25
1 No 5 Yes				Supports practice but not spectator events because o	f lack of seatin	ng.

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)	1	2	3	4	5	N/A		
Are facilities (dedicated storage) set up to support UIL sanctioned	1						Comments	
athletics for cross-country (high school only)?	-						0.25	0.2
1 No								
5 Yes							<u> </u>	
Are facilities (dedicated storage) set up to support UIL sanctioned	1						Comments	
athletics for golf (high school only)?	'						0.25	0.2
1 No								
5 Yes							1	
Are facilities (dedicated storage) set up to support UIL sanctioned	1						Comments	
athletics for swimming (high school only)?							0.25	0.:
1 No								
5 Yes				-				
Are facilities set up to support UIL sanctioned athletics for wrestling					5		Comments	
(high school only)?							0.25	1.2
1 No							They have wrestling mats that are pulled into the gym for events.	
5 Yes								
Are facilities set up to support UIL sanctioned athletics for baseball	1						Comments	
(high school only)?							0.25	0.
1 No							As per discussion with on campus staff, events held off campus.	
5 Yes								
Are facilities set up to support UIL sanctioned athletics for softball	1						Comments	_
(high school only)?							0.25	0.
1 No 5 Yes							There is a baseball field and softball field located on site.	
5 Yes	1							
1.17 Are facilities (dedicated space outside of the gymnasium) available to	1						Comments	
support competitive spirit activities for cheerleading and drill team?	'						0.25	0.
1 No							0.23	<u> </u>
5 Yes								
- Athletics and Wellness (cont.)	1	2	3	4	5	N/A		
How do the athletics fields align with FMP Campus Improvements?	'		0		J	14/ /		
1.18 Turf Field, Parking lot lighting, ADA accessible amenities (high School	1						Comments	
only)	'						0.00	0.0
1							Monitoring answer, but doesn't affect overall score.	
Very unsatisfactory - No turf, inaccessible, no site lighting							Monitoring driswer, but doesn't driect overdir score.	
2 Unsatisfactory - No turf/field in poor condition, some								
accessibility concerns, poor site lighting								
3 Average - Field in adequate condition, needs some								
updates or renovations to function well								
4 Satisfactory - Turf field in good condition, good ADA								
access and site lighting								
5 Very Satisfactory - Turf field with excellent maintenance,								
excellent ADA access for spectators and athletes,								
excellent site lighting								
N/A Does not apply.								

Perkins&Will 02/11/2022 10

12 -	Food Servi	ces								10.00	60%
12.	ls the Dinin	g Commons appropriately configured per the ed spec?			3	3			Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply									
	Are the Foo	od Services support spaces appropriately configured per								I	
12.:	the ed spec				3	3			Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
	-	Does not apply	_	_	_		_				
13 -	Media Res		1	2	3	3 4	5	N/A		30.00	87%
13.	visitors to t						5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition							Library and media center are on the second floor of Highly visible and accessible. Refer to construction de renovated spaces.		
	N/A	Does not apply									

13 - Media Res	ources - Continued	1	2	3	4	5	N/A	A		
13.2 How well d	loes the Library/Media Center support quiet study?			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy							Two small conference rooms are in the library area.		
N/A 13.3 How well d	Does not apply loes the Library/Media Center support social interaction?					5		Comments	1.00	5.00
1	Very unsatisfactory - No space							The library layout and openness to main space suppo		
2 3 4	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well.  Satisfactory - Good size, good condition, layout and furnishings support informal interactions							and chance encounters.	nts social inter	action
5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
N/A	Does not apply	1	ı	I	1	ı	1			
12 /	loes the Library/Media Center support collaborative work pups (4-8 students)?				4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply							Two small conference rooms are in the library area.		
How well d	loes the Library/Media Center support collaborative work									
13.5 in larger gr	roups (10-25)?				4			Comments	1.00	4.00
1 2 3 4	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition							Two large conference/presentation rooms are availal	ble in the libra	ry area.
5 N/A	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply									

	13 - Media Re	sources - Continued	1	2	3	4	5	N/A	A		
	13.6 How well o	does the Library/Media Center support technology?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No vis comm tools							New library will have projector, marker boards, and access	ss to powe	r/data.
	2	Unsatisfactory - Outdated, poorly functioning, or							No smart boards.		
	0	insufficient Average - Mix of old and new									
	3	whiteboards/projectors/etc.									
	4	Satisfactory - projectors, marker boards, smart boards in									
	·	most spaces - good condition									
	5	Very Satisfactory - projectors, marker boards, smart									
		boards in most spaces - new condition									
	N/A	Does not apply									
	14 - Technolog	эу	1	2	3	4	5	N/A	4	20.00	45%
	14.1 How well	equipped are the facilities with instructional technology?				4			Comments	1.00	4.00
L	1	Very unsatisfactory - Limited to no technology present in	<u> </u>						It appears that all studios have instructional technology.	1.00	4.00
	'	instructional spaces							it appears that all studios have instructional technology.		
	2	Unsatisfactory - One type of technology present									
	3	Average - Multiple types of technology, smart boards.									
		Poor condition. Limited to only certain areas of school.									
	4	Satisfactory - Multiple types of technology, smart									
		boards. Good condition.									
	5	Very Satisfactory - Multiple types of technology, smart									
		boards. Excellent condition									
	N/A	Does not apply	ı	ı		1	1	1			
	14.2	adequate number of power and data outlets in learning		2					Comments	1.00	
	spaces?	Very unsatisfactory - Outlet configuration does not							B	1.00	2.00
	1	support digital devices throughout school (1 per wall)							Power and data are limited at this time. Phase 2 of the ma		
	2	Unsatisfactory - Outlet configuration support digital							indicates additional technology and power to be added a	auring	
	2	devices only in certain areas of school (2 per wall)							renovations.		
	3	Average - Outlet configuration support digital devices									
		but limited capacity throughout school (3 per wall)									
	4	Satisfactory - Outlet configuration support digital									
		devices with adequate coverage and capacity in limited									
		locations (>3 per wall)									
	5	Very Satisfactory - Excellent outlet configuration to									
		support digital devices throughout school (>3 per wall)									
	N/A	Does not apply									

Perkins&Will 02/11/2022 13

y (cont.)	1	2	3	4	5	N/	/A
adequate charging locations for devices?		2					Comments 1.00 <b>2.</b>
Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school				1		l	Power is limited in studios.
• •							
equate AV for presentations spaces – cafeteria, gym, aux	1						Comments 1.00 <b>1.</b>
Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.							The cafeteria, gym and media center currently do not have presentation spaces built in. The new renovated Media Center will have dedicated presentation space.
Does not apply					1		
gital media signage at the reception area?				4			Comments 0.00 <b>0.</b>
Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good				1	1		New flat panel TVs in reception.
1	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition OR undersized / adequate condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition OR undersized / adequate condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition.  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition.  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  4  Very unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces – cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  4  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition

15 - Administration Spaces		1	2	3	4	5	N/A	<b>\</b>	20.00	80%
Is there a reception area that functions as a security che	ckpoint for all							Comments		
visitors?								Comments	1.00	
<ol> <li>Very unsatisfactory - No security checkpoir</li> </ol>	nt									
<ol> <li>Unsatisfactory - Checkpoint is too small, po</li> </ol>	oor condition									
3 Average - Needs updates or renovations to	function well									
4 Satisfactory - Good size, good condition										
5 Very Satisfactory - Generous size, excellent	condition									
N/A Does not apply										
15.2 Does the administration area feel welcoming?					4			Comments	1.00	4.00
1 Very unsatisfactory - No welcome space		ļ					ļ	Renovations will provide updates to this space.		
2 Unsatisfactory - Too small, poor lighting ar	nd									
transparency, limited informal seating, poo										
3 Average - Adequate size and layout, needs	s updates or									
renovations to feel welcoming										
4 Satisfactory - Good size and layout, good I	ighting and									
transparency, informal seating provided										
5 Very Satisfactory - Generous size and layou										
light and transparency, informal seating pr	rovided,									
excellent condition										
N/A Does not apply		ı				I	ı	T		
For those spaces that require it, does the administration	area have			3				Comments		
adequate acoustic privacy?		ļ					ļ		1.00	3.00
1 Very unsatisfactory - No acoustic separation										
Unsatisfactory - Acoustic separations do no     well	ot perform									
3 Average - Some acoustic separations funct	tion okay but									
portions need updates or renovations	lion okay, but									
4 Satisfactory - Good acoustic separations										
5 Very Satisfactory - Excellent acoustic separations										
N/A Does not apply										
11.7	_									
15.4 Are conference rooms easily accessed for public / paren	it use?				4			Comments	1.00	4.00
Very unsatisfactory - Not accessible for pul	olic/parent							Renovations will provide revisions for conference room	ns.	
use								'		
<ol> <li>Unsatisfactory - Limited access, no transpa</li> </ol>	2 Unsatisfactory - Limited access, no transparency, poor					Only one conference room in administration, with limi	ited access bel	hind		
condition, difficult to find					secure line of admin desk. There are other conference					
<ol> <li>Average - Adequate accessibility, needs up</li> </ol>	odates or							throughout school.	2 <b>2  </b>	
renovations to function well										
4 Satisfactory - Good accessibility, good tran	nsparency,									
good size and condition										
5 Very Satisfactory - Excellent accessibility, e										
transparency, generous size, excellent cond N/A Does not apply	aition									
N/A Does not apply										