



Lamar Middle School

Date: 01/12/2021

Score 52% Average

Lamar Middle School, serving an enrollment of approximately 1,230 students, is in north central Austin. It was built in the 1950s with stand-alone additions for fine arts constructed in 2000. The school consists of approximately 134,000 square feet with approximately 12,000 of that square footage in portables. While this assessment does not cover the portables, it is assumed spaces in portables will be found deficient. The school is a fine arts academy and has programs in visual arts, dance, band, orchestra, choral music, drama, classical guitar, piano, digital arts and media. As a feeder to McCallum High School, the programs are aligned to the offerings at McCallum.

Due to its age, there are numerous issues with the building. There are no collaboration spaces throughout the school, and even as a fine arts academy, there is not an adequate performance space. The cafeteria has a stage, but the infrastructure and seating space within the cafeteria is severely lacking. Portables house dance, special education and studios.

As a part of the 2017 bond program, an addition and renovation for fine arts is planned but the design has not yet been completed.

Interview Overview

The interview with Principal Tesano and staff highlighted multiple areas of interest and concern on campus. It was brought up that the existing school, even with eight portables on campus, cannot accommodate the current enrollment. Studios are overcrowded, a fourth lunch service needs to be added, and programs such as special education and dance that are ill-suited to be in portables are diminished in their capacity to teach. It was also mentioned that being a fine arts academy, many of the fine arts programs lack proper facilities for both teaching and performing. A new performance space is a high priority for the school and may be part of the 2017 bond improvements.

The belltower at the school entry was identified as an object of cultural significance, in addition to the gardens.

on campus, but the furniture is not ideal for teaching classes.

The instructors said that the lack of collaboration/flex space, small group and medium group rooms inside the building restricts their teaching abilities. It was discussed that these spaces are needed close to the studios so teachers can have the ability to monitor students while teaching. A request was brought up for more teacher workroom/lounge space. There is only one small teachers' lounge in the building and there are no distributed professional learning centers in the studio wings. The school would also like more opportunities to display student work and art, especially 3D display spaces. Due to the overcrowding in the school, many of the conference rooms are being used for other purposes, contributing to a lack of meeting spaces. It was also brought up that there are rodent

Lamar Middle School

issues that need to be addressed.

Moving forward, the campus would like to add a mental health center and focus more on college and career readiness.

Assessment Findings

The Educational Suitability Assessment of Lamar Middle School earned a 52% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Exterior

Score is unsatisfactory.

School signage is clear, but vehicle wayfinding signage is limited. The dumpsters are in completely different areas of the school. Composting is at the loading dock off of Wynona, and trash/recycling is at the north parking lot off of White Horse Trail.

General Building

Score is unsatisfactory.

Hallways are greater than 10 feet wide, have high ceilings and there is daylight at the end of the hallways. The gym can open for after-hours events, but the library and cafeteria cannot. There is not a dedicated community room. While the school appears to be well-kept, the original building is starting to show its age.

Security

Score is unsatisfactory.

Academics & Learning

Score is unsatisfactory.

Studios/science rooms are undersized. Many studios are in portables. There are limited support/storage spaces. There are no breakout rooms for collaboration, and the building does not support collaboration through flexible furniture or breakout spaces. The courtyard is an area that fosters informal interaction, but these spaces do not exist within the building.

Visual and Performing Arts

Score is unsatisfactory.

Choir/orchestra/band rooms are in good condition but are undersized and cannot support growing programs. There are limited practice rooms, and storage is not adequate. The art rooms are adequate in size, but do not have the proper number of sinks. Dance is in a portable. For theater arts, the stage and storage are very inadequate, and the cafeteria does not have enough audience space for performances. Current stage ceiling is low. While there are lights, these along with the A/V system are very dated.

Lamar Middle School

Athletics and Wellness

Score is unsatisfactory.

Both gyms are undersized and have dated finishes. There is not a dedicated weight room. There is not enough athletic storage and not enough lockers for students. The school requests gender neutral option for both restrooms and changing. The track is in excellent shape, and the community has access to it.

Food Services

Score is unsatisfactory.

Cafeteria and kitchen are adequate in size, but all finishes are dated. There is no dedicated chair storage. See notes above about the stage under Visual and Performing Arts

Technology

Score is unsatisfactory.

The cafeteria A/V is acceptable, but the gym A/V needs updating. There are not adequate charging locations for devices, and in a typical studio there are only two outlets per wall.

Administration Spaces

Score is unsatisfactory.

The main reception area is very small, **and the second sec**

Average Categories (51-65%):

Controllability of Systems

Score is average.

There are mini blinds in the studios, but they are in poor condition. There does not appear to be thermostat control as most studios have individual, temporary HVAC units.

Furniture, Fixtures, Equipment

Score is average.

The library has a small percentage of new, flexible seating. All studios have loose tables and chairs. Science labs have older, heavy lab tables, but they are in adequate condition.

Media Resources

Score is average.

Library is one large, open space broken up into different zones. It can accommodate large groups and has one breakout/conference room but would need updates to function well. There is a courtyard that students sometimes use. The storage and support spaces for the librarian are very inadequate.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

Lamar Middle School

There are a few outdoor learning spaces – one adjacent to the library/studios and another one by the cafeteria. These need updates to function well. There is a garden area with cisterns and a chicken coop.

Environmental Quality

Score is satisfactory.

Throughout the school, there is a lot of mechanical equipment noise from the temporary air units placed in hallways and studios. The studios have lighting upgrades with both indirect and direct lighting fixtures. All studios have views to the outside and access to daylight.

CTE and Career Connected Learning

Score is satisfactory.

Pathways align closely to the offerings at McCallum High School. Courses provided in arts, A/V technology, business, information technology and STEM.

Lamar Middle School

Supporting Photographs



School Entry: Not very inviting or open. Belltower adjacent to entry is well-loved and is one aspect of the campus that should not change in the future.



Main corridors are generous in width and have daylight at the end. There are no collaboration spaces or spaces for informal interaction within any of the corridors where studios are located.

Lamar Middle School

Supporting Photographs



Media Center: Square footage is adequate and there is a mix of old and new furniture. Space needs updates to function well. Media center does not have adequate support space.



02/11/2022 Perkins&Will

Educational Suitability Summary Report

Lamar Middle School

Supporting Photographs



All studios are undersized per current Ed Spec square footage. All studios have excellent access to daylight and views. Outlet placement is sporadic and does not allow for adequate charging locations. Many studios have mechanical equipment units taking up floor square footage.



Science studios are undersized and have old heavy tables. Water at sinks is sporadically hooked up and many sinks do not have water.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Lamar Middle School

Supporting Photographs





Art studios do not have adequate support. There is only one sink in each art studio, but they do not have clay traps and get clogged frequently.

Lamar Middle School

Supporting Photographs



Main Gym: Main/aux gym are undersized per Ed Spec.



Display throughout the school is limited. Even though it is a fine arts academy, that is not evident when walking the halls.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Lamar Middle School

Supporting Photographs



Main courtyard is a nice inviting space with shade. Studios do not have direct access to this space, and the library has no transparency into this space. Students use this space to study and collaborate.



02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Lamar Middle School	Travis Hughbanks / Lynn Petermann	1/12/2021

1 - E	xterior		1	2	3	4	5	N/A	N Contraction of the second seco	8.75	49%
1.1	Does the sit pedestrian	e permit desirable separation of vehicular, bus and traffic?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Principal's comment - Buses and pedestrians mix on B	urnet Rd. Ther	re have
		at the same location							been pedestrian accidents in the past.		
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but									
		stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
	_	like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
	N1/A	destination									
	N/A	Does not apply						1			
1.2		ng easily identified with appropriate signage and wayfinding?			3				Comments	0.05	0.75
	community	, .								0.25	0.75
	1	Very unsatisfactory - Campus has no signage / wayfinding							School signage clear and identifiable; limited vehicle	, ,	
		, ,							The school reports that people are often confused whe	ere the entry i	S
	2	Unsatisfactory - Signage/wayfinding is faded/hidden							located.		
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

02/11/2022 ²

1 - Exterior (co	ont.)	1	2	3	4	5	N/A	N		
1.3 Is the dum	pster accessible for trash / compost disposal?			3				Comments	0.50	1.5
1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free.							Dumpsters are in two separate locations. Composting is lo loading dock directly next to the cafeteria. Trash and recy centrally located.		
N/A	Does not apply									
2 - Outdoor Le	earning and Activity	1	2	3	4	5	N/A	N	10.00	80%
2.1 Are outdoo the ed spe	or studios and support spaces appropriately configured per c?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area Does not apply							Multiple outdoor learning spaces and two are covered.		
2 Are active	playgrounds (elementary only) and support spaces g per the ed spec?						N/A	Comments	0.00	0.0
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

02/11/2022 ³

2 - 0	utdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	A		
		ns and support spaces appropriately configured per the ed luation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation							Monitoring answer, does not affect score for Outdoo Activity. Gardens with raised beds are centrally locat water. Paths to garden need improvement and gard updates.	ed with easy ac	.cess to
	N/A	Does not apply		- 1				1			
2.4	Are the rained spec?	n gardens and/or cisterns appropriately configured per the			3				Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided							Monitoring answer, does not affect score for Outdoo Activity. Two cisterns. One located directly next to lea	-	
25	N/A Does the sc	Does not apply chool have animal husbandry? (optional)					5	1	Comments	0.00	0.00
2.0	1 5	No Yes					5			0.00	0.00
2.6		chool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
2.7		chool have a learning pond? (optional)	1						Comments	0.00	0.00
	1 5	No Yes							·		
2.8	-	chool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1 5	No Yes									

- General Bu	uilding	1	2	3	4	5	N/A	N Contraction of the second seco	11.25	47%
Are interio	r circulation routes wide enough to safely and effectively					_		Community		
.1 accommod	date student movement?					5		Comments	0.50	2.50
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Principal's comment - Passing periods are very crowd	led and there o	are
	wide							hallways that converge causing a traffic jam. Studen	ts report being	g shove
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide							and pushed due to crowded hallways. Lockers are no	ot usable due t	o traffi
3	Average - Primary circulation is 7'-0" to 8'-0" wide							in the hallways.		
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are comm	unity use areas arranged so that the school can allow night		_			[
	without full school access?		2					Comments	0.75	1.50
1	Very unsatisfactory - Cafeteria, gym, and library cannot							Library and cafeteria cannot be closed off for night f	unctions.	
	be accessed after hours									
2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
	Gym and Library) can be accessed from parking and									
	secured after hours									
3	Average - Only two of the public spaces can be accessed									
	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building but not individually									
5	,									
5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply									
ls there a c	community room that is a dedicated meeting space outside			1	1	1				
.3 of school f		1						Comments	0.75	0.7
1	Very unsatisfactory - No dedicated community room		1		1					
2	Unsatisfactory - Community room but within school									
	function, no access after school hours									
3	Average - Community room, moderate size, but need									
	some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
N/A	function Does not apply									
	general appearance of the school convey pride for the		Γ	1	1	1				
/	nd community?		2					Comments	0.25	0.5
1	Very unsatisfactory - General appearance is poor		L	i	I	<u>i</u>		School is clean and well taken care of but is showing		0.0
2	Unsatisfactory - General appearance is aged but ok								no ago.	
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
	campus and student works									
5	Very Unsatisfactory - General appearance shows pride									
	in campus and student works and is welcoming to the									
	community									
N/A	Does not apply									

- Security		1	2	3	4	5	N/A	16.25	
4.1 Does the fo	acility have key card access at all major entries?							Comments	
1	Very unsatisfactory - No entries	1 1		I					
2	Unsatisfactory - 1/4 of major entries								
3	Average - 1/2 of major entries								
4	Satisfactory - 3/4 of major entries								
5	Very satisfactory - All of major entries								
N/A	Does not apply	r r	-						
4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	
1	Very unsatisfactory - No exterior lighting, no secure perimeter))
2	Unsatisfactory - Lighting is limited to front entry only,								
-	parking lot lighting poor, security is minimal								
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate								
4	Satisfactory - Lighting at all night-use entries and								-
	parking lots, good condition, signage less visible, perimeter is well secured but needs updates								
5	Very satisfactory - Signage, parking lots, and entries are								
	well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply	, r							
43	office located at the school entry and configured with a ibule to the main corridor?							Comments	
secure vest	Very unsatisfactory - No secure vestibule, office located		1	1		1			
1	far from main entry, allows visitors access to school								
	unsupervised								
2	Unsatisfactory - No secure vestibule, office located								
	somewhat far from main entry, minimal supervision of								
	visitors								
3	Average - Office close to entry, views of front door, but no secure vestibule								
4	Satisfactory - Office is well-located with a secure								
	vestibule, but needs updates								
5	Very satisfactory - Office well-located with secure								
	vestibule and all appropriate security features								
N/A	Does not apply								
	ough interior transparency for faculty to passively supervise ad their activities who are not in studios?		2					Comments 1.00	2.0
1	Very unsatisfactory - No transparency of walls					1		No interior glazing for studios and limited interior glazing at library and	
2	Unsatisfactory - Limited transparency in certain locations							cafeteria.	
3	Average - Good transparency in certain locations but								
	inadequate or missing in other locations of school								
4	Satisfactory - Adequate transparency throughout the school								
5	Very satisfactory - Excellent transparency throughout the								
	school								
N/A	Does not apply								

5 - Environmental Quality	1	2	3	4	5	N//	Ą	25.00	729
5.1 How are acoustics in studios in general?		2					Comments	1.00	2.0
 Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room N/A Does not apply 							A lot of mechanical equipment noise. No acoustic ce corridors are not insulated.	ilings and wall	s to
5.2 Is the studio artificial lighting adequate quality?				4			Comments	1.00	4.0
 Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare N/A Does not apply 							New lights with up and down lighting.		
5.3 Is there access to natural light in studios?					5		Comments	1.00	5.0
 Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light N/A Does not apply 							All studios in the main building have one large wall a	f windows.	
N/A Does not apply 5.4 Is there access to outside views from learning spaces?					5	1	Comments		
 Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views 		<u> </u>	<u> </u>	<u> </u>	-	I	See above.	1.00	5.0

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	A Contraction of the second seco		
5.5	Does the bu	uilding have odor or pest problems?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							Staff said there is a rodent issue.		
6 - C	ontrollabi	lity of Systems	1	2	3	4	5	N/A	A	12.50	52%
6.1	Does the st	udio thermostat allow for individual control?	1						Comments	0.50	0.50
	1 5	No Yes	•								
6.2	Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades Does not apply							Mini blinds in studios and majority of other spaces.		
6.3	-	quality of lighting controls in the studios?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply	<u>.</u>	<u>.</u>	<u>.</u>		-				

7 - Furniture, F	ixtures & Equipment	1	2	3	4	5	N/A		18.75	55%
7.1 What is the	current condition of the furniture?			3				Comments	0.75	2.25
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply							Principal's note - Science tables are frequently repair off. Some science rooms do not have science tables.	ed - legs are f	alling
/ ')	ty of furniture types being accommodated throughout the Irning commons, dining commons, other multi-use spaces?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture Does not apply							Library has six new flexible tables and the rest of the some of it is fixed or hard to move. Cafeteria has fold chairs that provide flexibility.		
7.3 How well d	oes furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply									
7.4 Is the furnit	ure ergonomic and size appropriate for grade level?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow students to be active Does not apply									

02/11/2022 °

Waste		1	2	3	4	5	N/A	·	5.00	50
Do studios and corridors have blue recycle instructions and/or image sorting instruction	U U		2					Comments	0.50	1.
 Very unsatisfactory - There are bins and signage are sparse o only landfill bins with no recyc Unsatisfactory - Bins and sign infrequent and/or lack clear si Average - 50% of corridors an landfill bin and a recycle bin in The containers have clear sign Satisfactory - 75% of studios of landfill and recycle collection of location. The containers have Very satisfactory - All studios / visible landfill and recycle colle accessible locations. The conta and the style and format is con across campus. 	r infrequent, OR there are ling bins. age are sparse or gnage. d studios have both a an accessible location. age. and corridors have a visible containers in an accessible clear signage. f corridors (100%) have ection containers in ainers have clear signage,							A score for this category is being recorded, but this c calculated in the overall ESA average.	ategory is not	
N/A Does not apply							1			
Does the cafeteria (or wherever meals are s of each: green compost bin, blue recycle bi bins labelled clearly with bilingual and/or i	n, and landfill bin? Are the			3				Comments	0.50	1.
 Very unsatisfactory- There ma are no compost and/or recycle sorting signage. 	•	<u> </u>					1	A score for this category is being recorded, but this c calculated in the overall ESA average.	1	
2 Unsatisfactory- Recycle, landf present, but the bins are scatt next to one another. Signage	ered and no co-located									
3 Average- There is at least one three bins (recycle, compost, la proximity to one another. The consistent.	andfill) located with close									
4 Satisfactory- There are severa described above	l waste stations as									
5 Very Satisfactory - There are s described above, and addition cafeteria that encourages rec'	nal signage in the									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Lamar Middle School	Travis Hughbanks / Lynn Petermann	1/12/2021


8 - Academics & Learning	1	2	3	4	5	N//	A	65.00	37%
8.1 Are studios appropriately configured per the ed spec?		2					Comments	1.00	2.00
1 Very unsatisfactory - Too small, no flexibility, disconnected							All studios are undersized at 730 to 760 square feet.		
2 Unsatisfactory - Too small, only one area for all teachin methods, limited flexibility, disconnected	g						The principal notes that the school does not have en number of teachers.	ough studios fo	or the
3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.	0								
4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A Does not apply									
8.2 Do studios have appropriate support spaces such as storage per the ed spec?		2					Comments	1.00	2.00
1 Very unsatisfactory - None provided							Limited storage and support space.		
2 Unsatisfactory - Too small, disconnected, poor conditio	ı								
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, excellent condition									
N/A Does not apply									

02/11/2022 ²

8 - A		& Learning (cont.)	1	2	3	4	5	N/A	·		
8.3	Do typical le	earning neighborhoods have small and medium (high	1						Comments		
0.5	school only)	group rooms and open collaboration space?	I						Comments	1.00	1.0
	1	Very unsatisfactory - No breakout rooms or open							No collaboration space or small group rooms in lear	ning neighborł	noods.
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition									
		and flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply		1			1	1		1	
8.4		Labs and support spaces appropriately configured per		2					Comments		
••••	the ed spec									1.00	2.0
	1	Very unsatisfactory - No dedicated science room							All labs are undersized and need updates. Most eye	wash and eme	rgency
	2	Unsatisfactory - Too small, poor condition, no connected							showers do not work. Only two prep rooms but are u	used for storage	e.
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	_	support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N/A	connected support spaces									
		Does not apply		1	1	1	1	1		1	
8.5		Spaces and support spaces appropriately configured per ? (cross reference with CTE below)	1						Comments	1.00	
										1.00	1.0
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	0	from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	4	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	F	learning spaces Very Satisfactory - Generous size, excellent condition,									
	5										
	NI/A	connected to learning spaces									
	N/A	Does not apply									

02/11/2022 ³

8 - Academics	& Learning (cont.)	1	2	3	4	5	N/A			
8.6 Is there a Pr	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
1	Very unsatisfactory - No dedicated space for Professional Learning Center		<u>.</u>					One teachers' lounge provided by admin area.		
2	Unsatisfactory - Too small, poor condition, disconnected									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition, connected									
5	Very Satisfactory - Generous size, excellent condition, connected									
8/	dequate places to display the evidence and artifacts of oth 2D and 3D)?		2					Comments	1.00	2.00
1	Very unsatisfactory - No dedicated space							Very limited 3D display (2' x 6' cabinet) and most disp	lays need upd	ating.
2	Unsatisfactory - Too small, non-dedicated, poor condition									-
3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
Does the bu	uilding / learning neighborhood provide adequate									
	es for students/teachers to collaborate in varying group	1						Comments		
sizes?									1.00	1.00
1	Very unsatisfactory - No space to support collaboration in various sizes.							No collaboration, flex or breakout space.		
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple									
5	options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition,									
5	multiple options to support a variety of group sizes									
N/A	Does not apply									
8.9 Does the bu	ilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
1	Very unsatisfactory - No space							Exterior areas provide limited opportunity for informe	al interaction b	out all of
2	Unsatisfactory - Too small, poor condition, layout and							the interior spaces are enclosed, programmed learning	ng spaces.	
3	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply									



Does the '	s & Learning (cont.) building provide adequate opportunities for students to	1							
8 10	pendently?	1					Comments	1.00	1.0
1	Very unsatisfactory - No breakout rooms/small study					1		1.00	
	spaces								
2	Unsatisfactory - Too small, poor condition, no acoustic								
2	privacy, only one space for independent work,								
0	disconnected from learning neighborhood								
3	Average - Adequate size and condition, needs updates								
4	or renovations to function well.								
4	Satisfactory - Good size and condition, acoustic privacy,								
	variety of independent work space options, connected to								
-	learning neighborhood								
5	Very Satisfactory - Generous size, excellent condition,								
	acoustic privacy, variety of independent work space								
	options, connected to learning neighborhood								
N/A	Does not apply								
Special Ec	ducation		 						
Are Speci	al Education spaces appropriately configured per the ed	1					Commente		
8.11 spec?		1					Comments	1.00	1.4
1	Very unsatisfactory - Too small, no flexibility,						SBS and Scores are located in portables. Life skills lak	adequate in s	size b
	disconnected						needs updating.	, adoquato in c	
2	Unsatisfactory - Too small, only one area for all teaching						needs upduting.		
	methods, limited flexibility, disconnected						- · · · · · · · · · · ·		
3	Neutral - Adequate size, multiple areas for different						The principal reports that there is not enough space		
5	teaching methods, adequate flexibility, limited						Speech Pathologist, Diag, and other support staff wh	o provide dire	ct
	transparency and connection to other studios and						services to students.		
	shared learning spaces, needs updates or renovations to function well.								
4	Satisfactory - Good size, multiple areas for different								
4	teaching methods, good flexibility, good transparency								
	and connection to other studios and shared learning								
	spaces								
5	Spaces Very Satisfactory - Generous size, multiple areas for								
5									
	different teaching methods, excellent flexibility, generous display area and visual teaching tools,								
	denerous display area and visual teaching tools.								
	excellent transparency and connection with other								
N1/A	excellent transparency and connection with other studios and shared learning spaces								
N/A	excellent transparency and connection with other studios and shared learning spaces Does not apply		1	[1				
Are Specie	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for		3				Comments	100	
8.12 Are Specie washer/d	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec?		3					1.00	
8.12 Are Specie washer/d	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for		3				Washer/dryer are provided and storage is adequate	. There is a spe	
8.12 Are Specie washer/d	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided		3					. There is a spe	3. ecial
8.12 Are Specie washer/d 1 2	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition		3				Washer/dryer are provided and storage is adequate	. There is a spe	
8.12 Are Specie washer/d	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided		3				Washer/dryer are provided and storage is adequate education conference room but it is currently being u	. There is a spe	
8.12 Are Specie washer/d 1 2	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition		3				Washer/dryer are provided and storage is adequate education conference room but it is currently being u	. There is a spe	
8.12 Are Specie washer/d 1 2	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs		3				Washer/dryer are provided and storage is adequate education conference room but it is currently being u	. There is a spe	
8.12 Are Specie washer/d 1 2 3	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well		3				Washer/dryer are provided and storage is adequate education conference room but it is currently being u	. There is a spe	
8.12 Are Specie washer/d 1 2 3 4	excellent transparency and connection with other studios and shared learning spaces Does not apply al Education support spaces, such as storage, space for ryer, appropriately configured per the ed spec? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition		3				Washer/dryer are provided and storage is adequate education conference room but it is currently being u	. There is a spe	

8 - Academics & Learni	ng (cont.)	1	2	3	4	5	N/A			
813	oms and changing rooms readily available to the					5		Comments	1.00	
Special Education spo 1 No	aces?								1.00	5.00
5 Yes										
STEAM Center										
8.14 Does the campus hav	e space to support a "STEAM" center?			3				Comments	0.00	0.00
	atisfactory - No available space for STEAM			1				Monitoring answer, but does not count toward overa	ll score.	
2 Unsatisf CTE/CCL	nd inadequate studio / collaborative space actory - Collaborative areas / studios for . are completely separate but adequate size									
adjacen	 Collaborative areas / studios for CTE/CCL are t but function separately 									
function	ory - Collaborative areas / studios for CTE/CCL and have space availability to create STEAM									
-	isfactory - Functioning STEAM center offers									
multime	labs, common collaborative areas to support dia distance and hands-on project based									
learning N/A Does no										
9 - CTE and Career Con									11.25	73%
How close is your can	npus to a CTE cluster pathway that is aligned ms (Middle School only)?			3				Comments	1.00	3.00
	atisfactory - No correlation to CTE cluster		1	1			<u> </u>	All CTE programs identified in the Master Plan are pro	ovided with th	e
2 Unsatisf	y, no CTE programs. actory - School supports less than half of the CTE							exception of Hospitality and Tourism.		
3 Average	ns that are listed in the cluster pathway. - School support half of CTE programs listed in									
4 Satisfact	er pathway, but missing some. :ory - School support a majority of CTE programs									
	the CTE cluster pathway. isfactory - School is aligned with CTE cluster									
pathway N/A Does no	<i>.</i>									
	lign with the CTE Ed Spec Requirements for the									
	ered?: Architecture and Construction						N/A		0.00	0.00
1 No 5 Yes										
N/A Does no	t apply									
9.3 Arts, Audio and Video	P Technology and Communications					5		One computer lab is a converted studio and does not have outlets or furniture to support instruction.	0.25	1.25
9.4 Business, Manageme	nt and Administration					5			0.25	1.25
9.5 Education and Trainin	ng						N/A		0.00	0.00
9.6 Health Science							N/A		0.00	0.00

02/11/2022	6	
------------	---	--

9 - CTE and Career Connected Learning (cont.)	1		2	3	4	5	N/A			
9.7 Hospitality and Tourism	1								0.25	0.25
9.8 Human Services (high school only)							N/A		0.00	0.00
9.9 Information Technology						5			0.25	1.25
9.10 Agriculture, Food and Natural Resources							N/A		0.00	0.00
9.]] Science, Technology, Engineering, and Mathematics						5			0.25	1.25
9.12 Transportation, Distribution and Logistics							N/A		0.00	0.00
9.13 Finance (high school only)							N/A		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)							N/A		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)							N/A		0.00	0.00
9.16 Manufacturing (high school only)							N/A		0.00	0.00
9.17 Marketing, Sales and Services (high school only)							N/A			
10 - Visual and Performing Arts	<u> </u>	_						I	0.00	0.00 46%
10,1 Is there flexibility of space to also be used by CTE and Athletics?						5		Comments	0.00	0.00
IO.1 is there hexibility of space to also be used by CTE and Athletics?	ļ									
1 No								Monitoring answer, but doesn't affect overall score.		0.00
				3				Monitoring answer, but doesn't affect overall score. Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces				3					1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition				3				Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs		Γ		3				Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition				3				Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition				3				Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply				3				Comments	1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the			2	3				Comments	1.00 and practice r	3.00 ooms.
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec?				3				Comments Good condition; missing program spaces for storage	1.00 and practice r 1.00	3.00
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the				3				Comments Good condition; missing program spaces for storage of Comments	1.00 and practice r 1.00	3.00 ooms.
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs				3				Comments Good condition; missing program spaces for storage of Comments	1.00 and practice r 1.00	3.00 ooms.
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.				3				Comments Good condition; missing program spaces for storage of Comments	1.00 and practice r 1.00	3.00 ooms.
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition				3				Comments Good condition; missing program spaces for storage of Comments	1.00 and practice r 1.00	3.00 ooms.
1 No 5 Yes 10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 10.3 Are orchestra and support spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well.				3				Comments Good condition; missing program spaces for storage of Comments	1.00 and practice r 1.00	3.00 ooms.

10 - Visual and	Performing Arts (cont.)	1	2	3	4	5	N/A	Ą		
10.4 Are choir an spec?	nd support spaces appropriately configured per the ed			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Good condition but undersized. Only have rehearsal	space, office a	nd
2	Unsatisfactory - Too small, poor condition							small storage. Space not configured for choir instruct	ion.	
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1	r –	1	-	r –				
10.5 Are dance of spec?	and support spaces appropriately configured per the ed	1						Comments	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
10.6 Are theater spec?	and support spaces appropriately configured per the ed			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces				-			Two theater studios provided and storage. Good con		0.00
2	Unsatisfactory - Too small, poor condition							requests more storage - props are stored outside in th		nd in
3	Neutral - Adequate size, adequate condition, needs							the dressing room off the stage.		-
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply			_						
	irts and support spaces appropriately configured per the			3				Comments		
ed spec?				0					1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Need more sinks and in-room storage. Spaces are ad	•	but
2	Unsatisfactory - Too small, poor condition							need updating and more countertop surface/laydow	n space.	
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1				1				
10.8 Does the co	impus have adequate space for the specialty arts	1						Comments		
programs (Ensemble, Guitar, Music studies, Music theory and Piano)?	1						Comments	1.00	1.00
1	No	1					1	No space for guitar class and piano studio is too sma		
5	Yes							pianos.	n so students s	nure
								The rest of the re		

11 - Athletics and Wellness							18.75	36%
11.1 Does the campus meet ed spec standard for physical education program spaces?	1					Comments	1.00	1.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply		·	·			Both gyms are undersized and all spaces need updat	ng. No weight	t room.
11.2 Does the campus have a dedicated wellness center?	1					Comments	0.50	0.50
1 No 5 Yes					I			
11.3 Does the community have access to exterior playfields/courts?				5		Comments	0.50	2.50
1 No 5 Yes								
1].4 Are facilities available to facilitate eSports (High School only)?	1					Comments	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?	1					Comments	0.25	0.25
1 No 5 Yes					•	Per CAD plan, basketball court is 40' wide. 2' narrowe school. School reports that athletes cannot make 3 pc bounds.		
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1					Comments	0.25	0.25
1 No 5 Yes						Insufficient spectator space for hosting track meets.		
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1					Comments	0.25	0.25
1 No 5 Yes						Support practice but no spectator seating.		
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?				5		Comments	0.25	1.25
l No 5 Yes								
1].9 Are facilities set up to support UIL sanctioned athletics for tennis?	1					Comments	0.25	0.25
1 No 5 Yes						Two courts to support practice but not matches.		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1					Comments	0.25	0.25
1 No 5 Yes						Support practice but no spectator seating.		

02/11/2022	9
------------	---

1 - Athletics and Wellness (cont.)	1	2	3	4	5 I	N/A			
Are facilities (dedicated storage) set up to support UIL sanctioned						N/A	Comments		
athletics for cross-country (high school only)?						N/A	Comments	0.00	0.0
1 No									
5 Yes									
Are facilities (dedicated storage) set up to support UIL sanctioned						N/A	Comments		
athletics for golf (high school only)?						N/A	Comments	0.00	0.
1 No									
5 Yes									
Are facilities (dedicated storage) set up to support UIL sanctioned						N/A	Commente		
athletics for swimming (high school only)?						N/A	Comments	0.00	0.
1 No									
5 Yes									
Are facilities set up to support UIL sanctioned athletics for wrestling						1/4	Community		
1.14 (high school only)?						N/A	Comments	0.00	0.
1 No									
5 Yes									
Are facilities set up to support UIL sanctioned athletics for baseball						1/4	Community		
(high school only)?						N/A	Comments	0.00	0
1 No									
5 Yes									
Are facilities set up to support UIL sanctioned athletics for softball						N/A	Comments		
(high school only)?						N/A	Comments	0.00	0
1 No									
5 Yes									
Are facilities (dedicated space outside of the gymnasium) available to									
1.17 support competitive spirit activities for cheerleading and drill team?	1						Comments		
								0.25	0
1 No									
5 Yes		-	-	-					
- Athletics and Wellness (cont.)	1	2	3	4	5 I	N∕A	T. T		
How do the athletics fields align with FMP Campus Improvements?									
I.18 Turf Field, Parking lot lighting, ADA accessible amenities (high School						N/A	Comments		
only)	L							0.00	0
Very unsatisfactory - No turf, inaccessible, no site lighting							Monitoring answer, but doesn't affect overall score.		
2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting									
3 Average - Field in adequate condition, needs some									
updates or renovations to function well									
4 Satisfactory - Turf field in good condition, good ADA									
access and site lighting									
5 Very Satisfactory - Turf field with excellent maintenance,									
excellent ADA access for spectators and athletes,									
excellent site lighting									
N/A Does not apply.									

- Food Services								10.00	50%
2.1 Is the Dining Commons appropriately configured per the ed spec?		2					Comments	1.00	2.0
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) N/A Does not apply 							Current cafeteria size is 6,450 SF. For capacity of 1008, adequate. School is over-capacity at 1,230 students an cafeteria of 6,970 SF. School notes they do not have er 1/3 of students.	nd would requ	
Are the Food Services support spaces appropriately configured per the ed spec?			3				Comments	1.00	3.0
 Very unsatisfactory - None provided Unsatisfactory - Tas analy disconnected provided 							Kitchen adequate in size but chair storage inadequate updated.	e; everything r	need
 Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition 									
 Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 									
 Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition 	1	2	3 3	4	5	N/A	Comments	30.00	5:

13 - Media Res	sources - Continued	1	2	3	4	5	N/A	۸		
13.2 How well o	loes the Library/Media Center support quiet study?		2					Comments	1.00	2.0
1 2 3 4 5 N/A	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply							Only one enclosed breakout space provided, which is conference room. Conference room is shared with ac		ed
	loes the Library/Media Center support social interaction?		2					Comments	1.00	2.0
1 2 3 4 5 N/A	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply									
How well c	Joes the Library/Media Center support collaborative work oups (4-8 students)?			3				Comments	1.00	3.0
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition	<u> </u>	<u> </u>	L	1	I		Library is one large open space but it is broken up wi bookshelves that create zones for smaller group lear separation between zones.	th furniture an	d
1.4.5	Does not apply does the Library/Media Center support collaborative work roups (10-25)?			3	[Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply	L	L	1	1		1			

1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Average - Mix of old and new whiteboards/projectors/letc. 4 Satisfactory - projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - projectors, marker boards, smart boards, smart boards projector shut instructional technology? 4. Technology 1 2 3 5 N/A 20.00 50 1 Very unsatisfactory - United to no technology present in instructional spaces 3 Average - Multiple types of technology present in instructional spaces 3 Average - Multiple types of technology, smart boards. Poor condition. 1.00 3.1 1 Very satisfactory - One type of technology, smart boards. Poor condition. 5 Very Satisfactory - Multiple types of technology, smart boards. Poor condition. 4.1 Studios and learning spaces have mobile screens. 1.00 3.1 1 Very unsatisfactory - Multiple types of technology, smart boards. Poor condition. 4.1 Studios and learning spaces have mobile screens. 1.00 3.1 2 Unsatisfactory - Multiple types of technology, smart boards. Poor condition. 5 Very Satisfactory - Multiple types of technology, smart boards. 4.1 5.1 5.1 5.1<	13 - Media Res	ources - Continued	1	2	3	4	5	N/A	<u> </u>		
a Unsatificatory - Outdated, poorly functioning, or insufficient. Sufficient -	13.6 How well d	oes the Library/Media Center support technology?			3				Comments	1.00	3.0
4 - Technology 1 2 3 4 5 N/A 20.00 56 14.1 How well equipped are the facilities with instructional technology? 3 3 4 5 N/A 20.00 56 1 Very unsatisfactory - Limited to no technology present in instructional spaces 2 Unsatisfactory - One type of technology, smart boards. Poor condition. Limited to only certain areas of school. Average - Multiple types of technology, smart boards. Poor condition. All studios and learning spaces have mobile screens. All studios and learning spaces have mobile screens. 4.1 Satisfactory - Multiple types of technology, smart boards. Poor condition. 5 Very Satisfactory - Multiple types of technology, smart boards. Good condition. 5 Very Satisfactory - Multiple types of technology, smart boards. Comments 1.00 2.1 4.2 Is there an adequate number of power and data outlets in learning spaces? 2 0 Comments 1.00 2.1 4.2 Is there an adequate number of power and data outlets in learning space fighted devices throughout school () per wall) 2 0 Comments 1.00 2.1 4.2 Unsatisfactory - Outlet configuration support digital devices throughout school () per wall) 2 0 Comments 1.00 <t< td=""><td>3 4 5</td><td>Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td>ite areas with</td><td>deskto</td></t<>	3 4 5	Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition								ite areas with	deskto
14.1 How well equipped are the facilities with instructional technology? 3 3 Comments 1.00 3. 1 Very unsatisfactory - Limited to no technology present in instructional spaces All studios and learning spaces have mobile screens. 1.00 3. 3 Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. All studios and learning spaces have mobile screens. 1.00 3. 4 Satisfactory - Multiple types of technology, smart boards. Poor condition 5 Very Autisfactory - Multiple types of technology, smart boards. Excellent condition 2 Comments 1.00 2. 14.2 Is there an adequate number of power and data outlets in learning spaces? 2 Comments 1.00 2. 1 Very unsatisfactory - Outlet configuration does not support digital devices throughout school (2 per wall) 2 Comments 1.00 2. 1 Very Satisfactory - Outlet configuration support digital devices but limited capacity throughout school (2 per wall) 2 Comments 1.00 2.	,		1	2	3	1	5	NI//		20.00	503
instructional spaces 2 Unsatisfactory - One type of technology, smart boards. Poor condition. Limited to only certain areas of school. Poor condition. Limited to only certain areas of school, smart boards. Poor condition. Limited to only certain areas of technology, smart boards. Poor condition.						+					3.0
 Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to 	2 3 4 5	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition							All studios and learning spaces have mobile screens.		
 support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to 	14.7	adequate number of power and data outlets in learning		2					Comments	1.00	2.0
support digital devices throughout school (>3 per wall)	2 3 4	support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to									
N/A Does not apply	N/A										

14 - Technolog	yy (cont.)	1	2	3	4	5	N/A	A		
14.3 Are there o	adequate charging locations for devices?		2					Comments	1.00	2.0
1 2 3 4	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations,			<u> </u>		1		Many studios only have outlets for charging on two wo	alls.	
5	but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.									
N/A Is there ad gym?	Does not apply equate AV for presentations spaces – cafeteria, gym, aux			3				Comments	1.00	3.0
1 2 3 4 5	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.							Cafeteria has acceptable A/V but gym needs updating	g.	
N/A	Does not apply									
14.5 Is there dig	jital media signage at the reception area?				4			Comments	0.00	0.0
1 2 3 4 5 N/A	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply							It is not in the reception area but there is a large digita entry.	al display at s	chool

ration Spaces	1	2	3	4	5	N/	A	20.00	40
reception area that functions as a security checkpoint for all							Comments		
							Comments		
Very unsatisfactory - No security checkpoint			-)	
Unsatisfactory - Checkpoint is too small, poor condition									
Average - Needs updates or renovations to function well									
Satisfactory - Good size, good condition									
Very Satisfactory - Generous size, excellent condition									
Does not apply									
administration area feel welcoming?		2					Comments	1.00	2.0
Very unsatisfactory - No welcome space		1					Small, limited transparency and needs updating.		
Unsatisfactory - Too small, poor lighting and									
, , , , , , , , , , , , , , , , , , , ,							Principal's note - Students who are waiting to see co	unselor or	
							administrator have no privacy.		
5									
, , , , ,									
excellent condition									
Does not apply									
spaces that require it, does the administration area have			0				Commonte		
acoustic privacy?			5					1.00	3.
Very unsatisfactory - No acoustic separations							Sounds can be heard but words are not recognizable	e between offi	ices ar
Unsatisfactory - Acoustic separations do not perform							reception. School reports that parent volunteers are	able to hear	
							operations in the office.		
Does not apply		1	1					1	
rence rooms easily accessed for public / parent use?	1						Comments	100	1.
Very unsatisfactory - Not accessible for public/parent	l	L	I	1	<u> </u>		No conference room. They use conference room in lik		
use							,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,, ,,	,	
Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
Average - Adequate accessibility, needs updates or									
renovations to function well									
Satisfactory - Good accessibility, good transparency,									
good size and condition									
	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition Does not apply spaces that require it, does the administration area have acoustic privacy? Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations function okay, but portions need updates or renovations Satisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Does not apply rence rooms easily accessed for public / parent use? Very unsatisfactory - Inited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition Does not apply spaces that require it, does the administration area have acoustic privacy? Very unsatisfactory - No acoustic separations Unsatisfactory - Good acoustic separations Unsatisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Very Satisfactory - Excellent acoustic separations Very Satisfactory - Excellent acoustic separations Very Satisfactory - Not accessible for public/parent use Unsatisfactory - Not accessible for public/parent use Unsatisfactory - Limited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations function okay, but portions need updates or renovations Satisfactory - Excellent acoustic separations Very Satisfactory - Not accessible for public/parent use Unsatisfactory - Not accessible for public/parent use Unsatisfactory - Limited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition Does not apply spaces that require it, does the administration area have acoustic privacy? Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations Cose not apply rence rooms easily accessed for public / parent use? Very unsatisfactory - Not accessible for public/parent use Unsatisfactory - Limited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition Does not apply spaces that require it, does the administration area have acoustic privacy? Very unsatisfactory - No acoustic separations Unsatisfactory - Acoustic separations do not perform well Average - Some acoustic separations function okay, but portions need updates or renovations Satisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Very Satisfactory - Not accessible for public/parent use Unsatisfactory - Limited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size, and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition Does not apply spaces that require it, does the administration area have acoustic privacy? Very unsatisfactory - No acoustic separations Unsatisfactory - Good acoustic separations do not perform well Average - Some acoustic separations function okay, but portions need updates or renovations Satisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Does not apply rence rooms easily accessed for public / parent use? Very unsatisfactory - Inited access, no transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply administration area feel welcoming? 2 Very unsatisfactory - No welcome space Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel welcoming Satisfactory - Good size and layout, good lighting and transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided Very Satisfactory - No acoustic separations Unsatisfactory - Acoustic separations Very Satisfactory - No acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - Some acoustic separations Unsatisfactory - Good acoustic separations Unsatisfactory - Good acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - Good acoustic separations Very Satisfactory - Excellent acoustic separations Does not apply rence rooms easily accessed for public / parent use? Unsatisfactory - Not accessible for public/parent use Unsatisfactory - Not accessible for public/parent use Unsatisfactory - Not accessible for public/parent use Unsatisfactory - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Comments Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Good size, good condition Dees not apply administration area feel welcoming? 2 2 Comments Small, limited transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or renovations to feel velcoming Satisfactory - Good size and layout, plenty of light and transparency, limited informal seating, provided, excellent condition Dees not apply Spaces that require it, does the administration area have acoustic privacy? Very suitifactory - No acoustic separations Unsatisfactory - Good acoustic separations Unsatisfactory - Good acoustic separations Satisfactory - Good acoustic separations Satisfactory - Good acoustic separations Unsatisfactory - No acoustic separations Unsatisfactory - Comments Satisfactory - Comparency informal seating provided, excellent condition Dees not apply rence rooms easily accessed for public / parent use? 1 Very unsatisfactory - Comments Satisfactory - Good acoustic separations Unsatisfactory - Good access in transparency, poor condition, difficult to find Average - Adequate accessibility, needs updates or	reception area that functions as a security checkpoint for all Comments Very unsatisfactory - No security checkpoint Unsatisfactory - Checkpoint is too small, poor condition Average - Needs updates or renovations to function well Satisfactory - Generous size, excellent condition Dees not apply administration area feel welcoming Satisfactory - Too small, poor ighting and transparency, limited informal seating, poor condition Average - Adequate size and layout, plenty of light and transparency, informal seating provided, were lent condition addition to feel welcoming Satisfactory - Good size and layout, plenty of light and transparency, informal seating provided, were and apply spaces that require it, does the administration area have acoustic privacy - No acoustic separations Unsubifactory - Social coustic separations Unsubifactory - No acoustic separations Unsubifactory - No accustic separations Unsubifactory - No accustic separations Unsubifactory - No accustic separations Very unsubifactory - No coustic separations Unsubifactory - No coustic separations Very Subifactory - No coustic separations Unsubifactory - No coustic separations Very unsubifactory - No coustic separations Very Subifactory - Not accessible for public/par