

## **Educational Suitability Summary Report**

Martin Middle School

Date: 01/21/2021 Score 59% Average

Martin Middle School serves an enrollment of approximately 500 students in east Austin. It was constructed in 1966 and consists of approximately 109,000 square feet on 10 acres. The campus is in the Holly neighborhood just north of Lady Bird Lake. The school offers career and technology courses through Project Lead the Way and the Innovation Academy. Science, technology, engineering, arts and math lead the curriculum and provide students a learning environment to design, create and communicate solutions to real-world challenges.

Overall, the building does not support the goals of the school's curriculum, nor does it meet the district's Educational Specifications. The large gathering spaces on campus can all be accessed for after-hours events without access to the rest of the school, but only through courtyards and other exterior spaces. The site allows for vehicular and bus traffic to be separate, but stack space is limited.

Most

studios are slightly undersized and dated, lacking appropriate storage or access to power. Ample courtyard and covered spaces provide opportunities for outdoor learning but need updates to function well.

#### **Interview Overview**

The interview participants were Principal Dora Molina, Assistant Principal Cesar DeLeon, Head Custodian Maribel Rodriquez, and Administrative Assistant Lisa Brown. The interview discussion focused on inadequate and unsuitable spaces for programs, undersized studios and safety concerns.

The current layout of the science spaces does not function well and lacks needed resources. The orchestra room is not suitable, and there are no acoustic panels on the walls. Band spaces have humidity issues. Electrical rooms are not properly designed to function as electrical rooms contributing to a lack of space for equipment and heat issues.

It was also noted that the offices have poor acoustics. There are three individuals in the front office in an open area and all principal offices are very close to each other. The nurse's station is not in a suitable space. Rooms were modified for the front office, but the configuration does not function well. Some storage closets have been converted to offices.

CTE spaces do not have appropriate studios, and there is not enough electrical power for computers. The school has a track and field shared with the public that requires major updates to function well. The choir room was not designed as a true rehearsal space and has no soundproofing. The performance stage does not have power outlets for audio/visual equipment. According to the assistant principal, a designated STEM room is desired. However, there is not a suitable space for it,

## **Educational Suitability Summary Report** Martin Middle School

and there are concerns that power infrastructure is not adequate to support the program. The maker space is in a regular studio, and many of the STEM-related classes take place in the library. There have been complaints regarding frequent power outages. The studio spaces do not have adequate storage.

Collaboration is difficult with the current setup of the building. The school lacks designated spaces and technological resources for these collaboration spaces. The poor layout, minimal transparency, inadequate natural light and unsuitable spaces make it hard for the building to support the six C's.

The school has outdoor spaces, but they are not often utilized	
Concrete in the courtyard space becomes slippery when wet.	

The principal noted certain things on campus that should never change, including a butterfly garden by the tennis court. The garden in the open courtyard and benches outside the principal's office should also remain. Murals in the gym done by past students are important to school pride and spirit.

## **Assessment Findings**

The Educational Suitability Assessment of Martin Middle School earned a 59% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

#### **Unsatisfactory Categories (36-50%):**

# Security Score is unsatisfactory.

## **Academics & Learning**

Score is unsatisfactory.

Studios are undersized and storage is very limited with only one tall cabinet per room. Five science labs are present and well connected but have undersized, aged prep rooms. Two small labs are disconnected and located upstairs and have no prep room. A CTE lab doubles as a maker space, but there is no separate dedicated space for it. One large, shared supply and storage area is used as a professional learning center for teachers, but it is not centrally located for easy access. Outdoor corridors and spaces provide opportunity for informal interaction, but interior corridors are too narrow and confusing to function well with added furnishings.

## **Educational Suitability Summary Report**

Martin Middle School

#### **Media Resources**

Score is unsatisfactory.

The library is near the main office and main studio wings but is undersized. Due to its size, there is not much separation of space and no areas for quiet study. Most furniture is formal tables and chairs. Two projection screens, charging carts, two mobile TV displays and some power towers for charging devices are present.

## **Technology**

Score is unsatisfactory.

All studios have projection and mobile TV displays, but outlets are sparse, and some are dated. There is no projector or projection screen in the cafeteria or small gym, but the large gym has a large screen and mobile projection cart. There is a mobile TV display being used for digital media signage in the reception area, but no permanently installed TV.

### **Administration Spaces**

Score is unsatisfactory.

There is one conference room in the

administration suite, but it is not clearly identified.

### Average Categories (51-65%):

#### **Controllability of Systems**

Score is average.

All studios have thermostats for temperature control and blinds for daylight control. Some are in poor condition. Some spaces in older areas have single switches for lighting control; others have alternating rows and dual controls. Many spaces appear to have new LED lighting and modern controls.

#### **Furniture, Fixtures, Equipment**

Score is average.

There is a mix of old and new furniture throughout the campus, mostly in good condition. The library has a minimal amount of lounge furniture, mostly formal tables and chairs. Some is bulky and dated, while the rest is on casters and highly flexible. Studio furniture consists mostly of desks and chairs that can be more easily reconfigured.

#### **CTE and Career Connected Learning**

Score is average.

The school is a part of the Careers in Technology pathway and has CTE spaces for health/nursing, photography, STEM, keyboarding, robotics, engineering and A/V media. The specialized spaces for these programs are in good condition and adequate size. More studios are likely needed to fully support the number of programs offered.

#### **Visual and Performing Arts**

Score is average.

The campus has a large and small band hall, both adequately sized and in good condition but with only two practice rooms available. Orchestra space is undersized and shared with guitar and has

## **Educational Suitability Summary Report**

Martin Middle School

storage and an office but only one practice room. There is no dance program at this school because they do not have the space for it.

#### **Athletics and Wellness**

Score is average.

Large and small gyms are appropriately sized and in good condition. Stage was converted into a weight room and storage area is very undersized. Indoor athletics spaces are well-connected to outdoor athletics areas. Spaces appear to be set up to support UIL basketball, volleyball and tennis. Tennis courts do not have lighting.

#### **Food Services**

Score is average.

The cafeteria is undersized but has good connection to the central courtyard for outdoor dining opportunities. There are minimal windows and natural lighting in the space. The kitchen has two serving lines but is undersized.

## Satisfactory Categories (66-80%):

#### **Exterior**

Score is satisfactory.

Bus and vehicular drop-off are separate, but stack space is small and there are no canopies. There is a digital marquee on the street corner and signage on building is visible. Main entry is easy to locate.

#### **Outdoor Learning and Activity**

Score is satisfactory.

Garden areas have access to a water source but are disconnected from learning spaces and need maintenance and updates to be more functional. Courtyards have picnic tables for seating, but other outdoor areas are lacking furniture to work well for outdoor learning.

## **General Building**

Score is satisfactory.

Interior signage and wayfinding are nonexistent, and it is difficult to identify spaces. Corridors are well-sized between 8 and 10 feet wide. There is a large parent resources center near the main office. The cafeteria, library and gym can all be accessed for after-hour events without access to the rest of the school, but only through courtyards and other exterior spaces.

#### **Environmental Quality**

Score is satisfactory.

Acoustics and artificial lighting in studios are average. Not all studios have windows. Studios with windows have access to natural light and views of nature, but the windows are very small. Staff noted the presence of pests and odors in interview, primarily rats and plumbing odors.



Main reception area is not welcoming.



Gardens are a bit disconnected from learning spaces and need updates to function well.



The small cafeteria stage is the only area for performances, and it is difficult to fit all students and visitors. The space is undersized for food service and performances.



Orchestra and guitar share the same space with one practice room and limited storage.


Martin Middle School



Courtyard spaces are equipped with furniture but lack shade canopies or power access.




There are areas with murals around campus and most spaces are well-maintained given the age of the school.



Large and small gym are appropriately sized and in good condition. Patch of new flooring can be seen in the foreground of the photo.



The weight room is in the converted stage area of the large gym and is very undersized.



Media Resources: Library is slightly undersized with mostly flexible furniture that can be easily reconfigured.



Studios are equipped with projectors and mobile TV displays. Windows in some studios are narrow and provide limited natural light and views.



# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
Martin Middle School	Emilie Ogburn and Vishwesh Panchal	1.21.2021

1 - E	xterior		1	2	3	4	5	N/A	4	8.75	71%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Bus and vehicular drop-off are separate but stack sp	ace is small ar	nd there
		at the same location							is no dedicated canopy.		
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
	Ü	separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply									
1.0	Is the build	ing easily identified with appropriate signage and									
1.2	community	wayfinding?			3				Comments	0.25	0.75
	1	Very unsatisfactory - Campus has no signage /				•			Digital marquee present on street corner and signage	on building i	is visible.
		wayfinding							Main entry is easy to locate. Interior signage and way	finding are	
	2	Unsatisfactory - Signage/wayfinding is faded/hidden							nonexistent and it is difficult to identify spaces.		
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not									
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible and									
		easy to use									
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>2</sup>

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A			
1.3	Is the dump	oster accessible for trash / compost disposal?			3				Comments	0.50	1.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							All three dumpsters are adjacent but route is not accelloading dock.	essible; no ram	ps at
2-0	N/A Outdoor Le	Does not apply arning and Activity	1	2	3	4	5	N/A		10.00	80%
2.1	Are outdoo	r studios and support spaces appropriately configured per	<u>'</u>		3			IN//	Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
2.2	Are active p	Does not apply blaygrounds (elementary only) and support spaces per the ed spec?						N/A	Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full									
	N/A	shade coverage over play structure  Does not apply									

2 - Outdoor Learning and Activity (cont)		1	2	3	4	5	N/A	A		
Are gardens and support spaces appropriately conf	igured per the ed			3				Community		
spec? (evaluation on infrastructure not condition of	plants)			3				Comments	0.00	0.00
1 Very unsatisfactory - No dedicated gai	dens	•						Monitoring answer, does not affect score for Outdoo	r Learning and	
<ol> <li>Unsatisfactory - Too small, poor condit</li> </ol>	on, disconnected							Activity. Easy access to water source; area is disconne	ected from lear	ning
from learning spaces, no flexibility, no	accessible water							spaces and needs maintenance to be more accessib	le.	_
source										
3 Average - Adequate size, adequate co										
some renovations or updates to functions or updates to functions or updates to functions.	on well, water									
4 Satisfactory - Good size, good conditio	n connected to									
learning spaces, good flexibility, water										
accessible with 100 ft hose										
5 Very Satisfactory - Generous size, exce	lent condition.									
connected to learning spaces, excellen										
source is less than 50ft from the garde	n or has irrigation									
N/A Does not apply										
Are the rain gardens and/or cisterns appropriately of	onfigured per the	1						Comments		
ed spec?		'						Comments	0.00	0.00
1 Very unsatisfactory - No rain gardens o	or cisterns	•	•	•		•		Monitoring answer, does not affect score for Outdoo	r Learning and	
<ol> <li>Unsatisfactory - Too small, poor condit</li> </ol>	ion, not							Activity.		
functioning, disconnected										
3 Average - Adequate size, adequate co										
connected, needs some renovations or	updates to									
function well										
4 Satisfactory - Good size, good conditio	n, functions									
properly 5 Very Satisfactory - Generous size, exce	lant condition									
exceptional functionality, connected to										
educational signage provided	rieurning spaces,									
N/A Does not apply										
2.5 Does the school have animal husbandry? (optional)						5		Comments	0.00	0.00
1 No		•	•							
5 Yes										
2.6 Does the school have nature loop trails? (optional)		1						Comments	0.00	0.00
1 No										
5 Yes										
2.7 Does the school have a learning pond? (optional)		1						Comments	0.00	0.00
1 No 5 Yes										
5 Yes  2.8 Does the school have a grass play field and walking	trail?		1			5		Comments	1.00	5.00
2.8 Does the school have a grass play field and walking  1 No	uuii!	<u> </u>				5		Comments	1.00	5.00
1 NO 5 Yes										

	3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	80%
	1 3 1	r circulation routes wide enough to safely and effectively late student movement?				4			Comments	0.50	2.00
[	3 Are commu	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide  Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide  Average - Primary circulation is 7'-0" to 8'-0" wide  Satisfactory - Primary circulation is 8'-0"-10'-0" wide  Very satisfactory - Primary circulation is 10'-0"+ wide  Does not apply  unity use areas arranged so that the school can allow night vithout full school access?  Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours  Unsatisfactory - Only one of the public spaces (Cafeteria,				4			Comments	0.50	3.00
	3 4 5	Gym and Library) can be accessed from parking and secured after hours  Average - Only two of the public spaces can be accessed from parking and secured after hours  Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually  Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
	N/A	Does not apply					1				
	3.3 Is there a coordinate of school fu	ommunity room that is a dedicated meeting space outside unction?				4			Comments	0.75	3.00
	1 2 3 4 5	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function							113 is a large parent resource center; well located near office	r admin and r	nain
	N/A	Does not apply		1		1	ı				
		eneral appearance of the school convey pride for the nd community?				4			Comments	0.25	1.00
	1 2 3 4 5	Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the community							Murals throughout campus and most spaces are well the age of the school.	-maintained g	given
	N/A	Does not apply									

	4 - Security		1	2	3	4	5 N/A	A	16.25	
	4.1 Does the fa	cility have key card access at all major entries?						Comments		
,	1	Very unsatisfactory - No entries					· ·			
	2	Unsatisfactory - 1/4 of major entries								
	3	Average - 1/2 of major entries						,		
	4	Satisfactory - 3/4 of major entries								
	5	Very satisfactory - All of major entries								
	N/A	Does not apply								
	40 11 1									
	4.2 How adequ	ate is site lighting and security for the campus overall?						Comments		
Į.	1	Very unsatisfactory - No exterior lighting, no secure					· ·			)
		perimeter								)
	2	Unsatisfactory - Lighting is limited to front entry only,								
		parking lot lighting poor, security is minimal								
	3	Average - Lighting at all night-use entries and parking								
	· ·	lot, but poor condition. Security is moderate								
	4	Satisfactory - Lighting at all night-use entries and								
	7	parking lots, good condition, signage less visible,								
		perimeter is well secured but needs updates								
	5									
		Very satisfactory - Signage, parking lots, and entries are								
		well lit, visible and easy to use, perimeter is very secure								
	N/A	Does not apply								
	ls the main	office located at the school entry and configured with a						Comments		
	4.3 secure vesti	bule to the main corridor?	<b>L_</b>					Comments		
	1	Very unsatisfactory - No secure vestibule, office located								)
		far from main entry, allows visitors access to school								)
		unsupervised								
	2	Unsatisfactory - No secure vestibule, office located								
		somewhat far from main entry, minimal supervision of								
	0	visitors								
	3	Average - Office close to entry, views of front door, but no secure vestibule								
	4	Satisfactory - Office is well-located with a secure								
	7	vestibule, but needs updates								
	5	Very satisfactory - Office well-located with secure								
		vestibule and all appropriate security features								
	N/A	Does not apply								
	Is there eno	ugh interior transparency for faculty to passively supervise				1				
	11	d their activities who are not in studios?	1					Comments	1.00	1.00
ļ	1	Very unsatisfactory - No transparency of walls		L .				Small windows in doors but not enough visibility into		1.00
	2							Sitial windows in doors but not enough visibility into	corridors.	
		Unsatisfactory - Limited transparency in certain locations								
	3	Average - Good transparency in certain locations but								
		inadequate or missing in other locations of school								
	4	Satisfactory - Adequate transparency throughout the								
	_	school								
	5	Very satisfactory - Excellent transparency throughout the school								
	N/A	School  Does not apply								
	IN/A	bocs not apply								

Perkins&Will 02/11/2022 <sup>6</sup>

	5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	68%
	5.1 How are ac	coustics in studios in general?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
	5.2 Is the studio	o artificial lighting adequate quality?			3				Comments	1.00	3.00
,	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
	5.3 Is there acc	ess to natural light in studios?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							Not all studios have windows; some are internal in th	e building.	
		Does not apply ess to outside views from learning spaces?				1			Comments		
	5.4 is there acc	Very unsatisfactory - No learning spaces have views				4			Comments	1.00	4.00
	2 3 4 5	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out  Average - 26-50% of learning spaces have views  Satisfactory - 51-75% of learning spaces have views  Very satisfactory - 76-100% of learning spaces have views  Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	ouilding have odor or pest problems?			3				Comments	1.00	3.00
1	Very unsatisfactory - Evidence of both pests and odors	•		•			•			
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	4	12.50	60%
6.1 Does the s	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shade:	s provided to control natural light in learning spaces?			3				Comments	1.00	3.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
1	Very unsatisfactory - Single switch only per room							Some spaces in older areas have single switches; oth	ers have altern	ating
2	Unsatisfactory - Alternating rows switch off							rows and dual controls. Many spaces appear to have	e new updated	LED
3	Average - Alternating lamps in single fixtures switch off							lighting and modern controls.		
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, F	ixtures & Equipment	1	2	3	4	5	N/A	4	18.75	64%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
1	Very unsatisfactory - Damaged or broken, non-			•				Mix of old and new throughout, mostly in good condi	tion.	
	functioning									
2	Unsatisfactory - Torn/ bent/ wrong size									
3	Average - Scratched/dented/marked									
4	Satisfactory - Not new, but sturdy and clean									
5	Very satisfactory - New									
N/A	Does not apply				1	1	1	T		
_ Are a varie	ety of furniture types being accommodated throughout the									
1')	arning commons, dining commons, other multi-use spaces?		2					Comments		
									1.00	2.00
1	Very Unsatisfactory - Same furniture used in all spaces							Library has a minimal amount of lounge-type furnitur	-	
2	Unsatisfactory - Furniture variety in one multi-use space							tables and chairs. Cafeteria has only attached seat a	nd tables optio	n.
3	Average - Furniture variety in more than one multi-use									
	space									
4	Satisfactory - All multi-use spaces have greater than one									
5	type of furniture  Very satisfactory - All multi-use spaces have greater than									
3	two types of furniture									
N/A	Does not apply									
7.2 How well o	does furniture accommodate rapid reconfiguration of a			3				Comments		
7.3 space?				3				Comments	1.00	3.00
1	Very Unsatisfactory - Furniture is fixed or very heavy							Some library furniture is bulky and dated; the rest is o	n casters and h	nighly
2	Unsatisfactory - Furniture does not allow desks to be							flexible. Studio furniture is mostly desks and chairs the	at are easy for	
	configured as individuals, small groups, or large groups							students to move.		
3	Average - Mix of furniture that can reconfigure but is									
4	cumbersome to move Satisfactory - Furniture is flexible for multiple									
7	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
	configurations of space, easy to move and stack									
N/A	Does not apply									
7.4 Is the furni	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
1	Very unsatisfactory - Desk with attached chair									
	combinations too small for grade level									
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4	Very satisfactory - Tables with loose chairs									
5	Very satisfactory - Tables with loose chairs that allow									
Ĭ	students to be active									
N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>9</sup>

Waste	1	2	3	4	5	N/A	5.00	30%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?		2					Comments 0.50	1.00
<ol> <li>Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.</li> <li>Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.</li> <li>Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.</li> <li>Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.</li> <li>Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.</li> </ol>							A score for this category is being recorded, but this category is no calculated in the overall ESA average.	t
N/A Does not apply  Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?	1						Comments 0.50	0.50
<ol> <li>Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.</li> <li>Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.</li> <li>Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.</li> <li>Satisfactory- There are several waste stations as described above</li> <li>Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.</li> <li>N/A Does not apply</li> </ol>				,				



# **Austin ISD Educational Suitability Assessment Criteria**

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Martin Middle School	Emilie Ogburn and Vishwesh Panchal	1.21.2021

8 - 8	Academics 8	& Learning	1	2	3	4	5	N/A	Α	65.00	46%
8.1	Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility,			'				Studios are undersized by about 150 square feet in so	me rooms, pe	r the ed
		disconnected							spec. Storage is very limited.		
	2	Unsatisfactory - Too small, only one area for all teaching									
		methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different									
		teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different									
	7	teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
		spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous									
		display area and visual teaching tools, excellent									
		transparency and connection with other studios and									
	N1/A	shared learning spaces									
	N/A	Does not apply		1				1	T		
8.2	ed spec?	nave appropriate support spaces such as storage per the		2					Comments	1.00	2.00
	ea spec :	Very unsatisfactory - None provided							Standard studie angese only baye one tall storage on		2.00
	2	, ,							Standard studio spaces only have one tall storage cal	binet.	
		Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A										
	11/ /	Does not apply									

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
0.0	Do typical le	earning neighborhoods have small and medium (high	,								
8.3		group rooms and open collaboration space?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
0.4	Are Science	Labs and support spaces appropriately configured per			0						
8.4	the ed spec	?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated science room							5 science labs connected with access to undersized, a	aged prep roor	ns;
	2	Unsatisfactory - Too small, poor condition, no connected							some rooms in poor condition and slightly undersized	d. 2 small lab-ty	уре
		support space							spaces upstairs.		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected support spaces									
	N/A	Does not apply		,				,	<u></u>		
8.5		Spaces and support spaces appropriately configured per	1						Comments		
0.0	the ed spec	? (cross reference with CTE below)								1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces							CTE lab in Room 301 doubles for this, but no other de	edicated studio	for
	2	Unsatisfactory - Too small, poor condition, disconnected							maker space is present.		
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>3</sup>

8 - Academics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6 Is there a P	rofessional Learning Center in the learning neighborhood?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected							303 appears to be a very large shared supply storag offices/work areas for teachers to utilize, not centrall		oarate
	dequate places to display the evidence and artifacts of oth 2D and 3D)?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply							3D display throughout; very few tackboard opportun corridors.	ities for 2D dis	play in
Does the b	uilding / learning neighborhood provide adequate les for students/teachers to collaborate in varying group	1						Comments	1.00	1.00
1 2 3 4 5 N/A	Very unsatisfactory - No space to support collaboration in various sizes.  Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes  Average - Adequate space for collaboration, needs updates or renovations to function well.  Satisfactory - Good size, good condition, multiple options to support a variety of group sizes  Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes  Does not apply									
8.9 Does the b	uilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							Limited furniture in outdoor spaces; interior corridors confusing for added furnishings.	are too narrov	w and

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.10	Does the bu	uilding provide adequate opportunities for students to endently?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply									
	Special Edu	cation									
8.11	Are Special spec?	Education spaces appropriately configured per the ed				4			Comments	1.00	4.00
	1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected  Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected  Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.  Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces  Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							Room 106 has life skills. Suite of studios for special ed accessible restroom with shower, and washer and dr another studio. Not all connected but grouped toget disconnected from the rest of the teaching spaces.	yer are located	
	N/A Are Special	Does not apply  Education support spaces, such as storage, space for		l		l					
8.12	•	er, appropriately configured per the ed spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.13		ble restrooms and changing rooms readily available to the					5		Comments	1.00	
	Special Edu	ucation spaces?								1.00	5.00
	1 5	No V									
		Yes									
	STEAM Cen	ter								1	
8.14	Does the ca	ampus have space to support a "STEAM" center?	1						Comments	0.00	0.00
	1	Very unsatisfactory - No available space for STEAM							Monitoring answer, but does not count toward overc	all score	
	0	center and inadequate studio / collaborative space									
	2	Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size									
	3	Neutral - Collaborative areas / studios for CTE/CCL are									
	U	adjacent but function separately									
	4	Satisfactory - Collaborative areas / studios for CTE/CCL									
		function and have space availability to create STEAM									
		center									
	5	Very Satisfactory - Functioning STEAM center offers									
		studios, labs, common collaborative areas to support									
		multimedia distance and hands-on project based									
		learning									
	N/A	Does not apply									
9 - C		reer Connected Learning								16.25	63%
9.1		is your campus to a CTE cluster pathway that is aligned ITE programs (Middle School only)?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No correlation to CTE cluster							Careers in Technology is current pathway. Have heal	th science/nur	sing
		pathway, no CTE programs.							and photography. Will move to engineering/digital r	nedia next yec	ar.
	2	Unsatisfactory - School supports less than half of the CTE									
	3	programs that are listed in the cluster pathway.									
	3	Average - School support half of CTE programs listed in the cluster pathway, but missing some.									
	4	Satisfactory - School support a majority of CTE programs									
	-	listed in the CTE cluster pathway.									
	5	Very Satisfactory - School is aligned with CTE cluster									
		pathway.									
	N/A	Does not apply									
	Do campus	facilities align with the CTE Ed Spec Requirements for the									
9.2	•	hways offered?: Architecture and Construction						N/A			
		·								0.00	0.00
	1	No									
	5	Yes									
	N/A	Does not apply									
9.3	Arts, Audio	and Video Technology and Communications					5			0.25	1.25
9.4	Business, M	lanagement and Administration	1							0.25	0.25
9.5	Education a	and Training	1							0.25	0.25
9.6	Health Scien	nce					5			0.25	1.25
										0.20	0

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism	1						0	.25	0.25
9.8 Human Services (high school only)						N/A	0.	.00	0.00
9.9 Information Technology					5		0	.25	1.25
9.10 Agriculture, Food and Natural Resources	1						0	.25	0.25
9.11 Science, Technology, Engineering, and Mathematics					5		O	.25	1.25
9.12 Transportation, Distribution and Logistics	1						C	.25	0.25
9.13 Finance (high school only)						N/A	0.	.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)	5					N/A	0.	.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						N/A	0.	.00	0.00
9.16 Manufacturing (high school only)						N/A	0.	.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A	0.	.00	0.00
10 - Visual and Performing Arts							35.	.00	60%
10.1 Is there flexibility of space to also be used by CTE and Athletics?					5		Comments 0.	.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
10.2 Are band and support spaces (rehearsal and storage) appropriate configured per the ed spec?	ely			4				.00	4.00
<ol> <li>Very unsatisfactory - Too small, missing program space</li> <li>Unsatisfactory - Too small, poor condition</li> <li>Neutral - Adequate size, adequate condition, needs updates or renovations to function well.</li> <li>Satisfactory - Good size, good condition</li> <li>Very Satisfactory - Generous size, excellent condition</li> </ol>							Large and small band hall present, both adequately sized ar condition. Only two practice rooms available. Storage, librar office present.	_	
N/A Does not apply  10.3 Are orchestra and support spaces appropriately configured per the ed spec?	е		3				Comments 1.	.00	3.00
1 Very unsatisfactory - Too small, missing program space 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply		,	- 1				Space is undersized but has appropriate office and storage sone practice room.	paces.	Only

10 - Visual and	l Performing Arts (cont.)	1	2	3	4	5	N/A	A		
10.4 Are choir a spec?	nd support spaces appropriately configured per the ed			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Space is undersized, has office and storage. No practic	e rooms. Pro	jection
2	Unsatisfactory - Too small, poor condition							and screen and mobile TV display.		
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply						1			
10.5	and support spaces appropriately configured per the ed	1						Comments	1.00	
spec?								No days a second	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces							No dance on campus.		
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
4	updates or renovations to function well.									
5	Satisfactory - Good size, good condition									
N/A	Very Satisfactory - Generous size, excellent condition  Does not apply									
Are theater	r and support spaces appropriately configured per the ed		l							
10.6 spec?		1						Comments	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces		ı				<u> </u>	No theater on campus.		
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply						1			
10.7	arts and support spaces appropriately configured per the				4			Comments		
ed spec?									1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces							Drama room appears to be in 309; small stage in room		is art;
2	Unsatisfactory - Too small, poor condition							has spray booth with ventilation, adequate storage an	a a kiin.	
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5 N/A	Very Satisfactory - Generous size, excellent condition									
IN/A	Does not apply	l								
	ampus have adequate space for the specialty arts					5		Comments		
programs (	Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments	1.00	5.00
1	No							<u> </u>	1.00	0.00
5	Yes									

11 - Athletics and Wellness							18.75	63%
11.1 Does the campus meet ed spec standard for physical education program spaces?		;	3			Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply						Large and small gyms are appropriately sized and in a Stage was converted into a weight room and storage outdoor athletics areas. Coach Garcia mentioned issu under the floor and having to remove and replace the times over the last few years.	; well-connectes with moist	ted to ure
11.2 Does the campus have a dedicated wellness center?	1					Comments	0.50	0.50
1 No 5 Yes						No dedicated programs or rooms.		
11.3 Does the community have access to exterior playfields/courts?				5		Comments	0.50	2.50
1 No 5 Yes								
11.4 Are facilities available to facilitate eSports (High School only)?					N/A	Comments	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?				5		Comments	0.25	1.25
1 No 5 Yes								
11.6 Are facilities set up to support UIL sanctioned athletics for track?	1					Comments	0.25	0.25
1 No 5 Yes						Not a full sized competitive track.		
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1					Comments	0.25	0.25
1 No 5 Yes						No football field.		
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?				5		Comments	0.25	1.25
1 No 5 Yes								
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?				5		Comments	0.25	1.25
1 No 5 Yes						No court lighting.		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?	1					Comments	0.25	0.25
1 No 5 Yes	•			-		Soccer field adajcent to campus but is city property.		

Perkins&Will 02/11/2022 <sup>9</sup>

11 - Athletics and Welln	ess (cont.)	1	2	3 4	5	N/A			
	ed storage) set up to support UIL sanctioned ntry (high school only)?					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.12 Are facilities (dedicate athletics for golf (high	ed storage) set up to support UIL sanctioned school only)?					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.13 Are facilities (dedicate athletics for swimming	ed storage) set up to support UIL sanctioned g (high school only)?					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.14 Are facilities set up to (high school only)?	support UIL sanctioned athletics for wrestling					N/A	Comments	0.00	0.00
1 No 5 Yes									
(high school only)?	support UIL sanctioned athletics for baseball					N/A	Comments	0.00	0.00
1 No 5 Yes									
(high school only)?	support UIL sanctioned athletics for softball					N/A	Comments	0.00	0.00
1 No 5 Yes									
	ed space outside of the gymnasium) available to pirit activities for cheerleading and drill team?				5		Comments	0.25	1.25
1 No 5 Yes									
11 - Athletics and Welln		1	2	3 4	5	N/A			
	ields align with FMP Campus Improvements? lighting, ADA accessible amenities (high School					N/A	Comments	0.00	0.00
l Very uns	atisfactory - No turf, inaccessible, no site lighting						Monitoring answer, but doesn't affect overall score.		
	actory - No turf/field in poor condition, some lity concerns, poor site lighting								
_	- Field in adequate condition, needs some or renovations to function well								
	ory - Turf field in good condition, good ADA nd site lighting								
5 Very Sati excellent	sfactory - Turf field with excellent maintenance, ADA access for spectators and athletes, site lighting								
N/A Does not									

Perkins&Will 02/11/2022 10

12 -	Food Servi	ces							1	10.00	60%
12.	ls the Dinin	g Commons appropriately configured per the ed spec?				3			Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply							Cafeteria is undersized; good connection to central courty outdoors; minimal windows and natural light.	ard and	
12.2	Are the Foo	od Services support spaces appropriately configured per			Ι,	3			Comments		
12.2	the ed spec	??			,	3			Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Two serving lines and kitchen is undersized.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
13 -	Media Res	ources	1	2	3	3 4	5	N/A	3	80.00	50%
13.	ls the Librai visitors to tl	ry/Media Center easily accessible for the occupants and the school?			3	3			Comments	1.00	3.00
	1	Very unsatisfactory - Not accessible							Library is near admin area and main studio wings; some vis	sibility, ver	ry
	2	Unsatisfactory - Limited access, difficult to find, no							undersized; connected to the outdoor courtyard.		
		transparency									
	3	Average - Adequate accessibility, needs updates or renovations to function well									
	4	Satisfactory - Accessible, easy to find, good									
	4	transparency, good condition									
	5	Very Satisfactory - Accessible, easy to find, excellent									
	v	transparency, excellent condition									
	N/A	Does not apply							L		

13 - Media Resou	rces - Continued	1	2	3	4	5	N/A	4		
13.2 How well does	the Library/Media Center support quiet study?	1						Comments	1.00	1.00
2 U ar 3 A or 4 Sa ca 5 V ar ar	ery unsatisfactory - No quiet study spaces insatisfactory - One area in poor condition, poor coustic privacy verage - One or more areas provided, needing updates r renovations to function well atisfactory - Clusters or small rooms adjacent to media enter, good condition, good acoustic privacy ery Satisfactory - Multiple clusters or small rooms djacent to media center, excellent condition, excellent coustic privacy							Space is small and doesn't allow for much separation	n of areas.	
	the Library/Media Center support social interaction?		2					Comments	1.00	2.00
2 U ft 3 A oi 4 Si ft 5 Vi	ery unsatisfactory - No space Insatisfactory - Too small, poor condition, layout and Jurnishings do not support informal interaction well Inverage - Adequate size and condition, needs updates In renovations to function well. In atisfactory - Good size, good condition, layout and In Jurnishings support informal interactions In a size of the service o							Mostly formal seating; few opportunities for lounge s interaction.		
How well does	the Library/Media Center support collaborative work						I			
13.7	s (4-8 students)?			3				Comments	1.00	3.00
5 V: N/A D	ery unsatisfactory - No breakout rooms, no flexible urniture, no support insatisfactory - Too small, one area, poor condition verage - Adequate size, multiple areas provided, eeding updates or renovations to function well atisfactory - Clusters or small rooms adjacent to media enter, flexible furniture, good condition ery Satisfactory - Multiple clusters or small rooms djacent to media center, flexible furniture, excellent ondition							More tables than stacks so groups can be more sprea	ad out in the ro	om.
13.5 How well does in larger group	the Library/Media Center support collaborative work as (10-25)?			3				Comments	1.00	3.00
2 U se 3 A u <sub>l</sub> 4 So se 5 V	ery unsatisfactory - No gathering areas insatisfactory - Too small, one common space, limited eating, poor condition verage - Adequate size, one common space, needs pdates or renovations to function well atisfactory - Good size, multiple common spaces with eating, good condition ery Satisfactory - Generous size, multiple commons							One large common space for gathering.		
	paces with seating, excellent condition loes not apply									

13 - Media Res	ources - Continued	1	2	3	4	5	N/A			
13.6 How well de	oes the Library/Media Center support technology?			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition				•			2 projection screens present, charging carts, 2 mobile markerboard; a few power towers for charging at tak the room.		
N/A  14 - Technology	Does not apply	1	2	3	4	5	N/A		20.00	40%
	quipped are the facilities with instructional technology?	Ċ			4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition							Charging carts in some spaces. All studios have projectished	ction and mob	oile TV
N/A  Is there and spaces?	Does not apply adequate number of power and data outlets in learning	1						Comments	1.00	1.00
1 2	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)						1	Outlets are sparse in studios and some are so dated t in.		
3	Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall)									
5 N/A	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)  Does not apply									

y (cont.)	1	2	3	4	5	N.	I/A
dequate charging locations for devices?		2					Comments 1.00 <b>2.0</b>
Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.							Charging carts are scattered. Outlets are not in good condition in some spaces.
Does not apply	1	1					
equate AV for presentations spaces – cafeteria, gym, aux	1						Comments 1.00 <b>1.0</b>
space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.							No projector or screen in cafeteria; large screen and mobile projector in large gym, none in small gym.
ital media signage at the reception area?	1						Comments 0.00 <b>0.</b>
Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition				-1		1	Mobile TV display in reception, no permanent digital signage.
	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  Ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate condition  Satisfactory - Adequately sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  Ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Excellent condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Excellent condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  1  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average  Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  1  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition Satisfactory - Undersized / poor condition OR undersized / adequately sized / poor condition OR undersized / adequately sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices  Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition  Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average  Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  1  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Satisfactory - Media signage present, good sized, good condition

15 - Administration Spaces	1	2	3	4	5	N/A		20.00	45%
15.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments		
Very unsatisfactory - No security checkpoint				•	•				
2 Unsatisfactory - Checkpoint is too small, poor condition									
Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
15.2 Does the administration area feel welcoming?		2					Comments	1.00	2.00
<ol> <li>Very unsatisfactory - No welcome space</li> </ol>							Waiting space in reception area is limited.		
<ol><li>Unsatisfactory - Too small, poor lighting and</li></ol>									
transparency, limited informal seating, poor condition									
3 Average - Adequate size and layout, needs updates or									
renovations to feel welcoming 4 Satisfactory - Good size and layout, good lighting and									
4 Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of									
light and transparency, informal seating provided,									
excellent condition									
N/A Does not apply									
For those spaces that require it, does the administration area have			3				Comments		
adequate acoustic privacy?			3	,			Comments	1.00	3.00
<ol> <li>Very unsatisfactory - No acoustic separations</li> </ol>		-		•	-	-			
Unsatisfactory - Acoustic separations do not perform									
well									
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations 5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply		l			1	1			
15.4 Are conference rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
Very unsatisfactory - Not accessible for public/parent			<u> </u>		<u> </u>		One conference room in admin suite, not clearly identi		
use									
2 Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition  N/A  Does not apply									
14/A Does not apply									