



Educational Suitability Summary Report

Mendez Middle School

Date: 01/18/2021

Score 62% Average

Mendez Middle School, serving an enrollment of 580 students in southeast Austin, was built in 1987 and consists of 173,000 square feet on a 21-acre site. It is known for its project-based learning and STEM curriculum and is the only school in the district that has KickStart Kids, a program to teach character through karate. This is a popular and growing program at the school. The school is composed of three stand-alone buildings – the main building, performing arts building and a CTE/art shop building.

The school utilizes a block schedule where classes are 90-minutes in length. This allows for teachers to create more intensive projects and necessitates labs with more flexibility in studio spaces than currently exists.

The outdoor spaces need improvements to work well for outdoor learning. The school has ample space for these activities, but will need upgrades to infrastructure such as seating, electrical and shade. The interior of the building has murals dedicated to the school that show school pride, but in general there is a lack of color, ambience or display to highlight the school's programs.

The main entry is between two large studio wings that are two levels. The main lobby is a doubleheight space with a large stair in the middle to the second floor. During a normal school year, this space is used as an informal hangout space and is well-utilized.

Interview Overview

The interview took place virtually with Principal Rowley, who has been at Mendez for three years. She consulted with teachers and staff to go over the questionnaires, and she conveyed their answers during the meeting. She noted that the school has received few upgrades over its 30-year lifetime and would like the campus to reflect their mission in project-based learning and as a STEM academy. She wants the community to realize "this is the new Mendez."

The school is proud of a few items on campus that should be kept due to campus/community importance. The murals throughout the school are a mixture of old and new done by students and local artists and are well-loved. There are the gardens and pillars, 30 fruit trees, a chicken coop and an exterior mosaic that all should be kept. The students have to carry five-gallon buckets of water to the fruit trees, so having a water source close to the trees is a high priority.

The school has a KickStart Kids karate class that is being taught in a typical studio. The room needs mirrors, more windows for ventilation and a dedicated dressing room. This program is in its fourth year and is the only one of its kind at an AISD middle school. The program currently has 160 students, and 40 students are on a waiting list. The dance program uses the small gym and needs a dedicated studio with mirrors. They would also like to have an outdoor space for dance.

The parent support specialist serves an important role in the campus. Her space moves around each year depending on available studios. Working out of a typical studio does not meet the program's needs. There needs to be a dedicated office, studio setup for family training with appropriate technology and kitchenette, and ideally would have its own restroom and be close to an exterior door.

Outdoor studios are high on the teachers' priority list. As a school that promotes project-based learning, they would like an outdoor studio with shade, seating, whiteboard and adequate electrical support. The science labs, which are original to the building, are in one area of the school, and it would be ideal to have science labs throughout the school for each grade level. A dedicated maker space is also on the list. Additional outdoor features such as a cistern would create learning opportunities. The project-based learning curriculum has learning labs, and the school does not have any spaces that allow for small groups to meet or a space to provide group testing.

They would also like more staff restrooms. There are no adult restrooms in the performing arts wing and only one upstairs in the main building. Professional learning centers are in a typical studio, and they would like dedicated PLCs with large whiteboard walls. They would like to add a mariachi band program. The tennis courts have many cracks and are mostly unusable. The football field has many holes and is not safe for students to use. The coaches must fill the holes to play soccer matches on the field. The mindfulness suite is in a typical studio with previously used couches and does not have controllable lighting.



Assessment Findings

The Educational Suitability Assessment of Mendez Middle School earned a 62% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

General Building

Score is unsatisfactory.

The general appearance of the building is in good condition. Corridors are very satisfactory at 12 feet wide. A separate theater building allows for after-hours functions and presentations. The gym can be accessed after-hours as well. There is no dedicated community room.

CTE and Career Connected Learning

Score is unsatisfactory.

Mendez feeds into Akins and Travis high schools. These high schools offer every CTE program, and Mendez only offers coursework in STEM and Hospitality and Tourism.

Educational Suitability Summary Report

Mendez Middle School

Average Categories (51-65%):

Security

Score is average.

Furniture, Fixtures, Equipment

Score is average.

Furniture is in average condition. There is a variety of furniture types in the studios and library. Some studios have fixed tables and chairs, but the school noted that these are being phased out.

Academics & Learning

Score is average.

Typical studios are undersized and have no connection to group study rooms or collaboration spaces. There is no transparency between studios and the hallways. There are dedicated science rooms, CTE and special education rooms. Life skills studio needs updates to accessible restroom. Science labs are in only one area of school and need updates to function well.

Visual and Performing Arts

Score is average.

The performing arts program is in a separate building and has a well-maintained auditorium. The stage is a good size but does not have dedicated stage storage or a sink. The dance program uses the gym and does not have a dedicated studio with mirror. There is an orchestra program, but the school does not offer choir.

Athletics and Wellness

Score is average.

Both gyms are in adequate condition and have the proper supporting spaces such as a weight room. Large gym has bleachers on one side of gym, and small gym is undersized. The outdoor athletic amenities need improvement.

Food Services

Score is average.

The size of the prep area is adequate. The cafeteria space appears small for the enrollment. There is limited daylight in the cafeteria and limited connectivity to outdoor spaces or the adjacent lobby. The cafeteria has one type of seating.

Administration Spaces

Score is average.

The administration space is adjacent to the main entrance. The teachers' lounge is connected to the administration area. Acoustic privacy is an issue between offices and staff.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is very unsatisfactory.

There are limited outdoor learning experiences and spaces, and there is no shade provided in most of the outdoor spaces. The garden is adequate but needs better support spaces to function well. No cistern was observed. The fruit tree orchard needs a nearby source of water.

Environmental Quality

Score is satisfactory.

There were no visible rodents or pests and no odors during the assessment. The principal indicated there have been roach issues in the past. All studios have access to windows and natural daylight. The CTE building has small, limited windows and no transparency to other spaces.

Controllability of Systems

Score is satisfactory.

Studios have their own thermostats and two-switch lighting controls. Windows have blinds to help with the natural lighting.

Media Resources

Score is satisfactory.

Library is on the second floor and allows for small and large group configurations. There is one breakout room. There are adequate technology setups.

Technology

Score is satisfactory.

Studios are equipped with portable screens and projector screens. There are approximately three outlets per wall for charging but no charging towers. Gym A/V appears dated and not in adequate condition.

Very Satisfactory Categories (81-100%):


Exterior

Score is very satisfactory.

Canopies are provided between the main, CTE and Fine Arts buildings. Site has separation between vehicular and bus areas. The entrance has a large canopy to provide shelter, but the expansive concrete and lack of landscaping make the school feel unwelcoming. All three dumpster – trash, recycling and composting – are provided adjacent to cafeteria.

Educational Suitability Summary Report

Mendez Middle School




The school's entry is a generous, double-height daylit space. During a typical school year, the school provides couches and informal hangout space for students in this area.




Corridors are generous in width but are long with limited daylight. Lockers are not used and run throughout the main corridors.

Educational Suitability Summary Report

Mendez Middle School



Life Skills Restroom: Shower does not function, and room is inaccessible due to changing table in the center.




Media Center: Library is on second floor at main entry and has areas for different groups to meet. Furniture is bulky and not conducive to reconfiguration. A few pieces of furniture (not pictured) have been upgraded and are new.

Educational Suitability Summary Report

Mendez Middle School

Supporting Photographs



Cafeteria offers no flexibility in seating options and only a few windows allow for natural daylight. Cafeteria is undersized for campus capacity.

Educational Suitability Summary Report

Mendez Middle School



Studios are undersized and are on both sides of the double-loaded main corridor. There are no breakout or collaboration spaces provided near the studios.



Visual art studio in CTE building is in adequate condition with needed support space.

Educational Suitability Summary Report

Mendez Middle School



Auditorium is in satisfactory condition. Stage area does not have storage or a scene shop. There is no sink in the vicinity.



Main entry has covered canopy leading to fine arts building on the right. Glazing at main entry is limited to entry doors. There is hardscape all around the entry, which makes the entry feel unwelcoming.

Educational Suitability Summary Report

Mendez Middle School



Secured courtyard in back of school is adequately sized but needs shade and updated furniture to function well.



Pillars and garden are beloved by the school but require updates to function well.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:	
Mendez Middle School	Carlos Cruz and Lynn Petermann	1.18.21	

1	- Ex	terior		1	2	3	4	5	N/A		8.75	86%
	1.1	Does the signal pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen									
			at the same location									
		2	Unsatisfactory - Cars and buses mix, pedestrians are									
		0	separated									
		3	Average - Buses, cars, and pedestrians are separate but									
		4	stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place									
			like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are									
		Ū	separate and drop off area has a canopy and									
			destination									
		N/A	Does not apply									
	1.2	Is the build	ing easily identified with appropriate signage and				4			Germante		
	1.2	community	wayfinding?				4			Comments	0.25	1.00
		1	Very unsatisfactory - Campus has no signage /									
			wayfinding									
		2	Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not									
			good condition									
		5	Very satisfactory - Signage and wayfinding is visible									
			and easy to use									
		N/A	Does not apply									

02/11/2022 ²

Exterior (cont.)		2	3	4	5	N/A			
.3 Is the dumpster accessible for trash / compost disposal?					5		Comments	0.50	2.
 Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free 							All located outside of cafeteria.		
 Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it. 									
N/A Does not apply									
- Outdoor Learning and Activity	1	2	3	4	5	N/A	A Contract of the second se	10.00	7
Are outdoor studios and support spaces appropriately configured per the ed spec?		2					Comments	1.00	2
 Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided 							The Austin Energy solar charge area was the only pla outdoor learning.	ce observed fo	or
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area 									
5 Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
N/A Does not apply				1	1	1			
Are active playgrounds (elementary only) and support spaces configured per the ed spec?						Na	Comments	0.00	0
1 Very unsatisfactory - No dedicated active playground	L	L	1	1	1	1		0.00	0
2 Unsatisfactory - Too small, poor condition, no shade provided									
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
4 Satisfactory - Good size, good condition, more than 50%									
shade coverage over play structure									

02/11/2022 ³

	Learning and Activity (cont)	1	2	3	4	5	N/A			
2.3 Are gard spec? (e	lens and support spaces appropriately configured per the ed valuation on infrastructure not condition of plants)		2					Comments	0.00	0.0
1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							The garden is adequate, but needs better support sp No cistern. The fruit tree orchard needs a source of w answer, does not affect score for Outdoor Learning o	ater. (Monitori	
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
N/A	Does not apply									
2.4 Are the r ed speci		1						Comments	0.00	0.0
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoo	r Learning and	
2	Unsatisfactory - Too small, poor condition, not							Activity.		
	functioning, disconnected									
3	Average - Adequate size, adequate condition, is									
	connected, needs some renovations or updates to									
	function well									
4	Satisfactory - Good size, good condition, functions									
5	properly									
5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces,									
	educational signage provided									
N/A										
	e school have animal husbandry? (optional)	1				[Comments	0.00	0.0
1	No									
5	Yes									
2.6 Does the	e school have nature loop trails? (optional)	1						Comments	0.00	0.0
1	No									
5	Yes									
2.7 Does the	e school have a learning pond? (optional)	1						Comments	0.00	0.0
1	No							·		
5	Yes									
2.8 Does the	e school have a grass play field and walking trail?					5		Comments	1.00	5.0
1	No									
5	Yes									

General Building	1	2	3	4	5	N/A	A	11.25	4
Are interior circulation routes wide enough to safely and effectively					5		Comments		
accommodate student movement?					5		Comments	0.50	2.
1 Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							12-foot hallways		
wide									
2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A Does not apply									
Are community use areas arranged so that the school can allow night		2					Comments		
functions without full school access?		~					Commenta	0.75	1
1 Very unsatisfactory - Cafeteria, gym, and library cannot							Separate theater building allows for after-hours fund	ctions and	
be accessed after hours							presentations. Gym can be accessed after-hours.		
2 Unsatisfactory - Only one of the public spaces (Cafeteria,									
Gym and Library) can be accessed from parking and secured after hours									
3 Average - Only two of the public spaces can be accessed									
from parking and secured after hours									
4 Satisfactory - All of the public spaces can be accessed									
from parking and secured from the rest of the building									
but not individually									
5 Very satisfactory - Cafeteria, gym, and library can be									
accessed from parking and locked off from rest of									
campus for night/evening use with their own entrance									
N/A Does not apply									
ls there a community room that is a dedicated meeting space outside	1						Comments		
of school function?							Commente	0.75	0
1 Very unsatisfactory - No dedicated community room									
2 Unsatisfactory - Community room but within school									
function, no access after school hours 3 Average - Community room, moderate size, but need									
some renovations or updates to function well									
4 Satisfactory - Community room, good size /layout, meets									
needs /functions well									
5 Very Satisfactory - Community room, generous size, nice									
condition, functions appropriately outside of school									
function									
N/A Does not apply			1	r	1		1	[
Does the general appearance of the school convey pride for the			3				Comments	0.05	-
students and community?				I	L			0.25	C
Very unsatisfactory - General appearance is poor									
 Unsatisfactory - General appearance is aged but ok Average - General appearance is good 									
 Average - General appearance is good Satisfactory - General appearance shows pride in 									
4 Satisfactory - General appearance shows pride in campus and student works									
5 Very Satisfactory - General appearance shows pride in									
campus and student works and is welcoming to the									
community									
N/A Does not apply									

l - Security		1 2	2 3	3 4	5	N/A	/A1	6.25	
4.1 Does the fo	acility have key card access at all major entries?						Comments		-
1	Very unsatisfactory - No entries								
2	Unsatisfactory - 1/4 of major entries								
3	Average - 1/2 of major entries								
4	Satisfactory - 3/4 of major entries								
5	Very satisfactory - All of major entries								
N/A	Does not apply								
4.2 How adequ	uate is site lighting and security for the campus overall?						Comments		
1	Very unsatisfactory - No exterior lighting, no secure	1 1	-		1	1			
	perimeter								
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal								
3	Average - Lighting at all night-use entries and parking								
	lot, but poor condition. Security is moderate								
4	Satisfactory - Lighting at all night-use entries and								
	parking lots, good condition, signage less visible,								
	perimeter is well secured but needs updates								
5	Very satisfactory - Signage, parking lots, and entries are								
	well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply								
ls the main	office located at the school entry and configured with a						Comments		
4.3 secure vest	ibule to the main corridor?		_	_			Comments		
1	Very unsatisfactory - No secure vestibule, office located								
	far from main entry, allows visitors access to school								
0	unsupervised								
2	Unsatisfactory - No secure vestibule, office located								
	somewhat far from main entry, minimal supervision of								
3	visitors Average - Office close to entry, views of front door, but								
0	no secure vestibule								
4	Satisfactory - Office is well-located with a secure								
	vestibule, but needs updates								
5	Very satisfactory - Office well-located with secure								
	vestibule and all appropriate security features								
N/A	Does not apply								
Is there end	ough interior transparency for faculty to passively supervise		2				Comments		
4.4 learners an	nd their activities who are not in studios?	4	2				Comments	1.00	2
1	Very unsatisfactory - No transparency of walls								
2	Unsatisfactory - Limited transparency in certain locations								
3	Average - Good transparency in certain locations but								
	inadequate or missing in other locations of school								
4	Satisfactory - Adequate transparency throughout the								
	school								
5	Very satisfactory - Excellent transparency throughout the								
	school								_
N/A	Does not apply								

5 - Environme	ntal Quality	1	2	3	4	5	N/A	<u> </u>	25.00	809
5.1 How are a	coustics in studios in general?				4			Comments	1.00	4.0
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Sounds from the corridor can barely be heard in stua	lios	
5.2 Is the studi	io artificial lighting adequate quality?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there acc	cess to natural light in studios?				4			Comments	1.00	4.0
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply							The CTE building has small, limited windows	<u>.</u>	
-	cess to outside views from learning spaces?					5		Comments	1.00	5.0
1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views	L	1	1	L		L			

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	N		
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							None observed, but the principal mentioned they use	ed to have road	ches
6 - 0	Controllabi	lity of Systems	1	2	3	4	5	N/A	N Contraction of the second seco	12.50	68%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes				•					
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades Does not apply									
6.3	What is the	quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply							Some classrooms have single switch and other have t	wo switch.	

7 - Fi	rniture, F	ixtures & Equipment	1	2	3	4	5	N/A	<u> </u>	18.75	593
7.1	What is the	e current condition of the furniture?				4			Comments	0.75	3.0
	1	Very unsatisfactory - Damaged or broken, non-									
		functioning									
	2	Unsatisfactory - Torn/ bent/ wrong size									
	3	Average - Scratched/dented/marked									
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
	N/A	Does not apply		1		1	1	1			
	Are a varie	ty of furniture types being accommodated throughout the									
7.2		arning commons, dining commons, other multi-use spaces?		2					Comments		
										1.00	2.0
	1	Very Unsatisfactory - Same furniture used in all spaces							There is a variety of furniture types in the studios ar	nd library.	
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use									
		space									
	4	Satisfactory - All multi-use spaces have greater than one									
	5	type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply									
7.3	How well d	oes furniture accommodate rapid reconfiguration of a			3				Comments		
7.3	space?				S				Comments	1.00	3.0
	1	Very Unsatisfactory - Furniture is fixed or very heavy							Seats and desks are connected. Difficult to reconfig	ure. Typical for	most
	2	Unsatisfactory - Furniture does not allow desks to be							classrooms. Science rooms had loose chairs and tak	oles for quick	
		configured as individuals, small groups, or large groups							rearrangements.		
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple									
	-	configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple									
		configurations of space, easy to move and stack									
	N/A	Does not apply						_			
7.4	ls the furnit	ure ergonomic and size appropriate for grade level?			3				Comments	1.00	3.0
	1	Very unsatisfactory - Desk with attached chair					.				- / -
		combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									

02/11/2022 °

Zero Waste	1	2	3	4	5	N/A	<u> </u>	5.00	80%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?			3				Comments	0.50	1.50
 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. 							A score for this category is being recorded, but this co calculated in the overall ESA average.	itegory is not	
N/A Does not apply Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?					5		Comments	0.50	2.50
 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 			I					0.00	2.00
3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the 									
cafeteria that encourages recycling/composting. N/A Does not apply									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria


Academics - Middle School / High School

School Name	Walk Attendees:	Date:	
Mendez Middle School	Carlos Cruz and Lynn Petermann	1.18.21	

8 -	Academics	& Learning	1	2	3	4	5	N//	A	60.00	52%
8.] Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility,							Studios are undersized at 730-750 SF. Studios line do	uble-loaded c	orridor.
		disconnected							No collaboration or breakout space provided except	at main entry.	
	2	Unsatisfactory - Too small, only one area for all teaching									
		methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different									
		teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
		spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility,									
		generous display area and visual teaching tools,									
		excellent transparency and connection with other									
	N/A	studios and shared learning spaces									
-		Does not apply have appropriate support spaces such as storage per the	1	1		1		1		[
8.	2 ed spec?	nave appropriate support spaces such as storage per the			3				Comments	1.00	3.00
_	1	Very unsatisfactory - None provided						I	Just built-in cabinets	1.00	0.00
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
	3	updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	-	condition									
	N/A	Does not apply									

02/11/2022 ²

		& Learning (cont.)	1	2	3	4	5	N/A	·		
		learning neighborhoods have small and medium (high						Na	Comments		
scho	ool only	r) group rooms and open collaboration space?						Nu	Comments	0.00	0.0
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition									
		and flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply					1				
21		e Labs and support spaces appropriately configured per			3				Comments		
the e	ed spec	c?			0					1.00	3.0
	1	Very unsatisfactory - No dedicated science room							Plumbing around the edge. Storage between two st	udios. Good on	n size.
	2	Unsatisfactory - Too small, poor condition, no connected							Over 1200 s.f.		
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
		support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected support spaces									
	N/A	Does not apply							Γ		
		Spaces and support spaces appropriately configured per				4			Comments		
the e	ed spec	c? (cross reference with CTE below)							commenta	1.00	4.
	1	Very unsatisfactory - No dedicated maker spaces							Adequate space in CTE building		
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
									1		
	5	Very Satisfactory - Generous size, excellent condition,									
	5	5 1									



8 - Academics & Learning (cont.)	1	2	3	4	5	N/A	х		
8.6 Is there a Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
1 Very unsatisfactory - No dedicated space for Professional Learning Center		•		•					
2 Unsatisfactory - Too small, poor condition, disconnected									
3 Average - Adequate size, adequate condition, needs									
some renovations or updates to function well 4 Satisfactory - Good size, good condition, connected									
5 Very Satisfactory - Generous size, excellent condition,									
connected									
8.7 Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No dedicated space							Main lobby has display for 3D. Limited locations for 2	2D artifacts. Lin	nited
2 Unsatisfactory - Too small, non-dedicated, poor							display in CTE and fine arts building.		
condition 3 Average - Adequate size, adequate condition, needs									
3 Average - Adequate size, adequate condition, needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
Does the building / learning neighborhood provide adequate									
8.8 opportunities for students/teachers to collaborate in varying group		2					Comments		
sizes?								1.00	2.00
1 Very unsatisfactory - No space to support collaboration							Main lobby/library can accommodate groups, but w		•
in various sizes.							neighborhoods, no breakout spaces for informal inte	raction or grou	h
2 Unsatisfactory - Too small, inflexible, only one option,							study.		
does not support a variety of group sizes 3 Average - Adequate space for collaboration, needs									
updates or renovations to function well.									
4 Satisfactory - Good size, good condition, multiple									
options to support a variety of group sizes									
5 Very Satisfactory - Generous size, excellent condition,									
multiple options to support a variety of group sizes N/A Does not apply									
N/A Does not apply		1		1	1				
8.9 Does the building provide opportunities for informal interaction?			3				Comments	1.00	3.00
1 Very unsatisfactory - No space							Limited locations, such as main lobby, cafeteria, lobb	y, outdoor cou	urtyard.
2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well							Furniture doesn't promote this.		
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply							<u> </u>		

8 - A		& Learning (cont.)	1	2	3	4	5	N/A	A		
8.10	Does the bu work indep	ilding provide adequate opportunities for students to endently?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply							Disconnnected from studios and only one large space groups that are acoustically separate.	e. No spaces fo	or small
	Special Edu										
8.11	•	Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces Does not apply		<u> </u>					Typical studio size. Joined kitchen storage and restroo washer/dryer.		
8.12		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply		1					Kitchen and washer/dryer	1.00	4.00

8 - Academics & Learning (cont.)	1	2	2 3	4	5	N/A			
8.13 Are Accessible restrooms and changing rooms readily available to the Special Education spaces?	1						Comments	1.00	1.00
1 No 5 Yes						<u> </u>	Not fully accessible.		
STEAM Center									
8.14 Does the campus have space to support a "STEAM" center?					5		Comments	0.00	0.00
 Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning N/A Does not apply 		L				1	Monitoring answer, but does not count toward overa		
9 - CTE and Career Connected Learning								17.50	37%
9.1 How close is your campus to a CTE cluster pathway that is aligned with your CTE programs (Middle School only)? 1 Very unsatisfactory - No correlation to CTE cluster		2	2				Comments Mendez feeds into Akins/Travis high schools. Offers li	1.00	2.00 rses.
 pathway, no CTE programs. 2 Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway. 3 Average - School support half of CTE programs listed in the cluster pathway, but missing some. 4 Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway. 5 Very Satisfactory - School is aligned with CTE cluster pathway. 							Large program offerings in STEM and Hospitality/Tou additional programs have courses.	ırism. Not man <u>ı</u>	/
N/A Does not apply					1	1			
9.2 Do campus facilities align with the CTE Ed Spec Requirements for the current pathways offered?: Architecture and Construction	1							0.25	0.25
1 No 5 Yes N/A Does not apply							no course offering		
9.3 Arts, Audio and Video Technology and Communications	1						No course offerings.	0.25	0.25
9.4 Business, Management and Administration	1						No course offerings.	0.25	0.25
9.5 Education and Training	1						No course offerings.	0.25	0.25
9.6 Health Science	1						No course offerings.	0.25	0.25

02/11/2022 °

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism					5		Large participation	0.25	1.25
9.8 Human Services (high school only)						N/A		0.00	0.00
9.9 Information Technology	1						No course offerings.	0.25	0.25
9.10 Agriculture, Food and Natural Resources	1						No course offerings.	0.25	0.25
9,11 Science, Technology, Engineering, and Mathematics					5		Large participation	0.25	1.25
9.12 Transportation, Distribution and Logistics	1						No course offerings.	0.25	0.25
9.13 Finance (high school only)						N/A		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						N/A		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						N/A		0.00	0.00
9.16 Manufacturing (high school only)						N/A		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A		0.00	0.00
10 - Visual and Performing Arts								35.00	57%
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?				4			Comments	1.00	4.00
1 Very unsatisfactory - Too small, missing program spaces				<u> </u>			Band space and auxiliary band space. 3 practice roo	ms.	
 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition 									
N/A Does not apply Are orchestra and support spaces appropriately configured per the 10.3				4			Comments		
10.3 ed spec? 1 Very unsatisfactory - Too small, missing program spaces				+			Nice size and stage. No practice rooms.	1.00	4.00
 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 									

	10 - Visual and	Performing Arts (cont.)	1	2	3	4	5	N/A	N Contraction of the second seco		
	10.4 Are choir a spec?	nd support spaces appropriately configured per the ed	1						Comments	1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							Choir room and support spaces are undersized. Missi	ing program sp	baces.
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	10.5 Are dance spec?	and support spaces appropriately configured per the ed		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Dance is in gym but doesn't have mirrors		
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
	Ū.	updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	10.6	r and support spaces appropriately configured per the ed				4			Comments		
	spec?					4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces									
	2										
	2 3	Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs									
	5	updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
ľ	Are visual o	arts and support spaces appropriately configured per the		1		4			Comments		
	ed spec?					4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces									
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply						1	1		
	Does the co	ampus have adequate space for the specialty arts									
		Ensemble, Guitar, Music studies, Music theory and Piano)?	1						Comments		
										1.00	1.00
	1	No							No space for mariachi		
	5	Yes									

11 - Athletics and Wellness						18	8.75	63%
11.1 Does the campus meet ed spec standard for physical education program spaces?			4			Comments 1	1.00	4.00
1Very unsatisfactory - Too small, missing program spaces2Unsatisfactory - Too small, poor condition3Average - Adequate size, adequate condition, needs some renovations or updates to function well4Satisfactory - Good size, good condition5Very Satisfactory - Generous size, excellent conditionN/ADoes not apply						Small and large gym. Large gym is adequately sized. Small g undersized. Weight room. Good size locker rooms.	gym is	
11.2 Does the campus have a dedicated wellness center?	1					Comments	0.50	0.50
1 No 5 Yes								
11.3 Does the community have access to exterior playfields/courts?				5		Comments	0.50	2.50
1 No 5 Yes								
1].4 Are facilities available to facilitate eSports (High School only)?					Na	Comments 0	0.00	0.00
1 No 5 Yes						Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?				5		Comments	0.25	1.25
1 No 5 Yes								
1].6 Are facilities set up to support UIL sanctioned athletics for track?	1					Comments	0.25	0.25
1 No 5 Yes						Not a full size track.		
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1					Comments	0.25	0.25
1 No 5 Yes						Supports practice, but lacks spectator seating. Field is not a sized football fied.	regulatio	on
1.8 Are facilities set up to support UIL sanctioned athletics for volleyball?				5		Comments	0.25	1.25
1 No 5 Yes				1				
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1						0.25	0.25
1 No 5 Yes						Courts not in good shape		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?				5		Comments	0.25	1.25
1 No 5 Yes								

11 - Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
11.11 athletics for cross-country (high school only)?						N/A	Comments	0.00	0.00
1 No 5 Yes	-								
Are facilities (dedicated storage) set up to support UIL sanctioned athletics for golf (high school only)?						N/A	Comments	0.00	0.00
1 No 5 Yes	1							0.00	0.00
11.13 Are facilities (dedicated storage) set up to support UIL sanctioned athletics for swimming (high school only)?	Γ					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.14 Are facilities set up to support UIL sanctioned athletics for wrestling (high school only)?						N/A	Comments	0.00	0.00
1 No 5 Yes									
III.15 Are facilities set up to support UIL sanctioned athletics for baseball (high school only)?						N/A	Comments	0.00	0.00
1 No 5 Yes						T			
II.16 Are facilities set up to support UIL sanctioned athletics for softball (high school only)?						N/A	Comments	0.00	0.00
1 No 5 Yes		_				1			
11.17 Are facilities (dedicated space outside of the gymnasium) available to support competitive spirit activities for cheerleading and drill team?	1						Comments	0.25	0.25
1 No 5 Yes	1								
11 - Athletics and Wellness (cont.)	1	2	3	4	5	N/A			
How do the athletics fields align with FMP Campus Improvements? 11.18 Turf Field, Parking lot lighting, ADA accessible amenities (high School only)						N/A	Comments	0.00	0.00
Only in 1 Very unsatisfactory - No turf, inaccessible, no site lighting							Monitoring answer, but doesn't affect overall score.	0.00	0.00
2 Unsatisfactory - No turf/field in poor condition, some accessibility concerns, poor site lighting									
 3 Average - Field in adequate condition, needs some updates or renovations to function well 									
4 Satisfactory - Turf field in good condition, good ADA access and site lighting									
5 Very Satisfactory - Turf field with excellent maintenance, excellent ADA access for spectators and athletes,									
excellent site lighting N/A Does not apply.									

02/11/2022 °

2 - Food Serv	vices								10.00	60
2.1 Is the Dini	ng Commons appropriately configured per the ed spec?		2					Comments	1.00	2.0
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)				• •			Undersized by 3,000 SF for the campus capacity of 1 for current enrollment. One type of seating. Limited o connection to outside.	•	ely size
N/A	Does not apply	r –	r	1	1	1				
Are the Fo 2.2 the ed spe	bod Services support spaces appropriately configured per				4			Comments	1.00	4.(
1	Very unsatisfactory - None provided								1.00	4.
2	Unsatisfactory - Too small, disconnected, poor condition									
3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
8 - Media Re		1	2	3	4	5	N/A	х.	30.00	7
· X	ary/Media Center easily accessible for the occupants and the school?			3				Comments	1.00	3.
1 2 3 4 5	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition							On second floor.		

13 - Media Re	esources - Continued	1	2	3	4	5	N/A	<u> </u>		
13.2 How well	does the Library/Media Center support quiet study?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply							One breakout room		
13.3 How well	does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply									
	does the Library/Media Center support collaborative work groups (4-8 students)?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply				1	1		Open plan		
	does the Library/Media Center support collaborative work groups (10-25)?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply		L		L					

13 - Media Res	ources - Continued	1	2	3	4	5	N//	4		
13.6 How well d	loes the Library/Media Center support technology?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition Does not apply							Mobile screens and overhead projector		
14 - Technolog		1	2	3	4	5	N//	Δ	20.00	70%
	quipped are the facilities with instructional technology?				4			Comments	1.00	4.00
1 2 3	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school.							Screen and projector options		
4 5 N/A	Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition Does not apply									
	adequate number of power and data outlets in learning	1		3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									
N/A	Does not apply							L		

14 - Technolog	yy (cont.)	1	2	3	4	5	N/A	A	
14.3 Are there c	adequate charging locations for devices?			3				Comments 1.00	3.00
1	Very unsatisfactory - Not enough charging locations							There about 3 outlets per wall for charging but no charging towers	
	throughout school for 1:1								
2	Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices								
	locations, and inducquate in size for number of devices								
3	Average - Charging locations well organized but not								
	enough capacity for 1:1								
4	Satisfactory - Charging locations, haphazard locations,								
_	but supports 1:1.								
5	Very Satisfactory - Charging locations throughout school								
N/A	to support 1:1. Does not apply								
ls there ad	equate AV for presentations spaces – cafeteria, gym, aux		1			T			
14.4 gym?					4			Comments 1.00	4.00
1	Very unsatisfactory - AV not present in one or more							Gym A/V appears dated.	
	space								
2	Unsatisfactory - AV undersized for room. Poor condition								
3	Average - AV adequately sized / poor condition OR AV								
	undersized / average condition								
4	Satisfactory - AV adequately sized for room. Average								
	Condition.								
5	Very Satisfactory - AV adequately sized for room.								
	Excellent condition.								
N/A	Does not apply		r	1	1	T	1		
14.5 Is there dig	yital media signage at the reception area?	1						Comments 0.00	0.00
1	Very unsatisfactory - No digital media present in			1	1				
	reception area								
2	Unsatisfactory - Undersized, poor condition								
3	Average - Adequately sized / poor condition OR								
	undersized / adequate condition								
4	Satisfactory - Media signage present, good sized, good								
5	condition Very Satisfactory - Generously sized, excellent condition								
5	very outstactory - Generously sized, excendent condition								
N/A	Does not apply								

5 - Administre	ation Spaces	1	2	3	4	5	N/A		20.00	55
C 1	eception area that functions as a security checkpoint for all							Commonte		
D.I visitors?								Comments		(
1	Very unsatisfactory - No security checkpoint	•	•		•		•)		
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Cathifestana Candaine and deadhine									
4 5	Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
	Does not apply	1	1			1	1			
15.2 Does the administration area feel welcoming?					4			Comments	1.00	4.
1	Very unsatisfactory - No welcome space		1				1			
2	Unsatisfactory - Too small, poor lighting and									
-	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
N1/A	excellent condition									
N/A For those s	Does not apply paces that require it, does the administration area have	1	1	1	1	1	1	1	ſ	
E 2	acoustic privacy?		2					Comments	1.00	2.
1	Very unsatisfactory - No acoustic separations				I			The acoustic privacy is an issue between offices and		
2	Unsatisfactory - Acoustic separations do not perform							conversations.	stan. Stan can	mean
2	well							conversations.		
3	Average - Some acoustic separations function okay, but									
	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply									
E 4 Are confer	ence rooms easily accessed for public / parent use?	1						Comments		
5.4 Are conten	since rooms easily accessed for public? parent use:	1						Comments	1.00	1.
1	Very unsatisfactory - Not accessible for public/parent							None available		
	use									
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4										
4	Satisfactory - Good accessibility, good transparency,									
	good size and condition									
4 5										