

Educational Suitability Summary Report

Small Middle School

Date: 12/11/2020 Score 66% Average

Small Middle School serves an enrollment of approximately 1,180 students in southwest Austin and was built in 1999 with a total of 159,000 square feet. It is known for its Green Tech Academy. Students in this academy can choose coursework with an environmental emphasis, tech focus or a combination of the two. The "green" focus includes courses in agriculture, horticulture and landscape. The "tech" portion can be traditional CTE coursework, including photojournalism and media animation, or students can choose to participate in Project Lead the Way (PLTW), a national pre-engineering program. Currently, Small is the only AISD middle school that offers all 12 PLTW courses, which count as high school credit. PLTW continues at Austin High School, but there is not a pathway to continue the environmental studies portion.

The three-story campus sits on a large site surrounded by farm animals, nature trails and community soccer fields. The building has a great street presence and is very inviting. Although there is visible signage of the school from the street, circulation and drop-off are not well-defined or marked. Parent drop-off and bus drop-off are separated but no clear signage directing traffic and no covered walkways are present.

The campus has outdoor spaces for learning in a classroom setting or hands-on with the animals, greenhouse, gardens and ponds. Multiple cisterns and solar panels are on-site. The Green Tech Academy is very popular at Small and attracts students from across the district, but its dedicated suite is limited on space. The interior and exterior athletic amenities are all in good shape and support UIL competitions.

Interview Overview

The assessment team interviewed Principal Matthew Nelson. Principal Nelson emphasized how important the outdoor learning spaces and animal life are to Small Middle School. The campus enjoys large amounts of open space around the campus with ample room for field game play and support spaces for the animals. The school has animal enclosures for ducks, goats and sheep. The campus also has a large greenhouse, gardens and a pond. It was stressed that these outdoor spaces should never change.


Principal Nelson highlighted several programs needing larger or different space requirements on campus. Computer science/keyboarding was one of the first programs discussed. The current space utilized for this class is not large enough for 25 students, and the room only has one entry/exit point and no windows. They are considering ending this class next year due to lack of appropriate space and the current teacher's retirement. If this happens, Small will no longer be teaching all 12 of the PLTW courses.

Principal Nelson also noted that the performing arts spaces are undersized. The band hall is

Educational Suitability Summary Report

Small Middle School

insufficient to hold the entire band at one time. The campus would like to include a guitar class, but there is no room to teach the class or store guitars. The theater program does not have a dedicated space for rehearsals and performances because the stage is in the cafeteria and is in use for most of the day.



neighborhoods and incorporating them would benefit the teachers. The campus would like one PLC on each floor. Collaboration spaces within the corridors would be very beneficial. The teachers attempt to let the students use the corridors for group work, but the lack of flexible furniture prevents

Other wish list items include sit/stand desks, access to technology with portable power/internet connections throughout campus, and a dedicated community room for larger groups to collaborate. The only space on campus for larger groups or district meetings is the cafeteria, which is furnished with traditional cafeteria tables with attached seats.

Assessment Findings

it from being successful.

The Educational Suitability Assessment of Small Middle School earned a 66% overall score and places the campus in a category of Satisfactory. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Furniture, Fixtures and Equipment

Score is unsatisfactory.

The campus has little to no variety of furniture types. Furniture throughout is standard desk with attached chair or tables and chairs. This type of furniture is not easily reconfigurable or ergonomic and does not provide options for the students.

Average Categories (51-65%):

General Building

Score is average.

The overall building is attractive and in good shape. Corridors are wide and have areas that could promote student learning outside of the studio. There is no dedicated community room, and the Media Center is not easily accessible since it is on the second floor.

Educational Suitability Summary Report

Small Middle School

Security

Score is average.

There are card readers at all major entries.

Controllability of Systems

Score is average.

The studio thermostats can be controlled individually, but lighting is typically tied to one switch with no dimming. Specialized studios have two levels of lighting. Blinds are standard throughout the building. Approximately half are damaged and need to be replaced.

Academics & Learning

Score is average.

Learning studios are a little undersized at roughly 780 square feet and are connected in neighborhoods that have the potential to support open collaborative areas. Science labs are undersized at roughly 1,000 square feet but are within the neighborhoods and some can open to an adjoining studio. The neighborhoods do not include small group rooms or educator areas to meet and plan. There are display cabinets in the main corridors and tackable surfaces throughout neighborhood corridors.

Visual and Performing Arts

Score is average.

All spaces are under the square footage requirements but are in good condition and seem to function well. Band, choir and orchestra all share four practice rooms that are very small at 40 square feet each. There are no large or ensemble-sized practice rooms. Art rooms open to the exterior. Dance is currently in a portable. Theater storage seems to be inadequate for both prop and costume storage.

Media Resources

Score is average.

Located on the second floor, the Media Resources area is not easy to access for visitors but is sandwiched between the three-level academic wing and is somewhat central to students. It's undersized and technology access for group work is not apparent. The furniture in the space provides no options and there are not any whiteboards or collaborative equipment for student use. There are small rooms off the stack area that could be used for student group work or teacher planning.

Technology

Score is average.

Digital media in the main office is present but small. Both gyms have projection screens, but projector is brought in on a cart and is inadequate for presentations to large audiences. No charging locations were observed in any areas throughout the campus.

Administration Spaces

Score is average.

Reception area is welcoming, but there is no furniture present. No conference rooms for public or

Educational Suitability Summary Report

Small Middle School

parent use.

Satisfactory Categories (66-80%):

Environmental Quality

Score is satisfactory.

All learning studios have some access to natural light and exterior views (except band halls, choir and orchestra rooms), although windows are small, and some rooms only have one window. Acoustics are average for a school built at this time with some noise from other studios or corridors. Principal reported rodent problems.

Athletics and Wellness

Score is satisfactory.

Athletics facilities (interior and exterior) are in good shape and most are ready for UIL competitions. Locker rooms have some ADA accessibility issues.

Food Services

Score is satisfactory.

Per Ed Spec, the dining area is undersized by approximately 800 square feet at 6,200 square feet. There are ample windows and natural light in the space. Furniture is the standard cafeteria table with attached stool and does not provide seating options and cannot be reconfigured.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.

Parent drop-off and bus drop-off are separated but is hard to understand and lacks signage for directions. There are no covered walkways at any of the drop-offs. There is a monument sign at the street and the main entry of the school is easily identified. Access to dumpster and compost is next to cafeteria and easy to access.

Outdoor Learning and Activity

Score is very satisfactory.

Multiple areas for outdoor learning. One outdoor learning studio provides shade-cloth covering for 100% of the seating. Farm animals, greenhouse and gardens all provide spaces for hands-on learning.

CTE and Career Connected Learning

Score is very satisfactory.

The CTE space is in separate wing from the general learning neighborhoods. The Project Lead the Way area has a pathway to Austin High School. The environmental studies portion of the Green Tech Academy does not have a pathway to a high school.



Attractive entrance, good signage at street but no covered walkway for drop-off.





Campus provides multiple cisterns for rainwater harvesting and all are functioning.

Small Middle School



Multiple outdoor learning opportunities including studios, greenhouse and gardens.



Main corridors are large and open with lots of daylighting and are in good condition.






Classroom corridors are large and have ample space for collaboration but lack access for power and provide no daylighting.



Very little daylighting and access to outside views in studios. Most studios have two small windows, and some have only one small window. This room is currently serving as furniture storage due to COVID restrictions.





Furniture throughout campus is not flexible and provides no options for students.



Locker rooms in athletics/fitness department has ADA issues at shower areas.



No covered walkway at bus drop-off.





Interior and exterior athletics/fitness areas are in good condition.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Small MS	Lane Green & Jennifer Hoskins	12/7/2020

1 - E:	kterior		1	2	3	4	5	N/A	4	8.75	86%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen	•			•	•		Car drop-off at front entry, Bus drop-off in back. Pede	strians use sid	dewalk
		at the same location							system. No canopy at any entry points.		
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply									
1.2	Is the build	ing easily identified with appropriate signage and				1			Comments		
1.2	community	wayfinding?				7			Comments	0.25	1.00
	1	Very unsatisfactory - Campus has no signage /							Monument sign on street and signage on face of build	ding.	
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not									
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible									
		and easy to use									
	N/A	Does not apply									


Perkins&Will 02/11/2022 ²

1 - E	xterior (co	1	2	3	4	5	N/A				
1.3	Is the dump	oster accessible for trash / compost disposal?					5		Comments	0.50	2.50
	1 2 3	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly							From aerial views, dumpster area is large and adjace	nt to cafeteria	•
	5	adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - (arning and Activities	1	2	3	4	5	N/A		10.00	90%
2.1	Are outdoo the ed spec	or studios and support spaces appropriately configured per :?				4			Comments	1.00	4.00
	1 2	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided							Two outdoor studios created by the school. One is a c with 100% shade-cloth coverage. Second is an amphi wood benches and a wood lectern.	•	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2		playgrounds (elementary only) and support spaces per the ed spec?						N/A	Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated active playground									
	2	Unsatisfactory - Too small, poor condition, no shade									
	3	provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or									
	4	less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - 0	Outdoor Le	arning and Activities (cont)	1	2	3	4	5	N/A			
2.3		s and support spaces appropriately configured per the ed uation on infrastructure not condition of plants)				4			Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Outdoor garden spaces are large and sources of wat Only room for improvement would be that some infra maintenance.	-	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access Satisfactory - Good size, good condition, connected to									
	4	learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rained spec?	gardens and/or cisterns appropriately configured per the				4			Comments	0.00	0.00
	1 2 3	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Multiple rain harvesting cisterns on-site but no signathem.	ge visible on a	ny of
	4 5	Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply	ı	ı							
2.5	Does the sc	hool have animal husbandry? (optional) No	<u> </u>				5		Comments	0.00	0.00
	5	Yes									
2.6		hool have nature loop trails? (optional)					5		Comments	0.00	0.00
	1 5	No Yes	I	ı					2000000		
2.7	Does the sc	hool have a learning pond? (optional)					5		Comments	0.00	0.00
	1 5	No Yes									
2.8	Does the sc	hool have a grass play field and walking trail?					5		Comments	1.00	5.00
		No									

02/11/2022 4

3 - General Building			2	3	4	5	N/A	1	11.25	58%
3.1 Are interior	circulation routes wide enough to safely and effectively					5		Comments		
accommod	ate student movement?					5		Comments	0.50	2.50
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Corridors on the whole are very generous.		
	wide									
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are commu	nity use areas arranged so that the school can allow night			3				Community		
3.2 functions w	ithout full school access?			3				Comments	0.75	2.25
1	Very unsatisfactory - Cafeteria, gym, and library cannot							Cafeteria has good access from exterior without ente	ring through s	chool.
	be accessed after hours							Gym has exterior access from an outdoor stair and b	ridge but is not	:
2	Unsatisfactory - Only one of the public spaces (Cafeteria,							accessible. Library is on second floor and not easily a	ccessed by the	public
	Gym and Library) can be accessed from parking and secured after hours							after-hours.		
3	Average - Only two of the public spaces can be accessed									
3	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply									
22	ommunity room that is a dedicated meeting space outside	1						Comments		
of school fu									0.75	0.75
1 2	Very unsatisfactory - No dedicated community room							No community room.		
2	Unsatisfactory - Community room but within school function, no access after school hours									
3	Average - Community room, moderate size, but need									
	some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
N/A	function Does not apply									
Does the as	eneral appearance of the school convey pride for the				l					
2 /	d community?				4			Comments	0.25	1.00
1	Very unsatisfactory - General appearance is poor							On the whole, yes; there are a few maintenance item	s.	
2	Unsatisfactory - General appearance is aged but ok									
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
	campus and student works									
5	Very Satisfactory - General appearance shows pride in									
	campus and student works and is welcoming to the									
N/A	community Does not apply									
IN/A	Does not apply									



Perkins&Will 02/11/2022 ⁶

	5 - Environmen	- Environmental Quality				4	5	N/A		25.00	80%
	5.1 How are ac	oustics in studios in general?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
Ī		o artificial lighting adequate quality?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
	5.3 Is there acc	ess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios have at least one window for natural light are small, and quantity is either 1 or 2 windows per st		dows
F	N/A	Does not apply	I	ı			1	I		I	
	5.4 Is there acc	ess to outside views from learning spaces?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply							There is access to views but it is not optimal. Only 1-2	windows per s	tudio.

Perkins&Will 02/11/2022 7

5 -	Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.	5 Does the b	uilding have odor or pest problems?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Evidence of both pests and odors							Principal reported rodent problems.		
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school									
		cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in									
		excellent condition									
	N/A	Does not apply									
6 -	Controllabi	lity of Systems	1	2	3	4	5	N/A	4	12.50	60%
6	.1 Does the st	rudio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No									
	5	Yes									
6.	2 Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No, windows are covered with							Blinds in all studios. Condition of blinds varies throug	hout the camp	us.
		boards/paper							Some are in decent condition but some need to be re	placed.	
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply				1					
6.	3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Single switch only per room							Depends on the studio type. Some specialty rooms ha	ave multiple sw	vitches.
	2	Unsatisfactory - Alternating rows switch off							General studios were observed to only have one swit	ch that control	ls all
	3	Average - Alternating lamps in single fixtures switch off							fixtures with no dimming.		
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - Furniture,	- Furniture, Fixtures & Equipment					5	N/A		18.75	39%
7.1 What is th	ne current condition of the furniture?			3				Comments	0.75	2.25
1	Very unsatisfactory - Damaged or broken, non-							Student desks and chairs in satisfactory condition. To	ısk chairs are in	more
	functioning							unsatisfactory state.		
2 3	Unsatisfactory - Torn/ bent/ wrong size									
4	Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean									
5										
N/A	Very satisfactory - New Does not apply									
14/74	Does not apply	l	l	1						
	ety of furniture types being accommodated throughout the	,						Comments		
school - le	earning commons, dining commons, other multi-use spaces?	'						Comments	100	100
1	Very Unsatisfactory - Same furniture used in all spaces		<u> </u>					Studios have all formal seating consisting of chairs w	1.00	1.00
2								Cafeteria has only standard cafeteria tables with att		
	Unsatisfactory - Furniture variety in one multi-use space							Resources has only tables and chairs.	acried stools. IV	neala
3	Average - Furniture variety in more than one multi-use space							resources has only tables and chairs.		
4	Satisfactory - All multi-use spaces have greater than one									
· ·	type of furniture									
5	Very satisfactory - All multi-use spaces have greater									
	than two types of furniture									
N/A	Does not apply	ı	1	1		1	1			
7.3 How well space?	does furniture accommodate rapid reconfiguration of a		2					Comments	1.00	2.00
space:	Very Unsatisfactory - Furniture is fixed or very heavy							Studios consist of chairs with attached desks and are		
2	Unsatisfactory - Furniture does not allow desks to be							would be cumbersome to move around.	somewhatiai	ge and
	configured as individuals, small groups, or large groups							would be cambersome to move around.		
3	Average - Mix of furniture that can reconfigure but is									
	cumbersome to move									
4	Satisfactory - Furniture is flexible for multiple									
_	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
N/A	configurations of space, easy to move and stack									
IN/A	Does not apply	1	I	ı		Π	Γ			
7.4 Is the furn	iture ergonomic and size appropriate for grade level?		2					Comments	1.00	2.00
1	Very unsatisfactory - Desk with attached chair									
0	combinations too small for grade level									
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4	Very satisfactory - Tables with loose chairs									
5	Very satisfactory - Tables with loose chairs that allow									
N/A	students to be active									
11/7	Does not apply									

Perkins&Will 02/11/2022 ⁹

o Waste	1	2	3	4	5	N/A	A	5.00	50%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?		2					Comments	0.50	1.00
 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. 							A score for this category is being recorded, but this co-calculated in the overall ESA average. Team did not see any recycle or landfill bins in corridowere observed in some but not all studios.		e bins
N/A Does not apply Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?			3				Comments	0.50	1.50
1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting. N/A Does not apply									



Austin ISD Educational Suitability Assessment Criteria

Academics - Middle School / High School

School Name	Walk Attendees:	Date:
Small MS	Lane Green & Jennifer Hoskins	12/7/2020

B - Academics	& Learning	1	2	3	4	5	N/A	4	65.00	63%
8.1 Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
1 Very unsatisfactory - Too small, no flexibility, disconnected 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							ı	All studios are roughly between 750-800 sq. ft. Studio large commons areas that can be used as open colla however, the transparency is limited through a narro door. 12 out of 14 studios within the neighborhood can double door in the shared wall. Furniture does not suthe studio.	os are adjacen coration areas w lite in the clo n be joined by	nt to s; assroom a large
8.2 Do studios ed spec?	Does not apply have appropriate support spaces such as storage per the			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply							Storage is adequate but not abundant.		

8 - <i>A</i>	Academics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.3		earning neighborhoods have small and medium (high) group rooms and open collaboration space?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy							No small group rooms but neighborhoods provide spalthough very little visibility to those areas from the cacoustic privacy.		
	3 4	Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	5 N/A	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy Does not apply									
8.4	Are Science the ed spec	Labs and support spaces appropriately configured per ?				4			Comments	1.00	4.00
	1 2 3	Very unsatisfactory - No dedicated science room Unsatisfactory - Too small, poor condition, no connected support space Average - Adequate size, adequate condition, needs some renovations or updates to function well							Science rooms are undersized per the Ed Specs and T are in good shape overall. Science rooms are integra neighborhoods per the Ed Specs and two labs can op studio. One support/storage space shared per 3 Scie	ted into learnin oen to an adjoir	ng
	4 5	Satisfactory - Good size, good condition, connected support spaces Very Satisfactory - Generous size, excellent condition, connected support spaces							adjacent location.		
	N/A	Does not apply		1	ı	1	ı				
8.5		Spaces and support spaces appropriately configured per ? (cross reference with CTE below)		2					Comments	1.00	2.00
	1 2 3	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility Average - Adequate size, adequate condition, needs							No designated maker space for the campus. However printers are available in the CTE wing.	er, wood shop a	ınd 3D
	4	some renovations or updates to function well Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									,

8.6						4	5	N/A	1		
	Is there a P	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1 2	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected							Teachers hold PLC meetings within their classrooms.		
	3 4 5	Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected		_							
8.7		dequate places to display the evidence and artifacts of oth 2D and 3D)?				5			Comments	1.00	5.00
	1 2 3	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well							3D display in all corridors for Visual and Performing A display at main entry, Administration and outside of Tack strips in all corridors.		
	4 5 N/A	Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply									
8.8		uilding / learning neighborhood provide adequate es for students/teachers to collaborate in varying group			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes		,					Corridors are generous and could be an opportunity spaces if furniture, whiteboards and better lighting w		
8.9	N/A Does the bu	Does not apply uilding provide opportunities for informal interaction?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions							Corridors are generous in size and have some areas tables. Score could be improved with more furnishing	hat include ca	fé-type

8 - A	cademics &	k Learning (cont.)	1	2	3	4	5	N/A	4		
8.10	Does the but	ilding provide adequate opportunities for students to endently?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply							No furniture to support independent study, which isn visibility into the corridor.	't helped by littl	le
	Special Edu										
8.11	•	Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
	1 2 3	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							All Special Education areas are located within the mo- from all other learning studios.	ain admin suite	away
	4 5 N/A	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces Does not apply									
8.12		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply					,				

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.13		ble restrooms and changing rooms readily available to the lacation spaces?					5		Comments	1.00	5.00
	1	No	·			1					
	5	Yes									
	STEAM Cen	ter									
8.14	Does the ca	ampus have space to support a "STEAM" center?					5		Comments	0.00	0.00
	1	Very unsatisfactory - No available space for STEAM							Monitoring answer, but does not count toward overc		
	•	center and inadequate studio / collaborative space							Tech Academy functions within a separate suite awa		
	2	Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size							learning studios. Classes are taught in open- and clo		ios.
	3	Neutral - Collaborative areas / studios for CTE/CCL are							Furniture in corridors is used as group and collaborat	ion areas.	
	J	adjacent but function separately									
	4	Satisfactory - Collaborative areas / studios for CTE/CCL									
		function and have space availability to create STEAM									
		center									
	5	Very Satisfactory - Functioning STEAM center offers									
		studios, labs, common collaborative areas to support									
		multimedia distance and hands-on project based									
		learning									
	N/A	Does not apply									
9 - C		reer Connected Learning				1				10.00	90%
9.1		s your campus to a CTE cluster pathway that is aligned TE programs (Middle School only)?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No correlation to CTE cluster							The "green" environmental studies portion of the Gre	en Tech Acade	my
		pathway, no CTE programs.							does not currently have a pathway to Austin or Bowi	e High School.	Project
	2	Unsatisfactory - School supports less than half of the CTE							Lead the Way has a connected pathway to Austin Hi	gh School.	
	3	programs that are listed in the cluster pathway.									
	3	Average - School support half of CTE programs listed in the cluster pathway, but missing some.									
	4	Satisfactory - School support a majority of CTE programs									
	7	listed in the CTE cluster pathway.									
	5	Very Satisfactory - School is aligned with CTE cluster									
		pathway.									
	N/A	Does not apply						I.			
	Do campus	facilities align with the CTE Ed Spec Requirements for the									
9.2	•	hways offered?: Architecture and Construction					5				
		,								0.25	1.25
	1 -	No							Only comment is that learning is not "on display" sir	•	
	5 N/A	Yes							located in its own suite away from the learning	. neighborhood	ds.
	N/A	Does not apply							A // production studio was sheemed by assessed		
9.3	Arts, Audio	and Video Technology and Communications					5		A/V production studio was observed by assessment	0.25	1.25
									team.	0.20	1.25
9.4	Business, M	lanagement and Administration						N/A		0.00	0.00
9.5	Education a	and Training						N/A		0.00	0.00
9.6	Health Scien	nce						N/A		0.00	0.00
										0.00	0.00

9 - CTE and Career Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality and Tourism						N/A		0.00	0.00
9.8 Human Services (high school only)						N/A		0.00	0.00
9.9 Information Technology						N/A		0.00	0.00
9.10 Agriculture, Food and Natural Resources					5			0.25	1.25
9.]] Science, Technology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportation, Distribution and Logistics						N/A		0.00	0.00
9.13 Finance (high school only)						N/A		0.00	0.00
9.14 Government and Public Administration / JROTC Military programs (high school only)						N/A		0.00	0.00
9.15 Law, Public Safety, Corrections and Security (high school only)						N/A		0.00	0.00
9.16 Manufacturing (high school only)						N/A		0.00	0.00
9.17 Marketing, Sales and Services (high school only)						N/A		0.00	0.00
10 - Visual and Performing Arts		1						35.00	51%
10.1 Is there flexibility of space to also be used by CTE and Athletics?	1						Comments	0.00	0.00
1 No 5 Yes							CTE is adjacent and located in same area as visual at there were no "extra" spaces observed that can be fle		arts but
10.2 Are band and support spaces (rehearsal and storage) appropriately configured per the ed spec?			3				Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply							Band Hall and Aux Band rooms are under Ed Spec sq requirements but seem to function well and are in go Hall is 1400 sq. ft and Aux Band is at 866 sq. ft. There rooms shared between band, orchestra and choir, av each. All storage spaces are a little under the Ed Spec requirements.	od condition. are four pract eraging 40 sq	tice . ft.
10.3 Are orchestra and support spaces appropriately configured per the ed spec?			3				Comments	1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply		•	1	•			Orchestra Room is under Ed Spec square footage red ft. but seems to function well. There are four practice between band, orchestra and choir, averaging 40 sq spaces are a little under the Ed Spec requirements.	rooms shared	

10 - Visual and	d Performing Arts (cont.)	1	2	3	4	5	N/A	·		
10.4 Are choir a	and support spaces appropriately configured per the ed				4			Comments		
spec?					4			Comments	1.00	4.0
1	Very unsatisfactory - Too small, missing program spaces							Choir is under Ed Spec square footage requirements	at 1000 sq. ft.	There
2	Unsatisfactory - Too small, poor condition							are four practice rooms shared between band, orche	stra and choir	,
3	Neutral - Adequate size, adequate condition, needs							averaging 40 sq. ft. each. No large ensemble rooms.	Only one dedi	cated
	updates or renovations to function well.							choir storage at 140 sq. ft.		
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply			,						
() 5	and support spaces appropriately configured per the ed	1						Comments		
spec?		L .							1.00	1.0
1	Very unsatisfactory - Too small, missing program spaces							Dance is currently located in a portable building.		
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply								T	
O.6 Are theate spec?	er and support spaces appropriately configured per the ed		2					Comments	1.00	2.0
1	Very unsatisfactory - Too small, missing program spaces						•	Theater arts studio is under square footage at 1074 s	q. ft. Stage is ι	ınder
2	Unsatisfactory - Too small, poor condition							square footage at 1150 sq. ft. Prop storage is undersize	zed at 216 sq. f	t.
3	Neutral - Adequate size, adequate condition, needs							Costume storage was in a corridor but may be there	because of sto	rage
	updates or renovations to function well.							issues with current implemented COVID-19 measures	•	
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
0.7 Are visual o	arts and support spaces appropriately configured per the				4			Comments		
o.7 ed spec?					4			Comments	1.00	4.0
1	Very unsatisfactory - Too small, missing program spaces							Studios are only slightly under square footage requir	ements at 103	5 sq. ft
2	Unsatisfactory - Too small, poor condition							Storage is adequate with one for each studio and kill	n room is adec	juate.
3	Neutral - Adequate size, adequate condition, needs							Both art rooms have access to the exterior.		
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply								I	
Does the co	ampus have adequate space for the specialty arts									
0.8 programs ((Ensemble, Guitar, Music studies, Music theory and Piano)?	1						Comments		
									1.00	1.0
1	No									
5	Yes									

11 - Athletics and Wellness						18.75	73%
Does the campus meet ed spec standard for physical education program spaces?			5		Comments	1.00	5.00
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply					All spaces accounted for in gyms and support spaces. Very separate access for community.	nice area	ı with
11.2 Does the campus have a dedicated wellness center?	1				Comments	0.50	0.50
1 No 5 Yes							
11.3 Does the community have access to exterior playfields/courts?			5		Comments	0.50	2.50
1 No 5 Yes							
11.4 Are facilities available to facilitate eSports (High School only)?				N/	/A Comments	0.00	0.00
1 No 5 Yes	•			ı	Monitoring answer, but doesn't affect overall score.		
11.5 Are facilities set up to support UIL sanctioned athletics for basketball?			5		Comments	0.25	1.25
1 No 5 Yes	•			ı			
11.6 Are facilities set up to support UIL sanctioned athletics for track?			5		Comments	0.25	1.25
1 No 5 Yes					6 Iane track. Small area of spectator seating on one side of	track.	
11.7 Are facilities set up to support UIL sanctioned athletics for football?	1				Comments	0.25	0.25
1 No 5 Yes			_		Supports practice but spectator seating/lighting is not adea	quate.	
11.8 Are facilities set up to support UIL sanctioned athletics for volleyball?			5		Comments	0.25	1.25
1 No 5 Yes							
11.9 Are facilities set up to support UIL sanctioned athletics for tennis?	1				Comments	0.25	0.25
1 No 5 Yes					Tennis nets and posts were missing from tennis courts.		
11.10 Are facilities set up to support UIL sanctioned athletics for soccer?			5		Comments	0.25	1.25
1 No 5 Yes							

Perkins&Will 02/11/2022 9

11 - Athletics a	nd Wellness (cont.)	1	2	3 4	5	N/A			
1 11 11	es (dedicated storage) set up to support UIL sanctioned r cross-country (high school only)?					N/A	Comments	0.00	0.00
1 5	No Yes								
	es (dedicated storage) set up to support UIL sanctioned r golf (high school only)?					N/A	Comments	0.00	0.00
1 5	No Yes								
	es (dedicated storage) set up to support UIL sanctioned r swimming (high school only)?					N/A	Comments	0.00	0.00
1 5	No Yes				_				
11.14 Are facilitie (high school						N/A	Comments	0.00	0.00
1 5	No Yes								
11.15 Are facilitie (high school						N/A	Comments	0.00	0.00
1 5	No Yes								
11.16 Are facilitie (high school						N/A	Comments	0.00	0.00
1 5	No Yes								
1 11 17	es (dedicated space outside of the gymnasium) available to mpetitive spirit activities for cheerleading and drill team?	1					Comments	0.25	0.25
1 5	No Yes						Cheer practices in the gym or outside.		
11 - Athletics a	nd Wellness (cont.)	1	2	3 4	5	N/A			
	e athletics fields align with FMP Campus Improvements? Parking lot lighting, ADA accessible amenities (high School					N/A	Comments	0.00	0.00
1 2	Very unsatisfactory - No turf, inaccessible, no site lighting Unsatisfactory - No turf/field in poor condition, some						Monitoring answer, but doesn't affect overall score.		
3	accessibility concerns, poor site lighting Average - Field in adequate condition, needs some								
4	updates or renovations to function well Satisfactory - Turf field in good condition, good ADA								
5	access and site lighting Very Satisfactory - Turf field with excellent maintenance,								
N/A	excellent ADA access for spectators and athletes, excellent site lighting Does not apply.								

02/11/2022 ¹⁰

12 -	Food Service	es								10.00	70%
12.	ls the Dining	Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Dining is undersized by 800 square feet at 6,171 sq. ft	. Daylighting i	s good.
	2	Unsatisfactory - Too small, poor condition, only one							Furniture can't be reconfigured quickly only one ty	oe of furniture	e, the
	-	option for eating space provided, inadequate circulation							traditional cafeteria table with attached stools.		
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation,									
		multiple options for eating space (ex: connection to									
		outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition									
		and circulation, multiple options for eating space (ex:									
		connection to outdoor eating space)									
_	N/A	Does not apply		, ,							
12.2)	d Services support spaces appropriately configured per				4			Comments		
	the ed spec									1.00	4.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
13 -	Media Reso	ources	1	2	3	4	5	N/A	4	30.00	63%
13.	ls the Librar	y/Media Center easily accessible for the occupants and			0				Community		
13.	visitors to th	e school?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Not accessible							Located on 2nd floor but in same wing as learning ne	ighborhoods.	Campus
	2	Unsatisfactory - Limited access, difficult to find, no							has three floors with neighborhoods stacked so desig	ın puts media	center
		transparency							in the middle as best as possible. Not very easy for vis	sitors to find a	r access.
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Accessible, easy to find, good									
	_	transparency, good condition									
	5	Very Satisfactory - Accessible, easy to find, excellent									
	NI/A	transparency, excellent condition									
	N/A	Does not apply									

13 - Media Res	sources - Continued	1	2	3	4	5	N/	A	
13.2 How well o	does the Library/Media Center support quiet study?				4			Comments 1.00	4.00
1 2 3 4 5	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply							There is an area off the library with two small rooms and a larger where small or large groups can collaborate or a solo learner couroom.	
	does the Library/Media Center support social interaction?			3				Comments 1.00	3.00
1 2 3 4 5	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions						1	Updated furniture would help with social interaction and group discussions.	
N/A How well o	Does not apply does the Library/Media Center support collaborative work			l			l	6	
	oups (4-8 students)?				4			Comments 1.00	4.00
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply							Dedicated area off library supports these activities.	
13 5	does the Library/Media Center support collaborative work roups (10-25)?			3				Comments 1.00	3.00
1 2 3 4 5	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons							Once shelving is back in original layout, the library might not be I enough to support medium/large groups.	arge
N/A	spaces with seating, excellent condition Does not apply								

13	- Media Res	ources - Continued	1	2	3	4	5	N/A			
13	3.6 How well d	oes the Library/Media Center support technology?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition							The library is missing tack board and white board, an short supply. Computer stations along the wall but no students to interact with technology.	•	
14	N/A Tochnology	Does not apply	1	0	2	1	E	NI/A		20.00	400/
	- Technolog	quipped are the facilities with instructional technology?		2	3	4	5	N/A	Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school. Satisfactory - Multiple types of technology, smart boards. Good condition. Very Satisfactory - Multiple types of technology, smart boards. Excellent condition							Every room seemed to have the standard district cart monitor. There were also several of these in the facilit area.		
14	N/A Is there and spaces?	Does not apply adequate number of power and data outlets in learning			3				Comments	1.00	3.00
	1 2 3 4	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall)					ı		2-3 per wall. Some floor outlets in art rooms. Score comobile power added.		
	5 N/A	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall) Does not apply									

Perkins&Will 02/11/2022 13

14 - Technolog	y (cont.)	1	2	3	4	5	N/A	4		
14.3 Are there of	adequate charging locations for devices?		2					Comments	1.00	2.00
1 2 3	Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1							Did not observe any charging locations.		
4 5	Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.									
N/A	Does not apply equate AV for presentations spaces – cafeteria, gym, aux		I	ı		l	I			
14.4 gym?	equate AV for presentations spaces – caretena, gym, aux		2					Comments	1.00	2.00
1 2 3 4	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average							A/V present in cafeteria and gym but somewhat und screen in gym but projector has to be brought in on a	•	ion
5	Condition. Very Satisfactory - AV adequately sized for room. Excellent condition.									
N/A	Does not apply		l	1						
14.5 Is there dig	jital media signage at the reception area?			3				Comments	0.00	0.00
1	Very unsatisfactory - No digital media present in reception area							Flat screen but a little small.		
2	Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

15 - Administra	tion Spaces	1	2	3	4	5	N/A	\	20.00	60%
15.1 Is there a re-	ception area that functions as a security checkpoint for all							Comments		
1 2	Very unsatisfactory - No security checkpoint						-			
	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	ı				1	1			
	ministration area feel welcoming?			3				Comments	1.00	3.00
1	Very unsatisfactory - No welcome space							No seating provided but plenty of space to include it.		
2	Unsatisfactory - Too small, poor lighting and									
	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
_	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided, excellent condition									
N/A	Does not apply									
	aces that require it, does the administration area have									
	coustic privacy?				4			Comments	1.00	4.00
1	Very unsatisfactory - No acoustic separations					ļ				
2	Unsatisfactory - Acoustic separations do not perform									
3	Average - Some acoustic separations function okay, but									
Ŭ	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply									
15.4 Are confere	nce rooms easily accessed for public / parent use?	1						Comments	1.00	1.00
1	Very unsatisfactory - Not accessible for public/parent				ı			Conference rooms are not available for public use.		
	use							·		
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
5	good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A	Does not apply									
11/7	Docs not apply									