

## **Educational Suitability Summary Report**

Webb Middle School

Date: 01/14/2021 Score 59% Average

Webb Middle School serves an enrollment of approximately 630 students in the St. Johns neighborhood of Austin. It has a strong fine arts program and has CTE programs in animation, web design and app development. Webb is the only middle school that provides the English Language Development Academy for students who have been in the country less than two years.

The original school was built in 1961 and there is a stand-alone fine arts/band hall completed in 2009 with a total of 121,000 square feet. The front of the school is off St. Johns Avenue, which is a busy street. The original main entry has been closed off, due to accessibility issues and has been moved to the other side of the administration space. This smaller entry is difficult to find and feels unwelcoming.

. Most studios have access to windows and daylight, but the windows are small and do not let in much light in the main 1961 building.

The larger spaces, such as the gym and cafeteria, are in adequate shape and meet Ed Spec for the correct square footage. Finishes are dated in many places, especially within the life skills studio. The school has received new furniture throughout, and this new furniture has greatly improved the flexibility and use of space, specifically in the library.

#### **Interview Overview**

The interview took place virtually with Principal Sanchez, Assistant Principal Buckles and Kevin Ramirez, the head custodian. The group noted a few programs that need upgraded space. The English Language Development Academy is currently being housed out of a portable and is one of the only programs of its kind offered at the middle school level in the district. The performance area in the cafetorium does not function well. The stage is undersized, and if there is any large group, typically they perform on the floor within the cafeteria. The lighting is lacking as well as the A/V equipment. The group noted that other middle schools have proper auditoriums, and this is an area of needed improvement for their school. They also noted the need for a dedicated maker space.

It was noted that the school needs additional studio spaces. The group feels like they do not have an adequate number of studios to accommodate demand. There are a few floating teachers within the school who go to whichever studio is open. There is limited collaboration space only in the library and main hall by the cafeteria. There are no collaboration spaces or breakout rooms within the studio hallways. In thinking about the future of teaching and learning, the group noted the importance of these spaces.

The group also feels that the outdoors could be better utilized. Currently, the school does not have outdoor studios. There is a nicely sized courtyard, but it needs more flexible furniture, shade and technology for students to use it. There need to be outlets outside for charging.

Webb Middle School

The school is proud of all the community groups that use the school. The school is used seven days a week (during a normal year) by the Boys & Girls Clubs, Legal Aid, Honor Society, PTA, Korean school and Chinese school. Parking is an issue in hosting larger events. There is also concern that the path to the front door is not fully compliant as an accessible path.

The school has a few items on their list that should never change due to community importance. The community quilts in the main hallway are ceramic tiles and were completed through a program with the Smithsonian. The outdoor garden between the main building and fine arts building was created through a grant and highlights native Texas plants. The school is also proud of the fine arts building and also likes that the library is located at the heart of the school.

#### **Assessment Findings**

The Educational Suitability Assessment of Webb Middle School earned a 59% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and eight Academic categories to determine areas that need more attention.

#### **Unsatisfactory Categories (36-50%):**

#### **Controllability of Systems**

Score is unsatisfactory.

Most windows have blinds, but a few studios just have a small curtain. The lighting controls are a single on/off switch. There are thermostats in studios, but it is unclear how well they functioned.

### **Academic & Learning**

Score is unsatisfactory.

Studios are undersized at 730 square feet; science rooms are undersized at 920 square feet. There is limited collaboration space. There are no group/breakout rooms, and only certain locations, such as the library and courtyard, support informal interaction. The Life Skills studio is adequate, but the restroom, while attempting to be accessible, does not have the proper clearances around the toilet and door swings.

#### **Athletics and Wellness**

Score is average.

Main gym is slightly undersized, and the gym stage is being used as a weight room. The small gym is undersized. The bleachers in the main gym are very old, and at the end of their usable lifetime. The track is in adequate shape.

## **Administration Spaces**

Score is unsatisfactory.

The administration area is adequately sized, but with no seating and no transparency to the main

## **Educational Suitability Summary Report**

Webb Middle School

corridor, it feels unwelcoming. A conference room is not available for public/parent use.



### Average Categories (51-65%):

#### **Exterior**

Score is average.

Site circulation signage (visitor parking/staff parking) is unclear. Bus pickup and drop-off are separated between the St. Johns entrance and the entrance off of Roland Johnson Drive. The school has all three dumpsters – trash, recycling, composting – but staff is required to navigate five steps to them.

#### **Outdoor Learning and Activity**

Score is average.

The school does not currently have outdoor studio space. They have a garden area with native plants, but there is no cistern or rain garden present.

#### **General Building**

Score is average.

All hallways are wide at 10 feet plus. The gym and cafeteria can be used for after-hours functions. The school does not have a dedicated community room and hosts many of its after-school programs out of the cafeteria, library or studios.

#### Security

Score is average.



Score is average.

The art studios are satisfactory. There is no separate orchestra/choir room. All three programs – band, choir and orchestra – are adequately sized but missing some practice rooms. The school does not have a dance program, and there does not appear to be a dedicated drama room.

#### **Food Services**

Score is average.

The cafeteria/kitchen are appropriately sized. There is no chair/stage storage, and the stage does not function well.

#### **Technology**

Score is average.

Library has adequate charging. The remainder of the school does not. The A/V in the cafetorium is old and does not function well.

## Satisfactory Categories (66-80%):

#### **Environmental Quality**

## Perkins&Will

## **Educational Suitability Summary Report**

Webb Middle School

Score is satisfactory.

There is access to natural daylight in most studios. There are a few rooms where there are high windows that do not allow for views out. Acoustics are adequate in studios with some sound transmission through doors.

#### **CTE and Career Connected Learning**

Score is satisfactory.

Courses are offered in about a half of the CTE programs within the district. The high school feeder pattern is to McCallum, Navarro or Northeast. These three high schools offer every CTE program.

#### **Media Resources**

Score is satisfactory.

The library is sized appropriately and has different areas set up for different types of study. The furniture is new and allows for flexibility and adequate locations for charging.

#### **Very Satisfactory Categories (81-100%):**

#### Furniture, Fixtures, Equipment

Score is very satisfactory.

There is new furniture throughout the studios and library. The furniture is flexible and lightweight allowing for quick reconfiguration of spaces. In the library, charging poles are also being provided throughout the space.



Signage is adequate but no designation of staff/visitor parking lot.



Administration: Space is large but does not have seating in the reception area and does not feel welcoming.

Webb Middle School

## **Supporting Photographs**



School Pride: The community quilt is very important to the school and is an item that should not change due to campus importance.



Typical studio is undersized, but all have new, updated furniture. Small windows are provided in most studios.



Media Center: Library and rest of school have received updated/new furniture. The media center doesn't have small group breakout rooms but does provide a variety of furniture for different types of studies.



Food Services: Cafeteria is appropriately sized. The stage is not big enough for performances and has unsatisfactory A/V equipment.

Webb Middle School




Visual/Fine Arts: Art classrooms in fine arts building are in good shape and have good access to natural daylight.




CTE: Computer Lab and adjacent wood shop have had recent upgrades with the addition of flexible overhead power and overhead exhaust in the back of the room. The computer monitors are being installed, and their current location does not represent the typical state of the studio.

Webb Middle School



Corridors are approximately 10' wide but there is limited to no transparency into studios.



Gym is appropriately sized. Wood floor has had repairs in recent years. Bleachers are original to school and at the end of their useful life. The stage to the right of the image is being used as a weight room and is not adequate.



Updated furniture in main hall outside of cafeteria provides some group collaboration space. No collaboration or small group space provided near the studios.



Outdoor Learning: Courtyard between school and fine arts building is well utilized but needs additional upgrades, such as shade, furniture and technology, to function well.



# Perkins&Will

# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

	School Name								Walk Attendees:	Date:	
	Webb Mid	ddle School					_		Lynn Petermann / Patrick Reinhard	1/14/2021	
1 - E	xterior		1	2	3	4	5	N/A		8.75	51%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location									
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply							1	T	
1.2		ing easily identified with appropriate signage and vayfinding?		2					Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage / wayfinding							Signage is poor on where to park and general circul	ation.	
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not									
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

O2/11/2022 <sup>2</sup>

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A	4		
1.3	Is the dump	oster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							Required to navigate 5 steps down to dumpsters. Sor three.	t of long walk to	o all
2 - 0	N/A Dutdoor Le	Does not apply arning and Activity	1	2	3	4	5	N/A	<b>A</b>	10.00	60%
2.1		r studios and support spaces appropriately configured per	1		3	4	3	IN/F	Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated outdoor studios				<u> </u>	I.		No outdoor studios found		
	3 4 5	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area Does not apply							illo Gatassi stadios iodila		
2.2	Are active p	per the ed spec?						N/A	Comments	0.00	0.00
	1 2 3 4 5	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									

2 - C	outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	4		
2.3		s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)				4			Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens			1	1	1		Monitoring answer, does not affect score for Outdoor		
	2	Unsatisfactory - Too small, poor condition, disconnected							Activity. Nice garden space with native plants. Water	-	hose.
		from learning spaces, no flexibility, no accessible water									
		source									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well, water									
		source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition,									
	Ū	connected to learning spaces, excellent flexibility, water									
		source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
		gardens and/or cisterns appropriately configured per the									
2.4	ed spec?	gardens and/or disterns appropriately configured per the	1						Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns			1				Monitoring answer, does not affect score for Outdoor		0.00
	2	Unsatisfactory - Too small, poor condition, not							Activity.	Learning and	
	-	functioning, disconnected							Activity.		
	3	Average - Adequate size, adequate condition, is									
		connected, needs some renovations or updates to									
		function well									
	4	Satisfactory - Good size, good condition, functions									
	_	properly									
	5	Very Satisfactory - Generous size, excellent condition,									
		exceptional functionality, connected to learning spaces,									
	N/A	educational signage provided  Does not apply									
2.5	•	nool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No							Commonto	0.00	
	5	Yes									
2.6	Does the scl	nool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1	No							•		
	5	Yes									
2.7		nool have a learning pond? (optional)	1						Comments	0.00	0.00
	1	No									
0.0	5	Yes					-		Community	100	F 00
2.8	Does the sci	nool have a grass play field and walking trail?					5		Comments	1.00	5.00
	I E	NO Voc									

ŀ	3 - General Bui	- General Building  Are interior circulation routes wide anough to cafely and effectively				4	5	N/A		11.25	53%
	.5.1	circulation routes wide enough to safely and effectively ate student movement?					5		Comments	0.50	2.50
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Yes, generous hallways throughout.		
	•	wide									
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
	32	nity use areas arranged so that the school can allow night			3				Comments		
	functions w	ithout full school access?								0.75	2.25
	1	Very unsatisfactory - Cafeteria, gym, and library cannot							Gym and cafeteria can be closed from most of schoo	I. Library canno	ot.
	2	be accessed after hours Unsatisfactory - Only one of the public spaces (Cafeteria,									
	2	Gym and Library) can be accessed from parking and									
		secured after hours									
	3	Average - Only two of the public spaces can be accessed									
		from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building									
	_	but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
	N/A	Does not apply									
		ommunity room that is a dedicated meeting space outside									
	3.3 of school fu	,	1						Comments	0.75	0.75
_	1	Very unsatisfactory - No dedicated community room		1							
	2	Unsatisfactory - Community room but within school									
		function, no access after school hours									
	3	Average - Community room, moderate size, but need									
		some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
	ŭ	condition, functions appropriately outside of school									
		function									
	N/A	Does not apply									
		eneral appearance of the school convey pride for the		2					Comments		
	students an	d community?		_						0.25	0.50
	1	Very unsatisfactory - General appearance is poor							Grounds need more attention. School entry is not wh	ere the original	lentry
	2	Unsatisfactory - General appearance is aged but ok							was intended and looks unwelcoming.		
	3 4	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in campus and student works									
	5	Very Unsatisfactory - General appearance shows pride									
	-	in campus and student works and is welcoming to the									
		community									
	N/A	Does not apply									

4 - Security		1	2	3 4	5	N/A		16.25	
4.1 Does the fo	acility have key card access at all major entries?				_		Comments	0.25	
1	Very unsatisfactory - No entries		•	•					
2	Unsatisfactory - 1/4 of major entries								
3	Average - 1/2 of major entries								
4	Satisfactory - 3/4 of major entries								
5	Very satisfactory - All of major entries								
N/A	Does not apply								
4.2 How adequ	uate is site lighting and security for the campus overall?						Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter		Ī					1.00	
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal								
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate								
4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates								
5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply								
ls the main	office located at the school entry and configured with a						Comments		
4.3 secure vest	ibule to the main corridor?						Comments	1.00	
1	Very unsatisfactory - No secure vestibule, office located								
	far from main entry, allows visitors access to school								
0	unsupervised								
2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of								
	visitors								
3	Average - Office close to entry, views of front door, but								
· ·	no secure vestibule								
4	Satisfactory - Office is well-located with a secure								
	vestibule, but needs updates								
5	Very satisfactory - Office well-located with secure								
	vestibule and all appropriate security features								
N/A	Does not apply								
11	ough interior transparency for faculty to passively supervise at their activities who are not in studios?		2				Comments	1.00	2.00
learners an		]					Studio doors have small sidelight Very limited to be		2.00
2	Very unsatisfactory - No transparency of walls						Studio doors have small sidelight. Very limited to no	transparency.	
	Unsatisfactory - Limited transparency in certain locations								
3	Average - Good transparency in certain locations but								
4	inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the								
	school								
5	Very satisfactory - Excellent transparency throughout the								
	school								
N/A	Does not apply								

Perkins&Will 02/11/2022 <sup>6</sup>

!	5 - Environmen	tal Quality	1	2	3	4	5	N/A		25.00	72%
	5.1 How are acc	oustics in studios in general?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
	5.2 Is the studio	artificial lighting adequate quality?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
	5.3 Is there acce	ess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5	1 Very unsatisfactory - No learning spaces have natural light 2 Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light 3 Average - 26-50% of learning spaces have natural light 4 Satisfactory - 51-75% of learning spaces have natural light							Only few rooms on lower level do not have windows. large but provide adequate daylight.	Windows are r	not
	N/A	Does not apply	ı								
	5.4 Is there acce	ess to outside views from learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5	2 Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out 3 Average - 26-50% of learning spaces have views 4 Satisfactory - 51-75% of learning spaces have views							Not large windows. May not get a view of outside de	pending on se	at.
		<b>D</b>									

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5 Does the b	ouilding have odor or pest problems?			3				Comments	1.00	3.00
1	Very unsatisfactory - Evidence of both pests and odors							No evidence.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A		12.50	44%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?		2					Comments	1.00	2.00
1	Very unsatisfactory - No, windows are covered with							Most windows have poor condition blinds. A lot of cla	assrooms just h	ave
	boards/paper							sheer fabric covering.		
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5										
N/A	Does not apply									

7 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A		18.75	95%
7.] What is the current condition of the furniture?					5		Comments	0.75	3.75
1 Very unsatisfactory - Damaged or broken, non-							2017 Bond Note: Furniture refresh completed in studio	os, library and	
functioning							corridor spaces in November 2020.		
2 Unsatisfactory - Torn/ bent/ wrong size									
3 Average - Scratched/dented/marked									
4 Satisfactory - Not new, but sturdy and clean									
5 Very satisfactory - New									
N/A Does not apply									
Are a variety of furniture types being accommodated throughout the school - learning commons, dining commons, other multi-use spaces?					5		Comments		
school - learning commons, aining commons, other multi-use spaces?								1.00	5.00
1 Very Unsatisfactory - Same furniture used in all spaces			<u> </u>				Library and commons areas have new flexible furnitu		
							furniture available.	,	
orisatisfactory Turnitare variety in one main use space									
3 Average - Furniture variety in more than one multi-use space									
4 Satisfactory - All multi-use spaces have greater than one									
type of furniture									
5 Very satisfactory - All multi-use spaces have greater									
than two types of furniture									
N/A Does not apply									
How well does furniture accommodate rapid reconfiguration of a				4			Comments		
space?							Comments	1.00	4.00
1 Very Unsatisfactory - Furniture is fixed or very heavy									
Unsatisfactory - Furniture does not allow desks to be									
configured as individuals, small groups, or large groups									
3 Average - Mix of furniture that can reconfigure but is									
cumbersome to move									
4 Satisfactory - Furniture is flexible for multiple configurations of space									
5 Very satisfactory - Furniture is flexible for multiple									
configurations of space, easy to move and stack									
N/A Does not apply									
. 233		1							
7.4 Is the furniture ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
Very unsatisfactory - Desk with attached chair		l					Most desks have sit-stand capability.		
combinations too small for grade level							, ,		
2 Unsatisfactory - Desk with attached chair combinations									
Average - Mix of studios with tables/loose chairs and									
desks with fixed seats									
4 Very satisfactory - Tables with loose chairs									
5 Very satisfactory - Tables with loose chairs that allow									
students to be active									
N/A Does not apply									

Perkins&Will 02/11/2022 <sup>9</sup>

Z	ero Waste		1	2	3	4	5	N/A	4	5.00	60%
		and corridors have blue recycle bins with bilingual s and/or image sorting instructions?		2					Comments	0.50	1.00
	1 2 3 4 5	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.  Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.  Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location.  The containers have clear signage.  Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.  Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this co- calculated in the overall ESA average.	itegory is not	
_	N/A	Does not apply		,					<u>,                                      </u>		
	of each: gre	afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?				4			Comments	0.50	2.00
	2	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.  Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located							A score for this category is being recorded, but this co- calculated in the overall ESA average.	itegory is not	
	3	next to one another. Signage is absent or inconsistent.  Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
	<b>4</b> 5	Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
	N/A	Does not apply									



# Perkins&Will

# **Austin ISD Educational Suitability Assessment Criteria**

Academics - Middle School / High School

	School No	ıme							Walk Attendees:	Date:	
	Webb Mid	ddle School					_		Lynn Petermann / Patrick Reinhard	1/14/2021	
							_				
8 - A	cademics	& Learning	1	2	3	4	5	N/A	4	65.00	43%
8.1	Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1 2 3 4	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							Studios are undersized at 730 SF.		
	N/A Do studios	Does not apply have appropriate support spaces such as storage per the			l	l		1		<u> </u>	
8.2	ed spec?			2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided			•					-	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>2</sup>

8 - 8	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A	· ·		
8.3	Do typical l	earning neighborhoods have small and medium (high	1						Comments		
0.3	school only)	group rooms and open collaboration space?							Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open							No breakout rooms provided.		
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition									
		and flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
8.4		Labs and support spaces appropriately configured per		2					Comments		
	the ed spec									1.00	2.00
	1	Very unsatisfactory - No dedicated science room							Science labs are undersized at 920 SF.		
	2	Unsatisfactory - Too small, poor condition, no connected									
		support space									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	_	support spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N/A	connected support spaces Does not apply									
	•			1	Ι	ı	I	Ι			
8.5		Spaces and support spaces appropriately configured per ? (cross reference with CTE below)			3				Comments	1.00	3.00
	ı ı	•				<u> </u>			Cood CTF/ssalvay as see in years 10 and 10 A but set a		
	1	Very unsatisfactory - No dedicated maker spaces							Good CTE/maker space in room 12 and 12A but not a	dedicated mai	ker
	2	Unsatisfactory - Too small, poor condition, disconnected							space.		
	3	from learning spaces, no flexibility  Average - Adequate size, adequate condition, needs									
	3	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	4	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	3	connected to learning spaces									
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>3</sup>

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6	Is there a P	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected								•	
8.7		dequate places to display the evidence and artifacts of			3				Comments		
		oth 2D and 3D)?								1.00	3.00
	1	Very unsatisfactory - No dedicated space							Both 2D and 3D available.		
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	Does the bu	uilding / learning neighborhood provide adequate									
8.8		es for students/teachers to collaborate in varying group			3				Comments		
	sizes?									1.00	3.00
	1	Very unsatisfactory - No space to support collaboration							The main corridor has collaboration furniture availab	ole. Other locat	ions
		in various sizes.							throughout the school could utilize the space to creat	te these pocket	ts for
	2	Unsatisfactory - Too small, inflexible, only one option,							collaboration.		
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple									
		options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.9	Does the bu	uilding provide opportunities for informal interaction?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space							Yes. New furniture solutions in main hallway.		•
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
		furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
		layout and furnishings support informal interactions									
	N/A	Does not apply									

8 - A	cademics &	& Learning (cont.)	1	2	3	4	5	N/A	1		
8.10	Does the bu	uilding provide adequate opportunities for students to endently?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms/small study spaces Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Does not apply							None available. Library is just one open space but do solution that creates more individualized spaces.		
	Special Edu	cation									
8.11	Are Special spec?	Education spaces appropriately configured per the ed			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - Too small, no flexibility, disconnected  Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected  Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.  Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces  Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces  Does not apply							Life skills 111. Kitchen space very antiquated but all ele upgrades to function well. Bathroom is not fully acce	•	. Needs
8.12	Are Special	Education support spaces, such as storage, space for er, appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition		ı					Separate storage with washer/dryer.	1.00	5.55
	N/A	Does not apply									

8 - A	cademics & Learning (cont.)	1	2	3	4	5	N/A			
8.13	Are Accessible restrooms and changing rooms readily available to the Special Education spaces?	1						Comments	1.00	1.00
	1 No							Bathroom doors do not have proper pull clearance. N	No changing ro	oms.
	5 Yes STEAM Center									
8.14	Does the campus have space to support a "STEAM" center?	1		T				Comments	0.00	0.00
	1 Very unsatisfactory - No available space for STEAM center and inadequate studio / collaborative space 2 Unsatisfactory - Collaborative areas / studios for CTE/CCL are completely separate but adequate size 3 Neutral - Collaborative areas / studios for CTE/CCL are adjacent but function separately 4 Satisfactory - Collaborative areas / studios for CTE/CCL function and have space availability to create STEAM center 5 Very Satisfactory - Functioning STEAM center offers studios, labs, common collaborative areas to support multimedia distance and hands-on project based learning							Monitoring answer, but does not count toward overc	ıll score.	
0 - 0	N/A Does not apply TE and Career Connected Learning								13.75	78%
9.1	How close is your campus to a CTE cluster pathway that is aligned with your CTE programs (Middle School only)?			3				Comments	1.00	3.00
	<ol> <li>Very unsatisfactory - No correlation to CTE cluster pathway, no CTE programs.</li> <li>Unsatisfactory - School supports less than half of the CTE programs that are listed in the cluster pathway.</li> <li>Average - School support half of CTE programs listed in the cluster pathway, but missing some.</li> <li>Satisfactory - School support a majority of CTE programs listed in the CTE cluster pathway.</li> <li>Very Satisfactory - School is aligned with CTE cluster pathway.</li> </ol>							CTE room - 113. School location can be within both no clusters. School offers about half of the CTE program		
	N/A Does not apply									
9.2	Do campus facilities align with the CTE Ed Spec Requirements for the current pathways offered?: Architecture and Construction	1							0.25	0.25
	1 No 5 Yes N/A Does not apply									
9.3	Arts, Audio and Video Technology and Communications					5			0.25	1.25
9.4	Business, Management and Administration					5			0.25	1.25
9.5	Education and Training						N/A	no courses offered	0.00	0.00
9.6	Health Science						N/A	no courses offered	0.00	0.00

9 - CTE and Care	er Connected Learning (cont.)	1	2	3	4	5	N/A			
9.7 Hospitality ar	nd Tourism					5			0.25	1.25
9.8 Human Servic	ces (high school only)						N/A	no courses offered	0.00	0.00
9.9 Information T	echnology					5			0.25	1.25
9.10 Agriculture, Fo	ood and Natural Resources						N/A	no courses offered	0.00	0.00
9.11 Science, Tech	nology, Engineering, and Mathematics					5			0.25	1.25
9.12 Transportatio	on, Distribution and Logistics					5			0.25	1.25
9.13 Finance (high	school only)						N/A		0.00	0.00
9.14 Government (high school o	and Public Administration / JROTC Military programs only)						N/A		0.00	0.00
9.15 Law, Public Sc	afety, Corrections and Security (high school only)						N/A		0.00	0.00
9.16 Manufacturin	ng (high school only)						N/A		0.00	0.00
9.17 Marketing, Sc	ales and Services (high school only)						N/A		0.00	0.00
10 - Visual and P	Performing Arts					<u> </u>			35.00	60%
10.1 Is there flexib	ility of space to also be used by CTE and Athletics?					5		Comments	0.00	0.00
	No Yes							Monitoring answer, but doesn't affect overall score.		
	d support spaces (rehearsal and storage) appropriately er the ed spec?				4			Comments	1.00	4.00
2 1 3 1 4 5 5 N	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition							Practice rooms are available for band and orchestra missing a few.	but per Ed Spe	ec
	Does not apply and support spaces appropriately configured per the				4			Comments	1.00	4.00
2 1 3 1 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well. Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply							Orchestra and guitar Room 300. Missing practice roo storage. Only one storage room for instruments.	ms and library	,

10 - V	- Visual and Performing Arts (cont.)				3	4	5	N/A	4		
10.4	Are choir a	nd support spaces appropriately configured per the ed		2					Comments		
10.4	spec?								Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Unclear if choir shares with orchestra. No separate ch	noir room. Curr	ent
	2	Unsatisfactory - Too small, poor condition							orchestra room is set up for permanent risers.		
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply			,			,			
10.5		and support spaces appropriately configured per the ed	1						Comments		
	spec?									1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							The school doesn't have a dance program but is requ	ired per Ed Sp	ec.
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply			1	1	1				
10.6		and support spaces appropriately configured per the ed	1						Comments		
	spec?								No decree of the control of the cont	1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							No drama classroom, and the stage in the cafeteria i	s not in adequ	ate
	2	Unsatisfactory - Too small, poor condition							shape.		
	3	Neutral - Adequate size, adequate condition, needs									
	4	updates or renovations to function well.									
	4 5	Satisfactory - Good size, good condition									
	b N/A	Very Satisfactory - Generous size, excellent condition									
	· ·	Does not apply			l	l	I				
10.7	ed spec?	ırts and support spaces appropriately configured per the				4			Comments	1.00	4.00
	1	V							Art room in fine arts building is in excellent shape. Art		
	-	Very unsatisfactory - Too small, missing program spaces							kiln room. Appropriate number of sinks. Daylight and		
	2 3	Unsatisfactory - Too small, poor condition							graphics lab found.	The tall cellin	93.140
	3	Neutral - Adequate size, adequate condition, needs							graphics lab round.		
	4	updates or renovations to function well.									
	5	Satisfactory - Good size, good condition									
	N/A	Very Satisfactory - Generous size, excellent condition  Does not apply									
	IN/A	Does not apply					l				
10.8	Does the co	ampus have adequate space for the specialty arts					5		Comments		
10.8	programs (	Ensemble, Guitar, Music studies, Music theory and Piano)?					5		Comments	1.00	5.00
	1	No						_	Specialty band for mariachi and guitar program in or		
	5	Yes							band and orchestra.	chestra. Share	u with
	J	. ••							Thatia and ordiestra.		

11 -	Athletics and Wellness						18.75	47%
11.	Does the campus meet ed spec standard for physical education program spaces?		2			Comments	1.00	2.00
	1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply			•		Main gym slightly undersized. Stage for main gym is be room and is very inadequate. Small gym is undersized. work well and are original to the school.		
11.:	N/A Does not apply  Does the campus have a dedicated wellness center?	1				Comments	0.50	0.50
	1 No 5 Yes						0.50	0.50
11.3	Does the community have access to exterior playfields/courts?				5	Comments	0.50	2.50
	1 No 5 Yes							
11.4	Are facilities available to facilitate eSports (High School only)?				N/A	Comments	0.00	0.00
	1 No 5 Yes					Monitoring answer, but doesn't affect overall score.		
11.5	Are facilities set up to support UIL sanctioned athletics for basketball?				5	Comments	0.25	1.25
	1 No 5 Yes							
11.0	Are facilities set up to support UIL sanctioned athletics for track?	1				Comments	0.25	0.25
	1 No 5 Yes					Track is in good shape. No spectator seating.		
11.3	Are facilities set up to support UIL sanctioned athletics for football?	1				Comments	0.25	0.25
	1 No 5 Yes					Supports practice. No spectator seating. Field is not in (	great shape.	
11.8	Are facilities set up to support UIL sanctioned athletics for volleyball?				5	Comments	0.25	1.25
	1 No 5 Yes							
11.9	Are facilities set up to support UIL sanctioned athletics for tennis?	1				Comments	0.25	0.25
	1 No 5 Yes					only two courts - no spectator seating		
11.1	Are facilities set up to support UIL sanctioned athletics for soccer?	1				Comments	0.25	0.25
	1 No 5 Yes					Supports practice. No spectator seating.		

Perkins&Will 02/11/2022 9

11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A			
11.11 Are facilities (dedicated storage) set up to support UIL so athletics for cross-country (high school only)?	anctioned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.12 Are facilities (dedicated storage) set up to support UIL so athletics for golf (high school only)?	anctioned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.13 Are facilities (dedicated storage) set up to support UIL so athletics for swimming (high school only)?	anctioned					N/A	Comments	0.00	0.00
1 No 5 Yes									
11.14 Are facilities set up to support UIL sanctioned athletics for (high school only)?	or wrestling					N/A	Comments	0.00	0.00
1 No 5 Yes						ı			
11.15 Are facilities set up to support UIL sanctioned athletics for (high school only)?	or baseball					N/A	Comments	0.00	0.00
1 No 5 Yes						ı			
11.16 Are facilities set up to support UIL sanctioned athletics for (high school only)?	or softball					N/A	Comments	0.00	0.00
1 No 5 Yes						1			
11.17 Are facilities (dedicated space outside of the gymnasium support competitive spirit activities for cheerleading and		1					Comments	0.25	0.25
1 No 5 Yes									
11 - Athletics and Wellness (cont.)		1	2	3 4	5	N/A			
How do the athletics fields align with FMP Campus Impr 11.18 Turf Field, Parking lot lighting, ADA accessible amenities only)						N/A	Comments	0.00	0.00
l Very unsatisfactory - No turf, inaccessible, i	no site lighting						Monitoring answer, but doesn't affect overall score.		
2 Unsatisfactory - No turf/field in poor condit accessibility concerns, poor site lighting	tion, some								
3 Average - Field in adequate condition, nee updates or renovations to function well	eds some								
4 Satisfactory - Turf field in good condition, g access and site lighting	good ADA								
5 Very Satisfactory - Turf field with excellent excellent ADA access for spectators and atlexcellent site lighting									
N/A Does not apply.						ı.			

Perkins&Will 02/11/2022 10

12 - Food Ser	vices								10.00	60%
12.1 Is the Din	ning Commons appropriately configured per the ed spec?			63	3			Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply							Cafeteria (4400 SF) is slightly undersized for full scho students (4500 SF)	ol capacity of	800
12.2 Are the Fe	ood Services support spaces appropriately configured per			3	3			Comments		
the ed sp				L					1.00	3.00
1 2	Very unsatisfactory - None provided  Unsatisfactory - Too small, disconnected, poor condition							Two serving lines. Kitchen is adequate.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
13 - Media Re	esources	1	2	3	3 4	5	N/A		30.00	73%
12 1	rary/Media Center easily accessible for the occupants and othe school?			3	3			Comments	1.00	3.00
1 2 3	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or		•		,	•	•	At main entry but no transparency to hallway. Flexib provided throughout the space.	le, new furnitu	re
4	renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition									
5	Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A	Does not apply									

13 - Media Res	ources - Continued	1	2	3	4	5	N/A	A Company of the Comp		
13.2 How well d	oes the Library/Media Center support quiet study?				4			Comments	1.00	4.00
1 2 3	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy									
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy									
N/A	Does not apply									
	oes the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1	Very unsatisfactory - No space							New flexible furniture allows for small groups to meet	t.	
2	Unsatisfactory - Too small, poor condition, layout and									
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
4	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply									
How well d	oes the Library/Media Center support collaborative work				4			Comments		
in small gro	oups (4-8 students)?				4			Comments	1.00	4.00
1	Very unsatisfactory - No breakout rooms, no flexible									
	furniture, no support									
2	Unsatisfactory - Too small, one area, poor condition									
3	Average - Adequate size, multiple areas provided,									
4	needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition									
5	Very Satisfactory - Multiple clusters or small rooms									
ŭ	adjacent to media center, flexible furniture, excellent									
	condition									
N/A	Does not apply									
How well d	oes the Library/Media Center support collaborative work				4			Comments		
in larger gr	oups (10-25)?				4			Comments	1.00	4.00
1	Very unsatisfactory - No gathering areas									
2	Unsatisfactory - Too small, one common space, limited									
	seating, poor condition									
3	Average - Adequate size, one common space, needs									
,	updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with									
_	seating, good condition									
5	Very Satisfactory - Generous size, multiple commons									
N/A	spaces with seating, excellent condition  Does not apply									
IN/A	Does not apply									

13 - Media Res	ources - Continued	1	2	3	4	5	N/A		
13.6 How well do	pes the Library/Media Center support technology?			3				Comments 1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Average - Mix of old and new whiteboards/projectors/etc. Satisfactory - projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - projectors, marker boards, smart boards in most spaces - new condition Does not apply							Mobile displays. One projector screen. A lot of new power tower	s.
14 - Technology		1	2	3	4	5	N/A	20.00	55%
	quipped are the facilities with instructional technology?				4			Comments 1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present  Average - Multiple types of technology, smart boards. Poor condition. Limited to only certain areas of school.  Satisfactory - Multiple types of technology, smart boards. Good condition.  Very Satisfactory - Multiple types of technology, smart boards. Excellent condition  Does not apply								
14.2 Is there and spaces?	adequate number of power and data outlets in learning			3				Comments 1.00	3.00
1 2 3 4	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but limited capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity in limited locations (>3 per wall)  Very Satisfactory - Excellent outlet configuration to								
N/A	support digital devices throughout school (>3 per wall)  Does not apply								

Perkins&Will 02/11/2022 13

y (cont.)	1	2	3	4	5	N	/A		
dequate charging locations for devices?		2					Comments	1.00	2.0
Very unsatisfactory - Not enough charging locations throughout school for 1:1 Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1.	ı	ı		1			Library has adequate charging with new flexible furr school doesn't have charging stations - only outlets.		
Does not apply	I	I	ı	1	I	1			
equate AV for presentations spaces – careteria, gym, aux		2					Comments	1.00	2.0
Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Average Condition. Very Satisfactory - AV adequately sized for room. Excellent condition. Does not apply							Cafeteria A/V looks old.		
ital media signage at the reception area?		2					Comments	0.00	0.0
Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition				·			Not counted toward overall technology score.		
	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate ysized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequate y sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition  Average - Adequately sized / poor condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for 1:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1 Satisfactory - Charging locations, haphazard locations, but supports 1:1. Very Satisfactory - Charging locations throughout school to support 1:1. Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition Satisfactory - AV adequately sized for room. Excellent condition. Does not apply ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition OR average - Adequately sized / poor condition Average - Adequately sized / poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?  Very unsatisfactory - Not enough charging locations throughout school for I:1  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough capacity for 1:1  Satisfactory - Charging locations, haphazard locations, but supports 1:1.  Very Satisfactory - Charging locations throughout school to support 1:1.  Does not apply equate AV for presentations spaces - cafeteria, gym, aux  Very unsatisfactory - AV not present in one or more space  Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / average condition  Satisfactory - AV adequately sized for room. Average  Condition.  Very Satisfactory - AV adequately sized for room.  Excellent condition.  Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area  Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition.  Average - Adequately sized / poor condition  Average - Adequately sized / poor condition OR undersized / adequate condition  Satisfactory - Media signage present, good sized, good condition	dequate charging locations for devices?    2	dequate charging locations for devices?  2   Comments   1,00  Very unsatisfactory - Not enough charging locations throughout school for 1:]  Unsatisfactory - Charging locations, haphazard locations, and inadequate in size for number of devices Average - Charging locations well organized but not enough chargity for 1:]  Satisfactory - Charging locations, haphazard locations, but support 1:].  Very Satisfactory - Charging locations throughout school to support 1:].  Does not apply aquate AV for presentations spaces - cafeteria, gym, aux   2   Comments   1,00  Very unsatisfactory - AV not present in one or more space   Unsatisfactory - AV undersized for room. Poor condition Average - AV adequately sized / poor condition OR AV undersized / overage condition.  Satisfactory - AV adequately sized for room. Excellent condition.  Does not apply   Comments   Cafeteria A/V looks old.  Not counted toward overall technology score.  Cafeteria A/V looks old.  Cafeteria A/V looks old.  Not counted toward overall technology score.

15 - Administration Spaces	1	2	3	4	5	N/A		20.00	45%
15.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
1 Very unsatisfactory - No security checkpoint 2 Unsatisfactory - Checkpoint is too small, poor condition 3 Average - Needs updates or renovations to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									•
15.2 Does the administration area feel welcoming?			3				Comments	1.00	3.00
1 Very unsatisfactory - No welcome space 2 Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition 3 Average - Adequate size and layout, needs updates or					l		Adequate size but no seating and doesn't feel welcome		
renovations to feel welcoming 4 Satisfactory - Good size and layout, good lighting and transparency, informal seating provided 5 Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition									
N/A Does not apply  For those spaces that require it, does the administration area have adequate acoustic privacy?			3				Comments	1.00	3.00
Very unsatisfactory - No acoustic separations     Unsatisfactory - Acoustic separations do not perform     well     Average - Some acoustic separations function okay, but     portions need updates or renovations     Satisfactory - Good acoustic separations     Very Satisfactory - Excellent acoustic separations     N/A									
15.4 Are conference rooms easily accessed for public / parent use?	1						Comments	1.00	1.00
Very unsatisfactory - Not accessible for public/parent use      Unsatisfactory - Limited access, no transparency, poor condition, difficult to find      Average - Adequate accessibility, needs updates or renovations to function well      Satisfactory - Good accessibility, good transparency,									
good size and condition  5 Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A Does not apply									