

# **Educational Suitability Summary Report**

Zilker Elementary School

Date: 12/10/2020 Score 52% Average

Zilker Elementary School serves an enrollment of approximately 440 students in south Austin on Bluebonnet Lane. The school was built in 1950 and has been a fixture in the education of many young children of south Austin. While the building and grounds are beloved by some, the current school building has many challenges. Accessibility, poor HVAC, limited space for collaboration and storage are just a few of the issues facing the school.

There are two wings of the school that utilize exterior breezeways for circulation. This characteristic prohibits collaboration space between studios. The space between the wings is used for spill-out space, but its use is weather-dependent and requires upgrades to function well. The gym is undersized per the Ed Spec, and the kitchen and servery areas are also very undersized.

The school is utilizing portables for special education, second- and third-grade studios, and speech. While this assessment does not cover the portables, it is assumed that spaces in portables will be found deficient.

#### Interview Overview

The interview took place on campus with Principal Hill and administrative assistant Beth Ferry. Numerous challenges and issues were brought up around both the facility's condition as well as educational suitability. On the exterior of the building and due to site constraints, there are many challenges. There is not enough parking for staff. Bus circulation and pickup and drop-off all occur within the same small parking lot off of Rundell Place. With inadequate queueing space for pickup and drop-off, a line of cars blocks traffic on Rundell Place all the way to Bluebonnet Lane.

General accessibility of the campus is also an issue. There is a chair lift at the five steps in the main corridor that requires a key to be operated. Accessibility in the restrooms and the limited number of adult restrooms was also mentioned.

The garden at the school is well-loved and is a source of pride for the school. The playground is adequate but is too small for several classes at once. The playground also does not have any shade.

The interior of the building has some characteristics that the school likes. The breezeways seem to be both an attribute and a source of problems. The studios along the breezeways require all students to go outside to use the restroom at the end of the wing. The studios along the breezeway have very

## **Educational Suitability Summary Report**

Zilker Elementary School

little storage. HVAC units have been placed in the studios and take up valuable square footage and block windows. In general, all studios have satisfactory access to natural daylight and that is one aspect of the school that is seen as an asset of the current building.

The school supports the Six C's through the use of its STEAM lab and outdoor learning with its garden and general connectivity with the greater community. Collaboration spaces are lacking in the school. The interview attendees highlighted this issue multiple times. They requested more common-use spaces for students to gather and collaborate. They envision more after-school club and enrichment opportunities and would love for the cafeteria to function better for events and performances. The stage and A/V equipment are substandard and do not function well. A dedicated community space would be a huge asset to be used by students and their families.

The school is also used as voting precinct. The principal sees this as a positive for students to see democracy in action.

The library -- since it is a separate building -- can be used for afterhours meetings.

### **Assessment Findings**

The Educational Suitability Assessment of Zilker Elementary earned a 52% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

#### **Very Unsatisfactory Categories (0-35%):**

#### **PE and Wellness**

Score is very unsatisfactory.

Gym is very undersized, with no natural daylight, and does not have adequate support space or restrooms.

## **Unsatisfactory Categories (36-50%):**

#### **Exterior**

Score is unsatisfactory.

Bus circulation and pickup and drop-off are not separate and queueing space is nonexistent.

#### **General Building**

Score is unsatisfactory.

There are not adequate community-use areas. Outdoor breezeways create some challenges for moving students throughout the school, and the general appearance of the school is dated.

#### Security

Score is unsatisfactory.

### **Academics & Learning**

## **Educational Suitability Summary Report**

Zilker Elementary School

Score is unsatisfactory.

Studios are undersized. Support and storage are not consistent and undersized. Collaboration spaces are not present.

### **Visual and Performing Arts**

Score is unsatisfactory.

Art room and music room are undersized. Stage area does not function well.

#### **Food Services**

Score is unsatisfactory.

Kitchen and servery are very undersized. Cafeteria is dated. There is no chair storage, so any outside events require people to sit at the child-size cafeteria tables.

#### **Technology**

Score is unsatisfactory.

Inadequate charging/outlets in all studios for 1-to-1 devices. A/V in cafeteria and gym is unsatisfactory.

### **Administration Spaces**

Score is unsatisfactory.

The

reception is dated and does not feel welcoming. The conference room in the Admin space is small and does not function well.

### Satisfactory Categories (66-80%):

#### **Outdoor Learning and Activity**

Score is satisfactory.

Excellent gardens and well maintained. Cistern present but not currently hooked up. There is only one playground, and there is no shade.

### **Environmental Quality**

Score is satisfactory.

All studios have access to natural daylight.

### **Controllability of Systems**

Score is satisfactory.

All studios have thermostats and multilight switching.

## Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture is age appropriate and separate tables/chairs and in satisfactory condition.

#### **Media Resources**

Score is satisfactory.

Library had different areas for small/medium-size groups to gather but not acoustically separate. Technology was adequate.



Outdoor Gardens: Well-tended and source of pride for the school.



Outdoor Gardens and Husbandry: Chicken coop in the same area.



Media Center: Provides different seating areas.



Media Center: Access to technology and multiple seating options.





Stage and A/V in poor condition. Cafeteria SF accommodates 1/3 of learning population but is dated and doesn't function well in hosting events. School doesn't have storage available for adult-sized chairs.



Kitchen/servery is undersized and does not meet current Ed Spec standards.








Storage is not consistent in all the studios. Entire school lacks storage spaces.

## **Supporting Photographs**





Breezeway circulation has some challenges. Requires student to go outside to use restroom. Outdoor space is utilized for spill-out/workspace. Ground improvements are needed to make it accessible and more fully utilized.



School noted many issues with pests/vermin.



# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
Zilker Elemetary School	Lynn Petermann / Kelly McEachern	12.07.20

- Ext	erior		1	2	3	4	5	N/A	A	8.75	40%
11	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							All pickup/drop-off and bus circulation happen in the	same small p	arking
	2	at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated							lot off of Rundell Lane without any queueing space. The Rundell Place. The staff/teacher parking lot is also und		up into
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
12		ing easily identified with appropriate signage and wayfinding?		2					Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage / wayfinding							An average school marquee sign, but no signage on p staff parking.	oickup/drop-c	off or
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible									
		and easy to use									

Perkins&Will 02/11/2022 <sup>2</sup>

1 - E	xterior (cor	nt.)	1	2	3	4	5	N/A	1		
1.3	Is the dump	ster accessible for trash / compost disposal?				4			Comments	0.50	2.00
	1 2 3	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.  Satisfactory - Compost and dumpster are directly adjacent and route is barrier free							All in line and barrier free.		
	5 N/A	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.  Does not apply									
2-0	,	arning and Activity	1	2	3	4	5	N/A		15.00	73%
2.1		r studios and support spaces appropriately configured per	<u>'</u>			4		IN/ A	Comments	1.00	4.00
	1 2 3 4	Very unsatisfactory - No dedicated outdoor studios  Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided  Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area  Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area  Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Between the 400 and 500 wing, there is nice outdoo were working outside. Seating to accommodate a ful	_	
	N/A	Does not apply playgrounds (elementary only) and support spaces					1		1		
2.2		per the ed spec?		2					Comments	1.00	2.00
	1 2 3	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs							In average shape, but only 1 playground for all grade structure. Shade structure is over ball court.  The playground lacks options for older students (e.g.		e
	4 5	some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full									
	N/A	shade coverage over play structure  Does not apply									

2 - O	utdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A			
2.3	_	s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)					5		Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Recording answer, does not affect score of Outdoor L Welcoming gardens and in excellent condition. A poil school. Chicken coop is also there.	•	•
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access Satisfactory - Good size, good condition, connected to									
	5	learning spaces, good flexibility, water source is accessible with 100 ft hose									
	3	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rained spec?	gardens and/or cisterns appropriately configured per the		2					Comments	0.00	0.00
	1 2	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not							Recording answer, does not affect score of Outdoor L Cistern is present in the front but has been disconnec	•	•
	3	functioning, disconnected  Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply									
2.5	Does the sc	hool have animal husbandry? (optional)					5		Comments	0.00	0.00
	1 5	No Yes							Chickens		
2.6	Does the sc	hool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes							,		
2.7		hool have a learning pond? (optional)	1						Comments	0.00	0.00
	1	No									
2.8	Door thous	Yes hool have a grass play field and walking trail?					5		Comments	1.00	5.00
2.6	Does the sc	No					5		Comments In adjacent Little Zilker Park	1.00	5.00
	5	Yes							in dajacont Little Zinter i dik		

3 - General Build	ling	1	2	3	4	5	N/A	1	11.25	40%
3.1 Are interior cir	rculation routes wide enough to safely and effectively			3				Comments		
accommodate	e student movement?			3				Comments	0.50	1.50
1 \	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Main corridor is generous (10'+). Other corridors are a	outdoor breeze	ways.
	wide							Assigning a 3 because there are 5 steps that need to	be navigated r	near
	Jnsatisfactory - Primary circulation is 6'-0" to 7'-0" wide							the office to continue into the school. There is a chair	lift but it requi	res a
3 A	Average - Primary circulation is 7'-0" to 8'-0" wide							key and does not create an equitable entry into the s	chool.	
4 9	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 \	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A [	Does not apply									
Are communit	ty use areas arranged so that the school can allow night									
3.2 functions with	nout full school access?		2					Comments	0.75	1.50
1 \	Very unsatisfactory - Cafeteria, gym, and library cannot						•	Only library can be assessed after hours.		
k	pe accessed after hours									
	Unsatisfactory - Only one of the public spaces (Cafeteria,									
	Gym and Library) can be accessed from parking and									
	secured after hours									
	Average - Only two of the public spaces can be accessed									
	from parking and secured after hours									
	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building									
	out not individually									
	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
	Does not apply									
ls there a com	nmunity room that is a dedicated meeting space outside	_								
3.3 of school func	ction?	1						Comments	0.75	0.75
1 \	Very unsatisfactory - No dedicated community room						•			
2 (	Unsatisfactory - Community room but within school									
	function, no access after school hours									
	Average - Community room, moderate size, but need									
	some renovations or updates to function well									
	Satisfactory - Community room, good size /layout, meets needs /functions well									
	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
	function									
N/A [	Does not apply									
3.4 Does the gene	eral appearance of the school convey pride for the			3				Comments		
students and	community?			3				Comments	0.25	0.75
	Very unsatisfactory - General appearance is poor							Nice old-growth trees on lot. School is in average sho	pe for the mai	n
	Unsatisfactory - General appearance is aged but ok							portion being 70 years old. Garden condition improv	es appearance	of
	Average - General appearance is good							school.		
	Satisfactory - General appearance shows pride in									
	campus and student works									
	Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the									
	community									
	Does not apply									

	4 - Security		_1	2	3	4	5	N/A		16.25
	4.1 Does the fa	cility have key card access at all major entries?							Comments	0.25
	1	Very unsatisfactory - No entries								
	2	Unsatisfactory - 1/4 of major entries								
	3	Average - 1/2 of major entries								
	4	Satisfactory - 3/4 of major entries								
	5	Very satisfactory - All of major entries								
	N/A	Does not apply								
	4.2 How adequ	ate is site lighting and security for the campus overall?							Comments	1.00
	1	Very unsatisfactory - No exterior lighting, no secure perimeter								
	2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal								
	3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate								
	4	Satisfactory - Lighting at all night-use entries and								
		parking lots, good condition, signage less visible,								
		perimeter is well secured but needs updates								
	5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
	N/A	Does not apply								
	ls the main	office located at the school entry and configured with a							Community	
	4.3 secure vesti	bule to the main corridor?							Comments	1.00
	1	Very unsatisfactory - No secure vestibule, office located								
		far from main entry, allows visitors access to school								)
		unsupervised								•
	2	Unsatisfactory - No secure vestibule, office located								
		somewhat far from main entry, minimal supervision of								
	•	visitors								
	3	Average - Office close to entry, views of front door, but								
	4	no secure vestibule Satisfactory - Office is well-located with a secure								
	4	vestibule, but needs updates								
	5	Very satisfactory - Office well-located with secure								
	J	vestibule and all appropriate security features								
	N/A	Does not apply								
ı		ough interior transparency for faculty to passively supervise		1						
		d their activities who are not in studios?		2					Comments	1.00 2.00
	1	Very unsatisfactory - No transparency of walls							There is some transparency and because most of the	classrooms open to
	2	Unsatisfactory - Limited transparency in certain locations							the exterior and there are windows in all the classroc passive supervision outside.	oms, there can be
	3	Average - Good transparency in certain locations but								
		inadequate or missing in other locations of school								
	4	Satisfactory - Adequate transparency throughout the school								
	5	Very satisfactory - Excellent transparency throughout the school								
	N/A	Does not apply								

Perkins&Will 02/11/2022 <sup>6</sup>

5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	68%
5.1 How are a	coustics in studios in general?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Many studios had their doors and windows opened the nice weather.	to the exterior o	due to
·	o artificial lighting adequate quality?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there acc	ess to natural light in studios?					5		Comments	1.00	5.00
1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							Nice large windows to exterior.		
N/A	Does not apply									
5.4 Is there acc	vess to outside views from learning spaces?  Very unsatisfactory - No learning spaces have views					5		Comments	1.00	5.00
2 3 4 5	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out  Average - 26-50% of learning spaces have views  Satisfactory - 51-75% of learning spaces have views  Very satisfactory - 76-100% of learning spaces have views  Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	ouilding have odor or pest problems?	1						Comments	1.00	1.00
1	Very unsatisfactory - Evidence of both pests and odors							The school reports numerous issues with pests in all p	arts of the build	ding.
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	A	12.50	76%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No							Individual control, but school has a lot of HVAC issues	S.	
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?			3				Comments	1.00	3.00
1	Very unsatisfactory - No, windows are covered with							Blinds are very dated and not in good shape.		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply	,					,	<del>,</del>		
6.3 What is the	e quality of lighting controls in the studios?				4			Comments	1.00	4.00
1	Very unsatisfactory - Single switch only per room							Each row can individually switch on and off.		
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, F	Fixtures & Equipment	1	2	3	4	5	N/A		18.75	75%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply									
1 / ')	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
1 2 3	Very Unsatisfactory - Same furniture used in all spaces  Unsatisfactory - Furniture variety in one multi-use space  Average - Furniture variety in more than one multi-use space							Dining - same furniture. Library has new updated fur	niture.	
5 N/A	Satisfactory - All multi-use spaces have greater than one type of furniture  Very satisfactory - All multi-use spaces have greater than two types of furniture  Does not apply									
7.3 How well of space?	does furniture accommodate rapid reconfiguration of a				4			Comments	1.00	4.00
1 2	Very Unsatisfactory - Furniture is fixed or very heavy  Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
3 4 5	Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
N/A 7.4 Is the furni	Does not apply iture ergonomic and size appropriate for grade level?				4			Comments	100	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level  Unsatisfactory - Desk with attached chair combinations  Average - Mix of studios with tables/loose chairs and desks with fixed seats  Very satisfactory - Tables with loose chairs  Very satisfactory - Tables with loose chairs that allow students to be active  Does not apply								1.00	4.00

Perkins&Will 02/11/2022 <sup>9</sup>

Waste	1	2	3	4	5	N/A	5.00	:
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?			3				Comments 0.50	
<ol> <li>Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.</li> <li>Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.</li> <li>Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.</li> <li>Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.</li> <li>Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.</li> <li>N/A Does not apply</li> </ol>							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?						N/A	Comments 0.50	
1 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. 3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. 4 Satisfactory- There are several waste stations as described above 5 Very Satisfactory - There are several waste stations as							A score for this category is being recorded, but this category is not calculated in the overall ESA average.  Difficult to ascertain due to covid restrictions.	:
described above, and additional signage in the cafeteria that encourages recycling/composting.								



# Austin ISD Educational Suitability Assessment Criteria

**Academics - Elementary School** 

School Name	Walk Attendees:	Date:
Zilker Elementary School	Lynn Petermann / Kelly McEachern	12.07.20

8 - Aca	demics	& Learning	1	2	3	4	5	N/A	4	70.00	37%
8.1 A	re studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1 2 3	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited							Studios off of the breezeways are too small and SF is to mechanical units in each room. Due to nature of breeze classroom opens up to exterior, creating challenges.  Studios in 100 / 200 wing (with internal corridor) are 87 adequate storage and accessible restrooms.	eway, each	
		transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
27		and Kinder have appropriate support spaces such as and storage per the ed spec?			3				Comments	1.00	3.00
	1 2	Very unsatisfactory - None provided  Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4 5	Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
	N/A	condition Does not apply									

Perkins&Will 02/11/2022 <sup>2</sup>

8		& Learning (cont.)	1	2	3	4	5	N/A			
	8.3 Do studios ed spec?	have appropriate support spaces such as storage per the		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - None provided  Unsatisfactory - Too small, disconnected, poor condition  Neutral - Adequate size, average condition, needs updates or renovations to function well  Satisfactory - Good size, connected, good condition  Very Satisfactory - Generous size, connected, excellent condition  Does not apply							Storage throughout school is almost nonexistent. Bat issue throughout the school. Wing 400 and 500 stud to use the restroom. Wing 200 has restrooms internal small and not accessible.	hroom access i ents must go o	s an utside
Ī	8.4 Do typical I	learning neighborhoods have small group rooms and open	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy Does not apply							No interior collaboration space is provided.		
ľ	Are genera	Il studios large enough to support project-based learning le teaching modalities?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - Too small, no flexibility, does not support project-based learning Unsatisfactory - Undersized, decentralized resources, limited flexibility Average - Adequate size, needs some renovations or updates to function well Satisfactory - Good size, centralized resources, good flexibility Very Satisfactory - Generous size, centralized project resources, excellent flexibility						,			
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>3</sup>

8 - A	Academics 8	1	2	3	4	5	N/A	4			
8.6		Spaces and support spaces appropriately configured per			3				Comments		
	the ed spec									1.00	3.00
	1	Very unsatisfactory - No dedicated maker spaces							No dedicated maker space. Adjacent to the library is	a nice dedicat	:ed
	2	Unsatisfactory - Too small, poor condition, disconnected							STEM classroom.		
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply		1							
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply									
0.0	la thara a di	edicated science room and support space?	1						Comments		
0.0	is there a ac	edicated science room and support space:	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
	Are there a	dequate places to display the evidence and artifacts of									
8.9		oth 2D and 3D)?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No dedicated space									
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	NI/A	Door not apply									

Perkins&Will 02/11/2022 <sup>4</sup>

8 - A	cademics	1	2	3	4	5	N/A	i i			
8.10	Does the b	uilding provide adequate opportunities for		0					Comments		
8.10	students/te	eachers to collaborate in varying group sizes?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space to support collaboration							Only really available at the exterior between the win	gs.	
		in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple									
		options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply									
8 11	Does the b	uilding provide opportunities for informal interaction?		2					Comments		
									33	1.00	2.00
	1	Very unsatisfactory - No space									
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
	5	furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
		earning neighborhood / building provide adequate		I							
8.12		ies for students to work independently?	1						Comments	1.00	1.00
	оррогили	Very unsatisfactory - No breakout rooms/small study								1.00	1.00
	'	spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic									
	2	privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
	3	or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
	7	variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply							L		

02/11/2022 <sup>5</sup>

8 - A	cademics	& Learning (cont.)							
8.13	Are Special spec?	Education spaces appropriately configured per the ed		2			Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected					Undersized at 820 SF.		
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
8.14		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?		2			Comments	1.00	2.00
	1	Very unsatisfactory - None provided		•			Storage is inadequate. Washer/dryer not observed.		
	2	Unsatisfactory - Too small, disconnected, poor condition							
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
8.15		ble restrooms and changing rooms readily available to the location spaces?	1				Comments	1.00	1.00
	1	No							
	5	Yes							

Perkins&Will 02/11/2022 <sup>6</sup>

9 -	· Visual and I	Performing Arts	1	2	3	4	5	N/A	4	15.00	40%
9	.1 Are music s	paces and the cafeteria stage appropriately configured pec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Music room is in regular classroom.		
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
9	.2 Are music a per the ed s	nd performance storage spaces appropriately configured spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided							Cafeteria stage is not adequate. A/V is problematic.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	N/A	condition Does not apply									
	Are Visual A	arts spaces and storage appropriately configured per the	1				l				
9	.3 ed spec?	it a spaces and storage appropriately configured per tile		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Art is in regular classroom. No kiln.		
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

10 - PE and Wel	Iness	1	2	3	4	5	N/A		10.00	30%
1 10 1	mpus meet the ed spec standard for physical education	1						Comments		
program spo	dces?								1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces							Gym is only 2,200 SF and has no natural daylight or v	windows.	
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
1102	sical education storage spaces appropriately configured		2					Comments		
per the ed sp			_						1.00	2.00
1	Very unsatisfactory - None provided							Storage is undersized. Restrooms are not within gym	and require ch	ildren
2	Unsatisfactory - Too small, disconnected, poor condition							to go to adjacent wing.		
3	Neutral - Adequate size, average condition, needs									
,	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
N/A	condition Does not apply									
11 - Food Service	,	1	2	3	4	5	N/A		10.00	40%
11 - 1 000 361 110	5	•		3	_		19/7		10.00	40%
	Commons appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - Too small, missing program spaces							Cafeteria accommodates 1/3 of learner population a poor condition.	t 17 SF/person I	but is in
2	Unsatisfactory - Too small, poor condition, only one									
	option for eating space provided, inadequate circulation									
•										
3	Average - Adequate size and condition, needs updates									
4	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to									
	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition									
ŭ	and circulation, multiple options for eating space (ex:									
	connection to outdoor eating space)									
N/A	Does not apply									
Are the Food	d Services support spaces appropriately configured per		2					Comments		
the ed spec?			_					Comments	1.00	2.00
1	Very unsatisfactory - None provided							Kitchen/servery is very undersized at 1,300 SF. No sta	orage for	
2	Unsatisfactory - Too small, disconnected, poor condition							chairs/stage. Stage is adequate size but chair lift take	es up a lot of sp	oace.
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

12 - Media Resources	1	2	3	4	5	N/A	4	30.00	70%
12.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?					5		Comments	1.00	5.00
Very unsatisfactory - Not accessible     Unsatisfactory - Limited access, difficult to find, no     transparency     Average - Adequate accessibility, needs updates or     renovations to function well							Since library is separate building, the library can be a opening up the school.	ccessed withou	ut
4 Satisfactory - Accessible, easy to find, good transparency, good condition 5 Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A Does not apply									
12.2 How well does the Library/Media Center support quiet study?			3				Comments	1.00	3.00
<ol> <li>Very unsatisfactory - No quiet study spaces</li> <li>Unsatisfactory - One area in poor condition, poor acoustic privacy</li> </ol>							There is space to create quiet study nooks but current way.	ly not used in t	this
3 Average - One or more areas provided, needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1 Very unsatisfactory - No space							Updated furniture and generous seating areas.		
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.  4 Satisfactory - Good size, good condition, layout and									
4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply									
How well does the Library/Media Center support collaborative work			3				Comments		
12.4 in small groups (4-8 students)?			3				Comments	1.00	3.00
<ol> <li>Very unsatisfactory - No breakout rooms, no flexible</li> </ol>							Built-ins for small groups at the windows.		· · · · · ·
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
3 Average - Adequate size, multiple areas provided,									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

12 - Media Resources - Continued	1	2	3	4	5	N/A			
How well does the Library/Media Center support collaborative work			3				Comments		
in larger groups (10-25)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No gathering areas									
2 Unsatisfactory - Too small, one common space, limited									
seating, poor condition									
3 Average - Adequate size, one common space, needs									
updates or renovations to function well									
4 Satisfactory - Good size, multiple common spaces with									
seating, good condition									
5 Very Satisfactory - Generous size, multiple commons									
spaces with seating, excellent condition									
N/A Does not apply									
12.6 How well does the Library/Media Center support technology?			3				Comments		
			Ŭ				Commente	1.00	3.00
1 Very unsatisfactory - No vis comm tools									
Unsatisfactory - Outdated, poorly functioning, or									
insufficient									
Good - Mix of old and new whiteboards/projectors/etc.									
4 Satisfactory - Projectors, marker boards, smart boards in									
most spaces - good condition									
5 Very Satisfactory - Projectors, marker boards, smart									
boards in most spaces - new condition									
N/A Does not apply									
13 - Technology	1	2	3	4	5	N/A		20.00	50%
13.1 How well equipped are the facilities with instructional technology?			_			Ī		Ι	
13.1 How well equipped are the racilities with instructional technology:			3				Comments	1.00	3.00
1 Very unsatisfactory - Limited to no technology present in									
instructional spaces									
Unsatisfactory - One type of technology present									
3 Average - Multiple types of technology, smart boards,									
poor condition, limited to only certain areas of school									
4 Satisfactory - Multiple types of technology, smart									
boards, good condition.									
5 Very Satisfactory - Multiple types of technology, smart									
boards, excellent condition									
N/A Does not apply									
ls there an adequate number of power and data outlets in learning		2					Comments		
spaces?							Comments	1.00	2.00
Very unsatisfactory - Outlet configuration does not							Inadequate charging/outlets in all studios.		
support digital devices throughout school (1 per wall)									
Unsatisfactory - Outlet configuration support digital									
devices only in certain areas of school (2 per wall)									
Average - Outlet configuration support digital devices									
but not enough capacity throughout school (3 per wall)									
4 Satisfactory - Outlet configuration support digital									
devices with adequate coverage and capacity									
throughout school (>3 per wall)									
5 Very Satisfactory - Excellent outlet configuration to									
support digital devices throughout school (>3 per wall)									
N/A Does not apply									

02/11/2022 <sup>10</sup>

13 - Technology (cont.)		1	2	3	4	5	N/A			
13.3 Are there adequate charging locations for devices?				3				Comments	1.00	3.0
1 Very unsatisfactory - No centralized ch	arging location	•								
2 Unsatisfactory - Centralized charging l										
inadequate in size for number of device										
3 Average - Charging cart or tower but r sized for number of devices	ot adequately									
4 Satisfactory - Charging cart or tower n	ot centralized									
5 Very Satisfactory - Charging cart or to										
centralized location. Excellent condition	า									
N/A Does not apply						1				
13.4 Is there adequate AV for presentations spaces – caf	eteria and gym?		2					Comments	1.00	2.00
1 Very unsatisfactory - AV not present in	one or more					•		A/V at cafeteria stage is old and not good shape.		
space										
Unsatisfactory - AV undersized for roor	n, poor condition									
3 Average - Adequately sized / poor con	dition OR AV									
undersized / adequate condition										
4 Satisfactory - Good size, good condition										
5 Very Satisfactory - Generous sized, exc	ellent condition									
N/A Does not apply		- 1			ı			T		
13.5 Is there digital media signage at the reception area	?	1						Comments	0.00	0.00
1 Very unsatisfactory - No digital media	present in							Does not affect score.		
reception area										
<ul> <li>Unsatisfactory - Undersized, poor cond</li> <li>Average - Adequately sized / poor cond</li> </ul>										
undersized / adequate condition	dition ok									
4 Satisfactory - Media signage present, condition	good sized, good									
5 Very Satisfactory - Generously sized, ex	cellent condition									
N/A Does not apply										

14 - Administration Spaces	1	2	3	4	5	N/A		20.00	45%
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
Very unsatisfactory - No security checkpoint  Unsatisfactory - Checkpoint is too small, poor condition				•					
Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
14.2 Does the administration area feel welcoming?		2					Comments	1.00	2.00
Very unsatisfactory - No welcome space  Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition		I	l	•	·		Small and does not have visitor seating or feel particu	ularly welcomi	ng.
<ul> <li>Average - Adequate size and layout, needs updates or renovations to feel welcoming</li> <li>Satisfactory - Good size and layout, good lighting and transparency, informal seating provided</li> <li>Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition</li> </ul>									
N/A Does not apply  For those spaces that require it, does the administration area have		1		T	l				
14.3 adequate acoustic privacy?		2					Comments	1.00	2.00
1 Very unsatisfactory - No acoustic separations 2 Unsatisfactory - Acoustic separations do not perform well 3 Average - Some acoustic separations function okay, but portions need updates or renovations 4 Satisfactory - Good acoustic separations 5 Very Satisfactory - Excellent acoustic separations							Due to HVAC issues, half of the admin suite doesn't had and requires doors to stay open.	ave heating or	cooling
N/A Does not apply		1		1	ı				
14.4 Are conference rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
1 Very unsatisfactory - Not accessible for public/parent use 2 Unsatisfactory - Limited access, no transparency, poor condition, difficult to find 3 Average - Adequate accessibility, needs updates or renovations to function well 4 Satisfactory - Good accessibility, good transparency, good size and condition 5 Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition							Within admin suite. Not easily accessible.		