

Educational Suitability Summary Report

Baranoff Elementary School

Date: 12/15/2020 Score 64% Average

Baranoff Elementary School serves an enrollment of approximately 840 students in south Austin. It was built in 1999, with an additional building built in 2008, and consists of approximately 80,000 square feet on 16 acres. The school's exterior appearance could use an update, and improved signage and wayfinding would be helpful.


The school does not have adequate space for all the programs and students. Numerous programs are housed in portables, and there is limited flex space within the school. Second- and fifth-grade wings have common areas between the studios, which are well used and help give teachers flexibility to teach in varying group sizes.

The campus is well-sized with ample green space and play areas for students. The existing outdoor studio needs upgrades to function better. The pond on campus is a great resource, but it could be improved with permanent infrastructure that would make it usable in all weather.

Interview Overview

The interview with Principal Cantu, staff and parents at Baranoff Elementary provided great insights into what is working and what areas need improvement. They are proud of their campus grounds and the unique amenities and learning spaces they have, including a water cistern and informational display created as a Boy Scout project. They enjoy the outdoor deck near the music and art rooms for outdoor learning.

The teachers and staff are making do with the spaces that they have, but repeatedly brought up the need for additional space in the interview. They want more flexible learning spaces like they have in the second- and fifth-grade studio wings. They believe that these flexible spaces will be essential for teaching and learning in the future. In addition, they would like to have a space for pre-K, an early childhood special education program, and even a daycare for teachers with small children.



Assessment Findings

The Educational Suitability Assessment of Baranoff Elementary School earned a 64% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Educational Suitability Summary Report

Baranoff Elementary School

Unsatisfactory Categories (36-50%):

Food Services

Score is unsatisfactory.

Cafeteria is 3,800 square feet but based on current enrollment should be 4,800 square feet. There is no access to natural light or the outdoors. The kitchen is adequately sized and has two serving lines. There is no chair storage and only a very small room for stage storage.

Administration Spaces

Score is unsatisfactory.

The reception area is small

and acoustics can be poor. There is one small conference area in the back of the admin suite, which is not easily accessible for visitors. The teacher's lounge is also too small for the staff.

Average Categories (51-65%):

General Building

Score is average.

Interior corridors are between 8 and 10 feet wide, with two of the learning neighborhoods having a larger, shared-corridor flex space. The library, cafeteria and gym can all be closed off from the rest of the school to allow for after-hours functions.

Security

Score is average.

Controllability of Systems

Score is average.

Studios have individual thermostat controls and blinds to control natural light. Lighting is controlled by only one switch, which does not allow for any varied lighting.

Academics & Learning

Score is average.

Studios are appropriately sized but have limited transparency. All standard studios have appropriate support spaces, but only two grade levels have access to larger learning commons in the corridors to gather in groups of varying sizes. There is limited 3D display in corridors but plentiful 2D display that is well used.

Media Resources

Score is average.

The library is close to the main entry of the school, but limited signage and transparency make it hard to find. There are no quiet study areas, and the current configuration of the stacks limits the size of

Perkins&Will

Educational Suitability Summary Report

Baranoff Elementary School

groups that can work collaboratively. More informal seating could improve opportunities for social interaction. Two projection areas and a computer station are available for group and individual use.

Technology

Score is average.

All studios have mobile TV displays and projection available. There are limited charging opportunities with only two outlets on average per wall. A/V in the cafeteria is dated and does not function properly. There is a TV for media in the front hallway.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

Bus and parent drop-off are separated in the front and rear of the school, and both have covered canopies. Building signage is visible but faded and not digital.

Outdoor Learning and Activity

Score is satisfactory.

The campus has a multilevel deck that is shaded by trees, which can be used as an outdoor dining or outdoor learning environment. The space is adequate, but the deck needs updating. Two of the three playgrounds have canopy cover, as well as the outdoor basketball court. The small garden area uses reclaimed rainwater in small cisterns, created by a student's Boy Scout project.

Environmental Quality

Score is satisfactory.

General acoustics are good. Studios are paired together with an open vestibule for shared restrooms, but it does not seem to adversely affect sound. All studios have windows and access to natural light, but with higher clerestory windows not all studios have views.

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture appears to be a mix of old and new, with some pieces showing damage. Furniture is not mobile or very flexible but is a mix of tables, desks or chairs that are appropriately sized but cumbersome to move. Multi-use spaces other than the cafeteria have more variety in furniture types and seating options.

Visual and Performing Arts

Score is satisfactory.

The music and visual arts studios have the appropriate storage and support spaces. The music studio is next to the cafeteria stage, which has an accessible ramp, but the stage needs A/V upgrades to function well.


PE and Wellness

Score is satisfactory.

Gym is average size and was being prepped to get a new floor during the assessment. There are two large storage spaces and restrooms that connect in a vestibule for both gym and cafeteria use.

Baranoff Elementary School


Supporting Photographs




Large wooden deck serves as outdoor learning or dining space but needs updates.



Cafeteria is undersized and only has one type of seating.



Gym and cafeteria are connected by an operable wall. Flooring is in process of being replaced



Corridors are mostly narrow, but two learning neighborhoods have a larger flex space to be shared by studios.

Educational Suitability Summary Report Baranoff Elementary School

Supporting Photographs



Environmental Quality: All studios have windows and access to natural light.



Media Resources: Mix of old and new furniture present, but limited space for larger groups.



Two of the three playgrounds have a canopy and are in good condition.



Small cisterns collect rainwater for the gardens. This was completed as a project for a student in Boy Scouts.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Baranoff Elementary School	Kevin Kinsey and Emilie Ogburn	12.15.2020

1 - E	xterior		1	2	3	4	5	N/A		8.75	80%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated							Two separate drop-offs at front and rear of school wi	th canopies.	
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
1.2		ing easily identified with appropriate signage and wayfinding?		2					Comments	0.25	0.50
	1	Very unsatisfactory - Campus has no signage / wayfinding							Nondigital, but lit monument sign is only site signage	. Faded.	
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									,

Perkins&Will 02/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A			
1.3	Is the dump	oster accessible for trash / compost disposal?					5		Comments	0.50	2.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped							Ramp from loading dock. All 3 grouped together.		
		/ positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - (arning and Activity	1	2	3	4	5	N/A		15.00	80%
2.1	Are outdoo the ed spec	r studios and support spaces appropriately configured per ??			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							Outdoor deck with multiple levels shaded by trees. Th	ne deck needs	
	2	Unsatisfactory - Too small, poor condition, disconnected							maintenance or upgrades.		
	3	from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area							The school noted that additional structures are unablimpervious ground cover.	le to built due	to
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply			ı		ı				
2.2		playgrounds (elementary only) and support spaces per the ed spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No dedicated active playground							Playgrounds look to be in good condition. 2/3 play a	reas are cover	ed.
	2	Unsatisfactory - Too small, poor condition, no shade									
	2	provided									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - Outdoor Learning and Activity (cont)	1	2	3	4	5	N/A	1		
Are gardens and support spaces appropriately configured per the ed			3				Comments		
spec? (evaluation on infrastructure not condition of plants)							Comments	0.00	0.00
l Very unsatisfactory - No dedicated gardens							Recording answer, does not affect score for Outdoor	Learning and	Activity.
 Unsatisfactory - Too small, poor condition, disconnected 							Small garden area visible. No infrastructure, only cist	erns.	
from learning spaces, no flexibility, no accessible water									
source									
Average - Adequate size, adequate condition, needs									
some renovations or updates to function well, water									
source is difficult to access 4 Satisfactory - Good size, aood condition, connected to									
4 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is									
accessible with 100 ft hose									
5 Very Satisfactory - Generous size, excellent condition,									
connected to learning spaces, excellent flexibility, water									
source is less than 50ft from the garden or has irrigation									
N/A Does not apply									
Are the rain gardens and/or cisterns appropriately configured per the							_		
ed spec?			3				Comments	0.00	0.00
Very unsatisfactory - No rain gardens or cisterns					ļ		Recording answer, does not affect score for Outdoor		
2 Unsatisfactory - Too small, poor condition, not							Small shed with multiple rain barrels and educationa	-	-
functioning, disconnected							benefits of rainwater collection.		
3 Average - Adequate size, adequate condition, is							Benefite of family ator consectors.		
connected, needs some renovations or updates to									
function well									
4 Satisfactory - Good size, good condition, functions									
properly									
5 Very Satisfactory - Generous size, excellent condition,									
exceptional functionality, connected to learning spaces,									
educational signage provided N/A Does not apply									
2.5 Does the school have animal husbandry? (optional)	1						Comments	0.00	0.00
1 No							Commente	0.00	0.00
5 Yes									
2.6 Does the school have nature loop trails? (optional)	1						Comments	0.00	0.00
1 No							•		
5 Yes									
2.7 Does the school have a learning pond? (optional)	<u> </u>				5		Comments	0.00	0.00
1 No							Outside of secure fence		
5 Yes	_				- E		Community	1.00	E 00
Does the school have a grass play field and walking trail? No					5		Comments	1.00	5.00
1 N0 5 Yes									

3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	58%
	circulation routes wide enough to safely and effectively ate student movement?				4			Comments	0.50	2.00
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide							Hallways between 8 and 10 feet		
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
1 3 2	unity use areas arranged so that the school can allow night				4			Comments	0.75	
functions w	vithout full school access?							Liberton and the size and arrange to the size of the first	0.75	3.00
'	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							Library, cafeteria and gym can be closed off from res		after-
2	Unsatisfactory - Only one of the public spaces (Cafeteria,							school activities. These areas can not be individually	accessed.	
	Gym and Library) can be accessed from parking and									
	secured after hours									
3	Average - Only two of the public spaces can be accessed									
4	from parking and secured after hours Satisfactory - All of the public spaces can be accessed									
7	from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply				1					
3.3 Is there a co	ommunity room that is a dedicated meeting space outside unction?	1						Comments	0.75	0.75
1	Very unsatisfactory - No dedicated community room									
2	Unsatisfactory - Community room but within school									
3	function, no access after school hours									
3	Average - Community room, moderate size, but need some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
N/A	function Does not apply									
Does the a	eneral appearance of the school convey pride for the									
	nd community?			3				Comments	0.25	0.75
1	Very unsatisfactory - General appearance is poor							Exterior paint is faded.		
2	Unsatisfactory - General appearance is aged but ok									
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
5	campus and student works Very Unsatisfactory - General appearance shows pride in									
Ü	campus and student works and is welcoming to the									
	community									
N/A	Does not apply									

4 - Security		1	2	3	4	5	N/A		16.25	
4.1 Does the fa	cility have key card access at all major entries?							Comments	0.25	
1	Very unsatisfactory - No entries									
2	Unsatisfactory - 1/4 of major entries									
3	Average - 1/2 of major entries									
4	Satisfactory - 3/4 of major entries									
5	Very satisfactory - All of major entries									
N/A	Does not apply									
								_		
4.2 How adequ	ate is site lighting and security for the campus overall?							Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure	I	1			<u> </u>				
	perimeter									
2	Unsatisfactory - Lighting is limited to front entry only,									
_	parking lot lighting poor, security is minimal									
3										
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate									
4	Satisfactory - Lighting at all night-use entries and									
4	parking lots, good condition, signage less visible,									
	perimeter is well secured but needs updates									
5										
Ŭ	Very satisfactory - Signage, parking lots, and entries are									
	well lit, visible and easy to use, perimeter is very secure									
N/A	Does not apply						Į.			
ls the main	office located at the school entry and configured with a							6 .		
4.3 secure vesti	bule to the main corridor?							Comments	1.00	
1	Very unsatisfactory - No secure vestibule, office located									
	far from main entry, allows visitors access to school									
	unsupervised									
2	Unsatisfactory - No secure vestibule, office located									
	somewhat far from main entry, minimal supervision of									
•	visitors									
3	Average - Office close to entry, views of front door, but									
4	no secure vestibule Satisfactory - Office is well-located with a secure									
4	vestibule, but needs updates									
5	Very satisfactory - Office well-located with secure									
J	vestibule and all appropriate security features									
N/A	Does not apply						Į.			
ls thoro one	augh interior transparency for faculty to passively supervise	ı								
	d their activities who are not in studios?		2					Comments	1.00 2	.00
1	Very unsatisfactory - No transparency of walls	l .						Limited transparency. Only small window in each stu		.00
·								clifficed transparency. Only sitial will dow in each sta	alo door.	
2	Unsatisfactory - Limited transparency in certain locations									
3	Average - Good transparency in certain locations but									
4	inadequate or missing in other locations of school									
4	Satisfactory - Adequate transparency throughout the									
5	school Very satisfactory - Excellent transparency throughout the									
5	school									
N/A	Does not apply									
14/7	2 000 0,577									

5	- Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	76%
	5.1 How are ac	coustics in studios in general?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							In general acoustics are very good. Studio pairs are c	pen to each ot	ther.
	5.2 Is the studio	o artificial lighting adequate quality?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply							Ample natural light in studios.		
	5.3 Is there acc	ess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply							All studios have windows.		
	5.4 Is there acc	ress to outside views from learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply							Majority are clerestory windows, which limits views.	1.00	0.00

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	N.		
5.5 Does the b	uilding have odor or pest problems?			3				Comments	1.00	3.00
1	Very unsatisfactory - Evidence of both pests and odors		•	•			•			
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	\ \	12.50	60%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with							Mini blinds in all studios look to be in good condition.		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room							On or off.		
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							'		

7 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A		18.75	71%
7.1 What is the current condition of the furniture?			3				Comments	0.75	2.25
 Very unsatisfactory - Damaged or broken, non- 							Furniture is old and some is damaged.		
functioning									
2 Unsatisfactory - Torn/ bent/ wrong size 3 Average - Scratched/dented/marked									
4 Satisfactory - Not new, but sturdy and clean									
5 Very satisfactory - New									
N/A Does not apply				1	ı		I		
Are a variety of furniture types being accommodated throughout the							_		
7.2 school - learning commons, dining commons, other multi-use spaces?			3				Comments		
								1.00	3.00
1 Very Unsatisfactory - Same furniture used in all spaces							Multi-use spaces other than cafeteria have multiple s	eating types.	
2 Unsatisfactory - Furniture variety in one multi-use space									
orisatisfactory - Latritude variety in one filulit-use space									
3 Average - Furniture variety in more than one multi-use									
space									
4 Satisfactory - All multi-use spaces have greater than one									
type of furniture 5 Very satisfactory - All multi-use spaces have greater than									
two types of furniture									
N/A Does not apply									
7.3 How well does furniture accommodate rapid reconfiguration of a			3				Comments		
7.3 space?			3				Comments	1.00	3.00
1 Very Unsatisfactory - Furniture is fixed or very heavy							Mix of furniture but none is mobile.		
Unsatisfactory - Furniture does not allow desks to be									
configured as individuals, small groups, or large groups									
3 Average - Mix of furniture that can reconfigure but is									
cumbersome to move 4 Satisfactory - Furniture is flexible for multiple									
4 Satisfactory - Furniture is flexible for multiple configurations of space									
5 Very satisfactory - Furniture is flexible for multiple									
configurations of space, easy to move and stack									
N/A Does not apply									
					_		6 .		
7.4 Is the furniture ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
Very unsatisfactory - Desk with attached chair							Tables with loose chairs appropriately sized per grade	e level.	
combinations too small for grade level									
2 Unsatisfactory - Desk with attached chair combinations									
3 Average - Mix of studios with tables/loose chairs and									
desks with fixed seats									
4 Very satisfactory - Tables with loose chairs									
5 Very satisfactory - Tables with loose chairs that allow									
students to be active									
N/A Does not apply									

Perkins&Will 02/11/2022 ⁹

Waste		1	2	3	4	5	N/A	5.00	4
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?			3				Comments 0.50	
1 2 3 4 5	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this category is not calculated in the overall ESA average. Blue bins present, but no signage.	
of each: gr	Does not apply afeteria (or wherever meals are served) have at least one reen compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?	1						Comments	
2	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close							A score for this category is being recorded, but this category is not calculated in the overall ESA average. None present at time of tour.	



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Baranoff Elementary School	Kevin Kinsey and Emilie Ogburn	12.15.2020

8 - Academics	& Learning	1	2	3	4	5	N/A		70.00	51%
8.1 Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, no flexibility, disconnected							Studios are 850 sf. Limited transparency.		
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A	Does not apply									
ν,	and Kinder have appropriate support spaces such as and storage per the ed spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							Kindergarten has attached restrooms and storage.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

Perkins&Will 02/11/2022 ²

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A	\		
8.3		nave appropriate support spaces such as storage per the				4			Comments	_	
0.0	ed spec?					7			Comments	1.00	4.00
	1	Very unsatisfactory - None provided							Storage and restroom attached to most studios.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open		2					Comments		
0.4	collaboratio	on space?							Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms or open							Only fifth and second grades have open collaboration	n spaces.	
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	_	acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
	NI/A	neighborhood, acoustic privacy									
	N/A	Does not apply	1	1	1	l	l	П	T	<u> </u>	
8.5	•	studios large enough to support project-based learning e teaching modalities?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, does not						1	Good size.	1.00	3.00
	ı	support project-based learning							Good size.		
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or									
	v	updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply							•		

Perkins&Will 02/11/2022 ³

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6	Are Maker S	Spaces and support spaces appropriately configured per		2					Comments		
8.0	the ed spec	?							Comments	1.00	2.00
	1	Very unsatisfactory - No dedicated maker spaces							Located in portable. Disconnected, too small, with lim	nited resources.	
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces Very Satisfactory - Generous size, excellent condition,									
	5	connected to learning spaces									
	N/A	Does not apply									
	IN/A	Does not apply		1	I	I	I	I			
8.7	Is there a Pr	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply					1	1			
8.8	Is there a de	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
	Are there a	dequate places to display the evidence and artifacts of									
8.9		oth 2D and 3D)?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No dedicated space							Limited 3D but 2D display is plentiful and well-used.		
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	NI/A	Does not apply									

Perkins&Will 02/11/2022 ⁴

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
0.10	Does the b	uilding provide adequate opportunities for			2				Comments		
8.10	students/te	eachers to collaborate in varying group sizes?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space to support collaboration							Second and fifth grades have a learning commons th	nat allows stud	ents to
		in various sizes.							work in larger groups. But the other studio wings do i	not.	
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options									
		to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply		ı	1						
8.11	Does the b	uilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space							Limited informal seating; limited places to gather in a	orridors.	
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
		furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
		layout and furnishings support informal interactions									
	N/A	Does not apply									
8.12		arning neighborhood / building provide adequate			3				Comments		
0.12	opportuniti	es for students to work independently?								1.00	3.00
	1	Very unsatisfactory - No breakout rooms/small study							Students can work independently in the learning com	nmons in corrid	lors if
		spaces							needed but there are no separate private spaces for	individual wor	k.
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to									
	_	learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply									

O2/11/2022 ⁵

8 - Academi	cs & Learning (cont.)							
8.13 Are Spec spec?	cial Education spaces appropriately configured per the ed		2			Comments	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility, disconnected					Most special education studios are in typical studios		
2	Unsatisfactory - Too small, only one area for all teaching							
3	methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited							
	transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous							
	display area and visual teaching tools, excellent							
	transparency and connection with other studios and shared learning spaces							
N/A	<u> </u>							
X 1/1	cial Education support spaces, such as storage, space for dryer, appropriately configured per the ed spec?		2			Comments	1.00	2.00
1	Very unsatisfactory - None provided		•	•		Storage and accessible restroom. No changing table	or life skills spe	aces.
2	Unsatisfactory - Too small, disconnected, poor condition							
3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
4	Satisfactory - Good size, connected, good condition							
5	Very Satisfactory - Generous size, connected, excellent condition							
N/A	Does not apply							
Q IA	essible restrooms and changing rooms readily available to the Education spaces?	1				Comments	1.00	1.00
1	No					Accessible restroom in main building studio, but no cl	hanging space	s.
5	Yes							

Perkins&Will 02/11/2022 ⁶

9 -	Visual and I	Performing Arts	1	2	3	4	5	N/	A	15.00	73%
9.	Are music s per the ed s	paces and the cafeteria stage appropriately configured pec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Stage has accessible ramp. Small size but has project	ion and A/V sy	stem.
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									·
9.5	Are music a	nd performance storage spaces appropriately configured				Δ			Comorno orașto		
9.,	per the ed s	pec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided							Music room has storage and office. Restroom across	he hall. Stage	right
	2	Unsatisfactory - Too small, disconnected, poor condition							next to music room. Second music room has restroom	•	
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply				,	,		_		
9.5	₹	arts spaces and storage appropriately configured per the				4			Comments		
	ed spec?									1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces							Art studio has adequate storage, sinks and kiln room	No restroom.	
	2	Unsatisfactory - Too small, poor condition							Second additional art studio has attached restroom.		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply								·	

Perkins&Will 02/11/2022 ⁷

10 - PE and We	llness	1	2	3	4	5	N/	A	10.00	70%
10.1 Does the co	impus meet the ed spec standard for physical education			3				Comments		
program sp	paces?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Gym space is average size. Getting new floor. Restroo	oms connected	to
2	Unsatisfactory - Too small, poor condition							gym.		
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
10.2 Are the phy	sical education storage spaces appropriately configured				4			Comments		
per the ed s	spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							Two large storage rooms connected to both exterior	and interior.	
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									
11 - Food Service	es	1	2	3	4	5	N/	A	10.00	50%
11.1 Is the Dining	g Commons appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - Too small, missing program spaces	l			1			Cafeteria is 3800 SF. For current enrollment, size show		
2	Unsatisfactory - Too small, poor condition, only one							around 4,800 SF. There is also no natural light.		
	option for eating space provided, inadequate circulation									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation,									
	multiple options for eating space (ex: connection to									
5	outdoor eating space) Very Satisfactory - Generous size, excellent condition and									
3	circulation, multiple options for eating space (ex:									
	connection to outdoor eating space (ex.									
N/A	Does not apply									
Are the Foo	d Services support spaces appropriately configured per									
11.2 the ed spec				3				Comments	1.00	3.00
 1	Very unsatisfactory - None provided	I	1	l	1	1	1	Food service is of average size and has two serving lir	nes.	
2	Unsatisfactory - Too small, disconnected, poor condition							g a sa a		
3	Neutral - Adequate size, average condition, needs									
Ť	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

12 - Media Res		1	2	3	4	5	N/A	1	30.00	60%
12.1 Is the Libra	ry/Media Center easily accessible for the occupants and he school?			3				Comments	1.00	3.00
1	Very unsatisfactory - Not accessible	<u> </u>	1	<u> </u>	<u> </u>	<u> </u>		Close to main entry but limited signage. Limited trans		
2	Unsatisfactory - Limited access, difficult to find, no							close to main entry but inniced signage. Elimited trans	parericy.	
2	transparency									
3	Average - Adequate accessibility, needs updates or									
3	renovations to function well									
4	Satisfactory - Accessible, easy to find, good									
7	transparency, good condition									
5	Very Satisfactory - Accessible, easy to find, excellent									
ŭ	transparency, excellent condition									
N/A	Does not apply									
14/1	2000 app.y		l l							
12.2 How well d	loes the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1	Very unsatisfactory - No quiet study spaces		<u> </u>					One large area makes acoustic privacy difficult.	1.00	2.00
2								One large area makes acoustic privacy afficult.		
2	Unsatisfactory - One area in poor condition, poor									
	acoustic privacy									
3	Average - One or more areas provided, needing updates									
	or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media									
	center, good condition, good acoustic privacy									
5	Very Satisfactory - Multiple clusters or small rooms									
	adjacent to media center, excellent condition, excellent									
	acoustic privacy									
N/A	Does not apply		1	Г	Г	Г	1			
12.3 How well d	loes the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1	Very unsatisfactory - No space							Some informal seating but more would be better.		
2	Unsatisfactory - Too small, poor condition, layout and							_		
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply	,	,	,	,			,		
12.7	loes the Library/Media Center support collaborative work			3				Comments		
in small gro	oups (4-8 students)?			0				Comments	1.00	3.00
1	Very unsatisfactory - No breakout rooms, no flexible							Some mobile tables allow seating areas to be reconfi	gured.	
	furniture, no support									
2	Unsatisfactory - Too small, one area, poor condition									
3	Average - Adequate size, multiple areas provided,									
	needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media									
	center, flexible furniture, good condition									
5	Very Satisfactory - Multiple clusters or small rooms									
	adjacent to media center, flexible furniture, excellent									
	condition									
N/A	Does not apply									

12 - Media Res	ources - Continued	1	2	3	4	5	N/A	4		
How well de	oes the Library/Media Center support collaborative work			0				Community		
12.5 in larger gr	oups (10-25)?			3				Comments	1.00	3.00
1	Very unsatisfactory - No gathering areas							Stack configuration limits size of groups that can wor	k together in li	brary.
2	Unsatisfactory - Too small, one common space, limited								· ·	•
	seating, poor condition									
3	Average - Adequate size, one common space, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with									
	seating, good condition									
5	Very Satisfactory - Generous size, multiple commons									
	spaces with seating, excellent condition									
N/A	Does not apply									
12.6 How well do	oes the Library/Media Center support technology?				4			Comments		
12.0 1101/ 1/01/ 4	oos the Library, Modia conter support technology.				7			Comments	1.00	4.00
1	Very unsatisfactory - No vis comm tools							Projector screens and 8 computers set up for student	s to use.	
2	Unsatisfactory - Outdated, poorly functioning, or									
	insufficient									
3	Good - Mix of old and new whiteboards/projectors/etc.									
4	Satisfactory - Projectors, marker boards, smart boards in									
	most spaces - good condition									
5	Very Satisfactory - Projectors, marker boards, smart									
	boards in most spaces - new condition									
N/A	Does not apply									
13 - Technolog	У	1	2	3	4	5	N/A	1	20.00	55%
13.1 How well e	quipped are the facilities with instructional technology?				4			Comments		
_					ļ		ļ		1.00	4.00
1	Very unsatisfactory - Limited to no technology present in							TVs and projectors in all studios.		
0	instructional spaces									
2	Unsatisfactory - One type of technology present									
3	Average - Multiple types of technology, smart boards,									
4	poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart									
4	boards, good condition.									
5	Very Satisfactory - Multiple types of technology, smart									
Ü	boards, excellent condition									
N/A	Does not apply									
Is there an	adequate number of power and data outlets in learning				l					
13.2 spaces?	3		2					Comments	1.00	2.00
1	Very unsatisfactory - Outlet configuration does not	<u> </u>	I	I	1	1		Two outlets or fewer per wall.		
	support digital devices throughout school (1 per wall)							The same of terror per main		
2	Unsatisfactory - Outlet configuration support digital									
	devices only in certain areas of school (2 per wall)									
3	Average - Outlet configuration support digital devices									
	but not enough capacity throughout school (3 per wall)									
4	Satisfactory - Outlet configuration support digital									
	devices with adequate coverage and capacity									
	throughout school (>3 per wall)									
5	Very Satisfactory - Excellent outlet configuration to									
	support digital devices throughout school (>3 per wall)									
N/A	Does not apply									

02/11/2022 ¹⁰

13 - Technolog	gy (cont.)	1	2	3	4	5	N/	'A		
13.3 Are there of	adequate charging locations for devices?		2					Comments	1.00	2.00
1 2	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but				•			Not enough charging locations for devices.		
3	inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower located centralized location. Excellent condition									
N/A	Does not apply									
13.4 Is there ad	lequate AV for presentations spaces – cafeteria and gym?			3	;			Comments	1.00	3.00
1	Very unsatisfactory - AV not present in one or more space							Sound in cafeteria needs upgrade. It is old and doesn	't function well	
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV									
	undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply									
13.5 Is there dig	gital media signage at the reception area?			3	;			Comments	0.00	0.00
1	Very unsatisfactory - No digital media present in reception area							TV for media in the front hallway. Answer being monicontribute to overall technology score.	tored and does	sn't
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply							<u>'</u>		

14 - Administration Spaces	1	2	3	4	5	N/A		20.00	
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
Very unsatisfactory - No security checkpoint									
Unsatisfactory - Checkpoint is too small, poor condition									
Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
14.2 Does the administration area feel welcoming?			3				Comments	1.00	3.00
1 Very unsatisfactory - No welcome space							Feels small. Limited windows.		
 Unsatisfactory - Too small, poor lighting and 									
transparency, limited informal seating, poor condition									
3 Average - Adequate size and layout, needs updates or									
renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and									
transparency, informal seating provided 5 Very Satisfactory - Generous size and layout, plenty of									
, , , , , , , , , , , , , , , , , , , ,									
light and transparency, informal seating provided, excellent condition									
N/A Does not apply									
For those spaces that require it, does the administration area have	$\overline{}$			I	I			I	
14.3 adequate acoustic privacy?	i '	2					Comments	1.00	2.00
Very unsatisfactory - No acoustic separations		<u> </u>	<u> </u>				Can hear conversations in admin space and this is a		
2 Unsatisfactory - Acoustic separations do not perform							staff due to privacy.	problem for the	o dannin
well							stan due to privacy.		
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply									
14.4 Are conference rooms easily accessed for public / parent use?	 	2					Comments	1.00	2.00
1 Very unsatisfactory - Not accessible for public/parent					•	•	One small conference room in back of administration	ຳ.	
use									
2 Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition									
N/A Does not apply									