

# **Educational Suitability Summary Report**

Blackshear Elementary School

Date: 01/14/2021 Score 51% Average

Blackshear Elementary School is in east Austin and serves an enrollment of approximately 380 students. It was originally built in 1903, with two wings added since 1995, and consists of approximately 71,000 square feet. The school is known for being a fine arts academy and a National Blue Ribbon School. It focuses a portion of the school day on core instruction followed by fine arts, with an emphasis in dance.

The original building's age creates issues in how the campus can use certain spaces. Studios have been converted to accommodate some of the school's notable programs, including music. Music is held in a typical studio with an operable partition to an adjacent studio, which currently serves as storage. A small studio has also been modified to serve as a dance room.

The campus has had renovations to update learning studios. These renovations were done prior to the current education specifications and lack collaboration spaces. A computer lab area has been created at the end of a corridor on the second floor. The layout of the campus presents some confusion due to areas that do not connect at the second floor. Overall, the campus lacks technology connectivity and needs further development of outdoor spaces.

#### **Interview Overview**

An interview was held virtually with Principal Garner, teachers, staff and parents to discuss areas for improvement and priorities for the campus. A follow-up walk on campus was done with the principal to highlight how well the campus functions and where improvements are needed. The need for more technology was discussed and how the age of the campus presents complications in achieving these upgrades. Extension cords with power strips are a trip hazard. Some studios, specifically in the upstairs wing of the 200 building, are too small for classes with 22 students. Three studios (rooms 212, 213 and 215) are used as flex spaces. The music program uses two studio spaces in the original building. These rooms connect with an old accordion door.

To promote the campus as a fine arts school, they would like to have a dedicated fine arts building that would accommodate practice performance spaces and a performance hall. The current dance practice area is a small space with installed mirrors on one wall and a makeshift stage area. The campus lacks flex/collaboration spaces for the fine arts programs as well as spaces for tutors to work with students. The staff expressed the need for more flexible and varied furniture and mobile labs for blended learning.

The campus has some areas for outdoor learning, but these need upgrades to function well. One space between buildings is concrete and the staff would like to have some shading for this space. Better wireless connection is also needed to conduct class outdoors or hold meetings. Some areas have large limestone blocks for seating. The staff would like to have other seating and furniture

## **Educational Suitability Summary Report**

Blackshear Elementary School

options for outdoor learning. There is an insufficient grass play field space for older students, and the track surface has eroded to the point of becoming a hazard. The staff expressed that the front of the building lacks curb appeal with the chain-link fence and iron gate at the front door. These make the school look unwelcoming, and they would like new landscaping and removal of the iron gate to improve the appearance of the school.

The campus has a history of issues with pests, including rodents, bats and foxes. The staff would like entry points properly sealed off to prevent these issues.

The campus would like to include programs such as film, band/orchestra, stomp and steel drums to enhance the fine arts academy program. To do so, they need spaces to accommodate activities and equipment. The campus has an active alumni group who feels strongly about maintaining the campus and would like to keep the main façade as well as multiple murals, the historical marker and other artifacts such as the reader's chair. The community considers the campus a pillar in the neighborhood.

#### **Assessment Findings**

The Educational Suitability Assessment of Blackshear Elementary School earned a 51% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

#### Very Unsatisfactory Categories (0-35%):

#### **Technology**

Score is very unsatisfactory.

Extension cords are used in studios throughout campus. There are not adequate charging locations for devices and no centralized charging locations. The reception area lacks digital media signage.

### **Administration Spaces**

Score is very unsatisfactory.

The reception area is small and has minimal seating. The office spaces do not offer acoustic separation, and the admin area does not have a conference room accessible for public/parent use.

#### **Unsatisfactory Categories (36-50%):**

#### **Exterior**

Score is unsatisfactory.

Vehicles and buses mix due to parents dropping off at the front of the building on 11<sup>th</sup> Street, which is a very busy road. Pedestrian traffic happens separately from vehicle and buses. Marquee sign is old and not in good condition.

### **Outdoor Learning and Activity**

Score is unsatisfactory.

Main learning garden is too small with a small shade structure. Seating is minimal for the area.

#### **Educational Suitability Summary Report**

Blackshear Elementary School

Storage is insufficient for garden space. Alcoves to exterior doorway are used for storing gardening equipment. Walking path has been eroded by rain and poses trip hazards. There is not adequate space for field sports.

#### **General Building**

Score is unsatisfactory.

The corridors in the main portion of the building are wide while the corridors where the studios are located are slightly narrower. Both accommodate safe and effective circulation. Community areas are not arranged well for nighttime functions without full school access. The school does not have a community room that can be used outside of school functions.

#### **Academics & Learning**

Score is unsatisfactory.

Sizes are adequate for most studios, but some studios have been converted into music rooms and storage. Some spaces were deemed too small for typical studios and are used for dance and performance areas. There are no small group breakout spaces in the learning neighborhoods. Special education studios are in normal studio rooms without access to an accessible restroom or changing table.

#### **Media Resources**

Score is unsatisfactory.

Library is not easily accessible to visitors and cannot be accessed for after-hours functions without accessing other parts of the building. The library has no access to natural light. The library is limited in supporting larger groups and does not have any breakout rooms for student collaboration.

#### Average Categories (51-65%):

#### Security

Score is average.

#### **Food Services**

Score is average.

Cafeteria is adequately sized based on current student enrollment. Based on full capacity, cafeteria will be slightly undersized per Ed Spec. In general, the appearance is very dated, and the kitchen and servery are not in good condition. Only one option for eating space is provided. The existing storage spaces are not wide enough to store the cafeteria tables and are used to store other materials.

#### **Visual and Performing Arts**

Score is average.

The music room and its storage space are sufficient in size but are in two large studios connected by an old operable partition. The campus has a stage in the gym and is in good condition, but it is not close to the music room. The art room is adequate size but needs some more storage and a connected restroom.

### **Educational Suitability Summary Report**

Blackshear Elementary School

#### Satisfactory Categories (66-80%):

#### **Environmental Quality**

Score is satisfactory.

Acoustics in studios function well with only slight sound observed from outside the room. Studios have access to natural light. The studios in the original building have larger windows with ample natural light. The artificial light appears to produce some minor glare.

#### **Controllability of Systems**

Score is satisfactory.

Studios have thermostats for individual control. All studios have window blinds in good condition to control natural light. Older studios only have a single switch to control the lighting, and the newer studios have two switches to control alternating rows of lights.

#### **Furniture, Fixtures, Equipment**

Score is satisfactory.

Overall, the furniture in studios is not new, but appears to be sturdy and clean. The furniture in studios typically can accommodate rapid reconfiguration. The library has some variety of furniture, but it is somewhat less flexible.

#### **PE and Wellness**

Score is satisfactory.

Flooring and equipment in gym appears to be in good condition. The arrangement of support spaces is configured well, but storage space is small. Gym office door opens into the corridor but has a window for visibility into the gym.



Old iron gate at front entry is not used and is not inviting to visitors.




Chain-link fence is not visually pleasing and does not promote the campus as an inviting place. Exterior spaces need landscaping. Outdoor learning space needs further development to function well. Limestone blocks are too large for smaller student seating.

## **Supporting Photographs**



The main entry is small with a low ceiling and does not feel welcoming as an elementary school. The entry lacks a secure vestibule and is far from the main office. This layout allows visitors to enter without supervision.



The main corridor is wide and has murals and displays to promote school pride. The lighting is dim and could use upgrades.



One of the studios is used as a flex space for performance practice. Makeshift stage was created with attempt to soundproof with carpet tile (not fully adhered) and fabric wall.



Typical studio is being used as flex space for dance class. Storage within studio is an outcome of COVID-19 protocols and does not represent the room under normal use.




Typical studio device connections include extension cords and power strips.



Gym and stage area both appear in good condition.

# **Supporting Photographs**




Outdoor space between cafeteria and studio wing needs development to be utilized as a gathering place. The staff expressed the need for shading of this space.



Library does not support large groups and has no natural light.



Small grass field area is too small for field sports. Campus has another open area, but it is far from gym and near the pre-K wing.



Track surface is eroding from rain runoff and is a hazard for users. The District Project Manager noted that this will be addressed in an upcoming improvement project.



# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
Blackshear Elementary School	Kevin Kinsey & Anacleto Rojas Jr.	1/14/2021

1 - Exterior		1	2	3	4	5	N/A		8.75	43%
1.1 Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?		2					Comments	1.00	2.00
1 2 3 4				1			Parents do not drop off where they typically should on Concern is the drop-off happening on busy 11th Street.			
N/A	Does not apply									
	ling easily identified with appropriate signage and vayfinding?			3				Comments	0.25	0.75
1 2 3 4 5	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden Average - Signage / wayfinding visible but not apparent Satisfactory - Signage / wayfinding is visible but not good condition Very satisfactory - Signage and wayfinding is visible and							Old monument marquee sign, not digital.		
N/A	easy to use Does not apply									

1 - E	- Exterior (cont.)				3	4	5	N/A			
1.3	Is the dump	ster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	1 2 3	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly							Dumpsters are separate. Front near cafeteria only ho stair access. Compost and landfill dumpsters on othe	, ,	•
	5	adjacent and route is barrier free  Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0		arning and Activity	1	2	3	4	5	N/A		15.00	40%
2.1	Are outdoo the ed spec			2					Comments	1.00	2.00
	1 2	Very unsatisfactory - No dedicated outdoor studios  Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided							Storage for outdoor main garden area in alcoves of a Seating in the form of large limestone boulders. Other concrete without shade or classroom infrastructure.		
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2		olaygrounds (elementary only) and support spaces per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated active playground							Large shaded play area, but no dedicated playfield.	Walking path e	eroded
	2	Unsatisfactory - Too small, poor condition, no shade provided							by rain and poses a trip hazard.		
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - C	outdoor Led	arning and Activity (cont)	1	2	3	4	5	N/A	4		
2.3		s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect the score of Outd Activity. Need some maintenance. Large concrete ext developed.		
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain ed spec?	gardens and/or cisterns appropriately configured per the		2					Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns	•	•					Monitoring answer, does not affect the score of Outd	oor Learning o	and
	2	Unsatisfactory - Too small, poor condition, not functioning, disconnected							Activity. Small water trough		
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply									
2.5		hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No									
0.7	5	Yes								0.00	0.00
2.6	Does the sc	hool have nature loop trails? (optional)  No	1						Comments	0.00	0.00
	1 5	Yes									
2.7		hool have a learning pond? (optional)	1						Comments	0.00	0.00
	1	No (CF at the state of the stat								0.00	
	5	Yes									
2.8	Does the sc	hool have a grass play field and walking trail?	1						Comments	1.00	1.00
	1	No									
	5	Yes									

	3 - Gene	- General Building			2	3	4	5	N/A		11.25	38%
			circulation routes wide enough to safely and effectively ate student movement?				4			Comments	0.50	2.00
		1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide									
		2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
		3	Average - Primary circulation is 7'-0" to 8'-0" wide									
		4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
		5	Very satisfactory - Primary circulation is 10'-0"+ wide									
		N/A	Does not apply									
			nity use areas arranged so that the school can allow night ithout full school access?	1						Comments	0.75	0.75
		1	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours									
		2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours									
		3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
		4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
		5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
		N/A	Does not apply									
		here a co school fu	ommunity room that is a dedicated meeting space outside nction?	1						Comments	0.75	0.75
ľ		1	Very unsatisfactory - No dedicated community room									
		2	Unsatisfactory - Community room but within school function, no access after school hours									
		3	Average - Community room, moderate size, but need									
		4	some renovations or updates to function well Satisfactory - Community room, good size /layout, meets									
		5	needs /functions well  Very Satisfactory - Community room, generous size, nice									
		5	condition, functions appropriately outside of school function									
		N/A	Does not apply									
			eneral appearance of the school convey pride for the add community?			3				Comments	0.25	0.75
ا		1	Very unsatisfactory - General appearance is poor						1			
		2	Unsatisfactory - General appearance is aged but ok									
		3	Average - General appearance is good									
		4	Satisfactory - General appearance shows pride in campus and student works									
		5	Very Unsatisfactory - General appearance shows pride in campus and student works and is welcoming to the community									
		N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>6</sup>

5 - Environme	- Environmental Quality			3	4	5	N/A	4	25.00	68%
5.1 How are a	coustics in studios in general?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor  Unsatisfactory - Audible sound from adjacent studio/corridor  Average - Slight sound from outside room  Satisfactory - Walls to deck insulated only white noise from mechanical system  Very satisfactory - Able to hear quiet speaking from across the room  Does not apply							This varies across the school. In original 200 wing and acoustics are average. In the 100 wing, studios have adjacent studios, which creates acoustic issues.		g, the
	io artificial lighting adequate quality?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply					,				
5.3 Is there ac	cess to natural light in studios?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply									
								Comments		
	cess to outside views from learning spaces?			3					1.00	3.00
1 2 3 4 5	<ul> <li>Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out</li> <li>Average - 26-50% of learning spaces have views</li> <li>Satisfactory - 51-75% of learning spaces have views</li> </ul>							Some rooms have views to roof or adjacent building.		

5 -	<b>Environme</b>	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.	5 Does the b	ouilding have odor or pest problems?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition							Mentioned by principal that they have had issues wit foxes, rodents, termites. Odor noticed in Room 300.	h pests such a	s bats,
6 -	N/A <b>Controllab</b>	Does not apply  ility of Systems	1	2	3	4	5	N/A	4	12.50	68%
6.		tudio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes	•	•				•			
6.	2 Are shade	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades									
	N/A	Does not apply	ı	I	ı	1	Г	T	T	1	
6.	3 What is th	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply	•	•	•	•	•	•	Older studios only have one switch. Studios in 100 wi rows with two switches.	ng have altern	ating

7 - F	urniture, Fi	ixtures & Equipment	1	2	3	4	5	N/A	·	18.75	75%
7.1	What is the	current condition of the furniture?				4			Comments	0.75	3.00
	1	Very unsatisfactory - Damaged or broken, non- functioning				•		•			
	2	Unsatisfactory - Torn/ bent/ wrong size									
	3	Average - Scratched/dented/marked									
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
	N/A	Does not apply			1	1	1		T		
7.2	Are a varies	ty of furniture types being accommodated throughout the urning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Same furniture used in all spaces					•		Only in the library.		
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply									
7.3	How well d space?	oes furniture accommodate rapid reconfiguration of a				4			Comments	1.00	4.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy									
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	ls the furnit	ure ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

02/11/2022 9

Zero Waste	1	2	3	4	5	N/A		5.00	50%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?			3				Comments	0.50	1.50
1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. 2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. 3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. 4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. 5 Very satisfactory - All studios / corridors (100%) have							A score for this category is being recorded, but this cate calculated in the overall ESA average.	gory is not	
visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A Does not apply									
Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?		2					Comments	0.50	1.00
<ol> <li>Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.</li> </ol>							A score for this category is being recorded, but this cate calculated in the overall ESA average.	gory is not	
Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4 Satisfactory- There are several waste stations as described above									
5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
N/A Does not apply									



# Austin ISD Educational Suitability Assessment Criteria

**Academics - Elementary School** 

School Name	Walk Attendees:	Date:
Blackshear Elementary School	Kevin Kinsey & Anacleto Rojas Jr.	1/14/2021

8 - Ac	ademics	& Learning	1	2	3	4	5	N/A		70.00	37%
8.1	Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected		•		•					
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
		and Kinder have appropriate support spaces such as and storage per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided		•				•	Not all kindergarten studios have direct access to res	trooms.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

8 - A	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.3	Do studios l ed spec?	have appropriate support spaces such as storage per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Built-in storage		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
8.4	Do typical l collaboration	earning neighborhoods have small group rooms and open on space?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	N/A	Does not apply									
8.5		l studios large enough to support project-based learning e teaching modalities?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning		•	•	•	•		Two walls only available to project to or conduct inst	ruction from.	
	2	Unsatisfactory - Undersized, decentralized resources, limited flexibility									
	3	Average - Adequate size, needs some renovations or updates to function well									
	4	Satisfactory - Good size, centralized resources, good flexibility									
	5	Very Satisfactory - Generous size, centralized project resources, excellent flexibility									
	N/A	Does not apply									

8 - A	Academics	1	2	3	4	5	N/A				
8.6	Are Maker the ed spec	Spaces and support spaces appropriately configured per ?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	from learning spaces, no flexibility  Average - Adequate size, adequate condition, needs									
	3	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									
0.7	-	,	٠,			T			Community		
8.7	is there a P	rofessional Learning Center in the learning neighborhood?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
	0	Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected									
	2 3	Average - Adequate size, adequate condition, needs									
	3	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply						ı			
8.8	ls there a d	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9		dequate places to display the evidence and artifacts of oth 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space							Tack strips in corridors throughout school with limited	places for 3D	
	2	Unsatisfactory - Too small, non-dedicated, poor							display. Noted as not ideal by principal and staff with	n tacks as a ha	zard
		condition							for students.		
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4 Satisfactory - Good size, good condition										
	5 Very Satisfactory - Generous size, excellent condition										
	N/A Does not apply										

Perkins&Will 02/11/2022 <sup>4</sup>

8 - A	cademics 8	1	2	3	4	5	N/A				
8.10		ilding provide adequate opportunities for		2					Comments		
8.10	students/ted	achers to collaborate in varying group sizes?		_					Comments	1.00	2.00
	1	Very unsatisfactory - No space to support collaboration in various sizes.					•		Small computer lab area and tutoring space.		
	2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.11	Does the bu	ilding provide opportunities for informal interaction?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No space							There is no informal seating in corridors for informal i	nteraction	
	2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well							Ç .		
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
8.12	Does the lea	arning neighborhood / building provide adequate		2					Comments		
0.12	opportunitie	es for students to work independently?							Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms/small study spaces							Small computer lab area and tutoring space.		
	2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	NI/A	Door not apply									

8 - A	cademics 8	& Learning (cont.)									
8.13	Are Special spec?	Education spaces appropriately configured per the ed		2			Comments	1.00	2.00		
	1	Very unsatisfactory - Too small, no flexibility, disconnected			'		Typical studio being used as a resource room. No special education roon the campus.				
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected					· ·				
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
8.14		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?	1				Comments	1.00	1.00		
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
8.15		ble restrooms and changing rooms readily available to the location spaces?	1				Comments	1.00	1.00		
	1	No									
	5	Yes									

O2/11/2022 <sup>6</sup>

9 - Vi	isual and P	Performing Arts	1	2	3	4	5	N/A	A	15.00	60%
9.1	Are music sp per the ed s				3				Comments	1.00	3.00
	1 2	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition							Space is large enough but is using two typical studios operable partition.	connected wi	th an
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
9.2	Are music ar per the ed s	nd performance storage spaces appropriately configured pec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Storage space is an existing typical studio. Music room	m far from	
	2	Unsatisfactory - Too small, disconnected, poor condition							performance stage in gym.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
9.3	Are Visual A ed spec?	rts spaces and storage appropriately configured per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							No restroom connected to space and needs more sto	rage.	
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

02/11/2022 7

	10 - PE and We	liness	1	2	3	4	5	N/	A	10.00	70%
		impus meet the ed spec standard for physical education				4			Comments		
	program sp	paces?				·				1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces							New floor in good condition. Adequately sized gym a	t 2,900 square	feet.
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
	_	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
-	N/A	Does not apply	_	1	1	_	T	_	T		
	10.2 Are the phy per the ed s	rsical education storage spaces appropriately configured			3				Comments	1.00	3.00
L	per trie eu s	Very unsatisfactory - None provided							Consultation of the consul		3.00
	2	Unsatisfactory - Too small, disconnected, poor condition							Small storage area. Gym office not directly connected	d to gym.	
	3	Neutral - Adequate size, average condition, needs									
	3	updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
	11 - Food Servic	es	1	2	3	4	5	N/	Ą	10.00	60%
	11.1 Is the Dinin	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
Ī	1	Very unsatisfactory - Too small, missing program spaces							Based on current enrollment cafeteria is adequately	sized at 3,000	square
	2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation							feet.		
	3	Average - Adequate size and condition, needs updates or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
	N/A	Does not apply									
ſ		d Services support spaces appropriately configured per			3				Comments		
L	the ed spec								Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Kitchen and servery are undersized.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3 Neutral - Adequate size, average condition, needs updates or renovations to function well										
	4 Satisfactory - Good size, connected, good condition										
	5 Very Satisfactory - Generous size, connected, excellent condition										
	N/A Does not apply										

12 - Media Resources	1	2	3	4	5	N/A	4	30.00	50%
12.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?		2					Comments	1.00	2.00
1 Very unsatisfactory - Not accessible							Library is in back school and not easily accessible for	visitors.	
2 Unsatisfactory - Limited access, difficult to find, no transparency									
3 Average - Adequate accessibility, needs updates or renovations to function well									
4 Satisfactory - Accessible, easy to find, good transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A Does not apply									
12.2 How well does the Library/Media Center support quiet study?			3				Comments	1.00	3.00
Very unsatisfactory - No quiet study spaces		•		•		•	One open space		
<ol> <li>Unsatisfactory - One area in poor condition, poor acoustic privacy</li> </ol>									
3 Average - One or more areas provided, needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 Very unsatisfactory - No space									
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well  3 Average - Adequate size and condition, needs updates									
<ol> <li>Average - Adequate size and condition, needs updates or renovations to function well.</li> </ol>									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply									
How wall does the Library/Media Center support collaborative work in		_		П		П	_		
12.4 small groups (4-8 students)?		2					Comments	1.00	2.00
7 Very unsatisfactory - No breakout rooms, no flexible						•			
furniture, no support									
<ol> <li>Unsatisfactory - Too small, one area, poor condition</li> <li>Average - Adequate size, multiple areas provided,</li> </ol>									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent									
condition N/A Does not apply									
IVA DOES HOL APPLY									

	12 - Media Res	ources - Continued	1	2	3	4	5	N/A	A		
	12.5 How well d larger grou	oes the Library/Media Center support collaborative work in ps (10-25)?		2					Comments	1.00	2.00
ľ	1	Very unsatisfactory - No gathering areas		l .							
	2	Unsatisfactory - Too small, one common space, limited seating, poor condition									
	3	Average - Adequate size, one common space, needs updates or renovations to function well									
	4	Satisfactory - Good size, multiple common spaces with seating, good condition									
	5	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition									
	N/A	Does not apply									
	12.6 How well d	oes the Library/Media Center support technology?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No vis comm tools		•		•	•				
	2	Unsatisfactory - Outdated, poorly functioning, or insufficient									
	3	Good - Mix of old and new whiteboards/projectors/etc.									
	4	Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition									
	5	Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition									
	N/A	Does not apply									
	13 - Technology	1	1	2	3	4	5	N/A	1	20.00	30%
	13.1 How well e	quipped are the facilities with instructional technology?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Limited to no technology present in instructional spaces									
	2	Unsatisfactory - One type of technology present									
	3	Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school									
	4	Satisfactory - Multiple types of technology, smart boards, good condition.									
	5	Very Satisfactory - Multiple types of technology, smart boards, excellent condition									
	N/A	Does not apply									
	13.2 Is there an spaces?	adequate number of power and data outlets in learning	1						Comments	1.00	1.00
	1	Very unsatisfactory - Outlet configuration does not							Not adequate throughout school. Use of extension co	ords and powe	r strips
	_	support digital devices throughout school (1 per wall)							throughout.		
	2	Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)									
	3	Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)									
	4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall)									
	5	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									
	N/A	Does not apply									

13 - Technolog	Technology (cont.)		2	3 4	1	5	N/A			
13.3 Are there of	adequate charging locations for devices?	1						Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition			•	•					
N/A	Does not apply									
13.4 Is there ad	13.4 Is there adequate AV for presentations spaces – cafeteria and gym?		2					Comments	1.00	2.00
1 2 3 4	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply			 	_					
13.5 Is there dig	gital media signage at the reception area?	1						Comments	0.00	0.00
1 2 3 4 5	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

14 - Administro	- Administration Spaces			3	4	5	N/A	A.	20.00	30%
14.1 Is there a revisitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply		ı	ı	1	ı		T		
14.2 Does the a	dministration area feel welcoming?		2					Comments	1.00	2.00
1	Very unsatisfactory - No welcome space									
2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided, excellent condition									
N/A	Does not apply									
14.3 For those s	paces that require it, does the administration area have	1				Π		Comments		
adequate	acoustic privacy?	'						Comments	1.00	1.00
1	Very unsatisfactory - No acoustic separations									
2	Unsatisfactory - Acoustic separations do not perform well									
3	Average - Some acoustic separations function okay, but									
4	portions need updates or renovations Satisfactory - Good acoustic separations									
4 5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply									
14.4 Are confere	ence rooms easily accessed for public / parent use?	1						Comments		
								Commente	1.00	1.00
1	Very unsatisfactory - Not accessible for public/parent use									
2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
3	Average - Adequate accessibility, needs updates or renovations to function well									
4	Satisfactory - Good accessibility, good transparency, good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A	Does not apply									