

# **Educational Suitability Summary Report**

Clayton Elementary School

Date: 12/21/2020 Score 70% Satisfactory

Clayton Elementary School, serving an enrollment of approximately 720 students is in southwest Austin. It was built in 2006 and consists of approximately 103,300 square feet. Clayton focuses on the development of literacy, independent thinking, and problem solving as the essential building blocks to becoming responsible individuals. The overall condition of the school is good. The deficiencies that were found include a lack of maker space, specialized special education spaces, and inadequate flexible and breakout spaces that meet Ed Spec requirements.

The main building is two levels and is connected to the administration, library, gym and cafeteria via a central corridor. The studios are laid out in two wings distributed on two levels. There are learning stairs near the entrance with a large double-story hall.

#### **Interview Overview**

The interview was held with Principal Amy Gonzales and other staff members. The interview discussion focused on inadequate and unsuitable spaces for programs and safety concerns. The school enrollment is expected to grow in the next few years. According to the principal, the school can meet the needs of most of the functions and programs in the building however, six second grade studios and interventionists are in portables. The principal would like to have a dedicated science lab and maker space as there are none currently. The school does not have space for PTA or community meetings. The neighborhood community center is usually used for district meetings. The administration area has one conference room that can be used for parent meetings. One of the concerns mentioned by the principal was the acoustic separation for the life skills classes. If classes are taking place next to a regular studio or music rooms, it can be challenging for students who are sensitive to sound.

The school needs faster internet, flexible furniture, collaboration spaces and charging stations. The building has pod areas outside studios that are sometimes used for presentations, but there are no small group spaces. Library furniture is hard to move around and not ergonomic for the students. A dedicated computer lab is needed in or near the library. The principal also expressed interest in having more outdoor spaces that can tie back to the studios. Current outdoor learning spaces require more furniture and shade. One of the items on the wish list is turf for the field.

In the event of renovation or new construction, the principal mentioned a few things that need to remain, including a turtle terrace outside the library made to honor the library's founder. Artwork in the courtyard and interior murals, including in the front foyer and the cafeteria, are important for the

# Perkins&Will

# **Educational Suitability Summary Report**

Clayton Elementary School

school's pride and should remain.

# **Assessment Findings**

The Educational Suitability Assessment of Clayton Elementary School earned a 70% overall score and places the campus in a category of Satisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

# Average Categories (51-65%):

## **General Building**

Score is average.

Overall condition of the building is good. Corridors throughout the building vary in width and there is limited to no transparency into the learning spaces. All public spaces, cafeteria and gym can be accessed from parking and secured from the rest of the building but not individually.

## Security

Score is average.

## **Furniture, Fixtures, Equipment**

Score is average.

Furniture variety is average. Most of the spaces have similar chairs or desks. Library furniture is large and bulky, which can be difficult to move around for rapid configuration to accommodate small or large collaboration groups. The library furniture is not ergonomic or sized appropriately for students.

### **Academics & Learning**

Score is average.

Transparency and connection to other shared learning spaces could be better. There are some noise issues between adjoining studios. The size and support spaces satisfy current campus needs. Open teaching or breakout spaces are limited to library or pod spaces. No dedicates science lab is in the building.

#### **Media Resources**

Score is average.

The library is accessed from the main corridor but is a little far from the main entrance. No private quiet study rooms are provided. The furniture does not promote meetings of different group sizes. It is heavy, bulky and cannot be reconfigured. The library needs ergonomic furniture for students.

### Technology

Score is average.

Projectors and TV carts are in most rooms. There are limited charging stations overall. Common facilities and studios have a good representation of instructional technology. The computer lab is a standard studio that has been repurposed.

## Satisfactory Categories (66-80%):

# **Educational Suitability Summary Report**

Clayton Elementary School

## **Outdoor Learning and Activity**

Score is satisfactory.

Outdoor learning spaces are available but need updates to function well. Library is connected with an outside patio that needs renovations and shading. The play spaces are adequate in size but need more shade as well. The art room has a small courtyard that needs additional benches to make the space more usable. Limited garden space needs renovations and updates.

# **Environmental Quality**

Score is satisfactory.

Due to the shared spaces between studios, the hallway allows noise to transfer between the studios. The quality of the artificial lighting is appropriate for studio functions. Natural light is average in the studios. Not all studios get adequate natural light.

## **Controllability of Systems**

Score is satisfactory.

Blinds are provided to control natural light in learning spaces. Two-way switch system is provided for lighting controls in the studios.

#### **PE and Wellness**

Score is satisfactory.

Gym is good size and condition. The storage is in a good location and meets Ed Spec size.

#### **Food Services**

Score is satisfactory.

Dining and kitchen spaces are adequately sized. There are not multiple options for eating spaces and tables in dining area are large and bulky and not easy to break up into smaller groups.

### **Administration Spaces**

Score is satisfactory.

Administration spaces are by the main entrance,

There is good acoustical privacy between admin spaces.

## Very Satisfactory Categories (81-100%):

### **Exterior**

Score is very satisfactory.

Traffic circulation for vehicular, bus and pedestrian traffic is clearly noted, and the drop-off area has a canopy. Physical marquee sign is at road. No digital sign is provided.

# **Visual and Performing Arts**

Score is very satisfactory.

Art and music spaces are good size and good condition. Art room has a kiln and storage is adequate.




Most studios have adequate natural light, but doors with small windows provide little transparency into the learning spaces. Furniture is bulky and difficult to reconfigure.




Acoustic and visual privacy suffers from the current restroom connections in the studios.

# **Supporting Photographs**



Cafeteria: Adequate space but only one type of furniture is provided.



Hallways are adequate in size, varying from 8-10 feet in width. They are double-loaded corridors, and there is limited visual connection or transparency to the learning spaces.



Typical studio storage is provided by built-in cabinets.



Gym has natural light and is adequately sized. Storage space in gym is on smaller side.



Media Center: There is no flexible furniture available for different configurations and current furniture is not appropriately sized for students.



Media Center: Individual desks with computers. Better acoustical privacy could be provided. No private quiet study spaces. There is a need for different seating types for small- and large-group collaboration and to support informal interaction.



Outdoor learning spaces are available. They need renovations, additional seating and shade.



50% or less of the play areas are shaded. Some play areas need updates and are not in good condition.



# Perkins&Will

# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
Clayton Elementary School	Carlos Cruz, Vishwesh Panchal	12/14/2020

1 - Ex	terior		1	2	3	4	5	N/A		8.75	97%
1.1	Does the site pedestrian t	e permit desirable separation of vehicular, bus and craffic?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location							Traffic circulation for vehicular, bus, and pedestrian traff	fic is clearly not	ed.
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
1.2	Is the building	ng easily identified with appropriate signage and community ?				4			Comments	0.25	1.00
	1	Very unsatisfactory - Campus has no signage / wayfinding							Physical marquee sign at road. No digital sign.		
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

1 - E	xterior (con	t.)	1	2	3	4	5	N/A			
1.3	Is the dump	ster accessible for trash / compost disposal?					5		Comments	0.50	2.50
	1	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster				•	•				
	2	Unsatisfactory - Compost is present. Route has obstacles to dumpster									
	3	Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.									
	4	Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
	5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - (	Outdoor Lea	rning and Activity	1	2	3	4	5	N/A		15.00	73%
2.1	Are outdoor ed spec?	studios and support spaces appropriately configured per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							Outdoor learning spaces available but need updates to	function well. L	ibrary is
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided							connected with an outside patio.		-
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2	Are active p per the ed s	laygrounds (elementary only) and support spaces configured pec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated active playground							Monitoring answer, does not affect score for Outdoor Le	arning and Act	tivity.
	2	Unsatisfactory - Too small, poor condition, no shade provided							The play spaces are adequate in size, but the track need and renovations to function better.	ls some mainte	nance
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - 0	Outdoor Led	rning and Activity (cont)	1	2	3	4	5	N/A	<b>\</b>		
2.2		s and support spaces appropriately configured per the ed			3				Comments		
2.3	spec? (eval	uation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor Le	arning and Acti	vity.
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Limited garden space, needs some renovations or updat	tes.	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain spec?	gardens and/or cisterns appropriately configured per the ed			3				Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns									
	2	Unsatisfactory - Too small, poor condition, not functioning, disconnected									
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply									
2.5	Does the sc	hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No									
0.7	5	Yes	1	1			-			0.00	0.00
2.6	Does the sc	hool have nature loop trails? (optional)  No	L				5	<u> </u>	Comments	0.00	0.00
	1 5	Yes									
2.7		hool have a learning pond? (optional)	1					Г	Comments	0.00	0.00
	1	No									
	5	Yes									
2.8	Does the sc	hool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1	No									
	5	Yes									

3 -	General Buil	ding	1	2	3	4	5	N/A	4	11.25	60%
3.	l	circulation routes wide enough to safely and effectively				4			Comments		
L.	accommode	ate student movement?				<u> L</u>	1			0.50	2.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide							Varies in width		
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
		nity use areas arranged so that the school can allow night				1	Т	Т			
3.2		thout full school access?				4		L	Comments	0.75	3.00
	I	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							All of the public spaces can be accessed from parking ar rest of the building but not individually. Library located f		
	2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours							entrance.		
	3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
	N/A	Does not apply									
3.3	ls there a co	mmunity room that is a dedicated meeting space outside of	1			Т	Τ	Т	Comments		
3.	school funct	ion?							Comments	0.75	0.75
	1	Very unsatisfactory - No dedicated community room							No dedicated community room in the school		
	2	Unsatisfactory - Community room but within school function, no access after school hours									
	3	Average - Community room, moderate size, but need some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
	N/A	Does not apply									
3.4	Does the ge and commu	neral appearance of the school convey pride for the students nity?				4			Comments	0.25	1.00
	1	Very unsatisfactory - General appearance is poor				·			The general appearance of the school including the mai	n entry are nice	
	2	Unsatisfactory - General appearance is aged but ok							attributes. It shows pride in campus and student works.		
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in campus and student works									
	5	Very Satisfactory - General appearance shows pride in campus and student works and is welcoming to the community									
	N/A	Does not apply									

4 - Security	1 2 3 4 5 N/A		16.25
4.1 Does the facility have key card access at all major entries?		Comments	0.25
1 Very unsatisfactory - No entries 2 Unsatisfactory - 1/4 of major entries 3 Average - 1/2 of major entries 4 Satisfactory - 3/4 of major entries 5 Very satisfactory - All of major entries N/A Does not apply			
4.2 How adequate is site lighting and security for the campus overall?		Comments	1.00
Very unsatisfactory - No exterior lighting, no secure     perimeter			
2 Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal			
3 Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate			
4 Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates			
5 Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure			
N/A Does not apply			
4.3 Is the main office located at the school entry and configured with a		Comments	
secure vestibule to the main corridor?		Comments	1.00
1 Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised			
2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors			
3 Average - Office close to entry, views of front door, but no secure vestibule			
4 Satisfactory - Office is well-located with a secure vestibule, but needs updates			
5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features			
N/A Does not apply			
ls there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios?	3	Comments	1.00 3.00
1 Very unsatisfactory - No transparency of walls		Transparency only in certain locations. Small lite in door	s provide very little
2 Unsatisfactory - Limited transparency in certain locations		view into the classrooms for supervision.	
Average - Good transparency in certain locations but inadequate or missing in other locations of school			
4 Satisfactory - Adequate transparency throughout the school			
5 Very satisfactory - Excellent transparency throughout the school			
N/A Does not apply			

	5 - Environment	tal Quality	1	2	3	4	5	N/A		25.00	68%
	5.1 How are ac	oustics in studios in general?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor							Due to the shared spaces between classrooms, the restronoise to transfer between the two classrooms.	oom hallway allo	ws for
	2	Unsatisfactory - Audible sound from adjacent studio/corridor									
	3	Average - Slight sound from outside room									
	4	Satisfactory - Walls to deck insulated only white noise from mechanical system									
	5	Very satisfactory - Able to hear quiet speaking from across the room									
	N/A	Does not apply									
	5.2 Is the studio	artificial lighting adequate quality?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC							The quality of the artificial lighting is appropriate for cla	ssroom functions	S.
	2	Unsatisfactory - 10-19 FC or serious glare									
	3	Average- 20-29 FC minor glare									
	4	Satisfactory - 30-39 FC and no glare									
	5 N/A	Very satisfactory - 40+ FC and no glare  Does not apply									
_	IN/A	Does not apply							T		
	5.3 Is there acce	ess to natural light in studios?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No learning spaces have natural light							Natural light is average in the classrooms. Not all classronatural light.	ooms get adequo	ate
	2	Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light									
	3	Average - 26-50% of learning spaces have natural light									
	4	Satisfactory - 51-75% of learning spaces have natural light									
	5	Very satisfactory - 76-100% of learning spaces have natural light									
	N/A	Does not apply									
ſ	5.4.1.11					Ι					
	5.4 Is there acce	ess to outside views from learning spaces?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No learning spaces have views							Almost half of the leaning spaces have exterior views.	,	
	2	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out									
	3	Average - 26-50% of learning spaces have views									
	4	Satisfactory - 51-75% of learning spaces have views									
	5	Very satisfactory - 76-100% of learning spaces have views									
	N/A	Does not apply									

5 - E	nvironmen	tal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Evidence of both pests and odors									
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in excellent condition									
	N/A	Does not apply									
6 - C	ontrollabil	ity of Systems	1	2	3	4	5	N/A		12.50	76%
6.1	Does the stu	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No									
	5	Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No, windows are covered with boards/paper									
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply									
6.3	What is the	quality of lighting controls in the studios?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Single switch only per room							2 switch system		
	2	Unsatisfactory - Alternating rows switch off									
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - F	urniture, Fiz	xtures & Equipment	1	2	3	4	5	N/A		18.75	56%
7.1	What is the	current condition of the furniture?		2					Comments	0.75	1.50
	1 2 3 4 5	Very unsatisfactory - Damaged or broken, non-functioning  Unsatisfactory - Torn/ bent/ wrong size  Average - Scratched/dented/marked  Satisfactory - Not new, but sturdy and clean  Very satisfactory - New							Furniture needs upgrades at certain locations. Library has furniture. It is not ergonomic for student use.	as bulky and hea	vy
	N/A	Does not apply					,				
7.2		y of furniture types being accommodated throughout the rning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Same furniture used in all spaces				•	•		Furniture variety is average. Most of the spaces have sim	nilar chairs or de	sks.
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply									
7.3	How well do	bes furniture accommodate rapid reconfiguration of a space?			3				Comments	1.00	3.00
	1 2	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups							Except in cafeteria, larger tables would be difficult to mo flexible.	ove on; desks are	more
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	ls the furnit	ure ergonomic and size appropriate for grade level?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level							Library has bulky and heavy furniture. It is not ergonomic	c for student use	
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

o Waste		1	2	3	4	5	N/A	4	5.00	90
	and corridors have blue recycle bins with bilingual instructions age sorting instructions?				4			Comments	0.50	2.0
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.						•	A score for this category is being recorded, but this cate the overall ESA average.	gory is not calcu	ulated
2	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.									
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply									
each: gree	afeteria (or wherever meals are served) have at least one of en compost bin, blue recycle bin, and landfill bin? Are the bins early with bilingual and/or image sorting?					5		Comments	0.50	2
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.				1	<u> </u>	<u> </u>			
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average-There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4	Satisfactory- There are several waste stations as described above									
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
	that encourages recycling/composting.									



# Perkins&Will

# Austin ISD Educational Suitability Assessment Criteria

**Academics - Elementary School** 

School Name	Walk Attendees:	Date:
Clayton Elementary School	Carlos Cruz, Vishwesh Panchal	12/14/2020

- Academ	ics & Learning	1	2	3	4	5	N/A	A.	70.00	64%
8.1 Are stu	idios appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, no flexibility, disconnected							Transparency and connection to other shared learning s	oaces can be b	etter.
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							There are some noise issues between the two adjoining of windows are provided in the classroom doors.	lassrooms. Nar	row
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
2	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/	'A Does not apply									
	-K and Kinder have appropriate support spaces such as restrooms orage per the ed spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							The size and support spaces are satisfying for the campu	s needs.	
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	, ,									
5	condition									
N/	'A Does not apply									

8 -	Academics 8	Learning (cont.)	1	2	3	4	5	N/A	<b>\</b>		
8.	Do studios h spec?	ave appropriate support spaces such as storage per the ed				4			Comments	1.00	4.00
	1 2	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition						•	General building storage is adeaute, and most classroor in addition to built in cabinets.	ns have storage	closets
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
8.	Do typical le collaboration	earning neighborhoods have small group rooms and open on space?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided							Double-loaded corridors; open teaching or breakout spoor pod spaces.	aces limited to li	brary
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	N/A	Does not apply									
8.		studios large enough to support project-based learning and ching modalities?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning	•	•	•	•	•	•	The classroom spaces are adeautely sized and have app to accommodate project-based learning.	propriate storag	e space
	2	Unsatisfactory - Undersized, decentralized resources, limited flexibility							l l l l l l l l l l l l l l l l l l l		
	3	Average - Adequate size, needs some renovations or updates to function well									
	4	Satisfactory - Good size, centralized resources, good flexibility									
	5	Very Satisfactory - Generous size, centralized project resources, excellent flexibility									
	N/A	Does not apply								<u> </u>	

8 - A	cademics 8	Learning (cont.)	1	2	3	4	5	N/A			
8.6	Are Maker S ed spec?	Spaces and support spaces appropriately configured per the	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces						•	No dedicated maker spaces.	•	
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for Professional Learning Center							Only teacher lounge; no PLC.		
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition, connected									
	N/A	Does not apply					_				
8.8	Is there a de	edicated science room and support space?					5		Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9		dequate places to display the evidence and artifacts of hth 2D and 3D)?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No dedicated space									
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

8 - 8	Academics 8	Learning (cont.)	1	2	3	4	5	N/A			
8.10		ilding provide adequate opportunities for students/teachers			3				Comments		
0.10	to collabore	te in varying group sizes?			0				Comments	1.00	3.00
	1	Very unsatisfactory - No space to support collaboration in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.11	Does the bu	ilding provide opportunities for informal interaction?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space									
	2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
8.12		arning neighborhood / building provide adequate es for students to work independently?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No breakout rooms/small study spaces			•	•	•	•	No dedicated spaces. Open concept rooms; adequate s	pace but no bre	akout
	2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	N/A	Does not apply									

8 - A	cademics 8	Learning (cont.)							
8.13	Are Special	Education spaces appropriately configured per the ed spec?			4		Comments	1.00	4.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected					Multiple rooms for different needs.	•	
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
8.14		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?		3			Comments	1.00	3.00
	1	Very unsatisfactory - None provided					Special reading area is provided. Has it own restroom or	n second floor. I	Did not
	2	Unsatisfactory - Too small, disconnected, poor condition					see washer/dryer.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
8.15		ole restrooms and changing rooms readily available to the cation spaces?				5	Comments	1.00	5.00
	1	No							
	5	Yes							

9	- Vis	ual and Pe	erforming Arts	1	2	3	4	5	5	N/A		15.00	87%
		Are music spetched the ed spec?	aces and the cafeteria stage appropriately configured per				4				Comments	1.00	4.00
		1	Very unsatisfactory - Too small, missing program spaces										
		2	Unsatisfactory - Too small, poor condition										
		3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.										
		4	Satisfactory - Good size, good condition							İ			
		5	Very Satisfactory - Generous size, excellent condition							İ			
		N/A	Does not apply							·			
		Are music an the ed spec?	d performance storage spaces appropriately configured per				4				Comments	1.00	4.00
		1	Very unsatisfactory - None provided								Good size and in good condition.		
		2	Unsatisfactory - Too small, disconnected, poor condition										
		3	Neutral - Adequate size, average condition, needs updates or renovations to function well										
		4	Satisfactory - Good size, connected, good condition										
		5	Very Satisfactory - Generous size, connected, excellent condition										
		N/A	Does not apply										
		Are Visual Ar spec?	ts spaces and storage appropriately configured per the ed					5	5		Comments	1.00	5.00
		1	Very unsatisfactory - Too small, missing program spaces								Generous size; has a kiln and storage is adequate.		
		2	Unsatisfactory - Too small, poor condition										
		3	Average - Adequate size, adequate condition, needs some renovations or updates to function well										
		4	Satisfactory - Good size, good condition							l			
		5	Very Satisfactory - Generous size, excellent condition										
		N/A	Does not apply										

10 - PE and Wellness	1	2	3	4	5	N/A		10.00	80%
10.1 Does the campus meet the ed spec standard for physical education program spaces?				4			Comments	1.00	4.00
<ol> <li>Very unsatisfactory - Too small, missing program spaces</li> </ol>									
<ol> <li>Unsatisfactory - Too small, poor condition</li> </ol>									
Average - Adequate size, adequate condition, needs some									
renovations or updates to function well									
4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition									
5 Very Satisfactory - Generous size, excellent condition N/A Does not apply									
Are the physical education storage spaces appropriately configured per		1	l .	Т	Т	Г			
10.2 the ed spec?				4			Comments	1.00	4.00
1 Very unsatisfactory - None provided			·				Good location.		
<ol> <li>Unsatisfactory - Too small, disconnected, poor condition</li> </ol>									
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, excellent condition									
N/A Does not apply									
11 - Food Services	1	2	3	4	5	N/A		10.00	70%
11.1 Is the Dining Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
Very unsatisfactory - Too small, missing program spaces							Large tables. Not easy to break up in smaller groups.		
2 Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation									
3 Average - Adequate size and condition, needs updates or renovations to function well									
4 Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
5 Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A Does not apply									
11.2 Are the Food Services support spaces appropriately configured per the ed spec?				4			Comments	1.00	4.00
1 Very unsatisfactory - None provided					•				
<ol> <li>Unsatisfactory - Too small, disconnected, poor condition</li> </ol>									
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, excellent condition									
N/A Does not apply									

12 - Medio	a Resources		1	2	3	4	5	N/A		30.00	60%
	e Library/Media Center easily accessible for the occupa ors to the school?	ints and				4			Comments	1.00	4.00
	Very unsatisfactory - Not accessible     Unsatisfactory - Limited access, difficult to fine transparency	d, no	,			'			The library is accessed from the main corridor but a little entrance.	far from main	
	3 Average - Adequate accessibility, needs updo renovations to function well	ites or									
	4 Satisfactory - Accessible, easy to find, good tragood condition	ansparency,									
	Very Satisfactory - Accessible, easy to find, extransparency, excellent condition	cellent									
	N/A Does not apply										
12.2 How	v well does the Library/Media Center support quiet stud	y?			3				Comments	1.00	3.00
	Very unsatisfactory - No quiet study spaces     Unsatisfactory - One area in poor condition, p privacy	ooor acoustic							Individual desks with computers. Better acoustical privace private quiet study spaces.	cy can be provide	ed. No
	3 Average - One or more areas provided, needi renovations to function well	ng updates or									
	4 Satisfactory - Clusters or small rooms adjacen center, good condition, good acoustic privacy										
	Very Satisfactory - Multiple clusters or small re to media center, excellent condition, excellent privacy										
	N/A Does not apply										
	well does the Library/Media Center support social inte	raction?			3				Comments	1.00	3.00
	1 Very unsatisfactory - No space								Reading area and 6-person tables. Connection to outsid	e patio.	
	2 Unsatisfactory - Too small, poor condition, lay furnishings do not support informal interaction									•	
	3 Average - Adequate size and condition, needs renovations to function well.	s updates or									
	4 Satisfactory - Good size, good condition, layo furnishings support informal interactions	ut and									
	5 Very Satisfactory - Generous size, excellent co layout and furnishings support informal intercent										
1	N/A Does not apply										
	v well does the Library/Media Center support collaborat ill groups (4-8 students)?	tive work in			З				Comments	1.00	3.00
	Very unsatisfactory - No breakout rooms, no f furniture, no support	lexible							There is a need for other seating to support informal integroup collabration in the existing space. Furniture is bulk		
	2 Unsatisfactory - Too small, one area, poor cor	ndition									-
	3 Average - Adequate size, multiple areas provi updates or renovations to function well	ded, needing									
	4 Satisfactory - Clusters or small rooms adjacen center, flexible furniture, good condition	t to media									
	Very Satisfactory - Multiple clusters or small ro to media center, flexible furniture, excellent co										
	N/A Does not apply										

1	12 - Media Reso	ources - Continued	1	2	3	4	5	N/A	4		
	12.5 How well do	pes the Library/Media Center support collaborative work in ps (10-25)?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply							Bulky furniture, not easily configurable and limited zone: provided. Space is not comfortable and limited seating i		
		bes the Library/Media Center support technology?			3		Τ		Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Good - Mix of old and new whiteboards/projectors/etc. Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition							Computer lab needs some updates and needs more pov	L	
	N/A <b>I3 - Technology</b>	Does not apply	1	2	3	4	5	N/A		20.00	55%
		quipped are the facilities with instructional technology?			3	T	T		Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition							Projectors and TV carts in most rooms, limited charging s Common facilities and classrooms have a good represer technology. The computer lab is a standard classroom the repurposed.	ntation of instruc	ctional
Г	N/A  13.2 Is there an a	Does not apply adequate number of power and data outlets in learning			3	Τ	Г	Τ	Comments		
	spaces?  1  2  3  4  5	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall) Does not apply							Power locations could be improved to reduce extension	1.00 cord use.	3.00

13 - Technolog	y (cont.)	1	2	3	4	5	N/A			
13.3 Are there of	adequate charging locations for devices?		2					Comments	1.00	2.0
1 2	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices							Limited charging locations in the studios.		
3	Average - Charging cart or tower but not adequately sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower located centralized location. Excellent condition									
N/A	Does not apply									
13.4 Is there ad	equate AV for presentations spaces – cafeteria and gym?			3				Comments	1.00	3.0
1	Very unsatisfactory - AV not present in one or more space							No overhead projector. No outlets on stage for devices.		
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply									
13.5 Is there dig	gital media signage at the reception area?	1						Comments	0.00	0.0
1	Very unsatisfactory - No digital media present in reception area							No digital signage observed at the reception area		
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

	ation Spaces	 2	3		5	N/A	.	20.00	7
4.1 Is there a re visitors?	eception area that functions as a security checkpoint for all						Comments	1.00	
1	Very unsatisfactory - No security checkpoint								
2	Unsatisfactory - Checkpoint is too small, poor condition								
3	Average - Needs updates or renovations to function well								
4	Satisfactory - Good size, good condition								
5	Very Satisfactory - Generous size, excellent condition								
N/A	Does not apply	 	_						
4.2 Does the a	dministration area feel welcoming?			4			Comments	1.00	4
1	Very unsatisfactory - No welcome space				•				
2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition								
3	Average - Adequate size and layout, needs updates or renovations to feel welcoming								
4	Satisfactory - Good size and layout, good lighting and transparency, informal seating provided								
5	Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition								
N/A	Does not apply								
4.3 For those space adequate a	paces that require it, does the administration area have acoustic privacy?			4			Comments	1.00	
1	Very unsatisfactory - No acoustic separations			-		'			
2	Unsatisfactory - Acoustic separations do not perform well								
3	Average - Some acoustic separations function okay, but portions need updates or renovations								
4	Satisfactory - Good acoustic separations								
5	Very Satisfactory - Excellent acoustic separations								
N/A	Does not apply				_				
4.4 Are confere	ence rooms easily accessed for public / parent use?			4			Comments	1.00	
1	Very unsatisfactory - Not accessible for public/parent use				•	•			
2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find								
3	Average - Adequate accessibility, needs updates or renovations to function well								
4	Satisfactory - Good accessibility, good transparency, good size and condition								
5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition								
N/A	Does not apply								