

Educational Suitability Summary Report

Cowan Elementary School

Date: 01/05/2021 Score 64% Average

Cowan Elementary School, serving an enrollment of approximately 640 students, is in southwest Austin. It was built in 1999 and consists of approximately 70,000 SF. The school is named after longtime educator Dennis E. Cowan. Its mission is to nurture and inspire children to achieve their personal best every day. A signature program for social and emotional learning is provided through a certified therapist.

Learning studios are adequate, but no collaborative spaces or small group spaces are present. Studios are joined in pairs and sound travels between rooms. Learning opportunities are limited to specific studio setups. Furniture is flexible but lacks variety in types and options. Storage is ample with cabinetry. Special education studios are the same as a typical studio. Additional provisions are not in place. The addition of a changing table in the restroom limits the required ADA clearances.

Exterior learning spaces are	e limited.
	Picnic tables are provided under some trees, but no seating is provide
around other parts of the ca	ampus.

Exterior circulation paths are well-separated between buses and vehicular traffic. Parking is also well-separated. The front entry is well-planned with clear wayfinding and signage. Several features are in place to celebrate team spirit and community, such as the historic bell and printing press, coyote graphics and the crayon-shaped building columns at the front of the building.

Interview Overview

The interview was conducted with Principal Travis Brunner, Assistant Principal Christine Snowden, art teacher Angelica Wilson and teachers Wendy Sauceda and Katie Brown. The building is relatively new and in good condition on the exterior.

There is an outdoor learning space that requires students to cross the drive to access.

More outdoor spaces are desired for learning. Outdoor seating is needed for students waiting to be picked up as they currently sit on the ground. Seating at the playground is also a request.

A more robust computer lab is desired to incorporate STEAM projects and curriculum. The current setup is in the corridor and not enclosed as a dedicated room. Science space is lacking, and there is not enough space for science fair and lab uses. The G/T program also needs space options available

Educational Suitability Summary Report

Cowan Elementary School

for students that are pulled out of their studios.

The cafeteria and gym can be combined with an operable wall for performances and assemblies, but this space is not big enough for all students to use at once. There are visual and audio issues with the stage and equipment. Use of the stage often conflicts with the after-school program's use of the cafeteria.

Assessment Findings

The Educational Suitability Assessment of Cowan Elementary School earned a 64% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Administration Spaces

Score is unsatisfactory.

Administrative office is close to entry with clear visibility. Size is small with minimal seating and no digital display. Entry is welcoming with artwork and significant historical identifiers. Overall, the office atmosphere is not welcoming, but the school reports this is an outcome of Covid protocols and safety measures. There are acoustic issues between offices.

Average Categories (51-65%):

General Building

Score is average.

Water leaks are an issue in ceiling at library and art room. Corridors are 8'-0" wide at largest point. Community room is not provided. Small storage room at entry is used as a conference room. Exterior appearance is good. Interior appearance is dated but in average shape.

Security

Score is average.

Controllability of Systems

Score is average.

Learning studios have controllability of heating and cooling within rooms. Lighting controls are all on or all off with no dimming or fixture options.

Academics & Learning

Score is average.

Studios are adequately sized at 880-900 square feet. There are no group rooms for small or medium groups and no collaboration space aside from the library. Special education studios are in a typical studio. Additional provisions are not in place.

PE and Wellness

Perkins&Will

Educational Suitability Summary Report

Cowan Elementary School

Score is average.

Gym is slightly undersized by 200 square feet. Adequate support spaces are provided – storage, office, teacher restroom.

Technology

Score is average.

All teachers have digital and non-digital displays. Each studio has moderate power outlet counts.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

Exterior grounds are in good condition. Building signage is satisfactory. Bus and cars have separate circulation, but during pickup and drop-off, cars can back up onto West Gate Blvd. There were some water drainage issues noted at sidewalks and entries and will be assessed as part of the facility condition assessment. Walking track has eroded and has some tripping hazards.

Environmental Quality

Score is satisfactory.

Staff provided feedback that there was a sewage smell in fifth-grade wing and office. All studios have windows. Some windows are small providing limited outdoor views and limited access to natural light.

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture is sturdy and in good condition, but there is not much variety. All studios have loose tables and chairs.

Food Services

Score is satisfactory.

Cafeteria is sized appropriately for lunch service, but not large enough for all students to use at once. Servery is well-planned and functions adequately.

Media Resources

Score is satisfactory.

Library does not have any enclosed study rooms, but furniture is flexible to meet various learning group sizes. Library can be accessed for after-hours events and meetings.

Visual and Performing Arts

Score is satisfactory.

Music room is adequately sized. Performance space needs A/V updates.

Very Satisfactory Categories (81-100%):

Outdoor Learning and Activity

Score is very satisfactory.

Perkins&Will

Educational Suitability Summary Report

Cowan Elementary School

There is an outdoor studio space that has limited shade provided by tree canopy. Outdoor studio space seating requires some repairs. Access to this area involves crossing traffic paths and is a safety concern.

Playscapes are shaded. No gardens or natural learning opportunities are present.

Supporting Photographs



Entry has iconic crayon columns. Bus and car drop-off and pickup are separate and away from parking. Canopy does not sufficiently protect children from rain.



Historical relics are on display where visitors and students can view them.

Supporting Photographs



Outdoor learning space has bench seating and chalkboard display. Shade provided only from trees.




Play areas are fully covered by shade structures.

Supporting Photographs



Music and performance spaces are in good condition but currently being used to accommodate additional storage during COVID-19 protocols. Capacity to assemble all students at once is a concern for staff.




Administration space is small with limited seating.

Supporting Photographs



Media Center: There are reconfigurable tables and chairs for various group sizes.



Computer lab is open to corridor; no dedicated room.

Supporting Photographs



Neighborhood walking path connects Westgate to campus



Typical studios have minimal natural light and access to outdoor views.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Cowan ES	Kelly McEachern/Anacleto Rojas	12.17.2020

1 - E	xterior		1	2	3	4	5	N/A		8.75	66%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
	1 2 3 4	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination							Cars back up on West Gate lining up to drop off and p	oick up.	
	N/A	Does not apply									
1.2		ing easily identified with appropriate signage and wayfinding?					5		Comments	0.25	1.25
	1 2 3	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden Average - Signage / wayfinding visible but not apparent Satisfactory - Signage / wayfinding is visible but not									
	5 N/A	good condition Very satisfactory - Signage and wayfinding is visible and easy to use Does not apply									

O2/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A			
1.3	Is the dump	oster accessible for trash / compost disposal?			3				Comments	0.50	1.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped									
		/ positioned so people of all heights can access it.									
	N/A	Does not apply	_	_		_	_				
2 - (arning and Activity	1	2	3	4	5	N/A		15.00	87%
2.1	Are outdoo the ed spec	or studios and support spaces appropriately configured per c?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							Children must cross driveway to get to learning area.	Tree canopy p	orovides
	2	Unsatisfactory - Too small, poor condition, disconnected							some shade.		
	3	from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less							Principal's note: Outdoor studio space seating is in ne	ed of some re	pairs.
	4	shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2		playgrounds (elementary only) and support spaces per the ed spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No dedicated active playground							Principal's note: Playground slide was replaced this sp	oring due to cr	ack in
	2	Unsatisfactory - Too small, poor condition, no shade provided							previous slide. New slide is mismatching and not as w	vide as previou	ıs slide.
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less									
	4	shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply							L		

2 - C	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	4	
2.3		s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)	1						Comments 0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learning and Activity.	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access Satisfactory - Good size, good condition, connected to								
	7	learning spaces, good flexibility, water source is accessible with 100 ft hose								
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
	N/A	Does not apply								
2.4	Are the rair ed spec?	gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.00
	1 2 3	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Monitoring answer, does not affect score for Outdoor Learning and Activity.	
	4 5	Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
0.5	N/A	Does not apply	-	1			1			0.00
2.5	Does the so	hool have animal husbandry? (optional) No	-						Comments 0.00	0.00
	5	Yes								
2.6		hool have nature loop trails? (optional)					5		Comments 0.00	0.00
	1 5	No Yes		ļ			!			
2.7		hool have a learning pond? (optional)	1						Comments 0.00	0.00
	1 5	No Yes	•				ı			3.30
2.8		hool have a grass play field and walking trail?					5		Comments 1.00	5.00
	1	No								
	5	Yes								

3 - General Building	1	2	3	4	5	N/A		11.25	64%
3.1 Are interior circulation routes wide enough to safely and effectively accommodate student movement?				4			Comments	0.50	2.00
1 Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
wide									
2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A Does not apply									
Are community use areas arranged so that the school can allow night				4			Comments		
functions without full school access?								0.75	3.00
1 Very unsatisfactory - Cafeteria, gym, and library cannot							The gym and cafeteria can be accessed from the ma	-	_
be accessed after hours 2 Unsatisfactory - Only one of the public spaces (Cafeteria,							areas are secured. Library has side entrance that also	o allows learnir	ng
Gym and Library) can be accessed from parking and							areas to be secured.		
secured after hours									
3 Average - Only two of the public spaces can be accessed									
from parking and secured after hours									
4 Satisfactory - All of the public spaces can be accessed									
from parking and secured from the rest of the building									
but not individually									
5 Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of									
campus for night/evening use with their own entrance									
N/A Does not apply									
Is there a community room that is a dedicated meeting space outside							_		
3.3 of school function?	i	2					Comments	0.75	1.50
Very unsatisfactory - No dedicated community room							Small room near entry has been utilized for ARDS. Se	ats 2-3.	
Unsatisfactory - Community room but within school									
function, no access after school hours									
3 Average - Community room, moderate size, but need									
some renovations or updates to function well Satisfactory - Community room, good size /layout, meets									
needs /functions well									
5 Very Satisfactory - Community room, generous size, nice									
condition, functions appropriately outside of school									
function									
N/A Does not apply		ı				l	T	T	
3.4 Does the general appearance of the school convey pride for the students and community?	l		3				Comments	0.05	
Very unsatisfactory - General appearance is poor					<u> </u>		Principal's comment - General appearance muted by	0.25	0.75
2 Unsatisfactory - General appearance is aged but ok							Covid protocols.	mplementation	011 01
3 Average - General appearance is good							Covid protocois.		
4 Satisfactory - General appearance shows pride in									
campus and student works									
5 Very Unsatisfactory - General appearance shows pride in									
campus and student works and is welcoming to the									
community									
N/A Does not apply									

4 - Security		1	2	3	4	5 1	N/A		16.25
4.1 Does the fo	acility have key card access at all major entries?							Comments	0.25
1	Very unsatisfactory - No entries								
2	Unsatisfactory - 1/4 of major entries								
3	Average - 1/2 of major entries								
4	Satisfactory - 3/4 of major entries								
5	Very satisfactory - All of major entries								
N/A	Does not apply						•		
4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	1.00
1	Very unsatisfactory - No exterior lighting, no secure perimeter)
2	Unsatisfactory – Lighting is limited to front entry only, parking lot lighting poor, security is minimal								_
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate								
4	Satisfactory - Lighting at all night-use entries and								
	parking lots, good condition, signage less visible, perimeter is well secured but needs updates								
5	·								
	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply								
	office located at the school entry and configured with a							Comments	
secure vest	ibule to the main corridor?							Comments	1.00
1	Very unsatisfactory - No secure vestibule, office located								
	far from main entry, allows visitors access to school								
2	unsupervised Unsatisfactory - No secure vestibule, office located								
2	somewhat far from main entry, minimal supervision of								
	visitors								
3	Average - Office close to entry, views of front door, but								
	no secure vestibule								
4	Satisfactory - Office is well-located with a secure								
	vestibule, but needs updates								
5	Very satisfactory - Office well-located with secure								
	vestibule and all appropriate security features								
N/A	Does not apply								
1 /1 /1	ough interior transparency for faculty to passively supervise ad their activities who are not in studios?		2					Comments	1.00 2.00
1	Very unsatisfactory - No transparency of walls							Glass lite provided in door, but frequently covered w	ith curtains or paper.
2	Unsatisfactory - Limited transparency in certain locations								
3	Average - Good transparency in certain locations but								
	inadequate or missing in other locations of school								
4	Satisfactory - Adequate transparency throughout the								
	school								
5	Very satisfactory - Excellent transparency throughout the								
	school								
N/A	Does not apply								

Perkins&Will 02/11/2022 ⁶

	5 - Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	68%
	5.1 How are ac	coustics in studios in general?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Sound transfer between joined studios that have ope	ening between	rooms.
	5.2 Is the studio	o artificial lighting adequate quality?			3				Comments	1.00	3.00
•	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare		l			l		Some glare. Cloth coverings are used over direct ligh	ting.	
		Does not apply tess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply									
	5.4 Is there acc	ess to outside views from learning spaces?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views									

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	A.		
5.5 Does the b	ouilding have odor or pest problems?		2					Comments	1.00	2.00
1	Very unsatisfactory - Evidence of both pests and odors							Sewage smells reported at interview.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	L.	12.50	60%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, I	Fixtures & Equipment	1	2	3	4	5	N/A		18.75	69%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply				•					
1.7	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?		2					Comments	1.00	2.00
1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture									
7.3 How well a space?	Does not apply does furniture accommodate rapid reconfiguration of a				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply									
7.4 Is the furni	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow students to be active Does not apply									

Perkins&Will 02/11/2022 ⁹

	1	2	3	4	5	N/A		5.00	6
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?			3				Comments	0.50	
 Very unsatisfactory - There are no recycling and la bins and signage are sparse or infrequent, OR ther only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a landfill and recycle collection containers in an accellocation. The containers have clear signage. Very satisfactory - All studios / corridors (100%) havisible landfill and recycle collection containers in accessible locations. The containers have clear signand the style and format is consistent and uniform campus. 	a cion. I visible essible live						A score for this category is being recorded, but this cate calculated in the overall ESA average.	egory is not	
N/A Does not apply Does the cafeteria (or wherever meals are served) have at least of each: green compost bin, blue recycle bin, and landfill bin? A			3				Comments		
or each: green compost bin, blue recycle bin, and idnatili bin? A bins labelled clearly with bilingual and/or image sorting?								0.50	



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

	School Name								Walk Attendees:	Date:	
	Cowan ES								Kelly McEachern/Anacleto Rojas	12.17.202	20
							-				
8 - 8	Academics	& Learning	1	2	3	4	5	N/A	4	70.00	51%
8.1	Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1 2 3	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							Studios are between 860 to 930 square feet.		
	5 N/A	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces Does not apply									
8.2		and Kinder have appropriate support spaces such as				4			Comments		
	restrooms o	and storage per the ed spec?								1.00	4.00
	2	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition									
	3 4 5	Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
	N/A	condition									

O2/11/2022 ²

8 - <i>A</i>		& Learning (cont.)	1	2	3	4	5	N/A	V.		
8.3	Do studios ed spec?	have appropriate support spaces such as storage per the				4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		learning neighborhoods have small group rooms and open	1						Comments		
0.4	collaborati	•							Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	5	acoustic privacy Very Satisfactory - Generous size, excellent condition and									
	5	flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
	-	Il studios large enough to support project-based learning		1	l	1	1	T		l	
8.5		le teaching modalities?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, does not		l						1.00	3.00
	'	support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
		limited flexibility									
	3	Average - Adequate size, needs some renovations or									
	Ĭ	updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - 8	Academics 8	& Learning (cont.)	1	2	3	4	5	1	N/A			
8.6	Are Maker S the ed spec	Spaces and support spaces appropriately configured per ?		2						Comments	1.00	2.00
	1 2 3 4	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected to learning spaces Very Satisfactory - Generous size, excellent condition,								No science/makerspace. Computer lab is open to corr		
	N/A	connected to learning spaces Does not apply										
8.7	•	ofessional Learning Center in the learning neighborhood?			3			T		Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected								VIP area in open hallway separated with cubicle walls		
	N/A	Does not apply							L			
8.8	Is there a de	edicated science room and support space?	1							Comments	0.00	0.00
	1 5	No Yes								Monitoring answer, but doesn't affect overall score.		
8.9		dequate places to display the evidence and artifacts of oth 2D and 3D)?				4				Comments	1.00	4.00
	3	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well										
	4 5	Satisfactory - Good size, good condition										
	N/A	Very Satisfactory - Generous size, excellent condition Does not apply										

Perkins&Will 02/11/2022 ⁴

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.10	Does the bu	uilding provide adequate opportunities for		2					Comments		
0.10	students/te	eachers to collaborate in varying group sizes?							Comments	1.00	2.00
	1	Very unsatisfactory - No space to support collaboration							No collaboration spaces outside of library.		
		in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
	4	updates or renovations to function well. Satisfactory - Good size, good condition, multiple options									
	4	to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply									
				I		1					
8.11	Does the bu	uilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space									
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
	J	layout and furnishings support informal interactions									
	N/A	Does not apply									
		arning neighborhood / building provide adequate									
8.12		es for students to work independently?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms/small study							No dedicated areas for independent work.		
		spaces							·		
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to									
	5	learning neighborhood Very Satisfactory - Generous size, excellent condition,									
	ŭ	acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply							1		

Perkins&Will 02/11/2022 ⁵

8 - A	cademics 8	& Learning (cont.)							
8.13	Are Special spec?	Education spaces appropriately configured per the ed			3		Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected					Special education studio is same as typical studio.		
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and							
		shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning							
	5	spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent							
		transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
8.14	•	Education support spaces, such as storage, space for er, appropriately configured per the ed spec?		2			Comments	1.00	2.00
	1	Very unsatisfactory - None provided					No washer/dryer. Changing table in restroom blocki	ng clearance f	or ADA
	2	Unsatisfactory - Too small, disconnected, poor condition					needs.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
8.15		ble restrooms and changing rooms readily available to the location spaces?	1				Comments	1.00	1.00
	1	No					Changing table in restroom blocking clearance for A	DA needs.	
	5	Yes							

Perkins&Will 02/11/2022 ⁶

9	- Vi	sual and F	Performing Arts	1	2	3	4	5	N/A	A	15.00	80%
	Q I	Are music sp per the ed s	paces and the cafeteria stage appropriately configured pec?			3				Comments	1.00	3.00
		1	Very unsatisfactory - Too small, missing program spaces							A/V equipment needs updates.		
		2	Unsatisfactory - Too small, poor condition									
		3	Neutral - Adequate size, adequate condition, needs									
			updates or renovations to function well.									
		4	Satisfactory - Good size, good condition									
		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply									
	9.2	Are music a	nd performance storage spaces appropriately configured					5		Comments		
	9.2	per the ed s	pec?					5		Comments	1.00	5.00
		1	Very unsatisfactory - None provided							Music room has adequate storage and is adjacent to	stage/perforr	mance
		2	Unsatisfactory - Too small, disconnected, poor condition							area. Stage area has (2) small storage closets.		
		3	Neutral - Adequate size, average condition, needs									
			updates or renovations to function well									
		4	Satisfactory - Good size, connected, good condition									
		5	Very Satisfactory - Generous size, connected, excellent									
			condition									
		N/A	Does not apply		1							
	U · X		rts spaces and storage appropriately configured per the				4			Comments		
		ed spec?									1.00	4.00
		1	Very unsatisfactory - Too small, missing program spaces							No restrooms. Access to restrooms is far away from re	oom.	
		2	Unsatisfactory - Too small, poor condition									
		3	Average - Adequate size, adequate condition, needs									
			some renovations or updates to function well									
		4	Satisfactory - Good size, good condition									
		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply									

10.00	60%
Comments 1.00	3.00
edback that gym cannot support both gym te It the same time. Gym is slightly undersized at	
Comments 1.00	3.00
,	
10.00	70%
Comments 1.00	3.00
edback that cafeteria and gym combined car n all students.	not
Comments 1.00	4.00
	omments 1.00

12 - Media Resources	1	2	3	4	5	N/A	4	30.00	67%
Is the Library/Media Center easily accessible for the occupants and				4			Comments		
visitors to the school?				7			Comments	1.00	4.00
1 Very unsatisfactory - Not accessible							Public access through side entry.		
 Unsatisfactory - Limited access, difficult to find, no 									
transparency									
Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Accessible, easy to find, good transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent									
transparency, excellent condition									
N/A Does not apply									
***		l _					_		
12.2 How well does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
l Very unsatisfactory - No quiet study spaces		l .					Open area with tables and chairs provided.		
2 Unsatisfactory - One area in poor condition, poor									
acoustic privacy									
3 Average - One or more areas provided, needing updates									
or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy N/A Does not apply									
•••		1			1	T			
12.3 How well does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1 Very unsatisfactory - No space							3 different seating styles.		
 Unsatisfactory - Too small, poor condition, layout and 									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply									
How well does the Library/Media Center support collaborative work		1	1		I				
in small groups (4-8 students)?		2					Comments	1.00	2.00
Very unsatisfactory - No breakout rooms, no flexible	1	<u> </u>		1	1	1	No enclosed study rooms.		
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
 Average - Adequate size, multiple areas provided, 									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

12 - Media Resources - Continued	1	2	3	4	5	N/A	1		
12.5 How well does the Library/Media Center support collaborative work in larger groups (10-25)?				4			Comments	1.00	4.00
1 Very unsatisfactory - No gathering areas 2 Unsatisfactory - Too small, one common space, limited seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with							Flexible tables and seating.		
seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply									
12.6 How well does the Library/Media Center support technology?				4			Comments	1.00	4.00
1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply									
13 - Technology	1	2	3	4	5	N/A		20.00	55%
13.1 How well equipped are the facilities with instructional technology?				4			Comments	1.00	4.00
1 Very unsatisfactory - Limited to no technology present in instructional spaces 2 Unsatisfactory - One type of technology present 3 Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school 4 Satisfactory - Multiple types of technology, smart boards, good condition. 5 Very Satisfactory - Multiple types of technology, smart boards, excellent condition N/A Does not apply									
ls.there an adequate number of power and data outlets in learning spaces?			3				Comments	1.00	3.00
1 Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) 2 Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) 3 Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) 4 Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) 5 Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									3.00
N/A Does not apply									

O2/11/2022 ¹⁰

13.3 Are there adequate charging locations for devices? 1 Very unsatisfactory - No centralized charging location 2 Unsatisfactory - Centralized charging location, but inadequate in size for number of devices	1.00
2 Unsatisfactory - Centralized charging location, but inadequate in size for number of devices	
3 Average - Charging cart or tower but not adequately sized for number of devices	
4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition	
N/A Does not apply	
13.4 Is there adequate AV for presentations spaces – cafeteria and gym? 3 Comments	3.00
1 Very unsatisfactory - AV not present in one or more space 2 Unsatisfactory - AV undersized for room, poor condition Interview provided feedback that assembly space for all studer adequately supported by gym and cafeteria combined.	ts is not
 Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition 	
4 Satisfactory - Good size, good condition	
5 Very Satisfactory - Generous sized, excellent condition	
N/A Does not apply	
13.5 Is there digital media signage at the reception area?	0.00
1 Very unsatisfactory - No digital media present in reception area	
2 Unsatisfactory - Undersized, poor condition	
3 Average - Adequately sized / poor condition OR undersized / adequate condition	
4 Satisfactory - Media signage present, good sized, good condition	
Very Satisfactory - Generously sized, excellent condition	
N/A Does not apply	

14 - Administration Spaces	1	2	3	4	5	N/A	\	20.00	50%
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	100	
1 Very unsatisfactory - No security checkpoint		ļ		<u> </u>	<u> </u>		,	1.00	
- Official of a control of the contr									
3 Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply	ı		1	1				1	
14.2 Does the administration area feel welcoming?		2					Comments	1.00	2.00
1 Very unsatisfactory - No welcome space						-		•	
2 Unsatisfactory - Too small, poor lighting and									
transparency, limited informal seating, poor condition									
3 Average - Adequate size and layout, needs updates or									
renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and									
transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of									
light and transparency, informal seating provided,									
excellent condition									
N/A Does not apply	ı		1	1	1		T	T	
For those spaces that require it, does the administration area have			3				Comments		
adequate acoustic privacy?				<u> </u>				1.00	3.00
Very unsatisfactory - No acoustic separations							Sound and conversation can be heard between offic	es in the	
Unsatisfactory - Acoustic separations do not perform							administration area.		
well									
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply				1	1		T	I	
14.4 Are conference rooms easily accessed for public / parent use?			3				Comments	1.00	3.00
1 Very unsatisfactory - Not accessible for public/parent							Office conference is being used as office space. Store	age room is bei	ng
use							used as conference space. Seats 2-3.		
2 Unsatisfactory - Limited access, no transparency, poor							· ·		
condition, difficult to find									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition									
N/A Does not apply									