

Educational Suitability Summary Report

Galindo Elementary School

Date: 01/27/2021 Score 66% Satisfactory

Galindo Elementary School serves an enrollment of approximately 495 students in south Austin. It was constructed in 1989, with a mechanical building addition in 2001, and consists of approximately 85,000 square feet on 9 acres. The campus participates in the district's AVID (Advancement Via Individual Determination) program and the Creative Learning Institute to bring its students an innovative curriculum. It is also a dual-language school that focuses on social and emotional learning.

Overall, the building is able to support most of the campus's needs and programs, as well as meeting some of the district's Education Specifications. Outdoor learning spaces need updates to function well, but the campus has made do with what it has. The library is a much-loved space on campus, and its central location in the building allows for the surrounding corridor to be used as a parade route. The large flex spaces in three of the classroom wings provide opportunities for collaboration but create some inequity as one classroom wing does not have one. The visual and performing arts spaces are generous; both art and music have two studios on campus.

Interview Overview

The interview participants consisted of Principal Natascha Barreto-Romero and AISD Construction Manager Rumman Zamir. The campus is passionate about the outdoor learning areas, but infrastructure improvements are needed for full utilization. The wish list for outdoor learning spaces includes adding a Green and Global program, more suitable outdoor furniture, access to power and water, and signage. They would like to ensure that the following items remain intact: the Emma Courtyard off the cafeteria, the bee apiary, monarch gardens, goat pen and the trees on the back of campus throughout the playgrounds.

The principal also highlighted the immediate need for restructuring and adding a circle drive to the back of the building as a solution to the current traffic congestion during morning arrival and dismissal.

The campus lacks a maker space, STEM lab and suitable spaces for early childhood special education programs and life skills. These spaces are in portables and are disconnected from the rest of the campus and adequate resources. The cafeteria is undersized and unwelcoming, not allowing for family tables during lunch periods or for all students to fit at once. They have some open pod areas that encourage collaboration and a heavily utilized stage that promotes creativity and cultural events. They have adequate space to host district meetings, depending on the size, and due to the close proximity to the district's central office they get asked to host frequently.

Educational Suitability Summary Report

Galindo Elementary School

In the future, they would like to see more flex space, foldable partitions and flexible furniture. Having large, shared spaces where a whole grade level could gather to collaborate would be ideal. Outdoor learning should be expanded and improved to provide dedicated outdoor studios. Technology infrastructure needs to be updated and the number of outlets should be increased to improve studio function.

Assessment Findings

The Educational Suitability Assessment of Galindo Elementary School earned a 66% overall score and places the campus in a category of Satisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Average Categories (51-65%):

Exterior

Score is average.

Bus and vehicular traffic are separate, but stack space is small. The main entrance is clearly identifiable and exterior signage is adequate. The marquis is outdated and often not functional. All dumpsters are present at loading dock to cafeteria, but the route is not accessible.

General Building

Score is average.

Some corridors at studios are very narrow, but general circulation is adequate. The cafeteria and gym can be accessed from an exterior entry but only partially restricted from the rest of the campus for after-hours functions. There is a parent and community space across the hall from the reception area at the main entry, but it cannot be accessed after-hours or locked down from the rest of the building. This room is also undersized per Ed Spec requirements.

Security

Score is average.

Furniture, Fixtures, Equipment

Score is average.

Furniture is a mix of old and newer items, mostly in good condition. Only the library has variety in furniture types; all other multi-use spaces have only one type available. Larger tables in studios are more cumbersome to move, but student desks in other spaces allow for more flexibility.

Academics & Learning

Score is average.

Studios range in square footage and some are undersized. Two kinder classrooms are in non-early childhood spaces, and early childhood special education is located in a portable. There are no dedicated storage closets, but large cabinets are present in each room. Three studio wings have a large, shared flex space in the corridor that allows for group collaboration; one wing does not. Some wings have small, shared conference rooms in corridors for individual or small group breakouts, but they are sporadic and inconsistent. Furniture and niches in corridors allow for opportunities for

Educational Suitability Summary Report

Galindo Elementary School

informal interaction. There are no dedicated maker spaces or professional learning centers. Special education spaces have access to appropriate support spaces, but they are disconnected from each other.

Media Resources

Score is average.

The library is centrally located on campus and appropriately sized. There are no true quiet study space or breakout rooms for collaborative work, but the layout of the space allows for different zones of activity. Projection and mobile TV displays were present.

Administration Spaces

Score is average.

The administration area feels welcoming, but waiting room is minimal. Staff noted that conversations can be heard between offices in the suite.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

There are no dedicated outdoor studio spaces, but picnic tables and other resting areas are scattered throughout the playground and field areas. Playgrounds do not have shade structure, but there are trees that provide coverage at the upper grade level playgrounds. Gardens are disconnected from learning spaces and have no direct access to water. The campus has animal husbandry with both chickens and goats.

Environmental Quality

Score is satisfactory.

All studios have windows with access to natural light and views of nature. Staff notes issues with pests, including ants and rats, but no odors.

Controllability of Systems

Score is satisfactory.

All studios have blinds to control daylight and thermostats for individual temperature control. Artificial lights are controlled with two switches for alternating rows of lights.

Visual and Performing Arts

Score is satisfactory.

The campus has two music rooms, with one being adjacent to the stage for good connectivity, and both have storage space present. There are two art rooms, with a kiln in one space and storage closets and cabinets in both.

Food Services

Score is satisfactory.

The cafeteria is connected to the gym with an operable wall, and the space is a generous size. There is only one option for seating, but there is access to a courtyard for outdoor dining.

Educational Suitability Summary Report

Galindo Elementary School

Technology

Score is satisfactory.

Most studios have projection and mobile TV displays present but lack an adequate number of power and data outlets. The cafeteria is equipped with projection, but the gym only has a mobile TV display. A mobile TV display is used at the main entry. No permanent TV is installed in the reception area.

Very Satisfactory Categories (81-100%):

PE and Wellness

Score is very satisfactory.


The gym is appropriately sized, and the flooring is in excellent condition. Additional storage would be helpful to reduce items stored in gym, but storage space is present.



There is no secure vestibule at the main entry, but the reception space is close to the main entry doors. There is no permanent digital TV display but a mobile one is used.



Most studios are connected to an adjoining room and a shared restroom. Furniture is a mix of old and new, with some flexibility.



Media Resources: The library is generously sized and has a variety of furniture. It is laid out so that zones for different activities can be created.



The Emma Courtyard contains artwork honoring the namesake of the school that the campus would like to keep. It is off the cafeteria and could be used for outdoor dining as well as an outdoor studio space.



The cafeteria is appropriately sized but only has one option for furniture. It is well connected to the music room for easy access to the stage.



Primary corridors are wide and have opportunities for informal interaction and breakout spaces for students and teachers, with furniture available to support them.



Three of the four studio wings have a large, shared flex space in the corridor. This space is used for science activities with materials stored behind the back wall.



Pre-K and kindergarten have a separate playground with easy access to the studio wing. It is only partially shaded.



The gym is appropriately sized, and the flooring is in good condition.



On the back of campus there is a playground for upper grade levels, a play field and walking trails, and portables, as well as areas for outdoor studios. A covered outdoor concrete court is present (not shown in photograph). A water source for their bee apiary (not shown in photograph) is a high priority for the campus.

Educational Suitability Summary Report Galindo Elementary School



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Galindo Elementary School	Emilie Ogburn	1.27.2021

1 - E	kterior		1	2	3	4	5	N/A	1	8.75	54%
1.1	Does the sit	re permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Small stack area at front of school and small loop thr	ough parking l	ot
		at the same location							present at the back of campus.		
	2	Unsatisfactory - Cars and buses mix, pedestrians are									
		separated									
	3	Average - Buses, cars, and pedestrians are separate but									
		stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply									
1.2	ls the buildi	ng easily identified with appropriate signage and			3				Comments		
1.2	community	wayfinding?			9				Comments	0.25	0.75
	1	Very unsatisfactory - Campus has no signage /							Main entry is clearly identified and exterior signage is	s adequate. Int	terior
		wayfinding							wayfinding is more confusing due to layout of the bu	ilding.	
	2	Unsatisfactory - Signage/wayfinding is faded/hidden								· ·	
	3	Average - Signage / wayfinding visible but not apparent							Principal's note - Marguis is dated and often not fund	tional	
	4	Satisfactory - Signage / wayfinding is visible but not							Trincipal of foco in a figure to dated and of confidence	.c.o.rai.	
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible and									
		easy to use									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ²

1 - E	xterior (cor	nt.)	1	2	3	4	5	N/A			
1.3	Is the dump	oster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.							All three dumpsters are present but loading dock is n	ot accessible.	
2 - 0	N/A Outdoor Le	Does not apply arning and Activity	1	2	3	4	5	N/A		15.00	67%
2.1		r studios and support spaces appropriately configured per		2				.,,,	Comments	1.00	2.00
	1 2 3 4	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Picnic tables located near playgrounds have no shad disconnected from learning spaces. The school requests tables and equipment to display		nd are
2.2		Does not apply blaygrounds (elementary only) and support spaces per the ed spec?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply				1			Shade provided by trees at upper level playground; of are covered.		

2 - C	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	A	
2.3		s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)		2					Comments 0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learning an Activity. No access to water and disconnected from learning space	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
	4 5	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
	b N/A	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation Does not apply								
2.4	Are the rain ed spec?	gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.00
	1 2	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected							Monitoring answer, does not affect score for Outdoor Learning an Activity.	d
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well								
	4	Satisfactory - Good size, good condition, functions properly								
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
0.5	N/A	Does not apply					-	1		0.00
2.5	Does the sci	nool have animal husbandry? (optional) No					5		Comments 0.00	0.00
	5	Yes								
2.6	Does the scl	nool have nature loop trails? (optional)	1						Comments 0.00	0.00
	1 5	No Yes		•			•	-		
2.7	Does the scl	nool have a learning pond? (optional)	1						Comments 0.00	0.00
	1 5	No Yes								
2.8	Does the scl	nool have a grass play field and walking trail?					5		Comments 1.00	5.00
	1	No								
	5	Yes								

	3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	60%
	3.1	circulation routes wide enough to safely and effectively late student movement?				4			Comments	0.50	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide Average - Primary circulation is 7'-0" to 8'-0" wide Satisfactory - Primary circulation is 8'-0"-10'-0" wide Very satisfactory - Primary circulation is 10'-0"+ wide				•	l		Some corridors at classrooms are narrow (7 feet) and circulation areas are more generous (10 feet).	other primary	
	Are commu	Does not apply unity use areas arranged so that the school can allow night vithout full school access?		2					Comments	0.75	1.50
1	1 2 3 4	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours Average - Only two of the public spaces can be accessed from parking and secured after hours Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of							The cafeteria and gym can be accessed from the external and closed off from parts of the building but the scholocked down from these areas.	erior secondar	y entry
	N/A	campus for night/evening use with their own entrance Does not apply									
	Is there a co	ommunity room that is a dedicated meeting space outside									
	3.3 of school fu	unction?			3				Comments	0.75	2.25
	1 2 3 4 5	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function							Parent room across hall from reception, but area is no off from the rest of the building. It is undersized per E		
Ī	N/A Does the ge	Does not apply eneral appearance of the school convey pride for the		l	Π	Π	l	l			
		nd community?				4			Comments	0.25	1.00
	1 2 3 4 5	Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very Satisfactory - General appearance shows pride in campus and student works and is welcoming to the community Does not apply									

4 - Security		1	2	3 4	5	N/A		16.25	
4.1 Does the fa	ncility have key card access at all major entries?						Comments	0.25	
1 2 3 4 5 N/A	Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries Average - 1/2 of major entries Satisfactory - 3/4 of major entries Very satisfactory - All of major entries Does not apply		1	- 1	1				
	uate is site lighting and security for the campus overall?						Comments	1.00	
1 2	Very unsatisfactory - No exterior lighting, no secure perimeter Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal					l)
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate							,	
5	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply								
1 4 3	office located at the school entry and configured with a ibule to the main corridor?						Comments	1.00	
2	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors)
3	Average - Office close to entry, views of front door, but no secure vestibule								
4 5	Satisfactory - Office is well-located with a secure vestibule, but needs updates Very satisfactory - Office well-located with secure								
N/A	vestibule and all appropriate security features Does not apply								
	ough interior transparency for faculty to passively supervise d their activities who are not in studios?		2				Comments	1.00	2.00
1	Very unsatisfactory - No transparency of walls								
2	Unsatisfactory - Limited transparency in certain locations								
3 4	Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the								
5	school Very satisfactory - Excellent transparency throughout the school								
N/A	Does not apply								

Perkins&Will 02/11/2022 ⁶

5 - Environmental Quality		1	2	3	4	5	N/A		25.00	72%
5.1 How are acoustics in studios in general?				3				Comments	1.00	3.00
1 Very unsatisfactory - Recognized word/sound adjacent studio/corridor 2 Unsatisfactory - Audible sound from adjacent studio/corridor 3 Average - Slight sound from outside room 4 Satisfactory - Walls to deck insulated only wh from mechanical system 5 Very satisfactory - Able to hear quiet speaking across the room N/A Does not apply	ite noise									
5.2 Is the studio artificial lighting adequate quality?				3				Comments	1.00	3.00
1 Very unsatisfactory - Sporadic lights work, glo than 20 FC 2 Unsatisfactory - 10-19 FC or serious glare 3 Average- 20-29 FC minor glare 4 Satisfactory - 30-39 FC and no glare 5 Very satisfactory - 40+ FC and no glare N/A Does not apply	are, less									
5.3 Is there access to natural light in studios?						5		Comments	1.00	5.00
1 Very unsatisfactory - No learning spaces have light 2 Unsatisfactory - 1-25% of learning spaces have light or windows are too small to let in light 3 Average - 26-50% of learning spaces have not spaces have light 5 Very satisfactory - 76-100% of learning space natural light N/A Does not apply	e natural atural light natural							All studios have windows, average size.		
5.4 Is there access to outside views from learning spaces?						5		Comments	1.00	5.00
1 Very unsatisfactory - No learning spaces have 2 Unsatisfactory - 1-25% of learning spaces have windows are too small to see out 3 Average - 26-50% of learning spaces have vie 4 Satisfactory - 51-75% of learning spaces have 5 Very satisfactory - 76-100% of learning space views N/A Does not apply	e views or ews views								,	

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	building have odor or pest problems?		2					Comments	1.00	2.00
1	Very unsatisfactory - Evidence of both pests and odors							Ants and rats, no odors.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	4	12.50	68%
6.1 Does the s	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shade	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							1		

7 - Fu	urniture, F	ixtures & Equipment	1	2	3	4	5	N/A		18.75	64%
7.1	What is the	current condition of the furniture?				4			Comments	0.75	3.00
	1 2 3 4 5	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New									
	N/A	Does not apply									
7.2		ty of furniture types being accommodated throughout the irning commons, dining commons, other multi-use spaces?		2					Comments	1.00	2.00
	1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply oes furniture accommodate rapid reconfiguration of a				1	1				
7.3	space?	oes furniture accommodate rapid recominguration of a			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply							Large tables in studios are more difficult to move but desks as well.		
7.4	•	ure ergonomic and size appropriate for grade level?				4			Comments	100	4.00
	1 2 3 4 5	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow students to be active								1.00	4.00

Perkins&Will 02/11/2022 ⁹

Waste		1	2	3	4	5	N/A		5.00	8
Do studios and corridors have instructions and/or image sorti	blue recycle bins with bilingual ing instructions?				4			Comments	0.50	2.
bins and signage only landfill bins v Unsatisfactory - B infrequent and/o Average - 50% of landfill bin and a The containers ho Satisfactory - 75% landfill and recycl location. The cont Very satisfactory visible landfill and accessible locatio	ry - There are no recycling and landfill are sparse or infrequent, OR there are with no recycling bins. sins and signage are sparse or r lack clear signage. corridors and studios have both a recycle bin in an accessible location. sive clear signage. sof studios and corridors have a visible le collection containers in an accessible tainers have clear signage. - All studios / corridors (100%) have drecycle collection containers in ns. The containers have clear signage, format is consistent and uniform across							A score for this category is being recorded, but this co-calculated in the overall ESA average.	ategory is not	
•	er meals are served) have at least one ue recycle bin, and landfill bin? Are the uual and/or image sorting?				4			Comments	0.50	2
are no compost a sorting signage. 2 Unsatisfactory- Represent, but the back to one anoth 3 Average- There is three bins (recycle	ry-There may be landfill bins, but there nd/or recycle bins. There is not clear ecycle, landfill, and compost bins are sins are scattered and no co-located her. Signage is absent or inconsistent. It at least one waste station with all expressions, compost, landfill) located with close another. The signage is visible and the are several waste stations as									



Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Galindo Elementary School	Emilie Ogburn	1.27.2021

8 - Academics & Learning	1	2	3	4	5	N/A	A	70.00	57%
8.1 Are studios appropriately configured per the ed spec?			3				Comments	1.00	3.00
1 Very unsatisfactory - Too small, no flexibility, disconnected 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and							Most studios are undersized with some exceptions. Principal's note: Two kinder classes are assigned to no spaces, and the ECSE classroom is located in a portab	n early childh	
, ,			3				Comments	1.00	3.0
1 Very unsatisfactory - None provided							Not all rooms have restrooms connected.	1.00	3.00
2 Unsatisfactory - Too small, disconnected, poor condition							Two tall rooms have restrooms connected.		
 Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition 									
Very Satisfactory - Generous size, connected, excellent condition									
N/A Does not apply									

Perkins&Will 02/11/2022 ²

8 - <i>A</i>	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A	A		
8.3		nave appropriate support spaces such as storage per the			2				Comments		
8.3	ed spec?				3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							No dedicated closet spaces but large cabinet areas.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4	Do typical le	earning neighborhoods have small group rooms and open			3				Comments		
0.4	collaboratio	on space?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No breakout rooms or open							3 studio wings have large shared flex space on corrido	r.	
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
8.5		studios large enough to support project-based learning			3				Comments		
	and multipl	e teaching modalities?			Ů					1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, does not							Most studios are undersized, but some are generous a	nd able to su	pport
		support project-based learning							this well.		
	2	Unsatisfactory - Undersized, decentralized resources,									
		limited flexibility									
	3	Average - Adequate size, needs some renovations or									
		updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
	_	flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - <i>A</i>		& Learning (cont.)	1	2	3	4	5	N/A			
8.6		Spaces and support spaces appropriately configured per	1						Comments		
0.0	the ed spec	?	'						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N/A	connected to learning spaces									
	IN/A	Does not apply		l I	l	1		l I			
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for		<u> </u>				<u> </u>			
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply									
ΩΩ	ls there a de	edicated science room and support space?	1						Comments		
0.0	is there a ac	calcuted science room and support space.	-						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9	Are there a	dequate places to display the evidence and artifacts of							6 .		
8.9	learning (bo	oth 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space									
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	NI/A	Does not apply									

Perkins&Will 02/11/2022 ⁴

8 - A	cademics 8	1	2	3	4	5	N/A	1			
0.10	Does the bu	uilding provide adequate opportunities for				4			Community		
8.10	students/te	achers to collaborate in varying group sizes?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No space to support collaboration in various sizes. Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes							Three studio wings have large, shared space in corrid large groups to collaborate.	lors that allows	for
	3	Average - Adequate space for collaboration, needs updates or renovations to function well. Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply				1	ı				
8.11	Does the bu	uilding provide opportunities for informal interaction?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space							Furniture and niches in corridors provide opportunities	es for informal	
	2	Unsatisfactory - Too small, poor condition, layout and							interaction.		
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
		furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
		layout and furnishings support informal interactions									
	N/A	Does not apply									
0.10	Does the lea	arning neighborhood / building provide adequate		0					Community		
8.12	opportuniti	es for students to work independently?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms/small study							Some wings have conference rooms in corridors that	can serve as br	reakout
		spaces							space; others have a large, shared corridor space tha		
	2	Unsatisfactory - Too small, poor condition, no acoustic							individual work as well.		
		privacy, only one space for independent work,							individual work as well.		
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply									

O2/11/2022 ⁵

8 - A	cademics	& Learning (cont.)						
8.13	•	Education spaces appropriately configured per the ed		3		Comments		
	spec?						1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility,				Located in standard studios mostly, but they have ac	cess to multiple	е
		disconnected				resources.		
	2	Unsatisfactory - Too small, only one area for all teaching						
		methods, limited flexibility, disconnected						
	3	Neutral - Adequate size, multiple areas for different						
		teaching methods, adequate flexibility, limited						
		transparency and connection to other studios and						
		shared learning spaces, needs updates or renovations to						
		function well.						
	4	Satisfactory - Good size, multiple areas for different						
		teaching methods, good flexibility, good transparency						
		and connection to other studios and shared learning						
	_	spaces						
	5	Very Satisfactory - Generous size, multiple areas for						
		different teaching methods, excellent flexibility, generous						
		display area and visual teaching tools, excellent						
		transparency and connection with other studios and						
	N/A	shared learnina spaces Does not apply						
		Education support spaces, such as storage, space for		I				
8.14	•	ver, appropriately configured per the ed spec?		3		Comments	1.00	3.00
	1	Very unsatisfactory - None provided	1			Dispersed throughout school and adequately sized.	1.00	3.00
	2	Unsatisfactory - Too small, disconnected, poor condition				Dispersed tilloughout school and adequately sized.		
		·						
	3	Neutral - Adequate size, average condition, needs						
		updates or renovations to function well						
	4	Satisfactory - Good size, connected, good condition						
	5	Very Satisfactory - Generous size, connected, excellent						
		condition						
	N/A	Does not apply						
8.15		ble restrooms and changing rooms readily available to the			5	Comments		
0.13	Special Edu	ication spaces?			5	Confinents	1.00	5.00
	1	No						
	5	Yes						

Perkins&Will 02/11/2022 ⁶

9 -	· Visual and I	Performing Arts	1	2	3	4	5	N/A	4	15.00	80%
9	.1 Are music s per the ed s	paces and the cafeteria stage appropriately configured spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces							Good adjacency and well connected.		
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
9	Are music a	and performance storage spaces appropriately configured				4			Community		
9	.2 per the ed s	spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided							Two music rooms with practice rooms and storage.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
9	·2	Arts spaces and storage appropriately configured per the				4			Comments		
	ed spec?								Comments	1.00	4.00
	1	Very unsatisfactory - Too small, missing program spaces							Two arts room, kiln in one and storage in both.		
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁷

10 - PE and We	llness	1	2	3	4	5	N/A		10.00	90%
I 1∩ 1	mpus meet the ed spec standard for physical education					5		Comments		
program sp						Ŭ			1.00	5.00
1	Very unsatisfactory - Too small, missing program spaces							Gym appropriately sized. Flooring is in great shape.		
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply					1	1			
1 10 2	sical education storage spaces appropriately configured				4			Comments		
per the ed s	·								1.00	4.00
1	Very unsatisfactory - None provided							Could use additional storage.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
_	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
N/A	condition Does not apply									
11 - Food Servic		1	2	2	1	E	NI/A		10.00	00%
II - rood Servic	es	'	2	3	4	5	N/A	\ 	10.00	80%
11.1 Is the Dining	Commons appropriately configured per the ed spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces	<u> </u>			1			Generous size. Only one option for seating; some acc		
2									ess to outdoor	ureu
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation							for dining.		
3	Average - Adequate size and condition, needs updates									
ა	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation,									
7	multiple options for eating space (ex: connection to									
	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and									
	circulation, multiple options for eating space (ex:									
	connection to outdoor eating space)									
N/A	Does not apply									
Are the Foo	d Services support spaces appropriately configured per				4			Comments		
11.2 the ed spec	?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided									
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

12 - Media Resources	1	2	3	4	5	N/A	\	30.00	57%
ls the Library/Media Center easily accessible for the occupants and				4			Comments		
12.1 visitors to the school?				4			Comments	1.00	4.00
Very unsatisfactory - Not accessible							Centralized location and well sized.		
2 Unsatisfactory - Limited access, difficult to find, no									
transparency									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Accessible, easy to find, good									
transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent									
transparency, excellent condition									
N/A Does not apply				ı	ı	T	T		
12.2 How well does the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 Very unsatisfactory - No quiet study spaces									
2 Unsatisfactory - One area in poor condition, poor									
acoustic privacy									
3 Average - One or more areas provided, needing updates									
or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy 5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy									
N/A Does not apply									
***			3				Community		
12.3 How well does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 Very unsatisfactory - No space									
 Unsatisfactory - Too small, poor condition, layout and 									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply									
How well does the Library/Media Center support collaborative work				T	I				
in small groups (4-8 students)?		2					Comments	1.00	2.00
Very unsatisfactory - No breakout rooms, no flexible					1		No dedicated breakout rooms but layout of space all		
furniture, no support							zones of activity.		
2 Unsatisfactory - Too small, one area, poor condition							Zonos or delivity.		
 Average - Adequate size, multiple areas provided, 									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

	- Media Resources - Continued					5	N/A			
17) h	does the Library/Media Center support collaborative work roups (10-25)?				4			Comments	1.00	4.00
1	Very unsatisfactory - No gathering areas					l .	_		l .	
2	· · · · · · · · · · · · · · · · · · ·									
3	Average - Adequate size, one common space, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with									
	seating, good condition									
5	Very Satisfactory - Generous size, multiple commons									
	spaces with seating, excellent condition									
N/A	Does not apply					,				
2.6 How well d	does the Library/Media Center support technology?			3				Comments	1.00	3.00
1	Very unsatisfactory - No vis comm tools					•				
2	Unsatisfactory - Outdated, poorly functioning, or									
	insufficient									
3	Good - Mix of old and new whiteboards/projectors/etc.									
4	Satisfactory - Projectors, marker boards, smart boards in									
	most spaces - good condition									
5	Very Satisfactory - Projectors, marker boards, smart									
	boards in most spaces - new condition									
3 - Technolog	у	1	2	3	4	5	N/A	\ 	20.00	70%
13.1 How well e	equipped are the facilities with instructional technology?				4			Comments		
									1.00	4.00
1	Very unsatisfactory - Limited to no technology present in instructional spaces							Projection and mobile TV displays in most spaces.	1.00	4.00
1 2									1.00	4.00
	instructional spaces								1.00	4.00
2	instructional spaces Unsatisfactory - One type of technology present								1.00	4.00
2	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards,								1.00	4.00
2 3 4	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition.								1.00	4.00
2 3	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart								1.00	4.00
2 3 4 5	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition								1.00	4.00
2 3 4 5 N/A	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply								1.00	4.00
2 3 4 5 N/A Is there an	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition		2							
2 3 4 5 N/A 13.2 Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning		2					Projection and mobile TV displays in most spaces.	1.00	2.00
2 3 4 5 N/A Is there an	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A 13.2 Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A 13.2 Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A 13.2 Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces? 1 2 3	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces?	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces? 1 2 3	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces? 1 2 3	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital		2					Projection and mobile TV displays in most spaces.		
2 3 4 5 N/A [3.2] Is there an spaces? 1 2 3 4	instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (33 per wall)		2					Projection and mobile TV displays in most spaces.		
	3 4 5 N/A 2.6 How well c 1 2 3 4 5 N/A 5 N/A 3 - Technolog	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition	seating, poor condition 3	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 3 - Technology 1 2	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 3 - Technology 1 2 3	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 3 - Technology	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 3 - Technology	seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 1 Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Good - Mix of old and new whiteboards/projectors/etc. Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 1 2 3 4 5 N/A Technology	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 3 Comments 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition N/A Does not apply 3 Technology 1 2 3 4 5 N/A	seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces with seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 2.6 How well does the Library/Media Center support technology? 3 Comments 1 Very unsatisfactory - No vis comm tools 2 Unsatisfactory - No vis comm tools 2 Unsatisfactory - Outdated, poorly functioning, or insufficient 3 Good - Mix of old and new whiteboards/projectors/etc. 4 Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition 5 Very Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition N/A Does not apply 3 - Technology 1 2 3 4 5 N/A 20.00

O2/11/2022 ¹⁰

13 - Technolog	gy (cont.)	1	2	3	3 4	į	5	N/A			
13.3 Are there	adequate charging locations for devices?				4				Comments	1.00	4.00
1	Very unsatisfactory - No centralized charging location										
2	Unsatisfactory - Centralized charging location, but										
	inadequate in size for number of devices										
3	Average - Charging cart or tower but not adequately										
	sized for number of devices										
4	Satisfactory - Charging cart or tower not centralized										
5	Very Satisfactory - Charging cart or tower located										
	centralized location. Excellent condition										
N/A	Does not apply	ı					1	1			
13.4 Is there ac	dequate AV for presentations spaces – cafeteria and gym?				4				Comments	1.00	4.00
1	Very unsatisfactory - AV not present in one or more								No projection in gym but has a mobile TV display.		
	space										
2	Unsatisfactory - AV undersized for room, poor condition										
3	Average - Adequately sized / poor condition OR AV										
	undersized / adequate condition										
4	Satisfactory - Good size, good condition										
5	Very Satisfactory - Generous sized, excellent condition										
N/A	Does not apply	,									
13.5 Is there di	gital media signage at the reception area?	1							Comments	0.00	0.00
1	Very unsatisfactory - No digital media present in								Currently use a mobile TV display; no permanent TV	installed.	
	reception area										
2	Unsatisfactory - Undersized, poor condition										
3	Average - Adequately sized / poor condition OR										
	undersized / adequate condition										
4	Satisfactory - Media signage present, good sized, good										
-	condition										
5	Very Satisfactory - Generously sized, excellent condition										
N/A	Does not apply										

14 - Adm	inistro	ation Spaces	1	2	3	4	5	N/A	i.	20.00	55%
1 1/1 1	nere a re :ors?	eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint	-	•			•				
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
14.2 Doe	es the ac	dministration area feel welcoming?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No welcome space									
	2	Unsatisfactory - Too small, poor lighting and									
		transparency, limited informal seating, poor condition									
	3	Average - Adequate size and layout, needs updates or									
		renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
	_	transparency, informal seating provided									
	5	Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided,									
		excellent condition									
	N/A	Does not apply									
Fort		paces that require it, does the administration area have	1	I	Π	I					
1 121 :3		acoustic privacy?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No acoustic separations	ļ		!				Principal noted that conversations can be heard betw		
	2	Unsatisfactory - Acoustic separations do not perform									
		well									
	3	Average - Some acoustic separations function okay, but									
		portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
	N/A	Does not apply			_						
14.4 Are	confere	ence rooms easily accessed for public / parent use?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Not accessible for public/parent				•	-				
		use									
	2	Unsatisfactory - Limited access, no transparency, poor									
		condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Good accessibility, good transparency,									
	_	good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent									
	N/A	transparency, generous size, excellent condition Does not apply									
	IN/A	DOES HOL GDDIV									