



Educational Suitability Summary Report

Graham Elementary School

Date: 01/07/2021

Score 57% Average

Graham Elementary School serves an enrollment of approximately 490 students in northeast Austin. It was originally built in 1972 and consists of approximately 70,000 square feet on 10 acres. Graham is nationally recognized as a Blue Ribbon School and part of the Northeast Austin Communities for Educational Readiness. It is part of the Northeast Early College High School feeder pattern.

The campus has added two annex buildings, with the latest addition completed in 2008. These buildings are connected to the main building by covered walkways and house the upper grades and special education studios. Communal spaces are all near the main entrance, and they have their own exterior entrances for after-hours use. Outdoor play spaces are near the appropriate grade levels, but neither playscape is covered. There are a couple picnic tables provided but no dedicated outdoor learning space. The school lacks outdoor learning gardens and rain gardens.

Interview Overview

This interview was held virtually with Principal Ercilia Paredes and Assistant Principal Samantha Phillips. In terms of campus and community importance, they mentioned a historic plaque on the front of the building and the large educational murals in the main corridor as items that must remain. Graham has several portables and programs that are not in suitable spaces, but their focus was on the special education and PPCD rooms that need renovations to be made accessible for students. These spaces need changing tables and support spaces to help them function properly. Teachers have to travel to an accessible restroom to assist students. They also discussed classes and spaces that are in the portables, including pre-K, SBS and counselor offices. There are a number of dedicated spaces that the campus needs, including a maker space, science lab, PTA room and custodial staff breakroom.

Spaces on their wish list include an onsite daycare center for the staff and outdoor learning studios. The principal would like to create a covered area with furniture to establish an outdoor learning studio.

There were numerous comments regarding safety. The parent drop-off outside the gym entrance needs a covered canopy. They said this area is unsafe for students to wait in the sun or inclement weather.

Graham Elementary School

Assessment Findings

The Educational Suitability Assessment of Graham Elementary School earned a 57% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Visual and Performing Arts

Score is very unsatisfactory.

Music room is near the performance stage, but the room is undersized and lacks storage. Visual arts room is in a typical studio room, is undersized and does not allow for proper support space.

Unsatisfactory Categories (36-50%):

Furniture, Fixtures, Equipment

Score is unsatisfactory.

The school has mostly older furniture. Some rooms have desks with attached chairs, and the furniture is in average condition. There is not a variety of furniture types throughout the school, and larger tables in various studios are difficult for students to move.

Academics and Learning

Score is unsatisfactory.

Studios in the original building are very undersized while the newer buildings are closer to Ed Specs, but still undersized. Storage availability varies across buildings. Some studios have storage closets; others have more limited casework. Only one building has studios set up in a true learning neighborhood, though it does not have a PLC and collaboration space appears underutilized.

Food Services

Score is unsatisfactory.

Dining commons is a good size but only offers one seating option and no connection to outdoor seating. The kitchen is small and lacks a proper kitchen office.

Media Resources

Score is unsatisfactory.

Media center is across from the main office but is undersized and does not provide spaces for different group sizes. There are no private study rooms, and there is a limited variety of furniture available. There are two projectors and two mobile displays.

Technology

Score is unsatisfactory.

Some studios do not have projectors, but all have mobile displays. Studios have a whiteboard but limited tackable surface. A few spaces have charging carts, but no charging towers were seen. The reception area has two TVs.

Average Categories (51-65%):

Graham Elementary School

Exterior

Score is average.

The campus has two drop-off locations, separating bus and parent drop-offs. The building is easily identifiable but interior wayfinding is difficult. Dumpsters are adjacent to the kitchen but are not on an accessible route.

Outdoor Learning and Activity

Score is average.

Outdoor learning spaces are lacking, and no shade is provided. There are a couple scattered picnic tables, but no dedicated outdoor studio. Playscapes do not have shade, but the basketball court does. There are no learning gardens or support spaces, animal husbandry or a learning pond.

General Building

Score is average.

Community use areas are arranged so the school can allow after-hours functions. There is no dedicated community meeting room. The exterior appearance of the school is aged, and colors have faded over time. The exterior building sign is rusted and old. Interior appearance is dated, but large wall graphics contribute to overall school pride.

Security

Score is average.



Administration Spaces

Score is average.

Reception area is small and does not have informal seating. Offices are separated for adequate acoustic privacy. The conference room is easy to navigate to from the reception area and is a good size.

Satisfactory Categories (66-80%):

Controllability of Systems

Score is satisfactory.

Studios have individual thermostat controls, but controls are dated. Lighting controls vary from building to building. The 1993 building has single switches, while the original building and 2008 annex have zones and dual switches.

PE and Wellness

Score is satisfactory. Gym has updated floor but lacks a projector screen. Athletic storage is satisfactory.

Very Satisfactory Categories (81-100%):

Educational Suitability Summary Report

Graham Elementary School

Environmental Quality

Score is very satisfactory.

All studios have access to natural light and outside views. Artificial lighting varies across different studios, and corridors are dark. Overall acoustics are satisfactory in the studios. Some sound from the corridors could be heard, but it was not disruptive to learning.

Educational Suitability Summary Report

Graham Elementary School

Supporting Photographs



Bus drop-off at main entry has a proper overhang for waiting students. School exterior is in good condition, but appearance is aged by weather-faded colors.



Playscapes are in good condition but not shaded. There are a few picnic tables, but they are not dedicated outdoor learning studios.

Educational Suitability Summary Report

Graham Elementary School

Supporting Photographs



Educational Suitability Summary Report

Graham Elementary School

Supporting Photographs



Media center has a mix of old and new furniture. Tables are easily reconfigurable, but the space is too small for multiple groups or quiet study.



Gym has updated flooring and access to natural light. No projector screen, but there is a portable screen and a projector on a cart.


Educational Suitability Summary Report

Graham Elementary School

Supporting Photographs



Cafeteria lacks natural lighting and access to outdoor seating. Dining commons and stage size is adequate, but the stage lacks storage. (Due to COVID restrictions, the cafeteria is not in its typical arrangement in this photo.)



Original building corridors are small and lack natural daylight. Transparency between studios and corridors is inadequate.

Educational Suitability Summary Report

Graham Elementary School

Supporting Photographs



Studios in the newer annex buildings are larger than original building, and all have access to natural light. There is limited storage available.



The newest annex building has a central collaboration space for the surrounding studios. This space also functions as the main circulation for the building. There is limited transparency into the studios.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:	
Graham Elementary School	Emilie Ogburn and Patrick Reinhard	1.7.2021	

1	- Ex	terior		1	2	3	4	5	N/	/Α	8.75	54%
	1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen							Buses use front of building for drop-off while parents	use visitor par	king lot
		2	at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated							for drop-off. Neither has a canopy, but are near pote (gym/cafeteria and library).	ntial holding a	ireas
		3	Average - Buses, cars, and pedestrians are separate but stack space is small							Principal's note: A canopy is needed. It is too hot to sto weather for dismissal.	and outside in	hot
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria							weather for dismissal.		
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply									
	1.2		ing easily identified with appropriate signage and wayfinding?			3				Comments	0.25	0.75
		1	Very unsatisfactory - Campus has no signage /							Exterior signage is good but interior wayfinding is diff	icult.	
		2	wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not good condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									

02/11/2022 ²

1 - Exterior (co	ont.)	1	2	3	4	5	N/A	N	1	
1.3 Is the dun	npster accessible for trash / compost disposal?		2					Comments	0.50	1.00
1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are shaped / positioned so people of all heights can access it.							Curb with no ramp present.		
N/A	Does not apply earning and Activity	1	2	3	4	5	N/A		15.00	60%
	por studios and support spaces appropriately configured per	1	2	3	4	5	IN/A	Comments	1.00	1.00
1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area				1			A couple scattered picnic tables but not a dedicated		
	Does not apply e playgrounds (elementary only) and support spaces d per the ed spec?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply							No shade structures on playscapes but larger canop basketball court.	y over outdoor	

02/11/2022 ³

2 - Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	N Contraction of the second seco	
	s and support spaces appropriately configured per the ed uation on infrastructure not condition of plants)	1						Comments 0.00	0.00
1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source				•			Monitoring answer, does not affect score for Outdoor Learning and Activity.	1
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
N/A	Does not apply						1	1	
2.4 Are the rain ed spec?	a gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.00
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor Learning and	1
2	Unsatisfactory - Too small, poor condition, not							Activity.	
	functioning, disconnected								
3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well								
4	Satisfactory - Good size, good condition, functions properly								
5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
N/A	Does not apply								
	hool have animal husbandry? (optional)	1						Comments 0.00	0.00
1	No								
5	Yes								
	hool have nature loop trails? (optional)	1						Comments 0.00	0.00
1 5	No								
	Yes hool have a learning pond? (optional)	1				1		Comments 0.00	0.00
2.7 Does the sc	No	1						Comments 0.00	0.00
5	Yes								
	hool have a grass play field and walking trail?					5		Comments 1.00	5.00
							·		
1	No								

	eral Bui		1	2	3	4	5	N/A		11.25	62
31		circulation routes wide enough to safely and effectively ate student movement?				4			Comments	0.50	2.0
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"						1	6-8' wide in studio corridors, 10+ in largest main circu		
	0	wide									
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply									
20		nity use areas arranged so that the school can allow night ithout full school access?					5		Comments	0.75	3.
	1	Very unsatisfactory - Cafeteria, gym, and library cannot							Library is small but has a separate door that could se	erve as a secur	e entr
		be accessed after hours							point.		
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
		Gym and Library) can be accessed from parking and									
		secured after hours									
	3	Average - Only two of the public spaces can be accessed									
		from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
22		ommunity room that is a dedicated meeting space outside	1						Comments		
of s	school fu		<u> </u>							0.75	0.
	1	Very unsatisfactory - No dedicated community room							Used to have a parent center but no longer have the	program.	
	2	Unsatisfactory - Community room but within school									
	•	function, no access after school hours									
	3	Average - Community room, moderate size, but need									
	4	some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
	0	condition, functions appropriately outside of school									
		function									
	N/A	Does not apply									
2 /	-	neral appearance of the school convey pride for the		2					Comments		
5.4 stud	idents an	d community?		~					Comments	0.25	0.
	1	Very unsatisfactory - General appearance is poor									
	2	Unsatisfactory - General appearance is aged but ok									
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in									
		campus and student works									
	5	Very Satisfactory - General appearance shows pride in									
		campus and student works and is welcoming to the									
		community									
	N/A	Does not apply									

4 - Security		1 2	3	4	5	N/A		16.25	(
4.] Does the facility have key card	d access at all major entries?						Comments	0.25	
3Average - 1/2 of4Satisfactory - 3/4	1/4 of major entries)	
4.2 How adequate is site lighting	and security for the campus overall?						Comments	1.00	í
2 Unsatisfactory - parking lot lighti 3 Average - Lightir lot, but poor con 4 Satisfactory - Lig parking lots, goo perimeter is well 5 Very satisfactory	bry - No exterior lighting, no secure Lighting is limited to front entry only, ng poor, security is minimal og at all night-use entries and parking dition. Security is moderate hting at all night-use entries and od condition, signage less visible, secured but needs updates - Signage, parking lots, and entries are d easy to use, perimeter is very secure								
N/A Does not apply	ne school entry and configured with a		-	1				Γ	
4.3 secure vestibule to the main c							Comments	1.00	(
far from main en unsupervised 2 Unsatisfactory - somewhat far fro visitors 3 Average - Office no secure vestibu 4 Satisfactory - Of vestibule, but ne 5 Very satisfactory vestibule and all N/A Does not apply	fice is well-located with a secure eds updates - Office well-located with secure appropriate security features							·	
4.4 Is there enough interior transp learners and their activities w	parency for faculty to passively supervise ho are not in studios?	2					Comments	1.00	2.0
	bry - No transparency of walls Limited transparency in certain locations						Half glass doors or lites in doors; some spaces have v allow narrow visibility to corridors.		
inadequate or m 4 Satisfactory - Ad school 5 Very satisfactory	transparency in certain locations but issing in other locations of school equate transparency throughout the - Excellent transparency throughout the								
school N/A Does not apply									

02/11/2022 *

5 - Environme	ntal Quality	1	2	3	4	5	N/A	A	25.00	84%
5.1 How are a	acoustics in studios in general?				4			Comments	1.00	4.0
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply					1	1	Sound from corridors but not disruptive.		
5.2 Is the stud	io artificial lighting adequate quality?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply							Varied throughout; corridors are very dark.		
5.3 Is there ac	ccess to natural light in studios?					5		Comments	1.00	5.0
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply					1		All studios have windows but interior corridors are po		
-	ccess to outside views from learning spaces?					5		Comments	1.00	5.0
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply		<u> </u>		I	<u> </u>	<u> </u>		1.00	

5 - Ei	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	A		
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Evidence of both pests and odors							Some ants in library and food odors from cafeteria.		
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school									
		cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in									
		excellent condition									
	N/A	Does not apply									
6 - C	ontrollabi	lity of Systems	1	2	3	4	5	N/A		12.50	68%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No									
	5	Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No, windows are covered with									
		boards/paper									
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply	1	1	1	1	1	1			
6.3	What is the	quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Single switch only per room							1993 building has single switch; original building and	2008 annex h	ave
	2	Unsatisfactory - Alternating rows switch off							zones and dual switches.		
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - Furniture, F	Fixtures & Equipment	1	2	3	4	5	N/A	٦	8.75	49
7.1 What is the	e current condition of the furniture?			3				Comments	0.75	2.2
1 2	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size							Mostly older furniture; some rooms have desks with attache	d chairs.	
3	Average - Scratched/dented/marked									
4	Satisfactory - Not new, but sturdy and clean									
5	Very satisfactory - New									
N/A	Does not apply									
/ ')	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?	1						Comments	1.00	1.0
1	Very Unsatisfactory - Same furniture used in all spaces							Same types of tables, desks and chairs being used througho	out.	
2	Unsatisfactory - Furniture variety in one multi-use space									
3	Average - Furniture variety in more than one multi-use space									
4	Satisfactory - All multi-use spaces have greater than one type of furniture									
5	Very satisfactory - All multi-use spaces have greater									
-	than two types of furniture									
N/A	Does not apply									
/ 3	loes furniture accommodate rapid reconfiguration of a			3				Comments		
space?				0					1.00	3.0
1	Very Unsatisfactory - Furniture is fixed or very heavy							Larger tables are harder to move, but plenty of desks for eas	sy	
2	Unsatisfactory - Furniture does not allow desks to be							reconfiguring.		
3	configured as individuals, small groups, or large groups									
3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
4	Satisfactory - Furniture is flexible for multiple									
	configurations of space									
5	Very satisfactory - Furniture is flexible for multiple									
	configurations of space, easy to move and stack									
N/A	Does not apply		1		T			1		
7.4 Is the furni	ture ergonomic and size appropriate for grade level?			3				Comments	1.00	3.0
1	Very unsatisfactory - Desk with attached chair							A few spaces have desks with attached chairs.		
0	combinations too small for grade level									
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and									
4	desks with fixed seats Very satisfactory - Tables with loose chairs									
•										
5	Very satisfactory - Tables with loose chairs that allow students to be active									
N/A	Students to be active Does not apply									

02/11/2022 °

Waste		1	2	3	4	5	N/A	5.00	40
	corridors have blue recycle bins with bilingual I/or image sorting instructions?		2					Comments 0.50	1.0
bir on 2 Ur inf 3 Av lar Th 4 Sa lar loc 5 Ve vis ac an ac	ry unsatisfactory - There are no recycling and landfill ns and signage are sparse or infrequent, OR there are ly landfill bins with no recycling bins. Isatisfactory - Bins and signage are sparse or frequent and/or lack clear signage. The rage - 50% of corridors and studios have both a andfill bin and a recycle bin in an accessible location. The containers have clear signage. This factory - 75% of studios and corridors have a visible andfill and recycle collection containers in an accessible cation. The containers have clear signage. The style and format is consistent and uniform to coss campus. The containers have clear signage.							A score for this category is being recorded, but this category is r calculated in the overall ESA average.	ot
of each: green a	ria (or wherever meals are served) have at least one compost bin, blue recycle bin, and landfill bin? Are the early with bilingual and/or image sorting?		2					Comments 0.50	1.
ard so 2 Un pro ne 3 Av thi pro	rry unsatisfactory- There may be landfill bins, but there e no compost and/or recycle bins. There is not clear rting signage. Isatisfactory- Recycle, landfill, and compost bins are esent, but the bins are scattered and no co-located xt to one another. Signage is absent or inconsistent. There is at least one waste station with all ree bins (recycle, compost, landfill) located with close oximity to one another. The signage is visible and nsistent.								
4 Sa de 5 Ve	tisfactory- There are several waste stations as scribed above ry Satisfactory - There are several waste stations as								
do	scribed above, and additional signage in the								

02/11/2022



Perkins&Will


Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Graham Elementary School	Emilie Ogburn and Patrick Reinhard	1.7.2021

8 - Academics	& Learning	1	2	3	4	5	N/A	<u> </u>	70.00	39%
8.1 Are studios	s appropriately configured per the ed spec?			3				Comments	1.00	3.00
1 2 3 4 5	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces Does not apply							New buildings have larger studios but disconnection because of how spread out they are. Original buildin undersized.	between studio	
80	and Kinder have appropriate support spaces such as and storage per the ed spec?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition Does not apply							Restrooms attached with vestibules to pairs of studio, dedicated storage closets.	not ADA; no	

8 - A	cademics &	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.3	Do studios ł ed spec?	nave appropriate support spaces such as storage per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Some studios have storage closets and others have limite	d casewor	٠k.
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open	1						Comments		
0.4	collaboratio	on space?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
	3	neighborhood, poor acoustic privacy Average - Adequate size, adequate condition, needs									
	5	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition									
		and flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
_	N/A	Does not apply				1	1				
8.5		studios large enough to support project-based learning e teaching modalities?		2					Comments	1.0.0	
						I				1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning							In smaller studios, areas for multiple groups are limited.		
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or									
	-	updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									



3 - Academics & Learning (cont.)	1	2	2	3	4	5	N/A	<u> </u>		
 Are Maker Spaces and support spaces appropriately configu the ed spec? 	ured per							Comments	1.00	1.00
1 Very unsatisfactory - No dedicated maker space	205						1		1.00	
2 Unsatisfactory - Too small, poor condition, disco										
from learning spaces, no flexibility	onnoccou									
 Average - Adequate size, adequate condition, r 	needs									
some renovations or updates to function well										
4 Satisfactory - Good size, good condition, conne	ected to									
learning spaces										
5 Very Satisfactory - Generous size, excellent cond	dition,									
connected to learning spaces										
N/A Does not apply										
8.7 Is there a Professional Learning Center in the learning neight	borhood?							Comments	1.00	1.00
 Very unsatisfactory - No dedicated space for 	•									
Professional Learning Center										
2 Unsatisfactory - Too small, poor condition, disco	onnected									
3 Average - Adequate size, adequate condition, r	needs									
some renovations or updates to function well										
4 Satisfactory - Good size, good condition, conne	ected									
5 Very Satisfactory - Generous size, excellent cond	dition,									
connected										
N/A Does not apply							1			
8.8 Is there a dedicated science room and support space?						5		Comments	0.00	0.00
1 No	·							Monitoring answer, but doesn't affect overall score.		
5 Yes										
Are there adequate places to display the evidence and artif	acts of			~						
8.9 learning (both 2D and 3D)?				3				Comments	1.00	3.00
1 Very unsatisfactory - No dedicated space					1			Limited 3D storage; 1993 building has no decorated t	ackboard disp	olay, so
2 Unsatisfactory - Too small, non-dedicated, pool	r							teachers have stapled into laminate wall surface.		
condition										
3 Average - Adequate size, adequate condition, r	needs									
updates or renovations to function well										
4 Satisfactory - Good size, good condition										
5 Very Satisfactory - Generous size, excellent cond	dition									

	& Learning (cont.)	1	2	3	4	5	N/A	N		
	uilding provide adequate opportunities for		2					Comments		
students/te	achers to collaborate in varying group sizes?		2					Comments	1.00	2.0
1	Very unsatisfactory - No space to support collaboration							Library, cafeteria or gym are only options for other g	athering sizes	beside
	in various sizes.							what can fit in a studio. Library would be limited due	to small size.	
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple									
	options to support a variety of group sizes									
5	Very Satisfactory - Generous size, excellent condition,									
	multiple options to support a variety of group sizes									
N/A	Does not apply	1			1		1			
8.11 Does the bu	uilding provide opportunities for informal interaction?		2					Comments		
									1.00	2.0
1	Very unsatisfactory - No space							Narrow studio corridors; larger primary circulation co	ould be better	but no
2	Unsatisfactory - Too small, poor condition, layout and							furniture to support this.		
2	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
-	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
· ·	layout and furnishings support informal interactions									
N/A	Does not apply									
Does the lea	arning neighborhood / building provide adequate									
0.12 opportuniti	es for students to work independently?	1						Comments	1.00	1.0
1	Very unsatisfactory - No breakout rooms/small study		<u>.</u>	i	I	i				
	spaces									
2	Unsatisfactory - Too small, poor condition, no acoustic									
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy,									
	variety of independent work space options, connected to									
	learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space									
	options, connected to learning neighborhood									
	1 · · · · · · · · · · · · · · · · · · ·									


8 - A	cademics	& Learning (cont.)							
8.13	Are Special spec?	Education spaces appropriately configured per the ed		2			Comments	1.00	2.00
	1 2	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected					Located in standard studios.		
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply		1	1	1	1	T	
8.14		Education support spaces, such as storage, space for /er, appropriately configured per the ed spec?		2			Comments	1.00	2.00
	1	Very unsatisfactory - None provided					Changing tables in library and annex with PPCD; wa	sher but have r	no
	2	Unsatisfactory - Too small, disconnected, poor condition					connection and used for custodial purposes; special	education prog	grams
	3	Neutral - Adequate size, average condition, needs					are in standard classroom spaces.		
		updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent							
	N/A	condition							
	-	Does not apply			 	1	1	T	
8.15		ble restrooms and changing rooms readily available to the acation spaces?	1				Comments	1.00	1.00
	1	No							
	5	Yes							

02/11/2022 *

9 - Visual and	Performing Arts	1	2	3	4	5	N/A	15.00	33%
9.1 Are music per the ed	spaces and the cafeteria stage appropriately configured spec?		2					Comments 1.00	2.0
1	Very unsatisfactory - Too small, missing program spaces							Music room is not specialized, undersized; 2 storage closets but not	
2	Unsatisfactory - Too small, poor condition							adequate.	
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.								
4	Satisfactory - Good size, good condition								
5	Very Satisfactory - Generous size, excellent condition								
N/A	Does not apply								
9.2 Are music per the ed	and performance storage spaces appropriately configured spec?		2					Comments 1.00	2.0
1	Very unsatisfactory - None provided								
2	Unsatisfactory - Too small, disconnected, poor condition								
3	Neutral - Adequate size, average condition, needs								
	updates or renovations to function well								
4	Satisfactory - Good size, connected, good condition								
5	Very Satisfactory - Generous size, connected, excellent condition								
N/A	Does not apply								
9.3 Are Visual ed spec?	Arts spaces and storage appropriately configured per the	1						Comments 1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces							Not a specialized room. In a standard studio with only one sink.	
2	Unsatisfactory - Too small, poor condition								
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well								
4	Satisfactory - Good size, good condition								
5	Very Satisfactory - Generous size, excellent condition								
N/A	Does not apply								

0 - PE and We	ellness	1	2	3	4	5	N/A	N	10.00	80
01	ampus meet the ed spec standard for physical education				4			Comments		
program sp								connicita	1.00	4.0
1	Very unsatisfactory - Too small, missing program spaces							Updated flooring, no projector screen.		
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply		1		1	r	1	Τ	1	
0 9 · · ·	ysical education storage spaces appropriately configured				4			Comments	1.00	
o.2 per the ed	•								1.00	4.0
1	Very unsatisfactory - None provided							Large storage, PE office located across the hall.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
4	updates or renovations to function well									
4 5	Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent									
5	condition									
N/A	Does not apply							L		
I - Food Servi		1	2	3	4	5	N/A		10.00	50
		-				-	, .			
II.I Is the Dinin	ng Commons appropriately configured per the ed spec?			3				Comments	1.00	3.0
1	Very unsatisfactory - Too small, missing program spaces							Good size; only one seating option; no connection to	outdoors.	
2	Unsatisfactory - Too small, poor condition, only one									
	option for eating space provided, inadequate circulation									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation,									
	multiple options for eating space (ex: connection to									
-	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition									
	and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A	Does not apply									
Are the For	od Services support spaces appropriately configured per					1				
11.2 the ed spec			2					Comments	1.00	2.0
1	Very unsatisfactory - None provided		I	<u>.</u>	I	i	I	Very small kitchen and only one food line.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
3	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
	very satisfactory - Generous size, connected, excellent									
5	Very Satisfactory - Generous size, connected, excellent condition									

12 - Media Resources	1	2	3	4	5	N/A	N	30.00	479
 Is the Library/Media Center easily accessible for the occupants and visitors to the school? 			3				Comments	1.00	3.0
 Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition 							Located across from main office, undersized.		
N/A Does not apply 12.2 How well does the Library/Media Center support quiet study?	1						Comments	1.00	1.0
 Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy N/A Does not apply 							Not much space to spread out for private study; no s	1	
2.3 How well does the Library/Media Center support social interaction?		2					Comments	1.00	2.0
 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 							Limited variety in furniture.		
How well does the Library/Media Center support collaborative work in small groups (4-8 students)?		2					Comments	1.00	2.0
 Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition N/A Does not apply 		· · · · · ·		·		<u>.</u>	Not enough room for multiple small groups to work a	at the same tim	ie.



12.5 How well does the Library/Media Center support collaborative were in larger groups (10-25)? 1 Very unsatisfactory - No gathering areas 2 Unsatisfactory - Too small, one common space, limite seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces wit seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 12.6 How well does the Library/Media Center support technology?	ed ;		3				Comments	1.00	3.00
 2 Unsatisfactory - Too small, one common space, limits seating, poor condition 3 Average - Adequate size, one common space, needs updates or renovations to function well 4 Satisfactory - Good size, multiple common spaces wi seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 	ith								
 seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces wi seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 	ith								
 Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces wi seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 	ith								
 updates or renovations to function well Satisfactory - Good size, multiple common spaces wi seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 	ith								
 Satisfactory - Good size, multiple common spaces wi seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply 									
seating, good condition 5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply									
5 Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition N/A Does not apply									
spaces with seating, excellent condition N/A Does not apply									
N/A Does not apply									
2.6 How well does the Library/Media Center support technology?									
			3				Comments	1.00	3.0
1 Very unsatisfactory - No vis comm tools		1	<u> </u>	-		I	2 projectors (one at group area, one at Kiva), 2 edu-dis		
2 Unsatisfactory - Outdated, poorly functioning, or									
insufficient									
3 Good - Mix of old and new whiteboards/projectors/	etc.								
4 Satisfactory - Projectors, marker boards, smart board	ds in								
most spaces - good condition									
5 Very Satisfactory - Projectors, marker boards, smart									
boards in most spaces - new condition									
N/A Does not apply		•	0	4	-	N1/A		00.00	4.5
- Technology	I	2	3	4	5	N/A		20.00	45
3.1 How well equipped are the facilities with instructional technology		2					Comments	1.00	2.0
1 Very unsatisfactory - Limited to no technology preser	nt in						Some studios have projection. All have edu-displays; o	ne wall-mou	nted
instructional spaces							whiteboard and limited tackboards.		
2 Unsatisfactory - One type of technology present	la.								
3 Average - Multiple types of technology, smart board poor condition, limited to only certain areas of school									
4 Satisfactory - Multiple types of technology, smart	Л								
boards, good condition.									
5 Very Satisfactory - Multiple types of technology, sma	art								
boards, excellent condition									
N/A Does not apply									
Is there an adequate number of power and data outlets in learnir	ng	2					Comments		
spaces?		2					Comments	1.00	2.0
 Very unsatisfactory - Outlet configuration does not 							Original building has added surface-mounted boxes ir	n some locati	ions,
support digital devices throughout school (1 per wall)									
2 Unsatisfactory - Outlet configuration support digital									
devices only in certain areas of school (2 per wall)	~~								
3 Average - Outlet configuration support digital device but not enough capacity throughout school (3 per we									
	uii)								
4 Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity									
throughout school (>3 per wall)									
5 Very Satisfactory - Excellent outlet configuration to									
support digital devices throughout school (>3 per wa	III)								
N/A Does not apply	,								

3 - Technolog	y (cont.)	1	2	3	4	5	Ν	J/A
13.3 Are there a	dequate charging locations for devices?		2					Comments 1.00 2.0
1	Very unsatisfactory - No centralized charging location							A few spaces have charging carts; no charging towers observed.
2	Unsatisfactory - Centralized charging location, but inadequate in size for number of devices							
3	Average - Charging cart or tower but not adequately sized for number of devices							
4	Satisfactory - Charging cart or tower not centralized							
5	Very Satisfactory - Charging cart or tower located centralized location. Excellent condition							
N/A	Does not apply							
13.4 Is there add	equate AV for presentations spaces – cafeteria and gym?			3				Comments 1.00 3.0
1	Very unsatisfactory - AV not present in one or more							Gym has no screen but mobile projector; has edu-display for virtual
	space							learning. Cafeteria has screen but no surface-mounted projector.
2	Unsatisfactory - AV undersized for room, poor condition							
3	Average - Adequately sized / poor condition OR AV undersized / adequate condition							
4	Satisfactory - Good size, good condition							
5	Very Satisfactory - Generous sized, excellent condition							
N/A	Does not apply							
13.5 Is there dig	ital media signage at the reception area?			3				Comments 0.00 0.0
1	Very unsatisfactory - No digital media present in reception area							2 small TVs
2	Unsatisfactory - Undersized, poor condition							
3	Average - Adequately sized / poor condition OR							
	undersized / adequate condition							
4	Satisfactory - Media signage present, good sized, good condition							
5	Very Satisfactory - Generously sized, excellent condition							
N/A	Does not apply							

02/11/2022 "

4 - Administ	ration Spaces	1	2	3	4	5	N/A		20.00	65
14.1 Is there a visitors?	reception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply				1	r	1			
14.2 Does the	administration area feel welcoming?		2					Comments	1.00	2.0
1	Very unsatisfactory - No welcome space					•	•	Very small waiting area for visitors. Good visibility to	front entry. No	
2	Unsatisfactory - Too small, poor lighting and							furniture.		
	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
4	renovations to feel welcoming Satisfactory - Good size and layout, good lighting and									
-	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
	excellent condition									
N/A	Does not apply				1	r	1	I		
14.3	e spaces that require it, does the administration area have e acoustic privacy?			3				Comments	1.00	3.0
1	Very unsatisfactory - No acoustic separations				I		1	Small and has few offices that are spaced far enoug		
2	Unsatisfactory - Acoustic separations do not perform							control.	,	
3	 Average - Some acoustic separations function okay, but									
	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply				1	1	1	Ι		
4.4 Are confe	erence rooms easily accessed for public / parent use?				4			Comments	1.00	4.0
1	Very unsatisfactory - Not accessible for public/parent							Good size; located in admin area and easy to find.		
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find							Principal's note: Larger conference room is prefered	to seat up to 15	peop
3	Average - Adequate accessibility, needs updates or renovations to function well							and updated furniture is a must.		
4	Satisfactory - Good accessibility, good transparency,									
-	good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent									
	transparency, generous size, excellent condition									
N/A	Does not apply									