



Hart Elementary School

Date: 01/07/2021

Score 66% Average

Hart Elementary School serves an enrollment of approximately 570 students in northeast Austin. It was originally built in 1998, and an addition was added in 2010. The campus is composed of multiple buildings totaling approximately 81,000 square feet. The school sits on a 13-acre site. The school prides itself on being a community of learners dedicating to helping students develop their knowledge while learning how to contribute to their community. They are a dual-language campus and a part of the northeast Austin Communities for Education Readiness (NACER), which seeks to prepare students for college and beyond.

Overall, the campus adequately supports the school's needs and is aligned with the district's standards as described in the Education Specifications. All of the large common spaces on campus, including the gym, cafeteria and library, are well-connected and centrally located, providing easy access for students and visitors. Bus and vehicular traffic are separate but lack adequate canopies for shade and protection from the elements.

All studio spaces have windows with access to daylight and views of nature, as well as appropriate technology for teaching needs. Improvements could be made to outdoor teaching spaces throughout the campus to provide them with better functionality and more well-connected distribution of space for all grade levels.

Interview Overview

The interview participants consisted of Principal Sonia Tosh, Assistant Principal Ricardo Gonzalez-Gurza, librarian Jennifer Byer, counselor Danielle Trejo and specialist Kristen Troegle. They would like to keep the dedicated garden and rock garden, as well as the goats they have on campus. The track is an important feature that they want the campus and community to continue to benefit from but would like for it to be improved. The after-school enrichment programs are special to the families at the school; however, they would like a dedicated space for these programs. Extend-A-Care is another program that needs a dedicated space. All of the school's special education programs are in portables and are disconnected from the rest of the campus. Getting special education programs into better equipped spaces is a high priority. Communities in Schools is also in a portable; allowing that program to be better connected to the main building is important as well.

There is a need for more covered walkways, specifically from the portables to the main building. The campus could also use more meeting spaces for parents, faculty and the community. Parking for visitors is in high demand. Specialized STEM spaces such as maker labs and science labs are also on their wish list.

The campus wants to continue to expand the outdoor learning areas and equip them with the proper

02/11/2022 Perkins&Will

Hart Elementary School

furniture and technology for teaching. Their current buildings are aged and have not been updated adequately over the years. Having better access to water fountains and restrooms is needed for outdoor learning and play areas. Updated power access in studios and strong internet access across the campus is important. Above all, they would like all of their programs and students in one building, so they can increase collaboration, connection and community.

Assessment Findings

The Educational Suitability Assessment of Hart Elementary School earned a 66% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Security

Score is unsatisfactory.

Administration Spaces

Score is unsatisfactory.

. Visitors must go past the reception area to get to the rest of the school. The admin area feels welcoming but lacks adequate waiting space. Acoustic separation in the suite is adequate, but there is no dedicated conference room for visitors.

Average Categories (51-65%):

Controllability of Systems

Score is average.

All studios have individual temperature controls, but only one switch for lighting controls. Blinds are provided at all windows and are in adequate condition.

Academics & Learning

Score is average.

Studios are a good size with the space for flexibility to reconfigure for different teaching methods. Dedicated storage and restrooms are available for spaces that require it per the Education Specifications. Two of the four studio wings have a shared flex space in the corridors, but none of the learning neighborhoods have dedicated small group or breakout spaces. There are no maker spaces or professional learning centers on campus. Special education spaces are in portables, making them disconnected and without access to appropriate resources such as storage and space for a changing table.

Media Resources

Score is average.

The library is near the main entry and has an exterior entrance to the front parking lot. It lacks clear

Hart Elementary School

signage or visibility to the interior spaces. There are no dedicated quiet study spaces, but informal seating supports informal interaction. Inflexible furniture makes reconfiguration difficult and limits larger groups to gathering in one area.

Technology

Score is average.

All studios have access to projectors and mobile TV displays. Power outlets and charging stations are limited throughout the school. The cafeteria and gym are equipped with projectors and screens, and the reception area has two TVs for digital media signage near the main office.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

The campus has a large garden area that has access to resources and a small outdoor studio with a markerboard and canopy for shade. There is furniture available for other outdoor teaching spaces elsewhere, but they have no shade structures. Playgrounds are in good condition and shade canopies appear to be new.

General Building

Score is satisfactory.

Corridors are adequately sized, averaging 9 feet wide. All common spaces such as the gym, library and cafeteria are well-located near the main entry of the school and have the ability to be secure from the rest of the campus for after-hours events. The school is well-maintained. Student work and art throughout show pride for the campus.

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture throughout the campus is inconsistent and dated, but in good condition. The library is equipped with a variety of furniture types while the cafeteria only has one seating option. Some of the older, larger furniture would be difficult for younger students to move on their own. Overall, tables, desks and chairs are appropriately sized for each grade level.

Visual and Performing Arts

Score is satisfactory.

The cafeteria stage is adequately sized and ADA accessible. It has what appears to be a new A/V system. The music and art rooms could benefit from more storage space but are well-connected to the stage and back-of-house area.

PE and Wellness

Score is satisfactory.

The gym is adequately sized for the campus but could use updates such as new flooring to function better. It is well-connected to outdoor activity spaces and has two storage rooms that appear to meet current needs.

Food Services

Score is satisfactory.

Hart Elementary School

The cafeteria is appropriately sized and in good condition but has no access to outdoor dining areas. The kitchen has two lines for serving and the space shares an operable wall and restrooms with the gym.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.


There are separate areas for bus and vehicular traffic on-site and the vehicle stack space is generous. There are no canopies at either drop-off lane. Signage is visible and easily identifiable but dated and not digitized.

Environmental Quality

Score is very satisfactory.

All studios have windows that provide natural light and views to the outdoors. Acoustics appear adequate as some teachers in studios had music playing that was slightly audible but not disruptive.

Hart Elementary School




The cafeteria is an adequate size and in good condition. There is no connection to outdoor dining space, nor access to natural light. Two serving lines are present in the kitchen and the space has dedicated restrooms that are shared with the gym.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Hart Elementary School

Supporting Photographs



The media center is undersized and lacks the space to hold large groups or collaborative work. The inflexible furniture limits rapid reconfiguration of the space. At the time of the site walk spot coolers were present due to HVAC issues in the space.

Hart Elementary School



There are two covered playgrounds on campus for different grade levels. They have good connection to the gym and other outdoor activity spaces.



The campus has a thriving garden with access to water and a small outdoor classroom with a whiteboard under a canopy structure for shade.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Hart Elementary School



Corridors throughout the building are adequate in width and have opportunity for 3D or 2D display of student work.




The art studio is appropriately sized per the district's Education Specifications and has the appropriate support spaces, including storage and a kiln.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Hart Elementary School



Two of the studio wings have a centralized shared flex area in the corridor between six studios, creating a learning neighborhood for the grade level.



A large track is located at the back of the campus; it needs updates to function well.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Hart Elementary School	Emilie Ogburn and Patrick Reinhard	1.7.2021

I - Ex	cterior		1	2	3	4	ŀ	5	N/A	N Contraction of the second seco	8.75	86%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?				4	ļ.			Comments	1.00	4.0
	1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location								Bus stack is in the front; queuing space is small. Visitor Parent drop-off in the back. No drop-off canopy.	parking is se	parate
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated										
	3	Average - Buses, cars, and pedestrians are separate but stack space is small										
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria										
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination										
	N/A	Does not apply										
1.2		ling easily identified with appropriate signage and v wayfinding?				4	Ļ			Comments	0.25	1.0
	1	Very unsatisfactory - Campus has no signage / wayfinding								Easily identifiable. Sign is older, not digital.		
	2	Unsatisfactory - Signage/wayfinding is faded/hidden										
	3	Average - Signage / wayfinding visible but not apparent										
	4	Satisfactory - Signage / wayfinding is visible but not good condition										
	5	Very satisfactory - Signage and wayfinding is visible and easy to use										
	N/A	Does not apply										

02/11/2022 ²

- Exterior (con	t.)	1	2	3	4	5	N/A			
I.3 Is the dump	ster accessible for trash / compost disposal?					5		Comments	0.50	2.5
1 2 3	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.							Ramp outside kitchen to trash, recycling and compos for accessible access.	t bins. All conf	igured
4	Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
N/A	Does not apply									
- Outdoor Lec	arning and Activity	1	2	3	4	5	N/A		15.00	80%
2.1 Are outdoor the ed spec	r studios and support spaces appropriately configured per ?		2					Comments	1.00	2.00
1	Very unsatisfactory - No dedicated outdoor studios							Only garden area has shade, benches and a markerk		
2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided							other seating areas around campus, but they are wit dedicated teaching areas.	nout shade or	
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
N/A	Does not apply									
	laygrounds (elementary only) and support spaces per the ed spec?					5		Comments	1.00	5.00
1	Very unsatisfactory - No dedicated active playground							Shade structures appear to be new; elementary plays		wer
2	Unsatisfactory - Too small, poor condition, no shade provided							than pre-K playscapes but all are in excellent condition	on.	
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	sindle coverage over play structure									

02/11/2022 ³

- Οι	utdoor Le	arning and Activity (cont)	1	2	3	4	5	N//	A	
2.3	Are garde spec? (eva	ns and support spaces appropriately configured per the ed luation on infrastructure not condition of plants)					5		Comments 0.00	0.0
	1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor Learning and	
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Activity. Garden is good sized, maintained and used frequently.	
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
	N/A	Does not apply	_				_			
2.4	Are the rai ed spec?	n gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.0
	1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor Learning and	
	2	Unsatisfactory - Too small, poor condition, not functioning, disconnected							Activity.	
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well								
	4	Satisfactory - Good size, good condition, functions properly								
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
	N/A	Does not apply								
2.5	Does the s	chool have animal husbandry? (optional)					5		Comments 0.00	0.0
	1	No							Goats	
	5	Yes	1 -							
2.6	Does the s	chool have nature loop trails? (optional)	1						Comments 0.00	0.0
	1 5	No Yes								
2.7	-	chool have a learning pond? (optional)	1				1	<u> </u>	Comments 0.00	0.0
	1	No			_					
	5	Yes								
2.8	Does the s	chool have a grass play field and walking trail?					5		Comments 1.00	5.0
	1	No								
	5	Yes								

- General B	uilding	1	2	3	4	5	N/A	4	11.25	69
	or circulation routes wide enough to safely and effectively odate student movement?				4			Comments	0.50	2.0
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide							10' in main corridor, 9' into learning neighborhoods		
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
	nunity use areas arranged so that the school can allow night without full school access?					5		Comments	0.75	3.
1	Very unsatisfactory - Cafeteria, gym, and library cannot		1					Community spaces are all near the front with exterior	entrances an	d the
	be accessed after hours							ability to lock down the rest of the school.		
2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours									
3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
N/A	Does not apply									
	community room that is a dedicated meeting space outside function?	1						Comments	0.75	0.
1	Very unsatisfactory - No dedicated community room		1							
2	Unsatisfactory - Community room but within school function, no access after school hours									
3	Average - Community room, moderate size, but need some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets needs /functions well									
5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
N/A	Does not apply									
	general appearance of the school convey pride for the and community?					5		Comments	0.25	1.
1	Very unsatisfactory - General appearance is poor		1					School is well kept. Mural near the front displays com	munity pride c	as doe
2	Unsatisfactory - General appearance is aged but ok							artwork throughout the school corridors.	, i i i i i i i i i i i i i i i i i i i	
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in campus and student works									
5	Very Unsatisfactory - General appearance shows pride in campus and student works and is welcoming to the community									

Security		1	2	3	4	5	N/A		16.25	
•	acility have key card access at all major entries?			_				Comments		
									0.25	
1	Very unsatisfactory - No entries									
2	Unsatisfactory - 1/4 of major entries									
3	Average - 1/2 of major entries									
4	Satisfactory - 3/4 of major entries									
5	Very satisfactory - All of major entries									
N/A	Does not apply								1	
.2 How adeq	uate is site lighting and security for the campus overall?							Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter								·	
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal									
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate									
4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates									
5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure									
N/A	Does not apply									
.3 Is the main	office located at the school entry and configured with a							Commonto		
.o secure vest	tibule to the main corridor?							Comments	1.00	
1	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised									
2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors									
3	Average - Office close to entry, views of front door, but no secure vestibule									
4	Satisfactory - Office is well-located with a secure vestibule, but needs updates									
5	Very satisfactory - Office well-located with secure vestibule and all appropriate security features									
N/A	Does not apply									
	ough interior transparency for faculty to passively supervise nd their activities who are not in studios?			3				Comments	1.00	3
1	Very unsatisfactory - No transparency of walls							Half lite in door and half sidelite		
2	Unsatisfactory - Limited transparency in certain locations									
3	Average - Good transparency in certain locations but inadequate or missing in other locations of school									
4	Satisfactory - Adequate transparency throughout the school									
-	Very satisfactory - Excellent transparency throughout the									
5	school									

02/11/2022 °

	5 - Environmen	ntal Quality	1	2	3	4	5	N//	A	25.00	88%
	5.1 How are ac	coustics in studios in general?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Acoustics seem good in studios. You can hear outside music is being played, but sound is muffled.	of the studios	when
ſ	5.2 Is the studio	o artificial lighting adequate quality?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
	5.3 Is there acc	tess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios have exterior windows.		
ſ	N/A 5.4 Is there acc	Does not apply ress to outside views from learning spaces?					5		Comments		
l	1	Very unsatisfactory - No learning spaces have views					-		All windows are appropriately sized to see outside.	1.00	5.00
	2 3 4 5 N/A	Unsatisfactory - 1-25% of learning spaces have views windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply							An windows are appropriately sized to see outside.		

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the b	uilding have odor or pest problems?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Evidence of both pests and odors							None noticed	•	
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in excellent condition									
	N/A	Does not apply									
6 - C	ontrollabi	lity of Systems	1	2	3	4	5	N/A		12.50	60%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No								·	
	5	Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No, windows are covered with boards/paper									
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply									
6.3	What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Single switch only per room							Only have a single switch for entire room.		
	2	Unsatisfactory - Alternating rows switch off									
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

02/11/2022 *

7 - F	urniture, F	ixtures & Equipment	1	2	3	4	5	N/A	A	18.75	69 %
7.1	What is the	current condition of the furniture?				4			Comments	0.75	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply							Furniture is inconsistent and older, but not broken or	bent.	
7.2		ty of furniture types being accommodated throughout the Irning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Same furniture used in all spaces			•				Library has variety of furniture types. Cafeteria has o	nly folding tabl	les with
	2	Unsatisfactory - Furniture variety in one multi-use space							attached chairs.		
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply		-	1	1		-			
7.3	space?	oes furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy							Older furniture that is difficult for students to move o	n their own.	
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply	1								
7.4	ls the furnit	ure ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

02/11/2022 °

Zero Waste	1	2	3	4	5	N/A	<u>,</u>	5.00	60%
Do studios and corridors have blue recycle bins with bilingual instructions and/or image sorting instructions?			3				Comments	0.50	1.50
1 Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.							A score for this category is being recorded, but this ca calculated in the overall ESA average.	tegory is not	
2 Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.							Bins are present but lack signage.		
3 Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4 Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5 Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A Does not apply									
Does the cafeteria (or wherever meals are served) have at least one of each: green compost bin, blue recycle bin, and landfill bin? Are the bins labelled clearly with bilingual and/or image sorting?			3				Comments	0.50	1.50
 Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. 							A score for this category is being recorded, but this ca calculated in the overall ESA average.	tegory is not	
2 Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3 Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4 Satisfactory- There are several waste stations as described above									
5 Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
N/A Does not apply							L		

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

. .

School Name	Walk Attendees:	Date:
Hart Elementary School	Emilie Ogburn and Patrick Reinhard	1.7.2021

8 - Ac	ademics	& Learning	1	2	3	4	5	N/A	<u>\</u>	70.00	53%
8.1	Are studios	appropriately configured per the ed spec?				4			Comments	1.00	4.0
	1	Very unsatisfactory - Too small, no flexibility, disconnected							Studios are appropriately sized at 860 SF and able to different teaching methods. Adequate storage space	•	alf lite
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							and a half sidelite.		
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
		nd Kinder have appropriate support spaces such as and storage per the ed spec?				4			Comments	1.00	4.0
	1	Very unsatisfactory - None provided					•		Dedicated restrooms and storage for most kinderga	ten/pre-K stud	ios.
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

02/11/2022 ²

3 - Ac	ademics &	& Learning (cont.)	1	2	3	4	5	N/A	A
	Do studios ł ed spec?	nave appropriate support spaces such as storage per the				4			Comments 1.00 4.
	1	Very unsatisfactory - None provided				•			Good built-in casework, all studios have attached restrooms.
	2	Unsatisfactory - Too small, disconnected, poor condition							
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
	Do typical le collaboratio	earning neighborhoods have small group rooms and open on space?		2					Comments 1.00 2.0
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided				•			No breakout rooms provided. Some pods have open collaboration space in the center, but no furniture to support learning seen during assessmen
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy							
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well							
	4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy							
	5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy							
	N/A	Does not apply							
8.5	Are general and multipl	studios large enough to support project-based learning e teaching modalities?				4			Comments 1.00 4.
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning							Sized appropriately. Built-in storage furniture is not centralized.
	2	Unsatisfactory - Undersized, decentralized resources, limited flexibility							
	3	Average - Adequate size, needs some renovations or updates to function well							
	4	Satisfactory - Good size, centralized resources, good flexibility							
	5	Very Satisfactory - Generous size, centralized project resources, excellent flexibility							
	N/A	Does not apply							

02/11/2022 ³

8 - Academics	s & Learning (cont.)	1	2	3	4	5	N/A	N .		
8.6 Are Make the ed spe	r Spaces and support spaces appropriately configured per ec?	1						Comments	1.00	1.00
1	Very unsatisfactory - No dedicated maker spaces							No dedicated space		
2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition, connected to learning spaces									
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
N/A	Does not apply		1	1		r	1			
8.7 Is there a	Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
1	Very unsatisfactory - No dedicated space for Professional Learning Center									
2	Unsatisfactory - Too small, poor condition, disconnected									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition, connected									
5	Very Satisfactory - Generous size, excellent condition, connected									
N/A	Does not apply							<u></u>		
8.8 Is there a	dedicated science room and support space?	1						Comments	0.00	0.00
1	No							Monitoring answer, but doesn't affect overall score.		
5	Yes					_				
	adequate places to display the evidence and artifacts of both 2D and 3D)?				4			Comments	1.00	4.00
1	Very unsatisfactory - No dedicated space							A lot of 2D display, but lack 3D display cases.		
2	Unsatisfactory - Too small, non-dedicated, poor condition									
3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
4										
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply							L		

	& Learning (cont.)	1	2	3	4	5	N/A	4		
	uilding provide adequate opportunities for eachers to collaborate in varying group sizes?		2					Comments	1.00	2.0
1	Very unsatisfactory - No space to support collaboration in various sizes.							No dedicated collaboration rooms/spaces. Only 2 po collaboration space in center that functions as circulo		al
2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
N/A	Does not apply									
3.11 Does the bu	uilding provide opportunities for informal interaction?			3				Comments	1.00	3.0
1	Very unsatisfactory - No space							Has space necessary in 2 of the learning pods, but no	informal seat	ing
2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well							seen during assessment.		
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
N/A	Does not apply									
	arning neighborhood / building provide adequate es for students to work independently?	1						Comments	1.00	1.0
1	Very unsatisfactory - No breakout rooms/small study spaces		I	<u> </u>				No breakout rooms		
2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									

8 - Acc	ademics	& Learning (cont.)							
	Are Special spec?	Education spaces appropriately configured per the ed	1				Comments	1.00	1.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected		•		•	Currently in portables.	•	
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
		Education support spaces, such as storage, space for /er, appropriately configured per the ed spec?	1				Comments	1.00	1.0
	1	Very unsatisfactory - None provided					No dedicated washer/dryer or shower. Special educe	ation is in porto	ables.
	2	Unsatisfactory - Too small, disconnected, poor condition							
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
		ble restrooms and changing rooms readily available to the ucation spaces?				5	Comments	1.00	5.00
	1	No					Changing tables are shoved in the restrooms. No dea	dicated space.	
	5	Yes							

02/11/2022 °

9	- Visual and	Performing Arts	1	2	3	4	5	N/A		15.00	73%
9	Are music s per the ed	spaces and the cafeteria stage appropriately configured spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, missing program spaces							Stage is generously sized and has monumental stairs ramp in the back. New-looking A/V.	in the front a	nd a
	2	Unsatisfactory - Too small, poor condition							· · · · · · · · · · · · · · · · · · ·		
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
ç	.2 Are music of per the ed				3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Space could use more storage, closets are undersized	۶.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
_	N/A	Does not apply		r		-	1	1		1	
9	.3 Are Visual ed spec?	Arts spaces and storage appropriately configured per the			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Space could use more storage; closets undersized.		
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

10 - PE and We	1	2	3	4	5	5 N	/A	10.00	70%	
10.1 Does the co program sp	Impus meet the ed spec standard for physical education aces?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces	•						Good size and good condition. Flooring needs renov	ation.	
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	-	1	1					1	
10.2 Are the phy per the ed s	sical education storage spaces appropriately configured spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							2 storage closets which meet the need of the campus	s. No additional	
2	Unsatisfactory - Too small, disconnected, poor condition							clutter seen in the gym.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
11 - Food Servic	es	1	2	3	4	5	5 N	/A	10.00	70%
11.1 Is the Dining	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Dining commons is sized appropriately and in good of connection to outdoor seating. New projector and re		
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation									
3	Average - Adequate size and condition, needs updates or renovations to function well									
4	Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A	Does not apply									
Aro tho Eoo	d Services support spaces appropriately configured per				4	Т		Commente		
11.2 the ed spec	?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							Appears to be undersized per Ed Spec. Kitchen has 2	serving lines,	
2	Unsatisfactory - Too small, disconnected, poor condition							restroom and office and connection to dumpsters.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

02/11/2022 *

12 - Media Re	sources	1	2	3	4	5	N/A	A 30.00	53%
	ary/Media Center easily accessible for the occupants and the school?				4			Comments	4.00
1	Very unsatisfactory - Not accessible						<u> </u>		4.00
2	Unsatisfactory - Limited access, difficult to find, no transparency							Near main entrance and has an exterior entrance to the front park Lacks signage to find it from the main entrance.	ing.
3	Average - Adequate accessibility, needs updates or renovations to function well								
4	Satisfactory - Accessible, easy to find, good transparency, good condition								
5	Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition								
N/A	Does not apply								
12.2 How well	does the Library/Media Center support quiet study?	1						Comments 1.00	1.00
1	Very unsatisfactory - No quiet study spaces						1	No quiet study spaces, 1 large area.	
2	Unsatisfactory - One area in poor condition, poor acoustic privacy								
3	Average - One or more areas provided, needing updates or renovations to function well								
4	Satisfactory - Clusters or small rooms adjacent to media								
	center, good condition, good acoustic privacy								
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent								
	acoustic privacy								
N/A	Does not apply								
12.3 How well	does the Library/Media Center support social interaction?				4			Comments 1.00	4.00
1	Very unsatisfactory - No space	1						Multiple informal seating areas throughout.	
2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well								
3	Average - Adequate size and condition, needs updates								
	or renovations to function well.								
4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions								
5	Very Satisfactory - Generous size, excellent condition,								
	layout and furnishings support informal interactions								
N/A	Does not apply		-		-		1	1	
	does the Library/Media Center support collaborative work in .ps (4-8 students)?		2					Comments 1.00	2.00
1	Very unsatisfactory - No breakout rooms, no flexible							Library is only 1 space with limited seating options due to inflexible	
2	furniture, no support Unsatisfactory - Too small, one area, poor condition							furniture.	
3	Average - Adequate size, multiple areas provided,								
	needing updates or renovations to function well								
4	Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition								
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition								
N/A	Does not apply							L	

02/11/2022 °

12 -	12 - Media Resources - Continued					4	5	N/A	N .	
12.	5 How well do larger grou	oes the Library/Media Center support collaborative work in ps (10-25)?		2					Comments 1.00	2.00
	1	Very unsatisfactory - No gathering areas							Library is only 1 space with limited seating options due to inflexib	le
	2	Unsatisfactory - Too small, one common space, limited seating, poor condition							furniture.	
	3	Average - Adequate size, one common space, needs updates or renovations to function well								
	4	Satisfactory - Good size, multiple common spaces with seating, good condition								
	5	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition								
	N/A	Does not apply								
12.	6 How well d	oes the Library/Media Center support technology?			3				Comments 1.00	3.00
	1	Very unsatisfactory - No vis comm tools							Multiple portable screens and projector, but no desktop comput	ers or
	2	Unsatisfactory - Outdated, poorly functioning, or insufficient							whiteboards.	
	3	Good - Mix of old and new whiteboards/projectors/etc.								
	4	Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition								
	5	Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition								
	N/A	Does not apply								
13 -	Technology	/	1	2	3	4	5	N/A	20.00	60%
13.	1 How well e	quipped are the facilities with instructional technology?				4			Comments 1.00	4.00
	1	Very unsatisfactory - Limited to no technology present in instructional spaces				•	•		No smart boards, but multiple types of technology that are in ga condition.	od
	2	Unsatisfactory - One type of technology present								
	3	Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school								
	4	Satisfactory - Multiple types of technology, smart boards, good condition.								
	5	Very Satisfactory - Multiple types of technology, smart boards, excellent condition								
	N/A	Does not apply			-					
13.	2 Is there and spaces?	adequate number of power and data outlets in learning		2					Comments 1.00	2.00
	1	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)				-				
	2	Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)								
	3	Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)								
	4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall)								
	5	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)								
	N/A	Does not apply							<u></u>	

o - recimolog	ıy (cont.)	1	2	3	4	5	N/A			
3.3 Are there	adequate charging locations for devices?		2					Comments	1.00	2.0
1	Very unsatisfactory - No centralized charging location				•				•	
2	Unsatisfactory - Centralized charging location, but inadequate in size for number of devices									
3	Average - Charging cart or tower but not adequately sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower located centralized location. Excellent condition									
N/A	Does not apply									
3.4 Is there ac	lequate AV for presentations spaces – cafeteria and gym?				4			Comments	1.00	4.
1	Very unsatisfactory - AV not present in one or more space						_	Cafeteria appears to have new projector and screen and mobile projector but no audio system.	. Gym has a so	reen
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply									
						5		Comments		
3.5 Is there dig	gital media signage at the reception area?					Ŭ			0.00	0.
13.5 Is there dig	gital media signage at the reception area? Very unsatisfactory - No digital media present in reception area							2 digital TVs near main office	0.00	0.
	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition							2 digital TVs near main office	0.00	0.
1	Very unsatisfactory - No digital media present in reception area							2 digital TVs near main office	0.00	0.
1	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR							2 digital TVs near main office	0.00	0
1 2 3	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good							2 digital TVs near main office	0.00	0.

02/11/2022 "

1	4 - A	dministro	ation Spaces	1	2	3	4	5	N/A	A	20.00	50%
		ls there a r visitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
		1	Very unsatisfactory - No security checkpoint						•		•	
		2	Unsatisfactory - Checkpoint is too small, poor condition									
		3	Average - Needs updates or renovations to function well									
		4	Satisfactory - Good size, good condition									
		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply		1	r	-		1			
	14.2	Does the a	dministration area feel welcoming?			3				Comments	1.00	3.00
		1	Very unsatisfactory - No welcome space							Feels welcoming, but lacks waiting space.		
		2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition									
		3	Average - Adequate size and layout, needs updates or									
		0	renovations to feel welcoming									
		4	Satisfactory - Good size and layout, good lighting and									
		5	transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of									
		5	light and transparency, informal seating provided,									
			excellent condition									
_		N/A	Does not apply		1					-		
			paces that require it, does the administration area have acoustic privacy?				4			Comments	1.00	4.00
		1	Very unsatisfactory - No acoustic separations							Acoustic separation is good in offices.		
		2	Unsatisfactory - Acoustic separations do not perform well									
		3	Average - Some acoustic separations function okay, but portions need updates or renovations									
		4	Satisfactory - Good acoustic separations									
		5	Very Satisfactory - Excellent acoustic separations									
_		N/A	Does not apply		1	. – –		·	-		1	
	14.4	Are confer	ence rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
		1	Very unsatisfactory - Not accessible for public/parent use							No dedicated conference room. The admin break roo		he
		2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find							conference space with loud equipment in the backgr	ouna.	
		3	Average - Adequate accessibility, needs updates or renovations to function well									
		4	Satisfactory - Good accessibility, good transparency, good size and condition									
		5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
		N/A	Does not apply									