



Educational Suitability Summary Report

Kiker Elementary School

Date: 12/14/2020

Score 60% Average

Kiker Elementary School, serving an enrollment of approximately 800 students in southwest Austin, is known for its parental engagement and is a tranquil campus serving the Circle C neighborhood. The school was built in 1992 and has 75,000 square feet on an 11.5-acre site.

The school is overall in good condition. The campus is expansive but welcoming. The entry is secured by a large vestibule and has direct access to the reception area. Studios and circulation corridors are adequately sized, but there are no spaces for a variety of breakout group sizes. Large outdoor spaces could adequately house outdoor learning and activities, but current infrastructure to provide these opportunities is lacking. Additional PE space is housed in a portable because the current gym does not appear to accommodate the number of students enrolled.

Interview Overview

The interview with Principal Matheny, parents and various staff members provided insight into the operations at Kiker Elementary. They would like to maintain the front entry of the building; they like the aesthetics and think it functions well. They also value and do not wish to change the mature tree by the library, the sun dial, and the covered deck outside of the cafeteria where parents and students eat lunch together. The areas that function well include the art rooms, the kindergarten wing and annex building.

The main areas that do not function well in the main building are the cafeteria and gymnasium. Neither are able to accommodate the school enrollment without significant daily schedule strains. In general, the school needs more gathering or common spaces and meeting rooms. They would also like a designated computer and science lab. Additional storage is needed throughout.

On the exterior, the portables (where life skills and overflow PE are located) are prohibitive to their intended function. They would like more and improved outdoor learning spaces. The staff noted that a formal track would offer students extracurricular opportunities not currently supported and more playground space would offer opportunities for activity and creativity.

They would love a broadcast studio and language program as well. Overall, the interviewees do not feel the current spaces support the 6 C's. There is little to no connection between studios and a lack of meetings spaces for collaboration. There is also a lack of transparency throughout the school, compromising connectivity.

Assessment Findings

The Educational Suitability Assessment of Kiker Elementary School earned a 60% overall score and places the campus in a category of Average. The assessment consists of seven General Building

Kiker Elementary School

categories and seven categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Outdoor Learning and Activity

Score is unsatisfactory.

The outdoor play spaces are in good condition. The school has two playscapes. One has shade, and the other does not. The learning garden needs updates and is in poor condition. There is an outdoor patio (covered with picnic tables) for outdoor dining. It is not currently used as an outdoor studio.

General Building

Score is unsatisfactory.

The building is in overall good condition and has numerous display areas for art, school awards and murals. The school provides limited opportunities for hosting events after-hours. There is no dedicated community room, and the library, cafeteria and gym cannot be closed off from the rest of the school.

Academics & Learning

Score is unsatisfactory.

Studios throughout the campus are well-sized with adequate storage. The school is built with traditional hallways with studios on both sides. Limited transparency and lack of breakout spaces between studios mean teachers have limited flexibility to teach in different group sizes. Special education is divided between typical studios and portables. All the special education spaces lack the necessary support spaces. There are no accessible restrooms, changing areas or life skills spaces.

Technology

Score is unsatisfactory.

The technology infrastructure throughout the school needs improvement. Studios do not have enough outlets or a dedicated charging station. Gym and cafeteria A/V equipment is outdated.

Average Categories (51-65%):

Furniture, Fixtures, Equipment

Score is average.

The furniture throughout the school is not new, but generally in good condition. Tables and loose chairs can be reconfigured, but without wheels it may be difficult for students to move them without assistance. Furniture in the multi-use spaces could be improved with more variety and additional informal seating.

Visual and Performing Arts

Score is average.

The main art room and music room are equipped with a restroom and storage. Music has good proximity to the performance space in cafeteria. The cafeteria stage does not have accessible access and lacks adequate storage.

Food Services

Score is average.

Educational Suitability Summary Report

Kiker Elementary School

Cafeteria is not large enough for student enrollment, with no variety of seating and limited opportunity for outdoor dining. Parents often eat lunch with students on a covered deck between the school buildings, but upgrades would help this space function better. There is no natural light or views from within the cafeteria.

Satisfactory Categories (66-80%):

Security

Score is satisfactory.

Controllability of Systems

Score is satisfactory.

Each studio has an individual thermostat to control temperature. Individual heating / cooling units take up square footage in the studios. In the main building, lighting controls are single on/off switches, while studios in the annex have two lighting levels. Blinds are in good condition throughout the school.

Media Resources

Score is satisfactory.

The library is easily accessed by a short corridor from the main entry vestibule. The interior is a large, open space with high ceilings and adequate daylight. Two breakout rooms are being used for other functions but could support small groups or quiet study.

Environmental Quality

Score is satisfactory.

All studios have access to natural light and views to the exterior. Acoustics could be improved between the studios. Most have no door between pairs of studios.

Exterior

Score is satisfactory.

The exterior appearance is generally good. At the main entry, a small grove of trees sits between two drop-off canopies to create a pleasing initial view of the school. Bus and vehicular drop-off occur in two different areas and generally function well.

PE and Wellness

Score is satisfactory.

The main gym is adequately sized per Ed Spec, but some PE classes take place in a portable. The gym has appropriate support space – gym office, restroom and storage room, which opens both to the gym and to the exterior.

Administration Spaces

Score is satisfactory.


The administration space is nicely laid out and welcoming. It has good transparency and views to the main entry vestibule. Acoustics are good, providing privacy when speaking at normal voice levels.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Kiker Elementary School

Supporting Photographs






Gym is appropriately sized per Ed Spec but does not meet the current needs of the school. The gym and cafeteria open to one large space with an operable partition.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Kiker Elementary School

Supporting Photographs



Administration: Reception area is welcoming and colorful.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Kiker Elementary School

Supporting Photographs



Media Center: Library is in good condition, but furniture ergonomics could be improved.



Food Services: Cafeteria is in good condition, but size does not meet Ed Spec based on current enrollment.

Educational Suitability Summary Report

Kiker Elementary School

Supporting Photographs



Most studios have ample daylight. Furniture is dated and in average condition.



Annex Building: A central, open breakout space flanks studios in the annex building. Storage of chairs/tables is an outcome of Covid-19 protocols, but in general furniture is not flexible to allow for quick reconfiguration of space. This space is used daily. Built-in technology (i.e., large TVs on wall) is dated and not used.

Educational Suitability Summary Report

Kiker Elementary School

Supporting Photographs



Visual and Performing Arts: Art room is well-organized and has ample storage.



Outdoor Dining and Stream: A covered patio serves as a touchdown lunch area for students and parents.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Kiker Elementary School	Kevin Kinsey and Kendall Claus	12/14/2020

1 - E	xterior		1	2	3	4	5	N/A	N Contraction of the second	8.75	74%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location									
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
1.2		ing easily identified with appropriate signage and wayfinding?				4			Comments	0.25	1.00
	1	Very unsatisfactory - Campus has no signage / wayfinding							Small monument sign at street corner and canopy at Additional signage and better wayfinding would mak		ke it
	2	Unsatisfactory - Signage/wayfinding is faded/hidden							easier for visitors to access the main drop-off.		
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

02/11/2022 ²

1 - E	xterior (cor	nt.)	1	2	3	4	5	N/A			
1.3	ls the dump	oster accessible for trash / compost disposal?			3				Comments	0.50	1.50
	1 2 3 4 5 N/A	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it. Does not apply							No accessible route.		
2-0		arning and Activity	1	2	3	4	5	N/A		15.00	40%
2.1		r studios and support spaces appropriately configured per		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							One area serves as lunch breakout; therefore can't b	e used as stud	io.
2.2		Does not apply blaygrounds (elementary only) and support spaces per the ed spec?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply							Only one covered for first through fifth grades. Outd covered. Need more green space.	oor play court	is

02/11/2022 ³

1 Ver 2 Uns fror 3 Ave 3 Ave 3 Ave 3 Ave 3 Ave 3 Ave 5 Ver con 5 Ver con sou N/A Doe 4 Are the rain garc ed spec? 1 Ver 2 Uns	A support spaces appropriately configured per the ed n on infrastructure not condition of plants) y unsatisfactory - No dedicated gardens satisfactory - Too small, poor condition, disconnected m learning spaces, no flexibility, no accessible water rce erage - Adequate size, adequate condition, needs ne renovations or updates to function well, water rce is difficult to access isfactory - Good size, good condition, connected to rning spaces, good flexibility, water source is tessible with 100 ft hose y Satisfactory - Generous size, excellent condition, anected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation tes not apply dens and/or cisterns appropriately configured per the		2			Comments Recording answer, does not affect score for Outdoor L Spread out and current garden is in poor condition.	0.00 earning and	0.00 Activity
2 Uns from sou 3 Ave som sou 4 Sati lear acc 5 Ver con sou N/A Doe ed spec? 1 Ver 2 Uns	satisfactory - Too small, poor condition, disconnected m learning spaces, no flexibility, no accessible water rrce erage - Adequate size, adequate condition, needs ne renovations or updates to function well, water rrce is difficult to access isfactory - Good size, good condition, connected to rning spaces, good flexibility, water source is essible with 100 ft hose y Satisfactory - Generous size, excellent condition, unected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation es not apply						earning and	Activit
3 sou 3 Ave sorr sou 4 Sati lear acc 5 Ver con sou N/A Doe Are the rain garc ed spec? 1 Ver 2 Uns	rce rrage - Adequate size, adequate condition, needs he renovations or updates to function well, water rrce is difficult to access isfactory - Good size, good condition, connected to rning spaces, good flexibility, water source is essible with 100 ft hose y Satisfactory - Generous size, excellent condition, innected to learning spaces, excellent flexibility, water rrce is less than 50ft from the garden or has irrigation es not apply					Spread out and current garden is in poor condition.		
4 Sati lear acc 5 Ver con sou N/A Doe 4 Are the rain gard ed spec? 1 Ver 2 Uns	ne renovations or updates to function well, water rce is difficult to access isfactory - Good size, good condition, connected to rning spaces, good flexibility, water source is essible with 100 ft hose y Satisfactory - Generous size, excellent condition, unected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation es not apply							
4 Sati lear acc 5 Ver con sou N/A Doe 4 Are the rain gard ed spec? 1 Ver 2 Uns	isfactory - Good size, good condition, connected to rning spaces, good flexibility, water source is essible with 100 ft hose y Satisfactory - Generous size, excellent condition, unected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation es not apply							
5 Very con sou N/A Doe .4 Are the rain gard ed spec? 1 Very 2 Uns	y Satisfactory - Generous size, excellent condition, nected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation es not apply							
Are the rain garc ed spec? 1 Ver 2 Uns	nected to learning spaces, excellent flexibility, water rce is less than 50ft from the garden or has irrigation es not apply							
N/A Doe Are the rain gard ed spec? 1 Ver 2 Uns	es not apply	1						
.4 ed spec? 1 Ver 2 Uns	dens and/or cisterns appropriately configured per the			 				
2 Uns				4		Comments	0.00	0.0
	y unsatisfactory - No rain gardens or cisterns					Recording answer, does not affect score for Outdoor L	earning and	Activit
tun	satisfactory - Too small, poor condition, not							
3 Ave	ctioning, disconnected erage - Adequate size, adequate condition, is							
	inected, needs some renovations or updates to							
	ction well							
	isfactory - Good size, good condition, functions							
pro	perly							
5 Ver	y Satisfactory - Generous size, excellent condition,							
	eptional functionality, connected to learning spaces,							
	ucational signage provided							
	es not apply have animal husbandry? (optional)				5	Comments	0.00	0.0
1 No				1	-		0.00	
5 Yes	S							
.6 Does the school	have nature loop trails? (optional)	1				Comments	0.00	0.0
1 No								
5 Yes						 		
	have a learning pond? (optional)	1				Comments	0.00	0.0
1 No								
5 Yes		- 1		 		 Commerciate	100	
.8 Does the school I 1 No	have a grass play field and walking trail?	1				 Comments Play field provided but not walking trail.	1.00	1.0

- General Bu	lilding	1	2	3	4	5	N/A	N Contraction of the second seco	11.25	40
	r circulation routes wide enough to safely and effectively				A			Comments		
accommod	date student movement?				4			Comments	0.50	2.0
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
	wide									
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are commu	unity use areas arranged so that the school can allow night	1						Comments		
,.2 functions v	vithout full school access?	-							0.75	0
1	Very unsatisfactory - Cafeteria, gym, and library cannot							Cannot be closed off. Doors exist but studios within a	rea.	
	be accessed after hours									
2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
	Gym and Library) can be accessed from parking and secured after hours									
3	Average - Only two of the public spaces can be accessed									
5	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply			1			1	1		
2.12	community room that is a dedicated meeting space outside	1						Comments		
of school f									0.75	0
1	Very unsatisfactory - No dedicated community room									
2	Unsatisfactory - Community room but within school									
3	function, no access after school hours Average - Community room, moderate size, but need									
5	some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
	function									
N/A	Does not apply		r	1	1	1				
ξ <u>Λ</u> -	eneral appearance of the school convey pride for the nd community?				4			Comments	0.05	
students d			I		<u> </u>	I	L	Displayed plaques: clean: muscle	0.25	1
2	Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok							Displayed plaques; clean; murals.		
2	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
	campus and student works									
5	Very Unsatisfactory - General appearance shows pride in									
	campus and student works and is welcoming to the									
	community									
N/A	Does not apply									

- Security		1 2	3 4	5 N//	A	16.25
1.1 Does the fo	acility have key card access at all major entries?				Comments	0.25
1	Very unsatisfactory - No entries		•			•
2	Unsatisfactory - 1/4 of major entries					
3	Average - 1/2 of major entries					
4	Satisfactory - 3/4 of major entries					
5	Very satisfactory - All of major entries					
N/A	Does not apply					
.2 How adequ	uate is site lighting and security for the campus overall?				Comments	1.00
1	Very unsatisfactory - No exterior lighting, no secure perimeter				· · · · · · · · · · · · · · · · · · ·	
2	Unsatisfactory - Lighting is limited to front entry only,					
2	parking lot lighting poor, security is minimal					
3	Average - Lighting at all night-use entries and parking					
0	lot, but poor condition. Security is moderate					
4	Satisfactory - Lighting at all night-use entries and					
	parking lots, good condition, signage less visible,					
	perimeter is well secured but needs updates					
5	Very satisfactory - Signage, parking lots, and entries are					
	well lit, visible and easy to use, perimeter is very secure					
N/A	Does not apply					
Is the main	office located at the school entry and configured with a					
·2	tibule to the main corridor?				Comments	1.00
1	Very unsatisfactory - No secure vestibule, office located	1 1 1		1 1		
	far from main entry, allows visitors access to school					
	unsupervised					
2	Unsatisfactory - No secure vestibule, office located					
	somewhat far from main entry, minimal supervision of					
	visitors					
3	Average - Office close to entry, views of front door, but					
4	no secure vestibule					
4	Satisfactory - Office is well-located with a secure vestibule, but needs updates					
5	Very satisfactory - Office well-located with secure					
-	vestibule and all appropriate security features					
N/A	Does not apply					
Is there end	ough interior transparency for faculty to passively supervise					
	nd their activities who are not in studios?	2			Comments	1.00
1	Very unsatisfactory - No transparency of walls				Small window at each studio. Teachers complain th	nere's not enough
2	Unsatisfactory - Limited transparency in certain locations				visibility.	
3	Average - Good transparency in certain locations but					
-	inadequate or missing in other locations of school					
4	Satisfactory - Adequate transparency throughout the					
	school					
5	Very satisfactory - Excellent transparency throughout the	•				
	school					
N/A	Does not apply					

02/11/2022 *

5 - Environmental Quality	1	2	3	4	5	N/A	A	25.00	72
5.1 How are acoustics in studios in general?			3				Comments	1.00	3.
 Very unsatisfactory - Recognized word/s adjacent studio/corridor Unsatisfactory - Audible sound from adja studio/corridor Average - Slight sound from outside roor Satisfactory - Walls to deck insulated on from mechanical system Very satisfactory - Able to hear quiet spe across the room N/A Does not apply 	acent m Iy white noise						Most have no door between adjacent studios.		
5.2 Is the studio artificial lighting adequate quality?			3				Comments	1.00	3
 Very unsatisfactory - Sporadic lights wor than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare N/A Does not apply 	-						No dimming where needed.		
					-		Comments		
5.3 Is there access to natural light in studios? 1 Very unsatisfactory - No learning spaces	have natural				5		Comments	1.00	5
light 2 Unsatisfactory - 1-25% of learning space light or windows are too small to let in lig 3 Average - 26-50% of learning spaces ha	ght								
4 Satisfactory - 51-75% of learning spaces light	-								
5 Very satisfactory - 76-100% of learning s natural light N/A Does not apply	paces have								
N/A Does not apply 5.4 Is there access to outside views from learning spaces?	,				5		Comments	1.00	_
Very unsatisfactory - No learning spaces	have views		I					1.00	5
 2 Unsatisfactory - 1-25% of learning spaces windows are too small to see out 3 Average - 26-50% of learning spaces ha 	s have views or								
4 Satisfactory - 51-75% of learning spaces 5 Very satisfactory - 76-100% of learning s views	have views								
N/A Does not apply									

5 - E	nvironme	ntal Quality (cont.)	1	2	3	4	5	N/A	A		
5.5	Does the b	uilding have odor or pest problems?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Evidence of both pests and odors							Rats are a significant issue and have been for years.		
	2	Unsatisfactory - Evidence of pests or odors									
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school									
		cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in									
		excellent condition									
	N/A	Does not apply									
6 - 0	Controllabi	ility of Systems	1	2	3	4	5	N/A	A	12.50	68%
6.1	Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No							SF in studios is being taken up by heating / cooling ur	nits.	
	5	Yes									
6.2	Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No, windows are covered with									
		boards/paper									
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply	1	1	1	1	r –	1	1		
6.3	What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Single switch only per room							Main building on or off. Annex has 2 lighting levels.		
	2	Unsatisfactory - Alternating rows switch off									
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A	м	18.75	59%
7.1 What is the current condition of the furniture?				4			Comments	0.75	3.00
1 Very unsatisfactory - Damaged or broken, non-	I		<u> </u>					0.75	5.00
functioning									
2 Unsatisfactory - Torn/ bent/ wrong size									
3 Average - Scratched/dented/marked									
4 Satisfactory - Not new, but sturdy and clean									
5 Very satisfactory - New									
N/A Does not apply	1								
Are a variety of furniture types being accommodated throughout the 7.2		2					Comments		
^{7.2} school - learning commons, dining commons, other multi-use spaces?		2					Comments	1.00	
Very Unsatisfactory - Same furniture used in all spaces							Need more variety. No special furniture for art, music	1.00	2.00
								.,	
 Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use 									
space									
4 Satisfactory - All multi-use spaces have greater than one									
type of furniture									
5 Very satisfactory - All multi-use spaces have greater than two types of furniture									
N/A Does not apply									
How well does furniture accommodate rapid reconfiguration of a		2					Comments		
space?		2					Comments	1.00	2.00
1 Very Unsatisfactory - Furniture is fixed or very heavy									
2 Unsatisfactory - Furniture does not allow desks to be									
configured as individuals, small groups, or large groups 3 Average - Mix of furniture that can reconfigure but is									
cumbersome to move									
4 Satisfactory - Furniture is flexible for multiple									
configurations of space									
5 Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
N/A Does not apply									
7.4 Is the furniture ergonomic and size appropriate for grade level?				4			Comments		
								1.00	4.00
1 Very unsatisfactory - Desk with attached chair combinations too small for grade level									
2 Unsatisfactory - Desk with attached chair combinations									
3 Average - Mix of studios with tables/loose chairs and									
desks with fixed seats									
4 Very satisfactory - Tables with loose chairs									
5 Very satisfactory - Tables with loose chairs that allow									
students to be active									
N/A Does not apply									

02/11/2022 °

Waste		1	2	3	4	5	N/A	5.00	50
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?					5		Comments 0.50	2.
1 2 3 4 5 N/A	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
Does the ca of each: gre	Does not apply feteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the d clearly with bilingual and/or image sorting?						N/A	Comments 0.50	0.
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.						<u>I</u>	A score for this category is being recorded, but this category is not calculated in the overall ESA average. Cafeteria being used as studio/storage. No bins present.	
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.								
4 5	Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as								
	described above, and additional signage in the cafeteria								

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria


Academics - Elementary School

School Name	Walk Attendees:	Date:
Kiker Elementary School	Kevin Kinsey and Kendall Claus	12/14/2020

8.1 Are studios appropriately configured per the ed spec? 3 Comments	1.00	
		3.00
1 Very unsatisfactory - Too small, no flexibility, disconnected Good size but not flexible. Limited transparency to hallwe window).	/ays (small	
2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected		
 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 		
⁴ Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces		
 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces 		
N/A Does not apply		
8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 3 Comments	1.00	3.00
1 Very unsatisfactory - None provided Kindergarten has bathrooms attached and needs more s	storage.	
2 Unsatisfactory - Too small, disconnected, poor condition		
3 Neutral - Adequate size, average condition, needs		
updates or renovations to function well		
4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent		
condition		
N/A Does not apply		

02/11/2022 ²

8 - A	cademics a	& Learning (cont.)	1	2	3	4	5	N/A	4	
8.3	Do studios H ed spec?	nave appropriate support spaces such as storage per the				4			Comments 1.00	4.00
	1	Very unsatisfactory - None provided							Full wall of cabinets in every studio. The only studio that needs more i	is art
	2	Unsatisfactory - Too small, disconnected, poor condition							room.	
	3	Neutral - Adequate size, average condition, needs								
		updates or renovations to function well								
	4	Satisfactory - Good size, connected, good condition								
	5	Very Satisfactory - Generous size, connected, excellent								
		condition								
	N/A	Does not apply								
8.4		earning neighborhoods have small group rooms and open	1						Comments	
0.4	collaboratio								1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open							No breakout spaces in main buildings. Annex has large breakout grou	up
		collaboration spaces are provided							space.	
	2	Unsatisfactory - Too small or too few, poor condition, no								
		flexibility, lacks visual connection to learning								
	3	neighborhood, poor acoustic privacy Average - Adequate size, adequate condition, needs								
	3	some renovations or updates to function well								
	4	Satisfactory - Good size, good condition and flexibility,								
	-	transparency and connection to learning neighborhood,								
		acoustic privacy								
	5	Very Satisfactory - Generous size, excellent condition and								
		flexibility, transparency and connection to learning								
		neighborhood, acoustic privacy								
	N/A	Does not apply								
8.5		studios large enough to support project-based learning			3				Comments	
0.0	and multipl	e teaching modalities?			5				1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, does not							Furniture not movable.	
		support project-based learning								
	2	Unsatisfactory - Undersized, decentralized resources,								
		limited flexibility								
	3	Average - Adequate size, needs some renovations or								
	4	updates to function well Satisfactory - Good size, centralized resources, good								
	4	flexibility								
	5	Very Satisfactory - Generous size, centralized project								
	Ū	resources, excellent flexibility								
	N/A	Does not apply								



8 - A	cademics a	& Learning (cont.)	1	2	3	4	5	N//	A		
8.6	Are Maker S	Spaces and support spaces appropriately configured per	1						Comments		
0.0	the ed spec	?	I						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected									
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply			1	-	1	1		[
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply									
8.8	Is there a de	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
	Are there a	dequate places to display the evidence and artifacts of									
8.9	learning (bo	oth 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space							Adequate amount of space to hang 2D but no 3D.		
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

	nics & Learning (cont.)	1	2	3	4	5	N/A			
	he building provide adequate opportunities for		2					Comments		
studen	ts/teachers to collaborate in varying group sizes?		2					Comments	1.00	2.0
1	Very unsatisfactory - No space to support collaboration							Library and annex areas are only areas.		
	in various sizes.									
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple options									
	to support a variety of group sizes									
5										
	multiple options to support a variety of group sizes									
N/	A Does not apply	1	1	-		-	0			
8 11 Does tl	he building provide opportunities for informal interaction?		2					Comments		
0.11			-					Commonito	1.00	2.
1								Plain hallways, no breakout.		
2										
	furnishings do not support informal interaction well									
3										
	or renovations to function well.									
4	·····,									
_	furnishings support informal interactions									
5										
	layout and furnishings support informal interactions									
N/		1	1		1	1			1	
2 117	he learning neighborhood / building provide adequate	1						Comments		
opport	unities for students to work independently?								1.00	1.
1								No.		
	spaces									
2										
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	5									
	or renovations to function well.									
4										
	variety of independent work space options, connected to									
	learning neighborhood									
5										
	acoustic privacy, variety of independent work space									
	options, connected to learning neighborhood									
N/	A Does not apply									


3 - Aca	demics	& Learning (cont.)							
8.13	re Special bec?	Education spaces appropriately configured per the ed		2			Comments	1.00	2.0
	1	Very unsatisfactory - Too small, no flexibility, disconnected					Special education is divided, with some classes in the others in a portable. No sensory space is provided or	•	•
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected					restroom in special education portable is not accessil by students in gym, because there is no restroom in t		
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
RIN	•	Education support spaces, such as storage, space for rer, appropriately configured per the ed spec?		2			Comments	1.00	2.0
	1	Very unsatisfactory - None provided					No life skills kitchen or washer/dryer.		
	2	Unsatisfactory - Too small, disconnected, poor condition							
	3	Neutral - Adequate size, average condition, needs							
		updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent							
	N/A	condition							
		Does not apply			 				
216		ble restrooms and changing rooms readily available to the rcation spaces?	1				Comments	1.00	1.
	1	No					Large restroom; no grab bars; no changing room.		
	5	Yes							

02/11/2022 *

9 - Visual and	Performing Arts	1	2	3	4	5	N/	Ά	15.00	60%
9.1 Are music per the ed	spaces and the cafeteria stage appropriately configured spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Needs more storage but has restroom. Stage and mu	isic studio are	close to
2	Unsatisfactory - Too small, poor condition							one another. Stage isn't accessible.		
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
9.2 Are music per the ed	and performance storage spaces appropriately configured spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - None provided							Storage is limited.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply	1	1							
9.3 Are Visual ed spec?	Arts spaces and storage appropriately configured per the			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							One art room fully equipped with kiln, storage and re	estroom. Other	is in
2	Unsatisfactory - Too small, poor condition							regular studio.		
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply							<u></u>		

	llness	1	2	3	4	5	N/A	A	10.00	70
	ampus meet the ed spec standard for physical education			3				Comments		
program sp									1.00	3.
1	Very unsatisfactory - Too small, missing program spaces							Current gym that opens to cafeteria is 3,000 SF but o		
2	Unsatisfactory - Too small, poor condition							needs of the school currently. Auxiliary gym space in	portable with I	no
3	Average - Adequate size, adequate condition, needs							restroom.		
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	1		1	-	1		1	1	
0.2	vsical education storage spaces appropriately configured				4			Comments		
per the ed s									1.00	4.
1	Very unsatisfactory - None provided							Storage room is accessible from inside/outside. Have	e shed for addit	tiona
2	Unsatisfactory - Too small, disconnected, poor condition							storage.		
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
N/A	condition Does not apply									
I - Food Servic		,	2	~	4	~	N1/A	A	10.00	
- roou servic	.62		2	3	4	5	N/A		10.00	6
11.1 Is the Dinin	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.
1	Very unsatisfactory - Too small, missing program spaces							Not big enough for student enrollment. Currently 3,7	00 SF and bas	ed of
1 2								Not big enough for student enrollment. Currently 3,7 of enrollment of 800, need additional 800 SF. No na		
	Unsatisfactory - Too small, poor condition, only one								tural light/viev	vs
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation							of enrollment of 800, need additional 800 SF. No na	tural light/viev eat with studer	ws nts.
	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates						<u>.</u>	of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to	tural light/viev eat with studer ia, meaning th	ws nts.
2 3	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation,							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3 4	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3 4	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex:							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3 4 5	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)							of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts.
2 3 4 5 N/A	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply				1			of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th	ws nts.
2 3 4 5 N/A	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply ad Services support spaces appropriately configured per			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter	tural light/viev eat with studer ia, meaning th	ws nts. iere is
2 3 4 5 <u>N/A</u>	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply ad Services support spaces appropriately configured per			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts.
2 3 4 5 N/A 11.2 Are the Foo the ed spec	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply d Services support spaces appropriately configured per ? Very unsatisfactory - None provided			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is
2 3 4 5 N/A 11.2 Are the Foo the ed spec 1 2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply de Services support spaces appropriately configured per ? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is
2 3 4 5 N/A 11.2 Are the Foo the ed spec 1	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply d Services support spaces appropriately configured per ? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is
2 3 4 5 <u>N/A</u> 11.2 Are the Foo the ed spec 1 2 3	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply d Services support spaces appropriately configured per ? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is
2 3 4 5 <u>N/A</u> 11.2 Are the Foo the ed spec 1 2 3 4	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply d Services support spaces appropriately configured per ? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is
2 3 4 5 <u>N/A</u> 11.2 Are the Foo the ed spec 1 2 3	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply d Services support spaces appropriately configured per ? Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well			3				of enrollment of 800, need additional 800 SF. No na outside. There is a small patio outside for parents to However, this space has no visibility from the cafeter no flexibility for students to choose indoor/outdoor d	tural light/viev eat with studer ia, meaning th lining.	ws nts. iere is

12 - Media Resources	1	2	3	4	5	N/A	·	30.00	67%
12.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?			3				Comments	1.00	3.00
 Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition N/A Does not apply 							No transparency but on main hallway for ease of acc	cess.	
12.2 How well does the Library/Media Center support quiet study?			3				Comments	1.00	3.00
 Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy N/A Does not apply 		•					2 breakout rooms but being used for different functio	ns.	
12.3 How well does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 		1		L	I		Large open space.		
12.4 How well does the Library/Media Center support collaborative work in small groups (4-8 students)?			3				Comments	1.00	3.00
 Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition N/A Does not apply 							Library has two adjacent rooms which can function a	s breakout are	



12 - Media Res	ources - Continued	1	2	3	4	5	N/A			
	oes the Library/Media Center support collaborative work oups (10-25)?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply									
12.6 How well d	oes the Library/Media Center support technology?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Good - Mix of old and new whiteboards/projectors/etc. Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition Does not apply		1							
13 - Technolog	у	1	2	3	4	5	N/A		20.00	45%
13.1 How well e	quipped are the facilities with instructional technology?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply							TVs on carts and digital projector.		
13.2 Is there an spaces?	adequate number of power and data outlets in learning		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to				<u>.</u>	·		Could use more.		
	support digital devices throughout school (>3 per wall)									

- Technolog	y (cont.)	1	2	3	4	5	N//	4		
3.3 Are there a	dequate charging locations for devices?	1						Comments	1.00	1.0
1	Very unsatisfactory - No centralized charging location									
2	Unsatisfactory - Centralized charging location, but inadequate in size for number of devices									
3	Average - Charging cart or tower but not adequately									
-	sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower located									
	centralized location. Excellent condition									
N/A	Does not apply	1			-		1	1	T	
3.4 Is there ade	equate AV for presentations spaces – cafeteria and gym?			3				Comments	1.00	3.
1	Very unsatisfactory - AV not present in one or more							Needs to be renovated.		
	space									
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV									
	undersized / adequate condition									
4 5	Satisfactory - Good size, good condition									
	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply	1		1	-	1			1	
3.5 Is there dig	ital media signage at the reception area?			3				Comments	0.00	0.
1	Very unsatisfactory - No digital media present in							Recording answer, does not affect overall technolog	y score.	
	reception area									
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR									
4	undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

4 - Administro		1	2	3	4	5	N/A		20.00	80
14.1 Is there a re visitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint					ļ	1		1.00	
2	Unsatisfactory - Checkpoint is too small, poor condition								· · · · · · · · · · · · · · · · · · ·	
3										
	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply					1	1		T	
14.2 Does the a	dministration area feel welcoming?				4			Comments	1.00	4.
1	Very unsatisfactory - No welcome space							Ample transparency and large space.		
2	Unsatisfactory - Too small, poor lighting and									
	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
5	transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of									
5	light and transparency, informal seating provided,									
	excellent condition									
N/A	Does not apply									
For those s	paces that require it, does the administration area have						1			
	acoustic privacy?				4			Comments	1.00	4.
1	Very unsatisfactory - No acoustic separations							Admin said sound privacy is adequate.	<u> </u>	
2	Unsatisfactory - Acoustic separations do not perform									
	well									
3	Average - Some acoustic separations function okay, but									
4	portions need updates or renovations Satisfactory - Good acoustic separations									
4 5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply									
	ence rooms easily accessed for public / parent use?			3				Comments	100	
1	Very unsatisfactory - Not accessible for public/parent							Yes, only one provided.	1.00	3.
	use									
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
4	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
5	good size and condition Very Satisfactory - Excellent accessibility, excellent									
0	transparency, generous size, excellent condition									