



Educational Suitability Summary Report

Kocurek Elementary School

Date: 01/28/2021

Score 65% Average

Kocurek Elementary School, serving an enrollment of approximately 550 students, including pre-K through fifth grade, is in south Austin. It was originally built in 1986 (studio addition built in 1998) and consists of approximately 78,700 square feet on 12 acres. The school is known for its signature programs in Certified Academic Language Therapy and Social and Emotional Learning.

Kocurek Elementary has well-configured learning neighborhoods with studios surrounding a common open space, which is used for collaboration and breakout groups. The arrangement of windows to the studios allows for some transparency to supervise students in both the common space and studios. Studios in the main building are connected with a restroom corridor but arranged to avoid sound transmission between studios.

The studios in the addition are connected via a bathroom corridor, but also have two double doors connecting the rooms that allow more sound to transmit between the spaces. This building lacks common spaces for collaboration and breakout areas for students.

The central courtyard space needs maintenance to replace uneven walking surfaces. This area is readily accessible to the learning neighborhoods but is difficult to use with limited seating.

Interview Overview

A meeting was held with Principal Heather Parmalee, Assistant Principal Larry Frier, counselor Angela Vera, administrative assistant Christina Lavalliere and head custodian Norberta Aguilar. The campus is open to renovations but would like to keep the solar panels installed on the roof as well as some painted murals. They noted the areas that need attention and/or updates are the central courtyard, collaboration spaces for community and staff, gym, cafeteria, music room, art room, staff restrooms, and safety upgrades to the playground space.

The central courtyard is a prominent feature of the campus and is well-located for the main building learning neighborhoods. The walkways are uneven in many areas and are not well-connected or developed. There is a set of bleachers in one area that are too tall for younger students. The campus acknowledged use of a conference room as an office. They typically hold meetings in the library and do not have a dedicated conference room for community use. Other support spaces needed are rooms dedicated for speech and dyslexia programs. The campus also requested a change of flooring to the gym. It is thought to be the original flooring and becomes slippery when it becomes slightly wet. The operable partition between the gym and cafeteria is difficult to operate and often comes off the track. The music room is in a typical studio and does not have a dedicated storage room and the art room is in a room that is slightly larger than a typical studio.

The campus also expressed need for a mindfulness room. Typically, the life skills kitchen room is used,

but it is not always available. The campus has received new furniture for the library but studios throughout the campus need updated furniture. They would like better performance spaces with dedicated technology. The current projectors and screens have been donated by a church group that uses the stage. The cafeteria needs additional acoustic panels. The staff expressed a desire to have a maker space for STEM/STEAM programs. The campus also has restroom issues and consistently has

The staff discussed safety and security concerns<mark>.</mark>

Assessment Findings

a staff restroom out of order.

The Educational Suitability Assessment of Kocurek Elementary School earned a 65% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

General Building

Score is unsatisfactory.

The campus has narrow corridors toward the learning neighborhoods that average between 7 to 8 feet in width. The campus does not have any areas arranged to allow after-hours functions without full school access.

Average Categories (51-65%):

Security

Score is average.

Controllability of Systems

Score is average.

Studios have thermostats with individual controls. Most studios have a single switch or two switches for lighting control.

PE and Wellness

Score is average.

The gym is adequate size and adequate condition. The flooring appears to be original and needs to be replaced. The support spaces are not directly connected to the gym.

Visual and Performing Arts

Score is average.

Educational Suitability Summary Report

Kocurek Elementary School

Music room is in a slightly larger space than a typical studio. Storage space is lacking for instruments and equipment. Office space is shared with storage. Art room lacks sufficient storage with only one small closet.

Technology

Score is average.

Overall, the campus has multiple types of technology, but lacks adequate number of power and data outlets in the learning spaces for charging and connecting devices.

Administration Spaces

Score is average.

The conference room is used as an office for a staff member.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

There is separation of vehicular, bus and pedestrian traffic with two distinct drives at the front of the building. The campus has a digital marquee sign that is visible from the street but lacks interior signage.

Outdoor Learning and Activity

Score is satisfactory.

There is a central courtyard that has access to the main building learning studios. The space is ample to have multiple classes but needs maintenance and updates. There are accessibility issues due to the uneven paving of the brick paving walkways.

Environmental Quality

Score is satisfactory.

Most studios have minimal sound transmission between them. The newer building studios have more sound transmission due to the configuration. Most studios have ample access to natural light as do the common/collaboration spaces.

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture is not new but sturdy and in good condition. Studios could use newer and more flexible furniture. The library has new furniture, including tables with wheels for easier reconfiguration.

Academics & Learning

Score is satisfactory.

Learning neighborhoods in main building are configured around a shared common/collaboration space. The campus lacks a dedicated maker space and professional learning centers in the learning neighborhoods.

Food Services

Score is satisfactory.

Educational Suitability Summary Report

Cafeteria is in good condition and has some access to an outdoor area with seating options to have lunch in courtyard area. The support spaces are good size and connected and in good condition.

Media Resources

Score is satisfactory.

Library is central and allows ease of access for students and staff but is not easily accessible to visitors. The library supports collaborative work with the new furniture that is easily reconfigured.

Educational Suitability Summary Report

Kocurek Elementary School

Supporting Photographs



Library outfitted with flexible furniture, including tables with wheels for ease of reconfiguration but does not have a variety of furniture. The library is the space used for most meetings.



Cafeteria stage has two donated projectors that are dated but does not have a central screen for projection. There are some acoustic panels, but more are needed to reduce noise levels.

Educational Suitability Summary Report

Kocurek Elementary School



Shared common/collaboration space arranged with four studios. Spaces are in good condition and provide ample space to add technology and more learning space.



Studios in main building with a good amount of access to natural light. Blinds are old but in working condition. Furniture is in good shape but lacks flexibility and is somewhat cumbersome to reconfigure.

Educational Suitability Summary Report

Kocurek Elementary School



Newer studio addition building with studios that are connected, which allows sound to transmit easily between spaces.



Natural light access to newer studio addition limited to the connected restroom corridor.

Educational Suitability Summary Report

Kocurek Elementary School



Interior courtyard space used for outdoor learning. Space is underdeveloped and needs updates.



Kindergarten wing of building configured with covered area and direct access to a dedicated playground.

Educational Suitability Summary Report

Kocurek Elementary School



Playground space is shaded and equipment in good condition.



02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Kocurek Elementary School	Carlos Cruz and Anacleto Rojas	01.25.21

1	- Exte	erior		1	2	3	4	5	N/A		8.75	77%
		oes the site bedestrian t	e permit desirable separation of vehicular, bus and raffic?					5		Comments	1.00	5.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location									
		2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
		3	Average - Buses, cars, and pedestrians are separate but stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply						l			
			ng easily identified with appropriate signage and wayfinding?			3				Comments	0.25	0.75
		1	Very unsatisfactory - Campus has no signage / wayfinding									
		2	Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not good condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									

02/11/2022 ²

1 - Exter	ior (cont.)	1	2	3	4	5	N/A			
1.3 ls t	he dumpster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	 Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it. 							Dumpsters accessible from a loading dock with stairs and	d no ramp.	
	N/A Does not apply		•	•		-			15.00	
21 Are	loor Learning and Activity e outdoor studios and support spaces appropriately configured per e ed spec?		2	3	4	5	N/A	Comments	15.00	80% 3.00
	1 Very unsatisfactory - No dedicated outdoor studios 2 Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area 4 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area 5 Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area 6 Very satisfactory - Generous size, excellent flexibility, full shade coverage over studio area							Centralized courtyard outdoor space. Needs maintenand	ce and upda	tes to
	e active playgrounds (elementary only) and support spaces				4			Comments	1.00	4.00
	1 Very unsatisfactory - No dedicated active playground 2 Unsatisfactory - Too small, poor condition, no shade provided 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure 4 Satisfactory - Good size, good condition, more than 50% shade coverage over play structure 5 Very satisfactory - Generous size, excellent condition, full shade coverage over play structure N/A Does not apply									

02/11/2022 ³

2	- Outdoor Le	earning and Activity (cont)	1	2	3	4	5	N/A	A		
2		ns and support spaces appropriately configured per the ed Iluation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learr	ning and A	ctivity.
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply				-					
2	2.4 Are the ra ed spec?	in gardens and/or cisterns appropriately configured per the	1						Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected							Monitoring answer, does not affect score for Outdoor Learr	ning and A	ctivity.
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
_	N/A	Does not apply									
2		chool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
	-	chool have nature loop trails? (optional)	1				r –	1	Comments	0.00	0.00
	1	No			_					5.00	0.00
	5	Yes									
2	2.7 Does the s	chool have a learning pond? (optional)					5		Comments	0.00	0.00
	1	No							· · · · · · · · · · · · · · · · · · ·		
	5	Yes									
2	2.8 Does the s	chool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1 5	No Yes									

5 Yes

02/11/2022 4

General l	Building	1	2	3	4	5	N/A		11.25	36
	ior circulation routes wide enough to safely and effectively odate student movement?			3				Comments	0.50	1.5
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide						-			
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
	munity use areas arranged so that the school can allow night s without full school access?	1						Comments	0.75	c
1	Very unsatisfactory - Cafeteria, gym, and library cannot l accessed after hours	be							ł	
2	Unsatisfactory - Only one of the public spaces (Cafeteria Gym and Library) can be accessed from parking and secured after hours									
3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building bu not individually	ıt								
5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campu for night/evening use with their own entrance	s								
N/A	Does not apply							<u></u>		
.3 Is there school f	a community room that is a dedicated meeting space outside a unction?	of 1						Comments	0.75	(
1	Very unsatisfactory - No dedicated community room									
2	Unsatisfactory - Community room but within school function, no access after school hours									
3	Average - Community room, moderate size, but need some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets needs /functions well									
5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
N/A	Does not apply									
	general appearance of the school convey pride for the and community?				4			Comments	0.25	
1	Very unsatisfactory - General appearance is poor									
2	Unsatisfactory - General appearance is aged but ok									
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in campu and student works	S								
5	Very satisfactory - General appearance shows pride in									
5	campus and student works and is welcoming to the community									

02/11/2022 5

4 - Security		1	2	3	4	5	N/A		16.25	
4.1 Does the fo	cility have key card access at all major entries?							Comments	0.25	
1 2 3 4 5 N/A	Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries Average - 1/2 of major entries Satisfactory - 3/4 of major entries Very satisfactory - All of major entries Does not apply									
· · · · · ·	Jate is site lighting and security for the campus overall?							Comments	1.00	
1 2 3 4 5	Very unsatisfactory - No exterior lighting, no secure perimeter Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								1.00	
	Does not apply office located at the school entry and configured with a ibule to the main corridor?			[Comments	1.00	
1 2 3 4 5 N/A	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors Average - Office close to entry, views of front door, but no secure vestibule Satisfactory - Office is well-located with a secure vestibule, but needs updates Very satisfactory - Office well-located with secure vestibule and all appropriate security features Does not apply									
	bugh interior transparency for faculty to passively supervise d their activities who are not in studios?			Т	4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the school Very satisfactory - Excellent transparency throughout the school Does not apply	<u> </u>			1			Sidelite adequate	1	

02/11/2022 *

5 - En	vironmen	atal Quality	1	2	3	4	5	N/A		25.00	72%
5.1	How are ac	coustics in studios in general?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor		1	I	1	1	1	Ok acoustics		
	2	Unsatisfactory - Audible sound from adjacent studio/corridor									
	3	Average - Slight sound from outside room									
	4	Satisfactory - Walls to deck insulated only white noise from mechanical system									
	5	Very satisfactory - Able to hear quiet speaking from across the room									
	N/A	Does not apply									
5.2	ls the studio	o artificial lighting adequate quality?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC			•	1					
	2	Unsatisfactory - 10-19 FC or serious glare									
	3	Average- 20-29 FC minor glare									
	4	Satisfactory - 30-39 FC and no glare									
	5	Very satisfactory - 40+ FC and no glare									
	N/A	Does not apply									
5.3	ls there acc	ess to natural light in studios?				4			Comments	1.00	4.0
	1	Very unsatisfactory - No learning spaces have natural light									
	2	Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light									
	3	Average - 26-50% of learning spaces have natural light									
	4	Satisfactory - 51-75% of learning spaces have natural light									
	5	Very satisfactory - 76-100% of learning spaces have natural light									
	N/A	Does not apply									
5.4	ls there acc	ess to outside views from learning spaces?				4			Comments	1.00	4.0
	1	Very unsatisfactory - No learning spaces have views					1			1	
	2	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out									
	3	Average - 26-50% of learning spaces have views									
	4	Satisfactory - 51-75% of learning spaces have views									
	5	Very satisfactory - 76-100% of learning spaces have views									
	N/A	Does not apply									
	11/1										

02/11/2022 7

5	- Enviro	onment	al Quality (cont.)	1	2	3	4	5	N/A			
	5.5 Doe	es the bui	ilding have odor or pest problems?		2					Comments	1.00	2.00
		1 2	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors							Ants and rodents in several spaces on campus		
		2	Average - Limited evidence of pests of odors									
		4	Satisfactory - No evidence of pests / odors, school									
		-	cleanliness in good condition									
		5	Very Satisfactory - No evidence, school cleanliness in									
			excellent condition									
		N/A	Does not apply									
e	- Contro	ollabili	ty of Systems	1	2	3	4	5	N/A		12.50	60%
	6.1 Doe	es the stu	dio thermostat allow for individual control?					5		Comments	0.50	2.50
		1	No						·			
		5	Yes									
	6.2 Are	shades p	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
		1	Very unsatisfactory - No, windows are covered with boards/paper									
		2	Unsatisfactory - No, windows have no light control									
		3	Average - Yes, but poor condition blinds									
		4	Satisfactory - Yes, blinds									
		5	Very satisfactory - Blackout shades									
		N/A	Does not apply		-							
	6.3 Who	at is the o	quality of lighting controls in the studios?	1						Comments	1.00	1.00
		1	Very unsatisfactory - Single switch only per room							2 switch system		
		2	Unsatisfactory - Alternating rows switch off									
		3	Average - Alternating lamps in single fixtures switch off									
		4	Satisfactory - Tri level switching									
		5	Very satisfactory - Dimmable									
		N/A	Does not apply									

02/11/2022 8

7 - Furn	niture, Fi	ctures & Equipment	1	2	3	4	5	N/A		18.75	69 %
7.1 W	/hat is the	current condition of the furniture?				4			Comments	0.75	3.00
	1	Very unsatisfactory - Damaged or broken, non-functioning									
	2	Unsatisfactory - Torn/ bent/ wrong size									
	3	Average - Scratched/dented/marked									
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
	N/A	Does not apply	·		1	1		1			
7.2 ^{Ar} sc	re a variet <u>:</u> :hool - lear	y of furniture types being accommodated throughout the ning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Same furniture used in all spaces									
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply									
	ow well do pace?	es furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy							Except cafeteria		
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple									
	5	configurations of space Very satisfactory - Furniture is flexible for multiple									
	U	configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4 ls	the furnitu	re ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

Perkins&Will

02/11/2022 °

Waste		1	2	3	3	4	5	N/A	5.00	809
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?					4			Comments 0.50	2.0
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.		•					•	A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
2 3	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.								No bins in studios and cafeteria. Staff separate in cafeteria.	
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply									
each: greer	afeteria (or wherever meals are served) have at least one of n compost bin, blue recycle bin, and landfill bin? Are the bins early with bilingual and/or image sorting?					4			Comments 0.50	2.0
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.					1			A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4	Satisfactory- There are several waste stations as described above									
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
N/A	Does not apply								<u> </u>	

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria


Academics - Elementary School

School Name	Walk Attendees:	Date:
Kocurek Elementary	Carlos Cruz and Anacleto Rojas	1.25.21


8.1 Are studios appropriately configured per the ed spec? 4 4 Comments 1.0 1 Very unsatisfactory - Too small, no flexibility, disconnected	00 4.0
2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected	
methods, limited flexibility, disconnected	
2 Noutral Adaguate size multiple grage for different	
teaching methods, adequate flexibility, limited	
transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.	
4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces	
5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces	
N/A Does not apply	
B.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 4 Comments	00 4.0
1 Very unsatisfactory - None provided Connected restrooms. Dedicated storage and built-in.	
2 Unsatisfactory - Too small, disconnected, poor condition	
3 Neutral - Adequate size, average condition, needs updates or renovations to function well	
4 Satisfactory - Good size, connected, good condition	
5 Very Satisfactory - Generous size, connected, excellent condition	
N/A Does not apply	

02/11/2022 ²

8	3 - Ao	cademics &	& Learning (cont.)	1	2	3	4	5	N	/A			
	8.3	Do studios I spec?	nave appropriate support spaces such as storage per the ed				4				Comments	1.00	4.00
		1	Very unsatisfactory - None provided				•			E	Built-in cabinets and shared storage rooms.		
		2	Unsatisfactory - Too small, disconnected, poor condition										
		3	Neutral - Adequate size, average condition, needs updates or renovations to function well										
		4	Satisfactory - Good size, connected, good condition										
		5	Very Satisfactory - Generous size, connected, excellent condition										
		N/A	Does not apply										
	8.4	Do typical l collaboratio	earning neighborhoods have small group rooms and open on space?				4				Comments	1.00	4.00
		1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided							1	Needs updated furniture and better transparency		
		2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy										
		3	Average - Adequate size, adequate condition, needs some renovations or updates to function well										
		4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy										
		5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy										
		N/A	Does not apply										
	8.5		l studios large enough to support project-based learning e teaching modalities?				4				Comments	1.00	4.00
		1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning										
		2	Unsatisfactory - Undersized, decentralized resources, limited flexibility										
		3	Average - Adequate size, needs some renovations or updates to function well										
		4	Satisfactory - Good size, centralized resources, good flexibility										
		5	Very Satisfactory - Generous size, centralized project resources, excellent flexibility										
		N/A	Does not apply							_			



8 - Aca	demics 8	& Learning (cont.)	1	2	3	4	5	N/A	A		
	re Maker S d spec?	Spaces and support spaces appropriately configured per the	1						Comments	1.00	1.0
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									
8.7 ls	there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.0
	1	Very unsatisfactory - No dedicated space for Professional Learning Center				•					
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition, connected									
	N/A	Does not apply									
8.8 ls	there a de	edicated science room and support space?	1						Comments	0.00	0.0
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
		dequate places to display the evidence and artifacts of oth 2D and 3D)?				4			Comments	1.00	4.0
	1	Very unsatisfactory - No dedicated space					•		Plenty of both		
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									



		Learning (cont.)	1	2	3	4	5	N/A	A		
8.10	Does the bu to collabora	ilding provide adequate opportunities for students/teachers te in varying group sizes?			3				Comments	1.00	3.0
	1	Very unsatisfactory - No space to support collaboration in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.11	Does the bu	ilding provide opportunities for informal interaction?				4			Comments	1.00	4.0
	1	Very unsatisfactory - No space							Clusters share outside spaces that have potential for in	nteraction.	
	2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
8.12		rrning neighborhood / building provide adequate es for students to work independently?			3				Comments	1.00	3.0
	1	Very unsatisfactory - No breakout rooms/small study spaces			<u> </u>	<u> </u>			Common area is the only space. Used as computer lab		
	2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									

02/11/2022 5

8.13 Are Special Education spaces appropriately configured per the ed spec? 4 Comments	1.00	4.00
1 Very unsatisfactory - Too small, no flexibility, disconnected Dedicated ADA restroom, shower, changing connected.	g table but not directly	
2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected		
3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.		
4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces		
5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces		
N/A Does not apply		
8.14 Are Special Education support spaces, such as storage, space for washer/dryer, appropriately configured per the ed spec? 4 Comments	1.00	4.00
1 Very unsatisfactory - None provided Dedicated special education room.		
2 Unsatisfactory - Too small, disconnected, poor condition		
3 Neutral - Adequate size, average condition, needs updates or renovations to function well		
4 Satisfactory - Good size, connected, good condition		
5 Very Satisfactory - Generous size, connected, excellent condition		
N/A Does not apply		
8.15 Are Accessible restrooms and changing rooms readily available to the Special Education spaces? 5 Comments	1.00	5.00
1 No		
5 Yes		

02/11/2022 °


7 - visua	l and F	Performing Arts	1	2	3	4	5	N/A	N	15.00	60%
01	music s ed spec	paces and the cafeteria stage appropriately configured per ?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Small stage area		
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	music a the ed s	nd performance storage spaces appropriately configured spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided		•					Dedicated music room space slightly larger than a typic	al studio.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
9.3 Are		arts spaces and storage appropriately configured per the ed			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Set up in space slightly larger than a typical studio.		
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									

02/11/2022 7


) - PE and We	llness	1	2	3	4	5	N/A	A	10.00	60
0.1 Does the co program sp	ampus meet the ed spec standard for physical education baces?			3				Comments	1.00	3.0
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs some									
	renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply	r –	r –	1	1	r –	T		1	
0.2 Are the phy the ed spe				3				Comments	1.00	3.0
1	Very unsatisfactory - None provided							Storage room is adequately sized per Ed Spec. Have	outdoor storage	e but
2	Unsatisfactory - Too small, disconnected, poor condition							needs update.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
- Food Servi	es	1	2	3	4	5	N/A	A	10.00	80
1.1 Is the Dinin	g Commons appropriately configured per the ed spec?				4			Comments	1.00	4.0
1	Very unsatisfactory - Too small, missing program spaces							Adequately sized. Better acoustics and connection to	outdoors. Some	е
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation							seating set up in courtyard to have lunch.		
3	Average - Adequate size and condition, needs updates or renovations to function well									
4	Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A	Does not apply									
1.2 Are the Foo ed spec?	od Services support spaces appropriately configured per the				4			Comments	1.00	4.0
1	Very unsatisfactory - None provided							Adequately sized kitchen / serving lines in good cond	ition.	
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
	,									
5	Very Satisfactory - Generous size, connected, excellent condition									

02/11/2022 *

12 - Media Res		1	2	3	4	5	N	/A		30.00	70
	ary/Media Center easily accessible for the occupants and the school?			3					Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition								Center of building. Difficult without securing rest of scho	pol.	
	Does not apply does the Library/Media Center support quiet study?			3		Т			Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply									1.00	3.0
	does the Library/Media Center support social interaction?			3			Т	Т	Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply		1	1	1	1			Open concept		
	does the Library/Media Center support collaborative work in ups (4-8 students)?				4				Comments	1.00	4.0
1 2 3 4 5	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition		<u>.</u>	<u>.</u>							



12 - Media Resources -		1	2	3	4	5	N/A	N		
12.5 How well does the Li larger groups (10-25	brary/Media Center support collaborative work in)?				4			Comments	1.00	4.0
	nsatisfactory - No gathering areas							Movable furniture		
	factory - Too small, one common space, limited 1, poor condition									
	e - Adequate size, one common space, needs s or renovations to function well									
	ctory - Good size, multiple common spaces with 1, good condition									
	itisfactory - Generous size, multiple commons with seating, excellent condition									
N/A Does n	ot apply									
12.6 How well does the Li	brary/Media Center support technology?				4			Comments	1.00	4.0
1 Very ur	nsatisfactory - No vis comm tools							Projector screen and portable screen		
2 Unsatis insuffic	factory - Outdated, poorly functioning, or ient									
	Mix of old and new whiteboards/projectors/etc.									
most sp	ctory - Projectors, marker boards, smart boards in baces - good condition									
boards	itisfactory - Projectors, marker boards, smart in most spaces - new condition									
N/A Does no	ot apply									
13 - Technology		1	2	3	4	5	N/A	<u> </u>	20.00	55
13.1 How well equipped of	are the facilities with instructional technology?				4			Comments	1.00	4.0
	nsatisfactory - Limited to no technology present in cional spaces									
	factory - One type of technology present									
poor co	e - Multiple types of technology, smart boards, ondition, limited to only certain areas of school									
good c	ctory - Multiple types of technology, smart boards, ondition.									
	itisfactory - Multiple types of technology, smart , excellent condition									
	ot apply	1	1		1	-	1			
13.2 Is there an adequate spaces?	e number of power and data outlets in learning		2					Comments	1.00	2.0
	nsatisfactory - Outlet configuration does not t digital devices throughout school (1 per wall)									
	factory - Outlet configuration support digital s only in certain areas of school (2 per wall)									
	e - Outlet configuration support digital devices but bugh capacity throughout school (3 per wall)									
4 Satisfa	ctory - Outlet configuration support digital devices lequate coverage and capacity throughout school									
	itisfactory - Excellent outlet configuration to t digital devices throughout school (>3 per wall)									
N/A Does n	ot apply							•		



1 Very unsatisfactory - No centralized charging location 2 Unsatisfactory - Centralized charging location, but inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 1 Very unsatisfactory - AV not present in one or more space No overhead projector. No outlets on stage for devices. 2 Unsatisfactory - Geor size, good condition Average - Adequately sized / poor condition 3 Average - Adequate condition No overhead projector. No outlets on stage for devices. 4 Satisfactory - Geor size, good condition Average - Adequately sized / poor condition 3 Average - Adequate condition Average - Adequate condition 4 Satisfactory - Geore size, good condition Average - Adequately sized , poor condition 5 Very Satisfactory - Generous sized, excellent condition Average - Adequately condition N/A Does not apply Comments Comments <th>1</th> <th>3 - Technolog</th> <th>y (cont.)</th> <th>1</th> <th>2</th> <th>3</th> <th>4</th> <th>5</th> <th>N/A</th> <th>N</th> <th></th> <th></th>	1	3 - Technolog	y (cont.)	1	2	3	4	5	N/A	N		
2 Unsatisfactory - Centrolized charging location, but inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower but not adequately sized for number of devices 5 Very Satisfactory - Charging cart or tower located centrolized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 1 Very unsatisfactory - AV not present in one or more space 2 Unsatisfactory - AV undersized for room, poor condition 3 Average - Adequately sized / poor condition OR AV undersized / adequate condition 5 Very Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 6 1 Very unsatisfactory - Good size, good condition 6 4 1 Very unsatisfactory - Good size, good condition 7 4 1 Very unsatisfactory - No digital media present in reception area 4 2 Unsatisfactory - No digital media present in reception area 4 3 Average - Adequately sized / poor condition 8 0.00 3 Average - Adequately sized / poor condition 8 4 1 Very unsatisfactory - No digital		13.3 Are there	adequate charging locations for devices?		2					Comments	1.00	2.00
inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower not centralized centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 1 Very unsatisfactory - AV not present in one or more space 2 Unsatisfactory - AV undersized for room, poor condition 3 Average - Adequately sized / poor condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 4 Soutisfactory - No digital media present in reception area 2 Unsatisfactory - No digital media present in reception area 3 Average - Adequately sized / poor condition OR 3 Average - Adequately sized / poor condition OR 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition 3 Average - Adequately sized / poor condition OR and adequate condition		1	Very unsatisfactory - No centralized charging location								• · · · · ·	
for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower not centralized 5 N/A Does not apply 3 Comments 1.00 3.00 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 No overhead projector. No outlets on stage for devices. 1.00 3.00 2 Unsatisfactory - AV undersized for room, poor condition No overhead projector. No outlets on stage for devices. No overhead projector. No outlets on stage for devices. 1.00 3.00 3 Average - Adequate AV poor condition OR AV undersized / oper condition OR AV undersized / oper condition OR AV undersized / oper condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 6 0.00 0.00 13.5 Is there digital media signage at the reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area? 4 Comments 0.00 0.00 <t< td=""><td></td><td>2</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>		2										
5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 Comments 1.00 3.00 1 Very unsatisfactory - AV not present in one or more space No overhead projector. No outlets on stage for devices. No overhead projector. No outlets on stage for devices. 2 Unsatisfactory - Good size, good condition A verage - Adequately sized / poor condition No overhead projector. No outlets on stage for devices. 4 Satisfactory - Generous sized, excellent condition Very satisfactory - Generous sized, excellent condition 4 Comments 0.00 0.00 13.5 Is there digital media signage at the reception area? 4 4 Comments 0.00 0.00 13.5 Unsatisfactory - Undersized, poor condition 4 Average - Adequately sized, poor condition 0.00 0.00 13.5 Is there digital media signage at the reception area? 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized, poor condition 4 Comments 0.00 0.00 0.00 0.00		3										
centralized location. Excellent condition N/A Does not apply 3 Comments 1.00 3.00 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 3 Comments 1.00 3.00 1 Very unsatisfactory - AV not present in one or more space No overhead projector. No outlets on stage for devices. No overhead projector. No outlets on stage for devices. 3.00 2 Unsatisfactory - AV undersized for room, poor condition AVerage - Adequately sized / poor condition OR AV undersized / adequate condition No overhead projector. No outlets on stage for devices. Very Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition AVerage - Adequately sized / adequate condition 4 Comments 0.00 0.00 13.5 Is there digital media signage at the reception area? 4 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor co		4	Satisfactory - Charging cart or tower not centralized									
13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 Comments 1.00 3.00 1 Very unsatisfactory - AV not present in one or more space No overhead projector. No outlets on stage for devices. No overhead projector. No outlets on stage for devices. 2 Unsatisfactory - AV undersized for room, poor condition No overhead projector. No outlets on stage for devices. 3 Average - Adequately sized / poor condition OR AV undersized / adequate condition No 4 Satisfactory - Generous sized, excellent condition No N/A Does not apply 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area 4 Comments 0.00 0.00 1 Very unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition 4 Comments 0.00 0.00		5										
1 Very unsatisfactory - AV not present in one or more space No overhead projector. No outlets on stage for devices. 2 Unsatisfactory - AV undersized for room, poor condition No overhead projector. No outlets on stage for devices. 3 Average - Adequately sized / poor condition OR AV undersized / adequate condition No overhead projector. No outlets on stage for devices. 4 Satisfactory - Good size, good condition Satisfactory - Generous sized, excellent condition N/A Does not apply Very unsatisfactory - No digital media present in reception area? 1 Very unsatisfactory - No digital media present in reception area 4 1 Very unsatisfactory - No digital media present in reception area 0.00 2 Unsatisfactory - Undersized, poor condition OR undersized / adequately sized / poor condition OR undersized / adequate condition		N/A	Does not apply									
2 Unsatisfactory - AV undersized for room, poor condition 3 Average - Adequately sized / poor condition OR AV undersized / adequate condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous sized, excellent condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 1 Very unsatisfactory - No digital media present in reception area 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition		13.4 Is there ac	equate AV for presentations spaces – cafeteria and gym?			3				Comments	1.00	3.00
3 Average - Adequately sized / poor condition OR AV undersized / adequate condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous sized, excellent condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 4 1 Very unsatisfactory - No digital media present in reception area 2 Unsatisfactory - Undersized, poor condition OR undersized / poor condition OR undersized / adequate condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition		1	Very unsatisfactory - AV not present in one or more space							No overhead projector. No outlets on stage for device	s.	
3 Average - Adequately sized / poor condition OR AV undersized / adequate condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous sized, excellent condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 4 1 Very unsatisfactory - No digital media present in reception area 2 Unsatisfactory - No digital media present in reception area 3 Average - Adequately sized / poor condition OR undersized / adequate condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition												
undersized / adequate condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous sized, excellent condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 1 Very unsatisfactory - No digital media present in reception area 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition												
5 Very Satisfactory - Generous sized, excellent condition N/A Does not apply 13.5 Is there digital media signage at the reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition 0.00 0.00		3										
N/A Does not apply 13.5 Is there digital media signage at the reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area? 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition 0.00 0.00		4	Satisfactory - Good size, good condition									
13.5 Is there digital media signage at the reception area? 4 Comments 0.00 0.00 1 Very unsatisfactory - No digital media present in reception area 4 Comments 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition 0.00 0.00		5	Very Satisfactory - Generous sized, excellent condition									
1 Very unsatisfactory - No digital media present in reception area 0.00 0.00 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition	_	N/A	Does not apply								•	
area 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition		13.5 Is there die	jital media signage at the reception area?				4			Comments	0.00	0.00
3 Average - Adequately sized / poor condition OR undersized / adequate condition		1									•	
undersized / adequate condition		2	Unsatisfactory - Undersized, poor condition									
4 Satisfactory - Media signage present, good sized, good		3										
condition		4										
5 Very Satisfactory - Generously sized, excellent condition		5	Very Satisfactory - Generously sized, excellent condition									
N/A Does not apply		N/A	Does not apply									

02/11/2022 "

		tion Spaces	 2	3	4	5	N/A		20.00	55
	ls there a re visitors?	ception area that functions as a security checkpoint for all						Comments	1.00	
	1	Very unsatisfactory - No security checkpoint						No secure vestibule.	·	
	2	Unsatisfactory - Checkpoint is too small, poor condition								
	3	Average - Needs updates or renovations to function well								
	4	Satisfactory - Good size, good condition								
	5	Very Satisfactory - Generous size, excellent condition								
	N/A	Does not apply								
14.2	Does the ad	ministration area feel welcoming?			4			Comments	1.00	4.
	1	Very unsatisfactory - No welcome space	 	1						
	2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition								
	3	Average - Adequate size and layout, needs updates or renovations to feel welcoming								
	4	Satisfactory - Good size and layout, good lighting and transparency, informal seating provided								
	5	Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition								
	N/A	Does not apply								
14.3	For those sp adequate a	aces that require it, does the administration area have coustic privacy?	2					Comments	1.00	2
	1	Very unsatisfactory - No acoustic separations		1		1				
	2	Unsatisfactory - Acoustic separations do not perform well								
	3	Average - Some acoustic separations function okay, but portions need updates or renovations								
	4	Satisfactory - Good acoustic separations								
	5	Very Satisfactory - Excellent acoustic separations								
	N/A	Does not apply								
4.4	Are confere	nce rooms easily accessed for public / parent use?	2					Comments	1.00	2
	1	Very unsatisfactory - Not accessible for public/parent use						Current conference room used as an office.		
	2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find								
	3	Average - Adequate accessibility, needs updates or renovations to function well								
	4	Satisfactory - Good accessibility, good transparency, good size and condition								
	5	Very Satisfactory - Excellent accessibility, excellent								
		transparency, generous size, excellent condition								