

Educational Suitability Summary Report

Linder Elementary School

Date: 12/22/2020 Score 51% Average

Linder Elementary School serves an enrollment of approximately 400 students in south Austin. It was built in 1972, with a music building addition in 2008, and consists of approximately 70,000 square feet on 10 acres. The facility exhibits an overall average condition for educational suitability. Deficiencies involve the age and condition of the main studio spaces, cafeteria and technology as well as overall environmental quality. The school lacks specialty spaces such as a maker space and outdoor learning studios. Other deficiencies include accessibility to the school and ADA-compliant restrooms in some spaces. Accessibility will be covered fully in the facility condition assessment report. It is mentioned here because inaccessible spaces and restrooms contribute to an inequitable learning environment.

The main building is a single level, and the studio wings are connected by a central library and administration. The cafeteria and gym can be accessed after-hours and closed off from the rest of the school. The general appearance of the building is dated, and the interior feels relatively dark due to small openings to the outside. Studio spaces are dated, are not adequate in size, and there is no transparency to the corridors or other learning spaces. Some studios have operable partitions, which are aged, do not function well and create acoustic issues. Restrooms provided in the studios are not accessible. Storage space in the studios is inadequate. All studios lack a variety of flexible furniture. All studios have small windows and provide limited natural light and views to the outside. Corridors are double-loaded and opaque. Small windows in doors provide limited transparency to the learning spaces.

. There is no conference room in the administration space, and no designated community room is provided. The art room lacks adequate storage, and the sinks are not accessible. The cafeteria stage is small and lacks storage. There is only one type of seating provided in the cafeteria. The library is on the smaller side, does not have collaboration spaces, and its technological resources are outdated. Outside, small tables with no shade are far from the main building.

Interview Overview

The interview was conducted with Principal Melissa Rodriguez, counselor Becky Salinas, librarian Melissa Atterberry, four teachers and a community member. The educational suitability portion of the interview focused on inadequate and unsuitable spaces, the lack of collaborative spaces, and accessibility and safety concerns.

Programs not in suitable spaces include CIS, ACE, music and special education. There are a number of special education students and providing a suitable space with proper resources and infrastructure is important. Some programs are conducted in portables. Due to Brooke Elementary School's closure,

Educational Suitability Summary Report

Linder Elementary School

120 students were moved to Linder, which has resulted in a shortage of space. Music is in a repurposed typical studio and does not have suitable infrastructure or adequate space to function well. The school needs a bigger gym to accommodate required classes and practice. The principal expressed that they would like to have a designated science space and a flexible maker space for students to co-create and collaborate. They wish to have more collaboration and breakout spaces for small group classes to interact and learn. The ability to join studios and create more flexible environments for studying is preferable. The foldable partitions and studio furniture are outdated and do not function properly.

The principal mentioned that the library is very small, and all staff cannot fit into the library for meetings. There is not enough space for students to stretch out and read. The furniture in the library is large and bulky and needs to be more appropriate in size for the students. There are no exterior windows or office space. The library needs a separate entrance and exterior doors for easy community access or after-hours school events. Flexibility and community building through the library is important for the school. A place to display student work is also desired.

The school would like to keep the cafeteria and gym connection through the operable wall. The cafeteria needs a projector screen and stage updates. The school desires a counselor space for Social and Emotional Learning (SEL). They would like to have a new track and a centralized courtyard space to bring more daylight and flexibility to the building. The principal expressed desire to have more outdoor activity spaces to create a community focal point.



Other areas of concern

are the overall accessibility in the building and poor drainage, which causes damage to the sidewalks. The principal also highlighted the need for the teacher parking lot to be repayed and a sidewalk that is accessible.

If construction or renovation happens, the school would like to keep large outdoor play spaces and the blacktop, the open concept of the administration area, and the murals inside the building. They want to keep the flag that was once flown at the Texas Capitol building on display in the administration area.

Assessment Findings

The Educational Suitability Assessment of Linder Elementary School earned a 51% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Academics & Learning

Score is very unsatisfactory.

Studios are small and have limited flexibility. There is no transparency to corridors or other learning

Educational Suitability Summary Report

Linder Elementary School

spaces. Operable partitions in the studios are very old and do not function well. Special education spaces are not adequate. Special education studios are in typical studios and there are no accessible support spaces, such as restrooms and changing tables.

Unsatisfactory Categories (36-50%):

General Building

Score is unsatisfactory.

Cafeteria and gym can be accessed after-hours and closed off from rest of the school. There is a side entrance off the gym that can be used for this purpose. Overall, the building is showing its age, and many finishes are in unsatisfactory shape.

Environmental Quality

Score is unsatisfactory.

There are small windows in the studios and other learning spaces. Natural light is poor overall. Old foldable partitions do not seem to have good acoustics and do not function well.

Visual and Performing Arts

Score is unsatisfactory.

Stage in cafeteria is small and lacking storage. Sinks in art rooms are not accessible due to clearance and reach ranges requirements for at least one sink within the room. A kiln room is provided, and the art room has close access to outdoor space. Music is in a repurposed typical studio and does not have suitable infrastructure or adequate space to function well.

Food Services

Score is unsatisfactory.

There is a lack of furniture variety in the dining area. Outdoor seating option is away from cafeteria. Storage is limited and kitchen is small overall.

Technology

Score is unsatisfactory.

New surface-mounted power appears to have been added in some areas. Without this addition, outlets would be very limited. Technology resources are below average overall.

Media Resources

Score is unsatisfactory.

No quiet study rooms are available in the library, and the furniture is not flexible. Small reading space can limit number of students occupying the library at the same time. There are no markerboards, but there is a projection screen and projector for teaching.

Administration Spaces

Score is unsatisfactory.

, but decent visibility to corridors and main entry doors. Very small waiting area and does not seem welcoming overall.

Average Categories (51-65%):

Educational Suitability Summary Report

Linder Elementary School

Outdoor Learning and Activity

Score is average.

There is a small grouping of tables outside with no shade cover and far from the building. No rain gardens present on site. Playground is in good condition and generously sized but does not have shade.

Security

Score is average.

Furniture, Fixtures, Equipment

Score is average.

Furniture is aged and mismatched. No flexibility or variety of furniture available in studios and throughout major spaces. Studio furniture is composed of tables with loose chairs.

PE and Wellness

Score is average.

Flooring in gym seems new. The gym wall paint is chipping and peeling on the walls. There is a movable partition that opens to the cafeteria.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

Site allows for separation of buses, cars and pedestrians, but it is small with vehicle stack space. There is a digital marquee sign at the road and adequate signage on the building. The dumpsters (trash, recycling, compost) are present but were relocated due to construction during the assessment walk.

Controllability of Systems

Score is satisfactory.

Controllability of the systems is adequate. Blinds are provided in all learning spaces. To control the lights, some rooms have one switch; others have alternate fixture switching.



Library is undersized with limited space for larger groups and no private study spaces. Needs updates to function well.




Gym is connected to the cafeteria with an operable partition. The floor appears to be new and is in excellent condition, but paint on walls is chipping or peeling in many places.




Cafeteria has only one option for seating and is slightly undersized with limited circulation space.



Corridors are narrow and maze-like, and lack of wayfinding makes it difficult to navigate.



About half of the studios have aged operable partitions that may not perform well acoustically and are not always in functioning condition.



Outdated chalkboards are not used for instruction and limit flexibility of teaching in studios.



Large outdoor court/play pad with a large canopy is in excellent condition.



New chicken coop and fencing near small outdoor learning space.



Campus garden spaces have close access to water and are near other outdoor activity and learning features.



Many studios need more storage space and have a mix of old and new furniture.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Linder Elementary School	Emilie Ogburn and Vish Panchal	12.22.2020

1 - E:	xterior		1	2	3	4	5	N/A		8.75	71%
1.1	Does the site pedestrian t	e permit desirable separation of vehicular, bus and raffic?				4			Comments	1.00	4.00
	1 2 3	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small							Separate but small with limited stacking		
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply									
1.2	ls the buildir wayfinding?	ng easily identified with appropriate signage and community					5		Comments	0.25	1.25
	1	Very unsatisfactory - Campus has no signage / wayfinding							Digital marquee sign at road and signage on building		
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

1 - E	xterior (con	t.)	_1	2	3	4	5	N/A	·		
1.3	Is the dump	ster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	1 2	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to	•	•	•		•		Construction was happening at front of site at the time dumpsters appear to have been shifted to accommode machinery.		
	-	dumpster							indefinitery.		
	3	Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.									
	4	Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
	5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0	Outdoor Lea	ırning and Activity	1	2	3	4	5	N/A		15.00	60%
2.1	Are outdoor the ed spec	studios and support spaces appropriately configured per ?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated outdoor studios							Small groupings of tables outside with no shade cover	and far from bui	ilding
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2		laygrounds (elementary only) and support spaces per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated active playground							Play structures are in good shape but not shaded. Ther	e is a nice shade)
	2	Unsatisfactory - Too small, poor condition, no shade provided							canopy over the play court.		
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - C	utdoor Led	rning and Activity (cont)	_1	2	3	4	5	N/A	4		
2.3		s and support spaces appropriately configured per the ed uation on infrastructure not condition of plants)				4			Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor I	earnina and A	ctivity.
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain	gardens and/or cisterns appropriately configured per the	1						Comments		
2.4	ed spec?		'						Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor I	earning and A	ctivity.
	2	Unsatisfactory - Too small, poor condition, not functioning, disconnected								3	,,,
	3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
	N/A	Does not apply									
2.5	Does the sc	nool have animal husbandry? (optional)					5		Comments	0.00	0.00
	1	No									
0.1	5	Yes	-					,			
2.6	Does the sci	nool have nature loop trails? (optional)							Comments	0.00	0.00
	1 5	No Yes									
27		nool have a learning pond? (optional)	1					Т	Comments	0.00	0.00
2.7	1	No							Comments	0.00	0.00
	5	Yes									
2.8	Does the sc	nool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1	No					_		•		
	5	Yes									

3 - 0	eneral Bui		1	2	3	4	5	N/A		11.25	49%
3.1		circulation routes wide enough to safely and effectively ate student movement?				4			Comments	0.50	2.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Vary in width.		
	0	wide									
	2 3	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
		Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply				_					
3.2	functions w	nity use areas arranged so that the school can allow night thout full school access?			3				Comments	0.75	2.25
	1	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							Cafeteria and gym could be accessed after-hours and corridor; not a main entrance that would need to be us		side of
	2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours							gym.		
	3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
	N/A	Does not apply									
3.3	Is there a co	mmunity room that is a dedicated meeting space outside of ion?	1						Comments	0.75	0.75
	1	Very unsatisfactory - No dedicated community room									
	2	Unsatisfactory - Community room but within school function, no access after school hours									
	3	Average - Community room, moderate size, but need some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
	N/A	Does not apply									
3.4		neral appearance of the school convey pride for the d community?		2					Comments	0.25	0.50
	1	Very unsatisfactory - General appearance is poor		•	•				The school appearance and finishes feel dated. The lac	k of daylight in	ito
	2	Unsatisfactory - General appearance is aged but ok							corridors and teaching spaces makes the school feel un	welcoming.	
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in campus and student works									
	5	Very Unsatisfactory - General appearance shows pride in campus and student works and is welcoming to the community									
	N/A	Does not apply									

	4 - Security		1 2	3 4	4 5 N	N/A		16.25	
	4.1 Does the	facility have key card access at all major entries?					Comments	0.25	
,	1 2 3 4 5 N/A	Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries Average - 1/2 of major entries Satisfactory - 3/4 of major entries Very satisfactory - All of major entries Does not apply	,						
	4.2 How adea	quate is site lighting and security for the campus overall?					Comments	1.00	
,	1	Very unsatisfactory - No exterior lighting, no secure perimeter	')
	2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal				ľ			
	3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate							
	4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates							
	5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure							
	N/A	Does not apply				_			
		n office located at the school entry and configured with a stibule to the main corridor?					Comments	1.00	
	1	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised							
	2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors							
	3	Average - Office close to entry, views of front door, but no secure vestibule							
	4	Satisfactory - Office is well-located with a secure vestibule, but needs updates							
	5	Very satisfactory - Office well-located with secure vestibule and all appropriate security features							
	N/A	Does not apply							
		nough interior transparency for faculty to passively supervise and their activities who are not in studios?	1				Comments	1.00	1.00
	1	Very unsatisfactory - No transparency of walls					Only small lite in doors		
	2	Unsatisfactory - Limited transparency in certain locations							
	3	Average - Good transparency in certain locations but inadequate or missing in other locations of school							
	4	Satisfactory - Adequate transparency throughout the school							
	5	Very satisfactory - Excellent transparency throughout the school							
	N/A	Does not apply							

Ę	5 - Environmen	tal Quality	1	2	3	4	5	N/A	A	25.00	44%
	5.1 How are ac	oustics in studios in general?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Studio to corridors seems okay, 50/50 split of studios w partition that does not seem to have good acoustics. O pass-through to restrooms.		
Γ	,	o artificial lighting adequate quality?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
	5.3 Is there acco	ess to natural light in studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No learning spaces have natural light							Very few, very small windows throughout school.		
	2	Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light									
	3 4	Average - 26-50% of learning spaces have natural light									
	4	Satisfactory - 51-75% of learning spaces have natural light									
	5	Very satisfactory - 76-100% of learning spaces have natural light									
_	N/A	Does not apply				1	1		1		
	5.4 Is there acc	ess to outside views from learning spaces?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No learning spaces have views							Not all rooms have windows; those that do have views	to the outdoors	.
	2	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out									
	3	Average - 26-50% of learning spaces have views									
	4	Satisfactory - 51-75% of learning spaces have views									
	5	Very satisfactory - 76-100% of learning spaces have views									
	N/A	Does not apply									

5 - E	nvironmen	tal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	ilding have odor or pest problems?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Evidence of both pests and odors							Old building smell/off-gassing of materials and presence of	of ant trails i	n
	2	Unsatisfactory - Evidence of pests or odors							multiple studios.		
	3	Average - Limited evidence of pests, no odors									
	4	Satisfactory - No evidence of pests / odors, school cleanliness in good condition									
	5	Very Satisfactory - No evidence, school cleanliness in excellent condition									
	N/A	Does not apply									
6 - C	ontrollabil	ity of Systems	1	2	3	4	5	N/A		12.50	68%
6.1	Does the stu	adio thermostat allow for individual control?					5		Comments	0.50	2.50
	1	No	•								
	5	Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No, windows are covered with boards/paper	•	•	•	•	•	•			
	2	Unsatisfactory - No, windows have no light control									
	3	Average - Yes, but poor condition blinds									
	4	Satisfactory - Yes, blinds									
	5	Very satisfactory - Blackout shades									
	N/A	Does not apply									
6.3	What is the	quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Single switch only per room							Some rooms have one switch; others have alternate fixture	switching.	
	2	Unsatisfactory - Alternating rows switch off								•	
	3	Average - Alternating lamps in single fixtures switch off									
	4	Satisfactory - Tri level switching									
	5	Very satisfactory - Dimmable									
	N/A	Does not apply									

7 - Fu	ırniture, Fiz	xtures & Equipment	1	2	3	4	5	N/A	4	18.75	55%
7.1	What is the	current condition of the furniture?			3				Comments	0.75	2.25
	1 2 3	Very unsatisfactory - Damaged or broken, non-functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked							Furniture is aged and mismatched. Some spaces apper but other areas have furniture that is damaged or cum		
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
	N/A	Does not apply							1		
7.2		y of furniture types being accommodated throughout the rning commons, dining commons, other multi-use spaces?	1						Comments	1.00	1.00
	1	Very Unsatisfactory - Same furniture used in all spaces							All spaces have same tables, chairs or desks.		
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use space									
	4	Satisfactory - All multi-use spaces have greater than one type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply									
7.3	How well do space?	pes furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy				<u> </u>			Larger tables would be difficult to move. Desks are mo		0.00
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	Is the furnitu	ure ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

02/11/2022 9

o Waste		1	2	3	4	5	N/A		5.00	20%
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?	1						Comments	0.50	0.5
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.					•		A score for this category is being recorded, but this cat in the overall ESA average.	egory is not ca	lculate
2	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.									
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply									
each: green	feteria (or wherever meals are served) have at least one of compost bin, blue recycle bin, and landfill bin? Are the bins arly with bilingual and/or image sorting?	1						Comments	0.50	0.5
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.							A score for this category is being recorded, but this cat in the overall ESA average.	egory is not ca	lculate
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4	Satisfactory- There are several waste stations as described above									
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									
N/A	Does not apply							L		



Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Linder Elementary School	Emilie Ogburn and Vish Panchal	12.22.2020

8 - Academics 8	& Learning	1	2	3	4	5	N/A	A	70.00	33%
8.1 Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
1 2	Very unsatisfactory - Too small, no flexibility, disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected						•	Roughly 780 square feet on average. No transparency rooms. Some rooms have operable partitions that are a function well.		
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A	Does not apply									
	nd Kinder have appropriate support spaces such as and storage per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - None provided						•	No pre-K. Restrooms in all studios are not accessible.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									,

8 - A	cademics 8	k Learning (cont.)	1	2	3	4	5	N/A	·		
8.3	Do studios h spec?	nave appropriate support spaces such as storage per the ed			3				Comments	1.00 3	3.00
	1	Very unsatisfactory - None provided	•						No storage closets, just small sink casework area and v	vall of tall cabinets.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
8.4	Do typical le collaboration	earning neighborhoods have small group rooms and open on space?	1						Comments	1.00 1	1.00
	1	Very unsatisfactory - No breakout rooms or open collaboration spaces are provided							Double-loaded corridors, open teaching space limited undersized) or cafeteria.	to library (which is	
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy									
	N/A	Does not apply									
8.5		studios large enough to support project-based learning and sching modalities?		2					Comments	1.00 2	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning							Undersized studios with limited flexibility; only one mai casework gets in the way of changing teaching direction		Ŀ
	2	Unsatisfactory - Undersized, decentralized resources, limited flexibility									
	3	Average - Adequate size, needs some renovations or updates to function well									
	4	Satisfactory - Good size, centralized resources, good flexibility									
	5	Very Satisfactory - Generous size, centralized project resources, excellent flexibility									
	NI/A	Does not apply									

8 - A	cademics 8	Learning (cont.)	1	2	3	4	5	N/A			
8.6	Are Maker S ed spec?	spaces and support spaces appropriately configured per the	1						Comments	1.00	1.00
	1 2	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected							No maker space, only small computer lab		
	2	from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for Professional Learning Center							One large teacher's lounge/supply space but disconne studios	cted from main	1
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition, connected									
	N/A	Does not apply									
8.8	Is there a de	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9		dequate places to display the evidence and artifacts of the 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space							Limited 3D storage, decent amount of tackboards in co	orridors for 2D d	lisplay.
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

8 - A	cademics &	Learning (cont.)	1	2	3	4	5	N/A			
8.10		ilding provide adequate opportunities for students/teachers te in varying group sizes?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No space to support collaboration in various sizes.			,						
	2	Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply									
8.11	Does the bu	ilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space							Corridors are narrow and confusing; double-loaded wi	th limited oppo	rtunity
	2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well							for informal interaction		Í
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
8.12		rning neighborhood / building provide adequate s for students to work independently?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms/small study spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood									
	N/A	Does not apply									

8 - Academ	ics & Learning (cont.)			,				
8.13 Are Spe	cial Education spaces appropriately configured per the ed spec?		2			Comments	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility, disconnected				•	Not configured for special education; located in regula	r studio.	
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
N/A	A Does not apply							
	cial Education support spaces, such as storage, space for /dryer, appropriately configured per the ed spec?	1				Comments	1.00	1.00
1	Very unsatisfactory - None provided					Small nurse's bed in vestibule between studios and rest		kely
2	Unsatisfactory - Too small, disconnected, poor condition					used as a changing table. No other special education s	support spaces	
3	Neutral - Adequate size, average condition, needs updates or renovations to function well					present.		
4	Satisfactory - Good size, connected, good condition							
5	Very Satisfactory - Generous size, connected, excellent condition							
N/A	A Does not apply							
	essible restrooms and changing rooms readily available to the Education spaces?	1				Comments	1.00	1.00
1 5	No Yes					Not accessible; see above.		

9 - Visual a	and Performing Arts	1	2	3	4	5	N/A	4	15.00	40%
9.1 Are mu	usic spaces and the cafeteria stage appropriately configured per spec?		2					Comments	1.00	2.00
1 2 3	Neutral - Adequate size, adequate condition, needs							Stage is small and lacking storage; not directly adjacen be used as music instruction/performance space.	t to studios the	it could
2	Very Satisfactory - Generous size, excellent condition									
	/A Does not apply usic and performance storage spaces appropriately configured e ed spec?	1						Comments	1.00	1.00
2	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition							Music is in a repurposed typical studio and does not har infrastructure or adequate space to function well.	ve suitable	
3	or renovations to function well									
5										
N/	/A Does not apply									
9.3 Are Vis	sual Arts spaces and storage appropriately configured per the ed			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Sinks aren't accessible; has a kiln, storage is small; has a outdoor space.	lose access to	
2	Unsatisfactory - Too small, poor condition							'		
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5										
N/	/A Does not apply									

02/11/2022 7

10	0 - PE and Wellness			2	3	4	5	N/A		10.00	60%
	0.1 Does the car program spo	mpus meet the ed spec standard for physical education aces?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply sical education storage spaces appropriately configured per							Floors are new; could use new paint, lots of chipping/partition to cafeteria.	eeling; movable	•
1	0.2 the ed spec			2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition							Good location but very small		
	N/A	Does not apply									
11	- Food Service	es	1	2	3	4	5	N/A		10.00	40%
	11.1 Is the Dining	Commons appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space) Does not apply							All same furniture throughout; outdoor seating option i cafeteria; movable partition opens to gym.	s away from	
		d Services support spaces appropriately configured per the		2					Comments		
L	ed spec?	Vory unegticfactory. None provided					<u> </u>			1.00	2.00
	1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition							Storage is limited and kitchen is small overall; only one	tood service line	е.
	IN/A	Does not apply									

12 - Media Res	Media Resources - Continued				4	5	N/A			
12.5	oes the Library/Media Center support collaborative work in ps (10-25)?			3				Comments	1.00	3.00
1	Very unsatisfactory - No gathering areas							Only one zone for instruction	•	
2	Unsatisfactory - Too small, one common space, limited seating, poor condition							,		
3	Average - Adequate size, one common space, needs updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with seating, good condition									
5	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition									
N/A	Does not apply									
12.6 How well d	oes the Library/Media Center support technology?			3				Comments	1.00	3.00
1	Very unsatisfactory - No vis comm tools					•		No marker boards; projection screen and projector for	teaching, proje	ector
2	Unsatisfactory - Outdated, poorly functioning, or insufficient							screen in Kiva; TV carts present.		
3	Good - Mix of old and new whiteboards/projectors/etc.									
4	Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition									
5	Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition									
N/A	Does not apply									
13 - Technolog	y	1	2	3	4	5	N/A		20.00	45%
13.1 How well e	quipped are the facilities with instructional technology?			3				Comments	1.00	3.00
1	Very unsatisfactory - Limited to no technology present in instructional spaces							Projectors and TV carts in most rooms; chalkboards in r	ooms not used.	
2	Unsatisfactory - One type of technology present									
3	Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school									
4	Satisfactory - Multiple types of technology, smart boards, good condition.									
5	Very Satisfactory - Multiple types of technology, smart boards, excellent condition									
N/A	Does not apply									
13.2 Is there an spaces?	adequate number of power and data outlets in learning			3				Comments	1.00	3.00
1	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)							New surface-mounted power appears to have been a outlets would be very limited otherwise.	dded in some a	reas,
2	Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)							, , , , , , , , , , , , , , , , , , , ,		
3	Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)									
4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall)									
5								1		
3	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									

13 - Technology (co	ont.)	1	2	3	4	5	N/A	A		
13.3 Are there adequ	uate charging locations for devices?	1						Comments	1.00	1.00
1 Ve	ery unsatisfactory - No centralized charging location		•		•	•		Did not see any charging carts for devices in studios or	shared spaces.	
	nsatisfactory - Centralized charging location, but adequate in size for number of devices									
	verage - Charging cart or tower but not adequately sized r number of devices									
4 Sa	tisfactory - Charging cart or tower not centralized									
	ery Satisfactory - Charging cart or tower located Intralized location. Excellent condition									
N/A Do	pes not apply									
13.4 Is there adequa	te AV for presentations spaces – cafeteria and gym?		2					Comments		
				<u> </u>					1.00	2.00
l Ve	ery unsatisfactory - AV not present in one or more space							No presentation capabilities in gym; projection (small) cafeteria.	and TV cart in	
2 Ur	nsatisfactory - AV undersized for room, poor condition									
	verage - Adequately sized / poor condition OR AV adersized / adequate condition									
4 Sa	tisfactory - Good size, good condition									
5 Ve	ery Satisfactory - Generous sized, excellent condition									
N/A Do	pes not apply									
13.5 Is there digital n	nedia signage at the reception area?		2					Comments	0.00	0.00
	ery unsatisfactory - No digital media present in reception ea		•					Very small TV in reception office		
2 Ur	nsatisfactory - Undersized, poor condition									
	verage - Adequately sized / poor condition OR adersized / adequate condition									
	ıtisfactory - Media signage present, good sized, good endition									
5 Ve	ery Satisfactory - Generously sized, excellent condition									
N/A Do	pes not apply									

14 - Administration Spaces	1	2	3	4	5	N/A		20.00	50%
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
1 Very unsatisfactory - No security checkpoint									
2 Unsatisfactory - Checkpoint is too small, poor condition									
Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply	1	1		_	1		I	_	
14.2 Does the administration area feel welcoming?			3				Comments	1.00	3.00
1 Very unsatisfactory - No welcome space							Small waiting area with no seating present, likely due	to COVID; visibil	lity to
2 Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition							corridor with windows.		
3 Average - Adequate size and layout, needs updates or renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of light and transparency, informal seating provided, excellent condition									
N/A Does not apply									
14.3 For those spaces that require it, does the administration area have adequate acoustic privacy?				4			Comments	1.00	4.00
1 Very unsatisfactory - No acoustic separations	•				•			•	
2 Unsatisfactory - Acoustic separations do not perform well									
3 Average - Some acoustic separations function okay, but portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply	1						1	_	
14.4 Are conference rooms easily accessed for public / parent use?	1						Comments	1.00	1.00
Very unsatisfactory - Not accessible for public/parent use							No conference room, parent support specialist.		
 Unsatisfactory - Limited access, no transparency, poor condition, difficult to find 									
3 Average - Adequate accessibility, needs updates or renovations to function well									
4 Satisfactory - Good accessibility, good transparency, good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
N/A Does not apply									