

# **Educational Suitability Summary Report**

Mathews Elementary School

Date: 12/15/2020 Score 53% Average

Mathews Elementary School, serving an enrollment of approximately 350 students in central Austin, is known as an urban neighborhood school. It was originally built in 1916 and the site is fully integrated into the neighborhood grid. The school received a Texas Historical Medallion in 2006. Due to site constraints, there is no on-site parking, only on-street parking. There is a bus drop-off and pickup lane in front of the school. There are marked crosswalks and sidewalks for pedestrian circulation around the campus. The building configuration is a two-story facility in a basic "H" form with the playgrounds on the backside of the property.

The main entrance poses an accessibility issue. When you enter, there are steps down to the first floor, but there is no ramp. Administrators noted that special arrangements must be made for visitors or students who cannot enter through this main entrance.

The furniture allows for different size groups in the learning spaces but there is little opportunity for groups to break out in adjacent spaces. There is opportunity for this to occur in the hallways, but acoustical and visibility issues may arise. Not all learning spaces have restrooms in the studios. There are no designated storage closets in the studios; however, the built-in millwork provides storage. Studios have adequate natural lighting in every space.

There is a large concrete area with a fabric cover for protection at the back of the school where the playgrounds are. There is no large green open space, but some playgrounds are situated around existing trees that provide ample shade. There are edible gardens, butterfly gardens and a pond area. The pond area was locked during the assessment and could not be closely observed. There are numerous art pieces on the grounds, including sculptures and mosaics.

The gymnasium is undersized and in average condition. The support spaces for PE are lacking. The cafeteria is small and does not allow for different kinds of seating arrangements for the students. The ceiling height seems low for a stage area, and there is no dedicated chair or stage storage. The library is located close to the main entry but has limited transparency to the hall. The furniture allows for different groups to collaborate but there are no dedicated quiet rooms for individual study.

#### **Interview Overview**

The interview included Principal Grace Martino-Brewster, Cindy Bryan Sanders (teacher), Faye Holland (teacher), April Clark (parent), Adrianne (parent) and Jesus Delgado from AISD. There was discussion regarding the historical significance of the building, which was constructed in 1916 and has served multiple generations of families. It was discussed that the overall building has community importance due to its history in the neighborhood.

There is a desire to have a dedicated outdoor studio space for learning. There are several outdoor

## **Educational Suitability Summary Report**

Mathews Elementary School

spaces such as gardens and playgrounds, but a dedicated outdoor learning space was specified by the interviewees. There was also a request for an open green space. The open area is all concrete with a fabric cover and takes up a large portion of the playground area in the back. There are also two portables near the playgrounds. (While this assessment does not cover the portables, it is assumed that spaces in portables will be found deficient.) They prefer that the portables be removed, and the studios be integrated into the building, which would offer an opportunity to add more green space. They would like to keep the exterior stairs, but they need to verify if they meet code and safety requirements.

There was mention of the need for a larger cafeteria area with proper A/V equipment. The gym is often used for larger groups. The library seems adequate to the staff and parents but needs updates and more mobile furniture. They recognized the need for more outlets in the studios and in the maker space. There are no dedicated fine arts rooms for music or art. Art is in a typical studio that lacks the support for a typical art room. There was also mention of a culinary arts program as a wish list item.

## **Assessment Findings**

The Educational Suitability Assessment of Mathews Elementary earned a 53% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

## **Unsatisfactory Categories (36-50%):**

#### **Outdoor Learning and Activity**

Score is unsatisfactory.

The site is not large, but the campus uses the site effectively. The school does not have a grass play field or walking path. No direct connection to outdoor spaces.

### **General Building**

Score is unsatisfactory.

No dedicated community room or conference room for parent or public meetings. Interior circulation routes are adequate in width, but accessibility is a concern at both the main entrance and stage.

### **Academics & Learning**

Score is unsatisfactory.

Studios need updating to allow for more flexibility. Some have breakout spaces within studios but no flexibility with the corridor for group / collaboration spaces. Life skills room is missing washer/dryer and restroom is not ADA accessible.

#### **Visual and Performing Arts**

Score is unsatisfactory.

Need dedicated fine art spaces. There is no dedicated music room, and the stage is small and is not accessible. The ceiling height is low on the stage. Art room has kiln but is in a typical studio.

### **PE and Wellness**

Score is unsatisfactory.

Gym is undersized at 2300 square feet. There is not a dedicated storage room that can be accessed

## Perkins&Will

## **Educational Suitability Summary Report**

Mathews Elementary School

from the gym. There is not a shower / locker / toilet as part of the PE Office area.

#### **Food Services**

Score is unsatisfactory.

Cafeteria is slightly undersized and does not have any storage. The kitchen / serving area is very undersized.

## **Technology**

Score is unsatisfactory.

Need better technology in the media room. The stage has lighting and speakers but does not have overhead projector capability. There are inadequate outlets in the studios and power strips and extension cords are used throughout the school.

## **Administrative Spaces**

Score is unsatisfactory.

The administrative space could be more welcoming. Acoustics are indicated as being adequate.

## Average Categories (51-65%):

#### **Exterior**

Score is average.

Given the limitation of the site, the circulation is challenging to keep bus and vehicular traffic separated.

## Security

Score is average.

#### **Media Resources**

Score is average.

Adequate furniture that allows for different group sizes, but library is not overly generous to allow for different simultaneous activities between large and small groups. Better transparency and better spaces for individual study are needed.

## Satisfactory Categories (66-80%):

#### **Environmental Quality**

Score is satisfactory.

Acoustics between studios is satisfactory. Multiple options for different types of lighting from natural to artificial.

### **Controllability of Systems**

Score is satisfactory.

Individual light controls for artificial lighting. Shades and thermostats are provided in studios. Studios have typical two-switch control for artificial lighting.

# Perkins&Will

# **Educational Suitability Summary Report**


Mathews Elementary School

# Furniture, Fixtures, Equipment

Score is satisfactory.

Generally, the furniture appears in good condition.

Mathews Elementary School



Main entrance. Has dedicated bus lane off West Lynn.



Main entrance into building. Administration space is to the left. No ADA ramp or lift provided.



Hallway space and display area.



Library/media space. Furniture allows for different size groups.



Cafeteria and stage area are undersized and do not meet Ed Spec. Furniture does not allow for flexibility. The stage is not accessible.




Gymnasium area has limited storage and is undersized.

Mathews Elementary School



Maker space on the second floor. Ample room and equipment. All studios have abundant daylight and access to views.



Typical studio with built-in storage with cabinetry.

Mathews Elementary School



Outdoor playground area. Concrete area takes large portion of playground area.



Outdoor edible garden. Series of garden spaces make up the outdoor learning spaces.



# Perkins&Will

# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
Mathews Elementary School	Carlos Cruz, Kevin Kinsey	12/10/2020

- Exterior		1	2	3	4	5	N/A	4	8.75	54%
1.1 Does the s	site permit desirable separation of vehicular, bus and in traffic?		2					Comments	1.00	2.00
1 2 3 4 5	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination Does not apply							The school is integrated into the surrounding neighbor on-site parking only parallel parking along the street school. Off of West Lynn there is a drop-off and pick to buses. Given the school's location within the neighbor difficult to separate bus, cars and pedestrian circulating dedicated pedestrian sidewalks and crosswalks.	s surrounding up area dedic hood, it make	the ated to es it
12	ding easily identified with appropriate signage and ty wayfinding?			3				Comments	0.25	0.75
1 2 3 4	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden Average - Signage / wayfinding visible but not apparent Satisfactory - Signage / wayfinding is visible but not good condition							There is a sign on West Lynn.		

Perkins&Will 02/11/2022 <sup>2</sup>

1 - Ex	cterior (co	nt.)	1	2	3	4	5	N/A	A		
1.3	Is the dump	oster accessible for trash / compost disposal?				4			Comments	0.50	2.00
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped									
		/ positioned so people of all heights can access it.									
	N/A	Does not apply									
2-0	outdoor Le	arning and Activity	1	2	3	4	5	N/A		15.00	47%
2.1	Are outdoo	r studios and support spaces appropriately configured per ?			3				Comments	1.00	3.00
	1 2 3 4	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Good use of existing trees and outdoor space for gar pond. The outdoors lack a sufficient open green space		arning
	N/A Are active r	Does not apply blaygrounds (elementary only) and support spaces				Π					
2.2		per the ed spec?			3				Comments	1.00	3.00
	1 2 3	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50%							Ed Spec indicates adjacency of outdoor learning spa school is a two-story urban school. The adjacency of only works for the ground-level classes that face the limited.	the learning sp	oaces
	5 N/A	shade coverage over play structure  Very satisfactory - Generous size, excellent condition, full shade coverage over play structure  Does not apply									

2 - 0	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A	1		
2.3		s and support spaces appropriately configured per the eduction on infrastructure not condition of plants)				4			Comments	0.00	0.00
	1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source		L					Monitoring answer, does not affect score for Outdoor I Activity.		0.00
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is									
	5	accessible with 100 ft hose Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain ed spec?	gardens and/or cisterns appropriately configured per the			3				Comments	0.00	0.00
	1 2 3	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Monitoring answer, does not affect score for Outdoor I Activity.	Learning and	
	4 5	Satisfactory - Good size, good condition, functions properly Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
0.5	N/A	Does not apply	,				I			0.00	0.00
2.5	Does the sc	nool have animal husbandry? (optional)  No	I				<u> </u>		Comments	0.00	0.00
	5	Yes									
2.6		nool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1 5	No Yes		1							
2.7	Does the sc	nool have a learning pond? (optional)					5		Comments	0.00	0.00
	1 5	No Yes							· · · · · · · · · · · · · · · · · · ·		
2.8	Does the sc	nool have a grass play field and walking trail?	1						Comments	1.00	1.00
	1	No									
	5	Yes									

3	3 - General Bui	lding	1	2	3	4	5	N/A		11.25	44%
	.5 1	circulation routes wide enough to safely and effectively				4			Comments		
L	accommod	ate student movement?							Comments	0.50	2.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
	2	wide Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	•									
		Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
_	N/A	Does not apply									
		nity use areas arranged so that the school can allow night		2					Comments		
L	functions w	ithout full school access?								0.75	1.50
	1	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							Cafeteria is located on the perimeter of the building	-	
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,							opportunity to have after-hour functions. The doors t	o the rest of the	9
	2	Gym and Library) can be accessed from parking and							building would need to be secured or monitored.		
		secured after hours									
	3	Average - Only two of the public spaces can be accessed									
		from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
_	N/A	Does not apply									
	77	ommunity room that is a dedicated meeting space outside	1						Comments		
L	of school fu									0.75	0.75
	1	Very unsatisfactory - No dedicated community room							No dedicated community room		
	2	Unsatisfactory - Community room but within school function, no access after school hours									
	3	Average - Community room, moderate size, but need									
	3	some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets									
	·	needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
		condition, functions appropriately outside of school									
		function									
_	N/A	Does not apply					ı				
		eneral appearance of the school convey pride for the			3				Comments		
L	students an	d community?								0.25	0.75
	ı	Very unsatisfactory - General appearance is poor							The exterior needs some cleaning. Tree trimming at t	ne main entran	ce
	2	Unsatisfactory - General appearance is aged but ok							would help with the visibility of the building.		
	4	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in campus and student works									
	5	Very Satisfactory - General appearance shows pride in									
	Ü	campus and student works and is welcoming to the									
		community									

4 - Security	1	2	3	4	5	N/A		16.25	
4.1 Does the facility have key card access at all major entries?							Comments	0.25	
1 Very unsatisfactory - No entries								•	
2 Unsatisfactory - 1/4 of major entries									
3 Average - 1/2 of major entries									
4 Satisfactory - 3/4 of major entries									
5 Very satisfactory - All of major entries									
N/A Does not apply									
4.2 How adequate is site lighting and security for the campus overall?							Comments	1.00	
Very unsatisfactory - No exterior lighting, no secure perimeter									
Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal									
Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate									
4 Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates									
5 Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure	į.								
N/A Does not apply									
4.3 ls the main office located at the school entry and configured with a secure vestibule to the main corridor?							Comments	1.00	
1 Very unsatisfactory - No secure vestibule, office located									
far from main entry, allows visitors access to school									
unsupervised									
2 Unsatisfactory - No secure vestibule, office located									
somewhat far from main entry, minimal supervision of									
visitors  3 Average - Office close to entry, views of front door, but									
no secure vestibule									
4 Satisfactory - Office is well-located with a secure									
vestibule, but needs updates									
5 Very satisfactory - Office well-located with secure									
vestibule and all appropriate security features									
N/A Does not apply									
Is there enough interior transparency for faculty to passively supervise	e		T		1	1	_		
4.4 learners and their activities who are not in studios?			3		1	1	Comments	1.00	3.00
Very unsatisfactory - No transparency of walls		-		1	1	1		ı	
2 Unsatisfactory - Limited transparency in certain location	ıs								
3 Average - Good transparency in certain locations but									
inadequate or missing in other locations of school									
4 Satisfactory - Adequate transparency throughout the school									
Very satisfactory - Excellent transparency throughout the school	е								
N/A Does not apply									

Perkins&Will 02/11/2022 <sup>6</sup>

5 - Environmental Quality	1	2	3	4	5	N/A		25.00	80%
5.1 How are acoustics in studios in general?				4			Comments	1.00	4.00
1 Very unsatisfactory - Recognized word/sound from adjacent studio/corridor 2 Unsatisfactory - Audible sound from adjacent studio/corridor 3 Average - Slight sound from outside room 4 Satisfactory - Walls to deck insulated only white noise from mechanical system 5 Very satisfactory - Able to hear quiet speaking from across the room N/A Does not apply									
5.2 Is the studio artificial lighting adequate quality?				4			Comments	1.00	4.00
1 Very unsatisfactory - Sporadic lights work, glare, less than 20 FC 2 Unsatisfactory - 10-19 FC or serious glare 3 Average- 20-29 FC minor glare 4 Satisfactory - 30-39 FC and no glare 5 Very satisfactory - 40+ FC and no glare N/A Does not apply	•	1							
N/A Does not apply  5.3 Is there access to natural light in studios?				4			Comments	1.00	4.00
1 Very unsatisfactory - No learning spaces have natural liaht 2 Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light 3 Average - 26-50% of learning spaces have natural light 4 Satisfactory - 51-75% of learning spaces have natural light 5 Very satisfactory - 76-100% of learning spaces have natural light	ŧ								
N/A Does not apply		1	I	<u> </u>	ı			T	
5.4 Is there access to outside views from learning spaces?				4			Comments	1.00	4.00
1 Very unsatisfactory - No learning spaces have views 2 Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out 3 Average - 26-50% of learning spaces have views 4 Satisfactory - 51-75% of learning spaces have views 5 Very satisfactory - 76-100% of learning spaces have views N/A Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	A.		
5.5 Does the b	ouilding have odor or pest problems?				4			Comments	1.00	4.00
1	Very unsatisfactory - Evidence of both pests and odors		•							
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllabi	ility of Systems	1	2	3	4	5	N/A	L.	12.50	76%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with		•							
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?			3				Comments	1.00	3.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							<b>L</b>		

7 - Furi	niture, Fixtures & Equipment	1	2	3	4	5	N/A		18.75	75%
7.1 W	/hat is the current condition of the furniture?				4			Comments	0.75	3.00
	1 Very unsatisfactory - Damaged or broken, non- functioning 2 Unsatisfactory - Torn/ bent/ wrong size 3 Average - Scratched/dented/marked 4 Satisfactory - Not new, but sturdy and clean 5 Very satisfactory - New N/A Does not apply									
	re a variety of furniture types being accommodated throughout the chool - learning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	Very Unsatisfactory - Same furniture used in all spaces									
	2 Unsatisfactory - Furniture variety in one multi-use space									
	<ul> <li>Average - Furniture variety in more than one multi-use space</li> <li>Satisfactory - All multi-use spaces have greater than one type of furniture</li> <li>Very satisfactory - All multi-use spaces have greater than two types of furniture</li> <li>N/A Does not apply</li> </ul>									
/ '3	ow well does furniture accommodate rapid reconfiguration of a pace?				4			Comments	1.00	4.00
	1 Very Unsatisfactory - Furniture is fixed or very heavy 2 Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups 3 Average - Mix of furniture that can reconfigure but is cumbersome to move 4 Satisfactory - Furniture is flexible for multiple configurations of space 5 Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack N/A Does not apply									
7.4 ls	the furniture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1 Very unsatisfactory - Desk with attached chair combinations too small for grade level 2 Unsatisfactory - Desk with attached chair combinations 3 Average - Mix of studios with tables/loose chairs and desks with fixed seats 4 Very satisfactory - Tables with loose chairs 5 Very satisfactory - Tables with loose chairs that allow students to be active N/A Does not apply									

Perkins&Will 02/11/2022 <sup>9</sup>

Z	Zero Waste		1	2	3	4	5	N/A		5.00	60%
		d corridors have blue recycle bins with bilingual ad/or image sorting instructions?		2					Comments	0.50	1.00
	b oi 2 U in 3 A lc TI 4 Si lc lc V vi aa	ery unsatisfactory - There are no recycling and landfill ins and signage are sparse or infrequent, OR there are nly landfill bins with no recycling bins.  Insatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.  Inverage - 50% of corridors and studios have both a containers have clear signage.  Interest and of the containers have clear signage.  Interest and of the containers have a visible andfill and recycle collection containers in an accessible bocation. The containers have clear signage.  Interest and format is consistent and uniform cross campus.							A score for this category is being recorded, but this ca calculated in the overall ESA average.	itegory is not	
_	N/A D	oes not apply					1				
	of each: green	eria (or wherever meals are served) have at least one compost bin, blue recycle bin, and landfill bin? Are the learly with bilingual and/or image sorting?				4			Comments	0.50	2.00
	a sc 2 U p	ery unsatisfactory- There may be landfill bins, but there re no compost and/or recycle bins. There is not clear orting signage. Insatisfactory- Recycle, landfill, and compost bins are resent, but the bins are scattered and no co-located							A score for this category is being recorded, but this ca calculated in the overall ESA average.	tegory is not	
	3 A th p	ext to one another. Signage is absent or inconsistent.  verage- There is at least one waste station with all  nree bins (recycle, compost, landfill) located with close roximity to one another. The signage is visible and  onsistent.									
	d 5 V d cc	atisfactory- There are several waste stations as escribed above ery Satisfactory - There are several waste stations as escribed above, and additional signage in the afeteria that encourages recycling/composting.									
	N/A D	oes not apply									



# Perkins&Will

# **Austin ISD Educational Suitability Assessment Criteria**

**Academics - Elementary School** 

N/A

Does not apply

	School No	ame							Walk Attendees:	Date:	
	Mathews	Elementary School					_		Carlos Cruz, Kevin Kinsey	12.10.20	
8 - /	Academics	& Learning	1	2	3	4	5	N/A	N.	70.00	37%
8.1	Are studios	s appropriately configured per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility,							Studios are undersized at 780 SF.		
	0	disconnected									
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different									
	Ŭ	teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to									
		function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
	_	spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous display area and visual teaching tools,									
		excellent transparency and connection with other									
		studios and shared learning spaces									
	N/A	Does not apply									
	Do Pre-K	and Kinder have appropriate support spaces such as									
8.2	restrooms	and storage per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided				•	•				
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									

Perkins&Will 02/11/2022 <sup>2</sup>

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A			
8.3 Do studios have appropriate support spaces such as storage per the ed spec?			3				Comments	1.00	3.00
1 Very unsatisfactory - None provided									
2 Unsatisfactory - Too small, disconnected, poor condition									
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, excellent									
condition									
N/A Does not apply									
8.4 Do typical learning neighborhoods have small group rooms and open collaboration space?	1						Comments	1.00	1.00
Very unsatisfactory - No breakout rooms or open		1			1	1			
collaboration spaces are provided									
2 Unsatisfactory - Too small or too few, poor condition, no									
flexibility, lacks visual connection to learning									
neighborhood, poor acoustic privacy									
3 Average - Adequate size, adequate condition, needs									
some renovations or updates to function well									
4 Satisfactory - Good size, good condition and flexibility,									
transparency and connection to learning neighborhood,									
acoustic privacy  5 Very Satisfactory - Generous size, excellent condition									
and flexibility, transparency and connection to learning									
neighborhood, acoustic privacy									
N/A Does not apply									
Are general studios large enough to support project-based learning									
and multiple teaching modalities?		2					Comments	1.00	2.00
<ol> <li>Very unsatisfactory - Too small, no flexibility, does not</li> </ol>									
support project-based learning									
2 Unsatisfactory - Undersized, decentralized resources,									
limited flexibility									
3 Average - Adequate size, needs some renovations or									
updates to function well									
4 Satisfactory - Good size, centralized resources, good flexibility									
5 Very Satisfactory - Generous size, centralized project									
resources, excellent flexibility									
N/A Does not apply									

Perkins&Will 02/11/2022 <sup>3</sup>

8 - 8		& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6		Spaces and support spaces appropriately configured per				4			Comments	1.00	
	the ed spec			<u> </u>		<u> </u>			0.10	1.00	4.00
	2	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected							2nd floor open space		
	2	from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	-	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected to learning spaces									
	N/A	Does not apply		ı	ı	ı	ı	ı			
8.7	Is there a Pr	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for							No PLC space was observed.		
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected									
	N/A	Does not apply					ı	ı			
8.8	Is there a d	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.	0.00	0.00
	5	Yes							livioritioning driswer, but doesn't direct overdir score.		
	Are there a	dequate places to display the evidence and artifacts of		1	l	l					
8.9		oth 2D and 3D)?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated space							Hallways have different displays.		
	2	Unsatisfactory - Too small, non-dedicated, poor									
		condition									
	3	Average - Adequate size, adequate condition, needs									
	4	updates or renovations to function well									
	4 5	Satisfactory - Good size, good condition									
	5 N/A	Very Satisfactory - Generous size, excellent condition  Does not apply									
	IV/A	DOES HOLODON									

Perkins&Will 02/11/2022 <sup>4</sup>

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	A		
8.10	Does the b	uilding provide adequate opportunities for		2					Commonto		
8.10	students/te	eachers to collaborate in varying group sizes?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space to support collaboration in various sizes.  Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes							The collaboration occurs within the classrooms. Ther breakout rooms for collaborations. This could occur i acoustics and visibility could be an issue since there is	n the hallways	but
	3 4	Average - Adequate space for collaboration, needs updates or renovations to function well.  Satisfactory - Good size, good condition, multiple							between the classrooms and hallways.		
		options to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes									
	N/A	Does not apply				1					
8.11	Does the b	uilding provide opportunities for informal interaction?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No space							The circulation and stairs allow for informal interaction	ons.	
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
		Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
		furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
		layout and furnishings support informal interactions									
	N/A	Does not apply	1	1		1					
8.12		arning neighborhood / building provide adequate	1						Comments		
	opportunit	ies for students to work independently?								1.00	1.00
	1	Very unsatisfactory - No breakout rooms/small study spaces							No small breakout rooms observed in the existing co	nfiguration.	
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space										
		options, connected to learning neighborhood									
	N/A	Does not apply									

O2/11/2022 <sup>5</sup>

8 - A	Academics 8	& Learning (cont.)						
8.13	•	Education spaces appropriately configured per the ed	1			Comments		
	spec?						1.00	1.00
	1	Very unsatisfactory - Too small, no flexibility,				No Special Education classroom. Individual attention	session are	
		disconnected				conducted by visiting staff.		
	2	Unsatisfactory - Too small, only one area for all teaching						
		methods, limited flexibility, disconnected						
	3	Neutral - Adequate size, multiple areas for different						
		teaching methods, adequate flexibility, limited						
		transparency and connection to other studios and						
		shared learning spaces, needs updates or renovations to						
	_	function well.						
	4	Satisfactory - Good size, multiple areas for different						
		teaching methods, good flexibility, good transparency						
		and connection to other studios and shared learning						
	5	spaces Very Satisfactory - Generous size, multiple areas for						
	5	different teaching methods, excellent flexibility,						
		generous display area and visual teaching tools,						
		excellent transparency and connection with other						
		studios and shared learning spaces						
	N/A	Does not apply						
	Are Special	Education support spaces, such as storage, space for				_		
8.14		ver, appropriately configured per the ed spec?	1			Comments	1.00	1.00
	1	Very unsatisfactory - None provided						
	2	Unsatisfactory - Too small, disconnected, poor condition						
		·						
	3	Neutral - Adequate size, average condition, needs						
		updates or renovations to function well						
	4	Satisfactory - Good size, connected, good condition						
	5	Very Satisfactory - Generous size, connected, excellent						
		condition						
	N/A	Does not apply						
8.15		ble restrooms and changing rooms readily available to the	1			Comments		
0.10	Special Edu	ication spaces?				Comments	1.00	1.00
	1	No						
	5	Yes						

Perkins&Will 02/11/2022 <sup>6</sup>

9 - 1	Visual and I	Performing Arts	1	2	3	4	5	N/A	A	15.00	40%
9.1	Are music s per the ed s	paces and the cafeteria stage appropriately configured spec?	1						Comments	1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							No dedicated music room or space. Stage appears s	mall.	
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	Are music a	and performance storage spaces appropriately configured							6 .		
9.2	per the ed s	spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided						1			
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
9.3	Are Visual A	Arts spaces and storage appropriately configured per the			3				Comments		
9.3	ed spec?				3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Art room is in typical studio. Does have a kiln.		
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4 Satisfactory - Good size, good condition										
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

10 - PE and Wellness			2	3	4	5	N/A	A	10.00	50%
Does the co	impus meet the ed spec standard for physical education			3				Comments		
program sp	paces?			0				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Gym is undersized.		
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply		1			ı		T	ī	
1 10 2	rsical education storage spaces appropriately configured		2					Comments	1.00	0.00
per the ed s	•								1.00	2.00
1	Very unsatisfactory - None provided							Small storage space and is unsecured.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									
11 - Food Service	es	1	2	3	4	5	N/A		10.00	50%
11.1 Is the Dining	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, missing program spaces							Cafeteria is slightly undersized for school's capacity (	enrollment: 350	)/
2	Unsatisfactory - Too small, poor condition, only one							capacity: 400). Size is 1900 SF. Should be approx. 2,3	00 SF. Nice da	ylit
	option for eating space provided, inadequate circulation							space.		
3	Average - Adequate size and condition, needs updates									
3	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation,									
·	multiple options for eating space (ex: connection to									
	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition									
	and circulation, multiple options for eating space (ex:									
	connection to outdoor eating space)									
N/A	Does not apply									
	d Services support spaces appropriately configured per		2					Comments		
the ed spec									1.00	2.00
	Very unsatisfactory - None provided							Kitchen / servery is very undersized. Approx. 1100 SF	and that includ	es
2	Unsatisfactory - Too small, disconnected, poor condition							freezer / cooler and serving lines.		
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
N/A	condition  Does not apply									

12 - Media Resources	1	2	3	4	5	N/A	4	30.00	53%
ls the Library/Media Center easily accessible for the occupants and			3				Comments		
12.1 visitors to the school?			3				Comments	1.00	3.00
Very unsatisfactory - Not accessible					•		Library is near entry but limited visibility into the space	e from the hall	way.
2 Unsatisfactory - Limited access, difficult to find, no									
transparency									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Accessible, easy to find, good									
transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent									
transparency, excellent condition  N/A Does not apply									
N/A Does not apply						ı			
12.2 How well does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1 Very unsatisfactory - No quiet study spaces				1		<u> </u>	No dedicated quiet study or reading rooms.	1.00	
2 Unsatisfactory - One area in poor condition, poor							The dedicated quiet study of reading rooms.		
acoustic privacy									
Average - One or more areas provided, needing									
updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy									
N/A Does not apply	_	l		I		ı	T		
12.3 How well does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 Very unsatisfactory - No space	_				<u> </u>	<u> </u>	1	1.00	0.00
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
<ol> <li>Average - Adequate size and condition, needs updates</li> </ol>									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply	_	ı	l	ı	1	ı			
How well does the Library/Media Center support collaborative work in small groups (4-8 students)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No breakout rooms, no flexible						<u> </u>	1	1.00	3.00
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
3 Average - Adequate size, multiple areas provided,									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

12 - Media Resources - Continued	1	2	3	4	5	N/A			
How well does the Library/Media Center support collaborative work			3				Comments		
in larger groups (10-25)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No gathering areas									
2 Unsatisfactory - Too small, one common space, limited									
seating, poor condition									
3 Average - Adequate size, one common space, needs									
updates or renovations to function well									
4 Satisfactory - Good size, multiple common spaces with									
seating, good condition									
5 Very Satisfactory - Generous size, multiple commons									
spaces with seating, excellent condition									
N/A Does not apply									
12.6 How well does the Library/Media Center support technology?		2					Comments		
12.0 How well does the Library/Media Center support technology:							Comments	1.00	2.00
1 Very unsatisfactory - No vis comm tools									
<ol> <li>Unsatisfactory - Outdated, poorly functioning, or</li> </ol>									
insufficient									
3 Good - Mix of old and new whiteboards/projectors/etc.									
4 Satisfactory - Projectors, marker boards, smart boards in									
most spaces - good condition									
5 Very Satisfactory - Projectors, marker boards, smart									
boards in most spaces - new condition									
N/A Does not apply									
13 - Technology	1	2	3	4	5	N/A		20.00	40%
13.1 How well equipped are the facilities with instructional technology?				4			Comments		
		ļ	ļ	ļ	ļ	ļ		1.00	4.00
1 Very unsatisfactory - Limited to no technology present in									
instructional spaces									
2 Unsatisfactory - One type of technology present									
3 Average - Multiple types of technology, smart boards,									
poor condition, limited to only certain areas of school									
4 Satisfactory - Multiple types of technology, smart									
boards, good condition.									
5 Very Satisfactory - Multiple types of technology, smart									
boards, excellent condition  N/A Does not apply									
10.2		ı	<u> </u>	T	1	1			
13.2 Is there an adequate number of power and data outlets in learning spaces?		2					Comments	1.00	2.00
1 Very unsatisfactory - Outlet configuration does not		l		l	l	1	The second secon	1.00	2.00
support digital devices throughout school (1 per wall)							There was use of a lot of extension cords and powers	strips.	
2 Unsatisfactory - Outlet configuration support digital									
devices only in certain areas of school (2 per wall)									
3 Average - Outlet configuration support digital devices									
but not enough capacity throughout school (3 per wall)									
4 Satisfactory - Outlet configuration support digital									
devices with adequate coverage and capacity									
throughout school (>3 per wall)									
5 Very Satisfactory - Excellent outlet configuration to									
support digital devices throughout school (>3 per wall)									
N/A Does not apply									

02/11/2022 <sup>10</sup>

13 - Technolog	gy (cont.)	1	2	3	3 4	5	١	N/A			
13.3 Are there	adequate charging locations for devices?	1							Comments	1.00	1.0
1	Very unsatisfactory - No centralized charging location				•						
2	Unsatisfactory - Centralized charging location, but										
	inadequate in size for number of devices										
3	Average - Charging cart or tower but not adequately										
4	sized for number of devices Satisfactory - Charging cart or tower not centralized										
<del>4</del> 5	Very Satisfactory - Charging cart or tower not centralized  Very Satisfactory - Charging cart or tower located										
3	centralized location. Excellent condition										
N/A	Does not apply							L			
2.4 Is there as	dequate AV for presentations spaces – cafeteria and gym?	1							Comments		
3.4 is there uc	requate AV 101 presentations spaces – careteria and gym:	1							Comments	1.00	1.0
1	Very unsatisfactory - AV not present in one or more										
	space										
2	Unsatisfactory - AV undersized for room, poor condition										
3	Average - Adequately sized / poor condition OR AV										
	undersized / adequate condition										
4	Satisfactory - Good size, good condition										
5	Very Satisfactory - Generous sized, excellent condition										
N/A	Does not apply										
13.5 Is there dig	gital media signage at the reception area?	1							Comments	0.00	0.0
1	Very unsatisfactory - No digital media present in	<u> </u>		<u> </u>					1	0.00	0.0
	reception area										
2	Unsatisfactory - Undersized, poor condition										
3	Average - Adequately sized / poor condition OR										
	undersized / adequate condition										
4	Satisfactory - Media signage present, good sized, good										
5	condition  Very Satisfactory - Generously sized, excellent condition										
	·							L			
N/A	Does not apply										

14 - Administration Spaces	1	2	3	4	5	N/A	4	20.00	45%
ls there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
Very unsatisfactory - No security checkpoint	•			•		-			
2 Unsatisfactory - Checkpoint is too small, poor condition									
3 Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
14.2 Does the administration area feel welcoming?	1						Comments	1.00	1.00
1 Very unsatisfactory - No welcome space									
Unsatisfactory - Too small, poor lighting and									
transparency, limited informal seating, poor condition									
Average - Adequate size and layout, needs updates or									
renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and									
transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of									
light and transparency, informal seating provided, excellent condition									
N/A Does not apply									
For those spaces that require it does the administration area have	I	l		T .		1			
14.3 adequate acoustic privacy?				4			Comments	1.00	4.00
1 Very unsatisfactory - No acoustic separations	1		1			I			
2 Unsatisfactory - Acoustic separations do not perform									
well									
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply				_					
14.4 Are conference rooms easily accessed for public / parent use?	1						Comments	1.00	1.00
Very unsatisfactory - Not accessible for public/parent							No dedicated conference room for public/parent use.		
use									
2 Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition  5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition									
N/A Does not apply							L		