

## **Educational Suitability Summary Report**

McBee Elementary School

Date: 12/15/2020 Score 72% Satisfactory

McBee Elementary School, serving an enrollment of approximately 400 students in north Austin, is known for its community involvement and extracurricular activities. The school is on Braker Lane, which is a busy road, just west of Lamar Boulevard. The location has a lot of activity and getting students in and out of the campus safely is a priority for the school. The school was built in 1999 with a total of approximately 70,000 square feet on 11.5 acres.

The school is in good condition overall. The environmental quality is very satisfactory due to ample daylighting and access to views throughout. Security and the ability to host a variety of programming are issues facing the school.

#### **Interview Overview**

The interview took place with Principal Celorio-Reyes at the school. The custodian joined briefly to review some facility condition assessment items. After the interview, the principal walked the assessment team around the school to highlight some of the issues discussed during the interview. The principal explained that there is great involvement by staff and the community in building a better future for McBee students. They have invested time and resources into curating artwork, building an outdoor studio with the help of parent/teacher volunteers, growing their community garden and planting trees on campus. They are very involved with outside programming such as the Boys & Girls Clubs but due to the lack of community spaces, these programs must take place in the studios, which is not conducive for the number of kids and staff involved. The lack of a dedicated space for the speech therapist was also mentioned.

They would like to be able to expand their extracurricular programs to offer soccer, basketball, chess and bilingual academics, but they need personnel and dedicated spaces for these programs.

In thinking about teaching and learning 20 years from now, the principal relayed many ideas for consideration. These include improved acoustics in studios with mics and sound system to aid with the acquisition of language skills, a state-of-the-art STEM lab, 3D printers for project-based learning, a track for PE, improved charging for devices using formal charging stations, touchless restrooms, and additional outdoor studios with infrastructure such as whiteboards and furniture.

According to the principal, enrollment is dropping due to other charter schools in the area. Adding a digital marquee sign would give the school a better presence along Braker Lane. Appropriate signage and safe access of main roads are also needed. The principal has rerouted pickup/drop-off traffic to accommodate the heavy traffic of Braker Lane; however, it is still not ideal.

In terms of supporting the six C's, the principal believes McBee excels in creativity, collaboration, cultural proficiency, and communication. The school uses the collaboration spaces within the corridors every day, and the learning neighborhoods work well. The maker space is used by all

## **Educational Suitability Summary Report**

McBee Elementary School

studios. After-school programs such as Robotics Club and business partnerships contribute to collaboration and cultural proficiency.

#### **Assessment Findings**

The Educational Suitability Assessment of McBee Elementary School earned a 72% overall score and places the campus in a category of Satisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

#### Average Categories (51-65%):

### **General Building**

Score is average.

Security

The circulation spaces are adequately sized. Community use areas can be accessed after-hours, but all are within the same zone and cannot be used individually, which is something the principal says would be helpful. There is no dedicated community room. Overall, the school displays pride on the interior; however, this could be improved on the exterior.

Score is average.		

#### **Media Resources**

Score is average.

The library has an exterior entrance, but it is not configured well for visitors. There are no spaces provided for quiet study nor for small group collaboration. Mentor/mentee meetings happen while class is in session, and this is problematic. The library is all one open space, which is more conducive for larger group collaboration and social interactions. Technological support in the library is average.

#### Satisfactory Categories (66-80%):

#### **Exterior**

Score is satisfactory.

Site circulation is separate, and pickup and drop-off occur on the back side of the school. Wayfinding within the school could be improved. Signage is present but small. There are three streams for waste, but it seems staff/faculty are not educated on how the system works and all streams tend to end up in the trash.

#### **Outdoor Learning and Activity**

## **Educational Suitability Summary Report**

McBee Elementary School

Score is satisfactory.

The school has invested time into building and maintaining its outdoor learning spaces, including a small pergola and garden beds. Gardens are a work-in-progress, and a cistern would be helpful for more efficient watering. More outdoor learning spaces would be helpful.

There is a larger field to the south of the building, which accommodates a walking loop. There is a walking trail that is used by parents walking their children to and from school through the play area from Kramer Lane.

#### **Controllability of Systems**

Score is satisfactory.

The studios have individual control of thermostats. Blinds are in good condition. Dimming capabilities for artificial lighting could be beneficial at an individual studio level.

#### Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture is in good condition, but more variety would be useful, especially in the cafeteria. Library chairs are one size fits all.

#### **Academics & Learning**

Score is satisfactory.

The studios and storage are adequately sized. The typical studio size is 850 square feet, and pre-K and kindergarten studios are supported with restrooms and ample storage. Special education studios are 950 square feet. Small group breakout spaces are not available. There are two open collaboration spaces that are well-utilized. The maker space and computer lab are along the main corridor. There is no professional learning center or dedicated science room. Circulation spaces are adequately sized but do not offer any opportunities for informal interaction.

#### **Visual and Performing Arts**

Score is satisfactory.

These rooms are appropriately sized per the education specifications and are in good condition. There is general stage storage but no dedicated chair storage.

#### **PE and Wellness**

Score is satisfactory.

The gym is adequately sized and in good condition. There is appropriate storage.

#### **Food Services**

Score is satisfactory.

The cafeteria is generously sized and in good condition. There are two serving lines.

#### **Technology**

Score is satisfactory.

Although there are an adequate number of outlets, organization for charging and storing digital devices is needed. There is no digital signage in the reception area.

#### **Administration Spaces**

Score is satisfactory.

## **Educational Suitability Summary Report**

McBee Elementary School


The reception area is close to the front door, but line of sight is limited. The conference room is not easily accessible to visitors.

## Very Satisfactory Categories (81-100%):

## **Environmental Quality**

Score is very satisfactory.

The school excels in this category due to its layout. The wings allow for ample daylighting and views to all studios. Artificial lighting is satisfactory, although dimming capabilities could be useful. Some studios have covered light fixtures to achieve comfortable light levels. Acoustics in general are satisfactory.



Main entrance covered by canopy from driveway.



Entryway Art: The school takes great pride in this special art piece chosen by the McBee family.



Exterior – South Façade: The studio wings create an exterior area that is not utilized currently for outdoor learning.




The school built its own outdoor learning space/shelter and maintains the gardens. They take great pride in this area.




The cafeteria is adequately sized and has a movable partition separating it from the gymnasium. This provides for flexibility but compromises acoustics.




The gym is in great condition and serves its purpose well. It cannot be accessed independently from the exterior for school-related or other events.



Typical Hallway: The display of art, aspirational college flags and school pride is abundant, although signage and wayfinding could be improved. There is limited visibility from the studios.




Collaboration Space: One of two in the school, this space is used every day by students and extracurricular groups. The school could use more spaces like this.



Typical Studio: Due to the shape of the building, all studios have access to daylight and views. The studios are adequately sized; however, the school could benefit from smaller breakout spaces.



Media Center: There is a good mix of furniture types; however, the chairs are all one size. There could be additional space for accessible seating in the reading area.



Exterior - South Facade:



The detached field across the back drive serves as a recreation space.



South Driveway: The school must use the south driveway for drop-off and pickup since the main drive is located off Braker Lane. It works, but it is not ideal.



Art Studio: Storage is dated but adequate. Sinks are provided.



# Austin ISD Educational Suitability Assessment Criteria

**General Building** 

School Name	Walk Attendees:	Date:
McBee Elementary School	Kendall Claus / Lynn Petermann	12.15.2020

1 - E:	xterior		1	2	3	4	5	N/A	4	8.75	71%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?				4			Comments	1.00	4.00
	1 2 3 4 5 5 N/A	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination Does not apply							Principal reworked pickup and drop-off and currently space.	there is bette	r queue
1.2	Is the build	ing easily identified with appropriate signage and wayfinding?			3				Comments	0.25	0.75
	1 2 3 4 5 N/A	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden Average - Signage / wayfinding visible but not apparent Satisfactory - Signage / wayfinding is visible but not good condition Very satisfactory - Signage and wayfinding is visible and easy to use Does not apply									

Perkins&Will 02/11/2022 <sup>2</sup>

1 - E	xterior (cor	nt.)	1	2	3	4	5	N/A	4		
1.3	ls the dump	oster accessible for trash / compost disposal?			3				Comments	0.50	1.50
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly							Principal discussed that recycling is being deposited that even though dumpsters are present, there are n trash, recycling and compost.		
		adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0	Outdoor Le	arning and Activity	1	2	3	4	5	N/A	4	15.00	80%
2.1	Are outdoo	r studios and support spaces appropriately configured per			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							There is a small pergola that the school built.		
	2 3 4	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2	,	playgrounds (elementary only) and support spaces per the ed spec?				4			Comments	1.00	4.00
	1 2 3	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure							Principal's note - Loose landscape rocks are creating basketball court, back sidewalks, and back commen make it difficult to run and play without risking falling	area. Loose roc	cks
	4 5 N/A	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

2 - 0	Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A			
2.3		s and support spaces appropriately configured per the eduation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score of Outdoor	Learning and	Activity.
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Gardens are a work-in-progress.		
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water									
	4	source is difficult to access Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is									
	5	accessible with 100 ft hose  Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
2.4	Are the rain ed spec?	gardens and/or cisterns appropriately configured per the	1						Comments	0.00	0.00
	1 2	Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not							Monitoring answer, does not affect score of Outdoor	Learning and	Activity.
	3	functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to							No cistern.		
	4	function well Satisfactory - Good size, good condition, functions properly									
	5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces,									
	N/A	educational signage provided									
2.5		Does not apply hool have animal husbandry? (optional)	1						Comments	0.00	0.00
2.0	1	No	'	ı					Comments	0.00	0.00
	5	Yes									
2.6	Does the sc	hool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes	ı								
2.7	Does the sc	hool have a learning pond? (optional)	1						Comments	0.00	0.00
	1 5	No Yes									
2.8		hool have a grass play field and walking trail?					5		Comments	1.00	5.00
	1	No						1			2.20
	5	Yes									

Perkins&Will 02/11/2022 <sup>4</sup>

3	3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	58%
	3.1 Are interio	r circulation routes wide enough to safely and effectively				4			Commonts.		
	accommo	date student movement?				4			Comments	0.50	2.00
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
		wide									
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply		-	-						
		unity use areas arranged so that the school can allow night				4			Comments		
	functions	vithout full school access?								0.75	3.00
	1	Very unsatisfactory - Cafeteria, gym, and library cannot							All can be accessed after-hours but all within same z	one and canno	t be
	•	be accessed after hours							used individually.		
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
		Gym and Library) can be accessed from parking and							The school notes public access to the school grounds	in off-hours ho	ıs led to
	3	secured after hours  Average - Only two of the public spaces can be accessed							vandalism of the playground and unwanted paraphe		
	ა	from parking and secured after hours							campus.	orialia roaria ol	
	4	Satisfactory - All of the public spaces can be accessed							cumpus.		
	7	from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
	3	accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
	_ Is there a	community room that is a dedicated meeting space outside							_		
	3.3 of school f		1						Comments	0.75	0.75
	1	Very unsatisfactory - No dedicated community room									
	2	Unsatisfactory - Community room but within school									
		function, no access after school hours									
	3	Average - Community room, moderate size, but need									
		some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets									
		needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
	5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school									
		Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
	N/A	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply									
	N/A Does the g	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the			3				Comments	0.05	0.75
	N/A  N/A  Does the g students of	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?			3					0.25	0.75
	N/A  N/A  Does the g students of	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor			3				The school reports many dead landscaping plants af	ter the winter s	torm
	N/A  3.4 Does the g students of	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok			3				The school reports many dead landscaping plants af that are located at the front of the school along Brak	ter the winter s er Lane. The gr	torm ounds
	N/A  3.4 Does the g students of 1 2 3	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good			3				The school reports many dead landscaping plants af	ter the winter s er Lane. The gr	torm ounds
	N/A  3.4 Does the g students of	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in			3				The school reports many dead landscaping plants af that are located at the front of the school along Brak	ter the winter s er Lane. The gr	torm ounds
	N/A  3.4 Does the general students of the stud	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works			3				The school reports many dead landscaping plants af that are located at the front of the school along Brak	ter the winter s er Lane. The gr	torm ounds
	N/A  3.4 Does the g students of 1 2 3	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very Unsatisfactory - General appearance shows pride			3				The school reports many dead landscaping plants af that are located at the front of the school along Brak	ter the winter s er Lane. The gr	torm ounds
	N/A  3.4 Does the general students of the stud	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community?  Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works			3				The school reports many dead landscaping plants af that are located at the front of the school along Brak	ter the winter s er Lane. The gr	torm ounds

	4 - Security		1	2	3	4	5	N/A		16.25	
	4.1 Does the fa	cility have key card access at all major entries?							Comments	0.25	
ľ	1	Very unsatisfactory - No entries		•							
	2	Unsatisfactory - 1/4 of major entries									
	3	Average - 1/2 of major entries									
	4	Satisfactory - 3/4 of major entries									
	5	Very satisfactory - All of major entries									
	N/A	Does not apply						_			
	4.2 How adequ	uate is site lighting and security for the campus overall?							Comments	1.00	
	1	Very unsatisfactory - No exterior lighting, no secure									ī
		perimeter									)
	2	Unsatisfactory - Lighting is limited to front entry only,						Ī			
		parking lot lighting poor, security is minimal								,	
	3	Average - Lighting at all night-use entries and parking									
		lot, but poor condition. Security is moderate									
	4	Satisfactory - Lighting at all night-use entries and						ļ			,
		parking lots, good condition, signage less visible,						ļ			
		perimeter is well secured but needs updates						ļ			
	5	Very satisfactory - Signage, parking lots, and entries are									
		well lit, visible and easy to use, perimeter is very secure									
	N/A	Does not apply						L			_
ſ	Is the main	office located at the school entry and configured with a									_
	173	ibule to the main corridor?							Comments	1.00	
L	1	Very unsatisfactory - No secure vestibule, office located								1.00	
	·	far from main entry, allows visitors access to school									
		unsupervised									
	2	Unsatisfactory - No secure vestibule, office located									
		somewhat far from main entry, minimal supervision of									
	_	visitors									
	3	Average - Office close to entry, views of front door, but									
	4	no secure vestibule Satisfactory - Office is well-located with a secure									
	4	vestibule, but needs updates									
	5	Very satisfactory - Office well-located with secure									
	_	vestibule and all appropriate security features									
	N/A	Does not apply						_			
	Is there end	ough interior transparency for faculty to passively supervise							_		_
	// //	d their activities who are not in studios?		2					Comments	1.00 <b>2.0</b>	0
L	1	Very unsatisfactory - No transparency of walls									_
	2	Unsatisfactory - Limited transparency in certain locations									
	3	Average - Good transparency in certain locations but									
	3	inadequate or missing in other locations of school									
	4	Satisfactory - Adequate transparency throughout the									
	7	school									
	5	Very satisfactory - Excellent transparency throughout the									
		school									
	N/A	Does not apply						_			

Perkins&Will 02/11/2022 <sup>6</sup>

	5 - Environmental	Quality	1	2	3	4	5	N/A		25.00	88%
	5.1 How are acous	tics in studios in general?				4			Comments	1.00	4.00
	2 Ur str 3 Av 4 Sc frc 5 Ve	ery unsatisfactory - Recognized word/sound from djacent studio/corridor satisfactory - Audible sound from adjacent udio/corridor serage - Slight sound from outside room atisfactory - Walls to deck insulated only white noise om mechanical system ery satisfactory - Able to hear quiet speaking from cross the room pes not apply									
	5.2 Is the studio art	tificial lighting adequate quality?				4			Comments	1.00	4.00
	th 2 Ur 3 Av 4 Sc 5 Ve	ery unsatisfactory - Sporadic lights work, glare, less an 20 FC nsatisfactory - 10-19 FC or serious glare verage- 20-29 FC minor glare atisfactory - 30-39 FC and no glare ery satisfactory - 40+ FC and no glare poes not apply									
	. 50	to natural light in studios?					5		Comments	1.00	5.00
•	lig 2 Ur lig 3 Av 4 Sc lig 5 Ve	ery unsatisfactory - No learning spaces have natural ght nsatisfactory - 1-25% of learning spaces have natural ght or windows are too small to let in light verage - 26-50% of learning spaces have natural light atisfactory - 51-75% of learning spaces have natural ght ery satisfactory - 76-100% of learning spaces have atural light bees not apply									
	5.4 Is there access	to outside views from learning spaces?					5		Comments	1.00	5.00
	2 Ur wi 3 Av 4 So 5 Ve	ery unsatisfactory - No learning spaces have views insatisfactory - 1-25% of learning spaces have views or indows are too small to see out verage - 26-50% of learning spaces have views attisfactory - 51-75% of learning spaces have views ery satisfactory - 76-100% of learning spaces have ews				•	,				

Perkins&Will 02/11/2022 <sup>7</sup>

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	ouilding have odor or pest problems?				4			Comments	1.00	4.0
1	Very unsatisfactory - Evidence of both pests and odors									
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
- Controllab	ility of Systems	1	2	3	4	5	N/A	1	12.50	68
6.1 Does the s	tudio thermostat allow for individual control?					5		Comments	0.50	2.5
1	No								•	
5	Yes									
6.2 Are shade	s provided to control natural light in learning spaces?				4			Comments	1.00	4.0
1	Very unsatisfactory - No, windows are covered with				•			Blinds in good condition.	•	
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is th	e quality of lighting controls in the studios?		2					Comments	1.00	2.0
1	Very unsatisfactory - Single switch only per room					•				
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>8</sup>

7 - F	urniture, F	ixtures & Equipment	1	2	3	4	5	N/A	4	18.75	69%
7.1	What is the	current condition of the furniture?				4			Comments	0.75	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply									
7.2		ty of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Same furniture used in all spaces							Cafeteria - one type of seating. Some variety within I	ibrary.	
	2	Unsatisfactory - Furniture variety in one multi-use space									
	3	Average - Furniture variety in more than one multi-use									
	4 5	space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than									
	3	two types of furniture									
	N/A	Does not apply				_	1	-			
7.3	How well d space?	oes furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy							Flexible furniture in studios and library but chairs too	big for younge	er
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups							students in library.		
	3	Average - Mix of furniture that can reconfigure but is									
		cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple									
	5	configurations of space Very satisfactory - Furniture is flexible for multiple									
		configurations of space, easy to move and stack									
	N/A	Does not apply		,	,						
7.4	Is the furnit	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair									
	2	combinations too small for grade level Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and									
		desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow									
	N/A	students to be active  Does not apply									

Perkins&Will 02/11/2022 <sup>9</sup>

o Waste		1	2	3	4	5	N/A	5.00	809
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?				4			Comments 0.50	2.0
1 2 3 4 5	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.  Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.  Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location.  The containers have clear signage.  Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.  Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
	Does not apply afeteria (or wherever meals are served) have at least one								
-	een compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?				4			Comments 0.50	2.
2	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	
3	present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.  Average– There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and								
4	consistent. Satisfactory- There are several waste stations as described above								
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria								
N/A	that encourages recycling/composting.  Does not apply								



# Austin ISD Educational Suitability Assessment Criteria

**Academics - Elementary School** 

School Name	Walk Attendees:	Date:
McBee Elementary School	Kendall Claus / Lynn Petermann	12.15.2020

8 - 8	Academics (	& Learning	1	2	3	4	5	N/	Α	70.00	70%
8.1	Are studios	appropriately configured per the ed spec?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected							Studios adequately sized. Studios - 860 SF. Special Edi SF.	ucation studio	s - 950
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning									
	5	spaces Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
8.2		nd Kinder have appropriate support spaces such as and storage per the ed spec?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - None provided  Unsatisfactory - Too small, disconnected, poor condition  Neutral - Adequate size, average condition, needs  updates or renovations to function well  Satisfactory - Good size, connected, good condition  Very Satisfactory - Generous size, connected, excellent									
	N/A	condition Does not apply									

Perkins&Will 02/11/2022 <sup>2</sup>

8 - <i>A</i>	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.3		nave appropriate support spaces such as storage per the				4			Comments		
0.5	ed spec?					7			Comments	1.00	4.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open			3				Comments		
0.4	collaboratio	•			0					1.00	3.00
	1	Very unsatisfactory - No breakout rooms or open							Open collaboration space in 2 portions of the classro	om wings. Well-	
	•	collaboration spaces are provided							utilized.		
	2	Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
	Ü	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
	N1/A	neighborhood, acoustic privacy									
	N/A	Does not apply				ı	1	ı	T		
8.5	-	studios large enough to support project-based learning e teaching modalities?			3				Comments	1.00	0.00
	ana muitipi	Very unsatisfactory - Too small, no flexibility, does not								1.00	3.00
	ı	support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or									
		updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
	N/A	resources, excellent flexibility									
	NI/A										

Perkins&Will 02/11/2022 <sup>3</sup>

cademics	& Learning (cont.)	1	2	3	4	5	N/A			
					4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected to learning spaces Very Satisfactory - Generous size, excellent condition, connected to learning spaces							Computer lab and maker space in rooms C1 and C2. No learning spaces but right along main corridor.	Not connected	to
,		1						Comments	1.00	1.00
1 2 3 4 5	Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected Very Satisfactory - Generous size, excellent condition, connected							·		•
,		1						Comments	0.00	0.00
1 5	No Yes							Recording answer, but doesn't affect overall score.		
					4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No dedicated space Unsatisfactory - Too small, non-dedicated, poor condition Average - Adequate size, adequate condition, needs updates or renovations to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition									
	Are Maker the ed spect 1 2 3 4 5 N/A Is there a Property 1 5 N/A Is there a description of the spect 2 3 Are there a learning (but 1 2 3 4 4 5 1 2 4 1 5 1 2 1 2 1 3 1 4 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2 Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition, connected to learning spaces 5 Very Satisfactory - Generous size, excellent condition, connected to learning spaces N/A Does not apply  Is there a Professional Learning Center in the learning neighborhood?  1 Very unsatisfactory - No dedicated space for Professional Learning Center 2 Unsatisfactory - Too small, poor condition, disconnected 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition, connected 5 Very Satisfactory - Generous size, excellent condition, connected N/A Does not apply  Is there a dedicated science room and support space?  1 No 5 Yes  Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?  1 Very unsatisfactory - No dedicated space 2 Unsatisfactory - Too small, non-dedicated, poor condition 3 Average - Adequate size, adequate condition, needs updates or renovations to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Maker Spaces and support spaces appropriately configured per the ed spec?  1	Are Moker's Spaces and support spaces appropriately configured per the ed spec?  1

Perkins&Will 02/11/2022 <sup>4</sup>

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.10		ilding provide adequate opportunities for			3				Comments		
6.10	students/te	achers to collaborate in varying group sizes?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space to support collaboration							Certain locations allow for collaboration.		
	•	in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
	•	does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options									
	4	to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply		,							
8.11	Does the bu	illding provide opportunities for informal interaction?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No space			<u> </u>					1.00	3.00
	2	Unsatisfactory - Too small, poor condition, layout and									
	_	furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
	_	furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions									
	N/A	Does not apply									
		arning neighborhood / building provide adequate								I	
8.12		es for students to work independently?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No breakout rooms/small study			<u> </u>		<u> </u>		No small group rooms available. Not acoustically sep		
		spaces							The simula group rooms available rest assumed by		
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
	4	or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply									

O2/11/2022 <sup>5</sup>

8 - A	cademics	& Learning (cont.)						
8.13	Are Special spec?	Education spaces appropriately configured per the ed			5	Comments	1.00	5.00
	1	Very unsatisfactory - Too small, no flexibility,		•	•	Life Skills classroom are generously sized and have di	fferent areas f	for
		disconnected				teaching. All support spaces are provided as well.		
	2	Unsatisfactory - Too small, only one area for all teaching						
		methods, limited flexibility, disconnected						
	3	Neutral - Adequate size, multiple areas for different						
		teaching methods, adequate flexibility, limited						
		transparency and connection to other studios and						
		shared learning spaces, needs updates or renovations to						
		function well.						
	4	Satisfactory - Good size, multiple areas for different						
		teaching methods, good flexibility, good transparency						
		and connection to other studios and shared learning						
	5	spaces						
	3	Very Satisfactory - Generous size, multiple areas for						
		different teaching methods, excellent flexibility, generous						
		display area and visual teaching tools, excellent						
		transparency and connection with other studios and						
		shared learning spaces						
	N/A	Does not apply	ı					
8.14	•	Education support spaces, such as storage, space for		4		Comments		
		rer, appropriately configured per the ed spec?					1.00	4.00
	1	Very unsatisfactory - None provided						
	2	Unsatisfactory - Too small, disconnected, poor condition						
	3	Neutral - Adequate size, average condition, needs						
		updates or renovations to function well						
	4	Satisfactory - Good size, connected, good condition						
	5	Very Satisfactory - Generous size, connected, excellent						
		condition						
	N/A	Does not apply						
8.15	Are Accessi	ble restrooms and changing rooms readily available to the			5	Comments	<u></u>	
6.13	Special Edu	ication spaces?			5	Comments	1.00	5.00
	1	No				Changing table provided.	<u></u>	
	5	Yes						

Perkins&Will 02/11/2022 <sup>6</sup>

9	- Visua	ıl and F	Performing Arts	1	2	3	4	5	N/	'A	15.00	80%
	01	music sp the ed s	paces and the cafeteria stage appropriately configured spec?				4			Comments	1.00	4.00
		1	Very unsatisfactory - Too small, missing program spaces							Appropriately sized per Ed Spec. All rooms in good co	ndition.	
		2	Unsatisfactory - Too small, poor condition									
		3	Neutral - Adequate size, adequate condition, needs									
			updates or renovations to function well.									
		4	Satisfactory - Good size, good condition									
		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply									
	9.2 Are	music a	nd performance storage spaces appropriately configured				4			Comments		
	9.2 per	the ed s	pec?				4			Comments	1.00	4.00
		1	Very unsatisfactory - None provided							Stage storage is present but dedicated chair storage	is missing.	
		2	Unsatisfactory - Too small, disconnected, poor condition									
		3	Neutral - Adequate size, average condition, needs									
			updates or renovations to function well									
		4	Satisfactory - Good size, connected, good condition									
		5	Very Satisfactory - Generous size, connected, excellent									
			condition									
		N/A	Does not apply	1	-		1	1				
	<b>V</b> .3		arts spaces and storage appropriately configured per the				4			Comments	1.00	
	ed s	spec?									1.00	4.00
		ı	Very unsatisfactory - Too small, missing program spaces							Appropriately sized per Ed Spec.		
		2	Unsatisfactory - Too small, poor condition									
		3	Average - Adequate size, adequate condition, needs									
			some renovations or updates to function well									
		4	Satisfactory - Good size, good condition									
		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply									

Perkins&Will 02/11/2022 <sup>7</sup>

10 - PE and We	liness	1	2	3	4	5	N/A	1	10.00	80%
10.1 Does the co	impus meet the ed spec standard for physical education				4			Comments		
program sp	aces?				4			Comments	1.00	4.00
1	Very unsatisfactory - Too small, missing program spaces									
2	Unsatisfactory - Too small, poor condition									
3	Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									· ·
Are the phy	rsical education storage spaces appropriately configured									
10.2 per the ed	spec?				4			Comments	1.00	4.00
1	Very unsatisfactory - None provided							Appropriate storage and storage room for exterior.		
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
_	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									
11 - Food Service	es	1	2	3	4	5	N/A	4	10.00	80%
11.1 Is the Dining	g Commons appropriately configured per the ed spec?				4			Comments	1.00	4.00
1								Generous size.	1.00	4.00
'	Very unsatisfactory - Too small, missing program spaces							Generous size.		
2	11 C C T 11 C C T									
	Unsatisfactory - Too small, poor condition, only one									
	option for eating space provided, inadequate circulation									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well									
4	Satisfactory - Good size and condition, good circulation,									
	multiple options for eating space (ex: connection to									
	outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and									
	circulation, multiple options for eating space (ex:									
N/A	connection to outdoor eating space)									
,	Does not apply  d Services support spaces appropriately configured per					l	l l	1		
11.2 the ed spec					4			Comments	1.00	4.00
1	Very unsatisfactory - None provided						<u> </u>	Two serving lines. Adequate size.	1.00	4.00
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
9	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
Ü	condition									
N/A	Does not apply							1		

12 - Media Re	sources	1	2	3	4	5	N/A	4	30.00	57%
121	ary/Media Center easily accessible for the occupants and the school?			3				Comments	1.00	3.00
1	Very unsatisfactory - Not accessible							Library has exterior entrance.		
2	Unsatisfactory - Limited access, difficult to find, no									
	transparency									
3	Average - Adequate accessibility, needs updates or									
4	renovations to function well Satisfactory - Accessible, easy to find, good									
7	transparency, good condition									
5	Very Satisfactory - Accessible, easy to find, excellent									
	transparency, excellent condition									
N/A	Does not apply		ı	1	1	1	1			
12.2 How well	does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1	Very unsatisfactory - No quiet study spaces							All one space.		
2	Unsatisfactory - One area in poor condition, poor									
3	acoustic privacy  Average - One or more areas provided, needing updates									
3	or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media									
	center, good condition, good acoustic privacy									
5	Very Satisfactory - Multiple clusters or small rooms									
	adjacent to media center, excellent condition, excellent									
N/A	acoustic privacy Does not apply									
						I	<u> </u>			
12.3 How well	does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1	Very unsatisfactory - No space									
2	Unsatisfactory - Too small, poor condition, layout and									
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
'	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply		1		1					
	does the Library/Media Center support collaborative work		2					Comments	1.00	
	roups (4-8 students)?  Very unsatisfactory - No breakout rooms, no flexible								1.00	2.00
1	furniture, no support							No definition for small group space. Mentor/mentee r	•	ening
2	Unsatisfactory - Too small, one area, poor condition							at same time while class is there and that is problema	tic.	
3	Average - Adequate size, multiple areas provided,									
	needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media									
_	center, flexible furniture, good condition									
5	Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent									
	condition									
N/A	Does not apply									

Perkins&Will 02/11/2022 9

12 - Media Res	ources - Continued	1	2	3	4	5	N/	/A			
12 5	oes the Library/Media Center support collaborative work oups (10-25)?			3					Comments	1.00	3.00
1 2 3 4 5 N/A 12.6 How well do 1 2 3 4 5 5	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply oes the Library/Media Center support technology?  Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Good - Mix of old and new whiteboards/projectors/etc. Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - Projectors, marker boards, smart			3			<u>T</u>		Comments	1.00	3.00
N/A	boards in most spaces - new condition  Does not apply							L			
13 - Technology	У	1	2	3	4	5	N/	/A		20.00	80%
13.1 How well ed	quipped are the facilities with instructional technology?				4				Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply										
13.2 Is there an a spaces?	adequate number of power and data outlets in learning				4				Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)		_	l		1					

O2/11/2O22 <sup>10</sup>

y (cont.)	1	2	3	3 4	1	5	N/A			
adequate charging locations for devices?				4	1			Comments	1.00	4.00
Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition					-					
equate AV for presentations spaces – cafeteria and gym?				4	1			Comments	1.00	4.00
space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition										
gital media signage at the reception area?	1							Comments	0.00	0.00
Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Does not apply				-	,			Does not affect score. Monitoring answer.		
	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply jital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower located Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply jital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply jital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply  equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply  ital media signage at the reception area?  Very unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower located Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply  equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Generous sized, excellent condition Does not apply  jital media signage at the reception area?  Very unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Satisfactory - Undersized, poor condition Satisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower located very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply  very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition Does not apply  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Undersized, poor condition Satisfactory - Undersized, poor condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	dequate charging locations for devices?  Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower located centralized location. Excellent condition Does not apply  equate AV for presentations spaces - cafeteria and gym?  Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition Nery Satisfactory - Generous sized, excellent condition Does not apply  ital media signage at the reception area?  Very unsatisfactory - No digital media present in reception area Unsatisfactory - Not digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition Satisfactory - Modia signage present, good sized, good condition Very Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition	dequate charging locations for devices?    4

O2/11/2O22 11

14 - Administi	ration Spaces	1	2	3	4	5	N/A	A	20.00	70%
14.1 Is there a visitors?	reception area that functions as a security checkpoint for all							Comments	1.00	
1	Very unsatisfactory - No security checkpoint									)
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply						,			
14.2 Does the	administration area feel welcoming?				4			Comments	1.00	4.0
1	Very unsatisfactory - No welcome space				•					
2	Unsatisfactory - Too small, poor lighting and									
3	transparency, limited informal seating, poor condition Average - Adequate size and layout, needs updates or									
3	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided, excellent condition									
N/A	Does not apply									
For those	spaces that require it, does the administration area have									
	acoustic privacy?				4			Comments	1.00	4.0
1	Very unsatisfactory - No acoustic separations									
2	Unsatisfactory - Acoustic separations do not perform									
3	well  Average - Some acoustic separations function okay, but									
3	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply									
14.4 Are confe	rence rooms easily accessed for public / parent use?			3				Comments	1.00	3.0
1	Very unsatisfactory - Not accessible for public/parent				•					
	use									
2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
Г	good size and condition Very Satisfactory - Excellent accessibility, excellent									
5	transparency, generous size, excellent condition									
N/A	Does not apply							L		