

Norman-Sims Elementary School

Date: 01/25/2021 Score 89% Very Satisfactory

Norman-Sims Elementary School serves an enrollment of approximately 250 students in east Austin. The school fosters a cooperative learning environment that enhances the academic, social and emotional growth of students. The educational programs are aligned with the Early College High School initiative that supports preparation for college level courses beginning in ninth grade.

As part of the 2017 bond program, a brand-new campus at the site of the old Norman Elementary School was completed in 2020, opening to students in January 2021. The scope of work included complete renovation as well as an addition. The school features flexible learning spaces, ample natural light and covered outdoor spaces for learning. Studios are organized around shared open spaces with a variety of seating and small breakout rooms. Transparency from the studios gives teachers the ability to supervise students while in the shared spaces. A central two-story common space and a large outdoor area serve as the library, cafeteria dining and school assembly space. This layout fosters collaboration, connectivity and social interaction on campus.

Interview Overview

The interview was conducted with Principal Wendy Mills and members of the AISD Construction Management Division directly involved in the construction process of the new school. Principal Mills is excited about the school and how the design is already improving teaching methods. The school is currently around half of its planned capacity, but the principal expressed concerns about how the functions of spaces within the building may need to change to accommodate more students. The outdoor green space is well loved by the staff and students, and they worry about its potential loss if portables were ever required on site.

Students are using the collaboration spaces and small group rooms exactly as they are intended. The transparency in these spaces has allowed teachers to divide classes into different sized groups while maintaining passive supervision. This has helped to build trust between students and teachers in the first year. Students in different grade levels are more social with each other, commingling in the common spaces and helping each other learn.

The dispersed dining system has been very successful. They can serve the entire school in an hour and 15 minutes. With the flexibility of seating types in the central common space, students can find the seats they prefer. This has resulted in a significant decrease in behavioral problems during lunch from the typical cafeteria they had at the previous school. Acoustics in the space work very well, but they would like to find a way to incorporate a large projection screen to replace the mobile TV carts that they are currently using.

The school often uses the large covered outdoor area outside the common space. A few minor improvements in the outdoor learning areas would have a positive impact.

Norman-Sims Elementary School

. Teachers have asked for additional seating in the outdoor learning areas so that they have a place to sit while supervising students. The new water cistern system is very impressive, but the staff has had no instruction on how to operate it.

Assessment Findings

The Educational Suitability Assessment of Norman-Sims Elementary School earned an 89% overall score and places the campus in a category of Very Satisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

All playground equipment is new, but there is minimal shade coverage. There are other covered outdoor areas, but they have minimal support spaces. There are two gardens present: one area with raised planter beds and another with two adjacent large cisterns.

Media Resources

Score is satisfactory.

The library is highly visible and directly accessible from the main entry. It is undersized and while there is some of informal seating, there is very limited space for groups to gather for collaborative learning. The Literacy Library located on the second floor is currently used for teacher workspace and was not included in the square footage considerations for the library. There is no projector or screen in the main library space, but there were mobile TV displays present.

Technology

Score is satisfactory.

Most studios have mobile TV displays. Some spaces have projectors or charging carts for devices. No projectors or screens were observed in the dining commons or gym during the assessment and may be installed at a later date.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.

Bus and vehicular traffic are separated, with two drop-off lanes for cars at the front of the school and for buses at the side parking lot. Stack space is adequate for both. There is no signage on the building itself, but a large digital monument sign is located at the intersection in front of the building.

General Building

Score is very satisfactory.

All interior corridors are a generous size. The dining commons, gym and library area accessible from the main entry and can be secured from most of the first-floor spaces and the entire second floor. A community room is present at the secure vestibule for visitors to access after-hours.

Norman-Sims Elementary School

Security

Score is very satisfactory.

Environmental Quality

Score is very satisfactory.

All studios have large windows with ample access to natural light and views of nature. Acoustics in studios is adequate with only minor noise from corridors. There is an odor near the food services area but no evidence of pests.

Controllability of Systems

Score is very satisfactory.

All studios have thermostats for individual temperature control, as well as roller shades for daylight control. Artificial light controls are zoned and dimmable. The HVAC has had glitches since moving in and is an on-going issue.

Furniture, Fixtures, Equipment

Score is very satisfactory.

All furniture is brand new with a variety of seating types in all spaces. It is flexible or mobile to allow for easy reconfiguration and is appropriately sized per grade level.

Academics & Learning

Score is satisfactory.

Studios are well-sized and have great visibility to the outdoors and corridors, as well as multiple options for breakout spaces, including large, shared collaboration spaces and small group rooms. Storage is adequate but could be larger, and all studios have attached restrooms. There are two maker spaces, both with garage doors for extra connection to common areas and direct access to covered outdoor space on the first floor. There are a few tackable wall areas to display 2D student work, but limited areas for 3D display are present.

Visual and Performing Arts

Score is very satisfactory.

The stage is between pre-K and kindergarten dining commons and the gym. It does not have adequate storage, but stage lighting is provided. The music studio is in a different area of the building and not well connected to the stage area, but it has an attached restroom, large instrument storage and a recording/practice room. The art studio is adequately sized with appropriate storage and support, including an attached restroom.

PE and Wellness

Score is very satisfactory.

The gym is adequately sized and has ample natural light and a connected stage. There is large storage space with indoor and outdoor access, as well as a large office and attached restrooms.

Food Services

Score is very satisfactory.

Perkins&Will

Educational Suitability Summary Report

Norman-Sims Elementary School

There is no formal cafeteria. Instead, seating is distributed in common areas around the first floor. There are multiple seating types and areas present for lower grade levels closer to their studios.

Administration Spaces

Score is very satisfactory.

The space is welcoming with lots of natural light, and the offices have good acoustic separation. There is a parent center/community room accessible across the vestibule and a large conference room at the end of the administration corridor.

Supporting Photographs



A community room is easily accessible at the main entry and can be used after-hours.



Media Resources: Library space is small and mostly taken up by stacks with limited area for

Norman-Sims Elementary School

collaboration or furniture.



Dual-sided stage is in the gym, but it is disconnected from the music room and lacks performance lighting or technology.



Gym is well-located with connection to outdoor activity spaces and playgrounds.



Professional learning centers are located in each wing for shared collaboration space.

Norman-Sims Elementary School



Learning neighborhoods have shared breakout rooms along with a common collaborative flex space in the corridors.



Serving lines are very generous and are double-sided. With the distributed dining model, the serving space is separate from the dining area. The principal noted in the interview that this model

Norman-Sims Elementary School

has worked very well for students and developed their autonomy and independence.



Dining commons is a large open corridor space in the main hall off the entry. Pre-K and Kinder dining with size-appropriate furniture is down the hall near the pre-K and kinder wing.

Norman-Sims Elementary School



There are two dedicated maker spaces for lower and upper grades.



Studios are equipped with a mobile TV display and its attached accessories, plus ample whiteboard space on moveable walls. Furniture is appropriately sized per grade level.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Norman-Sims Elementary School	Emilie Ogburn and Kevin Kinsey	1.25.2021

1 - E	xterior		1	2	3	4	5	N/A		8.75	89%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen					•		Parents have 2 drop-off lanes in front of school with	arge stack spa	ce.
		at the same location							Buses drop off at side parking lot.		
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply				ı				1	
1.2		ling easily identified with appropriate signage and			3				Comments		
	community	wayfinding?								0.25	0.75
	1	Very unsatisfactory - Campus has no signage /							New monument sign with digital display. No building	ı signage.	
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									-

Perkins&Will 02/11/2022 ²

1 - E	xterior (co	nt.)	1	2	3	4	5	N/A	A		
1.3	Is the dump	oster accessible for trash / compost disposal?				4			Comments	0.50	2.00
	1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.		,			,		Barrier-free route to dumpsters.		
2-0	-	Does not apply arning and Activities	1	2	3	4	5	N/A		15.00	80%
2.1		or studios and support spaces appropriately configured per	•			4		,,	Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Multiple spaces with shade coverage. Not much infro	astructure supp	ort.
2.2		Does not apply playgrounds (elementary only) and support spaces per the ed spec?			3				Comments	1.00	3.00
	1 2 3 4 5	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure							Playgrounds are brand new, but have minimal shade		
	N/A	Does not apply									

2 - 0	Outdoor Le	arning and Activities (cont)	1	2	3	4	5	N/A	4		
	Are garden	s and support spaces appropriately configured per the ed									
2.3		uation on infrastructure not condition of plants)			3				Comments	0.00	0.00
	1	Very unsatisfactory - No dedicated gardens						ı	Monitoring answer, but does not affect overall score	for Outdoor Le	earning
	2	Unsatisfactory - Too small, poor condition, disconnected							& Activity.		
		from learning spaces, no flexibility, no accessible water							,		
		source							Small learning garden consisting of 4 raised planter b	oeds. Irrigation	า
	3	Average - Adequate size, adequate condition, needs							present in beds.	J	
		some renovations or updates to function well, water							ľ		
		source is difficult to access									
	4	Satisfactory - Good size, good condition, connected to									
		learning spaces, good flexibility, water source is accessible with 100 ft hose									
	5	Very Satisfactory - Generous size, excellent condition,									
	· ·	connected to learning spaces, excellent flexibility, water									
		source is less than 50ft from the garden or has irrigation									
	N/A	Does not apply									
	Are the rain	gardens and/or cisterns appropriately configured per the					_				
2.4	ed spec?						5		Comments	0.00	0.00
	1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, but does not affect overall score	for Outdoor Le	earning
	2	Unsatisfactory - Too small, poor condition, not							& Activity.		•
		functioning, disconnected							,		
	3	Average - Adequate size, adequate condition, is							2 large cisterns and attached planter beds.		
		connected, needs some renovations or updates to									
		function well									
	4	Satisfactory - Good size, good condition, functions									
	5	properly Very Satisfactory - Generous size, excellent condition,									
	5	exceptional functionality, connected to learning spaces,									
		educational signage provided									
	N/A	Does not apply									
2.5	Does the sc	hool have animal husbandry? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes									
2.6	Does the sc	hool have nature loop trails? (optional)	1						Comments	0.00	0.00
	1	No									
	5	Yes		ı				1			
2./		hool have a learning pond? (optional)	1					<u> </u>	Comments	0.00	0.00
	1 5	No Yes									
2.8		hool have a grass play field and walking trail?					5	l	Comments	1.00	5.00
2.0	1	No	1						Comments	1.00	0.00
	5	Yes									

3	3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	93%
	.3.1	r circulation routes wide enough to safely and effectively late student movement?					5		Comments	0.50	2.50
	1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
		wide									
	2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
	3	Average - Primary circulation is 7'-0" to 8'-0" wide									
	4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
	5	Very satisfactory - Primary circulation is 10'-0"+ wide									
	N/A	Does not apply						•			
	3.2 Are commu	unity use areas arranged so that the school can allow night				4			Comments		
	5.2 functions w	vithout full school access?				4			Comments	0.75	3.00
	1	Very unsatisfactory - Cafeteria, gym, and library cannot							Main commons, gym and library are accessible from	main entry. Ab	le to
		be accessed after hours							secure most studios and the entire second floor.		
	2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
		Gym and Library) can be accessed from parking and									
	3	secured after hours Average - Only two of the public spaces can be accessed									
	3	from parking and secured after hours									
	4	Satisfactory - All of the public spaces can be accessed									
		from parking and secured from the rest of the building									
		but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be									
		accessed from parking and locked off from rest of									
		campus for night/evening use with their own entrance									
	N/A	Does not apply									
	3.3 Is there a c	ommunity room that is a dedicated meeting space outside					5		Comments		
	of school fu	unction?					5		Comments	0.75	3.75
	1	Very unsatisfactory - No dedicated community room									
	2	Unsatisfactory - Community room but within school									
		function, no access after school hours									
	3	Average - Community room, moderate size, but need									
	4	some renovations or updates to function well									
	4	Satisfactory - Community room, good size /layout, meets needs /functions well									
	5	Very Satisfactory - Community room, generous size, nice									
	· ·	condition, functions appropriately outside of school									
		function									
	N/A	Does not apply						l.			
	Does the go	eneral appearance of the school convey pride for the					5		Comments		
	students ar	nd community?					J		Comments	0.25	1.25
	1	Very unsatisfactory - General appearance is poor									
	2	Unsatisfactory - General appearance is aged but ok									
	3	Average - General appearance is good									
	4	Satisfactory - General appearance shows pride in									
	F	campus and student works									
	5	Very satisfactory - General appearance shows pride in									
		campus and student works and is welcoming to the									
	N/A	community Does not apply									
	14/7	2000									

4 - Security 1 2 3 4 5 N/A	16.25
4.1 Does the facility have key card access at all major entries? Comments	0.25
1 Very unsatisfactory - No entries	
2 Unsatisfactory - 1/4 of major entries	
3 Average - 1/2 of major entries	
4 Satisfactory - 3/4 of major entries	
5 Very satisfactory - All of major entries	
N/A Does not apply	T
4.2 How adequate is site lighting and security for the campus overall?	1.00
1 Very unsatisfactory - No exterior lighting, no secure perimeter	
2 Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal	
3 Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate	
4 Satisfactory - Lighting at all night-use entries and	
parking lots, good condition, signage less visible,	
perimeter is well secured but needs updates	
5 Very satisfactory - Signage, parking lots, and entries are	
well lit, visible and easy to use, perimeter is very secure	
N/A Does not apply	
Is the main office located at the school entry and configured with a	
4.3 secure vestibule to the main corridor?	1.00
1 Very unsatisfactory - No secure vestibule, office located	
far from main entry, allows visitors access to school	
unsupervised	
2 Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of	
visitors	
3 Average - Office close to entry, views of front door, but	
no secure vestibule	
4 Satisfactory - Office is well-located with a secure	
vestibule, but needs updates	
5 Very satisfactory - Office well-located with secure	
vestibule and all appropriate security features N/A Does not apply	
	T
4.4 Is there enough interior transparency for faculty to passively supervise learners and their activities who are not in studios?	100 500
	1.00 5.00
1 Very unsatisfactory - No transparency of walls 2 Unsatisfactory - Limited transparency in certain locations Large windows into corridors.	
3 Average - Good transparency in certain locations but	
inadequate or missing in other locations of school	
4 Satisfactory - Adequate transparency throughout the school	
scnool Very satisfactory - Excellent transparency throughout the	
school	
N/A Does not apply	

Perkins&Will 02/11/2022 ⁶

5	- Environmer	ntal Quality	1	2	3	4	5	N/A		25.00	92%
:	5.1 How are ac	coustics in studios in general?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Some noise from corridor.		
į	5.2 Is the studio	o artificial lighting adequate quality?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
í	5.3 Is there acc	ess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply									
í	5.4 Is there acc	ess to outside views from learning spaces?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No learning spaces have views	1	1							2.20
	2 3 4 5	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply									

Perkins&Will 02/11/2022 ⁷

5 - Environm	ental Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the	building have odor or pest problems?				4			Comments	1.00	4.00
1	Very unsatisfactory - Evidence of both pests and odors	•				•	•	Odor near food service.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controlla	bility of Systems	1	2	3	4	5	N/A	4	12.50	92%
6.1 Does the	studio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shad	les provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with							Roller shades in studios. No ability to blackout.		
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is t	the quality of lighting controls in the studios?					5		Comments	1.00	5.00
1	Very unsatisfactory - Single switch only per room	•				•	•	Zoned and dimmable.		
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply									

7 - Furniture, I	Fixtures & Equipment	1	2	3	4	5	N/A		18.75	100%
7.1 What is the	e current condition of the furniture?					5		Comments	0.75	3.75
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply							Brand new with wide variety of seating types.		
1 / ')	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?					5		Comments	1.00	5.00
1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture									
7.3 How well a space?	Does not apply does furniture accommodate rapid reconfiguration of a					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is cumbersome to move Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack Does not apply					ı	ī			
7.4 Is the furni	iture ergonomic and size appropriate for grade level?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - Desk with attached chair combinations too small for grade level Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow students to be active Does not apply									

Perkins&Will 02/11/2022 ⁹

nstructions			2	3	4	5	N/A		5.00	6
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?			3				Comments	0.50	1
1 2 3 4	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have	-	1	,				A score for this category is being recorded, but this co- calculated in the overall ESA average. Bins present but no bilingual instructions.	ategory is not	
	visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. Does not apply Ifeteria (or wherever meals are served) have at least one seen compost bin, blue recycle bin, and landfill bin? Are the			3				Comments		
•	d clearly with bilingual and/or image sorting?			O				Comments	0.50	
2	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as							Waste station with three bins present but no signage		



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Norman-Sims Elementary School	Emilie Ogburn and Kevin Kinsey	1.25.2021

8 - Academics	& Learning	1	2	3	4	5	N/A	70.00	93%
8.1 Are studios	appropriately configured per the ed spec?					5		Comments 1.00	5.00
1	Very unsatisfactory - Too small, no flexibility,							Great transparency, well sized, space has numerous breakout are	as.
	disconnected								
2	Unsatisfactory - Too small, only one area for all teaching								
	methods, limited flexibility, disconnected								
3	Neutral - Adequate size, multiple areas for different								
	teaching methods, adequate flexibility, limited								
	transparency and connection to other studios and								
	shared learning spaces, needs updates or renovations to								
4	function well. Satisfactory - Good size, multiple areas for different								
4	teaching methods, good flexibility, good transparency								
	and connection to other studios and shared learning								
	spaces								
5	Very Satisfactory - Generous size, multiple areas for								
	different teaching methods, excellent flexibility, generous								
	display area and visual teaching tools, excellent								
	transparency and connection with other studios and								
	shared learning spaces								
N/A	Does not apply					,			
82	nd Kinder have appropriate support spaces such as				4			Comments	
restrooms o	and storage per the ed spec?							1.00	4.00
1	Very unsatisfactory - None provided							Mobile storage and casework is adequate but could be larger. Res	strooms
2	Unsatisfactory - Too small, disconnected, poor condition							attached.	
3	Neutral - Adequate size, average condition, needs								
	updates or renovations to function well								
4	Satisfactory - Good size, connected, good condition								
5	Very Satisfactory - Generous size, connected, excellent								
	condition								
N/A	Does not apply								

8 - 8		& Learning (cont.)	1	2	3	4	5	N/A			
8.3		have appropriate support spaces such as storage per the					5		Comments		
0.0	ed spec?									1.00	5.00
	1	Very unsatisfactory - None provided							Casework storage is small in the studio, supplemented by	y additional	
	2	Unsatisfactory - Too small, disconnected, poor condition							mobile storage.		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open					5		Comments		
0.4	collaborati	on space?)		Comments	1.00	5.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	5	acoustic privacy Very Satisfactory - Generous size, excellent condition and									
	5	flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
	Aro gonoro	Il studios large enough to support project-based learning						l			
8.5		le teaching modalities?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, no flexibility, does not						l	Flexible spaces with multiple areas to support different g		0.00
	•	support project-based learning							The spaces with multiple dreas to support different g	group sizes.	
	2	Unsatisfactory - Undersized, decentralized resources,									
		limited flexibility									
	3	Average - Adequate size, needs some renovations or									
		updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - 8	Academics (& Learning (cont.)	1	2	3	4	5	N/A	4		
8.6	Are Maker	Spaces and support spaces appropriately configured per					5		Comments		
0.0	the ed spec	?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No dedicated maker spaces							Large studio with garage door access to common are	ea and direct o	access to
	2	Unsatisfactory - Too small, poor condition, disconnected							covered outdoor space		
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
	4	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	Ü	connected to learning spaces									
	N/A	Does not apply									
		,							_		
8.7	Is there a Pr	rofessional Learning Center in the learning neighborhood?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply	1					ı			
8.8	Is there a de	edicated science room and support space?	1						Comments	0.00	0.00
	,	N	<u> </u>					<u> </u>	14 15 1 15 15 15 15 15 15 15 15 15 15 15 1	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9		dequate places to display the evidence and artifacts of		2					Comments		
	learning (bo	oth 2D and 3D)?								1.00	2.00
	1	Very unsatisfactory - No dedicated space							Few tackable areas and no 3D display seen		
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs									
	3	updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	NI/A	Does not apply									

O2/11/2022 ⁴

8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
8.10	Does the bu	uilding provide adequate opportunities for					5		Comments		
6.10	students/te	achers to collaborate in varying group sizes?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No space to support collaboration									
		in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options									
		to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply		,		,					
8.11	Does the bu	uilding provide opportunities for informal interaction?					5		Comments		
										1.00	5.00
	1	Very unsatisfactory - No space							Informal seating in common areas		
	2	Unsatisfactory - Too small, poor condition, layout and									
	0	furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
	4	or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
	5	layout and furnishings support informal interactions									
	N/A	Does not apply									
		arning neighborhood / building provide adequate									
8.12		es for students to work independently?					5		Comments	1.00	5.00
	эррогили	· · · · · · · · · · · · · · · · · · ·							Consultant and the second horses are second	1.00	5.00
	'	Very unsatisfactory - No breakout rooms/small study spaces							Small rooms with good transparency		
	2	Unsatisfactory - Too small, poor condition, no acoustic									
	2	privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
	3	or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
	-	variety of independent work space options, connected to									
		learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
	·	acoustic privacy, variety of independent work space									
		options, connected to learning neighborhood									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁵

8 - A	cademics	& Learning (cont.)								
8.13	•	Education spaces appropriately configured per the ed				5		Comments		
0.10	spec?					3		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, no flexibility,						Great size and connectivity to the other students and	the campus.	
		disconnected								
	2	Unsatisfactory - Too small, only one area for all teaching								
		methods, limited flexibility, disconnected								
	3	Neutral - Adequate size, multiple areas for different								
		teaching methods, adequate flexibility, limited								
		transparency and connection to other studios and								
		shared learning spaces, needs updates or renovations to								
		function well.								
	4	Satisfactory - Good size, multiple areas for different								
		teaching methods, good flexibility, good transparency								
		and connection to other studios and shared learning								
	-	spaces								
	5	Very Satisfactory - Generous size, multiple areas for								
		different teaching methods, excellent flexibility, generous								
		display area and visual teaching tools, excellent								
		transparency and connection with other studios and shared learning spaces								
	N/A	Does not apply								
		Education support spaces, such as storage, space for	Т	Т			1		I	
8.14	•	/er, appropriately configured per the ed spec?			4			Comments	1.00	4.00
	1	Very unsatisfactory - None provided		_			<u> </u>	No washer/ dryer present.	1.00	00
	2	Unsatisfactory - Too small, disconnected, poor condition						in a masher, any or processing		
	3	Neutral - Adequate size, average condition, needs								
	3	updates or renovations to function well								
	4	Satisfactory - Good size, connected, good condition								
	5	Very Satisfactory - Generous size, connected, excellent								
	Ü	condition								
	N/A	Does not apply								
	Are Accessi	ble restrooms and changing rooms readily available to the			—		<u> </u>			
8.15		ucation spaces?				5		Comments	1.00	5.00
	1	No					<u> </u>		1.00	- 0.00
	5	Yes								

Perkins&Will 02/11/2022 ⁶

9 - Visual	l and l	Performing Arts	1	2	3	4	5	N/	A	15.00	87%
01	music s _l the ed s	paces and the cafeteria stage appropriately configured spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Stage in cafeteria has very limited storage. No rigging	g or lighting.	
	2	Unsatisfactory - Too small, poor condition									
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
1	N/A	Does not apply									
Δre r	•	nd performance storage spaces appropriately configured									
0.7	the ed s						5		Comments	1.00	5.00
	1	Very unsatisfactory - None provided				1			Music is far from stage. Music has attached restroom.	. Large instrum	nent
	2	Unsatisfactory - Too small, disconnected, poor condition							storage, and attached recording room.	· ·	
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
1	N/A	Does not apply									
9.3 Are \	Visual A	Arts spaces and storage appropriately configured per the					5		Community		
9.3 ed sp	pec?						5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, missing program spaces							Art storage and support is good, with restroom attach	ned.	
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
1	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁷

	10 - PE and We	ellness	1	2	3	4	5	N/A		10.00	100%
	10.1 Does the co	ampus meet the ed spec standard for physical education					5		Comments		
	program sp	paces?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, missing program spaces							Gym is in great condition with lots of natural light and	d a large stage	e.
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
	10.2 Are the phy	vsical education storage spaces appropriately configured					5		Comments		
	per the ed	spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - None provided							Large storage with indoor/outdoor access. Large office	e. Restroom i	n the
	2	Unsatisfactory - Too small, disconnected, poor condition							gym.		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
	11 - Food Servi	es	1	2	3	4	5	N/A		10.00	100%
	11.1 Is the Dinin	g Commons appropriately configured per the ed spec?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Too small, missing program spaces							Dining takes place in central corridor. Multiple seating	g types.	
	2	Unsatisfactory - Too small, poor condition, only one									
		option for eating space provided, inadequate circulation									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation,									
		multiple options for eating space (ex: connection to outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition and									
	Ü	circulation, multiple options for eating space (ex:									
		connection to outdoor eating space)									
	N/A	Does not apply									
Ì	Are the Foo	od Services support spaces appropriately configured per							_		
	11.2 the ed spec						5		Comments	1.00	5.00
L	1	Very unsatisfactory - None provided			<u> </u>						
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									

12 - Media Resources	1	2	3	4	5	N/A		30.00	73%
12.1 Is the Library/Media Center easily accessible for the occupants and visitors to the school?					5		Comments	1.00	5.00
Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition N/A Does not apply				•			Very transparent. All glass walls. Directly accessible f	rom main entry.	
12.2 How well does the Library/Media Center support quiet study?			3				Comments	1.00	3.00
1 Very unsatisfactory - No quiet study spaces 2 Unsatisfactory - One area in poor condition, poor acoustic privacy 3 Average - One or more areas provided, needing updates							Informal seating but not acoustically separated		
or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy 5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interaction?					5		Comments	1.00	5.00
 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 							Lots of informal seating and transparency promote in	nteraction	
3 Average - Adequate size and condition, needs updates or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions N/A Does not apply									
How well does the Library/Media Center support collaborative work in small groups (4-8 students)?			3				Comments	1.00	3.00
Very unsatisfactory - No breakout rooms, no flexible							Limited areas for small groups		
furniture, no support 2 Unsatisfactory - Too small, one area, poor condition									
3 Average - Adequate size, multiple areas provided,									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition 5 Very Satisfactory - Multiple clusters or small rooms									
5 Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

12 - Media Res	sources - Continued	1	2	3	4	5	N/A	A		
How well o	does the Library/Media Center support collaborative work			3				Comments		
in larger g	roups (10-25)?			0				Comments	1.00	3.00
1	Very unsatisfactory - No gathering areas							Too small with book shelves to accommodate larger	groups.	
2	Unsatisfactory - Too small, one common space, limited									
	seating, poor condition									
3	Average - Adequate size, one common space, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with									
	seating, good condition									
5	Very Satisfactory - Generous size, multiple commons									
	spaces with seating, excellent condition									
N/A	Does not apply									
10 (de control de la la la companya de l			_						
12.6 How well o	does the Library/Media Center support technology?			3				Comments	1.00	3.00
1	Very unsatisfactory - No vis comm tools			<u> </u>		1		Mobile TVs on carts. No projectors		
2	Unsatisfactory - Outdated, poorly functioning, or									
_	insufficient									
3	Good - Mix of old and new whiteboards/projectors/etc.									
4	Satisfactory - Projectors, marker boards, smart boards in									
·	most spaces - good condition									
5	Very Satisfactory - Projectors, marker boards, smart									
· ·	boards in most spaces - new condition									
N/A	Does not apply									
	* * *	,	_	_	4	_	N1//	A	15.00	47 04
13 - Technolog	ly .	1	2	3	4	5	N/A	A	15.00	67%
13.1 How well e	equipped are the facilities with instructional technology?				4			Comments	1.00	4.00
1	Very unsatisfactory - Limited to no technology present in			<u> </u>				Digital projectors and multiple TV sarts	1.00	4.00
'	instructional spaces							Digital projectors and multiple TV carts		
2	Unsatisfactory - One type of technology present									
3	Average - Multiple types of technology, smart boards,									
3	poor condition, limited to only certain areas of school									
4	Satisfactory - Multiple types of technology, smart									
4										
5	boards, good condition. Very Satisfactory - Multiple types of technology, smart									
3	boards, excellent condition									
N/A	Does not apply									
	adequate number of power and data outlets in learning			1	T		T			
1 13 2	adequate number of power and data outlets in learning		2					Comments	100	2.00
spaces?	V			<u> </u>		1			1.00	2.00
1	Very unsatisfactory - Outlet configuration does not							2 per wall		
	support digital devices throughout school (1 per wall)									
2	Unsatisfactory - Outlet configuration support digital									
	devices only in certain areas of school (2 per wall)									
3	Average - Outlet configuration support digital devices									
	but not enough capacity throughout school (3 per wall)									
4	Satisfactory - Outlet configuration support digital									
	devices with adequate coverage and capacity									
	throughout school (>3 per wall)									
5	Very Satisfactory - Excellent outlet configuration to									
5 N/A	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall) Does not apply									

02/11/2022 ¹⁰

13 - Technolog	gy (cont.)	1	2	3	4	5	N,	/A
13.3 Are there of	adequate charging locations for devices?				4			Comments 1.00 4.
1	Very unsatisfactory - No centralized charging location							Some studios have charging carts
2	Unsatisfactory - Centralized charging location, but							
	inadequate in size for number of devices							
3	Average - Charging cart or tower but not adequately							
	sized for number of devices							
4	Satisfactory - Charging cart or tower not centralized							
5	Very Satisfactory - Charging cart or tower located							
	centralized location. Excellent condition							
N/A	Does not apply					_	1	
13.4 Is there ad	equate AV for presentations spaces – cafeteria and gym?						N/	/A Comments 0.00 0. 0
1	Very unsatisfactory - AV not present in one or more							No projector screen in either space. May be installed later
2	Unsatisfactory - AV undersized for room, poor condition							
3	Average - Adequately sized / poor condition OR AV							
	undersized / adequate condition							
4	Satisfactory - Good size, good condition							
5	Very Satisfactory - Generous sized, excellent condition							
N/A	Does not apply							
13.5 Is there dig	gital media signage at the reception area?					5		Comments 0.00 0. 1
1	Very unsatisfactory - No digital media present in					1		TV present
	reception area							
2	Unsatisfactory - Undersized, poor condition							
3	Average - Adequately sized / poor condition OR							
	undersized / adequate condition							
4	Satisfactory - Media signage present, good sized, good condition							
5	Very Satisfactory - Generously sized, excellent condition							
N/A	Does not apply							

	14 - Administro	ation Spaces	1	2	3	4	5	N/A		20.00	100%
	14.1 Is there a revisitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint)	
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply						'			
	14.2 Does the ac	dministration area feel welcoming?					5		Comments	1.00	5.00
	1	Very unsatisfactory - No welcome space							Lots of natural light. New finishes.		
	2	Unsatisfactory - Too small, poor lighting and									
		transparency, limited informal seating, poor condition									
	3	Average - Adequate size and layout, needs updates or									
		renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
	5	transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of									
	3	light and transparency, informal seating provided,									
		excellent condition									
	N/A	Does not apply									
ľ	For those sr	paces that require it, does the administration area have		T							
	1/1/2	acoustic privacy?					5		Comments	1.00	5.00
L	1	Very unsatisfactory - No acoustic separations		l l					Good acoustic separations	1.00	0.00
	2	Unsatisfactory - Acoustic separations do not perform									
		well									
	3	Average - Some acoustic separations function okay, but									
		portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
	N/A	Does not apply									
	14.4 Are confere	ence rooms easily accessed for public / parent use?					5		Comments	1.00	5.00
	1	Very unsatisfactory - Not accessible for public/parent							Community room across vestibule and large conferen	ce at end of a	dmin
		use							corridor.		
	2	Unsatisfactory - Limited access, no transparency, poor									
	•	condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
	4	renovations to function well									
	4	Satisfactory - Good accessibility, good transparency,									
	5	good size and condition Very Satisfactory - Excellent accessibility, excellent									
	3	transparency, generous size, excellent condition									
	N/A	Does not apply									