

Educational Suitability Summary Report

Oak Springs Elementary School

Date: 1/14/2021 Score 58% Average

Oak Springs Elementary School serves an enrollment of approximately 220 students in east Austin. The school was constructed in 1958 with a stand-alone gym building completed in 1984 for a total of approximately 47,000 square feet. The campus serves students from pre-kindergarten through fifth grade.

The building exterior has a dated appearance but is well maintained.

Studios are in average condition overall, and most studios have access to natural light and outdoor views. The learning neighborhoods lack collaboration spaces and reconfigurable furniture in the studios. The school does not have space for collaboration and informal interaction other than the library, which is centrally located but cannot be used for after-hours events. The gym allows after-hours access and has its own separate entry that can be accessed from the parking lot.

The gym and cafeteria spaces need renovation and updates to function well. The cafetorium stage lacks adequate storage, and the stage is not ADA accessible. The kitchen needs updated equipment and additional space to function properly. The gym is appropriately sized, however, there is peeling paint on the walls and uneven flooring. Current storage space is inadequate. The library is in average condition with a mix of old and new furniture. The library does not support quiet study rooms or small collaboration spaces. The library is centrally located, but there is no after-hours access. The music and art programs are in typical studios that do not meet Ed Spec standards.

Corridors are well lit and wide, which makes navigating easier. Wayfinding and signage are limited. Some spaces are not fully ADA compliant and there is no elevator. (Accessibility will be fully covered in the facility condition assessment report but is noted here since it does not create an equitable approach to the school for all students and visitors.) There is a courtyard that houses gardens and outdoor seating but needs upgrades to function well as an outdoor learning space.

Interview Overview

The interview was held with Principal Cynthia Jackson. Studio spaces are adequate in size but would benefit from upgrades and modernization. There are still chalkboards in the studios and technology is also lacking. It was noted that new projectors or smartboards would be helpful. A modernized computer lab is needed since computers and furniture in the lab are dated. Pre-K and early childhood learning spaces need updates. The principal desires a designated science lab, which is being taught out of a regular studio. Some of the programs that are on the school's wish list include technology, coding, science, debate, oratory and Literacy First. They would like to move Communities in Schools from the portables to a space inside the building.

Educational Suitability Summary Report

Oak Springs Elementary School

There are limited outdoor learning spaces. Existing outdoor spaces need furniture and shade to function well. The school has received a grant to develop outdoor learning spaces. The school is also partnering with the National Wildlife Federation and the Monarch Heroes program to build a butterfly garden and wildlife habitats.

The administration needs a dedicated workroom and a bigger conference room. Existing conference room is small and has limited access for visitors and parents.



If renovations or additions were to occur, the principal feels that the oak trees and the library mural should remain as identifying elements of the school. The existing outdoor learning spaces are important to the school and should remain. The location of the school is inextricably tied to the community and is seen as an accessible and beneficial resource.

Thinking forward to the next 20 years, the principal believes that open studio spaces, blended teaching strategies, and project-based exercises are important. Outdoor learning spaces will contribute significantly to curriculum. State-of-the-art facilities and resources for STEAM will be critical. The school will be an opportunity center where students can engage in various life opportunities (STEAM) but are not limited to magnet programming. The school will continue to serve the low-income population while attracting incoming families to a diverse learning community.

Assessment Findings

The Educational Suitability Assessment of Oak Springs Elementary School earned a 58% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Exterior

Score is unsatisfactory.

Traffic congestion can be problem since cars and buses are mixed and have very limited space for stacking. Pedestrians are separated. The dumpsters are not accessible for trash/compost disposal.

General Building

Score is unsatisfactory.

Corridors are 8-10 feet wide and well lit. Cafeteria and library cannot be accessed for after-hours events.

Academics & Learning

Score is unsatisfactory.

Studios are adequate in size overall but lack flexibility and connection to other learning spaces.

Educational Suitability Summary Report

Oak Springs Elementary School

Restrooms are dated and some are not ADA complaint. Storage is not adequate in most studios using old built-in cabinets. There are no breakout rooms or open collaboration spaces. Special education spaces are in typical studios and does not meet the program needs. No maker space is provided.

PE and Wellness

Score is unsatisfactory.

Gym is small and flooring needs to be renovated. Storage is not adequate.

Food Services

Score is unsatisfactory.

The cafeteria stage has inadequate storage and is not ADA accessible. Variety in seating is not provided. Kitchen is on the smaller side and needs updates.

Media Resources

Score is unsatisfactory.

Library is centrally located, but after-hours usage is limited since no exterior access is provided. No quiet study rooms are available. Computers are limited in number and some furniture in the reading space is outdated and not easily reconfigurable.

Average Categories (51-65%):

Security

Score is average.

Controllability of Systems

Score is average.

Studios have individual thermostats. Natural light is adequate in the studios and controlled by blinds that are in poor condition. Switches for artificial light limited to one-way switch system.

Visual and Performing Arts

Score is average.

Music and art spaces are in a typical studio and do not meet Ed Spec requirements. Music and art rooms are adequately sized but share storage space with the art room kiln.

Technology

Score is average.

Most of the projectors in the learning spaces are outdated or do not function. All studios rely on TV displays on a cart.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

The major outdoor space is a central courtyard near the entrance. Stone seats are provided, but it needs shade and updated furniture to function well as an outdoor learning space. Play structures do

Educational Suitability Summary Report

Oak Springs Elementary School

not have shade but are in adequate condition. .

Environmental Quality

Score is satisfactory.

Natural light is adequate in the studios and controlled by blinds that are in poor condition. All learning spaces have access to outdoor views. Acoustics between studios and corridors seemed sufficient during the assessment walk. Some spaces have constant HVAC noise and some odors due the age of the building.

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture is not new but is sturdy and in good condition overall. Some places such as the library have old computer tables, which are bulky and can be hard to move. There is not a variety of furniture.

Administration Spaces

Score is satisfactory.

The conference room

is small and not accessible for parent or community use.




Main entrance is not clearly marked and is not directly accessible from a student drop off area.



Cafeteria stage is not ADA accessible, and storage is inadequate. There is no variety in the types of seating provided.



Corridors are wide and well lit. There are locations for 2D and 3D display in corridors.



Administration Office: Good acoustic privacy in the admin area. Digital media signage is present and is in good condition.



Media Resources: Insufficient computers and outdated furniture is bulky and not flexible.



Media Resources: Space is adequate in size, but no quiet study rooms provided. There is a mix of old and new technology.



Repurposed space used as a workroom.



Academics and Learning: Good natural light in the space. Studio is adapted to current COVID-19 protocols. There is a mix of old and new technology. Projector is outdated and storage space is inadequate.



Pre-K studio: Space is adequate. Storage is not standardized in the studios.



PE and Wellness: Gym is adequately sized but needs updates to function well. Flooring is uneven and outdated. There is shortage of storage space.



Outdoor play areas are provided but do not have shade.



Central courtyard near the entrance serves as outdoor learning space. It needs shade and appropriate furniture to function well.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Oak Springs ES	Patrick Reinhard and Vishwesh Panchal	1/15/2021

1 - E	xterior		1	2	3	4	5	N/A		8.75	46%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							Traffic congestion can be a problem since cars and b	uses mix and h	ave
	2	at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated							very limited space for stacking.		
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place									
	5	like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
	N/A	Does not apply							L		
1.2		ing easily identified with appropriate signage and wayfinding?				4			Comments	0.25	1.00
	1	Very unsatisfactory - Campus has no signage /									
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not good condition									
	5	Very satisfactory - Signage and wayfinding is visible and easy to use									
	N/A	Does not apply									

O2/11/2022 ²

1 Exto	rior (cor	nt.)	1	2	3	4	5	N/A			
1.3 ls	the dump	ster accessible for trash / compost disposal?		2					Comments	0.50	1.00
	1 2 3	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly							Has barriers, not ADA accessible.		
	5	adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
2 - Out	N/A	Does not apply arning and Activity	1	2	3	4	5	N/A		15.00	67%
21 Aı		r studios and support spaces appropriately configured per	•		3			11//	Comments	1.00	3.00
	1 2 3 4	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area							Outdoor spaces are very sparse around the campus. central courtyard near the entrance. It needs shade to function well as an outdoor learning space.		
		Does not apply playgrounds (elementary only) and support spaces		2					Comments		
Z.Z cc	onfigured	per the ed spec?								1.00	2.00
	2	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs							No shades provided at the play areas. Playground a maintained.	rea is iimited a	na well-
	4	some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5 N/A	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

Are gardene and support an area appropriately configured por the ed		
Are gardens and support spaces appropriately configured per the ed		
2.3 spec? (evaluation on infrastructure not condition of plants) 4 Comments	0.00	0.00
1 Very unsatisfactory - No dedicated gardens Good size and near water source. (Monitoring answ		
2 Unsatisfactory - Too small, poor condition, disconnected score for Outdoor Learning and Activity.)	.,	
from learning spaces, no flexibility, no accessible water		
source		
3 Average - Adequate size, adequate condition, needs		
some renovations or updates to function well, water		
source is difficult to access		
4 Satisfactory - Good size, good condition, connected to		
learning spaces, good flexibility, water source is accessible with 100 ft hose		
5 Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water		
source is less than 50ft from the garden or has irrigation		
N/A Does not apply		
Are the rain gardens and/or cisterns appropriately configured per the		
2.4 At the rain gardens and/or esterns appropriately commigated per title 1 Comments	0.00	0.00
1 Very unsatisfactory - No rain gardens or cisterns (Monitoring answer, does not affect score for Outdo		
2 Unsatisfactory - Too small, poor condition, not Activity.)	or Loanning and	u .
functioning, disconnected		
3 Average - Adequate size, adequate condition, is		
connected, needs some renovations or updates to		
function well		
4 Satisfactory - Good size, good condition, functions		
properly		
5 Very Satisfactory - Generous size, excellent condition,		
exceptional functionality, connected to learning spaces,		
educational signage provided N/A Does not apply		
2.5 Does the school have animal husbandry? (optional)	0.00	0.00
1 No	0.00	0.00
5 Yes		
2.6 Does the school have nature loop trails? (optional)	0.00	0.00
1 No	-1	
5 Yes		
2.7 Does the school have a learning pond? (optional) 5 Comments	0.00	0.00
1 No		
5 Yes	100	
2.8 Does the school have a grass play field and walking trail? 5 Comments	1.00	5.00
l No 5 Yes		

3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	49%
3.1 Are interior	circulation routes wide enough to safely and effectively				Δ			Comments		
accommod	ate student movement?				4			Confinents	0.50	2.00
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
	wide									
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are commu	unity use areas arranged so that the school can allow night		0					Comments		
3.2 functions w	rithout full school access?		2					Comments	0.75	1.50
1	Very unsatisfactory - Cafeteria, gym, and library cannot							Access for the community is inadequate for cafeteria	gym and libra	ry.
	be accessed after hours							Both cafeteria and library cannot be accessed with the	ne remainder o	f the
2	Unsatisfactory - Only one of the public spaces (Cafeteria,							school closed during after-hours events.		
	Gym and Library) can be accessed from parking and									
3	secured after hours Average - Only two of the public spaces can be accessed									
3	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply									
33	ommunity room that is a dedicated meeting space outside	1						Comments		
of school fu	unction?								0.75	0.75
7										
1	Very unsatisfactory - No dedicated community room									
2	Unsatisfactory - Community room but within school									
2	Unsatisfactory - Community room but within school function, no access after school hours									
	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need									
2	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well									
3	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need									
3	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets									
2 3 4	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well									
2 3 4 5	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
2 3 4 5 N/A	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply									
2 3 4 5 N/A Does the go	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the					5		Comments	0.25	125
2 3 4 5 N/A Does the go	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the and community?					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students an	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the ad community? Very unsatisfactory - General appearance is poor					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students ar	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the ad community? Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students an	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the ad community? Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students ar	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the ad community? Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students ar	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community? Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance shows pride in					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students ar 1 2 3 4	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community? Very unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works					5		Comments	0.25	1.25
2 3 4 5 N/A 3.4 Does the go students ar 1 2 3 4	Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function Does not apply eneral appearance of the school convey pride for the nd community? Very unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very Satisfactory - General appearance shows pride in					5		Comments	0.25	1.25

4 - Security	1 2 3 4 5 N/A	1	16.25
4.1 Does the facility have key card access at all major entries?		Comments	0.25
1 Very unsatisfactory - No entries 2 Unsatisfactory - 1/4 of major entries 3 Average - 1/2 of major entries 4 Satisfactory - 3/4 of major entries 5 Very satisfactory - All of major entries			
N/A Does not apply		,	
4.2 How adequate is site lighting and security for the campus overall?		Comments	1.00
Very unsatisfactory - No exterior lighting, no secure perimeter			
2 Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal			
Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate			
4 Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates			
Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure	9		
N/A Does not apply			
ls the main office located at the school entry and configured with a		Comments	
secure vestibule to the main corridor?		Comments	1.00
1 Very unsatisfactory - No secure vestibule, office located			
far from main entry, allows visitors access to school			
unsupervised 2 Unsatisfactory - No secure vestibule, office located			
somewhat far from main entry, minimal supervision of			
visitors			
3 Average - Office close to entry, views of front door, but			
no secure vestibule			
4 Satisfactory - Office is well-located with a secure			
vestibule, but needs updates 5 Very satisfactory - Office well-located with secure			
vestibule and all appropriate security features			
N/A Does not apply			
Is there enough interior transparency for faculty to passively supervis		I	
4.4 learners and their activities who are not in studios?	4	Comments	1.00 4.00
l Very unsatisfactory - No transparency of walls			
Unsatisfactory - Limited transparency in certain location	ns		
3 Average - Good transparency in certain locations but			
inadequate or missing in other locations of school			
4 Satisfactory - Adequate transparency throughout the			
school 5 Very satisfactory - Excellent transparency throughout the school	e		
N/A Does not apply		L	

Perkins&Will 02/11/2022 ⁶

5 - Environm	ental Quality	1	2	3	4	5	N/A	4	25.00	80%
5.1 How are	acoustics in studios in general?				4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room									
5.2 Is the stu	Does not apply dio artificial lighting adequate quality?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there of	access to natural light in studios?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply									
	access to outside views from learning spaces?				4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply					L			1.00	4.00

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5 Does the b	ouilding have odor or pest problems?				4			Comments	1.00	4.00
1	Very unsatisfactory - Evidence of both pests and odors		•							
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllabi	ility of Systems	1	2	3	4	5	N/A		12.50	60%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	No									
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?	1						Comments	1.00	1.00
1	Very unsatisfactory - Single switch only per room									
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							L		

Perkins&Will 02/11/2022 ⁸

7 - Furniture, Fixtures	& Equipment	1	2	3	4	5	N/A		18.75	69%
7.1 What is the current o	condition of the furniture?				4			Comments	0.75	3.00
1 Very un	satisfactory - Damaged or broken, non-									
function	ning									
	factory - Torn/ bent/ wrong size									
3 Averag	e - Scratched/dented/marked									
4 Satisfac	ctory - Not new, but sturdy and clean									
5 Very sa	tisfactory - New									
N/A Does no	ot apply									
1.7	ture types being accommodated throughout the nmons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
1 Very Ur	nsatisfactory - Same furniture used in all spaces									
2 Unsatis	factory - Furniture variety in one multi-use space									
	e - Furniture variety in more than one multi-use									
space	e - Turniture variety in more than one matti-use									
	ctory - All multi-use spaces have greater than one									
	furniture									
5 Very sa	tisfactory - All multi-use spaces have greater than									
two typ	es of furniture									
N/A Does no	ot apply									
7.3 How well does furnit	ture accommodate rapid reconfiguration of a			3				Comments		
space?				Ü				Comments	1.00	3.00
-	nsatisfactory - Furniture is fixed or very heavy									
	factory - Furniture does not allow desks to be									
· ·	red as individuals, small groups, or large groups									
_	e - Mix of furniture that can reconfigure but is									
	some to move									
	ctory - Furniture is flexible for multiple									
•	rations of space									
,	tisfactory - Furniture is flexible for multiple rations of space, easy to move and stack									
	· · · · · · · · · · · · · · · · · · ·									
IN/A Does n	ot apply				1	Π	Ι			
	nomic and size appropriate for grade level?				4			Comments	1.00	4.00
·	satisfactory - Desk with attached chair									
	ations too small for grade level									
	factory - Desk with attached chair combinations									
_	e - Mix of studios with tables/loose chairs and vith fixed seats									
4 Very sa	tisfactory - Tables with loose chairs									
•	tisfactory - Tables with loose chairs that allow									
	s to be active									
N/A Does no	ot apply									

Perkins&Will 02/11/2022 ⁹

		1	2	3	4	5	N/A		5.00	40
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?	1						Comments	0.50	0.
1 2 3 4 5	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.							A score for this category is being recorded, but this category calculated in the overall ESA average.	ry is not	
of each: gr	Does not apply afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the			3				Comments		
bins labelle	ed clearly with bilingual and/or image sorting?								0.50	



Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name							Walk Attendees:	Da	te:	
Oak Springs ES						_	Patrick Reinhard and Vishwesh Panchal			
Academics & Learning	1	2	3	4	5	N/A			70.00	47%

- Acade	mics 8	& Learning	1	2	3	4	5	N/	A	70.00	479
8.1 Are s	studios	appropriately configured per the ed spec?			3				Comments	1.00	3.0
	1	Very unsatisfactory - Too small, no flexibility, disconnected							Studios are adequate in size overall but lack flexibilit other learning spaces.	and connecti	on to
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
١	N/A	Does not apply									
27		nd Kinder have appropriate support spaces such as and storage per the ed spec?				4			Comments	1.00	4.0
	1	Very unsatisfactory - None provided							Restrooms are dated and some are not ADA complai	nt. Studio store	age
	2	Unsatisfactory - Too small, disconnected, poor condition							capacity is not adequate in most of them since they r	ely on old built	t-in
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							cabinets which are not sufficient.		
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ²

8 - A	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.3		nave appropriate support spaces such as storage per the			3				Comments		
0.0	ed spec?				3				Comments	1.00	3.00
	1	Very unsatisfactory - None provided							Studio storage capacity is not adequate in most of th	em since they	rely on
	2	Unsatisfactory - Too small, disconnected, poor condition							old built-in cabinets which are not sufficient.		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply				1					· ·
8.4		earning neighborhoods have small group rooms and open	1						Comments		
	collaboration	very unsatisfactory - No breakout rooms or open						<u> </u>		1.00	1.00
	'	collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
	-	flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
	N/A	neighborhood, acoustic privacy Does not apply									
		studios large enough to support project-based learning	l				l	ı			
8.5		e teaching modalities?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not	l	<u> </u>						1.00	2.00
	·	support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
		limited flexibility									
	3	Average - Adequate size, needs some renovations or									
		updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
	_	flexibility									
	5	Very Satisfactory - Generous size, centralized project									
	NI/A	resources, excellent flexibility									

Perkins&Will 02/11/2022 ³

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A			
8.6 Are Maker Spaces and support spaces appropriately configured per the ed spec?	1						Comments	1.00	1.00
 Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility 									
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4 Satisfactory - Good size, good condition, connected to learning spaces									
5 Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
N/A Does not apply									
8.7 Is there a Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
 Very unsatisfactory - No dedicated space for 									
Professional Learning Center									
2 Unsatisfactory - Too small, poor condition, disconnected									
3 Average - Adequate size, adequate condition, needs									
some renovations or updates to function well									
4 Satisfactory - Good size, good condition, connected									
5 Very Satisfactory - Generous size, excellent condition,									
connected									
N/A Does not apply					1	1	T		
8.8 Is there a dedicated science room and support space?	1						Comments	0.00	0.00
1 No							Monitoring answer, but doesn't affect overall score.		
5 Yes									
8.9 Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?			3				Comments	1.00	3.00
1 Very unsatisfactory - No dedicated space									
2 Unsatisfactory - Too small, non-dedicated, poor condition									
3 Average - Adequate size, adequate condition, needs									
updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									

Perkins&Will 02/11/2022 ⁴

1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 3 Comments 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.	8 - A	cademics 8	& Learning (cont.)	1	2	3	4	5	N/A			
students/teachers to collaborate in varying group sizes? Very unsatisfactory - No space	0.10	Does the bu	ilding provide adequate opportunities for		2					Commonts		
in various sizes. 2 Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes 3 Average - Adequate space for collaboration, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 Very Statisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 8.11 Very unsatisfactory - Os small, poor condition, layout and furnishings aupport informal interaction well. 4 Very unsatisfactory - Too small, poor condition, layout and furnishings support informal interactions layout and furnishings support informal interactions 5 Very Statisfactory - Good size, good condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 8.12 Possible and the learning neighborhood of a verage - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.	8.10	students/te	achers to collaborate in varying group sizes?		2					Comments	1.00	2.00
2 Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes 3 Average - Adequates space for callaboration, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Sood size, good condition, multiple options to support a variety of group sizes 8.11 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well A Very analysis of unction well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions N/A Description of furnishings support informal interactions 10 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 11 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions 12 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions 13 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions 14 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 15 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions 16 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 17 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 18 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 18 Very satisfactory - Good size, good condition, layout and furnishings support informal interactions 19 Very Satisfactory - Good size, good condition, layout and furnishin		1	Very unsatisfactory - No space to support collaboration									
does not support a variety of group sizes 3			in various sizes.									
3 Average - Adequate space for collaboration, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 1 Very unsatisfactory - No space 2 Unsatisfactory - No space 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions line and furnishings support informal interactions of provide provide adequate opportunities for renovations to function well. N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - To small, poor condition, layout and furnishings support informal interactions to function well. 2 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions to function well. 3 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		2	Unsatisfactory - Too small, inflexible, only one option,									
updates or renovations to function well. 4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes 8.11 Does the building provide opportunities for informal interaction? 2 Very unsatisfactory - No space 2 Unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, layout and furnishings support informal interactions 5 Very Satisfactory - Good size, good condition, layout and furnishings support informal interactions 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - Room and the provide adequate opportunities for students to work independently? 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - Room and supply 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.			does not support a variety of group sizes									
4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 8.11 Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings support informal interaction well. A verage - Adequate size and condition, layout and furnishings support informal interactions For Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the Laming and provide opportunities for informal interaction well. A verage - Adequate size and condition, layout and furnishings support informal interactions For Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Solvent Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions The very Satisfactory - Too small, poor condition, no acoustic privacy, only one space for independently? Unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood A verage - Adequate size and condition, needs updates or renovations to function well.		3	Average - Adequate space for collaboration, needs									
to support a variety of group sizes Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 8.11 Very unsatisfactory - No space 1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, layout and furnishings support informal interactions 5 Very Satisfactory - Goes rize, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate or privacy, only one space for independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - No breakout rooms/small study spaces 3 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.			updates or renovations to function well.									
8.11 Does the building provide opportunities for informal interaction? 8.11 Very unsatisfactory - Too small, poor condition, layout and furnishings support informal interaction well 8.12 Very unsatisfactory - Too small, poor condition, layout and furnishings support informal interaction well 8.12 Does the learning neighborhood / building provide adequate opportunities for informal interactions 8.12 Does the learning neighborhood / building provide adequate oproportunities for students to work independently? 8.12 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 8.13 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 8.14 Average - Adequate size and condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 8.15 Average - Adequate size and condition, needs updates or renovations to function well.		4	Satisfactory - Good size, good condition, multiple options									
multiple options to support a variety of group sizes N/A Does not apply 8.11 Does the building provide opportunities for informal interaction? 2 0 0 Comments 1,00 2,00 1 Very unsatisfactory - No space 2 Unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 1,00 1,00 1,000			to support a variety of group sizes									
8.11 Does the building provide opportunities for informal interaction? 2		5	Very Satisfactory - Generous size, excellent condition,									
8.11 Does the building provide opportunities for informal interaction? 2 Only library allows informal interaction opportunities.			multiple options to support a variety of group sizes									
1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - No breakout rooms/small study spaces 3 Average - Adequate size and condition, needs updates or renovations to function well.		N/A	Does not apply									
1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - No breakout rooms/small study spaces 3 Average - Adequate size and condition, needs updates or renovations to function well.	8 11	Does the bu	uilding provide apportunities for informal interaction?		2					Comments		
2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.	0.11	2000 1.10 20	·		_							2.00
furnishings do not support informal interaction well 3		1	· · · · · · · · · · · · · · · · · · ·							Only library allows informal interaction opportunities.		
3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		2	·									
or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.			• • • • • • • • • • • • • • • • • • • •									
4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		3										
furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.												
5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		4	,									
layout and furnishings support informal interactions N/A Does not apply		_										
N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		5										
8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		N1/A										
8.12 opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.			* * *		ı	ı						
opportunities for students to work independently? 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.	8.12		· · · · · · · · · · · · · · · · ·			3				Comments		
spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.			•								1.00	3.00
2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		1	•									
privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well.			•									
disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well.		2										
3 Average - Adequate size and condition, needs updates or renovations to function well.												
or renovations to function well.												
		3										
		_										
		4	Satisfactory - Good size and condition, acoustic privacy,									
variety of independent work space options, connected to												
learning neighborhood		_										
5 Very Satisfactory - Generous size, excellent condition,		5										
acoustic privacy, variety of independent work space												
options, connected to learning neighborhood N/A Does not apply		NI/A										

O2/11/2022 ⁵

8 - A	cademics	& Learning (cont.)									
8.13	•	l Education spaces appropriately configured per the ed		2					Comments		
	spec?		<u> </u>	Ь_						1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility,							No dedicated special education studio. It is in typical	studio. No	
		disconnected							washer/dryer provided.		
	2	Unsatisfactory - Too small, only one area for all teaching									
		methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different									
		teaching methods, adequate flexibility, limited									
		transparency and connection to other studios and									
		shared learning spaces, needs updates or renovations to									
		function well.									
	4	Satisfactory - Good size, multiple areas for different									
		teaching methods, good flexibility, good transparency									
		and connection to other studios and shared learning									
	-	spaces									
	5	Very Satisfactory - Generous size, multiple areas for									
		different teaching methods, excellent flexibility, generous									
		display area and visual teaching tools, excellent									
		transparency and connection with other studios and									
	N1/A	shared learning spaces									
	N/A	Does not apply	_	_	1	1	ı	1	T		
8.14	•	l Education support spaces, such as storage, space for	1						Comments	1.00	
		yer, appropriately configured per the ed spec?	Щ.	<u> </u>	<u> </u>					1.00	1.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.15	Are Accessi	ible restrooms and changing rooms readily available to the					5		Commonto		
8.15	Special Edu	ucation spaces?					5		Comments	1.00	5.00
	1	No									
	5	Yes									

Perkins&Will 02/11/2022 ⁶

1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition N/A Does not apply 9.3 Are Yisual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 3 Noutral - Adequate size, adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 6 Very Satisfactory - Good size, good condition 7 Noutral Park Park Park Park Park Park Park Park	9 - 1	Visual and I	Performing Arts	1	2	3	4	5	N/A	4	15.00	53%
2 Unsatisfactory - Too small, poor condition 3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Generous size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Too small, poor condition 1 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 6 Very Satisfactory - Good size, good condition 7 Very unsatisfactory - Too small, poor condition 8 Average - Adequate size, adequate condition, needs some renovations or updates to function well 9 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 7 Average - Adequate size, adequate condition well 9 Satisfactory - Good size, good condition 9 Average - Adequate size, average condition well 9 Satisfactory - Good size, good condition 9 Average - Adequate size, average condition well 9 As at signal and the provided of th	9.1				2					Comments	1.00	2.00
3 Neutral - Adequate size, adequate condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.3 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - Generous size, excellent condition N/A Does not apply 9.3 Average - Adequate size, adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Too small, poor condition 3 Average - Adequate size, adequate function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition 6 Very Satisfactory - Generous size, excellent condition 1 Nusic and art rooms are adequately sized but share storage space with the art room kiln.		1	Very unsatisfactory - Too small, missing program spaces							Music and art spaces are in a regular studio and do r	ot meet ed sp	ecs. No
updates or renovations to function well. 4 Satisfactory - Good size, good condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Good size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		2	Unsatisfactory - Too small, poor condition							storage for cafeteria stage. Stage not ADA accessible		
4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 6 Very Satisfactory - Good size, good condition 7 September 2 Unsatisfactory - Too small, missing program spaces 9 Unsatisfactory - Too small, poor condition 1 Average - Adequate size, adequate condition, needs some renovations or updates to function well 1 Satisfactory - Good size, good condition 5 Very Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		3	Neutral - Adequate size, adequate condition, needs									
5 Very Satisfactory - Generous size, excellent condition N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, missing program spaces 3 Nousic and art rooms are adequately sized but share storage space with the art room kiln. 4 Satisfactory - Too small, poor condition 5 Very Satisfactory - Good size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition 5 Very Satisfactory - Generous size, excellent condition			updates or renovations to function well.									
N/A Does not apply 9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Wisual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, condition 5 Very Satisfactory - Generous size, excellent condition Satisfactory - Generous size, excellent condition Music and art rooms are adequately sized but share storage space with the art room kiln.		4	Satisfactory - Good size, good condition									
9.2 Are music and performance storage spaces appropriately configured per the ed spec? 1		5	Very Satisfactory - Generous size, excellent condition									
9.2 per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition 5 Very Satisfactory - Generous size, excellent condition		N/A	Does not apply									
per the ed spec? 1	0.0	Are music a	nd performance storage spaces appropriately configured			2				Community		
2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition 1 Very Satisfactory - Generous size, excellent condition 1 Very Satisfactory - Generous size, excellent condition	9.2	per the ed s	pec?			3				Comments	1.00	3.00
3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		1	Very unsatisfactory - None provided									
updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		2	Unsatisfactory - Too small, disconnected, poor condition									
4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		3	Neutral - Adequate size, average condition, needs									
5 Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition			updates or renovations to function well									
condition N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		4	Satisfactory - Good size, connected, good condition									
N/A Does not apply 9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		5	Very Satisfactory - Generous size, connected, excellent									
9.3 Are Visual Arts spaces and storage appropriately configured per the ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition			condition									
9.3 ed spec? 1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		N/A	Does not apply									
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition	0.3		arts spaces and storage appropriately configured per the			3				Comments		
2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition	7.0	ed spec?				0				Comments	1.00	3.00
Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition		1	Very unsatisfactory - Too small, missing program spaces							Music and art rooms are adequately sized but share	storage space	with
some renovations or updates to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition		2	Unsatisfactory - Too small, poor condition							the art room kiln.		
4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition		3	Average - Adequate size, adequate condition, needs									
5 Very Satisfactory - Generous size, excellent condition			some renovations or updates to function well									
		4	Satisfactory - Good size, good condition									
N/A Does not apply		5	Very Satisfactory - Generous size, excellent condition									
		N/A	Does not apply									

Perkins&Will 02/11/2022 ⁷

10 - PE and Wellness	1	2	3	4	5	N/A	10.00	50%
Does the campus meet the ed spec standard for physical education			3				Comments	
program spaces?			3				1.00	3.00
1 Very unsatisfactory - Too small, missing program spaces							Gym size meets Ed Spec but flooring needs renovations or upda	es.
2 Unsatisfactory - Too small, poor condition								
Average - Adequate size, adequate condition, needs								
some renovations or updates to function well								
4 Satisfactory - Good size, good condition								
5 Very Satisfactory - Generous size, excellent condition								
N/A Does not apply								
Are the physical education storage spaces appropriately configured		2					Community	
per the ed spec?							Comments 1.00	2.00
1 Very unsatisfactory - None provided					•			
2 Unsatisfactory - Too small, disconnected, poor condition								
 Neutral - Adequate size, average condition, needs 								
updates or renovations to function well								
4 Satisfactory - Good size, connected, good condition								
5 Very Satisfactory - Generous size, connected, excellent								
condition								
N/A Does not apply								
11 - Food Services	1	2	3	4	5	N/A	10.00	50%
11.1 Is the Dining Commons appropriately configured per the ed spec?			3				Comments 1.00	3.00
l Very unsatisfactory - Too small, missing program spaces					•		Cafeteria is 2,000 square feet. With current enrollment, this is a	sufficient
2 Unsatisfactory - Too small, poor condition, only one							size. If school is at capacity, this is slightly undersized by 300 squ	are feet.
option for eating space provided, inadequate circulation								
3 Average - Adequate size and condition, needs updates								
or renovations to function well								
4 Satisfactory - Good size and condition, good circulation,								
multiple options for eating space (ex: connection to								
outdoor eating space)								
5 Very Satisfactory - Generous size, excellent condition and								
circulation, multiple options for eating space (ex:								
connection to outdoor eating space)								
N/A Does not apply	ı		ı			ı		
Are the Food Services support spaces appropriately configured per		2					Comments	
the ed spec?							1.00	2.00
l Very unsatisfactory - None provided							Kitchen is very small at 1,100 square feet, which includes freezer	coolers,
2 Unsatisfactory - Too small, disconnected, poor condition							storage and serving line.	
3 Neutral - Adequate size, average condition, needs								
updates or renovations to function well								
4 Satisfactory - Good size, connected, good condition								
5 Very Satisfactory - Generous size, connected, excellent								
condition								
N/A Does not apply								

12 - Media Resources	1	2	3	4	5	N/A		30.00	50%
Is the Library/Media Center easily accessible for the occupants and			3				Comments		
visitors to the school?	L	L	3				Comments	1.00	3.00
Very unsatisfactory - Not accessible							Library is centrally located but after-hours usage can	be limited sinc	e no
2 Unsatisfactory - Limited access, difficult to find, no							exterior access is provided.		
transparency									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Accessible, easy to find, good									
transparency, good condition 5 Very Satisfactory - Accessible, easy to find, excellent									
5 Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A Does not apply									
***	1	1		T					
12.2 How well does the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 Very unsatisfactory - No quiet study spaces		<u> </u>		1	<u> </u>	1	No quiet study rooms are provided.		
2 Unsatisfactory - One area in poor condition, poor							The quiet stady rooms are provided.		
acoustic privacy									
3 Average - One or more areas provided, needing updates									
or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy									
N/A Does not apply	1	ı		1	I	ı			
12.3 How well does the Library/Media Center support social interaction?			3				Comments	1.00	3.00
1 Very unsatisfactory - No space		l				1		1.00	0.00
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
 Average - Adequate size and condition, needs updates 									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply		ı			1	1	T		
How well does the Library/Media Center support collaborative work in small groups (4-8 students)?			3				Comments	1.00	2.00
1 Very unsatisfactory - No breakout rooms, no flexible	L			1	<u> </u>	1		1.00	3.00
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
3 Average - Adequate size, multiple areas provided,									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

ľ	12 - Media Res	ources - Continued	1	2	3	4	5	N/A	1		
	12.5 How well d	oes the Library/Media Center support collaborative work		2					Comments		
	in larger gr	oups (10-25)?		_					Comments	1.00	2.00
	1	Very unsatisfactory - No gathering areas									
	2	Unsatisfactory - Too small, one common space, limited									
		seating, poor condition									
	3	Average - Adequate size, one common space, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, multiple common spaces with									
		seating, good condition									
	5	Very Satisfactory - Generous size, multiple commons									
		spaces with seating, excellent condition									
	N/A	Does not apply						ı			
	12.6 How well d	oes the Library/Media Center support technology?			3				Comments		
L		•								1.00	3.00
	1	Very unsatisfactory - No vis comm tools									
	2	Unsatisfactory - Outdated, poorly functioning, or									
		insufficient									
	3	Good - Mix of old and new whiteboards/projectors/etc.									
	4	Satisfactory - Projectors, marker boards, smart boards in									
	_	most spaces - good condition									
	5	Very Satisfactory - Projectors, marker boards, smart									
	N1/A	boards in most spaces - new condition									
	N/A	Does not apply									
	13 - Technolog	у	ı	2	3	4	5	N/A		20.00	65%
	13.1 How well e	quipped are the facilities with instructional technology?			3				Comments	100	0.00
		Vancousatisfustamo limita de ma tantonala monare in				ļ	ļ	ļ	NA - L - C Lb	1.00	3.00
	1	Very unsatisfactory - Limited to no technology present in							Most of the projectors in the learning spaces are out	dated or do no	Ī.
	2	instructional spaces Unsatisfactory - One type of technology present							function. All studios rely on TV displays on a cart.		
	3	Average - Multiple types of technology, smart boards,									
	3	poor condition, limited to only certain areas of school									
	4	·									
	-	Satistactory - Multiple types of technology smart									
		Satisfactory - Multiple types of technology, smart									
	5	boards, good condition.									
	5	boards, good condition. Very Satisfactory - Multiple types of technology, smart									
	5 N/A	boards, good condition.									
	N/A	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply							-		
	N/A 13.2 Is there an	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition			3				Comments	1.00	3.00
	N/A	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces?	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces?	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces?	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)			3				Comments	1.00	3.00
_	N/A 13.2 Is there an spaces?	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces? 1	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces? 1	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices			3				Comments	1.00	3.00
_	N/A 13.2 Is there an spaces? 1 2 3	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces? 1 2 3 4	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces? 1 2 3	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to			3				Comments	1.00	3.00
	N/A 13.2 Is there an spaces? 1 2 3 4	boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply adequate number of power and data outlets in learning Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (33 per wall)			3				Comments	1.00	3.00

O2/11/2022 ¹⁰

3 - Technolog	y (cont.)	1	2	(3 4	4	5	N/A	Ą	
13.3 Are there o	dequate charging locations for devices?				4	4			Comments 1.00	4.0
1	Very unsatisfactory - No centralized charging location							ı		
2	Unsatisfactory - Centralized charging location, but									
0	inadequate in size for number of devices									
3	Average - Charging cart or tower but not adequately sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower not centralized									
J	centralized location. Excellent condition									
N/A	Does not apply									
2.4 Is there ad	equate AV for presentations spaces – cafeteria and gym?			,	3				Comments	
3.4 is there do	equate AV for presentations spaces – careteria ana gym:			`	3				1.00	3.0
1	Very unsatisfactory - AV not present in one or more									
	space									
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV									
	undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply	ı	1	1						
13.5 Is there dig	ital media signage at the reception area?				4	4			Comments 0.00	0.0
1	Very unsatisfactory - No digital media present in									
	reception area									
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR									
	undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Very Satisfactory - Generously sized, excellent condition									

14 - Administration Spaces	1	2	3	4	5	N/A		20.00	70%
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
Very unsatisfactory - No security checkpoint					4				
2 Unsatisfactory - Checkpoint is too small, poor condition									
3 Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
14.2 Does the administration area feel welcoming?				4			Comments	1.00	4.00
1 Very unsatisfactory - No welcome space				•	•	•			
 Unsatisfactory - Too small, poor lighting and 									
transparency, limited informal seating, poor condition									
Average - Adequate size and layout, needs updates or									
renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and									
transparency, informal seating provided 5 Very Satisfactory - Generous size and layout, plenty of									
light and transparency, informal seating provided,									
excellent condition									
N/A Does not apply									
For those spaces that require it does the administration area have									
14.3 adequate acoustic privacy?					5		Comments	1.00	5.00
1 Very unsatisfactory - No acoustic separations									
2 Unsatisfactory - Acoustic separations do not perform									
well									
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply	ı	ı	1		1				
14.4 Are conference rooms easily accessed for public / parent use?		2					Comments	1.00	2.00
1 Very unsatisfactory - Not accessible for public/parent							Conference rooms have limited access; very small.		
use									
2 Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition 5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition									
N/A Does not apply									