

Educational Suitability Summary Report

Pecan Springs Elementary School

Date: 12/14/2020 Score 56% Average

Pecan Springs Elementary School serves an enrollment of approximately 260 students. The school is located in east Austin and was built in the 1950s. The building is approximately 58,700 square feet and sits on a 7.5-acre site. The overall condition of the campus is average. Many campus amenities are missing or do not meet modern academic standards.

Two wings of the building have studios that open directly to open exterior courtyards. In corridors and many studio spaces, walls and floors are generally in disrepair and are cracking and wet. Many spaces have issues with temperature controls. Natural light is generally quite sufficient in the studios, but many windows and blinds do not function properly.

Peeling paint, malfunctioning outlets and exposed rough edges around tackboards are also concerns.

Interview Overview

The interview included Principal Andrea Williams and a few teachers. The campus also provided written responses from those who could not attend.

The principal and teachers stated that a sensory room, flexible learning spaces, outdoor studios and common areas for both students and parents are missing from the campus and they would like them to be provided. The library and cafeteria are used to hold community meetings, and only small events can be held in these spaces. The interviewees stated that group rooms, flexible gathering spaces and proper technology are all needed on campus. The speed of the wi-fi is a concern as well.

They noted that the gym is old and not utilized well. Music and art rooms are in typical studios without needed storage, risers, casework or plumbing. Additionally, there is no soundproofing in the music space. Storage is generally insufficient throughout campus.

They also shared many concerns surrounding facility and maintenance issues, including cracked walls, exposed wires, peeling paint and falling or damaged wall panels. Power outlets in studios are quite old and unstable. The principal and school administrators have reported issues with sewage backups in the past.

Wish list items shared during the meeting included green building and outdoor learning

Perkins&Will

Educational Suitability Summary Report

Pecan Springs Elementary School

opportunities, a science lab, flexible common areas and proper technology.

Assessment Findings

The Educational Suitability Assessment of Pecan Springs Elementary School earned a 56% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Academics & Learning

Score is very unsatisfactory.

Studios are small and isolated without access to elements of learning neighborhoods. Attached restrooms are not accessible and do not have a connected sink. Storage is limited to recessed cabinets in poor condition.

Technology

Score is very unsatisfactory.

Power and charging areas are very limited. There are potential safety issues with unstable power outlets in some studios.

Visual and Performing Arts

Score is very unsatisfactory.

Music and art rooms are in typical studios that do not support the functions and do not have enough storage. The art room is missing sinks.

Unsatisfactory Categories (36-50%):

Controllability of Systems

Score is unsatisfactory.

All studios have natural light, but windows and blinds are in poor condition. There are no temperature and humidity control systems in the studios.

Food Services

Score is unsatisfactory.

Cafeteria square footage meets Ed Spec for campus capacity. The food preparation space is insufficient, and no outdoor eating options are provided.

Average Categories (51-65%):

General Building

Score is average.

Studios are open to the outdoor courtyard and have nice natural light. Library and cafeteria have access to outside, but campus doesn't have proper common area or dedicated community room.

Security

Score is average.

Educational Suitability Summary Report

Pecan Springs Elementary School

PE and Wellness

Score is average.

Overall conditions are okay. Equipment is old and needs upgrades. Storage spaces are insufficient.

Media Resources

Score is average.

Media center has adequate space and is well maintained well but has limited areas for quiet study. Upgraded technology is needed as well. There is no projector or screen for large gatherings.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

A learning garden between the studio wings is in poor condition. Outdoor studio has tables and shades but needs upgrades to function more as a studio. No other outdoor learning spaces are provided. The playground equipment is aged and needs upgrades. There is a walking loop and play field in the adjoining Pecan Springs School Park.

Environmental Quality

Score is satisfactory.

Natural lighting conditions are good in all studios. There are acoustic issues in some studios.

Furniture, Fixtures, Equipment

Score is satisfactory.

Most furniture is movable and in good condition.

Administration Spaces

Score is satisfactory.


Administration space is spacious and clean and maintained well. Spaces and finishes were updated in 2019.

Very Satisfactory Categories (81-100%):

Exterior

Score is very satisfactory.

Overall exterior condition is good; roads and playgrounds are clean. The site circulation is separate between buses and vehicle. Signage and wayfinding need improvement.



Studios are small and do not have adequate storage.



Studios' attached restrooms are tight spaces, and most sinks in 100 and 200 wing are not connected to water.




Exterior breezeways connect campus. Outdoor space between wings needs upgrades. There have been recent improvements to courtyard drainage.



Garden is small and needs improvements to function well.



Media Center: Library is in good condition but needs bigger screen and projector.




Cafeteria is accessible to outdoor area, but no outdoor eating space is provided. Small community meetings are held in the cafeteria. Upgrades in 2019 included ceiling, lighting and flooring replacement.



Studio walls are cracking, and paint is failing.



Cafeteria is adequately sized for campus capacity. Kitchen and serving line are undersized.



School marquee is cracked, in poor condition and not visible.



Main entry is well-defined and covered with an awning.



Gym: Adequate space, but storage is insufficient. Sewage backups have flooded one of the storage spaces.



Main entry vestibule is generous but finishes and paint are dated.



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building


	School Na	School Name							Walk Attendees:	Date:	
	Pecan Spr	ings ES							Angela Whitaker-Williams, Lily Zhang	12/10/2020	
1 - Ex	terior		1	2	3	4	5	N/A		8.75	86%
1.1	Does the sit pedestrian	te permit desirable separation of vehicular, bus and traffic?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - Bus, car and pedestrian all happen at the same location Unsatisfactory - Cars and buses mix, pedestrians are separated Average - Buses, cars, and pedestrians are separate but stack space is small Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination Does not apply									
1.2		ing easily identified with appropriate signage and wayfinding?		2					Comments	0.25	0.50
	1 2 3 4 5	Very unsatisfactory - Campus has no signage / wayfinding Unsatisfactory - Signage/wayfinding is faded/hidden Average - Signage / wayfinding visible but not apparent Satisfactory - Signage / wayfinding is visible but not good condition Very satisfactory - Signage and wayfinding is visible and easy to use Does not apply	I								

Perkins&Will 02/11/2022 ²

1 - E:	xterior (con	1	2	3	4	5	N/A				
1.3	Is the dump	ster accessible for trash / compost disposal?				4			Comments	0.50	2.00
	1 2 3 4	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
	5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
	N/A	Does not apply									
2 - 0		arning and Activity	1	2	3	4	5	N/A		15.00	67%
2.1	Are outdoor the ed spec	studios and support spaces appropriately configured per?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No dedicated outdoor studios							Outdoor learning space between studio wings does n	ot have writing	9
	3	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less							surfaces but has tables and shade.		
	4	shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
	5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	N/A	Does not apply									
2.2	-	laygrounds (elementary only) and support spaces per the ed spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No dedicated active playground							Basketball area has shade but playscapes do not. The	e playscapes a	re
	2	Unsatisfactory - Too small, poor condition, no shade provided							rusty. The rubber below the playscapes is wavy and c Basketball court is outdated and paint is old / crackin		ulch.
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
	4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
	5	Very satisfactory - Generous size, excellent condition, full shade coverage over play structure									
	N/A	Does not apply									

2 - Outdoor Learning and Activity (cont)	1	2	3	4	5	N/A		
2.3 Are gardens and support spaces appropriately configured per the ed spec? (evaluation on infrastructure not condition of plants)			3				Comments 0.	.00 0.0 0
Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learnir Activity. Gardens are between studio wings. Sides of raised b failing. Garden in poor condition.	•
3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
4 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
N/A Does not apply								
2.4 Are the rain gardens and/or cisterns appropriately configured per the ed spec?	1						Comments 0.	.00 0.00
Very unsatisfactory - No rain gardens or cisterns Unsatisfactory - Too small, poor condition, not functioning, disconnected Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well							Monitoring answer, does not affect score for Outdoor Learnin Activity.	ng and
4 Satisfactory - Good size, good condition, functions properly								
5 Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided								
N/A Does not apply								
2.5 Does the school have animal husbandry? (optional)	1						Comments 0.	.00 0.00
1 No 5 Yes								
2.6 Does the school have nature loop trails? (optional)	1						Comments 0.	.00 0.00
1 No								
5 Yes								
2.7 Does the school have a learning pond? (optional)	1						Comments 0.	.00 0.00
1 No								
5 Yes								
2.8 Does the school have a grass play field and walking trail?	<u> </u>				5			.00 5.0 0
1 No							Pecan Springs School Park has small exercise loop.	

3	3 - General Bu	ilding	1	2	3	4	5	N/A		11.25	56%
	.3.1	circulation routes wide enough to safely and effectively late student movement?				4			Comments	0.50	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide Average - Primary circulation is 7'-0" to 8'-0" wide Satisfactory - Primary circulation is 8'-0"-10'-0" wide Very satisfactory - Primary circulation is 10'-0"+ wide Does not apply							100 and 200 wing studios do not have interior circulat open directly to courtyard.	ion. Those stu	udios
	3.2 Are commu	unity use areas arranged so that the school can allow night vithout full school access?				4			Comments	0.75	3.00
	1 2 3	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours Average - Only two of the public spaces can be accessed from parking and secured after hours				1			Library and cafeteria have exterior doors. Gym can be campus. Restrooms are not available.		
	4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
	5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
_	N/A	Does not apply			1	1	ı				
	3.3 Is there a co	ommunity room that is a dedicated meeting space outside unction?	1						Comments	0.75	0.75
	1 2 3	Very unsatisfactory - No dedicated community room Unsatisfactory - Community room but within school function, no access after school hours Average - Community room, moderate size, but need some renovations or updates to function well							Campus does not have a dedicated community room.		
	4 5	Satisfactory - Community room, good size /layout, meets needs /functions well Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
	N/A	Does not apply									
	3/1 -	eneral appearance of the school convey pride for the and community?		2					Comments	0.25	0.50
	1 2 3 4 5	Very unsatisfactory - General appearance is poor Unsatisfactory - General appearance is aged but ok Average - General appearance is good Satisfactory - General appearance shows pride in campus and student works Very satisfactory - General appearance shows pride in campus and student works and is welcoming to the community				,					
	N/A	Does not apply									



Perkins&Will 02/11/2022 ⁶

	5 - Environmen	ntal Quality	1	2	3	4	5	N/A		25.00	68%
	5.1 How are a	coustics in studios in general?			3				Comments	1.00	3.00
•	1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply									
	5.2 Is the studi	o artificial lighting adequate quality?		2					Comments	1.00	2.00
	1 2 3 4 5	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare							Glare and aged light fixtures in 100 and 200 wings.		
	N/A	Does not apply									
	5.3 Is there acc	tess to natural light in studios?					5		Comments	1.00	5.00
	1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios have windows. The 100 and 200 wings ha	ve large windo	ows.
		Does not apply									
		ess to outside views from learning spaces?					5		Comments	1.00	5.00
	1 2 3 4	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views									
	5	Very satisfactory - 76-100% of learning spaces have views									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	A		
5.5 Does the b	uilding have odor or pest problems?		2					Comments	1.00	2.00
1	Very unsatisfactory - Evidence of both pests and odors	•			•		•	There is a moldy odor in 300 wing.		
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	\	12.50	44%
6.1 Does the st	tudio thermostat allow for individual control?	1						Comments	0.50	0.50
1	No							Limited AC control in 100/200 wing.		
5	Yes									
6.2 Are shades	s provided to control natural light in learning spaces?			3				Comments	1.00	3.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
1	Very unsatisfactory - Single switch only per room							100/200 wing has dual switching and vacancy senso	rs.	
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	Does not apply							,		

7 - Furniture, Fixtures & Equipment	1	2	3	4	5	N/A		18.75	69%
7,1 What is the current condition of the furniture?				4			Comments	0.75	3.00
l Very unsatisfactory - Damaged or broken, non-									
functioning									
2 Unsatisfactory - Torn/ bent/ wrong size									
3 Average - Scratched/dented/marked									
4 Satisfactory - Not new, but sturdy and clean									
5 Very satisfactory - New									
N/A Does not apply									
7.2 Are a variety of furniture types being accommodated throughout the school - learning commons, dining commons, other multi-use spaces?			3				Comments		
school - learning commons, aining commons, other multi-use spaces?								1.00	3.00
Very Unsatisfactory - Same furniture used in all spaces					ı				
2 Unsatisfactory - Furniture variety in one multi-use space									
3 Average - Furniture variety in more than one multi-use									
space									
4 Satisfactory - All multi-use spaces have greater than one									
type of furniture									
5 Very satisfactory - All multi-use spaces have greater than two types of furniture									
N/A Does not apply									
How well does furniture accommodate rapid reconfiguration of a				I		l			
7.3 space?			3				Comments	1.00	3.00
Very Unsatisfactory - Furniture is fixed or very heavy									
2 Unsatisfactory - Furniture does not allow desks to be									
configured as individuals, small groups, or large groups									
3 Average - Mix of furniture that can reconfigure but is cumbersome to move									
4 Satisfactory - Furniture is flexible for multiple									
configurations of space									
5 Very satisfactory - Furniture is flexible for multiple									
configurations of space, easy to move and stack									
N/A Does not apply									
7.4 Is the furniture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
Very unsatisfactory - Desk with attached chair				1				1.00	7.00
combinations too small for grade level									
Unsatisfactory - Desk with attached chair combinations									
3 Average - Mix of studios with tables/loose chairs and									
desks with fixed seats									
4 Very satisfactory - Tables with loose chairs									
5 Very satisfactory - Tables with loose chairs that allow									
students to be active									
N/A Does not apply									

Perkins&Will 02/11/2022 ⁹

o Waste		1	2	3	4	5	N/A	5.00	40
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?			3				Comments 0.50	1
2	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.					I	l	A score for this category is being recorded, but this category is not calculated in the overall ESA average. Bins are present and not marked in multiple languages.	t
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.								
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.								
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.								
N/A	Does not apply								
of each: gre	feteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the d clearly with bilingual and/or image sorting?	1						Comments 0.50	(
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.							A score for this category is being recorded, but this category is not calculated in the overall ESA average.	t
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.							Cafeteria is not in use due to COVID-19. No bins were visible.	
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.								
4	Satisfactory- There are several waste stations as described above								
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.								
N/A	Does not apply								



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Pecan Springs ES	Angela Whitaker-Williams, Lily Zhang	12.20.2020

- Academics	& Learning	1	2	3	4	5	N/A	A	70.00	30%
8.1 Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility,							All studios are isolated without access to elements of	learning	
	disconnected							neighborhood such as small group areas.		
2	Unsatisfactory - Too small, only one area for all teaching									
	methods, limited flexibility, disconnected							All studios are slightly undersized at 825SF.		
3	Neutral - Adequate size, multiple areas for different									
	teaching methods, adequate flexibility, limited									
	transparency and connection to other studios and									
	shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different									
	teaching methods, good flexibility, good transparency									
	and connection to other studios and shared learning									
	spaces									
5	Very Satisfactory - Generous size, multiple areas for									
	different teaching methods, excellent flexibility, generous									
	display area and visual teaching tools, excellent									
	transparency and connection with other studios and									
N/A	shared learning spaces Does not apply									
Do Pre-K a	nd Kinder have appropriate support spaces such as						l			
X')	and storage per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - None provided							Studios are small. Attached restrooms are not access		
2	Unsatisfactory - Too small, disconnected, poor condition							connected sink.		
3	Neutral - Adequate size, average condition, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

Perkins&Will 02/11/2022 ²

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	4		
8.3		nave appropriate support spaces such as storage per the		2					Comments		
0.0	ed spec?			_					Comments	1.00	2.00
	1	Very unsatisfactory - None provided							Storage is limited to recessed cabinets in poor conditi	on.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4	Do typical le	earning neighborhoods have small group rooms and open	1						Comments		
0.4	collaboration	on space?	_						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
		neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	_	acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply		ı	ı	1		1	T		
8.5	•	studios large enough to support project-based learning		2					Comments	1.00	
		e teaching modalities?		<u> </u>	<u> </u>					1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not									
	•	support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
	*	flexibility									
	5	Very Satisfactory - Generous size, centralized project									
	v	resources, excellent flexibility									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ³

8 - Acade	mics & Learning (cont.)	1	2	3	4	5	N/A			
8 6	Maker Spaces and support spaces appropriately configured per	1						Comments		
the e	d spec?	'						Comments	1.00	1.00
	1 Very unsatisfactory - No dedicated maker spaces									
	2 Unsatisfactory - Too small, poor condition, disconnected									
	from learning spaces, no flexibility									
	3 Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
	4 Satisfactory - Good size, good condition, connected to									
	learning spaces									
	5 Very Satisfactory - Generous size, excellent condition,									
	connected to learning spaces									
N	N/A Does not apply		1						T	
8.7 Is the	ere a Professional Learning Center in the learning neighborhood	? 1						Comments	1.00	1.00
	1 Very unsatisfactory - No dedicated space for									
	Professional Learning Center									
	2 Unsatisfactory - Too small, poor condition, disconnected									
	3 Average - Adequate size, adequate condition, needs									
	some renovations or updates to function well									
	4 Satisfactory - Good size, good condition, connected									
	5 Very Satisfactory - Generous size, excellent condition,									
	connected									
N	N/A Does not apply									
8.8 Is the	ere a dedicated science room and support space?	1						Comments		
0.0 10 1110								Comments	0.00	0.00
	1 No							Monitoring answer, but doesn't affect overall score.		
	5 Yes									
8.9 Are the	here adequate places to display the evidence and artifacts of		0					Community		
8.9 learn	ing (both 2D and 3D)?		2					Comments	1.00	2.00
	1 Very unsatisfactory - No dedicated space		•					In studios, tackboards are layered on top of other tag	kboards with	nails
	2 Unsatisfactory - Too small, non-dedicated, poor							and rough edges showing. Exterior corridors do not h	ave display ar	eas.
	condition								, ,	
	3 Average - Adequate size, adequate condition, needs									
	updates or renovations to function well									
	4 Satisfactory - Good size, good condition							Bulletin boards or white boards outdated. Many of le	arnina enaces	ctill
	5 Very Satisfactory - Generous size, excellent condition							bulletin boards of white boards outdated. Many of Re	surning spaces	SUII
N.	J/A Does not apply									

Perkins&Will 02/11/2022 ⁴

8 - Aca	demics 8	& Learning (cont.)	1	2	3	4	5	N/A	4		
Do	oes the bu	ilding provide adequate opportunities for	-								
8.10 st	udents/te	achers to collaborate in varying group sizes?	ı						Comments	1.00	1.00
	1	Very unsatisfactory - No space to support collaboration		•		•				•	
		in various sizes.									
	2	Unsatisfactory - Too small, inflexible, only one option,									
		does not support a variety of group sizes									
	3	Average - Adequate space for collaboration, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition, multiple options									
		to support a variety of group sizes									
	5	Very Satisfactory - Generous size, excellent condition,									
		multiple options to support a variety of group sizes									
	N/A	Does not apply									
9 11 D	oes the hi	uilding provide opportunities for informal interaction?	1						Comments		
0.11									Comments	1.00	1.00
	1	Very unsatisfactory - No space							Only space outdoors		
	2	Unsatisfactory - Too small, poor condition, layout and									
		furnishings do not support informal interaction well									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size, good condition, layout and									
	-	furnishings support informal interactions									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	layout and furnishings support informal interactions									
_	N/A	Does not apply		1		1				I	
		arning neighborhood / building provide adequate	1						Comments		
op	·	es for students to work independently?								1.00	1.00
	1	Very unsatisfactory - No breakout rooms/small study									
		spaces									
	2	Unsatisfactory - Too small, poor condition, no acoustic									
		privacy, only one space for independent work,									
		disconnected from learning neighborhood									
	3	Average - Adequate size and condition, needs updates									
		or renovations to function well.									
	4	Satisfactory - Good size and condition, acoustic privacy,									
		variety of independent work space options, connected to									
	_	learning neighborhood									
	5	Very Satisfactory - Generous size, excellent condition,									
		acoustic privacy, variety of independent work space									
	N1/A	options, connected to learning neighborhood									
	N/A	Does not apply									

Perkins&Will 02/11/2022 ⁵

8 - A	cademics :	& Learning (cont.)								
8.13	Are Special spec?	Education spaces appropriately configured per the ed		2				Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected						Undersized at 825 SF.		
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected								
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.								
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces								
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and								
		shared learning spaces								
	N/A	Does not apply	1	1		ı	1		1	
8.14		Education support spaces, such as storage, space for ver, appropriately configured per the ed spec?		2				Comments	1.00	2.00
	1	Very unsatisfactory - None provided						Support spaces are inadequate. There is no washer of	or dryer. Storaç	ge is
	2	Unsatisfactory - Too small, disconnected, poor condition						limited to cabinets only.		
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well								
	4	Satisfactory - Good size, connected, good condition								
	5	Very Satisfactory - Generous size, connected, excellent condition								
	N/A	Does not apply								
8.15		ble restrooms and changing rooms readily available to the acation spaces?	1					Comments	1.00	1.00
	1	No						No changing areas are available. Restrooms are not	accessible and	d do not
	5	Yes						have a sink		

Perkins&Will 02/11/2022 ⁶

9 - V	isual and l	Performing Arts	1	2	3	4	5	N/A	4	15.00	33%
9.1	Are music sper the ed s	•		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Music is in a standard studio and does not have ade	quate storage	or
	2	Unsatisfactory - Too small, poor condition							acoustics.		
	3	Neutral - Adequate size, adequate condition, needs									
		updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
9.2	Are music a	nd performance storage spaces appropriately configured		0					Community		
9.2	per the ed s	pec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided					•				
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
9.3	Are Visual A	arts spaces and storage appropriately configured per the	1						Comments		
9.3	ed spec?		-						Comments	1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							Visual arts is in a standard studio and does not have	sinks or storag	e per
	2	Unsatisfactory - Too small, poor condition							Ed Spec.		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

O2/11/2O22 ⁷

	10 - PE and V	Vellness	1	2	3	4	5	N/A	4	10.00	60%
	10.1 Does the	campus meet the ed spec standard for physical education			3				Comments		
	program	spaces?)				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces									
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply			1						
	10.2	hysical education storage spaces appropriately configured			3				Comments		
	per the e	· · · · · · · · · · · · · · · · · · ·							33	1.00	3.00
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	N/A	condition Does not apply									
	11 - Food Ser		1	2	2	4	E	NI/A		10.00	400/
	11 - F000 Ser	vices	- 1	2	3	4	5	N/A		10.00	40%
	11.1 Is the Dir	ing Commons appropriately configured per the ed spec?		2					Comments	1.00	2.00
ı	1	Very unsatisfactory - Too small, missing program spaces							The campus does not have outdoor dining spaces. Co		
	2	Unsatisfactory - Too small, poor condition, only one							sized for campus capacity, but finishes need updating		quatory
	2	option for eating space provided, inadequate circulation							sized for earnpus capacity, but mismes freed aparting	9.	
	3	Average - Adequate size and condition, needs updates									
	Ū	or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation,									
		multiple options for eating space (ex: connection to									
		outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition and									
		circulation, multiple options for eating space (ex:									
		connection to outdoor eating space)									
	N/A	Does not apply			1						
	11.2	ood Services support spaces appropriately configured per		2					Comments		
	the ed sp			L	<u> </u>		<u> </u>	<u> </u>		1.00	2.00
	1	Very unsatisfactory - None provided							Kitchen and serving line are undersized.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	N/A	condition									
		Doos not apply									

12 - Media Resources			2	3	4	5	N/A	4	30.00	63%
12.1 Is the Library visitors to the	ry/Media Center easily accessible for the occupants and he school?				4			Comments	1.00	4.00
1 2 3	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or							Library/media center is in a detached building with its ov	vn exterior	access.
4	renovations to function well Satisfactory - Accessible, easy to find, good									
5	transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A	Does not apply									
12.2 How well d	oes the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 2	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy							There are no independent study areas.		
3	Average - One or more areas provided, needing updates or renovations to function well									
4 5	Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms									
	adjacent to media center, excellent condition, excellent acoustic privacy									
N/A	Does not apply		ı				ı			
	12.3 How well does the Library/Media Center support social interaction?				4			Comments	1.00	4.00
1 2	Very unsatisfactory - No space									
2	Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
Ĭ	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply									
1.7 /1	oes the Library/Media Center support collaborative work		2					Comments		
in small gro	oups (4-8 students)?		_					Comments	1.00	2.00
1	Very unsatisfactory - No breakout rooms, no flexible							There are no small group rooms but furniture is flexible.		
0	furniture, no support									
2	Unsatisfactory - Too small, one area, poor condition									
3	Average - Adequate size, multiple areas provided, needing updates or renovations to function well									
4	Satisfactory - Clusters or small rooms adjacent to media									
7	center, flexible furniture, good condition									
5	Very Satisfactory - Multiple clusters or small rooms									
· ·	adjacent to media center, flexible furniture, excellent									
	condition									
N/A	Does not apply							,		

12 - Media Resources - Continued		1	2	3	4	5	N/A			
How well o	does the Library/Media Center support collaborative work					5		Comments		
in larger g	roups (10-25)?					5		Comments	1.00	5.00
1	Very unsatisfactory - No gathering areas									
2	Unsatisfactory - Too small, one common space, limited									
	seating, poor condition									
3	Average - Adequate size, one common space, needs									
	updates or renovations to function well									
4	Satisfactory - Good size, multiple common spaces with									
	seating, good condition									
5	Very Satisfactory - Generous size, multiple commons									
	spaces with seating, excellent condition									
N/A	Does not apply									
12.6 How well o	does the Library/Media Center support technology?			3				Comments	1.00	
									1.00	3.00
1	Very unsatisfactory - No vis comm tools							Library needs a big projector and screen for large ga	therings. The s	speakers
2	Unsatisfactory - Outdated, poorly functioning, or							need to be updated.		
	insufficient									
3	Good - Mix of old and new whiteboards/projectors/etc.									
4	Satisfactory - Projectors, marker boards, smart boards in									
	most spaces - good condition									
5	Very Satisfactory - Projectors, marker boards, smart									
	boards in most spaces - new condition									
N/A	Does not apply									
13 - Technolog	у	1	2	3	4	5	N/A		20.00	35%
13.1 How well e	equipped are the facilities with instructional technology?		2					Comments	1.00	2.00
1	Very unsatisfactory - Limited to no technology present in						1	All studios have an edu-display.		
	instructional spaces							, ,		
2	Unsatisfactory - One type of technology present									
3	Average - Multiple types of technology, smart boards,									
	poor condition, limited to only certain areas of school									
4	Satisfactory - Multiple types of technology, smart									
	boards, good condition.									
5	Very Satisfactory - Multiple types of technology, smart									
	boards, excellent condition									
N/A	Does not apply	1				1			ı	
13.2	adequate number of power and data outlets in learning	1						Comments		
spaces?									1.00	1.00
'	Very unsatisfactory - Outlet configuration does not							Power and data in studios are limited to one on teac	hing wall. Old	er powe
	support digital devices throughout school (1 per wall)							in studios is not stable to use.		
2	Unsatisfactory - Outlet configuration support digital									
	devices only in certain areas of school (2 per wall)									
3	Average - Outlet configuration support digital devices									
	but not enough capacity throughout school (3 per wall)									
4	Satisfactory - Outlet configuration support digital									
	devices with adequate coverage and capacity									
_	throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to									
5	support digital devices throughout school (>3 per wall)									
N/A	Does not apply									

O2/11/2022 ¹⁰

3 - Technolog	gy (cont.)	1	2	3	4	5	N/	/A
13.3 Are there	adequate charging locations for devices?	1						Comments 1.00 1.
1 2 3 4 5	Very unsatisfactory - No centralized charging location Unsatisfactory - Centralized charging location, but inadequate in size for number of devices Average - Charging cart or tower but not adequately sized for number of devices Satisfactory - Charging cart or tower not centralized Very Satisfactory - Charging cart or tower located centralized location. Excellent condition				-			There are no charging areas and not enough power in studios to charge
N/A	Does not apply							
	dequate AV for presentations spaces – cafeteria and gym?			3				Comments 1.00 3
1 2 3 4 5	Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition							
N/A 13.5 Is there dig	Does not apply gital media signage at the reception area?						5	5 Comments 0.00 0 .
1 2 3 4 5	Very unsatisfactory - No digital media present in reception area Unsatisfactory - Undersized, poor condition Average - Adequately sized / poor condition OR undersized / adequate condition Satisfactory - Media signage present, good sized, good condition Very Satisfactory - Generously sized, excellent condition					1		0.00
N/A	very Satisfactory - Generously sized, excellent condition Does not apply							

14 -	Administro	ation Spaces	1	2	3	4	5	N/A	i.	20.00	75%
14.1	Is there a re visitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint									
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
14.2	Does the ac	dministration area feel welcoming?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No welcome space					•	•			
	2	Unsatisfactory - Too small, poor lighting and									
		transparency, limited informal seating, poor condition									
	3	Average - Adequate size and layout, needs updates or									
		renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
	_	transparency, informal seating provided									
	5	Very Satisfactory - Generous size and layout, plenty of									
		light and transparency, informal seating provided,									
	N/A	excellent condition Does not apply									
		paces that require it, does the administration area have				1					
14.3		acoustic privacy?				4			Comments	1.00	4.00
-	1	Very unsatisfactory - No acoustic separations						-		1.00	
	2	Unsatisfactory - Acoustic separations do not perform									
		well									
	3	Average - Some acoustic separations function okay, but									
		portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
	N/A	Does not apply									
14.4	Are confere	ence rooms easily accessed for public / parent use?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Not accessible for public/parent									
		use									
	2	Unsatisfactory - Limited access, no transparency, poor									
		condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
		renovations to function well									
	4	Satisfactory - Good accessibility, good transparency,									
	-	good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent									
	N/A	transparency, generous size, excellent condition Does not apply									
	IN/A	DOGS HOL UDDIV									