



Educational Suitability Summary Report

Reilly Elementary School

Date: 02/05/2021

Score 54% Average

Reilly Elementary School, serving an enrollment of approximately 250 students in north central Austin, is known for its dual-language Spanish and Chinese programs, Creating Learning Initiative, and Social and Emotional Learning. The school was constructed in 1954 and consists of 41,600 square feet on 4 acres. The school abuts Reilly School Park, and the expansive grounds adjacent to Waller Creek feel open and inviting. The school is at the corner of Denson Drive and Guadalupe Street. Both have protected bike lanes and queueing for pickup and drop-off has been reconfigured to accommodate these lanes.

The school is efficiently designed in terms of orientation of corridors and studios. All spaces are very well daylit and have great views to the outdoors. There is attention being given to the exterior spaces, including a new playground and the presence of several rainwater cisterns. The biggest deficiency is the lack of collaboration spaces within the layout of the studios. The administration area is too small for staff

Interview Overview

The interview took place virtually with Principal Saenz, the school bookkeeper, the head custodian and an AISD project manager. The school has put a lot of attention into its outside spaces and does not wish to change its current outdoor learning spaces, rain gardens, chicken coop, Social Emotional Learning garden and cisterns. There are multiple playgrounds, including one being built at the time of the assessment.

According to the interview attendees, the school needs more space. Enrollment is at an all-time high, and they expect to exceed capacity within the next several years. There are five portables on-site, which are being used for AISD departments and a music room. Beginning in the 2021-2022 school year, the portables will be used for classrooms. Reception in the administration space is too small to accommodate staff, and there is only one gender-neutral restroom for adults down the hallway. There is not enough storage throughout the school. Studios have some built-in casework storage. The gym storage is in a school entryway and also takes up space in restrooms. Storage for clothes for students, supplies and materials do not exist but would be helpful. Gathering spaces are too small, including the cafeteria, and the school would like to host more after-school programming, PTA activities and other community functions. A functioning workroom and a conference room for faculty would also be helpful.

There are no designated spaces for maker space, science lab, language camp or special education.

Educational Suitability Summary Report

Reilly Elementary School

There are limited spaces in general to encourage creativity. The addition of these spaces would help support the six C's. The school would also benefit from designated spaces for the International Welcoming Department and the Social Emotional Learning department. The staff/faculty feel that an annex building would best suit all their needs.

Assessment Findings

The Educational Suitability Assessment of Reilly Elementary School earned a 54% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Academics & Learning

Score is very unsatisfactory.

Studios are average size and adequately function for their needs. The restrooms in the pre-K and kindergarten studios adequately support needs per the ed spec; however, they are not ergonomic. Storage space is very limited throughout the school. The studio spaces are adequately sized and could support multiple learning and teaching modalities with upgrades. The layout of the studios is not conducive to collaboration. There is no designated space for a maker space, outside of a small corner in the library, and no designated space for science. There are no professional learning centers or special education spaces.

Administration Spaces

Score is very unsatisfactory.

There is a reception area to accommodate visitors; however, it is small, not very welcoming There are not enough spaces to support administrative staff. The assistant principal is in a back corner, and the conference room was converted into an office. The staff says there is little to no acoustic privacy; everything can be heard.

Unsatisfactory Categories (36-50%):

Controllability of Systems

Score is unsatisfactory.

The studios have individual thermostats; however, control is not consistent. Blinds are provided on most windows for shading, but they appear outdated. Artificial lighting control in studios is unsatisfactory. There are alternating rows for switching.

Visual and Performing Arts

Score is unsatisfactory.

The music space is in a portable. The art room is quite small. The cafeteria stage is adequately sized but does not have any storage space for the cafeteria or the stage area.

PE and Wellness

Score is unsatisfactory.

The gymnasium is too small at 2,400 square feet and is in poor condition. Storage is very limited, and many items are being stored in the hallway.

Food Services

Score is unsatisfactory.

The cafeteria is appropriately sized for school capacity, but upgrades are needed to finishes. The kitchen and servery are very undersized. Accessing freezer/cooler requires staff to walk outside across loading dock to a separate space.

Media Resources

Score is unsatisfactory.

The library is not easily accessible to visitors. There are no spaces for quiet study, but it can accommodate medium-sized gatherings. There is a small area for computers, but the presentation equipment is outdated. Most furniture seems to be new. There is good visibility from the librarian's office.

Technology

Score is unsatisfactory.

The studios and other spaces have typical instructional technology compared to other AISD elementary schools, including movable TVs and projectors. Outlets average two per wall in the studios, but charging support is inadequate. Portable charging stations were observed in some studios. There is no digital signage at reception.

Average Categories (51-65%):

General Building

Score is average.

Interior circulation routes are very satisfactory for safe and effective student movement. Most are 10 feet wide. The library and gym can be accessed independently for after-hours access, but the cafeteria cannot. There is no community room dedicated to after-hours meetings. Overall, the building appearance conveys pride for the students and community.

Security

Score is average.

Satisfactory Categories (66-80%):

Exterior

Score is satisfactory.

The separation between vehicular, bus and pedestrian traffic is average. There is heavy backup during drop-off and pick up hours. Signage and access to trash/composting bins are satisfactory. The site is very large and overall, in great condition.

Environmental Quality

Score is satisfactory.

Educational Suitability Summary Report

The newer studios perform better acoustically than existing or older studios. Studio lighting is average and could be improved, but natural light is quite abundant throughout. More than half of the learning spaces have adequate views to outside. There are problems with rats and insects.

Furniture, Fixtures, Equipment

Score is satisfactory.

Most furniture is not new but seems sturdy and clean. There is an average mix of furniture types, but they could benefit from more variety. Every studio has a mix of loose tables and chairs. The furniture can be reconfigured if needed.

Very Satisfactory Categories (81-100%):


Outdoor Learning and Activity

Score is very satisfactory.

Outdoor studios, support spaces, playgrounds, gardens and cisterns are appropriately configured per the Ed Spec.

Educational Suitability Summary Report

Reilly Elementary School



Food Services: The cafeteria is adequately sized for capacity per Ed Spec but does not meet the needs of the school. It is too small for accommodating the entire enrollment at once or hosting large events. The kitchen is very undersized.

Educational Suitability Summary Report

Reilly Elementary School



General Building: All the corridors are well lit due to the large window walls and are adequate in width.



Educational Suitability Summary Report

Reilly Elementary School



PE and Wellness: The gym is undersized, and finishes are outdated.



PE and Wellness: The gym storage is detached from the main gym area in what used to be a school entry and restrooms.

Educational Suitability Summary Report

Reilly Elementary School




Visual and Performing Arts: Art room is slightly undersized at 900 square feet but has adequate number of sinks. There is a kiln, but storage is limited.



Administration Spaces: The faculty workroom is in a converted studio.

Educational Suitability Summary Report

Reilly Elementary School



Academics and Learning: Studios are well lit and have great views to the outside. Storage is limited and lighting is outdated.



Media Resources: The library seems to have had some recent updates, including flooring and furniture. There is a projector but no screen. There is no access to the outdoors.

Educational Suitability Summary Report

Reilly Elementary School

Supporting Photographs



Outdoor Learning and Activity: The school is proud of the new sensory gardens. They are optimally located between studio wings and have access to a water supply.



Outdoor Learning and Activity: The school recently added a new playscape. The exterior portion of the campus is quite large due to the adjacency to Reilly School Park. There is a large walking path present as well.

02/11/2022




Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Reilly Elementary School	Carlos Cruz and Kendall Claus	1/13/2021

ľ	1 - Exterior		1	2	3	4	5	N/	/A		8.75	74%
	11	ne site permit desirable separation of vehicular, bus and rian traffic?			3					Comments	1.00	3.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen							١	Very bad backup during pickup and drop-off. Need c	rosswalks as p	arents
		at the same location							F	park across street to avoid lines. Bike lanes moved or	ganization aro	und.
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									-	
	3	Average - Buses, cars, and pedestrians are separate but stack space is small										
	4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria										
	5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination										
	N/	A Does not apply							-			
	ls the b	uilding easily identified with appropriate signage and				4				Community		
	I.2 commu	unity wayfinding?				4				Comments	0.25	1.00
	1	Very unsatisfactory - Campus has no signage / wayfinding						•				
	2	Unsatisfactory - Signage/wayfinding is faded/hidden										
	3	Average - Signage / wayfinding visible but not apparent										
	4	Satisfactory - Signage / wayfinding is visible but not good condition										
	5											
	N/											



1 - Exterior (co	nt.)	1	2	3	4	5	N/A			
1.3 Is the dum	pster accessible for trash / compost disposal?					5		Comments	0.50	2.50
1 2 3 4 5	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Very Satisfactory - Compost and dumpster are shaped / positioned so people of all heights can access it.									
N/A 2 - Outdoor Le	Does not apply carning and Activity	1	2	3	4	5	N/A		15.00	93%
	or studios and support spaces appropriately configured per	•			4			Comments	1.00	4.00
1 2 3 4 5	Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
	Does not apply playgrounds (elementary only) and support spaces I per the ed spec?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply									

02/11/2022 ³

	Learning and Activity (cont)		2	3	4	5	N/A			
	lens and support spaces appropriately configured per the ed valuation on infrastructure not condition of plants)					5		Comments	0.00	0.0
1 2 3	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source Average - Adequate size, adequate condition, needs							Located in the center of the school, the gardens are in very satisfactory expectations. The school is very prou (Monitoring answer, does not affect score for Outdoor Activity.)	Id of this space	э.
	some renovations or updates to function well, water source is difficult to access									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
N/A	Does not apply									
2.4 Are the r ed spec?	rain gardens and/or cisterns appropriately configured per the ?					5		Comments	0.00	0.0
1	Very unsatisfactory - No rain gardens or cisterns	-					-	There are several cisterns around the building. (Monit	toring answer,	does
2	Unsatisfactory - Too small, poor condition, not							not affect score for Outdoor Learning and Activity.)		
	functioning, disconnected									
3	Average - Adequate size, adequate condition, is									
	connected, needs some renovations or updates to									
1	function well									
4	Satisfactory - Good size, good condition, functions properly									
5	Very Satisfactory - Generous size, excellent condition,									
	exceptional functionality, connected to learning spaces,									
	educational signage provided									
N/A	Does not apply									
2.5 Does the	e school have animal husbandry? (optional)					5		Chickens	0.00	0.0
1	No									
5	Yes						-			
2.6 Does the	e school have nature loop trails? (optional)	1						Very open, could be more vegetated.	0.00	0.0
1	No									
5	Yes		-					1		
	e school have a learning pond? (optional)					5		Comments	0.00	0.0
1	No									
5	Yes					5		Commente	1.00	
	e school have a grass play field and walking trail?					5		Comments	1.00	5.0
1	No									
5	Yes									

3 - General Bu	ilding	1	2	3	4	5	N/A	A Contraction of the second seco	11.25	58
Are interior	r circulation routes wide enough to safely and effectively					5		Comments		
accommod	date student movement?					5		Comments	0.50	2.5
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"									
	wide									
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are commu	unity use areas arranged so that the school can allow night			0						
	vithout full school access?			3				Comments	0.75	2.
1	Very unsatisfactory - Cafeteria, gym, and library cannot							Cafeteria is the most easily accessible for after-hour	s events. Gym	locate
	be accessed after hours							in back of school. Library is near entry but cannot pro	ovide after-ho	urs
2	Unsatisfactory - Only one of the public spaces (Cafeteria,							access.		
	Gym and Library) can be accessed from parking and									
	secured after hours									
3	Average - Only two of the public spaces can be accessed									
4	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
Ŭ	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply									
ls there a c	community room that is a dedicated meeting space outside				1	Γ				
3.3 of school fu	, .	1						Comments	0.75	0.
1	Very unsatisfactory - No dedicated community room							No dedicated space. Typically have to use library or	cafeteria.	
2	Unsatisfactory - Community room but within school									
	function, no access after school hours									
3	Average - Community room, moderate size, but need									
	some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets									
_	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school function									
N/A	Does not apply									
Does the a	eneral appearance of the school convey pride for the				1					
3 /	nd community?				4			Comments	0.25	1.0
1	Very unsatisfactory - General appearance is poor							Landscaping, grounds and general building are well		
2	Unsatisfactory - General appearance is aged but ok									
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in									
	campus and student works									
5	Very Satisfactory - General appearance shows pride in									
	campus and student works and is welcoming to the									
	community									
N/A	Does not apply									

Security		1	2	3 4	4	5 N/	'A		16.25	
.] Does the fe	acility have key card access at all major entries?							Comments	0.25	
1	Very unsatisfactory - No entries									
2	Unsatisfactory - 1/4 of major entries									
3	Average - 1/2 of major entries									
4	Satisfactory - 3/4 of major entries									
5	Very satisfactory - All of major entries									
N/A	Does not apply									
.2 How adeq	uate is site lighting and security for the campus overall?							Comments	1.00	
1	Very unsatisfactory - No exterior lighting, no secure perimeter	<u> </u>								
2	Unsatisfactory - Lighting is limited to front entry only,									
	parking lot lighting poor, security is minimal									
3	Average - Lighting at all night-use entries and parking									
Ū	lot, but poor condition. Security is moderate									
4	Satisfactory - Lighting at all night-use entries and									
Ŧ	parking lots, good condition, signage less visible,									
	perimeter is well secured but needs updates									
5	· Very satisfactory - Signage, parking lots, and entries are									
	well lit, visible and easy to use, perimeter is very secure									
N/A	Does not apply n office located at the school entry and configured with a	1								
2	tibule to the main corridor?							Comments	1.00	
1	Very unsatisfactory - No secure vestibule, office located								1.00	
1	far from main entry, allows visitors access to school								,	
	unsupervised									
2	Unsatisfactory - No secure vestibule, office located									
	somewhat far from main entry, minimal supervision of									
	visitors									
3	Average - Office close to entry, views of front door, but									
	no secure vestibule									
4	Satisfactory - Office is well-located with a secure									
-	vestibule, but needs updates									
5	Very satisfactory - Office well-located with secure									
N/A	vestibule and all appropriate security features									
	Does not apply	, 1			-					
	ough interior transparency for faculty to passively supervise nd their activities who are not in studios?			3				Comments	100	
learners ai									1.00	3
	Very unsatisfactory - No transparency of walls									
2	Unsatisfactory - Limited transparency in certain locations									
3	Average - Good transparency in certain locations but									
	inadequate or missing in other locations of school									
4	Satisfactory - Adequate transparency throughout the school									
5										
5	Very satisfactory - Excellent transparency throughout the school									

02/11/2022 *

5 - Environmei	- Environmental Quality		2	3	4	5	N/A	<u> </u>	25.00	72%
5.1 How are a	coustics in studios in general?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply							Newer studios are better than original buildings. Orig clerestory windows to corridor that allow sound trans		,
5.2 Is the studi	o artificial lighting adequate quality?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there acc	cess to natural light in studios?					5		Comments	1.00	5.00
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply				•					
5.4 Is there acc	cess to outside views from learning spaces?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply						1			

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A	<u> </u>		
5.5	Does the bu	uilding have odor or pest problems?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							They have problems with rats and insects.		
6 - 0	ontrollabi	lity of Systems	1	2	3	4	5	N/A	A	12.50	44%
6.1	Does the st	udio thermostat allow for individual control?	1						Comments	0.50	0.50
	1 5	No Yes							Individual units but control is not consistent.		
6.2	Are shades	provided to control natural light in learning spaces?			3				Comments	1.00	3.00
	1 2 3 4 5 N/A	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades Does not apply									
6.3	What is the	quality of lighting controls in the studios?		2					Comments	1.00	2.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply									

71 What is the current condition of the furniture?	699 3.00
1 Very unsatisfactory - Damaged or broken, non-functioning 0.75 3 2 Unsatisfactory - Torn/ bent/ wrong size 3 Average - Scratched/dented/marked 3 Average - Scratched/dented/marked 4 Satisfactory - Not new, but sturdy and clean	3.00
functioning 2 Unsatisfactory - Torn/ bent/ wrong size 3 Average - Scratched/dented/marked 4 Satisfactory - Not new, but sturdy and clean	
 2 Unsatisfactory - Torn/ bent/ wrong size 3 Average - Scratched/dented/marked 4 Satisfactory - Not new, but sturdy and clean 	
3 Average - Scratched/dented/marked 4 Satisfactory - Not new, but sturdy and clean	
4 Satisfactory - Not new, but sturdy and clean	
5 Very satisfactory - New	
N/A Does not apply	
Are a variety of furniture types being accommodated throughout the	
7.2 School - learning commons, dining commons, other multi-use spaces?	
1.00 3	3.00
1 Very Unsatisfactory - Same furniture used in all spaces	
² Unsatisfactory - Furniture variety in one multi-use space	
3 Average - Furniture variety in more than one multi-use	
space	
4 Satisfactory - All multi-use spaces have greater than one	
type of furniture 5 Very satisfactory - All multi-use spaces have greater than	
5 Very satisfactory - All multi-use spaces have greater than two types of furniture	
N/A Does not apply	
How well does furniture accommodate rapid reconfiguration of a	
7.3 row well does runnique decommodate rupid recommodate rupid rup	3.00
1 Very Unsatisfactory - Furniture is fixed or very heavy	
2 Unsatisfactory - Furniture does not allow desks to be	
configured as individuals, small groups, or large groups	
3 Average - Mix of furniture that can reconfigure but is	
cumbersome to move 4 Satisfactory - Furniture is flexible for multiple	
configurations of space	
5 Very satisfactory - Furniture is flexible for multiple	
configurations of space, easy to move and stack	
N/A Does not apply	
7.4 Is the furniture ergonomic and size appropriate for grade level?	
1 Very unsatisfactory - Desk with attached chair	4.00
combinations too small for grade level	
2 Unsatisfactory - Desk with attached chair combinations	
3 Average - Mix of studios with tables/loose chairs and	
desks with fixed seats	
4 Very satisfactory - Tables with loose chairs	
5 Very satisfactory - Tables with loose chairs that allow	
students to be active	
N/A Does not apply	

02/11/2022 °

Waste		1	2	3	4	5	N/A	N	5.00	80
	and corridors have blue recycle bins with bilingual s and/or image sorting instructions?				4			Comments	0.50	2.0
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.							A score for this category is being recorded, but this cat calculated in the overall ESA average.	egory is not	
2	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.							Blue bins are located in most studios.		
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across									
N/A	campus. Does not apply									
of each: gre	afeteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the ed clearly with bilingual and/or image sorting?				4			Comments	0.50	2.0
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.			<u> </u>			1			
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
3	Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent.									
4	Satisfactory- There are several waste stations as described above									
5	Very Satisfactory - There are several waste stations as described above, and additional signage in the cafeteria that encourages recycling/composting.									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Reilly Elementary School	Carlos Cruz and Kendall Claus	1/13/2021


8 - Academics	& Learning	1	2	3	4	5	N/A	A	70.00	34%
8.1 Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - Too small, no flexibility,							Studios are adequately sized and range in size from 8	390 - 910 squar	e feet.
	disconnected							Updates are needed to finishes and lighting. Some st	udios still have	
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							chalkboards.		
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A	Does not apply							T		
82	and Kinder have appropriate support spaces such as and storage per the ed spec?			3				Comments	1.00	3.00
1	Very unsatisfactory - None provided								1.00	3.00
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs									
5	updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent									
	condition									
N/A	Does not apply									

02/11/2022 ²

8 - A	cademics &	& Learning (cont.)	1	2	3	4	5	N/A	N N N N N N N N N N N N N N N N N N N		
8.3		nave appropriate support spaces such as storage per the		2					Comments		
0.5	ed spec?			~					Comments	1.00	2.00
	1	Very unsatisfactory - None provided							Just built-in cabinets. Not a lot of closet space.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open	1						Comments		
0.4	collaboratio	•	I						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
	3	neighborhood, poor acoustic privacy Average - Adequate size, adequate condition, needs									
	5	some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply		1		r			Τ	1	
8.5		studios large enough to support project-based learning		2					Comments	1.00	
_		e teaching modalities?								1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
	2	limited flexibility									
	3	Average - Adequate size, needs some renovations or									
		updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
		flexibility									
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A	Does not apply									

02/11/2022 ³

8 - Academics & L	earning (cont.)	1	2	3	4	5	N/A	N Contraction of the second		
8.6 Are Maker Spant the ed spec?	ces and support spaces appropriately configured per	1						Comments	1.00	1.00
1 Ve 2 Ur fro 3 Av so 4 Sc lee 5 Ve co	ery unsatisfactory - No dedicated maker spaces nsatisfactory - Too small, poor condition, disconnected om learning spaces, no flexibility verage - Adequate size, adequate condition, needs ome renovations or updates to function well atisfactory - Good size, good condition, connected to arning spaces ery Satisfactory - Generous size, excellent condition, onnected to learning spaces							Trying to make one in library.		
	oes not apply ssional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
Pr 2 Ur 3 Av so 4 Sc 5 Ve co	ery unsatisfactory - No dedicated space for rofessional Learning Center insatisfactory - Too small, poor condition, disconnected verage - Adequate size, adequate condition, needs ome renovations or updates to function well atisfactory - Good size, good condition, connected ery Satisfactory - Generous size, excellent condition, onnected oes not apply									
	cated science room and support space?	1						Comments	0.00	0.00
1 No 5 Ye	25							Monitoring answer, but doesn't affect overall score.		
8.9 learning (both :				3				Comments	1.00	3.00
2 Ur co 3 Av up 4 Sc 5 Ve	ery unsatisfactory - No dedicated space nsatisfactory - Too small, non-dedicated, poor ondition verage - Adequate size, adequate condition, needs odates or renovations to function well atisfactory - Good size, good condition ery Satisfactory - Generous size, excellent condition oes not apply									



8 - Academics 8	k Learning (cont.)	1	2	3	4	5	N/A	A		
B.10 Does the bui	ilding provide adequate opportunities for	1						Comments		
8.10 students/tec	achers to collaborate in varying group sizes?	1						Comments	1.00	1.00
1	Very unsatisfactory - No space to support collaboration									
	in various sizes.									
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple options									
	to support a variety of group sizes									
5	Very Satisfactory - Generous size, excellent condition,									
	multiple options to support a variety of group sizes									
N/A	Does not apply									
8 11 Does the bu	ilding provide opportunities for informal interaction?			3				Comments		
									1.00	3.00
1	Very unsatisfactory - No space							Some of the hallways are big enough for informal in	teraction but re	equire
2	Unsatisfactory - Too small, poor condition, layout and							updates to function in this capacity.		
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply					1	1		1	
212	arning neighborhood / building provide adequate	1						Comments		
opportunitie	es for students to work independently?							commonte	1.00	1.00
1	Very unsatisfactory - No breakout rooms/small study									
	spaces									
2	Unsatisfactory - Too small, poor condition, no acoustic									
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy,									
	variety of independent work space options, connected to learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space									


8 - Academics	& Learning (cont.)						
8.13 Are Specia spec?	Il Education spaces appropriately configured per the ed	1			Comments	1.00	1.00
1	Very unsatisfactory - Too small, no flexibility, disconnected				The campus doesn't currently have a special education would like to accommodate this program on their ca		-
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected				don't have the resources or adequate space.		onay
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.						
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces						
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces						
N/A	Does not apply		_				
81/1 .	Il Education support spaces, such as storage, space for yer, appropriately configured per the ed spec?	1			Comments	1.00	1.0
1	Very unsatisfactory - None provided						
2	Unsatisfactory - Too small, disconnected, poor condition						
3	Neutral - Adequate size, average condition, needs updates or renovations to function well						
4	Satisfactory - Good size, connected, good condition						
5	Very Satisfactory - Generous size, connected, excellent condition						
N/A	Does not apply						
	ible restrooms and changing rooms readily available to the ucation spaces?	1			Comments	1.00	1.0
1	No					-	
5	Yes						

02/11/2022 *

9 - Vis	sual and l	Performing Arts	1	2	3	4	5	N,	/A 15.00	40%
01	Are music s per the ed s	paces and the cafeteria stage appropriately configured spec?	1						Comments 1.00	1.00
	1	Very unsatisfactory - Too small, missing program spaces							In portable. The stage is adequately sized but does not have any	
	2	Unsatisfactory - Too small, poor condition							dedicated storage space.	
	3	Neutral - Adequate size, adequate condition, needs								
		updates or renovations to function well.								
	4	Satisfactory - Good size, good condition								
	5	Very Satisfactory - Generous size, excellent condition								
	N/A	Does not apply				-	-			
02		and performance storage spaces appropriately configured		2					Comments	
	per the ed s	•							1.00	2.00
	1	Very unsatisfactory - None provided								
	2	Unsatisfactory - Too small, disconnected, poor condition								
	3	Neutral - Adequate size, average condition, needs								
		updates or renovations to function well								
	4	Satisfactory - Good size, connected, good condition								
	5	Very Satisfactory - Generous size, connected, excellent								
		condition								
	N/A	Does not apply				-				
03	Are Visual A ed spec?	Arts spaces and storage appropriately configured per the			3				Comments 1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces						-	Organized but appears too small. Could use more storage but he	s a kiln.
	2	Unsatisfactory - Too small, poor condition								
	3	Average - Adequate size, adequate condition, needs								
		some renovations or updates to function well								
	4	Satisfactory - Good size, good condition								
	5	Very Satisfactory - Generous size, excellent condition								
	N/A	Does not apply								

) - PE and Wellness	1	2	3	4	5	N/A	A Contract of the second se	10.00	30
Does the campus meet the ed spec standard for physical education		2					Comments		
program spaces?		~					Comments	1.00	2.0
 Very unsatisfactory - Too small, missing program spaces 							Needs new floor, upgrade to materials and insulatio	n, and needs to	o be
							bigger. Too small at 2,400 square feet.		
2 Unsatisfactory - Too small, poor condition									
3 Average - Adequate size, adequate condition, needs									
some renovations or updates to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply				1	1	1	1	[
Are the physical education storage spaces appropriately configured	1						Comments		-
per the ed spec?								1.00	1.0
1 Very unsatisfactory - None provided							Located in hallway - big but not proper storage area	•	
2 Unsatisfactory - Too small, disconnected, poor condition									
3 Neutral - Adequate size, average condition, needs									
updates or renovations to function well 4 Satisfactory - Good size, connected, good condition									
5 Very Satisfactory - Generous size, connected, good condition									
condition									
N/A Does not apply									
- Food Services	1	2	3	4	5	N/A		10.00	5
		-		-		1,1,7,		10.00	
I.] Is the Dining Commons appropriately configured per the ed spec?			3				Comments	1.00	3.
1 Very unsatisfactory - Too small, missing program spaces						I	Cafetorium is adequately sized per school capacity.		
2 Unsatisfactory - Too small, poor condition, only one							and lighting. Has A/V. Could use more outlets and a		
option for eating space provided, inadequate circulation									<u>g</u> .
3 Average - Adequate size and condition, needs updates									
or renovations to function well									
4 Satisfactory - Good size and condition, good circulation,									
multiple options for eating space (ex: connection to									
outdoor eating space)									
5 Very Satisfactory - Generous size, excellent condition and									
circulation, multiple options for eating space (ex:									
connection to outdoor eating space)									
N/A Does not apply			-						
Are the Food Services support spaces appropriately configured per		2					Comments		
^{.2} the ed spec?		2					Commenta	1.00	2.
 Very unsatisfactory - None provided 							Kitchen and servery very small at 630 square feet (de	pes not include	
2 Unsatisfactory - Too small, disconnected, poor condition							storage and freezer/cooler).		
3 Neutral - Adequate size, average condition, needs									
3 Neutral - Adequate size, average condition, needs updates or renovations to function well									
updates or renovations to function well									
updates or renovations to function well 4 Satisfactory - Good size, connected, good condition									

12 - Media Res		1	2	3	4	5	N/A	<u> </u>	30.00	50%
121	ary/Media Center easily accessible for the occupants and the school?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, no transparency Average - Adequate accessibility, needs updates or renovations to function well Satisfactory - Accessible, easy to find, good transparency, good condition Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition Does not apply									
	does the Library/Media Center support quiet study?		2					Comments	1.00	2.0
1 2 3 4 5 N/A	Very unsatisfactory - No quiet study spaces Unsatisfactory - One area in poor condition, poor acoustic privacy Average - One or more areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, good condition, good acoustic privacy Very Satisfactory - Multiple clusters or small rooms adjacent to media center, excellent condition, excellent acoustic privacy Does not apply		<u> </u>					Reading room is one open area.		
	does the Library/Media Center support social interaction?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No space Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size, good condition, layout and furnishings support informal interactions Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions Does not apply	1	<u> </u>						1 1.00	3.00
	does the Library/Media Center support collaborative work oups (4-8 students)?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - No breakout rooms, no flexible furniture, no support Unsatisfactory - Too small, one area, poor condition Average - Adequate size, multiple areas provided, needing updates or renovations to function well Satisfactory - Clusters or small rooms adjacent to media center, flexible furniture, good condition Very Satisfactory - Multiple clusters or small rooms adjacent to media center, flexible furniture, excellent condition Does not apply							Can be achieved with updated furniture.		



12 - Media R	Resources - Continued	1	2	3	4	5	N/A	N		
	II does the Library/Media Center support collaborative work r groups (10-25)?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - No gathering areas Unsatisfactory - Too small, one common space, limited seating, poor condition Average - Adequate size, one common space, needs updates or renovations to function well Satisfactory - Good size, multiple common spaces with seating, good condition Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition Does not apply									
12.6 How we	II does the Library/Media Center support technology?		2					Comments	1.00	2.00
1 2 3 4 5 N/A	Very unsatisfactory - No vis comm tools Unsatisfactory - Outdated, poorly functioning, or insufficient Good - Mix of old and new whiteboards/projectors/etc. Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition Does not apply									
13 - Technol		1	2	3	4	5	N/A	N N N N N N N N N N N N N N N N N N N	20.00	45%
13.1 How we	Il equipped are the facilities with instructional technology?			3				Comments	1.00	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Limited to no technology present in instructional spaces Unsatisfactory - One type of technology present Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school Satisfactory - Multiple types of technology, smart boards, good condition. Very Satisfactory - Multiple types of technology, smart boards, excellent condition Does not apply									
13.2 Is there	an adequate number of power and data outlets in learning		2					Comments	1.00	2.00
1012 spaces? 1 2 3 4 5	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall) Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall) Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall) Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall) Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)					<u> </u>	1		1.00	2.00

13 - Technolog	gy (cont.)	1	2	3	4	5	N/A	4		
13.3 Are there of	adequate charging locations for devices?		2					Comments	1.00	2.00
1	Very unsatisfactory - No centralized charging location							Portable charging stations.		
2	Unsatisfactory - Centralized charging location, but									
3	inadequate in size for number of devices Average - Charging cart or tower but not adequately									
3	sized for number of devices									
4	Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower located									
	centralized location. Excellent condition									
N/A	Does not apply									
13.4 Is there ad	lequate AV for presentations spaces – cafeteria and gym?		2					Comments	1.00	2.00
1	Very unsatisfactory - AV not present in one or more	•	•			<u> </u>				
	space									
2	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV									
	undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply	1	1	1	1	1	1		[
13.5 Is there dig	gital media signage at the reception area?	1						Comments	0.00	0.00
1	Very unsatisfactory - No digital media present in									
	reception area									
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR									
	undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good condition									
5	Condition Very Satisfactory - Generously sized, excellent condition									
-										
N/A	Does not apply									

4 - Administr	ation Spaces	1	2	3	4	5	N/A		20.00	3
14 1	reception area that functions as a security checkpoint for all							Comments		
visitors?								comments	1.00	
1	Very unsatisfactory - No security checkpoint									
2	Unsatisfactory - Checkpoint is too small, poor condition									
3	Average - Needs updates or renovations to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply						L			
4.2 Does the a	administration area feel welcoming?		2					Comments	1.00	2.
1	Very unsatisfactory - No welcome space		I					Reception is small.	1.00	Ζ.
2	Unsatisfactory - Too small, poor lighting and									
-	transparency, limited informal seating, poor condition									
3	Average - Adequate size and layout, needs updates or									
	renovations to feel welcoming									
4	Satisfactory - Good size and layout, good lighting and									
	transparency, informal seating provided									
5	Very Satisfactory - Generous size and layout, plenty of									
	light and transparency, informal seating provided,									
	excellent condition									
N/A	Does not apply									
4.3 For those s	spaces that require it, does the administration area have		2					Comments		
4.0 adequate	acoustic privacy?		~					Comments	1.00	2
1	Very unsatisfactory - No acoustic separations				-			Reception/office area does not have adequate acous	stic separation.	
2	Unsatisfactory - Acoustic separations do not perform									
	well									
3	Average - Some acoustic separations function okay, but									
	portions need updates or renovations									
4	Satisfactory - Good acoustic separations									
5	Very Satisfactory - Excellent acoustic separations									
N/A	Does not apply		1							
4.4 Are confer	rence rooms easily accessed for public / parent use?	1						Comments	1.00	1
1	Very unsatisfactory - Not accessible for public/parent									
	use									
2	Unsatisfactory - Limited access, no transparency, poor									
	condition, difficult to find									
3	Average - Adequate accessibility, needs updates or									
	renovations to function well									
4	Satisfactory - Good accessibility, good transparency,									
-	good size and condition									
5	Very Satisfactory - Excellent accessibility, excellent									
N1/A	transparency, generous size, excellent condition						l			
N/A	Does not apply									