

Educational Suitability Summary Report

Ridgetop Elementary School

Date: 1/11/2021 Score 62% Average

Ridgetop Elementary School serves an enrollment of approximately 350 students in north central Austin. Built in 1939, the building consists of approximately 35,000 square feet and sits on 4.5 acres. Given its urban setting, there is limited parking for staff, visitors and parents and there is no separation between bus and parent pickup and drop-off in front of the school. It is typical for parents, visitors and sometimes staff to park in the neighborhood.

Visitors do need to walk past reception in order to access the rest of the building. The reception office is very limited in size and acoustic privacy levels are insufficient. Learning spaces are spread between two wings of the school. Studios are small in comparison to the Ed Spec, averaging 675 square feet. Studios do not have dedicated restrooms; restrooms are located in the corridor. Studio doors have a half lite, which is typically covered. Otherwise, they lack transparency into the corridors.

The gym needs updating and has limited storage and no dedicated office for the PE instructor. The gym can be accessed from the outside but has no direct connection to visitor parking. The cafeteria is adjacent to the gymnasium. The solid wall between them cannot be opened to make one larger space. Because this school has a dedicated auditorium, the cafeteria does not have a stage or an overhead projector. The library is one large space with columns in the middle that allow for two areas to be arranged in different setups. The furniture allows for different arrangements, but the space does not include individual space for reading or studying. There is access to an outdoor learning studio through the library that appears to be for reading sessions.

Interview Overview

The interview consisted of Principal Kara Schultz, Assistant Principal Jose Salazar, along with teachers Rita Tomillo, Sara Ruttan and Wai Ping Lau-Suarez. There was discussion regarding items that must be kept, the functionality interior spaces and outdoor learning spaces, as well as the desire for campus upgrades.

One item mentioned that should be kept is the auditorium space. It is original to the school and is important to the community as a meeting and performance space. The seats in the auditorium were recently updated, but lighting and A/V updates are needed. Other items mentioned as important to the campus are the old-growth oak and willow trees on campus. The lack of a car pickup line was mentioned as a positive feature, as it fosters a sense of community and encourages interaction between families during pickup times.

Art and music spaces are in standard studios and are lacking appropriate storage and support items. There are four portables due to enrollment numbers. (While this assessment does not cover the portables, it is assumed that spaces in portables will be found deficient.) The special education studio

Educational Suitability Summary Report

Ridgetop Elementary School

is too small and lacks a nearby restroom and washer and dryer. The campus also lacks indoor student and teacher collaboration spaces.

The cafeteria is adequately sized for the number of students but requires updated finishes, including ceiling tiles and flooring. The gym requires interior updates including updated ceiling, upgraded lighting and updated equipment, including a climbing wall and soft-play elements. The campus would like to have a dedicated maker space. Many of the studios have adjacent restrooms for students, but these are not accessible. Additionally, there are too few adult restrooms provided and current adult restrooms need updating.

The campus exterior spaces are seen as being an important part of instruction. The exterior learning spaces are well-maintained and provide covered learning spaces. Items desired to make the outdoor learning spaces more functional include extended Wi-Fi coverage, portable dry erase boards, and more flexible seating and tables.

Assessment Findings

The Educational Suitability Assessment of Ridgetop Elementary School earned a 62% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Academics and Learning

Score is unsatisfactory.

All studios are undersized at 670 square feet. There is limited transparency to other studios and very limited shared learning spaces. Special education room is undersized and lacks support spaces. The building does not offer space for collaboration or informal meeting.

PE and Wellness

Score is unsatisfactory.

Gym is undersized at 2,200 square feet. There is access to the exterior that leads to the staff parking lot. Storage is small and accessed through a vestibule. Entry into the vestibule is not accessible due to steps up to door.

Food Services

Score is unsatisfactory.

Cafeteria is adequately sized for current enrollment. Kitchen is small, and there is only one serving line. Space needs updating. Lack of flexible seating and connection to the exterior.

Average Categories (51-65%):

Educational Suitability Summary Report

Ridgetop Elementary School

Exterior

Score is average.

Site has no separation between vehicular and bus areas. Insufficient parking for the public and staff. School signage needs updating.

General Building

Score is average.

Interior circulation is satisfactory with 10'-12' wide corridors throughout the school. Gym, library and auditorium can be accessed from exterior doors; however, there is no sidewalk leading to the library entrance. There is no dedicated community room, and the overall appearance of the school is dated.

Visual and Performing Arts

Score is average.

Both art and music are held in a typical studio, and both are undersized and lack storage. There is a separate auditorium space for gathering and performances.

Media Resources

Score is average.

Media center is located down main corridor, and there is no transparency to the rest of the school. There is one large space that is divided into two areas through columns in the center. There are a variety of furniture types, but the space is not set up for quiet or independent study. Outside of the media center, is a small outdoor secured seating area.

Administration Spaces

Score is average.

Acoustics in the admin offices are insufficient. There is no dedicated conference room in the admin suite.

Technology

Score is average.

There are multiple types of technology available in each studio. The cafeteria does not have A/V capabilities. The auditorium does have adequate AV. Charging capabilities appeared inadequate but may be an outcome of charging towers being removed due to Covid protocols.

Satisfactory Categories (66-80%):

Security

Score is satisfactory.

Controllability of Systems

Score is satisfactory.

Studios have their own thermostats and two-switch lighting controls. Windows have blinds that are in average condition.

Educational Suitability Summary Report

Ridgetop Elementary School

Furniture, Fixtures, Equipment

Score is satisfactory.

Furniture appears in good condition. Furniture in studios is separate table and loose chairs. There is a variety of furniture types in the library.

Very Satisfactory Categories (81-100%):

Outdoor Learning and Activity

Score is very satisfactory.

There are a variety of outdoor learning spaces in good condition provided for students and teachers. School gardens are in good condition and rainwater cisterns are available.

Environmental Quality

Score is very satisfactory.

Acoustics from the corridor is an issue, but studio-to-studio sound is not noticeable. All learning spaces have access to natural light and views outside.



Typical studio with portable screen, built-in cabinetry for storage and furniture that can be reconfigured.



Some studios are joined by a connector space that could be used as small group setting. Restrooms are not ADA accessible.




Typical hallway.



Library has minimal visual connection to the school and to the outdoors.



Outdoor studio is accessed through the library. Space is not accessible from library due to steps leading up to the door.



Cafeteria with elongated tables. Serving line is at the end of the space and gym is adjacent to this space through the red double doors.



Gymnasium is undersized and has limited storage accessed through a vestibule.



A separate auditorium is adjacent to the main entrance. There are speakers and a permanent overhead projector.



Covered outdoor basketball court adjacent to the portables.



One of two playgrounds. Only one of them is covered.



Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Ridgetop ES	Carlos Cruz and Kristen Klein	01.11.21

1 - E	xterior		1	2	3	4	5	N/A	4	8.75	54%
1.1	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Bus, car and pedestrian all happen				•		•	Urban setting with limited space for separation. City s	treet in front of	
		at the same location							school acts as drop-off and pickup for buses and pare	ents.	
	2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
	3	Average - Buses, cars, and pedestrians are separate but stack space is small									
	4	Satisfactory - Buses, cars, and pedestrians are separate									
		but drop off does not have a canopy or a holding place									
		like a commons or cafeteria									
	5	Very satisfactory - Buses, cars, and pedestrians are									
		separate and drop off area has a canopy and									
		destination									
	N/A	Does not apply						1			
1.2		ing easily identified with appropriate signage and			3				Comments		
	community	wayfinding?			Ů				Commente	0.25	0.75
	1	Very unsatisfactory - Campus has no signage /									
		wayfinding									
	2	Unsatisfactory - Signage/wayfinding is faded/hidden									
	3	Average - Signage / wayfinding visible but not apparent									
	4	Satisfactory - Signage / wayfinding is visible but not									
		good condition									
	5	Very satisfactory - Signage and wayfinding is visible and									
		easy to use									
	N/A	Does not apply									

O2/11/2022 ²

1 - Ex	- Exterior (cont.)				3	4	5	N,	N/A
1.3	Is the dump	ster accessible for trash / compost disposal?				4			Comments 0.50 2.00
	 Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly 								
	adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.								
2 - 0	N/A Does not apply - Outdoor Learning and Activity		1	2	3	4	5	N	N/A 15.00 87%
21	Are outdoor studios and support spaces appropriately configured per					4			Comments 1.00 4.00
	1 Very unsatisfactory - No dedicated outdoor studios 2 Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area 4 Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area 5 Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area								Multiple outdoor studios in a variety of configurations. In good condition.
','',		olaygrounds (elementary only) and support spaces per the ed spec?				4			Comments 1.00 4.00
	 Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure 								
	4 5 N/A	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure Does not apply							

2 - Outdoor Le	earning and Activity (cont)	1	2	3	4	5	N/A	1	
2.3 Are garder	ns and support spaces appropriately configured per the ed				4			Comments	
2.3 spec? (eva	luation on infrastructure not condition of plants)				4			Comments 0.00	0.00
1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor Learning o	and
2	Unsatisfactory - Too small, poor condition, disconnected							Activity.	
	from learning spaces, no flexibility, no accessible water								
	source								
3	Average - Adequate size, adequate condition, needs								
	some renovations or updates to function well, water source is difficult to access								
4	Satisfactory - Good size, good condition, connected to								
7	learning spaces, good flexibility, water source is								
	accessible with 100 ft hose								
5	Very Satisfactory - Generous size, excellent condition,								
	connected to learning spaces, excellent flexibility, water								
	source is less than 50ft from the garden or has irrigation								
N/A	Does not apply								
2.4 Are the rai	n gardens and/or cisterns appropriately configured per the				4			Comments	
ed spec?					4			Comments 0.00	0.00
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor Learning o	and
2	Unsatisfactory - Too small, poor condition, not							Activity.	
	functioning, disconnected								
3	Average - Adequate size, adequate condition, is								
	connected, needs some renovations or updates to								
4	function well Satisfactory - Good size, good condition, functions								
7	properly								
5	Very Satisfactory - Generous size, excellent condition,								
	exceptional functionality, connected to learning spaces,								
	educational signage provided								
N/A	Does not apply								
2.5 Does the s	chool have animal husbandry? (optional)	1						Comments 0.00	0.00
1	No								
5	Yes								
	chool have nature loop trails? (optional)	1						Comments 0.00	0.00
1	No								
5 2.7 Does the s	Yes chool have a learning pond? (optional)					5		Comments 0.00	0.00
2.7 Does the s	No					J		Learning pond in front garden.	0.00
5	Yes								
2.8 Does the s	chool have a grass play field and walking trail?					5		Comments 1.00	5.00
1	No								
5	Yes								

3 - General Building	1	2	3	4	5	N/A		11.25	56%
3.1 Are interior circulation routes wide enough to safely and effectively accommodate student movement?					5		Comments	0.50	2.50
1 Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Hallways are 10-12 feet throughout.		
wide									
2 Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3 Average - Primary circulation is 7'-0" to 8'-0" wide									
4 Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5 Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A Does not apply									
Are community use areas arranged so that the school can allow night			3				Comments		
functions without full school access?			Ŭ				Comments	0.75	2.25
1 Very unsatisfactory - Cafeteria, gym, and library cannot							Auditorium, library, and gym can be entered directly		
be accessed after hours 2 Unsatisfactory - Only one of the public spaces (Cafeteria,							upon exiting those spaces, a visitor would have acces		the
Gym and Library) can be accessed from parking and							school. No sidewalk leading to exterior library entran	ce.	
secured after hours									
3 Average - Only two of the public spaces can be accessed									
from parking and secured after hours									
4 Satisfactory - All of the public spaces can be accessed									
from parking and secured from the rest of the building									
but not individually									
5 Very satisfactory - Cafeteria, gym, and library can be									
accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
N/A Does not apply									
Is there a community room that is a dedicated meeting space outside		1	1		l				
3.3 of school function?	1						Comments	0.75	0.75
Very unsatisfactory - No dedicated community room		<u> </u>	<u> </u>		l		No dedicated Community Room.	0.70	
Unsatisfactory - Community room but within school							,		
function, no access after school hours									
3 Average - Community room, moderate size, but need									
some renovations or updates to function well									
4 Satisfactory - Community room, good size /layout, meets									
needs /functions well 5 Very Satisfactory - Community room, generous size, nice									
condition, functions appropriately outside of school									
function									
N/A Does not apply									
Does the general appearance of the school convey pride for the			3				Comments		
students and community?								0.25	0.75
1 Very unsatisfactory - General appearance is poor							General appearance is ok but dated.		
Unsatisfactory - General appearance is aged but ok Average - General appearance is good									
Average - General appearance is good Satisfactory - General appearance shows pride in									
campus and student works									
5 Very Unsatisfactory - General appearance shows pride in									
campus and student works and is welcoming to the									
community									
N/A Does not apply									

4 - Security	1	2	3	4	5	N/A	(16.25
4.1 Does the facility have key card access at all major entries?							Comments	0.25
1 Very unsatisfactory - No entries	•			•)	
2 Unsatisfactory - 1/4 of major entries								
3 Average - 1/2 of major entries								
4 Satisfactory - 3/4 of major entries								
5 Very satisfactory - All of major entries								
N/A Does not apply								
14/A Does not apply	T	1		l	l			
4.2 How adequate is site lighting and security for the campus overall?							Comments	1.00
l Very unsatisfactory - No exterior lighting, no secure								
perimeter								
2 Unsatisfactory - Lighting is limited to front entry only,								
parking lot lighting poor, security is minimal								
Average - Lighting at all night-use entries and parking								
lot, but poor condition. Security is moderate								
4 Satisfactory - Lighting at all night-use entries and								
parking lots, good condition, signage less visible,								
perimeter is well secured but needs updates								
5								
Very satisfactory - Signage, parking lots, and entries are								
well lit, visible and easy to use, perimeter is very secure								
N/A Does not apply								
ls the main office located at the school entry and configured with a							Comments	
secure vestibule to the main corridor?							Comments	1.00
1 Very unsatisfactory - No secure vestibule, office located)	
far from main entry, allows visitors access to school								
unsupervised								
2 Unsatisfactory - No secure vestibule, office located								
somewhat far from main entry, minimal supervision of								
visitors								
3 Average - Office close to entry, views of front door, but								
no secure vestibule								
4 Satisfactory - Office is well-located with a secure								
vestibule, but needs updates								
5 Very satisfactory - Office well-located with secure vestibule and all appropriate security features								
ls there enough interior transparency for faculty to passively supervise	•		3				Comments	
learners and their activities who are not in studios?				<u> </u>				1.00 3.00
1 Very unsatisfactory - No transparency of walls							Some studios have narrow glazing lites in doors; other	ers are 1/2 glazing. No
2 Unsatisfactory - Limited transparency in certain location	3						additional glazing between studios and corridors.	
3 Average - Good transparency in certain locations but								
inadequate or missing in other locations of school								
4 Satisfactory - Adequate transparency throughout the								
school								
5 Very satisfactory - Excellent transparency throughout the	•							
school								
N/A Does not apply								

5 - Environmental Quality			2	3	4	5	N/A		25.00	84%
5.1 How are a	coustics in studios in general?			3				Comments	1.00	3.00
1 Very unsatisfactory - Recognized word/sound from adjacent studio/corridor 2 Unsatisfactory - Audible sound from adjacent studio/corridor 3 Average - Slight sound from outside room 4 Satisfactory - Walls to deck insulated only white noise from mechanical system 5 Very satisfactory - Able to hear quiet speaking from across the room N/A Does not apply								Can hear sound from corridor inside studios. Sound k studios is not noticeable.	oetween conne	cted
•	o artificial lighting adequate quality?				4			Comments	1.00	4.00
1 2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there acc	tess to natural light in studios?					5		Comments	1.00	5.00
1 2 3 4 5	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light							All studios have multiple windows and abundent nat	tural light.	
N/A 5.4 Is there acc	Does not apply ress to outside views from learning spaces?					5		Comments	1.00	5.00
1 2 3 4 5	Very unsatisfactory - No learning spaces have views Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views Does not apply								1.00	5.00

Perkins&Will 02/11/2022 ⁷

5 - Environme	ntal Quality (cont.)	1	2	3	4	5	N/A	4		
5.5 Does the b	uilding have odor or pest problems?				4			Comments	1.00	4.00
1	Very unsatisfactory - Evidence of both pests and odors		•	•		•				
2	Unsatisfactory - Evidence of pests or odors									
3	Average - Limited evidence of pests, no odors									
4	Satisfactory - No evidence of pests / odors, school									
	cleanliness in good condition									
5	Very Satisfactory - No evidence, school cleanliness in									
	excellent condition									
N/A	Does not apply									
6 - Controllab	ility of Systems	1	2	3	4	5	N/A	\	12.50	68%
6.1 Does the st	tudio thermostat allow for individual control?					5		Comments	0.50	2.50
1	1 No									
5										
6.2 Are shades	s provided to control natural light in learning spaces?				4			Comments	1.00	4.00
1	Very unsatisfactory - No, windows are covered with									
	boards/paper									
2	Unsatisfactory - No, windows have no light control									
3	Average - Yes, but poor condition blinds									
4	Satisfactory - Yes, blinds									
5	Very satisfactory - Blackout shades									
N/A	Does not apply									
6.3 What is the	e quality of lighting controls in the studios?		2					Comments	1.00	2.00
1	Very unsatisfactory - Single switch only per room							2-switch system		
2	Unsatisfactory - Alternating rows switch off									
3	Average - Alternating lamps in single fixtures switch off									
4	4 Satisfactory - Tri level switching									
5	Very satisfactory - Dimmable									
N/A	N/A Does not apply							1		

7 - Furniture, F	7 - Furniture, Fixtures & Equipment				4	5	N/A		18.75	75%
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.00
1 2 3 4 5 N/A	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New Does not apply									
	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?			3				Comments	1.00	3.00
1 2 3 4 5	Very Unsatisfactory - Same furniture used in all spaces Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space Satisfactory - All multi-use spaces have greater than one type of furniture Very satisfactory - All multi-use spaces have greater than two types of furniture							Variety of seating configuration in library, movable k		
N/A How well d	Does not apply does furniture accommodate rapid reconfiguration of a									
7.3 space?	associationals association apia reconsignation of a				4			Comments	1.00	4.00
1 2	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups							Except cafeteria. Long tables in cafeteria.		
3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
4 5	Satisfactory - Furniture is flexible for multiple configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
N/A	Does not apply									
7.4 Is the furnit	ture ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
2	Unsatisfactory - Desk with attached chair combinations									
3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4	very satisfactory Tables with roose chairs									
5	Very satisfactory - Tables with loose chairs that allow students to be active									
N/A	Does not apply									

Perkins&Will 02/11/2022 ⁹

Waste		1	2	3	4	5	N/A	5.0	0	
Do studios and corridors have binstructions and/or image sortin	,				4			Comments 0.5	0	:
bins and signage only landfill bins w	y - There are no recycling and landfill are sparse or infrequent, OR there are ith no recycling bins. ns and signage are sparse or							A score for this category is being recorded, but this category is calculated in the overall ESA average. No green bins in studios and cafeteria. Staff separate in cafete		
•	corridors and studios have both a ecycle bin in an accessible location.							ino green bins in studios and caretend. Stan separate in carete	iiu.	
landfill and recycle location. The conto	of studios and corridors have a visible collection containers in an accessible ainers have clear signage.									
visible landfill and accessible location	All studios / corridors (100%) have recycle collection containers in as. The containers have clear signage, format is consistent and uniform across									
N/A Does not apply										
	meals are served) have at least one e recycle bin, and landfill bin? Are the ual and/or image sorting?				4			Comments 0.5	0	
	y- There may be landfill bins, but there id/or recycle bins. There is not clear							A score for this category is being recorded, but this category is calculated in the overall ESA average.	not	
present, but the bi next to one anothe	cycle, landfill, and compost bins are ns are scattered and no co-located er. Signage is absent or inconsistent.									
three bins (recycle,	at least one waste station with all compost, landfill) located with close nother. The signage is visible and									
4 Satisfactory- There described above	e are several waste stations as									
	There are several waste stations as and additional signage in the cafeteria									
	ecycling/composting.									



Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Ridgetop ES	Carlos Cruz and Kristen Klein	1.11.21

1 Very unsatisfactory - Too small, no flexibility, disconnected 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply S 2 Do Pre-K and Kinder have appropriate support spaces such as	8 - 8	- Academics & Learning		1	2	3	4	5	N/A	4	70.00	47%
disconnected 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, undequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shored learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequates size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition	8.1	Are studios	appropriately configured per the ed spec?		2					Comments	1.00	2.00
2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Generous size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		1	Very unsatisfactory - Too small, no flexibility,							Studios are undersized at 670 SF. Some studios have	a connecting	
methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition			disconnected							multipurpose room to allow for breakout space. It is s	hared with oth	er
teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		2	,							studio.		
teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		3	teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to									
different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces N/A Does not apply 8.2 Po Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		4	teaching methods, good flexibility, good transparency and connection to other studios and shared learning									
B.2 Do Pre-K and Kinder have appropriate support spaces such as restrooms and storage per the ed spec? 1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		5	different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and									
restrooms and storage per the ed spec? 1		N/A	Does not apply									
Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition	8.2)				3				Comments	1.00	3.00
Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition		1	Very unsatisfactory - None provided							Restrooms are within a shared breakout room.		
updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition		2	Unsatisfactory - Too small, disconnected, poor condition									
5 Very Satisfactory - Generous size, connected, excellent condition			updates or renovations to function well									
N/A Does not apply		-	Very Satisfactory - Generous size, connected, excellent									
		N/A	Does not apply									

Perkins&Will 02/11/2022 ²

8 - <i>A</i>	Academics 8	& Learning (cont.)	1	2	3	4	5	N/A	A		
8.3	Do studios h ed spec?	nave appropriate support spaces such as storage per the					5		Comments	1.00	5.00
	1	Very unsatisfactory - None provided							Built-in cabinets and connecting space has storage.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4	Do typical le	earning neighborhoods have small group rooms and open			3				Comments		
0.4	collaboration	on space?			3				Comments	1.00	3.00
	1	Very unsatisfactory - No breakout rooms or open							About half the studios share a multipurpose room be	tween the two	studios.
		collaboration spaces are provided							This layout could allow for small group rooms to be p	rovided, but w	ill need
	2 Unsatisfactory - Too small or too few, poor condition, no								updates to function as such.		
		flexibility, lacks visual connection to learning							'		
		neighborhood, poor acoustic privacy									
	3 Average - Adequate size, adequate condition, needs										
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
		transparency and connection to learning neighborhood,									
	_	acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply	1			ı				Ī	
8.5		studios large enough to support project-based learning		2					Comments		
	ana multipi	e teaching modalities?								1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not							General studios are undersized with limited flexibility	'.	
	•	support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,							Principal's comment - Students frequently participate	e in PBL and te	achers
	•	limited flexibility Average - Adequate size, needs some renovations or							use multiple teaching modalities.		
	3	updates to function well									
	4	Satisfactory - Good size, centralized resources, good									
	flexibility										
	5	Very Satisfactory - Generous size, centralized project									
		resources, excellent flexibility									
	N/A Does not apply										

Perkins&Will 02/11/2022 ³

8 - Academics & Learning (cont.)	1	2	3	4	5	N/A			
8.6 Are Maker Spaces and support spaces appropriately configured per the ed spec?	1						Comments	1.00	1.00
Very unsatisfactory - No dedicated maker spaces Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility									
 Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition, connected to learning spaces 									
5 Very Satisfactory - Generous size, excellent condition, connected to learning spaces N/A Does not apply									
8.7 Is there a Professional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
Very unsatisfactory - No dedicated space for Professional Learning Center Unsatisfactory - Too small, poor condition, disconnected Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4 Satisfactory - Good size, good condition, connected 5 Very Satisfactory - Generous size, excellent condition, connected									
N/A Does not apply					1				
8.8 Is there a dedicated science room and support space?	1						Comments	0.00	0.00
1 No 5 Yes							Monitoring answer, but doesn't affect overall score.		
Are there adequate places to display the evidence and artifacts of learning (both 2D and 3D)?				4			Comments	1.00	4.00
1 Very unsatisfactory - No dedicated space									
2 Unsatisfactory - Too small, non-dedicated, poor condition									
3 Average - Adequate size, adequate condition, needs									
updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									

Perkins&Will 02/11/2022 ⁴

8 - Academ	ics & Learning (cont.)	1	2	3	4	5	N/A	1		
Does th	e building provide adequate opportunities for									
	s/teachers to collaborate in varying group sizes?			3				Comments	1.00	3.00
1	Very unsatisfactory - No space to support collaboration									
	in various sizes.									
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple options									
	to support a variety of group sizes									
5	Very Satisfactory - Generous size, excellent condition,									
	multiple options to support a variety of group sizes									
N/A	Does not apply									
9.11 Does th	e building provide opportunities for informal interaction?			3				Comments		
				J				Comments	1.00	3.00
1	Very unsatisfactory - No space									
2	Unsatisfactory - Too small, poor condition, layout and									
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	11.7					,		<u>, </u>		
	e learning neighborhood / building provide adequate			3				Comments		
opportu	nities for students to work independently?			Ü				Comments	1.00	3.00
1	Very unsatisfactory - No breakout rooms/small study							Common area is the only space. Used as computer la	b.	
	spaces									
2	Unsatisfactory - Too small, poor condition, no acoustic									
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy,									
	variety of independent work space options, connected to									
	learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space									
	options, connected to learning neighborhood									
N/A	Does not apply									

Perkins&Will 02/11/2022 ⁵

8 - Academics	& Learning (cont.)							
8.13 Are Specia spec?	ll Education spaces appropriately configured per the ed	1				Comments	1.00	1.00
1	Very unsatisfactory - Too small, no flexibility, disconnected	l		1		No dedicated room for life skills. Regular studio.		
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited							
	transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous							
	display area and visual teaching tools, excellent transparency and connection with other studios and							
N/A	shared learning spaces Does not apply							
Are Specia	Il Education support spaces, such as storage, space for yer, appropriately configured per the ed spec?	1				Comments	1.00	1.00
1	Very unsatisfactory - None provided					No dedicated Special Education room.		
2	Unsatisfactory - Too small, disconnected, poor condition							
3	Neutral - Adequate size, average condition, needs							
	updates or renovations to function well							
4	Satisfactory - Good size, connected, good condition							
5	Very Satisfactory - Generous size, connected, excellent condition							
N/A	Does not apply							
X IA	ible restrooms and changing rooms readily available to the ucation spaces?	1				Comments	1.00	1.00
1	No							
5	Yes							

Perkins&Will 02/11/2022 ⁶

9 - Visual and	Performing Arts	1	2	3	4	5	N/A		15.00	53%
9.1 Are music sper the ed	spaces and the cafeteria stage appropriately configured spec?				4			Comments	1.00	4.00
1 2 3	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Neutral - Adequate size, adequate condition, needs updates or renovations to function well.							Separate auditorium from cafeteria		
4 5 N/A	Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply									
9.2 Are music of per the ed	and performance storage spaces appropriately configured spec?		2					Comments	1.00	2.0
1 2 3 4 5	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition							Located in standard studio. Undersized. Missing supp	ort programs.	
9.3 Are Visual ed spec?	Does not apply Arts spaces and storage appropriately configured per the		2					Comments	1.00	2.0
1 2 3 4 5 N/A	Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition Average - Adequate size, adequate condition, needs some renovations or updates to function well Satisfactory - Good size, good condition Very Satisfactory - Generous size, excellent condition Does not apply							Located in standard studio. Undersized. Missing supp	ort programs.	

Perkins&Will 02/11/2022 ⁷

	10 - PE and We	llness	1	2	3	4	5	N/	A	10.00	50%
	10.1	impus meet the ed spec standard for physical education		2					Comments		
	program sp	aces?		_						1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Gym is small at 2250 square feet. There are high win	dows that prov	ide
	2	Unsatisfactory - Too small, poor condition							natural daylight.		
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
ı	N/A	Does not apply		,						1	
	10.2	sical education storage spaces appropriately configured			3				Comments		
	per the ed s	·								1.00	3.00
	1	Very unsatisfactory - None provided							Support spaces are adequate. Storage room is acces	sed off of vesti	bule
	2	Unsatisfactory - Too small, disconnected, poor condition							from the gym. No PE Storage (outdoor) provided.		
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
	N/A	condition Does not apply									
	11 - Food Service	,	1	2	2	4	E	NI/	Α.	10.00	E09/
ĺ	11 - rood Servic	.es	1	2	3	4	5	N/.	<u>A</u>	10.00	50%
	11.1 Is the Dining	g Commons appropriately configured per the ed spec?			3				Comments	1.00	3.00
	1	Very unsatisfactory - Too small, missing program spaces							Large tables. Good access to daylight. Size meets Ed	Spec.	
	2	Unsatisfactory - Too small, poor condition, only one									
		option for eating space provided, inadequate circulation									
	_										
	3	Average - Adequate size and condition, needs updates									
	4	or renovations to function well									
	4	Satisfactory - Good size and condition, good circulation,									
		multiple options for eating space (ex: connection to outdoor eating space)									
	5	Very Satisfactory - Generous size, excellent condition and									
	ŭ	circulation, multiple options for eating space (ex:									
		connection to outdoor eating space)									
	N/A	Does not apply									
	Are the Foo	d Services support spaces appropriately configured per		_					6		
	11.2 the ed spec	?		2					Comments	1.00	2.00
,	1	Very unsatisfactory - None provided							Kitchen is undersized.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Door not apply									

- Media Resources		2	3	4	5	N/A		30.00	57%
Is the Library/Media Center easily accessible for the occupants and		2					Comments		
visitors to the school?							Comments	1.00	2.00
Very unsatisfactory - Not accessible					•	•	Library has limited transparency to the rest of the sch	ool and is locat	ted
2 Unsatisfactory - Limited access, difficult to find, no							next to the gym and cafeteria. This is down the main	hallway somew	vhat
transparency							removed from main entry.		
3 Average - Adequate accessibility, needs updates or							,		
renovations to function well									
4 Satisfactory - Accessible, easy to find, good									
transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent									
transparency, excellent condition N/A Does not apply									
N/A Does not apply		l l	ı	Г	I	Π			
12.2 How well does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1 Very unsatisfactory - No quiet study spaces		1	<u> </u>				Only one large area and depends on overall noise lev		
2 Unsatisfactory - One area in poor condition, poor							Only one large area and depends on overall hoise lev	ei witiiii iibiai	у.
acoustic privacy									
 3 Average - One or more areas provided, needing updates 									
or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interaction?		2					Comments	1.00	2.00
1 Very unsatisfactory - No space			<u> </u>					1.00	2.00
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply									
How well does the Library/Media Center support collaborative work			3				Comments		
in small groups (4-8 students)?			L				Commonto	1.00	3.00
1 Very unsatisfactory - No breakout rooms, no flexible									
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
Average - Adequate size, multiple areas provided, pooding undates or repoyations to function wall.									
needing updates or renovations to function well 4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									

	12 - Media Resources - Continued		1	2	3	4	5	N/A	1		
	12.5 How well do	oes the Library/Media Center support collaborative work				4			Comments		
	in larger gro	oups (10-25)?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No gathering areas							Movable furniture.		
	2	Unsatisfactory - Too small, one common space, limited									
		seating, poor condition									
	3	Average - Adequate size, one common space, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, multiple common spaces with									
		seating, good condition									
	5	Very Satisfactory - Generous size, multiple commons									
		spaces with seating, excellent condition									
	N/A	Does not apply					1	ı	T	Τ	
	12.6 How well do	oes the Library/Media Center support technology?				4			Comments	1.00	4.00
	1	Very unsatisfactory - No vis comm tools								•	
	2	Unsatisfactory - Outdated, poorly functioning, or									
		insufficient									
	3	Good - Mix of old and new whiteboards/projectors/etc.									
	4	Satisfactory - Projectors, marker boards, smart boards in									
		most spaces - good condition									
	5	Very Satisfactory - Projectors, marker boards, smart									
		boards in most spaces - new condition									
	N/A	Does not apply									
	13 - Technolog	у	1	2	3	4	5	N/A		20.00	70%
	13.1 How well ed	quipped are the facilities with instructional technology?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Limited to no technology present in					ļ	ļ	Updated as part of 2017 bond. All learning spaces ha		
	·	instructional spaces							opuated as part of 2017 bond. All learning spaces no	ive edudispidy:	5.
	2	Unsatisfactory - One type of technology present									
	3	Average - Multiple types of technology, smart boards,									
	· ·	poor condition, limited to only certain areas of school									
	4	Satisfactory - Multiple types of technology, smart									
		boards, good condition.									
	5	Very Satisfactory - Multiple types of technology, smart									
		boards, excellent condition									
	N/A	Does not apply									
	13.2 Is there and	adequate number of power and data outlets in learning				4			Comments		
	spaces?					7			Comments	1.00	4.00
	1	Very unsatisfactory - Outlet configuration does not									
		support digital devices throughout school (1 per wall)									
	2	Unsatisfactory - Outlet configuration support digital									
		devices only in certain areas of school (2 per wall)									
	3	Average - Outlet configuration support digital devices									
		but not enough capacity throughout school (3 per wall)									
	4	Satisfactory - Outlet configuration support digital									
		devices with adequate coverage and capacity									
	5	throughout school (>3 per wall)									
	5	Very Satisfactory - Excellent outlet configuration to									
J	•										
	N/A	support digital devices throughout school (>3 per wall) Does not apply									

13 - Technology (cont.)	1	2	3	3 4	5	N/A	4		
13.3 Are there adequate charging locations for devices?			3	3			Comments	1.00	3.00
1 Very unsatisfactory - No centralized charging location 2 Unsatisfactory - Centralized charging location, but inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition							Principal's note: In normal school year, the school has carts. These were relocated during 2020-2021 school		ging
N/A Does not apply									
13.4 Is there adequate AV for presentations spaces – cafeteria and gym?			3	3			Comments	1.00	3.0
 Very unsatisfactory - AV not present in one or more space Unsatisfactory - AV undersized for room, poor condition Average - Adequately sized / poor condition OR AV undersized / adequate condition Satisfactory - Good size, good condition Very Satisfactory - Generous sized, excellent condition 							There is no AV capabilities in the cafeteria. The audit capabilities.	orium has AV	
N/A Does not apply 13.5 Is there digital media signage at the reception area?			3	3			Comments	0.00	0.0
1 Very unsatisfactory - No digital media present in reception area 2 Unsatisfactory - Undersized, poor condition 3 Average - Adequately sized / poor condition OR undersized / adequate condition 4 Satisfactory - Media signage present, good sized, good condition 5 Very Satisfactory - Generously sized, excellent condition									
N/A Does not apply									

14 - Administration Spaces	1	2	3	4	5	N/A	\	20.00	55%
14.1 Is there a reception area that functions as a security checkpoint for all visitors?							Comments	1.00	
l Very unsatisfactory - No security checkpoint	-	•	•		·•			•	
2 Unsatisfactory - Checkpoint is too small, poor condition									
Average - Needs updates or renovations to function well									
4 Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous size, excellent condition									
N/A Does not apply									
14.2 Does the administration area feel welcoming?			3				Comments	1.00	3.00
1 Very unsatisfactory - No welcome space									
 Unsatisfactory - Too small, poor lighting and 									
transparency, limited informal seating, poor condition									
Average - Adequate size and layout, needs updates or									
renovations to feel welcoming									
4 Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
5 Very Satisfactory - Generous size and layout, plenty of									
light and transparency, informal seating provided,									
excellent condition									
N/A Does not apply									
For those spaces that require it, does the administration area have									
14.3 adequate acoustic privacy?		2					Comments	1.00	2.00
l Very unsatisfactory - No acoustic separations									
2 Unsatisfactory - Acoustic separations do not perform									
well									
3 Average - Some acoustic separations function okay, but									
portions need updates or renovations									
4 Satisfactory - Good acoustic separations									
5 Very Satisfactory - Excellent acoustic separations									
N/A Does not apply						1			
14.4 Are conference rooms easily accessed for public / parent use?			3				Comments	1.00	2 00
1 Very unsatisfactory - Not accessible for public/parent		<u> </u>		<u> </u>	<u> </u>	<u> </u>	In library anges. For 9 poorls	1.00	3.00
use							In library space. For 8 people.		
2 Unsatisfactory - Limited access, no transparency, poor									
condition, difficult to find									
Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Good accessibility, good transparency,									
good size and condition									
5 Very Satisfactory - Excellent accessibility, excellent									
transparency, generous size, excellent condition									
N/A Does not apply									