



Educational Suitability Summary Report

Wooten Elementary School

Date: 10/28/2020

Score 45% Unsatisfactory

Wooten Elementary School serves an enrollment of approximately 380 students in north Austin and is adjacent to Wooten Park, a public park. The building was built in 1955 and additions were constructed in 1960 and 1966. The school provides multiple programs, including dual-language and pre-K, and has an animal husbandry area to raise goats.

The current configuration of the three main studio wings with narrow outdoor space in between has remained since it was originally built. The school needs updates since most of the spaces are configured as they were more than 50 years ago.

Interview Overview

The intervie	w was conducted with Principal Angelo San Segundo, who had concerns with the overall
flow	. It was noted that it is confusing for visitors to locate the front entry.
	The front office is
not conduci	ve to receiving the number of visitors typically on the campus.
	. (While this assessment does not cover the
portables, it	t is assumed that spaces in portables will be found deficient.)

The campus overall is dated, and the teachers work within spaces that lack sufficient technology and power outlets by using extension cords. The learning spaces also lack flexibility and sufficient support spaces. Lack of community and conference rooms is also a challenge. Counseling programs are in portables, as well as life skills and music. Most of the furniture is current and allows for flexibility. The layout does not lend itself for a variety of learning environments such as desired pods. The main outdoor learning space is between two studio wings where there is a small, fenced area for raising goats. Outdoor spaces need furniture to conduct class outside. When outdoor learning occurs, it often becomes a distraction to other studios due to the ease of sound transmission between studios and the corridor.

Assessment Findings

The Educational Suitability Assessment of Wooten Elementary earned a 45% overall score and places the campus in a category of unsatisfactory. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Very Unsatisfactory Categories (0-35%):

Educational Suitability Summary Report

Wooten Elementary School

Exterior

Score is very unsatisfactory.

Confusing to determine where main entry to building is for visitors. Few narrow outdoor spaces for learning. Main outdoor learning space is taken up with fenced-in goats. Small bus lane and no loop for parent pickup/drop-off. Children are dropped off from public street.

General Building

Score is very unsatisfactory.

Corridors are narrow and lowered ceilings make space appear even narrower and uninviting. Spaces are not well located to support community use for evening functions without entering the main part of the building. Unable to separate studio wings from gym or cafeteria. Lack of a dedicated community room for after-hours functions. Conference room table is in assistant principal's office.

Academics & Learning

Score is very unsatisfactory.

Studios are not updated to current standards and have limited flexibility, lack of transparency and connection to corridor and other studios. Pre-K and kindergarten spaces are undersized and lack support spaces with storage. The small amount of built-in storage is dated and insufficient. Learning neighborhoods do not have small group or collaboration spaces. Studios are not large enough to support project-based learning and multiple learning modalities. No dedicated maker space on campus. Library has been used but is inadequate to function as a maker space. Campus does not have a dedicated professional learning center. Few display cases or other areas dedicated to show evidence and artifacts of learning. Special education spaces are in portables and are deficient.

Visual and Performing Arts

Score is very unsatisfactory.

Music spaces are not appropriately configured. Music studio is in a portable and occasionally taught in the library. Art room does not have adequate sinks and is lacking necessary storage.

Administration Spaces

Score is very unsatisfactory. Reception/front desk is very small and has minimal seating for waiting area.

. Overall arrangement does not

feel welcoming. Sound could be easily heard through spaces and there is no acoustic privacy from nurse's room. The campus does not have a dedicated conference room. Observed a conference table in the assistant principal's office.

Unsatisfactory Categories (36-50%):

Security

Score is unsatisfactory.

Media Resources Score is unsatisfactory.

Educational Suitability Summary Report

Library/media center is not easy to find and lacks wayfinding signage. It does not support quiet study with only one area with a kiva area that is open to the rest of the library. It is not very supportive for small or larger group collaborative work since it is a single large space. Technology has limited support with few outlets. Extension cords are heavily used to connect A/V devices.

Technology

Score is unsatisfactory.

Technology is mixed and walls are too cluttered to effectively use the markerboards. Learning spaces have a limited number of outlets and rely on use of extension cords. There is no digital media signage at the reception area and the gym lacks any A/V equipment for presentations.

PE and Wellness

Score is unsatisfactory. Gym is undersized and lacks adequate storage space. Exterior storage is available.

Food Services

Score is unsatisfactory.

Cafeteria has odd configuration and presents sightline issues to view performances on stage. Only one space for eating, with no option to eat outside.

Average Categories (51%-65%)

Outdoor Learning and Activity

Score is average.

Main outdoor learning space is occupied by fenced-in goats. There is the opportunity for outdoor learning spaces between studio wings, but these are undeveloped. Campus shares a playground and basketball courts with a community park.

Controllability of Systems

Score is average.

Most studios have old light switches, and many have only one switch. Blinds are present in rooms to control sunlight and most rooms have new thermostats.

Furniture, Fixtures, Equipment

Score is average.

Mix of old and new furniture. Not much variety of furniture types observed throughout the school. New furniture is capable of reconfiguring easily. Most furniture is ergonomic and size-appropriate for grade level.

Satisfactory Categories (66%-80%)

Environmental Quality

Score is satisfactory.

Most studios and learning spaces have access to natural light with outside views. Light levels from both natural and artificial light are satisfactory. No evidence of pest issues or odors were observed. Acoustics in studios are unsatisfactory due to existing louvers in corridor walls.

Educational Suitability Summary Report

Wooten Elementary School



Confusing front entry and flow for visitors into building. Front entry is not where drive is. The school has attempted to make the front entry more visible with plants and signage. Stack space lacking for traffic with student pickup/drop-off on public street.



desk area is narrow with minimal furniture for waiting area.

Educational Suitability Summary Report

Wooten Elementary School



Ceilings are low and in aged condition. Signage and clocks mounted as close to ceiling as possible.

Educational Suitability Summary Report

Wooten Elementary School



Playground equipment on campus is dated, not for a variety of ages and does not have shade.



Library (left) and typical studio (right) show outlet connections not dispersed well within spaces.

Educational Suitability Summary Report

Wooten Elementary School



Main outdoor spaces between studio wings are narrow. Animal husbandry uses up one of the outdoor spaces.



Typical studio has ample daylight. Finishes are dated. Storage is inconsistent between studios and larger tables do not allow for flexible teaching configurations.

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Wooten Elementary School	Patrick Reinhard & Anacleto Rojas Jr.	10.21.2020

1	- Ext	erior		1	2	3	4	5	N/	Ά	8.75	34%
	11	Does the si pedestrian	te permit desirable separation of vehicular, bus and traffic?	1						Comments	1.00	1.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen							Bus drop-off doesn't have much stacking room. Very	small amount o	of
			at the same location							visitor parking on site, not clearly labeled. Parent pick	up and drop-a	off is in
		2	Unsatisfactory - Cars and buses mix, pedestrians are separated							adjacent street.		
		3	Average - Buses, cars, and pedestrians are separate but stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply									
	12		ing easily identified with appropriate signage and vwayfinding?		2					Comments	0.25	0.50
		1	Very unsatisfactory - Campus has no signage /							Street marquee is old, faded, and not as apparent fro	om intersection	•
			wayfinding							Signage on the building looks to be original. Interior s	ignage is close	to low
		2	Unsatisfactory - Signage/wayfinding is faded/hidden							ceilings and not apparent.	0	
		3	Average - Signage / wayfinding visible but not apparent							5		
		4	Satisfactory - Signage / wayfinding is visible but not aood condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									

02/11/2022 ²

1 - Exterior (cont.)	1	2	3	4	5	N/A	N		
1.3 Is the dumpster accessible for trash / compost disposal?			3				Comments	0.50	1.50
 Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster Unsatisfactory - Compost is present. Route has obstacles to dumpster Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent. Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Nery Satisfactory - Compost and dumpster are shaped / positioned so people of all heights can access it. 							Dumpster/recycling are near kitchen and cafeteria o compost dumpster seen, but staff mention they com		oute. No
2 - Outdoor Learning and Activity	1	2	3	4	5	N/A	A Contract of the second s	15.00	60%
2.1 Are outdoor studios and support spaces appropriately configured per the ed spec?		2					Comments	1.00	2.00
 Very unsatisfactory - No dedicated outdoor studios Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area 							Few narrow spaces between studio wings that are no sufficiently. Main outdoor learning space taken up w Outdoor spaces are not well connected to studios.		goats.
N/A Does not apply Are active playgrounds (elementary only) and support spaces 2.2		2					Comments		
 ²¹² configured per the ed spec? Very unsatisfactory - No dedicated active playground Unsatisfactory - Too small, poor condition, no shade provided Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure Satisfactory - Good size, good condition, more than 50% shade coverage over play structure Very satisfactory - Generous size, excellent condition, full shade coverage over play structure N/A Does not apply 							Single playscape on site looks dated and doesn't allo Campus shares playground and basketball courts wi community park. It looks to have a new canopy over but old basketball hoops and shared with community Principal's note - The playground and ball courts can during campus hours, and there has been pushback that they are not able to use it during these times.	th adjacent the basketbal y park. only be used	l court school

02/11/2022 ³

	earning and Activity (cont)	1	2	3	4	5	N/A		
	ns and support spaces appropriately configured per the ed luation on infrastructure not condition of plants)			3				Comments 0.00	0.0
1 2	Very unsatisfactory - No dedicated gardens Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source							Monitoring answer, does not affect score for Outdoor Learning and Activity. Planters are a good size, but are tucked away very far from studios. No water source was apparent.	
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access								
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose								
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation								
N/A	Does not apply			-					
2.4 ed spec?	n gardens and/or cisterns appropriately configured per the	1						Comments 0.00	0.
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor Learning and	k
2	Unsatisfactory - Too small, poor condition, not							Activity.	
3	functioning, disconnected Average - Adequate size, adequate condition, is								
5	connected, needs some renovations or updates to								
	function well								
4	Satisfactory - Good size, good condition, functions								
	properly								
5	Very Satisfactory - Generous size, excellent condition,								
	exceptional functionality, connected to learning spaces,								
N1/A	educational signage provided								
N/A	Does not apply chool have animal husbandry? (optional)					5	1	Comments 0.00	0.
1	No					0		Commenta 0.00	0.
5	Yes								
2.6 Does the se	chool have nature loop trails? (optional)	1					[Comments 0.00	0.
1	No						•	•	
5	Yes								
2.7 Does the so	chool have a learning pond? (optional)	1						Comments 0.00	0.
1	No								
5	Yes					-	-		
	chool have a grass play field and walking trail?					5	I	Comments 1.00	5.
2.8 Does the so 1	No								_

- General Bu	ilding	1	2	3	4	5	N/A	A	11.25	31
Are interior	r circulation routes wide enough to safely and effectively			0				Commente		
3.1 accommod	date student movement?		L	3				Comments	0.50	1.5
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0"							Studio corridors with low ceilings make space seem s	maller.	
	wide									
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are commu	unity use areas arranged so that the school can allow night	1						Community		
3.2 functions w	vithout full school access?	1						Comments	0.75	0.
1	Very unsatisfactory - Cafeteria, gym, and library cannot							No internal security gates or separation.		
	be accessed after hours									
2	Unsatisfactory - Only one of the public spaces (Cafeteria,									
	Gym and Library) can be accessed from parking and									
2	secured after hours Average - Only two of the public spaces can be accessed									
3	from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed									
	from parking and secured from the rest of the building									
	but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be									
	accessed from parking and locked off from rest of									
	campus for night/evening use with their own entrance									
N/A	Does not apply									
ls there a c	community room that is a dedicated meeting space outside	1						Comments		
of school fu	unction?	1						Comments	0.75	0.
1	Very unsatisfactory - No dedicated community room									
2	Unsatisfactory - Community room but within school									
	function, no access after school hours									
3	Average - Community room, moderate size, but need									
4	some renovations or updates to function well Satisfactory - Community room, good size /layout, meets									
7	needs /functions well									
5	Very Satisfactory - Community room, generous size, nice									
	condition, functions appropriately outside of school									
	function									
N/A	Does not apply	1					1			
	eneral appearance of the school convey pride for the		2					Comments		
students ar	nd community?		_						0.25	0.
1	Very unsatisfactory - General appearance is poor							Overall very dated exterior.		
2	Unsatisfactory - General appearance is aged but ok									
2	Average - General appearance is good									
3										
	Satisfactory - General appearance shows pride in									
3 4	campus and student works									
3	campus and student works Very satisfactory - General appearance shows pride in									
3 4	campus and student works									

- Security		1 2	23	4	5 I	N/A		16.25	
4.1 Does the fo	acility have key card access at all major entries?						Comments	0.25	
1 2 3 4 5 N/A	Very unsatisfactory - No entries Unsatisfactory - 1/4 of major entries Average - 1/2 of major entries Satisfactory - 3/4 of major entries Very satisfactory - All of major entries Does not apply							•	
1.2 How adeq	uate is site lighting and security for the campus overall?						Comments	1.00	i
1 2 3 4 5	Very unsatisfactory - No exterior lighting, no secure perimeter Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure								
N/A	Does not apply					L			
1 12	n office located at the school entry and configured with a						Comments		
secure ves	tibule to the main corridor?							1.00	
1 2 3 4 5	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors Average - Office close to entry, views of front door, but no secure vestibule Satisfactory - Office is well-located with a secure vestibule, but needs updates Very satisfactory - Office well-located with secure vestibule and all appropriate security features Does not apply								
N/A									
Is there en	ough interior transparency for faculty to passively supervise	1					Comments	100	
4.4 Is there en learners ar	nd their activities who are not in studios?	1						1.00 parency in wall	
4.4 Is there en learners ar 1	nd their activities who are not in studios? Very unsatisfactory - No transparency of walls						Comments Studio doors have a half light, but otherwise no trans		
4.4 Is there en learners ar 1 2	nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations								
4.4 Is there en learners ar 1	nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school Satisfactory - Adequate transparency throughout the								
4.4 Is there en learners ar 1 2 3	nd their activities who are not in studios? Very unsatisfactory - No transparency of walls Unsatisfactory - Limited transparency in certain locations Average - Good transparency in certain locations but inadequate or missing in other locations of school								<u>1</u> .

5 - Environmer	ntal Quality	1	2	3	4	5	N/A	A	25.00	769
5.1 How are a	coustics in studios in general?			3				Comments	1.00	3.0
1 2 3 4 5 N/A	Very unsatisfactory - Recognized word/sound from adjacent studio/corridor Unsatisfactory - Audible sound from adjacent studio/corridor Average - Slight sound from outside room Satisfactory - Walls to deck insulated only white noise from mechanical system Very satisfactory - Able to hear quiet speaking from across the room Does not apply			<u>.</u>				Louvered windows on corridor walls are still in place poor acoustic separation. Other studio corridors are		reating
5.2 Is the studi	o artificial lighting adequate quality?				4			Comments	1.00	4.0
2 3 4 5 N/A	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC Unsatisfactory - 10-19 FC or serious glare Average- 20-29 FC minor glare Satisfactory - 30-39 FC and no glare Very satisfactory - 40+ FC and no glare Does not apply									
5.3 Is there acc	cess to natural light in studios?				4			Comments	1.00	4.0
1 2 3 4 5 N/A	Very unsatisfactory - No learning spaces have natural light Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light Average - 26-50% of learning spaces have natural light Satisfactory - 51-75% of learning spaces have natural light Very satisfactory - 76-100% of learning spaces have natural light Does not apply							Studios have large windows due to original single-lo A few rooms in the later renovated areas do not hav		-
	cess to outside views from learning spaces?				4			Comments	1.00	4.0
1	Very unsatisfactory - No learning spaces have views				1			Studios have large windows due to original single-lo		
2	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out							A few rooms in the later renovated areas do not hav		-
3 4 5	Average - 26-50% of learning spaces have views Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have									

5 - E	nvironmer	ntal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1 2 3 4 5 N/A	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition Does not apply							No apparent signs of pests.		
6 - C	Controllabi	lity of Systems	1	2	3	4	5	N/A	<u>,</u>	12.50	60%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes							Most rooms have new thermostats.		
6.2		provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades									
	N/A	Does not apply		T							
6.3	What is the	quality of lighting controls in the studios?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply							Most studios have old light switches and many have a	only one switch	1.

7 - Furniture, F	Fixtures & Equipment	1	2	3	4	5	N/A	A	18.75	539
7.1 What is the	e current condition of the furniture?				4			Comments	0.75	3.0
1 2 3 4 5	Very unsatisfactory - Damaged or broken, non- functioning Unsatisfactory - Torn/ bent/ wrong size Average - Scratched/dented/marked Satisfactory - Not new, but sturdy and clean Very satisfactory - New				1			Mix of relatively new and old furniture throughout co type though.	ampus; same fi	urnituro
N/A	Does not apply				1	1	1			
	ety of furniture types being accommodated throughout the arning commons, dining commons, other multi-use spaces?	1						Comments	1.00	1.0
1	Very Unsatisfactory - Same furniture used in all spaces									
2 3	Unsatisfactory - Furniture variety in one multi-use space Average - Furniture variety in more than one multi-use space									
4	Satisfactory - All multi-use spaces have greater than one type of furniture									
5 N/A	Very satisfactory - All multi-use spaces have greater than two types of furniture Does not apply									
	does furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.0
1 2	Very Unsatisfactory - Furniture is fixed or very heavy Unsatisfactory - Furniture does not allow desks to be									
3	configured as individuals, small groups, or large groups Average - Mix of furniture that can reconfigure but is									
4	cumbersome to move Satisfactory - Furniture is flexible for multiple									
5	configurations of space Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
N/A	Does not apply									
7.4 Is the furni	ture ergonomic and size appropriate for grade level?			3				Comments	1.00	3.0
1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
2 3	Unsatisfactory - Desk with attached chair combinations Average - Mix of studios with tables/loose chairs and desks with fixed seats									
4 5	Very satisfactory - Tables with loose chairs Very satisfactory - Tables with loose chairs that allow									
5	students to be active									

02/11/2022 °

Naste		1	2	3	4	5	N/A		5.00	70
	and corridors have blue recycle bins with bilingual and/or image sorting instructions?				4			Comments	0.50	2.0
1 2 3 4 5 N/A	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins. Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage. Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage. Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage. Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus. Does not apply							A score for this category is being recorded, but this catego calculated in the overall ESA average. Students are eating breakfast and lunch in the studios due protocols. Rooms have trash, recycling and compost bins.		
of each: gre	feteria (or wherever meals are served) have at least one een compost bin, blue recycle bin, and landfill bin? Are the d clearly with bilingual and/or image sorting?			3				Comments	0.50	1.
1 2 3 4 5	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage. Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described above Very Satisfactory - There are several waste stations as									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

Academics - Elementary School

School Name	Walk Attendees:	Date:
Wooten Elementary School	Patrick Reinhard & Anacleto Rojas Jr.	10.21.2020

8 - Academ	ics & Learning	1	2	3	4	5	N/A	A	70.00	33%
8.1 Are stur	dios appropriately configured per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - Too small, no flexibility,							No transparency or connection to corridor or other st	udios. Limited	
	disconnected							flexibility. Studios vary in size from 820 SF (100 and 20	00 wing) to 860) SF
2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							(300 wing)		
3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
N/A										
82	K and Kinder have appropriate support spaces such as ms and storage per the ed spec?		2					Comments	1.00	2.00
1	Very unsatisfactory - None provided							Shared restroom between studios, but restroom was	undersized. Stu	ıdios
2	Unsatisfactory - Too small, disconnected, poor condition							are lacking storage space.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									

8 - A	cademics &	& Learning (cont.)	1	2	3	4	5	N/A	N Contraction of the second seco		
8.3	Do studios ł	nave appropriate support spaces such as storage per the		0					Comments		
8.3	ed spec?			2					Comments	1.00	2.00
	1	Very unsatisfactory - None provided							Small amount of built-in storage in each studio space.		
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent									
		condition									
	N/A	Does not apply									
8.4		earning neighborhoods have small group rooms and open	1						Comments		
0.4	collaboratio	•	1						Comments	1.00	1.00
	1	Very unsatisfactory - No breakout rooms or open									
		collaboration spaces are provided									
	2	Unsatisfactory - Too small or too few, poor condition, no									
		flexibility, lacks visual connection to learning									
	0	neighborhood, poor acoustic privacy									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition and flexibility,									
	4	transparency and connection to learning neighborhood,									
		acoustic privacy									
	5	Very Satisfactory - Generous size, excellent condition and									
		flexibility, transparency and connection to learning									
		neighborhood, acoustic privacy									
	N/A	Does not apply									
8.5	•	studios large enough to support project-based learning		2					Comments		
0.0	and multiple	e teaching modalities?		~					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, no flexibility, does not							Not arranged for multiple or flexible teaching styles.		
		support project-based learning									
	2	Unsatisfactory - Undersized, decentralized resources,									
		limited flexibility									
	3	Average - Adequate size, needs some renovations or									
	1	updates to function well									
	4	Satisfactory - Good size, centralized resources, good flexibility									
	5	Very Satisfactory - Generous size, centralized project									
	U	resources, excellent flexibility									
	N/A	Does not apply							L		
	,										

02/11/2022 ³

8 - A	cademics	& Learning (cont.)	1	2	3	4	5	N/A	A		
8.6	Are Maker	Spaces and support spaces appropriately configured per	1						Comments		
8.0	the ed spec	c?	-						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces							No maker spaces. Librarian says they've tried using the	ne library, but	it was
	2	Unsatisfactory - Too small, poor condition, disconnected							not adequate.		
		from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to									
	_	learning spaces									
	5	Very Satisfactory - Generous size, excellent condition,									
	N1/A	connected to learning spaces									
	N/A	Does not apply		r	1		1			1	
8.7	Is there a P	rofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for									
		Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs									
		some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition,									
		connected									
	N/A	Does not apply					1	1		[
8.8	ls there a d	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9	Are there a	dequate places to display the evidence and artifacts of		2					Comments		
0.9	learning (b	oth 2D and 3D)?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No dedicated space							There were a few display cases in the corridor, but no	t much wall u	sable
	2	Unsatisfactory - Too small, non-dedicated, poor							wall space to hang up student work.		
		condition									
	3	Average - Adequate size, adequate condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

	s & Learning (cont.)	I	2	3	4	5	N/A			
	building provide adequate opportunities for	1						Comments		
students/	teachers to collaborate in varying group sizes?	-						Comments	1.00	1.0
1	Very unsatisfactory - No space to support collaboration							No collaboration space outside of the studio.		
	in various sizes.									
2	Unsatisfactory - Too small, inflexible, only one option,									
	does not support a variety of group sizes									
3	Average - Adequate space for collaboration, needs									
	updates or renovations to function well.									
4	Satisfactory - Good size, good condition, multiple options									
	to support a variety of group sizes									
5	Very Satisfactory - Generous size, excellent condition,									
	multiple options to support a variety of group sizes									
N/A	Does not apply									
8 11 Does the	building provide opportunities for informal interaction?	1						Comments		
0.11 Doct the								comments	1.00	1.0
1	Very unsatisfactory - No space							Corridors are not set up for informal interaction or se	eating areas.	
2	Unsatisfactory - Too small, poor condition, layout and									
	furnishings do not support informal interaction well									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size, good condition, layout and									
	furnishings support informal interactions									
5	Very Satisfactory - Generous size, excellent condition,									
	layout and furnishings support informal interactions									
N/A	Does not apply			-	1					
	learning neighborhood / building provide adequate	1						Comments		
opportun	ities for students to work independently?	-						Commenta	1.00	1.
1	Very unsatisfactory - No breakout rooms/small study									
	spaces									
2	Unsatisfactory - Too small, poor condition, no acoustic									
	privacy, only one space for independent work,									
	disconnected from learning neighborhood									
3	Average - Adequate size and condition, needs updates									
	or renovations to function well.									
4	Satisfactory - Good size and condition, acoustic privacy,									
	variety of independent work space options, connected to									
	learning neighborhood									
5	Very Satisfactory - Generous size, excellent condition,									
	acoustic privacy, variety of independent work space									
	options, connected to learning neighborhood									
	Does not apply									


 disconnected Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected Neutral - Adequate size, multiple areas for different 	Comments	1.00 g washer and d	1.00 Iryer.
 disconnected 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different 	ation rooms are in portables and lacking	g washer and d	lryer.
 2 Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected 3 Neutral - Adequate size, multiple areas for different 			
teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to			
function well. 4 Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces			
 5 Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces 			
N/A Does not apply			
8.14 Are Special Education support spaces, such as storage, space for washer/dryer, appropriately configured per the ed spec? 1	Comments	1.00	1.00
1 Very unsatisfactory - None provided			
2 Unsatisfactory - Too small, disconnected, poor condition			
3 Neutral - Adequate size, average condition, needs			
updates or renovations to function well 4 Satisfactory - Good size, connected, good condition			
 Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent 			
condition			
N/A Does not apply			
8.15 Are Accessible restrooms and changing rooms readily available to the Special Education spaces? 5	Comments	1.00	5.00
1 No Portable res	trooms are ADA compliant	•	
5 Yes			

02/11/2022 *

9 -	Visual and	Performing Arts	1	2	3	4	5	N/A		15.00	33%
9.	Are music s per the ed s	paces and the cafeteria stage appropriately configured spec?		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Music is in portables and use library sometimes. Stage	e is small and a	doesn't
	2	Unsatisfactory - Too small, poor condition							have enough seating room in front because of oddly	shaped room.	
	3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									
9.2	Are music c per the ed s	nd performance storage spaces appropriately configured spec?	1						Comments	1.00	1.00
	1	Very unsatisfactory - None provided							Back of stage behind curtains is used as storage space	e.	
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs									
		updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									
9.3	3 Are Visual A ed spec?	Arts spaces and storage appropriately configured per the		2					Comments	1.00	2.00
	1	Very unsatisfactory - Too small, missing program spaces							Art room doesn't have enough sinks and is lacking sto	rage necessar	у.
	2	Unsatisfactory - Too small, poor condition									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									

10 - PE and Wellness	1	2	3	4	5	N/A	A	10.00	409
10.1 Does the campus meet the ed spec standard for physical education program spaces?		2					Comments	1.00	2.0
1 Very unsatisfactory - Too small, missing program spaces 2 Unsatisfactory - Too small, poor condition 3 Average - Adequate size, adequate condition, needs 3 some renovations or updates to function well 4 Satisfactory - Good size, good condition 5 Very Satisfactory - Generous size, excellent condition N/A Does not apply							Gym is small.		
10.2 Are the physical education storage spaces appropriately configured per the ed spec?		2					Comments	1.00	2.0
 Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent condition N/A Does not apply 							Gym lacks storage space. Additional storage space p storage room.	provided in ext	erior
11 - Food Services	1	2	3	4	5	N/A	A	10.00	50
1].] Is the Dining Commons appropriately configured per the ed spec?		2					Comments	1.00	2.0
 Very unsatisfactory - Too small, missing program spaces Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation Average - Adequate size and condition, needs updates or renovations to function well Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space) Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: 							Only 1 option for eating space, which is in poor cond option for eating.	ition. No outsid	le
connection to outdoor eating space) N/A Does not apply									
11.2 Are the Food Services support spaces appropriately configured per the ed spec?			3				Comments	1.00	3.0
 Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well Satisfactory - Good size, connected, good condition Very Satisfactory - Generous size, connected, excellent 							Line equipment looked new. Kitchen was locked and looks adequate per floor plans.	had an alarm,	, but

12 - Media Resources	1	2	3	4	5	N/A	A	30.00	43%
Is the Library/Media Center easily accessible for the occupants and		2					Comments		
visitors to the school?		2					Commenta	1.00	2.0
1 Very unsatisfactory - Not accessible							Library is not easy to find and lacks signage on the co	orridor. Far fron	n main
2 Unsatisfactory - Limited access, difficult to find, no							entrance.		
transparency									
3 Average - Adequate accessibility, needs updates or									
renovations to function well									
4 Satisfactory - Accessible, easy to find, good									
transparency, good condition									
5 Very Satisfactory - Accessible, easy to find, excellent transparency, excellent condition									
N/A Does not apply									
	T				1		• · · ·		
12.2 How well does the Library/Media Center support quiet study?		2					Comments	1.00	2.00
1 Very unsatisfactory - No quiet study spaces	<u> </u>						No acoustic separation in library. It is one large area		
2 Unsatisfactory - One area in poor condition, poor									
acoustic privacy									
3 Average - One or more areas provided, needing updates									
or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, good condition, good acoustic privacy 5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, excellent condition, excellent									
acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interaction?		2					Comments	1.00	2.00
1 Very unsatisfactory - No space					I		Only 3 informal tables. Room is small and lacks a var		2.00
2 Unsatisfactory - Too small, poor condition, layout and									
furnishings do not support informal interaction well									
3 Average - Adequate size and condition, needs updates									
or renovations to function well.									
4 Satisfactory - Good size, good condition, layout and									
furnishings support informal interactions									
5 Very Satisfactory - Generous size, excellent condition,									
layout and furnishings support informal interactions									
N/A Does not apply	1	1	1	1	1	r			
12.4 How well does the Library/Media Center support collaborative work in small groups (4-8 students)?		2					Comments	1.00	2.00
1 Very unsatisfactory - No breakout rooms, no flexible		I		I	I		One large open area and a kiva area. All spaces cou		
furniture, no support									
2 Unsatisfactory - Too small, one area, poor condition									
3 Average - Adequate size, multiple areas provided,									
needing updates or renovations to function well									
4 Satisfactory - Clusters or small rooms adjacent to media									
center, flexible furniture, good condition									
5 Very Satisfactory - Multiple clusters or small rooms									
adjacent to media center, flexible furniture, excellent									
condition									
N/A Does not apply									



12 - Media Resources	s - Continued	1	2	3	4	5	N/A			
12.5 in larger groups (10				3				Comments	1.00	3.00
2 Unsa seatii 3 Avero upda 4 Satist seatii 5 Very space	unsatisfactory - No gathering areas tisfactory - Too small, one common space, limited ng, poor condition age - Adequate size, one common space, needs tes or renovations to function well factory - Good size, multiple common spaces with ng, good condition Satisfactory - Generous size, multiple commons es with seating, excellent condition not apply									
12.6 How well does the	Library/Media Center support technology?		2					Comments	1.00	2.00
2 Unsa insuff 3 Good 4 Satist most 5 Very board	unsatisfactory - No vis comm tools tisfactory - Outdated, poorly functioning, or ficient I - Mix of old and new whiteboards/projectors/etc. factory - Projectors, marker boards, smart boards in spaces - good condition Satisfactory - Projectors, marker boards, smart ds in most spaces - new condition not apply							Very limited outlets throughout the library. Extension A/V systems for students to use. Kiva area has a very		ded for
13 - Technology		1	2	3	4	5	N/A		20.00	40%
	d are the facilities with instructional technology?			3				Comments	1.00	3.00
instru 2 Unsa 3 Avero poor 4 Satist board 5 Very board	unsatisfactory - Limited to no technology present in actional spaces tisfactory - One type of technology present age - Multiple types of technology, smart boards, condition, limited to only certain areas of school factory - Multiple types of technology, smart ds, good condition. Satisfactory - Multiple types of technology, smart ds, excellent condition not apply							Mobile screens and projectors in most rooms. Walls o cluttered to utilize markerboards.	ind rooms are	too
	ate number of power and data outlets in learning		2					Comments	1.00	2.00
supp 2 Unsa devic 3 Avero but n 4 Satist	unsatisfactory - Outlet configuration does not ort digital devices throughout school (1 per wall) tisfactory - Outlet configuration support digital es only in certain areas of school (2 per wall) age - Outlet configuration support digital devices ot enough capacity throughout school (3 per wall) factory - Outlet configuration support digital es with adequate coverage and capacity							Very limited amount of outlets throughout studios.		
supp 2 Unsa devic 3 Avero but n 4 Satist devic throu 5 Very supp	ort digital devices throughout school (1 per wall) tisfactory - Outlet configuration support digital es only in certain areas of school (2 per wall) age - Outlet configuration support digital devices ot enough capacity throughout school (3 per wall) factory - Outlet configuration support digital							Very limited amount of outlets throughout studios.		

13 - Technolog	ıy (cont.)	1	2	3	4	5	N/A	A		
13.3 Are there o	adequate charging locations for devices?		2					Comments 1.0	0	2.0
1	Very unsatisfactory - No centralized charging location							1 charging cart noticed in the computer room, which wasn't in	a cent	ralize
2	Unsatisfactory - Centralized charging location, but							location.		
	inadequate in size for number of devices									
3	Average - Charging cart or tower but not adequately sized for number of devices									
4	sized for number of devices Satisfactory - Charging cart or tower not centralized									
5	Very Satisfactory - Charging cart or tower not centralized									
0	centralized location. Excellent condition									
N/A	Does not apply									
13.4 Is there ad	equate AV for presentations spaces – cafeteria and gym?	1						Comments		
	· · · · · · · · · · · · · · · · · · ·							1.0	-	1.0
1	Very unsatisfactory - AV not present in one or more							Small project screen was in dining commons, but no projector.	Gym	didn
0	space							have a screen or projector.		
2 3	Unsatisfactory - AV undersized for room, poor condition									
3	Average - Adequately sized / poor condition OR AV undersized / adequate condition									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous sized, excellent condition									
N/A	Does not apply									
	jital media signage at the reception area?	1						Comments	~	•
1	Very unsatisfactory - No digital media present in				1			0.0	0	0.0
	reception area									
2	Unsatisfactory - Undersized, poor condition									
3	Average - Adequately sized / poor condition OR									
	undersized / adequate condition									
4	Satisfactory - Media signage present, good sized, good									
	condition									
5	Very Satisfactory - Generously sized, excellent condition									
N/A	Does not apply									

4 - 4	Administre	ation Spaces	1	2	3	4	5	N/A		20.00	35
14.1	ls there a re visitors?	eception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint								ł	
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply					1		1	1	
14.2	Does the a	dministration area feel welcoming?		2					Comments	1.00	2.0
	1	Very unsatisfactory - No welcome space							Limited seating provided. New small window allows	transparency,	but
	2	Unsatisfactory - Too small, poor lighting and							overall doesn't feel welcoming.		
		transparency, limited informal seating, poor condition									
	3	Average - Adequate size and layout, needs updates or									
		renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and									
	5	transparency, informal seating provided Very Satisfactory - Generous size and layout, plenty of									
	5	light and transparency, informal seating provided,									
		excellent condition									
	N/A	Does not apply									
14.0	For those s	paces that require it, does the administration area have									
14.3		acoustic privacy?		2					Comments	1.00	2.
	1	Very unsatisfactory - No acoustic separations							Could easily hear through doors. Nurse's room did no	ot have adequ	ate
	2	Unsatisfactory - Acoustic separations do not perform							acoustic privacy either.		
		well									
	3	Average - Some acoustic separations function okay, but									
		portions need updates or renovations									
	4 5	Satisfactory - Good acoustic separations									
	5 N/A	Very Satisfactory - Excellent acoustic separations Does not apply									
	IN/A	Does not apply	1	1	1	1		1			
14.4	Are confere	ence rooms easily accessed for public / parent use?	1						Comments	1.00	1.0
	1	Very unsatisfactory - Not accessible for public/parent							No dedicated conference room provided. Conferenc	e table arrang	jed in
	2	Use							assistant principal's office.		
	2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or									
	Ū	renovations to function well									
	4	Satisfactory - Good accessibility, good transparency,									
		good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent									
		transparency, generous size, excellent condition									
	N/A	Does not apply									