Sunset Valley Elementary School



Educational Suitability and Facility Condition Assessments - 2021



Facility Summary

Sunset Valley Elementary School, serving an enrollment of approximately 500 students in south Austin, is known for its dual-language program. The school is an AVID and Austin Literacy Academy campus and offers the Creative Learning Initiative to its students. The original building was built in 1971, and an annex classroom building was constructed in 1996. The building is somewhat dated, but the learning spaces function quite well, with several large collaboration spaces surrounded by studios. This layout gives teachers flexibility to divide students into a variety of group sizes, while still supervising those students in the shared space. Acoustic privacy is difficult in these studios due to the fact that they are connected by sliding walls or open corridors.

Building Address: 3000 Jones Road Austin, TX 78745

Building Square Footage: 67,000 SF Site Acreage: 10 Acres Date of First Construction: 1971


Student Demographics:


Demographic	Percentage
African American	2.5%
Hispanic	57.4%
White	35.0%
American Indian	0.0%
Asian	1.4%
Pacific Islander	0.0%
Two or More Races	3.7%
Economically Disadvantaged	29.8%
English Language Learners	28.0%
Special Education	12.6%
Enrollment	486

Educational Suitability Assessment Score:

– – District ElementarySchool's ESA Average: 64










Facility Condition Assessment Score:

– – District Elementary School's FCA Average: 62



Questions/Comments? Email: Assessments@perkinswill.com

Sunset Valley Elementary School



Educational Suitability and Facility Condition Assessments - 2021

The ESA evaluates how well a facility supports teaching and learning using the district's Educational Specifications as the standard. It includes items such as the exterior, general building, security, controllability of lighting, furniture, academic and administrative spaces, and technology.

The FCA evaluates the physical condition of a facility to measure what systems are broken, aging, etc. This includes items such as roofing, heating and air conditioning, plumbing, electrical, site drainage, and parking.

Both assessments incorporate data, staff interviews, facility walk-throughs, cost-estimating, and analysis.

ESA Score:

District Elementary School's ESA Average: 64



General Building

1 - Exterior 2 - Outdoor Learning and Activity

3 - General Building

4 - Security

5 - Environmental Quality


6 - Controllability of Systems

7 - Furniture, Fixtures, Equipment



District Elementary School's FCA Average: 62

FCA Score:



Campus-wide

1 - Exterior Architecture

2 - Interior Architecture

3 - Structural

4 - Mechanical / HVAC

5 - Electrical

6 - Plumbing

7 - Site / Civil

8 - Crawlspace



Academics

8 - Academics & Learning

9 - Visual and Performing Arts

10 - PE and Wellness

11 - Food Service

12 - Media Resources

13 - Technology

14 - Administration Spaces

Very Unsatisfactory 0-35

Unsatisfactory 36-50

Average 51-65

Satisfactory 66-80 Very Satisfactory 81-100

Questions/Comments?

Email: Assessments@perkinswill.com