



Ortega Elementary School

Date: 01/08/2021

Score 55% Average

Ortega Elementary School, serving an enrollment of approximately 240 students, is in east Austin. It was built in 1959 with additions in 1966 and 1968 and consists of approximately 47,800 square feet. The school provides an early childhood development program and two-way dual-language program in addition to core subjects that are part of the district's creative learning initiative to promote an arts-rich education. The campus is known for its Super Star Choir program.

The school grounds are large, and the adjacency to Ortega School Park provides additional outdoor amenities such as a large walking track that is open to the community. Large, open green spaces and numerous playscapes give students a wide variety of areas to play. The building wings form two large courtyards that are well-used by the school and contain a learning pond and gardens, a shaded outdoor studio, and a partially covered dining area. The school's outdoor learning program has a fenced-in area containing several goats.

Interview Overview

An interview with Principal Jennifer Stephens, Assistant Principal Carrie Freeman, teachers and administrative staff was held to discuss concerns and how well spaces function on the campus. They are proud of their school and really like how the cafeteria, gym and courtyard spaces between the buildings function. They discussed several areas that could be improved but said they do not let the physical space limit them.

Lack of suitable space means that several programs are in either typical studios or portables. Music and the ACE after-school program are in portables, and the staff would like to have a soundproof music and separate choir room with risers as part of the permanent facilities. Special education does not have accessible restrooms. The school needs a dedicated maker space, professional development areas, a true teachers' lounge, and additional adult restrooms.

When thinking about the future of education, the staff sees several trends that they hope to be able to address. Lighting and furniture for education will continue to evolve, with more options for seating types and desks that change height. The staff feels that green initiatives will continue to play an important role and would like to see the windows and lighting in the school be more energy efficient.

The school uses its outdoor spaces often, but staff have numerous ideas for how they could be improved. The existing outdoor studio needs repairs due to rotten wood and exposed nails and could be updated with larger benches. Additional outdoor studios with desks and power would enable them to hold several classes simultaneously. The walking trail is quite large, but could be better activated with plantings, distance markers, small play areas, or exercise stations spaced around it.

Ortega Elementary School

Assessment Findings

The Educational Suitability Assessment of Ortega Elementary School earned a 55% overall score and places the campus in a category of Average. The assessment consists of seven General Building categories and seven Academic categories to determine areas that need more attention.

Unsatisfactory Categories (36-50%):

Academics & Learning

Score is unsatisfactory.

Studios are adequately sized but lack transparency and shared spaces for flexible teaching. Storage cabinets run along a full wall and are in generally good condition. Special education classes do not have access to an accessible restroom. Currently, the school does not provide a life skills program. There are limited 2D display areas and no 3D display areas.

Visual and Performing Arts

Score is unsatisfactory.

The music and art rooms are not in dedicated spaces. Music takes place in a portable and art is held in a typical studio without the required support spaces. The school stage in the cafeteria is large and in good condition.

PE and Wellness

Score is unsatisfactory.

The gym is very small with low ceilings and no natural light. Basketball goals are original to the school and offer no ability to raise or lower them. Gym support is limited, with a small office and inadequate storage room.

Media Resources

Score is unsatisfactory.

The library is close to the main entrance but has limited signage or transparency. The library is a small open space, with a reading amphitheater but little flexible seating. Attached rooms that could be used for group activities or breakouts currently house storage and a conference room.

Technology

Score is unsatisfactory.

Studios are equipped with flat panel TVs on carts with digital projectors and screens. Charging capabilities are limited, with limited wall outlets and no centralized charging locations. The cafeteria has some A/V equipment, but it is limited and makes it difficult for them to hold large meetings.

Administration Spaces

Score is unsatisfactory. The administration space is small and feels dated. **Ortega Elementary School**

02/11/2022 Perkins&Will

Average Categories (51-65%):

Exterior

Score is average.

Building and site signage need to be updated. The monument sign is old and faded, with peeling letters. The building signage is partially hidden by trees and is small and unlit. Bus and parent dropoff is separated, with parents using the front entry drive and buses in the side parking lot. There are times when the buses block the staff parking lot.

General Building

Score is average.

The building hallways are well-sized at 10 feet wide and are easy to navigate. The school's layout allows the gym and cafeteria to be used after-hours and secured from the rest of the school.

Security

Score is average.

Controllability of Systems

Score is average.

Each studio has its own thermostat to control the temperature. Window blinds are installed at each window and are in generally good condition. Lighting controls are limited to a single switch turning all fixtures on or off.

Furniture, Fixtures, Equipment

Score is average.

Furniture throughout the school is in good condition and seems relatively new. Many of the studios have arrow-shaped desks and loose chairs, which can quickly switch between group and individual learning.

Satisfactory Categories (66-80%):

Outdoor Learning and Activity

Score is satisfactory.

The gardens and outdoor learning spaces in the courtyards between the building wings are well utilized. The shaded outdoor studio is well-configured but needs some updates. Play areas are dated with little shade provided. Only the outdoor basketball court has a shade canopy over it.

Environmental Quality

Score is satisfactory.

Studios generally have ample natural light. Most have windows running the full length of the exterior wall. Views are limited, and many studios look out to the adjacent building wing.

Ortega Elementary School

Food Services

Score is satisfactory.

The cafeteria is well-sized, and the school is very happy with how it functions. The space has lots of natural light with windows on both sides of the hall. A secure outdoor dining area is next to the cafeteria, providing numerous options for seating.

Ortega Elementary School



Main building entry provides covered area for pickup and drop-off, but main entry door feels unwelcoming.



Monument sign is faded, and letters are peeling. Staff requested a digital marquee.

02/11/2022 Perkins&Will

Educational Suitability Summary Report

Ortega Elementary School



Outdoor Learning and Activity: Learning garden and shaded outdoor studio.



Outdoor Learning and Activity: Courtyard outside the cafeteria is partially covered. Seating is provided but is not reconfigurable.


02/11/2022 Perkins&Will

Educational Suitability Summary Report

Ortega Elementary School



Main Entry Hallway: Library is on the right side of the photo, but there is no transparency into the space.



Reception area is small and feels somewhat dated.

Ortega Elementary School



Typical studios have reconfigurable furniture, casework storage and natural light. Chalkboards are present but are not being used.



Media Center: Library is small with limited flexibility and no breakout spaces.

Ortega Elementary School



Outdoor Learning and Activity: The playscape does not have shade. A wide walking trail around the green space is provided.




Goat pen on campus is very popular with students.

Ortega Elementary School



Gym is undersized (2,350 square feet) per Ed Spec. The space does not have any natural light.



Food Services: Cafeteria has ample natural light and large stage. Functions well.

02/11/2022




Perkins&Will

Austin ISD Educational Suitability Assessment Criteria

General Building

School Name	Walk Attendees:	Date:
Ortega Elementary School	_ Anacleto Rojas, Kevin Kinsey	1/4/2021

1	- Ex	terior		1	2	3	4	5	N/A		8.75	63%
	1.1	Does the site pedestrian t	e permit desirable separation of vehicular, bus and traffic?			3				Comments	1.00	3.00
		1	Very unsatisfactory - Bus, car and pedestrian all happen at the same location							Pickup/drop-off at front of school. Bus loop at side of so	chool.	
		2	Unsatisfactory - Cars and buses mix, pedestrians are separated									
		3	Average - Buses, cars, and pedestrians are separate but stack space is small									
		4	Satisfactory - Buses, cars, and pedestrians are separate but drop off does not have a canopy or a holding place like a commons or cafeteria									
		5	Very satisfactory - Buses, cars, and pedestrians are separate and drop off area has a canopy and destination									
		N/A	Does not apply									
	1.2	ls the buildir wayfinding?	ng easily identified with appropriate signage and community ?		2					Comments	0.25	0.50
		1	Very unsatisfactory - Campus has no signage / wayfinding									
		2	Unsatisfactory - Signage/wayfinding is faded/hidden									
		3	Average - Signage / wayfinding visible but not apparent									
		4	Satisfactory - Signage / wayfinding is visible but not good condition									
		5	Very satisfactory - Signage and wayfinding is visible and easy to use									
		N/A	Does not apply									



Exterior (cor	nt.)	1	2	3	4	5	N/A	<u> </u>		
.3 Is the dump	oster accessible for trash / compost disposal?				4			Comments	0.50	2.0
1	Very unsatisfactory - No compost present, route has obstacles (stairs, curbs, barriers) to dumpster				•	•			•	
2	Unsatisfactory - Compost is present. Route has obstacles to dumpster									
3	Average - Compost is present (<100' to cafeteria), Route to dumpster is free and clear but the two are not directly adjacent.									
4	Satisfactory - Compost and dumpster are directly adjacent and route is barrier free									
5	Very Satisfactory - Compost and dumpster are directly adjacent and route is barrier free. Dumpster are shaped / positioned so people of all heights can access it.									
N/A	Does not apply									
Outdoor Lee	arning and Activity	1	2	3	4	5	N/A	A Contraction of the second seco	15.00	e
2.1 Are outdoo the ed spec	r studios and support spaces appropriately configured per ?			3				Comments	1.00	3
1	Very unsatisfactory - No dedicated outdoor studios							Outdoor learning needs upgrades to furniture, infrastr	ucture and sho	ade t
2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no shade provided							function well.		
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over studio area									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, more than 50% shade coverage over studio area									
5	Very satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, full shade coverage over studio area									
N/A	Does not apply									
	playgrounds (elementary only) and support spaces per the ed spec?		2					Comments	1.00	2
1	Very unsatisfactory - No dedicated active playground								•	
2	Unsatisfactory - Too small, poor condition, no shade provided									
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, 50% or less shade coverage over play structure									
4	Satisfactory - Good size, good condition, more than 50% shade coverage over play structure									
5	Very satisfactory - Generous size, excellent condition, full									
0	shade coverage over play structure									

02/11/2022 ³

- Outdoor Le	arning and Activity (cont)	1	2	3	4	5	N/A			
	ns and support spaces appropriately configured per the ed luation on infrastructure not condition of plants)			3				Comments	0.00	0.00
1	Very unsatisfactory - No dedicated gardens							Monitoring answer, does not affect score for Outdoor L	earning and A	Activity.
2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility, no accessible water source								J.	,
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well, water source is difficult to access									
4	Satisfactory - Good size, good condition, connected to learning spaces, good flexibility, water source is accessible with 100 ft hose									
5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces, excellent flexibility, water source is less than 50ft from the garden or has irrigation									
N/A	Does not apply									
2.4 Are the rain ed spec?	n gardens and/or cisterns appropriately configured per the		2					Comments	0.00	0.00
1	Very unsatisfactory - No rain gardens or cisterns							Monitoring answer, does not affect score for Outdoor L	earnina and A	Activity.
2	Unsatisfactory - Too small, poor condition, not functioning, disconnected								g	,
3	Average - Adequate size, adequate condition, is connected, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition, functions properly									
5	Very Satisfactory - Generous size, excellent condition, exceptional functionality, connected to learning spaces, educational signage provided									
N/A	Does not apply									
2.5 Does the so	chool have animal husbandry? (optional)					5		Comments	0.00	0.00
1	No									
5	Yes									
2.6 Does the so	chool have nature loop trails? (optional)	1						Comments	0.00	0.00
1	No									
5	Yes	r —				-	r —	Grandel	0.00	0.00
2.7 Does the so	chool have a learning pond? (optional) No					5	L	Comments	0.00	0.00
5	Yes									
-	chool have a grass play field and walking trail?	r				5	1	Comments	1.00	5.00
1	No									
5	Yes									

02/11/2022 4


- General Bu	ilding	1	2	3	4	5	N/A	N Contraction of the second seco	11.25	62%
	r circulation routes wide enough to safely and effectively date student movement?				4			Comments	0.50	2.00
1	Very unsatisfactory - Primary circulation is 5'-0" to 6'-0" wide	•								
2	Unsatisfactory - Primary circulation is 6'-0" to 7'-0" wide									
3	Average - Primary circulation is 7'-0" to 8'-0" wide									
4	Satisfactory - Primary circulation is 8'-0"-10'-0" wide									
5	Very satisfactory - Primary circulation is 10'-0"+ wide									
N/A	Does not apply									
Are comm	unity use areas arranged so that the school can allow night	1	1	<u> </u>		1	r –			
	vithout full school access?			3				Comments	0.75	2.2
1	Very unsatisfactory - Cafeteria, gym, and library cannot be accessed after hours							Cafeteria can easily be used for after-hours activities. I but cannot be secured from rest of school.	ibrary is close	to entr
2	Unsatisfactory - Only one of the public spaces (Cafeteria, Gym and Library) can be accessed from parking and secured after hours									
3	Average - Only two of the public spaces can be accessed from parking and secured after hours									
4	Satisfactory - All of the public spaces can be accessed from parking and secured from the rest of the building but not individually									
5	Very satisfactory - Cafeteria, gym, and library can be accessed from parking and locked off from rest of campus for night/evening use with their own entrance									
N/A	Does not apply									
1.3 Is there a c school fun	community room that is a dedicated meeting space outside of ction?			3				Comments	0.75	2.2
1	Very unsatisfactory - No dedicated community room				1			Shared space with library		
2	Unsatisfactory - Community room but within school function, no access after school hours									
3	Average - Community room, moderate size, but need some renovations or updates to function well									
4	Satisfactory - Community room, good size /layout, meets needs /functions well									
5	Very Satisfactory - Community room, generous size, nice condition, functions appropriately outside of school function									
N/A	Does not apply									
	eneral appearance of the school convey pride for the nd community?		2					Comments	0.25	0.5
1	Very unsatisfactory - General appearance is poor							School from outside and main entry feels unwelcoming	and dated.	
2	Unsatisfactory - General appearance is aged but ok							, · · · · · · · · · · · · · · · · · · ·		
3	Average - General appearance is good									
4	Satisfactory - General appearance shows pride in campus and student works									
5	Very Unsatisfactory - General appearance shows pride in									
	campus and student works and is welcoming to the community									

02/11/2022 5

- Security		1	2	3	4	5	N/A		16.25	
	acility have key card access at all major entries?							Comments	0.25	
1	Very unsatisfactory - No entries									
2	Unsatisfactory - 1/4 of major entries									
3	Average - 1/2 of major entries									
4 5	Satisfactory - 3/4 of major entries Very satisfactory - All of major entries									
5 N/A	Does not apply						l			
	uate is site lighting and security for the campus overall?							Comments		_
1	Very unsatisfactory - No exterior lighting, no secure				I				1.00	
	perimeter									
2	Unsatisfactory - Lighting is limited to front entry only, parking lot lighting poor, security is minimal									
3	Average - Lighting at all night-use entries and parking lot, but poor condition. Security is moderate									
4	Satisfactory - Lighting at all night-use entries and parking lots, good condition, signage less visible, perimeter is well secured but needs updates									
5	Very satisfactory - Signage, parking lots, and entries are well lit, visible and easy to use, perimeter is very secure									
N/A	Does not apply						ı			
	office located at the school entry and configured with a							Comments		
secure vest	ibule to the main corridor?							conmenta	1.00	
1	Very unsatisfactory - No secure vestibule, office located far from main entry, allows visitors access to school unsupervised									
2	Unsatisfactory - No secure vestibule, office located somewhat far from main entry, minimal supervision of visitors									
3	Average - Office close to entry, views of front door, but no secure vestibule									
4	Satisfactory - Office is well-located with a secure vestibule, but needs updates									
5	Very satisfactory - Office well-located with secure vestibule and all appropriate security features									
N/A	Does not apply									
	ough interior transparency for faculty to passively supervise Ind their activities who are not in studios?		2					Comments	1.00	
1	Very unsatisfactory - No transparency of walls				1					
2	Unsatisfactory - Limited transparency in certain locations									
3	Average - Good transparency in certain locations but inadequate or missing in other locations of school									
4	Satisfactory - Adequate transparency throughout the school									
5	Very satisfactory - Excellent transparency throughout the school									
N/A	Does not apply						ľ			

02/11/2022 °

- Environme	ntal Quality	1	2	3	4	5	N/A		25.00	72
	icoustics in studios in general?	•	2		<u> </u>			Comments		
1	Very unsatisfactory - Recognized word/sound from								1.00	2.0
	adjacent studio/corridor									
2	Unsatisfactory - Audible sound from adjacent studio/corridor									
3	Average - Slight sound from outside room									
4	Satisfactory - Walls to deck insulated only white noise from mechanical system									
5	Very satisfactory - Able to hear quiet speaking from across the room									
N/A	Does not apply									
5.2 Is the stud	io artificial lighting adequate quality?			3				Comments	1.00	3.0
1	Very unsatisfactory - Sporadic lights work, glare, less than 20 FC									
2	Unsatisfactory - 10-19 FC or serious glare									
3	Average- 20-29 FC minor glare									
4	Satisfactory - 30-39 FC and no glare									
5	Very satisfactory - 40+ FC and no glare									
N/A	Does not apply									
5.3 Is there ac	cess to natural light in studios?					5		Comments	1.00	5.0
1	Very unsatisfactory - No learning spaces have natural light				•			Some only have two windows		
2	Unsatisfactory - 1-25% of learning spaces have natural light or windows are too small to let in light									
3	Average - 26-50% of learning spaces have natural light									
4	Satisfactory - 51-75% of learning spaces have natural light									
5	Very satisfactory - 76-100% of learning spaces have natural light									
N/A	Does not apply									
5.4 Is there ac	cess to outside views from learning spaces?				4			Comments	1.00	4.
1	Very unsatisfactory - No learning spaces have views									
2	Unsatisfactory - 1-25% of learning spaces have views or windows are too small to see out									
3	Average - 26-50% of learning spaces have views									
4	Satisfactory - 51-75% of learning spaces have views									
4	Satisfactory - 51-75% of learning spaces have views Very satisfactory - 76-100% of learning spaces have views									



5 - E	nvironmen	tal Quality (cont.)	1	2	3	4	5	N/A			
5.5	Does the bu	uilding have odor or pest problems?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - Evidence of both pests and odors Unsatisfactory - Evidence of pests or odors Average - Limited evidence of pests, no odors Satisfactory - No evidence of pests / odors, school cleanliness in good condition Very Satisfactory - No evidence, school cleanliness in excellent condition		<u> </u>							
	N/A	Does not apply									
6 - 0		ity of Systems	1	2	3	4	5	N/A		12.50	60%
6.1	Does the st	udio thermostat allow for individual control?					5		Comments	0.50	2.50
	1 5	No Yes									
6.2	Are shades	provided to control natural light in learning spaces?				4			Comments	1.00	4.00
	1 2 3 4 5	Very unsatisfactory - No, windows are covered with boards/paper Unsatisfactory - No, windows have no light control Average - Yes, but poor condition blinds Satisfactory - Yes, blinds Very satisfactory - Blackout shades							Blinds are in adequate shape.		
	N/A	Does not apply	_							-	
6.3	What is the	quality of lighting controls in the studios?	1						Comments	1.00	1.00
	1 2 3 4 5 N/A	Very unsatisfactory - Single switch only per room Unsatisfactory - Alternating rows switch off Average - Alternating lamps in single fixtures switch off Satisfactory - Tri level switching Very satisfactory - Dimmable Does not apply									

02/11/2022 *

7 - Fu	urniture, Fiz	xtures & Equipment	1	2	3	4	5	N/A	<u></u>	18.75	64%
7.1	What is the	current condition of the furniture?				4			Comments	0.75	3.00
	1	Very unsatisfactory - Damaged or broken, non-functioning							Furniture is in good shape.		
	2	Unsatisfactory - Torn/ bent/ wrong size									
	3	Average - Scratched/dented/marked									
	4	Satisfactory - Not new, but sturdy and clean									
	5	Very satisfactory - New									
_	N/A	Does not apply			r	-	1	1	1		
7.2		y of furniture types being accommodated throughout the		2					Comments		
/.2	school - lea	rning commons, dining commons, other multi-use spaces?		_						1.00	2.00
	1	Very Unsatisfactory - Same furniture used in all spaces					1		Cafeteria does not have furniture variety. Library can b		
	2	Unsatisfactory - Furniture variety in one multi-use space							utilizing due to COVID-19 protocols.		
	3	Average - Furniture variety in more than one multi-use									
	4	space Satisfactory - All multi-use spaces have greater than one									
	-	type of furniture									
	5	Very satisfactory - All multi-use spaces have greater than two types of furniture									
	N/A	Does not apply			r						
7.3	How well do space?	bes furniture accommodate rapid reconfiguration of a			3				Comments	1.00	3.00
	1	Very Unsatisfactory - Furniture is fixed or very heavy								1	
	2	Unsatisfactory - Furniture does not allow desks to be configured as individuals, small groups, or large groups									
	3	Average - Mix of furniture that can reconfigure but is cumbersome to move									
	4	Satisfactory - Furniture is flexible for multiple configurations of space									
	5	Very satisfactory - Furniture is flexible for multiple configurations of space, easy to move and stack									
	N/A	Does not apply									
7.4	ls the furnitu	are ergonomic and size appropriate for grade level?				4			Comments	1.00	4.00
	1	Very unsatisfactory - Desk with attached chair combinations too small for grade level									
	2	Unsatisfactory - Desk with attached chair combinations									
	3	Average - Mix of studios with tables/loose chairs and desks with fixed seats									
	4	Very satisfactory - Tables with loose chairs									
	5	Very satisfactory - Tables with loose chairs that allow students to be active									
	N/A	Does not apply									

02/11/2022 °

Waste		1	2	3	4	5	N/A		5.00	60
	and corridors have blue recycle bins with bilingual a and/or image sorting instructions?			3				Comments	0.50	1.
1	Very unsatisfactory - There are no recycling and landfill bins and signage are sparse or infrequent, OR there are only landfill bins with no recycling bins.							A score for this category is being recorded, but this cat in the overall ESA average.	egory is not ca	lculat
2	Unsatisfactory - Bins and signage are sparse or infrequent and/or lack clear signage.									
3	Average - 50% of corridors and studios have both a landfill bin and a recycle bin in an accessible location. The containers have clear signage.									
4	Satisfactory - 75% of studios and corridors have a visible landfill and recycle collection containers in an accessible location. The containers have clear signage.									
5	Very satisfactory - All studios / corridors (100%) have visible landfill and recycle collection containers in accessible locations. The containers have clear signage, and the style and format is consistent and uniform across campus.									
N/A	Does not apply									
each: greer	afeteria (or wherever meals are served) have at least one of n compost bin, blue recycle bin, and landfill bin? Are the bins early with bilingual and/or image sorting?			3				Comments	0.50	1.
1	Very unsatisfactory- There may be landfill bins, but there are no compost and/or recycle bins. There is not clear sorting signage.							A score for this category is being recorded, but this cat in the overall ESA average.	egory is not ca	lculat
	ser ting eightaget									
2	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent.									
2 3	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next									
	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity									
3	Unsatisfactory- Recycle, landfill, and compost bins are present, but the bins are scattered and no co-located next to one another. Signage is absent or inconsistent. Average- There is at least one waste station with all three bins (recycle, compost, landfill) located with close proximity to one another. The signage is visible and consistent. Satisfactory- There are several waste stations as described									

02/11/2022



Perkins&Will

Austin ISD Educational Suitability Assessment Criteria


Academics - Elementary School

School Name	Walk Attendees:	Date:
Ortega Elementary School	Anacleto Rojas, Kevin Kinsey	1/4/2021


3 - Ac	ademics &	& Learning	1	2	3	4	5	N//	A	70.00	40%
8.1	Are studios	appropriately configured per the ed spec?			3				Comments	1.00	3.0
	1	Very unsatisfactory - Too small, no flexibility, disconnected							Studios are a mixture of sizes. Some in main wing are 8 addition are smaller at 780 SF.	370 SF and stud	lios in
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected									
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.									
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces									
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces									
	N/A	Does not apply									
		nd Kinder have appropriate support spaces such as and storage per the ed spec?			3				Comments	1.00	3.0
	1	Very unsatisfactory - None provided									
	2	Unsatisfactory - Too small, disconnected, poor condition									
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, connected, good condition									
	5	Very Satisfactory - Generous size, connected, excellent condition									
	N/A	Does not apply									

02/11/2022 ²

1 Very unsatisfactory - None provided 2 Unsatisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, average condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Good size, connected, excellent condition 0 NA 0 Does not apply 8.4 Do typical learning neighborhoods have small group rooms and open collaboration spaces? 1 1 Very statisfactory - No breakout rooms or open collaboration spaces? 1 1 Very unsatisfactory - No breakout rooms or open collaboration spaces are provided 2 2 Unsatisfactory - Too small or too few, poor condition, no flexibility, lack visual connection to learning neighborhood, poor acoustic privacy 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition needs some renovations or updates to function well 4 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 5 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy N/A Does no	8 - 8	Academics a	& Learning (cont.)	1	2	3	4	5	N/A			
2 Unastisfactory - Too small, disconnected, poor condition 3 Neutral - Adequate size, overage condition, needs updates or renovations to function well 4 Satisfactory - Generous size, connected, scellent condition 5 Very Satisfactory - Reperous size, connected, scellent condition no flexibility, facts visual connection to learning neighborhoods have small group rooms and open collaboration space? 1 Comments 1.00 1.00 8.4 Do typical learning neighborhoods have small group rooms and open collaboration space? 1 Comments 1.00 1.00 2 Unastifactory - No breakout rooms or open collaboration space? Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 3 Average - Adequate size, adequate condition, no flexibility. Icats visual connection to learning neighborhood, acoustic privacy Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 4 Satisfactory - Generous size, excellent condition and flexibility. Itorapsency and connection to learning neighborhood, acoustic privacy Soutificatory - Too small, no flexibility. does not support prioet-based learning and resulting and result visoa (regree sough to support privacy) 3 Comments 1.00 3.00 8.5 Average - Adequate size, needs some renovations or update	8.3		nave appropriate support spaces such as storage per the ed				4			Comments	1.00	4.00
3 Neutral - Adequade size, overage condition, needs updates or renovations to function well 4 Satisfactory - Good size, connected, good condition 5 Very Satisfactory - Generous size, connected, excellent condition 1 1 Comments 1.00 1.00 8.4 Do typical learning neighborhoods have small group rooms and open colleboration spaces are provided 1 Image: Colleboration spaces 1.00 1.00 1.00 1 Very unsatisfactory - No breakout rooms or open colleboration spaces are provided Studics on double-loaded corridor. No flexibility for small group or 1.00 1.00 1.00 2 Unsatisfactory - Too small or too few, poor condition, need space renovations or updates to function well Studics on double-loaded corridor. No flexibility for small group or collaboration spaces 3 Average - Adequate size, a		1	Very unsatisfactory - None provided							Studios have adequate built-in storage.		
a Sotisfactory - Good size, connected, good condition 5 Very Sotisfactory - Generous size, connected, excellent condition N/A Does not apply 8.4 Do typical learning neighborhoods have small group rooms and open collaboration space? 1 Image: Connected studies of the studies of t		2	Unsatisfactory - Too small, disconnected, poor condition									
5 Very Stitifactory - Generous size, connected, excellent condition N/A Dees not apply 8.4 Dotypical learning neighborhoods have small group rooms and open collaboration space? 1 Comments 1.00 1.00 1 Very usatiafactory - No breakout rooms or open collaboration spaces are provided Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 3 Average - Adequate size, adequate condition, no flexibility, lack sizual connection to learning neighborhood, occoustic privacy Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 5 Very Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, occoustic privacy Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 5 Very Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, occoustic privacy Studios on double-loaded corridor. No flexibility for small group or collaboration spaces. 8.5 Are general studios large enough to support project-based learning and hexibility. does not support project-based learning and support project-based learning and upport		3										
volume N/A Does not apply 8.4 Dotypical learning neighborhoods have small group rooms and open colladoration space? 1 Comments 1.00 1.00 8.4 Dotypical learning neighborhoods have small group rooms on open colladoration spaces are provided 1 Image: Comments 1.00 1.00 1 Very unsatisfactory - No breakout rooms or open colladoration spaces are provided 1 Image: Comments Studios on double-loaded corridor. No flexibility for small group or colladoration spaces. 2 Unsatisfactory - Too small or too few. poor condition, no flexibility, tacks visual connection to learning neighborhood, poor accustic privacy Studios on double-loaded corridor. No flexibility for small group or colladoration spaces. 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 3 Comments 1.00 3.00 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 3 Comments 1.00 3.00 8.5 Are general studios large enough to support project-based learning and multiple teaching modellites? 3 Comments 1.00 3.00 9 Very Satisfactory - Good size, centralized resources, limitted flexibility 3 Com		4	Satisfactory - Good size, connected, good condition									
8.4 Do typical learning neighborhoods have small group rooms and open collaboration spaces 1 Comments 1.00 1.00 1 Very unsatisfactory - No breakout rooms or open collaboration spaces are provided 1 Comments 1.00 1.00 2 Unsatisfactory - Too small or too few, poor condition, no flexibility, lacks visual connection to learning neighborhood, poor acoustic privacy Studies on double-loaded corridor. No flexibility for small group or collaboration spaces. Studies on double-loaded corridor. No flexibility for small group or collaboration spaces. 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well Studies on double-loaded corridor. No flexibility for small group or collaboration spaces. 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy Studies on double -loaded corridor. No flexibility for small group or collaboration spaces. 5 Very Stifactory - Goenerous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 3 Comments 1.00 3.00 8.5 Are general studies large enough to support project-based learning and support project-based learning 3 Comments 1.00 3.00 1 Very satisfactory - Too small, no flexibility, apport project-based learning 3 <t< td=""><td></td><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></t<>		5										
8.4 collaboration space? 1 1 1 1.00 1.00 1.00 1 Very unsatisfactory - No breakout rooms or open collaboration spaces are provided 2 Unsatisfactory - Too small or too few, poor condition, no flexibility, lack sizual connection to learning neighborhood, poor acoustic privacy 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 3 Comments 1.00 3.00 8.5 Are general studios large enough to support project-based learning medifies? 3 Comments 1.00 3.00 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning and multiple teaching modellities? 3 Comments 1.00 3.00 2 Unsatisfactory - Too small, no flexibility, does not support project-based learning 3 Comments 1.00 3.00 3 Average - Adequate size, needs some renovations or updates to function well 3 Comments 1.00 3.00 2 Unsatisfactory - Too small, no flexibility. does not support project-b		N/A	Does not apply									
collaboration spaces are provided 2 Unsatisfactory - Too small or too few, poor condition, no fielxibility, lacks visual connection to learning neighborhood, poor acoustic privacy 3 Average - Adequate size, adequate some renovations or updates to function and flexibility, transparency and connection to learning neighborhood, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 7 NA Does not apply 8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 1 Very notatisfactory - Too small, no flexibility, does not support project-based learning 2 Unsatisfactory - Undersized, decentralized resources, limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Good size, centralized resources, limited flexibility 5 Very Satisfactory - Good size, centralized project resources, excellent flexibility 5 Very Satisfactory - Good size, centralized project resources, excellent flexibility	8.4		on space?	1						Comments	1.00	1.00
flexibility, lacks visual connection to learning neighborhoad, poor acoustic privacy 3 Average - Adequate size, adequate condition, needs some renovations or updates to function well 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhoad, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhoad, acoustic privacy 5 Are general studies large enough to support project-based learning and multiple teaching modalities? 3 Comments 1.00 3.00 8.5 Are general studies large enough to support project-based learning multiple teaching modalities? 3 Comments 1.00 3.00 9 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 3 Comments 1.00 3.00 1 Very unsatisfactory - Undersized, decentralized resources, limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Goed size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility Very Ventralized resources, good flexibility 5		1			-						all group or	
renovations or updates to function well 4 Satisfactory - Good size, good condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy N/A Does not apply 8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 3 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 3 2 Unsatisfactory - Undersized, decentralized resources, limited flexibility 3 3 Average - Adequate size, needs some renovations or updates to function well 4 4 Satisfactory - Good size, centralized resources, good flexibility 5 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility 5		2	flexibility, lacks visual connection to learning									
transparency and connection to learning neighborhood, acoustic privacy 5 Very Satisfactory - Generous size, excellent condition and flexibility, transparency and connection to learning neighborhood, acoustic privacy N/A Dees not apply 8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 3 Comments 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 3 Are general studios large enough to support project-based learning and multiple teaching modalities? 1.00 3.00 2 Unsatisfactory - Too small, no flexibility, does not support project-based learning 3 Comments 1.00 3.00 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Good size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, good flexibility 5 Very Satisfactory - Generous size, centralized project 5 Very Satisfactory - Generous size, centralized project 5		3										
flexibility, transparency and connection to learning neighborhood, acoustic privacy N/A Does not apply 8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 3 Comments 1.00 3.00 8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 3 Comments 1.00 3.00 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 2 Unsatisfactory - Undersized, decentralized resources, limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Good size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility		4	transparency and connection to learning neighborhood,									
8.5 Are general studios large enough to support project-based learning and multiple teaching modalities? 3 Comments 1.00 3.00 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 2 Unsatisfactory - Undersized, decentralized resources, limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Goenerous size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility		5	flexibility, transparency and connection to learning									
8.5 multiple teaching modalities? 1.00 3.00 1 Very unsatisfactory - Too small, no flexibility, does not support project-based learning 1.00 3.00 2 Unsatisfactory - Undersized, decentralized resources, limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Good size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility		N/A	Does not apply									
 support project-based learning Unsatisfactory - Undersized, decentralized resources, limited flexibility Average - Adequate size, needs some renovations or updates to function well Satisfactory - Good size, centralized resources, good flexibility Very Satisfactory - Generous size, centralized project resources, excellent flexibility 	8.5					3				Comments	1.00	3.00
limited flexibility 3 Average - Adequate size, needs some renovations or updates to function well 4 Satisfactory - Good size, centralized resources, good flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility		1										
 updates to function well Satisfactory - Good size, centralized resources, good flexibility Very Satisfactory - Generous size, centralized project resources, excellent flexibility 		2										
flexibility 5 Very Satisfactory - Generous size, centralized project resources, excellent flexibility		3										
resources, excellent flexibility		4	,									
N/A Does not apply		5										
		N/A	Does not apply									



8 - A	cademics &	k Learning (cont.)	1	2	3	3 4	5	N/A	4		
8.6	Are Maker S ed spec?	Spaces and support spaces appropriately configured per the	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated maker spaces									
	2	Unsatisfactory - Too small, poor condition, disconnected from learning spaces, no flexibility									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected to learning spaces									
	5	Very Satisfactory - Generous size, excellent condition, connected to learning spaces									
	N/A	Does not apply									
8.7	Is there a Pr	ofessional Learning Center in the learning neighborhood?	1						Comments	1.00	1.00
	1	Very unsatisfactory - No dedicated space for Professional Learning Center									
	2	Unsatisfactory - Too small, poor condition, disconnected									
	3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
	4	Satisfactory - Good size, good condition, connected									
	5	Very Satisfactory - Generous size, excellent condition, connected									
	N/A	Does not apply									
8.8	ls there a de	edicated science room and support space?	1						Comments	0.00	0.00
	1	No							Monitoring answer, but doesn't affect overall score.		
	5	Yes									
8.9		dequate places to display the evidence and artifacts of oth 2D and 3D)?		2					Comments	1.00	2.00
	1	Very unsatisfactory - No dedicated space							Limited locations of 2D display. No 3D display areas.		
	2	Unsatisfactory - Too small, non-dedicated, poor condition									
	3	Average - Adequate size, adequate condition, needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply									



1 Very unsatisfactory - No space to support collaboration in various sizes. 2 Unsatisfactory - Too small, inflexible, only one option, does not support a variety of group sizes 3 Average - Adequate space for collaboration, needs updates or renovations to function well. 4 Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 8.11 Does the building provide opportunities for informal interaction? 1 Very satisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, layout and furnishings support informal interactions 4 Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions	8 - A		k Learning (cont.)	1	2	3	4	5	N/A			
variance sizes. 2 Unsufficiency - Too small inflexible, only one option, does not support a variety of group sizes 3 3 Average - Adequate space for collaboration, meeds updates or renovations to function will. 4 Satisfactory - Good size, good condition, multiple options to support a variety of group sizes 5 5 Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes 6 8.11 Does not apply Comments 1.00 8.12 Very Satisfactory - Too small, poor condition, layout and furnishings support informal interactions well 3 3 Average - Adequate size and condition, layout and furnishings support informal interactions well 1 0 8.12 Does the learning neighborhood / building provide adequate for apply 1 1 1.00 8.12 Does the learning neighborhood / building provide adequate or renovations to function well. 1 0 Comments 1.00 1.00 8.12 Does the learning neighborhood 1 0 Comments 1.00 1.00 8.12 opportunities for student to work independentify? 1 0 Comments 1.00 1.00 1 Very Satiffactory - No breakout rooms/small study spoce	8.10	Does the bu to collabora	ilding provide adequate opportunities for students/teachers ite in varying group sizes?	1						Comments	1.00	1.00
an upport a variety of group sizes 3 Average - Adequate space for collaboration, needs updates or renovations to function well. 4 Satisfactory - Coencous size, excellent condition, multiple options to support a variety of group sizes 5 Very Satisfactory - Coencous size, excellent condition, multiple options to support a variety of group sizes 8.11 Does not apply 8.11 Very satisfactory - Too small, poor condition, layout and furnishings do not support informal interactions well 3 Average - Adequate size and condition, needs updates or renovations to function well 3 Average - Adequate size and condition, layout and furnishings support informal interactions 4 Satisfactory - Goo small, poor condition, layout and furnishings support informal interactions 5 Very satisfactory - Goo small, poor condition, layout and furnishings support informal interactions 6.10 Does the learning neighborhood / building provide adequate opport. 1 Comments 1.00 1.00 8.12 Dees the learning neighborhood 1 Comments 1.00 1.00 3 Average - Adequate size and condition, needs updates or renovations to work independently vork, disconnected from learning neighborhood 1 Comments 1.00 1.00 100 Usatisfactory - Os smal		1	, , , , , ,		•		•					
4 Satisfactory - Generous size, excellent condition, multiple options is to support a variety of group sizes 5 Very Satisfactory - Generous size, excellent condition, multiple options to support a variety of group sizes N/A Does not apply 8.11 Does not apply 8.11 Does not apply 8.11 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interactions well 3 Average - Adequate size, good condition, layout and furnishings support informal interactions well 4 Satisfactory - Gon size, good condition, layout and furnishings support informal interactions well 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Very Satisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 1 Very Satisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 2 Very Satisfactory - Too space 1 Comments 1.00 1.00 1 Very Satisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 1 Comments 1.00		2										
to support a variety of group sizes 5 Yery Stratactory - Generous size, excellent condition, multiple options to support a variety of group sizes 8.11 Does not apply 8.11 Does not apply 1 Very stratactory - Too small, poor condition, layout and furnishings do not support informal interaction well. 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Goo size, good condition, layout and furnishings support informal interactions 5 Very Stratactory - Generous size, excellent condition, acoustic privacy, variety of independent work, disconnected form learning neighborhood 8.12 Does the learning neighborhood 1 Image: Stratactory - Sense: Strata		3										
N/A Does not apply 8.11 Does the building provide opportunities for informal interaction? 1 Comments 1.00 1.00 1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, loyout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well 3 Average - Adequate size and condition, layout and furnishings support informal interactions		4										
8.11 Does the building provide opportunities for informal interaction? 1 Comments 1.00 1.00 1 Very unsatisfactory - No space 1 Comments 1.00 1.00 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 1 Comments 1.00 1.00 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Goed size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 1 Comments 1.00 1.00 8.12 Does the learning neighborhood / building provide adequate spaces 1 Comments 1.00 1.00 1 Very unsatisfactory - Too small, poor condition, neads updates or renovations to function well. 1 Comments 1.00 1.00 1 Very unsatisfactory - Too small, poor condition, neads updates or renovations to function well. 1 Comments 1.00 1.00 3 Average - Adequate size and condition, neads updates or renovations to function well. 3 Average - Adequate size and condition, neads updates or renovations to function well. 4 Satisfactory - Goed size and c		5										
1 Very unsatisfactory - No space 2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does not apply 8.12 opportunities for students to work independently? 1 Comments 1,00 1,00 1 Comments 1,00 1,00 1 Comments 1,00 1,00 1 Comments 1,00 1,00 1 Comments 2 Unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, neads updates or renovations to function well. 3 Average - Adequate size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 3 Average - Good size and condition, acoustic privacy, variety of independent work spa		N/A	Does not apply									
2 Unsatisfactory - Too small, poor condition, layout and furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 N/A Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Comments 1.00 1.00 8.12 Does the learning neighborhood 1 Comments 1.00 1.00 3 Average - Adequate size and condition, needs updates or renovations to function well. 1 Comments 1.00 1.00 8.12 Does the learning neighborhood 3 Average - Adequate size and condition, necoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size and condition, needs updates or renovations to function well. 4 Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work, space options, connected to learning neighborhood 5 Very Satisfactory	8.11	Does the bu	ilding provide opportunities for informal interaction?	1						Comments	1.00	1.00
furnishings do not support informal interaction well 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does not apply 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, needs updates or renovations to function well. 3 Average - Adequate size and condition, acoustic privacy, variety of independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood		1	Very unsatisfactory - No space							·		
renovations to function well. 4 Satisfactory - Good size, good condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 1 Very unsatisfactory - No breakout rooms/small study spaces 1 2 Unsatisfactory - Too small, poor condition, ne acoustic privacy, only one space for independent work, disconnected from learning neighborhood 1 3 Average - Adequate size and condition, acoustic privacy, variety of independent work, space options, connected to learning neighborhood 1 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 1		2										
furnishing's support informal interactions 5 Very Satisfactory - Generous size, excellent condition, layout and furnishings support informal interactions N/A Does not apply 8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Comments 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - No space for independent work, disconnected from learning neighborhood 1 0 1.00 3 Average - Adequate size and condition, needs updates or renovations to function well. 3 Average - Adequate size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5		3										
layout and furnishings support informal interactions N/A Does not apply B.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Comments 1.00 1.00 1 Very unsatisfactory - No breakout rooms/small study spaces 1 Comments 1.00 1.00 2 Unsatisfactory - No small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, wariety of independent work space options, connected to learning neighborhood		4										
8.12 Does the learning neighborhood / building provide adequate opportunities for students to work independently? 1 Comments 1.00 1.00 1 Very unsatisfactory - No breakout rooms/small study spaces 1 0 1.00 1.00 1.00 1.00 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5		5										
8.12 opportunities for students to work independently? 1 Comments 1.00 1.00 1 Very unsatisfactory - No breakout rooms/small study spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5		N/A	Does not apply									
 spaces 2 Unsatisfactory - Too small, poor condition, no acoustic privacy, only one space for independent work, disconnected from learning neighborhood 3 Average - Adequate size and condition, needs updates or renovations to function well. 4 Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 5 Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 	8.12			1						Comments	1.00	1.00
 privacy, only one space for independent work, disconnected from learning neighborhood Average - Adequate size and condition, needs updates or renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 		1										
 renovations to function well. Satisfactory - Good size and condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 		2	privacy, only one space for independent work,									
 variety of independent work space options, connected to learning neighborhood Very Satisfactory - Generous size, excellent condition, acoustic privacy, variety of independent work space options, connected to learning neighborhood 		3										
acoustic privacy, variety of independent work space options, connected to learning neighborhood		4	variety of independent work space options, connected to									
N/A Does not apply		5	acoustic privacy, variety of independent work space									
		N/A	Does not apply							L		

02/11/2022 5

8 - A	cademics &	& Learning (cont.)		 					
8.13	Are Special	Education spaces appropriately configured per the ed spec?		3			Comments	1.00	3.00
	1	Very unsatisfactory - Too small, no flexibility, disconnected	•		•		It was inferred from the interview that the school does unit.	not have a Life	Skills
	2	Unsatisfactory - Too small, only one area for all teaching methods, limited flexibility, disconnected							
	3	Neutral - Adequate size, multiple areas for different teaching methods, adequate flexibility, limited transparency and connection to other studios and shared learning spaces, needs updates or renovations to function well.							
	4	Satisfactory - Good size, multiple areas for different teaching methods, good flexibility, good transparency and connection to other studios and shared learning spaces							
	5	Very Satisfactory - Generous size, multiple areas for different teaching methods, excellent flexibility, generous display area and visual teaching tools, excellent transparency and connection with other studios and shared learning spaces							
	N/A	Does not apply							
8.14		Education support spaces, such as storage, space for er, appropriately configured per the ed spec?		3			Comments	1.00	3.00
	1	Very unsatisfactory - None provided	•				Built in storage provided. No washer / dryer.		
	2	Unsatisfactory - Too small, disconnected, poor condition							
	3	Neutral - Adequate size, average condition, needs updates or renovations to function well							
	4	Satisfactory - Good size, connected, good condition							
	5	Very Satisfactory - Generous size, connected, excellent condition							
	N/A	Does not apply							
8.15		ble restrooms and changing rooms readily available to the cation spaces?	1				Comments	1.00	1.00
	1	No	-						
	5	Yes							

02/11/2022 °

9 - Visual and	Performing Arts	1	2	3	4	5	N/A		15.00	40%
9.1 Are music the ed spe	spaces and the cafeteria stage appropriately configured per c?	1						Comments	1.00	1.00
1	Very unsatisfactory - Too small, missing program spaces							Music in portable		
2	Unsatisfactory - Too small, poor condition									
3	Neutral - Adequate size, adequate condition, needs updates or renovations to function well.									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									
9.2 Are music per the ed	and performance storage spaces appropriately configured spec?			3				Comments	1.00	3.0
1	Very unsatisfactory - None provided							Music room disconnected from stage. Stage in adequat	e shape.	
2	Unsatisfactory - Too small, disconnected, poor condition									
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
9.3 Are Visual spec?	Arts spaces and storage appropriately configured per the ed		2					Comments	1.00	2.0
1	Very unsatisfactory - Too small, missing program spaces							Typical classroom used as art room. Does not have the	correct numbe	er of
2	Unsatisfactory - Too small, poor condition							sinks or adeuqate storage.		
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply									

02/11/2022 7


	ellness	1	2	3	4	5	N/.	A	10.00	40
10.1 Does the co program sp	ampus meet the ed spec standard for physical education paces?		2					Comments	1.00	2.0
1	Very unsatisfactory - Too small, missing program spaces							No natural light, low-ceiling restrooms not connected.	Gym is small at	: 2,30
2	Unsatisfactory - Too small, poor condition							square feet.		
3	Average - Adequate size, adequate condition, needs some renovations or updates to function well									
4	Satisfactory - Good size, good condition									
5	Very Satisfactory - Generous size, excellent condition									
N/A	Does not apply			r				1		
IO.2 Are the phy the ed spec			2					Comments	1.00	2.
1	Very unsatisfactory - None provided							Small office/storage room adjacent to gym. Student re	strooms are ac	ross
2	Unsatisfactory - Too small, disconnected, poor condition							hallway.		
3	Neutral - Adequate size, average condition, needs updates or renovations to function well									
4	Satisfactory - Good size, connected, good condition									
5	Very Satisfactory - Generous size, connected, excellent condition									
N/A	Does not apply									
1 - Food Servic	ces	1	2	3	4	5	N/	A	10.00	7
11.1 Is the Dinin	g Commons appropriately configured per the ed spec?				4			Comments	1.00	4.
1	Very unsatisfactory - Too small, missing program spaces							Cafeteria is adequately sized for current enrollment. Sp	bace has ample	•
2	Unsatisfactory - Too small, poor condition, only one option for eating space provided, inadequate circulation							daylight and functioning stage.		
3	Average - Adequate size and condition, needs updates or renovations to function well									
4	Satisfactory - Good size and condition, good circulation, multiple options for eating space (ex: connection to outdoor eating space)									
5	Very Satisfactory - Generous size, excellent condition and circulation, multiple options for eating space (ex: connection to outdoor eating space)									
N/A	Does not apply									
	od Services support spaces appropriately configured per the			3				Comments	1.00	3.
ed spec?			•	-			-		-	
ed spec?	Very unsatisfactory - None provided									
ea spec?	Very unsatisfactory - None provided Unsatisfactory - Too small, disconnected, poor condition									
ea spec ?										
l ed spec? 1 2	Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates									
ed spec?	Unsatisfactory - Too small, disconnected, poor condition Neutral - Adequate size, average condition, needs updates or renovations to function well									

02/11/2022 *

12 - Media Resources	1	2	3	4	5	N/A	A	30.00	43%
12.1 Is the Library/Media Center easily accessible for the occupants visitors to the school?	s and		3				Comments	1.00	3.00
 Very unsatisfactory - Not accessible Unsatisfactory - Limited access, difficult to find, n transparency 	10					•	Library is close to main entry but does not have any tro for the space.	ansparency or s	ignage
3 Average - Adequate accessibility, needs updates renovations to function well	s or								
4 Satisfactory - Accessible, easy to find, good trans good condition	sparency,								
5 Very Satisfactory - Accessible, easy to find, excell transparency, excellent condition	ent								
N/A Does not apply			_					•	
12.2 How well does the Library/Media Center support quiet study?	1						Comments	1.00	1.00
1 Very unsatisfactory - No quiet study spaces	•						Library is one large space and has limited flexibility. Th	e main reading	g room
 Unsatisfactory - One area in poor condition, poo privacy 	r acoustic						is 1400 square feet.		
3 Average - One or more areas provided, needing or renovations to function well	updates								
4 Satisfactory - Clusters or small rooms adjacent to center, good condition, good acoustic privacy	o media								
5 Very Satisfactory - Multiple clusters or small roon adjacent to media center, excellent condition, ex acoustic privacy									
N/A Does not apply									
12.3 How well does the Library/Media Center support social interact	ction? 1						Comments	1.00	1.00
1 Very unsatisfactory - No space									
 Unsatisfactory - Too small, poor condition, layou furnishings do not support informal interaction w 	/ell								
3 Average - Adequate size and condition, needs up renovations to function well.	pdates or								
4 Satisfactory - Good size, good condition, layout of furnishings support informal interactions	and								
5 Very Satisfactory - Generous size, excellent cond layout and furnishings support informal interacti									
N/A Does not apply									
12.4 How well does the Library/Media Center support collaborative small groups (4-8 students)?	e work in		3				Comments	1.00	3.00
 Very unsatisfactory - No breakout rooms, no flex furniture, no support 	ible				•		Small group work areas provided through furniture sol	utions.	
 Unsatisfactory - Too small, one area, poor condit 	tion								
3 Average - Adequate size, multiple areas provide updates or renovations to function well	d, needing								
4 Satisfactory - Clusters or small rooms adjacent to center, flexible furniture, good condition	o media								
5 Very Satisfactory - Multiple clusters or small roon adjacent to media center, flexible furniture, exce condition									
N/A Does not apply							L		

02/11/2022 °

12 - N		ources - Continued	1	2	3	4	5	N/A	۱ <u>ــــــــــــــــــــــــــــــــــــ</u>		
12.5	How well de larger grou	• • •		2					Comments	1.00	2.0
	1	Very unsatisfactory - No gathering areas							Current size only allows for one large group of students to	o meet.	
	2	Unsatisfactory - Too small, one common space, limited seating, poor condition									
	3	Average - Adequate size, one common space, needs updates or renovations to function well									
	4	Satisfactory - Good size, multiple common spaces with seating, good condition									
	5	Very Satisfactory - Generous size, multiple commons spaces with seating, excellent condition									
	N/A	Does not apply	_								
12.6	How well d	oes the Library/Media Center support technology?			3				Comments	1.00	3.0
	1	Very unsatisfactory - No vis comm tools	•								
	2	Unsatisfactory - Outdated, poorly functioning, or insufficient									
	3	Good - Mix of old and new whiteboards/projectors/etc.									
	4	Satisfactory - Projectors, marker boards, smart boards in most spaces - good condition									
	5	Very Satisfactory - Projectors, marker boards, smart boards in most spaces - new condition									
	N/A	Does not apply									
13 - T	[echnology	y	1	2	3	4	5	N/A		20.00	40
13.1	How well e	quipped are the facilities with instructional technology?			3				Comments	1.00	3.0
	1	Very unsatisfactory - Limited to no technology present in instructional spaces									
	2	Unsatisfactory - One type of technology present									
	3	Average - Multiple types of technology, smart boards, poor condition, limited to only certain areas of school									
	4	Satisfactory - Multiple types of technology, smart boards, good condition.									
	5	Very Satisfactory - Multiple types of technology, smart boards, excellent condition									
	N/A	Does not apply									
13.2	ls there an o spaces?	adequate number of power and data outlets in learning	1						Comments	1.00	1.0
	1	Very unsatisfactory - Outlet configuration does not support digital devices throughout school (1 per wall)							Dated studios do not have adequate number of outlets.		
	2	Unsatisfactory - Outlet configuration support digital devices only in certain areas of school (2 per wall)									
	3	Average - Outlet configuration support digital devices but not enough capacity throughout school (3 per wall)									
	4	Satisfactory - Outlet configuration support digital devices with adequate coverage and capacity throughout school (>3 per wall)									
	5	Very Satisfactory - Excellent outlet configuration to support digital devices throughout school (>3 per wall)									
	N/A	Does not apply									



13.3 Are there adequate charging locations for devices? 1 I	13	- Technology	(cont.)	1	2	3	4	5	N/A			
2 Unsatisfactory - Centralized charging location, but inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 Comments 1 Very unsatisfactory - AV not present in one or more space Cafeteria has A/V. 2 Unsatisfactory - AV undersized for room, poor condition Cafeteria has A/V.	13	.3 Are there a	dequate charging locations for devices?	1						Comments	1.00	1.00
inadequate in size for number of devices 3 Average - Charging cart or tower but not adequately sized for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 1 Very unsatisfactory - AV not present in one or more space 2 Unsatisfactory - AV undersized for room, poor condition		1	Very unsatisfactory - No centralized charging location									
for number of devices 4 Satisfactory - Charging cart or tower not centralized 5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces – cafeteria and gym? 3 1 Very unsatisfactory - AV not present in one or more space 2 Unsatisfactory - AV undersized for room, poor condition		2										
5 Very Satisfactory - Charging cart or tower located centralized location. Excellent condition N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 Comments 1.00 1 Very unsatisfactory - AV not present in one or more space Cafeteria has A/V. Cafeteria has A/V. 2 Unsatisfactory - AV undersized for room, poor condition Cafeteria has A/V. Cafeteria has A/V.		3										
N/A Does not apply 13.4 Is there adequate AV for presentations spaces - cafeteria and gym? 3 Comments 1.00 1 Very unsatisfactory - AV not present in one or more space Cafeteria has A/V. Cafeteria has A/V. 2 Unsatisfactory - AV undersized for room, poor condition Cafeteria has A/V. Cafeteria has A/V.		4	Satisfactory - Charging cart or tower not centralized									
13.4 Is there adequate AV for presentations spaces – cafeteria and gym? 3 Comments 1.00 1 Very unsatisfactory – AV not present in one or more space Cafeteria has A/V. Cafeteria has A/V. 2 Unsatisfactory – AV undersized for room, poor condition Cafeteria has A/V. Cafeteria has A/V.		5										
1 Very unsatisfactory - AV not present in one or more space Cafeteria has A/V. 2 Unsatisfactory - AV undersized for room, poor condition		N/A	Does not apply									
2 Unsatisfactory - AV undersized for room, poor condition	13	.4 Is there ade	quate AV for presentations spaces – cafeteria and gym?			3				Comments	1.00	3.00
		1	Very unsatisfactory - AV not present in one or more space		•					Cafeteria has A/V.		
2 Average Adequately sized / peer condition OP AV		2	Unsatisfactory - AV undersized for room, poor condition									
undersized / adequate condition		3	Average - Adequately sized / poor condition OR AV undersized / adequate condition									
4 Satisfactory - Good size, good condition		4	Satisfactory - Good size, good condition									
5 Very Satisfactory - Generous sized, excellent condition		5	Very Satisfactory - Generous sized, excellent condition									
N/A Does not apply		N/A	Does not apply									
13.5 Is there digital media signage at the reception area? 3 Comments 0.00	13	.5 Is there digi	tal media signage at the reception area?			3				Comments	0.00	0.00
1 Very unsatisfactory - No digital media present in reception In corridor outside reception area area In corridor outside reception area		1							•	In corridor outside reception area	•	
2 Unsatisfactory - Undersized, poor condition		2	Unsatisfactory - Undersized, poor condition									
3 Average - Adequately sized / poor condition OR undersized / adequate condition		3										
4 Satisfactory - Media signage present, good sized, good condition		4										
5 Very Satisfactory - Generously sized, excellent condition		5	Very Satisfactory - Generously sized, excellent condition									
N/A Does not apply		N/A	Does not apply									

02/11/2022 "

14 - A	dministra	tion Spaces	1	2	3	4	5	N/A		20.00	45%
	ls there a revisitors?	ception area that functions as a security checkpoint for all							Comments	1.00	
	1	Very unsatisfactory - No security checkpoint									
	2	Unsatisfactory - Checkpoint is too small, poor condition									
	3	Average - Needs updates or renovations to function well									
	4	Satisfactory - Good size, good condition									
	5	Very Satisfactory - Generous size, excellent condition									
	N/A	Does not apply	-		-		1			1	
14.2	Does the ad	ministration area feel welcoming?			3				Comments	1.00	3.0
	1	Very unsatisfactory - No welcome space							Small space and needs updates. Feels dated.	•	
	2	Unsatisfactory - Too small, poor lighting and transparency, limited informal seating, poor condition	,								
	3	Average - Adequate size and layout, needs updates or renovations to feel welcoming									
	4	Satisfactory - Good size and layout, good lighting and transparency, informal seating provided									
	5	Very Satisfactory - Generous size and layout, plenty of ligh and transparency, informal seating provided, excellent condition	t								
	N/A	Does not apply									
		aces that require it, does the administration area have coustic privacy?		2					Comments	1.00	2.0
	1	Very unsatisfactory - No acoustic separations	_	1	1		1			1	
	2	Unsatisfactory - Acoustic separations do not perform well									
	3	Average - Some acoustic separations function okay, but portions need updates or renovations									
	4	Satisfactory - Good acoustic separations									
	5	Very Satisfactory - Excellent acoustic separations									
	N/A	Does not apply				_			-		
14.4	Are confere	nce rooms easily accessed for public / parent use?		2					Comments	1.00	2.0
	1	Very unsatisfactory - Not accessible for public/parent use									
	2	Unsatisfactory - Limited access, no transparency, poor condition, difficult to find									
	3	Average - Adequate accessibility, needs updates or renovations to function well									
	4	Satisfactory - Good accessibility, good transparency, good size and condition									
	5	Very Satisfactory - Excellent accessibility, excellent transparency, generous size, excellent condition									
	N/A	Does not apply									